Site UPRN	Site Code	Site Name	Block No	Component	Location	Product	Type	Surface Treatment	Damage	Recommendations	Change Control	Priority Assessment Type	No Access	Material Risk Assessment	Material Assessment Total	Review Date	Indentification	Overall Risk Assessment	Asbestos ID	Lab Reference	Survey Ref	Survey Date	Survey Company
#REF!	QAA	Craigavon Hospital	18	Bitumen Felt		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	60269	BA3217/01	9724/1 ?	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	18	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	60270	BA3217/04	9724/1 ?	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	18	Fire Lining Board		Cement Products	Chrysotile	Cement Sheets	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	4	24/06/2023	Identified	Very Low Risk	60271	BA3217/02	9724/1 ?	24/06/2022	WHS
#REF!	QAA	Craigavon Hospital	18	Fire Lining Board	Fire Lining Board at Junctions with the Roof	Cement Products	NO ASBESTOS	Unsealed Board	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	60272	BA3217/03	9724/1 ?	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	18	Fire Lining Board	Cut Offs to Roof Void Floor	Cement Products	NO ASBESTOS	Unsealed Board	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	60273	BA3217/03	9724/1 ?	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	18	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	60274	BA3217/04	9724/1 ?	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	18	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	60275	BA3217/04	9724/1 ?	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	18	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	60276	BA3217/04	9724/1 ?	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	18	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	60277	BA3217/04	9724/1 ?	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	18	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	60278	BA3217/04	9724/1 ?	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	18	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	60279	BA3217/04	9724/1 ?	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	18	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	60280	BA3217/04	9724/1 ?	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	18	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	60281	BA3217/04	9724/1 ?	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	18	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	60282	BA3217/04	9724/1 ?	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	18	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	60283	BA3217/04	9724/1 ?	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	18	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	60284	BA3217/04	9724/1 ?	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	18	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	60285	BA3217/04	9724/1 ?	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	18	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	60286	BA3217/04	9724/1 ?	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	18	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	60287	BA3217/04	9724/1 ?	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	18	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	60288	BA3217/04	9724/1 ?	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	18	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	60289	BA3217/04	9724/1 ?	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	18	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	60290	BA3217/04	9724/1 ?	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	18	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	60291	BA3217/04	9724/1 ?	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	18	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	60292	BA3217/04	9724/1 ?	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	18	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	60293	BA3217/04	9724/1 ?	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	18	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	60294	BA3217/04	9724/1 ?	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	18	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	60295	BA3217/04	9724/1 ?	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	18	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	60296	BA3217/04	9724/1 ?	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	18	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	60297	BA3217/04	9724/1 ?	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	18	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	60298	BA3217/04	9724/1 ?	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	18	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	60299	BA3217/04	9724/1 ?	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	18	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	60300	BA3217/04	9724/1 ?	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	18	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	60301	BA3217/04	9724/1 ?	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	18	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	60302	BA3217/04	9724/1 ?	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	18	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	60303	BA3217/04	9724/1 ?	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	18	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	60304	BA3217/05	9724/1 ?	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	18	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	60305	BA3217/05	9724/1 ?	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	18	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	60306	BA3217/05	9724/1 ?	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	18	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	60307	BA3217/05	9724/1 ?	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	18	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	60308	BA3217/05	9724/1 ?	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	18	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	60309	BA3217/05	9724/1 ?	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	18	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	60310	BA3217/05	9724/1 ?	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	18	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	60311	BA3217/05	9724/1 ?	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	18	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	60312	BA3217/05	9724/1 ?	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	18	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	60313	BA3217/05	9724/1 ?	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	18	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	60314	BA3217/05	9724/1 ?	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	18	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	60315	BA3217/05	9724/1 ?	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	18	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	60316	BA3217/05	9724/1 ?	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	18	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	60317	BA3217/05	9724/1 ?	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	18	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	60318	BA3217/05	9724/1 ?	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	18	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	60319	BA3217/05	9724/1 ?	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	18	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	60320	BA3217/05	9724/1 ?	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	18	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	60321	BA3217/05	9724/1 ?	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	18	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	60322	BA3217/05	9724/1 ?	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	18	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	60323	BA3217/05	9724/1 ?	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	18	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	60324	BA3217/05	9724/1 ?	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	18	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	60325	BA3217/05	9724/1 ?	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	18	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	60326	BA3217/05	9724/1 ?	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	18	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	60327	BA3217/05	9724/1 ?	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	18	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	60328	BA3217/05	9724/1 ?	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	18	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	60329	BA3217/05	9724/1 ?	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	18	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	60330	BA3217/05	9724/1 ?	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	18	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	60331	BA3217/05	9724/1 ?	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	18	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	60332	BA3217/05	9724/1 ?	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	18	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	60333	BA3217/05	9724/1 ?	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	18	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	60334	BA3217/05	9724/1 ?	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	18	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	60335	BA3217/05	9724/1 ?	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	18	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	60336	BA3217/05	9724/1 ?	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	18	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	60337	BA3217/05	9724/1 ?	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	18	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	60338	BA3217/06	9724/1 ?	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	18	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	60339	BA3217/06	9724/1 ?	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	18	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	60340	BA3217/06	9724/1 ?	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	18	Sink Pad		Composite Material	Chrysotile	Composite Material	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	24/06/2023	Identified	Very Low Risk	60341	BA3217/07	9724/1 ?	24/06/2022	WHS

#REF!	QAA	Craigavon Hospital	18	Sink Pad		Reinforced Composites	Chrysotile	Composite Material	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	24/06/2023	Strongly Presumed Similar to	Very Low Risk	60342	BA3217/07	9324/17	24/06/2022	WHS		
#REF!	QAA	Craigavon Hospital	18	Sink Pad		Reinforced Composites	Chrysotile	Composite Material	Low	Label & Manage	Re-inspection	HSG227	Unchecked	Very Low Risk	3	24/06/2023	Strongly Presumed Similar to	Very Low Risk	60343	BA3217/07	9324/17	24/06/2022	WHS		
#REF!	QAA	Craigavon Hospital	18	Sink Pad		Reinforced Composites	Chrysotile	Composite Material	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	24/06/2023	Strongly Presumed Similar to	Very Low Risk	60344	BA3217/07	9324/17	24/06/2022	WHS		
#REF!	QAA	Craigavon Hospital	18	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	60345	BA3217/08	9724/17	05/09/2017	WHS		
#REF!	QAA	Craigavon Hospital	18	Door Panel	Freeze Board Panel Above Door	Insulating Board	NO ASBESTOS	Unsealed Board	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	60346	BA3217/09	9724/17	05/09/2017	WHS		
#REF!	QAA	Craigavon Hospital	18	Door Panel		Insulating Board	NO ASBESTOS	Unsealed Board	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	60347	BA3217/09	9724/17	05/09/2017	WHS		
#REF!	QAA	Craigavon Hospital	18	Door Panel		Insulating Board	NO ASBESTOS	Unsealed Board	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	60348	BA3217/09	9724/17	05/09/2017	WHS		
#REF!	QAA	Craigavon Hospital	18	Door Panel		Insulating Board	NO ASBESTOS	Unsealed Board	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	60349	BA3217/09	9724/17	05/09/2017	WHS		
#REF!	QAA	Craigavon Hospital	18	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Low	Label & Manage	Re-inspection	HSG227	Unchecked	Very Low Risk	3	24/06/2023	Identified	Very Low Risk	60350	BA3217/10	9324/17	24/06/2022	WHS		
#REF!	QAA	Craigavon Hospital	18	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	24/06/2023	Identified	Very Low Risk	60351	BA3217/11	9324/17	24/06/2022	WHS		
#REF!	QAA	Craigavon Hospital	18	Fire Break Panel	Panel above Toilet Cistern	Insulating Board	NO ASBESTOS	Enclosed Spray or Lagging/Sealed AIB	No visible damage or deterioration	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	60352	BA3217/12	9724/17	05/09/2017	WHS		
#REF!	QAA	Craigavon Hospital	18	Fire Break Panel		Insulating Board	NO ASBESTOS	Enclosed Spray or Lagging/Sealed AIB	No visible damage or deterioration	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	60353	BA3217/12	9724/17	05/09/2017	WHS		
#REF!	QAA	Craigavon Hospital	18	Stair Nosing		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	60354	BA3217/13	9724/17	05/09/2017	WHS		
#REF!	QAA	Craigavon Hospital	18	Stair Nosing		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	60355	BA3217/13	9724/17	05/09/2017	WHS		
#REF!	QAA	Craigavon Hospital	18	Bitumen Felt	Bitumen to Rear Flat Roof	Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	60356	BA3217/14	9724/17	05/09/2017	WHS		
#REF!	QAA	Craigavon Hospital	18	Bitumen Felt	Bitumen to Front Flat Roof	Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	60357	BA3217/14	9724/17	05/09/2017	WHS		
#REF!	QAA	Craigavon Hospital	18	Soffit Boards	Soffit Boards	Cement Products	Chrysotile	Cement Sheets	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	4	24/06/2023	Identified	Very Low Risk	60358	BA3217/15	9324/17	24/06/2022	WHS		
#REF!	QAA	Craigavon Hospital	18	Gaskets	Gaskets to Pipework	Textiles & Paper	NO ASBESTOS	Composite Material	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	60359	BA3217/16	9724/17	05/09/2017	WHS		
#REF!	QAA	Craigavon Hospital	18	Ceiling Board		Insulating Board	NO ASBESTOS	Enclosed Spray or Lagging/Sealed AIB	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	60360	BA3217/17	9724/17	05/09/2017	WHS		
#REF!	QAA	Craigavon Hospital	18	Cowl	Cowls to Roof	Cement Products	Presumed Asbestos	Composite Material	No visible damage or	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	4	24/06/2023	Presumed	Very Low Risk	60361		9324/17	24/06/2022	WHS		
#REF!	QAA	Craigavon Hospital	18	Fuse Flash Guards	Flashbacks to Electrical Switchgear	Textiles & Paper	Presumed Asbestos	Enclosed Fuse Flash Guards	Very Low	Apply Caution when Maintaining	Re-inspection	HSG227	Unchecked	Low Risk	6	24/06/2023	Presumed	Low Risk	60362		9324/17	24/06/2022	WHS		
#REF!	SAA	Daisy Hill Hospital Estate	23		Roof Covering		NO ASBESTOS			No further action required (No Asbestos Detected)	Correcting Previous Data	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	60544	BA3284/01					
#REF!	SJG	Teach Sona	01				NO ASBESTOS				Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63198		9327/17	23/04/2018	WH Stephens		
#REF!	SJG	Teach Sona	01	Sink / Drainer Pads		Reinforced Composites	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	63199	A72374	9327/17	23/04/2018	WH Stephens		
#REF!	SJG	Teach Sona	01				NO ASBESTOS				Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63200		9327/17	23/04/2018	WH Stephens		
#REF!	SJG	Teach Sona	01				NO ASBESTOS				Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63201		9327/17	23/04/2018	WH Stephens		
#REF!	SJG	Teach Sona	01				NO ASBESTOS				Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63202		9327/17	23/04/2018	WH Stephens		
#REF!	SJG	Teach Sona	01				NO ASBESTOS				Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63203		9327/17	23/04/2018	WH Stephens		
#REF!	SJG	Teach Sona	01				NO ASBESTOS				Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63204		9327/17	23/04/2018	WH Stephens		
#REF!	SJG	Teach Sona	01				NO ASBESTOS				Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63205		9327/17	23/04/2018	WH Stephens		
#REF!	SJG	Teach Sona	01				NO ASBESTOS				Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63206		9327/17	23/04/2018	WH Stephens		
#REF!	SJG	Teach Sona	01				NO ASBESTOS				Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63207		9327/17	23/04/2018	WH Stephens		
#REF!	SJG	Teach Sona	01				NO ASBESTOS				Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63208		9327/17	23/04/2018	WH Stephens		
#REF!	SJG	Teach Sona	01				NO ASBESTOS				Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63209		9327/17	23/04/2018	WH Stephens		
#REF!	SJG	Teach Sona	01				NO ASBESTOS				Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63210		9327/17	23/04/2018	WH Stephens		
#REF!	SJG	Teach Sona	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63211		9327/17	23/04/2018	WH Stephens		
#REF!	SJG	Teach Sona	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63212		9327/17	23/04/2018	WH Stephens		
#REF!	SJG	Teach Sona	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63213		9327/17	23/04/2018	WH Stephens		
#REF!	SJG	Teach Sona	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63214		9327/17	23/04/2018	WH Stephens		
#REF!	SJG	Teach Sona	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63215		9327/17	23/04/2018	WH Stephens		
#REF!	SJG	Teach Sona	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63216		9327/17	23/04/2018	WH Stephens		
#REF!	SJG	Teach Sona	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63217		9327/17	23/04/2018	WH Stephens		
#REF!	SJG	Teach Sona	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63218		9327/17	23/04/2018	WH Stephens		
#REF!	SJG	Teach Sona	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63219		9327/17	23/04/2018	WH Stephens		
#REF!	SJG	Teach Sona	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63220		9327/17	23/04/2018	WH Stephens		
#REF!	SJG	Teach Sona	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63221		9327/17	23/04/2018	WH Stephens		
#REF!	SJG	Teach Sona	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63222		9327/17	23/04/2018	WH Stephens		
#REF!	SJG	Teach Sona	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63223		9327/17	23/04/2018	WH Stephens		
#REF!	SJG	Teach Sona	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63224		9327/17	23/04/2018	WH Stephens		
#REF!	SJG	Teach Sona	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63225		9327/17	23/04/2018	WH Stephens		
#REF!	SJG	Teach Sona	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63226		9327/17	23/04/2018	WH Stephens		
#REF!	SJG	Teach Sona	01	Boards to back of Trap Doors		Cement Products	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	63227	A72375	9327/17	23/04/2018	WH Stephens		
#REF!	SJG	Teach Sona	01	Undercloak	Undercloak to roof of main dwelling	Cement Products	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	63228	A72376	9327/17	23/04/2018	WH Stephens		
#REF!	SJG	Teach Sona	01	Undercloak	Undercloak to Garage	Cement Products	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	63229	A72377	9327/17	23/04/2018	WH Stephens		
#REF!	SHA	Drumalane Estate	06				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63297		9327/17	04/04/2018	WH Stephens		
#REF!	SHA	Drumalane Estate	06				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63298		9327/17	04/04/2018	WH Stephens		
#REF!	SHA	Drumalane Estate	06				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63299		9327/17	04/04/2018	WH Stephens		
#REF!	SHA	Drumalane Estate	06				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63300		9327/17	04/04/2018	WH Stephens		
#REF!	SHA	Drumalane Estate	06				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63301		9327/17	04/04/2018	WH Stephens		
#REF!	SHA	Drumalane Estate	06				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63302		9327/17	04/04/2018	WH Stephens		
#REF!	SHA	Drumalane Estate	06				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63303		9327/17	04/04/2018	WH Stephens		
#REF!	SHA	Drumalane Estate	06				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63304		9327/17	04/04/2018	WH Stephens		
#REF!	SHA	Drumalane Estate	06				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63305		9327/17	04/04/2018	WH Stephens		
#REF!	SHA	Drumalane Estate	06				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63306		9327/17	04/04/2018	WH Stephens		
#REF!	SHA	Drumalane Estate	06				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63307		9327/17	04/04/2018	WH Stephens		
#REF!	SHA	Drumalane Estate	06				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63308		9327/17	04/04/2018	WH Stephens		
#REF!	SHA	Drumalane Estate	06				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63309		9327/17	04/04/2018	WH Stephens		
#REF!	SHA	Drumalane Estate	06				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63310		9327/17	04/04/2018	WH Stephens		
#REF!	SHA	Drumalane Estate	06				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63311		9327/17	04/04/2018	WH Stephens		
#REF!	SHA	Drumalane Estate	06				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63312		9327/17	04/04/2018	WH Stephens		
#REF!	SHA	Drumalane Estate	06				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63313		9327/17	04/04/2018	WH Stephens		
#REF!	SHA	Drumalane Estate	06				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63314		9327/17	04/04/2018	WH Stephens		
#REF!	SHA	Drumalane Estate	06				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63315		9327/17	04/04/2018	WH Stephens		
#REF!	SHA	Drumalane Estate	06				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63316		9327/17	04/04/2018	WH Stephens		
#REF!	SHA	Drumalane Estate	06				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63317		9327/17	04/04/2018	WH Stephens		
#REF!	SHA	Drumalane Estate	06				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63318		9327/17	04/04/2018	WH Stephens		
#REF!	SHA	Drumalane Estate	06				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63319		9327/17	04/04/2018	WH Stephens		
#REF!	SHA	Drumalane Estate	06				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63320		9327/17	04/04/2018	WH Stephens		
#REF!	SHA	Drumalane Estate	06				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63321		9327/17	04/04/2018	WH Stephens		
#REF!	SHA	Drumalane Estate	06				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63322		9327/17	04/04/2018	WH Stephens		
#REF!	SHA	Drumalane Estate	06				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63323		9327/17	04/04/2018	WH Stephens		
#REF!	SHA	Drumalane Estate	06				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63324		9327/17	04/04/2018	WH Stephens		

#REF!	SHA	Drumalane Estate	06			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63325		932717	04/04/2018	WH Stephens
#REF!	SHA	Drumalane Estate	06	Ceiling Board		Insulating Board	Amosite/Chrysotile	Encapsulated Spray or	Minor Damage of	Label & Manage	Re-inspection	HSG227	Unchecked	Low Risk	6	14/09/2023	Stronnly Presumed	Low Risk	63326		930027	12/11/2020	WHS
#REF!	SHA	Drumalane Estate	06	Wall Panel		Insulating Board	Amosite/Chrysotile	Encapsulated Spray or Lacoinn/Unsealed AIB	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Medium Risk	7	14/09/2023	Strongly Presumed	Low Risk	63327		930027	30/08/2022	WHS
#REF!	SHA	Drumalane Estate	06				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63328		932717	04/04/2018	WH Stephens
#REF!	SHA	Drumalane Estate	06				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63329		932717	04/04/2018	WH Stephens
#REF!	SHA	Drumalane Estate	06				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63330		932717	04/04/2018	WH Stephens
#REF!	SHA	Drumalane Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63343		932717	27/04/2018	WH Stephens
#REF!	SHA	Drumalane Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63344		932717	27/04/2018	WH Stephens
#REF!	SHA	Drumalane Estate	01	Drainer Pad		Reinforced Comoosites	NO ASBESTOS	Composite Materials	High	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Presumed	No Asbestos Detected	63345	A73553	932717	27/04/2018	WH Stephens
#REF!	SHA	Drumalane Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63346		932717	27/04/2018	WH Stephens
#REF!	SHA	Drumalane Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63347		932717	27/04/2018	WH Stephens
#REF!	SHA	Drumalane Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63348		932717	27/04/2018	WH Stephens
#REF!	SHA	Drumalane Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63349		932717	27/04/2018	WH Stephens
#REF!	SHA	Drumalane Estate	01	Roof Slate		Cement Products	Chrysotile		Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	14/09/2023	Identified	Very Low Risk	63350	A73554	930027	30/08/2022	WHS
#REF!	SHA	Drumalane Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63351		932717	27/04/2018	WH Stephens
#REF!	SHA	Drumalane Estate	01	Soffit & Verge Boards		Insulating Board	Chrysotile	Encapsulated Spray or	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Low Risk	5	14/09/2023	Identified	Very Low Risk	63352	A73555	930027	12/09/2019	WHS
#REF!	SHA	Drumalane Estate	05				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63353		932717	04/10/2018	WH Stephens
#REF!	SHA	Drumalane Estate	05				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63354		932717	04/10/2018	WH Stephens
#REF!	SHA	Drumalane Estate	05				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63355		932717	04/10/2018	WH Stephens
#REF!	SHA	Drumalane Estate	05				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63356		932717	04/10/2018	WH Stephens
#REF!	SHA	Drumalane Estate	05				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63357		932717	04/10/2018	WH Stephens
#REF!	SHA	Drumalane Estate	05				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63358		932717	04/10/2018	WH Stephens
#REF!	SHA	Drumalane Estate	05	Brown Floor Tiles		Reinforced Comoosites	NO ASBESTOS	Composite Materials	Medium	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	63359	A73563-E	932717	04/10/2018	WH Stephens
#REF!	SHA	Drumalane Estate	05				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63360		932717	04/10/2018	WH Stephens
#REF!	SHA	Drumalane Estate	05				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63361		932717	04/10/2018	WH Stephens
#REF!	SHA	Drumalane Estate	05				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63362		932717	04/10/2018	WH Stephens
#REF!	SHA	Drumalane Estate	05				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63363		932717	04/10/2018	WH Stephens
#REF!	SHA	Drumalane Estate	05	Red Floor Tiles		Reinforced Comoosites	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	63364	A73562	932717	04/10/2018	WH Stephens
#REF!	SHA	Drumalane Estate	05				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63365		932717	04/10/2018	WH Stephens
#REF!	SHA	Drumalane Estate	05				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63366		932717	04/10/2018	WH Stephens
#REF!	SHA	Drumalane Estate	05				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63367		932717	04/10/2018	WH Stephens
#REF!	SHA	Drumalane Estate	05	Sink / Drainer Pads		Reinforced Comoosites	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	63368	A73561	932717	04/10/2018	WH Stephens
#REF!	SHA	Drumalane Estate	05	Green Floor Tiles		Reinforced Comoosites	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	63369	A73560	932717	04/10/2018	WH Stephens
#REF!	SHA	Drumalane Estate	05				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63370		932717	04/10/2018	WH Stephens
#REF!	SHA	Drumalane Estate	05				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63371		932717	04/10/2018	WH Stephens
#REF!	SHA	Drumalane Estate	05				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63372		932717	04/10/2018	WH Stephens
#REF!	SHA	Drumalane Estate	05	Drainer Pad		Reinforced Comoosites	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	14/09/2023	Identified	Very Low Risk	63373	A73564	930027	30/08/2022	WHS
#REF!	SHA	Drumalane Estate	05	Brown Floor Tiles		Reinforced Comoosites	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	63374	A73563	932717	04/10/2018	WH Stephens
#REF!	SHA	Drumalane Estate	05				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63375		932717	04/10/2018	WH Stephens
#REF!	SHA	Drumalane Estate	05	Light Green Floor Tiles		Reinforced Comoosites	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	63376	A73567	932717	04/10/2018	WH Stephens
#REF!	SHA	Drumalane Estate	05	Sink / Drainer Pads		Reinforced Comoosites	NO ASBESTOS	Composite Materials	High	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	63377	A73565	932717	04/10/2018	WH Stephens
#REF!	SHA	Drumalane Estate	05				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63378		932717	04/10/2018	WH Stephens
#REF!	SHA	Drumalane Estate	05				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63379		932717	04/10/2018	WH Stephens
#REF!	SHA	Drumalane Estate	05				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63380		932717	04/10/2018	WH Stephens
#REF!	SHA	Drumalane Estate	05	Soffit Boards		Insulating Board	NO ASBESTOS	Encapsulated Spray or Lacoinn/Unsealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	63381	A73568	932717	04/10/2018	WH Stephens
#REF!	SHA	Drumalane Estate	05				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63382		932717	04/10/2018	WH Stephens
#REF!	SHA	Drumalane Estate	05				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63383		932717	04/10/2018	WH Stephens
#REF!	SHA	Drumalane Estate	05				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63384		932717	04/10/2018	WH Stephens
#REF!	SHA	Drumalane Estate	05	Sink Pad		Reinforced Comoosites	NO ASBESTOS	Composite Materials	High	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	63385	A73566	932717	04/10/2018	WH Stephens
#REF!	SHA	Drumalane Estate	05	Undercloak to verge		Insulating Board	Chrysotile	Encapsulated Spray or Lacoinn/Unsealed AIB	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Medium Risk	7	14/03/2023	Identified	Medium Risk	63386	A73569	930027	30/08/2022	WHS
#REF!	SHA	Drumalane Estate	05	Ceiling Board	Entrance Porch Ceiling	Insulating Board	Amosite/Chrysotile	Encapsulated Spray or	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Medium Risk	7	14/03/2023	Identified	Medium Risk	63387	A73570	930027	30/08/2022	WHS
#REF!	SHA	Drumalane Estate	04				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63388		932717	23/03/2018	WH Stephens
#REF!	SHA	Drumalane Estate	04				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63389		932717	23/03/2018	WH Stephens
#REF!	SHA	Drumalane Estate	04				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63390		932717	23/03/2018	WH Stephens
#REF!	SHA	Drumalane Estate	04				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63391		932717	23/03/2018	WH Stephens
#REF!	SHA	Drumalane Estate	04				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63392		932717	23/03/2018	WH Stephens
#REF!	SHA	Drumalane Estate	04				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63393		932717	23/03/2018	WH Stephens
#REF!	SHA	Drumalane Estate	04				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63394		932717	23/03/2018	WH Stephens
#REF!	SHA	Drumalane Estate	04				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63395		932717	23/03/2018	WH Stephens
#REF!	SHA	Drumalane Estate	04				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63396		932717	23/03/2018	WH Stephens
#REF!	SHA	Drumalane Estate	04				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63397		932717	23/03/2018	WH Stephens
#REF!	SHA	Drumalane Estate	04				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63398		932717	23/03/2018	WH Stephens
#REF!	SHA	Drumalane Estate	04				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63399		932717	23/03/2018	WH Stephens
#REF!	SHA	Drumalane Estate	04				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63400		932717	23/03/2018	WH Stephens
#REF!	SHA	Drumalane Estate	04				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63401		932717	23/03/2018	WH Stephens
#REF!	SHA	Drumalane Estate	04				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63402		932717	23/03/2018	WH Stephens
#REF!	SHA	Drumalane Estate	04				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63403		932717	23/03/2018	WH Stephens
#REF!	SHA	Drumalane Estate	04				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63404		932717	23/03/2018	WH Stephens
#REF!	SHA	Drumalane Estate	04				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63405		932717	23/03/2018	WH Stephens
#REF!	SHA	Drumalane Estate	04				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63406		932717	23/03/2018	WH Stephens
#REF!	SHA	Drumalane Estate	04				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63407		932717	23/03/2018	WH Stephens
#REF!	SHA	Drumalane Estate	04				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63408		932717	23/03/2018	WH Stephens
#REF!	SHA	Drumalane Estate	04				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63409		932717	23/03/2018	WH Stephens
#REF!	SHA	Drumalane Estate	04				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63410		932717	23/03/2018	WH Stephens
#REF!	SHA	Drumalane Estate	04				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63411		932717	23/03/2018	WH Stephens

#REF!	SHA	Drumalane Estate	04			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63412		9327/17	23/03/2018	WH Stephens
#REF!	SHA	Drumalane Estate	04			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63413		9327/17	23/03/2018	WH Stephens
#REF!	SHA	Drumalane Estate	04			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63414		9327/17	23/03/2018	WH Stephens
#REF!	SHA	Drumalane Estate	04			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63415		9327/17	23/03/2018	WH Stephens
#REF!	SHA	Drumalane Estate	04			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63416		9327/17	23/03/2018	WH Stephens
#REF!	SHA	Drumalane Estate	04			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63417		9327/17	23/03/2018	WH Stephens
#REF!	SHA	Drumalane Estate	04			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63418		9327/17	23/03/2018	WH Stephens
#REF!	SHA	Drumalane Estate	04			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63419		9327/17	23/03/2018	WH Stephens
#REF!	SHA	Drumalane Estate	04			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63420		9327/17	23/03/2018	WH Stephens
#REF!	SHA	Drumalane Estate	04			NO ASBESTOS				Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63421		9327/17	23/03/2018	WH Stephens
#REF!	SHA	Drumalane Estate	04			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63422		9327/17	23/03/2018	WH Stephens
#REF!	SHA	Drumalane Estate	04			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63423		9327/17	23/03/2018	WH Stephens
#REF!	SHA	Drumalane Estate	04			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63424		9327/17	23/03/2018	WH Stephens
#REF!	SHA	Drumalane Estate	04			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63425		9327/17	23/03/2018	WH Stephens
#REF!	SHA	Drumalane Estate	04			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63426		9327/17	23/03/2018	WH Stephens
#REF!	SHA	Drumalane Estate	04			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63427		9327/17	23/03/2018	WH Stephens
#REF!	SHA	Drumalane Estate	04			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63428		9327/17	23/03/2018	WH Stephens
#REF!	SHA	Drumalane Estate	04			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63429		9327/17	23/03/2018	WH Stephens
#REF!	SHA	Drumalane Estate	04			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63430		9327/17	23/03/2018	WH Stephens
#REF!	SHA	Drumalane Estate	04			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63431		9327/17	23/03/2018	WH Stephens
#REF!	SHA	Drumalane Estate	04			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63432		9327/17	23/03/2018	WH Stephens
#REF!	SHA	Drumalane Estate	04			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63433		9327/17	23/03/2018	WH Stephens
#REF!	SHA	Drumalane Estate	04			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63434		9327/17	23/03/2018	WH Stephens
#REF!	SHA	Drumalane Estate	04			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63435		9327/17	23/03/2018	WH Stephens
#REF!	SHA	Drumalane Estate	04			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63436		9327/17	23/03/2018	WH Stephens
#REF!	SHA	Drumalane Estate	04			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63437		9327/17	23/03/2018	WH Stephens
#REF!	SHA	Drumalane Estate	04			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63438		9327/17	23/03/2018	WH Stephens
#REF!	SHA	Drumalane Estate	04			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63439		9327/17	23/03/2018	WH Stephens
#REF!	SHA	Drumalane Estate	04			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63440		9327/17	23/03/2018	WH Stephens
#REF!	SHA	Drumalane Estate	04			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63441		9327/17	23/03/2018	WH Stephens
#REF!	SHA	Drumalane Estate	04			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63442		9327/17	23/03/2018	WH Stephens
#REF!	SHA	Drumalane Estate	04			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63443		9327/17	23/03/2018	WH Stephens
#REF!	SHA	Drumalane Estate	04			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63444		9327/17	23/03/2018	WH Stephens
#REF!	SHA	Drumalane Estate	04			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63445		9327/17	23/03/2018	WH Stephens
#REF!	SHA	Drumalane Estate	04			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63446		9327/17	23/03/2018	WH Stephens
#REF!	SHA	Drumalane Estate	04			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63447		9327/17	23/03/2018	WH Stephens
#REF!	SHA	Drumalane Estate	04			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63448		9327/17	23/03/2018	WH Stephens
#REF!	SHA	Drumalane Estate	04			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63449		9327/17	23/03/2018	WH Stephens
#REF!	SHA	Drumalane Estate	04			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63450		9327/17	23/03/2018	WH Stephens
#REF!	SHA	Drumalane Estate	04			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63451		9327/17	23/03/2018	WH Stephens
#REF!	SHA	Drumalane Estate	04			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63452		9327/17	23/03/2018	WH Stephens
#REF!	SHA	Drumalane Estate	04			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63453		9327/17	23/03/2018	WH Stephens
#REF!	SHA	Drumalane Estate	04			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63454		9327/17	23/03/2018	WH Stephens
#REF!	SHA	Drumalane Estate	04	Wall Panels	Insulating Board	Amosite/Chrysotile	Encapsulated Spray or	High	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	Medium Risk	8	14/12/2022	Identified	High Risk	63455	A73559	9300.2	30/08/2022	WHS
#REF!	SHA	Drumalane Estate	04			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked		0			No Asbestos Detected	63456		9327/17	23/03/2018	WH Stephens
#REF!	SHA	Drumalane Estate	04	Wall Panels	Insulating Board	Amosite/Chrysotile	Encapsulated Spray or Lacoino/Unsealed AIB	Medium	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	Medium Risk	8	14/12/2022	Strongly Presumed	High Risk	63457	A73559-E	9300.2	30/08/2022	WHS
#REF!	SHA	Drumalane Estate	04			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63458		9327/17	23/03/2018	WH Stephens
#REF!	SHA	Drumalane Estate	04			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63459		9327/17	23/03/2018	WH Stephens
#REF!	SHA	Drumalane Estate	04	Fire Break Panel	Insulating Board	NO ASBESTOS	Encapsulated Spray or Lacoino/Unsealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Presumed	No Asbestos Detected	63460	A73558	9327/17	23/03/2018	WH Stephens
#REF!	SHA	Drumalane Estate	04	Undercloaks to Verges	Cement Products	Presumed Asbestos	Composite Materials	Low	Manage and monitor	Re-inspection	HSG227	Checked	High Risk	5	14/09/2023	Strongly Presumed	Very Low Risk	63461		9300.2	30/08/2022	WHS
#REF!	SHA	Drumalane Estate	04			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63462		9327/17	23/03/2018	WH Stephens
#REF!	SHA	Drumalane Estate	04			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63463		9327/17	23/03/2018	WH Stephens
#REF!	SHA	Drumalane Estate	04			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63464		9327/17	23/03/2018	WH Stephens
#REF!	SHA	Drumalane Estate	04			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63465		9327/17	23/03/2018	WH Stephens
#REF!	SHA	Drumalane Estate	04			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63466		9327/17	23/03/2018	WH Stephens
#REF!	SHA	Drumalane Estate	04			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63467		9327/17	23/03/2018	WH Stephens
#REF!	SHA	Drumalane Estate	04			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63468		9327/17	23/03/2018	WH Stephens
#REF!	SHA	Drumalane Estate	04			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63469		9327/17	23/03/2018	WH Stephens
#REF!	SHA	Drumalane Estate	04			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63470		9327/17	23/03/2018	WH Stephens
#REF!	SHA	Drumalane Estate	04			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63471		9327/17	23/03/2018	WH Stephens
#REF!	SHA	Drumalane Estate	04			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63472		9327/17	23/03/2018	WH Stephens
#REF!	SHA	Drumalane Estate	04			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63473		9327/17	23/03/2018	WH Stephens
#REF!	SHA	Drumalane Estate	04			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63474		9327/17	23/03/2018	WH Stephens
#REF!	SHA	Drumalane Estate	04			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63475		9327/17	23/03/2018	WH Stephens
#REF!	SHA	Drumalane Estate	04			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63476		9327/17	23/03/2018	WH Stephens
#REF!	SHA	Drumalane Estate	04			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63477		9327/17	23/03/2018	WH Stephens
#REF!	SHA	Drumalane Estate	04			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63478		9327/17	23/03/2018	WH Stephens
#REF!	SHA	Drumalane Estate	04			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63479		9327/17	23/03/2018	WH Stephens
#REF!	SHA	Drumalane Estate	04			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63480		9327/17	23/03/2018	WH Stephens
#REF!	SHA	Drumalane Estate	04			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63481		9327/17	23/03/2018	WH Stephens
#REF!	SHA	Drumalane Estate	04			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63482		9327/17	23/03/2018	WH Stephens
#REF!	SHA	Drumalane Estate	04			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63483		9327/17	23/03/2018	WH Stephens
#REF!	SHA	Drumalane Estate	04			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63484		9327/17	23/03/2018	WH Stephens
#REF!	SHA	Drumalane Estate	04			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63485		9327/17	23/03/2018	WH Stephens

#REF!	SHA	Drumalane Estate	04				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	63486		9327/17	23/03/2018	WH Stephens
#REF!	SHA	Drumalane Estate	04				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	63487		9327/17	23/03/2018	WH Stephens
#REF!	SHA	Drumalane Estate	04				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	63488		9327/17	23/03/2018	WH Stephens
#REF!	SHA	Drumalane Estate	04				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	63489		9327/17	23/03/2018	WH Stephens
#REF!	SHA	Drumalane Estate	04				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	63490		9327/17	23/03/2018	WH Stephens
#REF!	SHA	Drumalane Estate	04				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	63491		9327/17	23/03/2018	WH Stephens
#REF!	SHA	Drumalane Estate	04				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	63492		9327/17	23/03/2018	WH Stephens
#REF!	SHA	Drumalane Estate	04				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	63493		9327/17	23/03/2018	WH Stephens
#REF!	SHA	Drumalane Estate	04				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	63494		9327/17	23/03/2018	WH Stephens
#REF!	SHA	Drumalane Estate	04				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	63495		9327/17	23/03/2018	WH Stephens
#REF!	SHA	Drumalane Estate	04				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	63496		9327/17	23/03/2018	WH Stephens
#REF!	SHA	Drumalane Estate	04				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	63497		9327/17	23/03/2018	WH Stephens
#REF!	SHA	Drumalane Estate	04				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	63498		9327/17	23/03/2018	WH Stephens
#REF!	SHA	Drumalane Estate	04				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	63499		9327/17	23/03/2018	WH Stephens
#REF!	SHA	Drumalane Estate	04				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	63500		9327/17	23/03/2018	WH Stephens
#REF!	SHA	Drumalane Estate	04				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	63501		9327/17	23/03/2018	WH Stephens
#REF!	SHA	Drumalane Estate	04				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	63502		9327/17	23/03/2018	WH Stephens
#REF!	SHA	Drumalane Estate	04				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	63503		9327/17	23/03/2018	WH Stephens
#REF!	SHA	Drumalane Estate	04				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	63504		9327/17	23/03/2018	WH Stephens
#REF!	SHA	Drumalane Estate	04				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	63505		9327/17	23/03/2018	WH Stephens
#REF!	SHA	Drumalane Estate	04				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	63506		9327/17	23/03/2018	WH Stephens
#REF!	SHA	Drumalane Estate	04				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	63507		9327/17	23/03/2018	WH Stephens
#REF!	SHA	Drumalane Estate	04				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	63508		9327/17	23/03/2018	WH Stephens
#REF!	SHA	Drumalane Estate	04				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	63509		9327/17	23/03/2018	WH Stephens
#REF!	SHA	Drumalane Estate	04				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	63510		9327/17	23/03/2018	WH Stephens
#REF!	SHA	Drumalane Estate	04				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	63511		9327/17	23/03/2018	WH Stephens
#REF!	SHA	Drumalane Estate	04				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	63512		9327/17	23/03/2018	WH Stephens
#REF!	SHA	Drumalane Estate	04				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	63513		9327/17	23/03/2018	WH Stephens
#REF!	SHA	Drumalane Estate	04				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	63514		9327/17	23/03/2018	WH Stephens
#REF!	SHA	Drumalane Estate	04				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	63515		9327/17	23/03/2018	WH Stephens
#REF!	SHA	Drumalane Estate	04				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	63516		9327/17	23/03/2018	WH Stephens
#REF!	SHA	Drumalane Estate	04				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	63517		9327/17	23/03/2018	WH Stephens
#REF!	SHA	Drumalane Estate	04				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	63518		9327/17	23/03/2018	WH Stephens
#REF!	SHA	Drumalane Estate	04				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	63519		9327/17	23/03/2018	WH Stephens
#REF!	SHA	Drumalane Estate	04				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	63520		9327/17	23/03/2018	WH Stephens
#REF!	SHA	Drumalane Estate	04				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	63521		9327/17	23/03/2018	WH Stephens
#REF!	SHA	Drumalane Estate	04				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	63522		9327/17	23/03/2018	WH Stephens
#REF!	SHA	Drumalane Estate	04				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	63523		9327/17	23/03/2018	WH Stephens
#REF!	SHA	Drumalane Estate	04				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	63524		9327/17	23/03/2018	WH Stephens
#REF!	SHA	Drumalane Estate	04				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	63525		9327/17	23/03/2018	WH Stephens
#REF!	SHA	Drumalane Estate	04				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	63526		9327/17	23/03/2018	WH Stephens
#REF!	SHA	Drumalane Estate	04	Wall Panels	Wall boarding around lift shaft in roofspace	Insulating Board	NO ASBESTOS	Encapsulated Spray or Lacoinin/Unsealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Identified	No Asbestos Detected	63527	SHA/11/02/16/06M S-E	9327/17	23/03/2018	WH Stephens
#REF!	SJC	Millview Resource Centre	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	63558		9327/17	22/04/2018	WH Stephens
#REF!	SJC	Millview Resource Centre	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	63559		9327/17	22/04/2018	WH Stephens
#REF!	SJC	Millview Resource Centre	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	63560		9327/17	22/04/2018	WH Stephens
#REF!	SJC	Millview Resource Centre	01	Sink / Drainer Pads		Rainforced Composities	NO ASBESTOS	Composite Materials	Medium	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Identified	No Asbestos Detected	63561	A73578	9327/17	22/04/2018	WH Stephens
#REF!	SJC	Millview Resource Centre	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	63562		9327/17	22/04/2018	WH Stephens
#REF!	SJC	Millview Resource Centre	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	63563		9327/17	22/04/2018	WH Stephens
#REF!	SJC	Millview Resource Centre	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	63564		9327/17	22/04/2018	WH Stephens
#REF!	SJC	Millview Resource Centre	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	63565		9327/17	22/04/2018	WH Stephens
#REF!	SJC	Millview Resource Centre	01	Sink Pad		Rainforced Composities	NO ASBESTOS	Composite Materials	High	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Identified	No Asbestos Detected	63566	A73579	9327/17	22/04/2018	WH Stephens
#REF!	SJC	Millview Resource Centre	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	63567		9327/17	22/04/2018	WH Stephens
#REF!	SJC	Millview Resource Centre	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	63568		9327/17	22/04/2018	WH Stephens
#REF!	SJC	Millview Resource Centre	01	Sink Pad		Rainforced Composities	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Identified	No Asbestos Detected	63569	A73580	9327/17	22/04/2018	WH Stephens
#REF!	SJC	Millview Resource Centre	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	63570		9327/17	22/04/2018	WH Stephens
#REF!	SJC	Millview Resource Centre	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	63571		9327/17	22/04/2018	WH Stephens
#REF!	SJC	Millview Resource Centre	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	63572		9327/17	22/04/2018	WH Stephens
#REF!	SJC	Millview Resource Centre	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	63573		9327/17	22/04/2018	WH Stephens
#REF!	SJC	Millview Resource Centre	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	63574		9327/17	22/04/2018	WH Stephens
#REF!	SJC	Millview Resource Centre	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	63575		9327/17	22/04/2018	WH Stephens
#REF!	SJC	Millview Resource Centre	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	63576		9327/17	22/04/2018	WH Stephens
#REF!	SJC	Millview Resource Centre	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	63577		9327/17	22/04/2018	WH Stephens
#REF!	SJC	Millview Resource Centre	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	63578		9327/17	22/04/2018	WH Stephens
#REF!	SJC	Millview Resource Centre	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	63579		9327/17	22/04/2018	WH Stephens
#REF!	SJC	Millview Resource Centre	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	63580		9327/17	22/04/2018	WH Stephens
#REF!	SJC	Millview Resource Centre	01	Boarding to back of trap door		Rainforced Composities	NO ASBESTOS	Enclosed Spray or Lacoinin/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Identified	No Asbestos Detected	63581	A73581	9327/17	22/04/2018	WH Stephens
#REF!	SJB	Needham House	01	Resins	Kitchen worktop	Rainforced Composities	NO ASBESTOS	Composite Materials	None	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Asbestos Removed	63624	A62992	9327/17	23/04/2018	WH Stephens
#REF!	SJB	Needham House	01		FLOOR		NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	63625	A62993	9327/17	23/04/2018	WH Stephens
#REF!	SJB	Needham House	01	Resins	kitchen unit	Rainforced Composities	NO ASBESTOS	Composite Materials	None	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Identified	Asbestos Removed	63626	A62994	9327/17	23/04/2018	WH Stephens
#REF!	SJB	Needham House	01		Pipework		NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	63627	A62996	9327/17	23/04/2018	WH Stephens
#REF!	SJB	Needham House	01		trap door		NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	63628	A62997	9327/17	23/04/2018	WH Stephens
#REF!	SJB	Needham House	01		Board under water tank		NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	63629	A62998	9327/17	23/04/2018	WH Stephens
#REF!	SJB	Needham House	01		Finelining within roofspace	Cement Products	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	63630	A62999	9327/17	23/04/2018	WH Stephens

#REF!	SJB	Needham House	01		fanlight above door		NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63631	A63000	932717	23/04/2018	WH Stephens
#REF!	SJB	Needham House	01		ceiling, fireline board to trap door	Cement Products	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63632	A63000	932717	23/04/2018	WH Stephens
#REF!	SJB	Needham House	01		Ceiling		NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63633	A69003	932717	23/04/2018	WH Stephens
#REF!	SJB	Needham House	01		ceiling		NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63634	A69004	932717	23/04/2018	WH Stephens
#REF!	SJB	Needham House	01				NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63635		932717	23/04/2018	WH Stephens
#REF!	SJB	Needham House	01				NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63636		932717	23/04/2018	WH Stephens
#REF!	SJB	Needham House	01				NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63637		932717	23/04/2018	WH Stephens
#REF!	SJB	Needham House	01				NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63638		932717	23/04/2018	WH Stephens
#REF!	SJB	Needham House	01				NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63639		932717	23/04/2018	WH Stephens
#REF!	SJB	Needham House	01				NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63640		932717	23/04/2018	WH Stephens
#REF!	SJB	Needham House	01				NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63641		932717	23/04/2018	WH Stephens
#REF!	SJB	Needham House	01				NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63642		932717	23/04/2018	WH Stephens
#REF!	SJB	Needham House	01				NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63643		932717	23/04/2018	WH Stephens
#REF!	SJB	Needham House	01				NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63644		932717	23/04/2018	WH Stephens
#REF!	SJB	Needham House	01				NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63645		932717	23/04/2018	WH Stephens
#REF!	SJB	Needham House	01				NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63646		932717	23/04/2018	WH Stephens
#REF!	SJB	Needham House	01				NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63647		932717	23/04/2018	WH Stephens
#REF!	SJB	Needham House	01				NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63648		932717	23/04/2018	WH Stephens
#REF!	SJB	Needham House	01				NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63649		932717	23/04/2018	WH Stephens
#REF!	SJB	Needham House	01				NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63650		932717	23/04/2018	WH Stephens
#REF!	SJB	Needham House	01				NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63651		932717	23/04/2018	WH Stephens
#REF!	SJB	Needham House	01				NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63652		932717	23/04/2018	WH Stephens
#REF!	SJB	Needham House	01				NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63653		932717	23/04/2018	WH Stephens
#REF!	SJB	Needham House	01				NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63654		932717	23/04/2018	WH Stephens
#REF!	SJB	Needham House	01				NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63655		932717	23/04/2018	WH Stephens
#REF!	SJB	Needham House	01				NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63656		932717	23/04/2018	WH Stephens
#REF!	SJB	Needham House	01				NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63657		932717	23/04/2018	WH Stephens
#REF!	SJB	Needham House	01				NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63658		932717	23/04/2018	WH Stephens
#REF!	SJB	Needham House	01				NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63659		932717	23/04/2018	WH Stephens
#REF!	SJB	Needham House	01				NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63660		932717	23/04/2018	WH Stephens
#REF!	SJB	Needham House	01				NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63661		932717	23/04/2018	WH Stephens
#REF!	SJB	Needham House	01		Verge to roof		NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63662	A69006	932717	23/04/2018	WH Stephens
#REF!	SJB	Needham House	01				NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63663		932717	23/04/2018	WH Stephens
#REF!	SJB	Needham House	01				NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63664		932717	23/04/2018	WH Stephens
#REF!	SJB	Needham House	01				NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63665		932717	23/04/2018	WH Stephens
#REF!	SJB	Needham House	01				NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63666		932717	23/04/2018	WH Stephens
#REF!	SJB	Needham House	01				NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63667		932717	23/04/2018	WH Stephens
#REF!	SJB	Needham House	01				NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63668		932717	23/04/2018	WH Stephens
#REF!	SJB	Needham House	01				NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63669		932717	23/04/2018	WH Stephens
#REF!	SJB	Needham House	01				NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63670		932717	23/04/2018	WH Stephens
#REF!	SJB	Needham House	01				NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63671		932717	23/04/2018	WH Stephens
#REF!	SJB	Needham House	01				NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63672		932717	23/04/2018	WH Stephens
#REF!	SJB	Needham House	01		Stair nosing		NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63673	A62995	932717	23/04/2018	WH Stephens
#REF!	SJB	Needham House	01		Verge board		NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63674	A69005	932717	23/04/2018	WH Stephens
#REF!	SJB	Needham House	01				NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63675	A62995	932717	23/04/2018	WH Stephens
#REF!	SJB	Needham House	01		fanlight above door		NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63678	A62002	932717	23/04/2018	WH Stephens
#REF!	SHA	Drumalane Estate	06	Ceiling Board		Insulating Board	Amosite/Chrysotile	Encased Spray or	Areas of Damage or		Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Medium Risk	7	14/03/2023	Presumed	Low Risk	63696		932717	30/08/2022	WHS
#REF!	SHA	Drumalane Estate	06	Ceiling Board		Insulating Board	Amosite/Chrysotile	Encased Spray or	Low		Conduct annual routine inspections	Re-inspection	HSG227	Checked	High Risk	6	14/12/2022	Strongly Presumed	High Risk	63697		932717	30/08/2022	WHS
#REF!	SHA	Drumalane Estate	06	Ceiling Board		Insulating Board	Amosite/Chrysotile	Encased Spray or	Low		Label & Manage	Re-inspection	HSG227	Unchecked	Low Risk	6	14/09/2023	Strongly Presumed	Low Risk	63698		932717	30/08/2022	WHS
#REF!	SBD	Newtownhamilton Health Centre	01				NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63700		932717	04/04/2018	WHS
#REF!	SBD	Newtownhamilton Health Centre	01	Biege Floor Tiles	floor covering	Reinforced Composites	NO ASBESTOS	Composite Materials	Low		No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	Asbestos Removed	63701	A72392	932717	04/04/2018	WHS
#REF!	SBD	Newtownhamilton Health Centre	01				NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63702		932717	04/04/2018	WHS
#REF!	SBD	Newtownhamilton Health Centre	01				NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63703		932717	04/04/2018	WHS
#REF!	SBD	Newtownhamilton Health Centre	01				NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63704		932717	04/04/2018	WHS
#REF!	SBD	Newtownhamilton Health Centre	01				NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63705		932717	04/04/2018	WHS
#REF!	SBD	Newtownhamilton Health Centre	01				NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63706		932717	04/04/2018	WHS
#REF!	SBD	Newtownhamilton Health Centre	01				NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63707		932717	04/04/2018	WHS
#REF!	SBD	Newtownhamilton Health Centre	01				NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63708		932717	04/04/2018	WHS
#REF!	SBD	Newtownhamilton Health Centre	01				NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63709		932717	04/04/2018	WHS
#REF!	SBD	Newtownhamilton Health Centre	01				NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63710		932717	04/04/2018	WHS
#REF!	SBD	Newtownhamilton Health Centre	01				NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63711		932717	04/04/2018	WHS
#REF!	SBD	Newtownhamilton Health Centre	01				NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63712		932717	04/04/2018	WHS
#REF!	SBD	Newtownhamilton Health Centre	01				NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63713		932717	04/04/2018	WHS
#REF!	SBD	Newtownhamilton Health Centre	01				NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63714		932717	04/04/2018	WHS
#REF!	SBD	Newtownhamilton Health Centre	01	Grey Floor Tiles		Reinforced Composites	NO ASBESTOS	Composite Materials	Low		No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	Asbestos Removed	63715	A72403	932717	04/04/2018	WHS
#REF!	SBD	Newtownhamilton Health Centre	01				NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63716		932717	04/04/2018	WHS
#REF!	SBD	Newtownhamilton Health Centre	01				NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63717		932717	04/04/2018	WHS
#REF!	SBD	Newtownhamilton Health Centre	01	Toilet Cistern		Reinforced Composites	NO ASBESTOS	Composite Materials	Low		No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	63718	A72402	932717	04/04/2018	WHS
#REF!	SBD	Newtownhamilton Health Centre	01	Grey Floor Tiles		Reinforced Composites	NO ASBESTOS	Composite Materials	Low		No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	Asbestos Removed	63719	A72401	932717	04/04/2018	WHS
#REF!	SBD	Newtownhamilton Health Centre	01	Green Floor Tiles		Reinforced Composites	NO ASBESTOS	Composite Materials	Low		No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	Asbestos Removed	63720	A72400	932717	04/04/2018	WHS
#REF!	SBD	Newtownhamilton Health Centre	01	Fawn Floor Tiles		Reinforced Composites	NO ASBESTOS	Composite Materials	Low		No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	Asbestos Removed	63721	A72398	932717	04/04/2018	WHS
#REF!	SBD	Newtownhamilton Health Centre	01	Light Grey Floor Tiles		Reinforced Composites	NO ASBESTOS	Composite Materials	Low		No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	Asbestos Removed	63722	A72390	932717	04/04/2018	WHS
#REF!	SBD	Newtownhamilton Health Centre	01				NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63723		932717	04/04/2018	WHS
#REF!	SBD	Newtownhamilton Health Centre	01				NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63724		932717	04/04/2018	WHS

#REF!	SBD	Newtownhamilton Health Centre	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	63725		9327/17	04/04/2018	WHS
#REF!	SBD	Newtownhamilton Health Centre	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	63726		9327/17	04/04/2018	WHS
#REF!	SJF	Shanlieve House	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	63727		9327/17	23/04/2018	WH Stephens
#REF!	SAA	Daisy Hill Hospital Estate	25			NO ASBESTOS			No further action required (No Asbestos Detected)	Original Survey Data	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	63794				
#REF!	SAA	Daisy Hill Hospital Estate	25			NO ASBESTOS			No further action required (No Asbestos Detected)	Original Survey Data	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	63795				
#REF!	SAA	Daisy Hill Hospital Estate	25			NO ASBESTOS			No further action required (No Asbestos Detected)	Original Survey Data	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	63796				
#REF!	SAA	Daisy Hill Hospital Estate	25			NO ASBESTOS			No further action required (No Asbestos Detected)	Original Survey Data	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	63797				
#REF!	SAA	Daisy Hill Hospital Estate	25			NO ASBESTOS			No further action required (No Asbestos Detected)	Original Survey Data	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	63798				
#REF!	SJF	Shanlieve House	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	63799		9327/17	23/04/2018	WH Stephens
#REF!	SJF	Shanlieve House	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	63800		9327/17	23/04/2018	WH Stephens
#REF!	SJF	Shanlieve House	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	63801		9327/17	23/04/2018	WH Stephens
#REF!	SJF	Shanlieve House	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	63802		9327/17	23/04/2018	WH Stephens
#REF!	SJF	Shanlieve House	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	63803		9327/17	23/04/2018	WH Stephens
#REF!	SJF	Shanlieve House	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	63804		9327/17	23/04/2018	WH Stephens
#REF!	SJF	Shanlieve House	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	63805		9327/17	23/04/2018	WH Stephens
#REF!	SJF	Shanlieve House	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	63806		9327/17	23/04/2018	WH Stephens
#REF!	SJF	Shanlieve House	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	63807		9327/17	23/04/2018	WH Stephens
#REF!	SJF	Shanlieve House	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	63808		9327/17	23/04/2018	WH Stephens
#REF!	SJF	Shanlieve House	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	63809		9327/17	23/04/2018	WH Stephens
#REF!	SJF	Shanlieve House	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	63810		9327/17	23/04/2018	WH Stephens
#REF!	SJF	Shanlieve House	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	63811		9327/17	23/04/2018	WH Stephens
#REF!	SJF	Shanlieve House	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	63812		9327/17	23/04/2018	WH Stephens
#REF!	SJF	Shanlieve House	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	63813		9327/17	23/04/2018	WH Stephens
#REF!	SJF	Shanlieve House	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	63814		9327/17	23/04/2018	WH Stephens
#REF!	SJF	Shanlieve House	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	63815		9327/17	23/04/2018	WH Stephens
#REF!	SJF	Shanlieve House	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	63816		9327/17	23/04/2018	WH Stephens
#REF!	SJF	Shanlieve House	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	63817		9327/17	23/04/2018	WH Stephens
#REF!	SJF	Shanlieve House	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	63818		9327/17	23/04/2018	WH Stephens
#REF!	SJF	Shanlieve House	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	63819		9327/17	23/04/2018	WH Stephens
#REF!	SJF	Shanlieve House	01	SINK / DRAINER PADS	Reinforced Composites	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Identified	No Asbestos Detected	63820	A74222	9327/17	23/04/2018	WH Stephens
#REF!	SJF	Shanlieve House	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	63821		9327/17	23/04/2018	WH Stephens
#REF!	SJF	Shanlieve House	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	63822		9327/17	23/04/2018	WH Stephens
#REF!	SJF	Shanlieve House	01		Insulating Board	NO ASBESTOS	Encapsulated Spray or Lagging/Unsealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Identified	No Asbestos Detected	63823	A74223	9327/17	23/04/2018	WH Stephens
#REF!	SJF	Shanlieve House	02			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	63824		9327/17	23/04/2018	WH Stephens
#REF!	SJF	Shanlieve House	02			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	63825		9327/17	23/04/2018	WH Stephens
#REF!	SJF	Shanlieve House	02			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	63826		9327/17	23/04/2018	WH Stephens
#REF!	SJF	Shanlieve House	02			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	63827		9327/17	23/04/2018	WH Stephens
#REF!	SJF	Shanlieve House	02			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	63828		9327/17	23/04/2018	WH Stephens
#REF!	SJF	Shanlieve House	02			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	63829		9327/17	23/04/2018	WH Stephens
#REF!	SJF	Shanlieve House	02			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	63830		9327/17	23/04/2018	WH Stephens
#REF!	SJF	Shanlieve House	02			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	63831		9327/17	23/04/2018	WH Stephens
#REF!	SJF	Shanlieve House	02			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	63832		9327/17	23/04/2018	WH Stephens
#REF!	SJF	Shanlieve House	02	SINK / DRAINER PADS	Reinforced Composites	NO ASBESTOS	Composite Materials	Medium	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Identified	No Asbestos Detected	63833	A74224	9327/17	23/04/2018	WH Stephens
#REF!	SJF	Shanlieve House	02			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	63834		9327/17	23/04/2018	WH Stephens
#REF!	SJF	Shanlieve House	02			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	63835		9327/17	23/04/2018	WH Stephens
#REF!	SJF	Shanlieve House	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	63836		9327/17	23/04/2018	WH Stephens
#REF!	SJF	Shanlieve House	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	63837		9327/17	23/04/2018	WH Stephens
#REF!	SJF	Shanlieve House	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	63838		9327/17	23/04/2018	WH Stephens
#REF!	SJF	Shanlieve House	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	63839		9327/17	23/04/2018	WH Stephens
#REF!	SAA	Daisy Hill Hospital Estate	24			NO ASBESTOS			No further action required (No Asbestos Detected)	Original Survey Data	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	63903				
#REF!	SAA	Daisy Hill Hospital Estate	24			NO ASBESTOS			No further action required (No Asbestos Detected)	Original Survey Data	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	63904				
#REF!	SAA	Daisy Hill Hospital Estate	24			NO ASBESTOS			No further action required (No Asbestos Detected)	Original Survey Data	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	63905				
#REF!	SAA	Daisy Hill Hospital Estate	24			NO ASBESTOS			No further action required (No Asbestos Detected)	Original Survey Data	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	63906				
#REF!	SAA	Daisy Hill Hospital Estate	24			NO ASBESTOS			No further action required (No Asbestos Detected)	Original Survey Data	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	63907				
#REF!	SAA	Daisy Hill Hospital Estate	24			NO ASBESTOS			No further action required (No Asbestos Detected)	Original Survey Data	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	63908				
#REF!	SAA	Daisy Hill Hospital Estate	24			NO ASBESTOS			No further action required (No Asbestos Detected)	Original Survey Data	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	63909				
#REF!	SAA	Daisy Hill Hospital Estate	24			NO ASBESTOS			No further action required (No Asbestos Detected)	Original Survey Data	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	63910				
#REF!	SAA	Daisy Hill Hospital Estate	24			NO ASBESTOS			No further action required (No Asbestos Detected)	Original Survey Data	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	63911				
#REF!	SAA	Daisy Hill Hospital Estate	24			NO ASBESTOS			No further action required (No Asbestos Detected)	Original Survey Data	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	63912				
#REF!	SAA	Daisy Hill Hospital Estate	24			NO ASBESTOS			No further action required (No Asbestos Detected)	Original Survey Data	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	63913				
#REF!	SAA	Daisy Hill Hospital Estate	24			NO ASBESTOS			No further action required (No Asbestos Detected)	Original Survey Data	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	63914				
#REF!	SAA	Daisy Hill Hospital Estate	24			NO ASBESTOS			No further action required (No Asbestos Detected)	Original Survey Data	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	63915				
#REF!	SAA	Daisy Hill Hospital Estate	24			NO ASBESTOS			No further action required (No Asbestos Detected)	Original Survey Data	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	63916				
#REF!	SAA	Daisy Hill Hospital Estate	24			NO ASBESTOS			No further action required (No Asbestos Detected)	Original Survey Data	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	63917				
#REF!	SAA	Daisy Hill Hospital Estate	24			NO ASBESTOS			No further action required (No Asbestos Detected)	Original Survey Data	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	63918				
#REF!	SAA	Daisy Hill Hospital Estate	24			NO ASBESTOS			No further action required (No Asbestos Detected)	Original Survey Data	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	63920				
#REF!	SAA	Daisy Hill Hospital Estate	24			NO ASBESTOS			No further action required (No Asbestos Detected)	Original Survey Data	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	63921				
#REF!	SAA	Daisy Hill Hospital Estate	24			NO ASBESTOS			No further action required (No Asbestos Detected)	Original Survey Data	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	63922				
#REF!	SAA	Daisy Hill Hospital Estate	24			NO ASBESTOS			No further action required (No Asbestos Detected)	Original Survey Data	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	63923				
#REF!	SAA	Daisy Hill Hospital Estate	24			NO ASBESTOS			No further action required (No Asbestos Detected)	Original Survey Data	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	63924				
#REF!	SAA	Daisy Hill Hospital Estate	24			NO ASBESTOS			No further action required (No Asbestos Detected)	Original Survey Data	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	63925				
#REF!	SAA	Daisy Hill Hospital Estate	24			NO ASBESTOS			No further action required (No Asbestos Detected)	Original Survey Data	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	63926				
#REF!	SAA	Daisy Hill Hospital Estate	24			NO ASBESTOS			No further action required (No Asbestos Detected)	Original Survey Data	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	63927				

#REF!	SAA	Daisy Hill Hospital Estate	24				NO ASBESTOS			No further action required (No Asbestos Detected)	Original Survey Data	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63929				
#REF!	SAA	Daisy Hill Hospital Estate	24				NO ASBESTOS			No further action required (No Asbestos Detected)	Original Survey Data	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63930				
#REF!	SAA	Daisy Hill Hospital Estate	24				NO ASBESTOS			No further action required (No Asbestos Detected)	Original Survey Data	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63931				
#REF!	SAA	Daisy Hill Hospital Estate	24				NO ASBESTOS			No further action required (No Asbestos Detected)	Original Survey Data	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63932				
#REF!	SAA	Daisy Hill Hospital Estate	24				NO ASBESTOS			No further action required (No Asbestos Detected)	Original Survey Data	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63933				
#REF!	SAA	Daisy Hill Hospital Estate	24				NO ASBESTOS			No further action required (No Asbestos Detected)	Original Survey Data	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63934				
#REF!	SAA	Daisy Hill Hospital Estate	24				NO ASBESTOS			No further action required (No Asbestos Detected)	Original Survey Data	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	63935				
#REF!	SAA	Daisy Hill Hospital Estate	18				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64031		9327/17	17/04/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	18	Soffit Boards		Cement Products	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	64032	A74333	9327/17	17/04/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	18				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64033		9327/17	17/04/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	14	Sink / Drainer Pads		Reinforced Composites	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	64034	A74335	9327/17	04/03/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	14				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64035		9327/17	04/03/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	14				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64036		9327/17	04/03/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	23				NO ASBESTOS			No further action required (No Asbestos Detected)	Original Survey Data	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64037				
#REF!	SAA	Daisy Hill Hospital Estate	23				NO ASBESTOS			No further action required (No Asbestos Detected)	Original Survey Data	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64038				
#REF!	SAA	Daisy Hill Hospital Estate	23				NO ASBESTOS			No further action required (No Asbestos Detected)	Original Survey Data	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64039				
#REF!	SAA	Daisy Hill Hospital Estate	19				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64040		9506/18	14/02/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	19				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64041		9506/18	14/02/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	19				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64042		9506/18	14/02/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	19				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64043		9506/18	14/02/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	19	Sink / Drainer Pads		Reinforced Composites	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	09/11/2023	Identified	Very Low Risk	64044	A74334	9506/18	01/06/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	19				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64045		9506/18	14/02/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	19				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64046		9506/18	14/02/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	19				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64047		9506/18	14/02/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	19				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64048		9506/18	14/02/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	17				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64049		9327/17	15/02/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	17				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64050		9327/17	15/02/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	11				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64056		9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	11				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64057		9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	11				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64058		9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	11				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64059		9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	11				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64060		9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	11				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64061		9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	11				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64062		9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	11				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64063		9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	11				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64064		9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	11	Floor Tiles	Floor	Reinforced Composites	NO ASBESTOS	Composite Materials	None	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	18/02/2011	Identified	Asbestos Removed	64065	A63939	9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	11	Board	Door	Cement Products	NO ASBESTOS	Enclosed Spray or Lagging/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	18/02/2011	Identified	Asbestos Removed	64066	A63941	9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	11	Floor Tiles	Floor	Reinforced Composites	NO ASBESTOS	Composite Materials	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	18/02/2011	Strongly Presumed	Asbestos Removed	64067	A63936	9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	11	Floor Tiles	Floor	Reinforced Composites	NO ASBESTOS	Composite Materials	None	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	18/02/2011	Identified	Asbestos Removed	64068	A63937	9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	11	Resins	Under kitchen sink	Reinforced Composites	NO ASBESTOS	Composite Materials	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	29/11/2019	Identified	Asbestos Removed	64069	A63938	9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	11	Floor Tiles	Floor	Reinforced Composites	NO ASBESTOS	Composite Materials	None	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	18/02/2011	Identified	Asbestos Removed	64070	A63936	9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	11	Floor Tiles	Floor	Reinforced Composites	NO ASBESTOS	Composite Materials	None	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	18/02/2011	Strongly Presumed	Asbestos Removed	64071	A63936	9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	11	Floor Tiles	Floor	Reinforced Composites	NO ASBESTOS	Composite Materials	None	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	18/02/2011	Strongly Presumed	Asbestos Removed	64072	A63939	9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	11	Floor Tiles	Floor within bedroom 009	Reinforced Composites	NO ASBESTOS	Composite Materials	None	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	18/02/2011	Strongly Presumed	Asbestos Removed	64073	A63936	9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	11	Floor Tiles	Floor	Reinforced Composites	NO ASBESTOS	Composite Materials	None	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	18/02/2011	Strongly Presumed	Asbestos Removed	64074	A63936	9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	11	Floor Tiles	Floor	Reinforced Composites	NO ASBESTOS	Composite Materials	None	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	18/02/2011	Strongly Presumed	Asbestos Removed	64075	A63936	9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	11	Floor Tiles	Floor	Reinforced Composites	NO ASBESTOS	Composite Materials	None	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	18/02/2011	Strongly Presumed	Asbestos Removed	64076	A63939	9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	11	Floor Tiles	Floor	Reinforced Composites	NO ASBESTOS	Composite Materials	None	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	18/02/2011	Strongly Presumed	Asbestos Removed	64077	A63939	9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	11	Floor Tiles	Floor	Reinforced Composites	NO ASBESTOS	Composite Materials	None	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	18/02/2011	Strongly Presumed	Asbestos Removed	64078	A63939	9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	11	Floor Tiles	Floor	Reinforced Composites	Chrysotile	Composite Materials	Low	Label and Remove if likely to be disturbed	Re-inspection	HSG227	Unchecked	Very Low Risk	3	15/09/2023	Strongly Presumed	Very Low Risk	64079	A63939	9309/2	22/04/2022	WHS
#REF!	SHB	Cloughreagh House	03				NO ASBESTOS				Review – No Change	HSG227	Unchecked	NO ASBESTOS	0				64080		9327/1	04/04/2018	WH Steohens
#REF!	SAA	Daisy Hill Hospital Estate	21							Re-Survey	Review – No Change	HSG227	Checked	High Risk	0				64201		9506/1	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	21							Re-Survey	Review – No Change	HSG227	Checked	High Risk	0				64206		9506/1	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	21							Re-Survey	Review – No Change	HSG227	Checked	High Risk	0				64209		9506/1	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	11	Board	Back side of entrance door	Cement Products	NO ASBESTOS	Enclosed Spray or Lagging/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	18/02/2011	Strongly Presumed	Asbestos Removed	64210	A63941	9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	21				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64211		9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	21				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64222		9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	21				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64231		9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	21				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64232		9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	21				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64233		9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	21				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64234		9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	21				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64235		9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	21				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64236		9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	21				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64237		9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	21				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64238		9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	21				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64239		9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	21							Re-Survey	Review – No Change	HSG227	Checked	High Risk	0			Very Low Risk	64240		9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	21				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64241		9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	21				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64242		9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	21				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64243		9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	21				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64244		9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	21				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64245		9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	21				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64246		9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	21				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64247		9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	21				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64248		9506/18	19/11/2018	WHS

#REF!	SAA	Daisy Hill Hospital Estate	21				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64249		9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	21				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64250		9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	21				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64251		9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	21				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64252		9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	21				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64253		9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	21				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64254		9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	21				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64255		9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	21				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64256		9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	21				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64257		9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	21				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64258		9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	21				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64259		9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	21				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64260		9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	21				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64261		9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	21				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64262		9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	21				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64263		9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	21				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64264		9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	21				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64265		9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	21				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64266		9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	11	Floor Tiles	Floor	Reinforced Composites	NO ASBESTOS	Composite Materials	None	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	18/02/2011	Identified	Asbestos Removed	64297	A63935	9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	11	Resins	Under kitchen sink	Reinforced Composites	NO ASBESTOS	Composite Materials	None	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed	Asbestos Removed	64298	A63942	9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	11	Floor Tiles	Floor	Reinforced Composites	NO ASBESTOS	Composite Materials	None	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	18/02/2011	Strongly Presumed	Asbestos Removed	64302	A63937	9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	11	Floor Tiles	Floor	Reinforced Composites	NO ASBESTOS	Composite Materials	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	18/02/2011	Strongly Presumed	Asbestos Removed	64319	A63936	9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	11	Floor Tiles	Floor	Reinforced Composites	NO ASBESTOS	Composite Materials	None	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	18/02/2011	Identified	Asbestos Removed	64320	A63933	9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	11	Board	Entrance door	Cement Products	NO ASBESTOS	Enclosed Spray or Lagging/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	18/02/2011	Identified	Asbestos Removed	64321	A63941	9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	11	Floor Tiles	Floor	Reinforced Composites	NO ASBESTOS	Composite Materials	None	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	18/02/2011	Identified	Asbestos Removed	64322	A63930	9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	11	Floor Tiles	Floor	Reinforced Composites	NO ASBESTOS	Composite Materials	None	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	18/02/2011	Identified	Asbestos Removed	64323	A63929	9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	11	Floor Tiles	Floor	Reinforced Composites	Chrysotile	Composite Materials	Low	Label and Remove if likely to be disturbed	Re-inspection	HSG227	Unchecked	Very Low Risk	3	15/09/2023	Identified	Very Low Risk	64324	A63929	9300/22	22/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	11	Floor Tiles	Floor	Reinforced Composites	NO ASBESTOS	Composite Materials	None	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	18/02/2011	Identified	Asbestos Removed	64325	A63929	9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	11	Floor Tiles	Floor	Reinforced Composites	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	18/02/2011	Identified	Asbestos Removed	64326	A63929	9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	11	Floor Tiles	Floor	Reinforced Composites	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	15/09/2023	Identified	Very Low Risk	64327	A63929	9300/22	22/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	11	Floor Tiles	Floor	Reinforced Composites	NO ASBESTOS	Composite Materials	None	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	18/02/2011	Identified	Asbestos Removed	64328	A63929	9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	11	Board	Entrance door	Cement Products	NO ASBESTOS	Enclosed Spray or Lagging/Sealed AIB	Low	None	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	18/02/2011	Strongly Presumed	Asbestos Removed	64329	A63941	9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	11	Floor Tiles	Floor	Reinforced Composites	NO ASBESTOS	Composite Materials	None	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	18/02/2011	Identified	Asbestos Removed	64330	A63928	9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	11	Floor Tiles	Floor	Reinforced Composites	NO ASBESTOS	Composite Materials	None	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	18/02/2011	Strongly Presumed	Asbestos Removed	64331	A63928	9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	11	Resins	Under kitchen sink	Reinforced Composites	NO ASBESTOS	Composite Materials	None	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	Asbestos Removed	64332	A63927	9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	11	Resins	Under kitchen sink	Reinforced Composites	NO ASBESTOS	Composite Materials	None	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	29/11/2019	Strongly Presumed	Asbestos Removed	64333	A63927	9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	11	Floor Tiles	Floor	Reinforced Composites	NO ASBESTOS	Composite Materials	None	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	18/02/2011	Identified	Asbestos Removed	64334	A63925	9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	11	Floor Tiles	Floor	Reinforced Composites	NO ASBESTOS	Composite Materials	None	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	18/02/2011	Strongly Presumed	Asbestos Removed	64335	A63925	9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	11	Floor Tiles	Floor	Reinforced Composites	NO ASBESTOS	Composite Materials	None	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	18/02/2011	Strongly Presumed	Asbestos Removed	64336	A63925	9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	11	Floor Tiles	Floor	Reinforced Composites	NO ASBESTOS	Composite Materials	None	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	18/02/2011	Strongly Presumed	Asbestos Removed	64337	A63925	9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	11	Floor Tiles	Floor	Reinforced Composites	NO ASBESTOS	Composite Materials	None	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	18/02/2011	Identified	Asbestos Removed	64338	A63925	9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	11	Board	Door	Cement Products	NO ASBESTOS	Enclosed Spray or Lagging/Sealed AIB	Low	Re-Survey	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	18/02/2011	Identified	Asbestos Removed	64339	A63932	9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	11	Board	Roofspace trap door	Cement Products	NO ASBESTOS	Composite Materials	Medium	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	18/02/2011	Identified	Asbestos Removed	64340	A63931	9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	21				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64341		9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	21				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64342		9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	21				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64343		9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	21				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64344		9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	21				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64345		9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	21				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64346		9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	21				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64347		9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	21				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64348		9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	21				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64349		9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	21				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64350		9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	21				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64351		9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	21				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64352		9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	21				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64353		9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	21				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64354		9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	21				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64355		9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	21				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64356		9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	21				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64357		9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	21				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64358		9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	21				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64359		9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	21				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64360		9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	21				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64361		9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	21				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64362		9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	21				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64363		9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	21				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64364		9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	21				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64365		9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	21				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64366		9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	21				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64367		9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	21				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64368		9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	21				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64369		9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	21				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64370		9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	21				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64371		9506/18	19/11/2018	WHS

#REF!	SAA	Daisy Hill Hospital Estate	21			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64372		9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	21			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64373		9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	21			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64374		9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	21			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64375		9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	21			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64376		9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	21			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64377		9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	21			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64378		9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	21			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64379		9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	21			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64380		9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64381		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	Wall Panels	Insulating Board	NO ASBESTOS	Enclosed Spray or Lagging/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	64382	A74667	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64383		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64384		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64385		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64386		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64387		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64388		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64389		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64390		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64391		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64392		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64393		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64394		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64395		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64396		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64397		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64398		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	Sink Pad	Reinforced Composites	NO ASBESTOS	Composite Materials	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	21/05/2020	Identified	Asbestos Removed	64399	A74668	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64400		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64401		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64402		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64403		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64404		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64405		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	Sink Pad	Reinforced Composites	NO ASBESTOS	Composite Materials	Medium	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	21/05/2020	Strongly Presumed	Asbestos Removed	64406	A74668-E	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64407		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64408		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64409		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64410		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64411		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64412		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64413		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64414		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64415		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64416		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64417		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01						Re-Survey	Review – No Change	HSG227	Checked	Hidh Risk	0				64418		9506/1	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64419		9506/1A	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64420		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64421		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64422		9506/1A	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64423		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64424		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64425		9506/1A	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64426		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	11			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64427		9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64428		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64429		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64430		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64431		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64432		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64433		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64434		9506/1A	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64435		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64436		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64437		9506/1A	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64438		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64439		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64440		9506/1A	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64441		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64442		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64443		9506/1A	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64444		9506/18	20/03/2019	WHS

#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64445		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64446		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64447		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64448		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64449		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64450		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64451		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64452		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64453		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64454		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64455		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64456		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64457		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64458		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64459		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64460		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64461		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64462		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64463		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS				Re-Survey	Review – No Change	HSG227	Checked	High Risk	0				64464		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64465		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	11	Floor Tiles	Floor	Reinforced Composites	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	15/09/2023	Identified	Very Low Risk	64466	BS320435		9300/2	22/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	11	Floor Tiles	Floor	Reinforced Composites	Chrysotile	Composite Materials	Minor damage or deterioration	Label and Remove if likely to be disturbed	Re-inspection	HSG227	Unchecked	Very Low Risk	3	15/09/2023	Identified	Low Risk	64467	A63939		9300/22	22/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	11	Floor Tiles	Floor	Reinforced Composites	NO ASBESTOS	Composite Materials	None	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	18/02/2011	Strongly Presumed	Asbestos Removed	64468	A63936		9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	11	Floor Tiles	Floor	Reinforced Composites	NO ASBESTOS	Composite Materials	None	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	29/11/2019	Identified	Asbestos Removed	64469	A63929		9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64470		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64471		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64472		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64473		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64474		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64475		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64476		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64477		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64478		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64479		9506/1a	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64480		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64481		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64482		9506/1a	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64483		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64484		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64485		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64486		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64487		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64488		9506/1a	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64489		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64490		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64491		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS				Re-Survey	Review – No Change	HSG227	Checked	High Risk	0				64492		9506/1a	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	11	Soffit Boards	Roof eaves	Cement Products	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	15/09/2023	Presumed	Low Risk	64493			9300/22	22/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64494		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64495		9506/1a	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64496		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64497		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64498		9506/1a	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	11	Soffit Boards	Verge to roof	Cement Products	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	15/09/2023	Presumed	Low Risk	64499			9300/24	24/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64500		9506/1a	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64501		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64502		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64503		9506/1a	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64504		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64505		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64506		9506/1a	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64507		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64508		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64509		9506/1a	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64510		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64511		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64512		9506/1a	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64513		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64514		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64515		9506/1a	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64516		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64517		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64518		9506/1a	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64519		9506/18	20/03/2019	WHS

#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	64520		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	64521		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	64522		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	64523		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	64524		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	64525		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	64526		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	64527		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	64528		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	64529		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	64530		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	64531		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	64532		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01							Re-Survey	Review – No Change	HSG227	Checked	High Risk	0			64533		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	64534		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	64535		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	64536		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	64537		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	64538		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	64539		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	64540		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	64541		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	64542		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	64543		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	64544		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	64545		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	64546		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	64547		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	64548		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	64549		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	64550		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	64551		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	64552		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	64553		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	64554		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	64555		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	64556		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	64557		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	Wall Boards		Wall Board	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Identified	No Asbestos Detected	64558	A74670	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	64559		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	64560		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	64561		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	64562		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	64563		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	64564		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	64565		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	64566		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	64567		9506/1A	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	64568		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	64569		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	64570		9506/1A	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	64571		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	64572		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	64573		9506/1A	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	64574		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	64575		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	64576		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	64577		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	64578		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS				Review – No Change	HSG227	Checked	High Risk	0			64579		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	Wall Plaster	VERTICAL DUCT IN ESCAPE STAIRS	Plaster	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Identified	No Asbestos Detected	64580	A74669	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	64581		9506/1A	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	Wall Panels	WALL CLADDING TO TANK ROOM ON ROOF	Insulating Board	NO ASBESTOS	Encapsulated Spray or Lagging/Unsealed AIB	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Identified	Asbestos Removed	64582	05/10/10-004	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	64583		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	Wall Panels		Insulating Board	NO ASBESTOS	Encapsulated Spray or Lagging/Unsealed AIB	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Identified	Asbestos Removed	64584	05/10/10-006	9506/1A	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01							Re-Survey	Review – No Change	HSG227	Checked	High Risk	0			64585		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	64586		9506/1A	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	64587		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	64588		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	64589		9506/1A	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	64590		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	64591		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	64592		9506/1A	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	64593		9506/18	20/03/2019	WHS

#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64594		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64595		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64596		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64597		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64598		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64599		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64600		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64601		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64602		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64603		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64604		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64605		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64606		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64607		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64608		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64609		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64610		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64611		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64612		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01						Re-Survey	Review – No Change	HSG227	Checked	High Risk	0				64613		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64614		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64615		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64616		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64617		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64618		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	Sink Pads	Reinforced Composites	NO ASBESTOS	Composite Materials	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	21/05/2020	Identified	Asbestos Removed	64619	A74672	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64620		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64621		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64622		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64623		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64624		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64625		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64626		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64627		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64628		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64629		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64630		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64631		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64632		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64633		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64634		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64635		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64636		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64637		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64638		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64639		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64640		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64641		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64642		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64643		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64644		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64645		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64646		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64647		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64648		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64649		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64650		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64651		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64652		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01						Re-Survey	Review – No Change	HSG227	Checked	High Risk	0				64653		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64654		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64655		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64656		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64657		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64658		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64659		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64660		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64661		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64662		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64663		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64664		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64665		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	Sink Pad	Reinforced Composites	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed	No Asbestos Detected	64666	A74673	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64667		9506/18	20/03/2019	WHS

#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64668		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64669		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	Sink / Drainer Pads		Reinforced Composites	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	64670	A74673	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64671		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64672		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64673		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64674		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64675		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64676		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64677		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64678		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64679		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64680		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64681		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64682		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64683		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64684		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64685		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64686		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64687		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64688		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64689		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64690		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01							Re-Survey	Review – No Change	HSG227	Checked	High Risk	0				64691		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64692		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64693		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64694		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64695		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	12				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64696		9327/17	13/02/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	12				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64697		9327/17	13/02/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	12				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64698		9327/17	13/02/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	12				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64699		9327/17	13/02/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	12				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64700		9327/17	13/02/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	12				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64701		9327/17	13/02/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	12				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64702		9327/17	13/02/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	12	Floor Tiles	Floor	Reinforced Composites	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	21/09/2023	Identified	Low Risk	64703	BS320436	9327/17	22/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	12	Floor Tiles	Floor Tile	Reinforced Composites	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	21/09/2023	Identified	Low Risk	64704	A64180	9327/17	22/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	12	Resins	Floor tile	Reinforced Composites	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	21/09/2023	Presumed	Low Risk	64705		9327/17	22/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	12	Floor Tiles	Floor tile	Reinforced Composites	Chrysotile	Composite Materials	Pockets of damage o	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	4	21/09/2023	Strongly Presumed	Low Risk	64706	A64181	9327/17	27/07/2020	WHS
#REF!	SAA	Daisy Hill Hospital Estate	12	Floor Tiles	Floor	Reinforced Composites	Chrysotile	Composite Materials	None	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	2	21/09/2023	Identified	No Asbestos Detected	64707	A64181	9327/17	22/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	12				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64708		9327/17	13/02/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	12				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64709		9327/17	13/02/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	12				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64710		9327/17	13/02/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	12	Floor Tiles	Floor	Reinforced Composites	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	21/09/2023	Stronnlv Presumed	Low Risk	64711	A64184	9327/17	22/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	12	Resins	under kitchen sink	Reinforced Composites	NO ASBESTOS	Composite Materials	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	06/12/2019	Identified	Asbestos Removed	64712	A64182	9327/17	13/02/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	12				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64713		9327/17	13/02/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	12	Floor Tiles	Floor	Reinforced Composites	Chrysotile	Composite Materials	None	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	2	21/09/2023	Identified	Low Risk	64714	A64185	9327/17	22/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	12				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64715		9327/17	13/02/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	12	Floor Tiles	Floor	Reinforced Composites	Chrysotile	Composite Materials	None	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	2	21/09/2023	Stronnlv Presumed	Low Risk	64716	A64180	9327/17	22/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	12	Floor Tiles	Floor	Reinforced Composites	Chrysotile	Composite Materials	None	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	2	21/09/2023	Strongly Presumed	Low Risk	64717	A64184	9327/17	22/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	12	Floor Tiles	Floor	Reinforced Composites	Chrysotile	Composite Materials	None	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	2	21/09/2023	Strongly Presumed	Low Risk	64718	A64180	9327/17	22/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	12	Floor Tiles	Floor	Reinforced Composites	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	21/09/2023	Stronnlv Presumed	Low Risk	64719	A64184	9327/17	22/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	12	Floor Tiles	Floor	Reinforced Composites	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	21/09/2023	Strongly Presumed	Low Risk	64720	A64180	9327/17	22/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	12	Floor Tiles	Floor	Reinforced Composites	Chrysotile	Composite Materials	None	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	2	21/09/2023	Strongly Presumed	Low Risk	64721	A64184	9327/17	22/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	12	Floor Tiles	Floor	Reinforced Composites	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	21/09/2023	Stronnlv Presumed	Low Risk	64722	A64184	9327/17	22/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	12	Floor Tiles	Floor	Reinforced Composites	NO ASBESTOS	Composite Materials	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	06/12/2019	Identified	Asbestos Removed	64723	A64181	9327/17	13/02/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	12	Floor Tiles	Floor	Reinforced Composites	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	21/09/2023	Stronnlv Presumed	Low Risk	64724	A64181	9327/17	22/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	12	Floor Tiles	Floor	Reinforced Composites	Chrysotile	Composite Materials	None	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	2	21/09/2023	Strongly Presumed	Low Risk	64725	A64180	9327/17	22/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	12	Resins	Floor	Reinforced Composites	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	21/09/2023	Presumed	Low Risk	64726		9327/17	22/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	12	Floor Tiles	Floor	Reinforced Composites	Chrysotile	Composite Materials	None	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	2	21/09/2023	Stronnlv Presumed	Low Risk	64727	A64180	9327/17	22/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	12	Floor Tiles	Floor	Reinforced Composites	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	27/08/2021	Strongly Presumed	Low Risk	64728	A64181	9327/17	27/07/2020	WHS
#REF!	SAA	Daisy Hill Hospital Estate	12	Resins	Pad under sink	Reinforced Composites	NO ASBESTOS	Composite Materials	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	18/02/2011	Strongly Presumed	Asbestos Removed	64729	A64182	9327/17	13/02/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	12	Floor Tiles	Floor	Reinforced Composites	Chrysotile	Composite Materials	None	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	2	21/09/2023	Identified	Low Risk	64730	A64184	9327/17	22/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	12	Floor Tiles	Floor	Reinforced Composites	Chrysotile	Composite Materials	None	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	2	21/09/2023	Stronnlv Presumed	Low Risk	64731	A64184	9327/17	24/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	12	Floor Tiles	Floor	Reinforced Composites	Chrysotile	Composite Materials	None	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	2	21/09/2023	Stronnlv Presumed	Low Risk	64732	A64184	9327/17	22/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	12	Floor Tiles	Floor	Reinforced Composites	Chrysotile	Composite Materials	None	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	2	21/09/2023	Strongly Presumed	Low Risk	64733	A64184	9327/17	22/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	12	Floor Tiles	Floor	Reinforced Composites	Chrysotile	Composite Materials	None	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	2	21/09/2023	Stronnlv Presumed	Low Risk	64734	A64184	9327/17	22/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	12	Floor Tiles	Floor	Reinforced Composites	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	21/09/2023	Strongly Presumed	Low Risk	64735	A64184	9327/17	22/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	12	Floor Tiles	Floor	Reinforced Composites	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	21/09/2023	Strongly Presumed	Low Risk	64736	A64184	9327/17	22/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	12	Floor Tiles	Floor	Reinforced Composites	Chrysotile	Composite Materials	None	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	2	21/09/2023	Presumed	Low Risk	64737	A64180	9327/17	22/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	12	Floor Tiles	Floor	Reinforced Composites	Chrysotile	Composite Materials	None	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	2	21/09/2023	Presumed	Low Risk	64738	A64180	9327/17	22/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	12	Floor Tiles	Floor	Reinforced Composites	NO ASBESTOS	Composite Materials	None	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	06/12/2019	Presumed	Asbestos Removed	64739	A64180	9327/17	13/02/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	12	Floor Tiles	Floor	Reinforced Composites	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	21/09/2023	Presumed	Low Risk	64740	A64180	9327/17	22/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	12	Resins	Underside of kitchen sink	Reinforced Composites	Chrysotile	Composite Materials	High	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Low Risk	5	21/09/2023	Strongly Presumed	Low Risk	64741	A64182	9327/17	22/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	12	Floor Tiles	Floor	Reinforced Composites	NO ASBESTOS	Composite Materials	None	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed	Asbestos Removed	64742	A64181	9327/17	13/02/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	12	Resins	Floor	Reinforced Composites	NO ASBESTOS	Composite Materials	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	06/12/2019	Strongly Presumed	Asbestos Removed	64743		9327/17	13/02/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	12	Soffit Boards	Eaves/ Verge	Cement Products	Amosite/Chrysotile	Composite Materials	Very Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	4	21/09/2023	Presumed	Low Risk	64744		9327/17	22/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	12	Cement board	Verge to roof	Cement Products	Amosite/Chrysotile	Composite Materials	Very Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	4	21/09/2023	Presumed	Low Risk	64745		9327/17	22/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64746		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64747		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64748		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64749		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64750		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64751		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64752		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64753		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64754		9506/1A	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64755		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64756		9506/18	20/03/2019	WHS

#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	64757	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	64758	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	64759	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	64760	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	64761	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	64762	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	64763	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	64764	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	64765	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	64766	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	64767	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	64768	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	64769	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01		Re-Survey	Review – No Change	HSG227	Checked	High Risk	0		64770	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	64771	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	64772	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	64773	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	64774	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	64775	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	64776	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	64777	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	64778	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	64779	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	64780	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	64781	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	64782	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	64783	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	64784	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	64785	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	64786	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	64787	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	64788	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	64789	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	64790	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	64791	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	64792	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	64793	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	64794	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	64795	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	64796	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	64797	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	64798	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	64799	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	64800	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	64801	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01		Re-Survey	Review – No Change	HSG227	Checked	High Risk	0		64802	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	64803	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	64804	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	64805	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	64806	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	64807	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	64808	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	64809	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	64810	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	64811	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	64812	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	64813	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	64814	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	64815	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	64816	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	64817	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	64818	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	64819	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	64820	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	64821	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	64822	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	64823	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	64824	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	64825	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	64826	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	64827	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	64828	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	64829	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	64830	9506/18	20/03/2019	WHS

#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	64831	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	64832	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	64833	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	64834	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	64835	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	64836	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	64837	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01		Re-Survey	Review – No Change	HSG227	Checked	High Risk	0		64838	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	64839	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	64840	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	64841	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	64842	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	64843	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	64844	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	64845	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	64846	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	64847	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	64848	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	64849	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	64850	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	64851	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	64852	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	64853	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	64854	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	64855	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	64856	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	64857	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	64858	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	64859	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	64860	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	64861	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	64862	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	64863	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	64864	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01		Re-Survey	Review – No Change	HSG227	Checked	High Risk	0		64865	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	64866	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	64867	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Re-Survey	Review – No Change	HSG227	Checked	High Risk	0		64868	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	64869	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	64870	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	64871	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	64872	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	64873	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01		Re-Survey	Review – No Change	HSG227	Checked	High Risk	0		64874	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01		Re-Survey	Review – No Change	HSG227	Checked	High Risk	0		64875	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01		Re-Survey	Review – No Change	HSG227	Checked	High Risk	0		64876	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	64877	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	64878	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	64879	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	64880	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	64881	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	64882	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	64883	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	64884	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	64885	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	64886	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	64887	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	64888	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	64889	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	64890	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	64891	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	64892	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	64893	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	64894	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	64895	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	64896	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	64897	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	64898	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	64899	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	64900	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	64901	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01		Re-Survey	Review – No Change	HSG227	Checked	High Risk	0		64902	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	64903	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	64904	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01		Re-Survey	Review – No Change	HSG227	Checked	High Risk	0		64905	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	64906	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	64907	9506/18	20/03/2019	WHS

#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	64908		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	64909		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	64910		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	64911		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	64912		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	64913		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	64914		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	64915		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	64916		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	64917		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	64918		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	64919		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	64920		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	64921		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	64922		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	64923		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	64924		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	Sink Pad		Reinforced Composites	NO ASBESTOS	Composite Materials	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Identified	No Asbestos Detected	64925	A74674	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	64926		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	64927		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	64928		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	64929		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	64930		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	64931		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	64932		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	64933		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	64934		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	64935		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	64936		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	64937		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01							Re-Survey	Review – No Change	HSG227	Checked	High Risk	0			64938		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01							Re-Survey	Review – No Change	HSG227	Checked	High Risk	0			64939		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01							Re-Survey	Review – No Change	HSG227	Checked	High Risk	0			64940		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	64941		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	64942		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	64943		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	64944		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	64945		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	64946		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	64947		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	64948		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	64949		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	64950		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	64951		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	64952		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	64953		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	64954		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	64955		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01							Re-Survey	Review – No Change	HSG227	Checked	High Risk	0			64956		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01							Re-Survey	Review – No Change	HSG227	Checked	High Risk	0			64957		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	64958		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	64959		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	64960		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	64961		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	64962		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	Wall Board	PLASTER TO VERTICAL DUCT	Wall Board	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Identified	No Asbestos Detected	64963	A74675	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	64964		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	64965		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	64966		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	64967		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	64968		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	64969		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	64970		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	64971		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01							Re-Survey	Review – No Change	HSG227	Checked	High Risk	0			64972		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01							Re-Survey	Review – No Change	HSG227	Checked	High Risk	0			64973		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	26				NO ASBESTOS			No further action required (No Asbestos Detected)	Original Survey Data	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	64974				
#REF!	SAA	Daisy Hill Hospital Estate	26				NO ASBESTOS			No further action required (No Asbestos Detected)	Original Survey Data	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	64975				
#REF!	SAA	Daisy Hill Hospital Estate	26				NO ASBESTOS			No further action required (No Asbestos Detected)	Original Survey Data	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	64976				
#REF!	SAA	Daisy Hill Hospital Estate	26				NO ASBESTOS			No further action required (No Asbestos Detected)	Original Survey Data	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	64977				
#REF!	SAA	Daisy Hill Hospital Estate	26				NO ASBESTOS			No further action required (No Asbestos Detected)	Original Survey Data	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	64978				
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	64979		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	64980		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	64981		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	64982		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	64983		9506/18	20/03/2019	WHS

#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64984		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64985		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64986		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01						Re-Survey	Review – No Change	HSG227	Checked	High Risk	0			Very Low Risk	64987		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01						Re-Survey	Review – No Change	HSG227	Checked	High Risk	0				64988		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64989		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	Ceiling Board	Insulating Board	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	64990	A75019	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64991		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64992		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	Ceiling Board	Insulating Board	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	64993	A75018	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64994		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64995		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64996		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64997		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64998		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	64999		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	65000		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	65001		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	65002		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	65003		9506/1A	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	65004		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	65005		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	65006		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	65007		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	65008		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	65009		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	65010		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	65011		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	65012		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	65013		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	65014		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	65015		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	65016		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	65017		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	65018		9506/1A	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	65019		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	65020		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	65021		9506/1A	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	Blue Floor Tiles	Reinforced Composites	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	65022	A75017	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	65023		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	65024		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	65025		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	65026		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	Beige Floor Tiles	[illegible]	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	13/12/2023	Identified	Low Risk	65027	A75012	[illegible]	26/10/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	Beige Floor Tiles	Reinforced Composites	NO ASBESTOS	Composite Materials	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed	Asbestos Removed	65028	A75012-E	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	65029		9506/1A	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	65030		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	65031		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	65032		9506/1A	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	65033		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	65034		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	65035		9506/1A	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	65036		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	65037		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	65038		9506/1A	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	65039		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	65040		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	65041		9506/1A	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	65042		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	65043		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	65044		9506/1A	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	65045		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	65046		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	65047		9506/1A	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	Sink Pads	Reinforced Composites	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	65048	A75011	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	65049		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	65050		9506/1A	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	65051		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	65052		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	65053		9506/1A	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	65054		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	65055		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	65056		9506/1A	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	65057		9506/18	20/03/2019	WHS

#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65058	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65059	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65060	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65061	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65062	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65063	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65064	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65065	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65066	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65067	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65068	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65069	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65070	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65071	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65072	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65073	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65074	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65075	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65076	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65077	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65078	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65079	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65080	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65081	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65082	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65083	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65084	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65085	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65086	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65087	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65088	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65089	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65090	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65091	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65092	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65093	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	28	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65235	9327/17	14/03/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	28	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65236	9327/17	14/03/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	28	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65237	9327/17	14/03/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	28	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65238	9327/17	14/03/2018	WHS
#REF!	SJD	Rathfriland Road Site	11	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65240	9327/17	04/04/2018	WHS
#REF!	SJD	Rathfriland Road Site	11	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65241	9327/17	04/04/2018	WHS
#REF!	SJD	Rathfriland Road Site	11	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65242	9327/17	04/04/2018	WHS
#REF!	SJD	Rathfriland Road Site	11	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65243	9327/17	04/04/2018	WHS
#REF!	SJD	Rathfriland Road Site	11	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65244	9327/17	04/04/2018	WHS
#REF!	SJD	Rathfriland Road Site	11	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65245	9327/17	04/04/2018	WHS
#REF!	SJD	Rathfriland Road Site	11	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65246	9327/17	04/04/2018	WHS
#REF!	SJD	Rathfriland Road Site	11	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65247	9327/17	04/04/2018	WHS
#REF!	SJD	Rathfriland Road Site	11	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65248	9327/17	04/04/2018	WHS
#REF!	SJD	Rathfriland Road Site	11	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65249	9327/17	04/04/2018	WHS
#REF!	SJD	Rathfriland Road Site	11	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65250	9327/17	04/04/2018	WHS
#REF!	SJD	Rathfriland Road Site	11	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65251	9327/17	04/04/2018	WHS
#REF!	SJD	Rathfriland Road Site	11	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65252	9327/17	04/04/2018	WHS
#REF!	SJD	Rathfriland Road Site	11	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65253	9327/17	04/04/2018	WHS
#REF!	SJD	Rathfriland Road Site	11	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65254	9327/17	04/04/2018	WHS
#REF!	SJD	Rathfriland Road Site	11	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65255	9327/17	04/04/2018	WHS
#REF!	SJD	Rathfriland Road Site	11	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65256	9327/17	04/04/2018	WHS
#REF!	SJD	Rathfriland Road Site	11	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65257	9327/17	04/04/2018	WHS
#REF!	SJD	Rathfriland Road Site	11	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65258	9327/17	04/04/2018	WHS
#REF!	SJD	Rathfriland Road Site	11	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65259	9327/17	04/04/2018	WHS
#REF!	SJD	Rathfriland Road Site	11	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65260	9327/17	04/04/2018	WHS
#REF!	SJD	Rathfriland Road Site	11	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65261	9327/17	04/04/2018	WHS
#REF!	SJD	Rathfriland Road Site	11	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65262	9327/17	04/04/2018	WHS
#REF!	SJD	Rathfriland Road Site	11	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65263	9327/17	04/04/2018	WHS
#REF!	SJD	Rathfriland Road Site	11	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65264	9327/17	04/04/2018	WHS
#REF!	SJD	Rathfriland Road Site	11	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65265	9327/17	04/04/2018	WHS
#REF!	SJD	Rathfriland Road Site	11	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65266	9327/17	04/04/2018	WHS
#REF!	SJD	Rathfriland Road Site	11	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65267	9327/17	04/04/2018	WHS
#REF!	SJD	Rathfriland Road Site	11	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65268	9327/17	04/04/2018	WHS
#REF!	SJD	Rathfriland Road Site	11	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65269	9327/17	04/04/2018	WHS
#REF!	SJD	Rathfriland Road Site	11	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65270	9327/17	04/04/2018	WHS
#REF!	SJD	Rathfriland Road Site	11	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65271	9327/17	04/04/2018	WHS
#REF!	SJD	Rathfriland Road Site	11	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65272	9327/17	04/04/2018	WHS

#REF!	SJD	Rathfinland Road Site	11	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65273	93271?	04/04/2018	WHS
#REF!	SJD	Rathfinland Road Site	11	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65274	93271?	04/04/2018	WHS
#REF!	SJD	Rathfinland Road Site	11	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65275	93271?	04/04/2018	WHS
#REF!	SJD	Rathfinland Road Site	11	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65276	93271?	04/04/2018	WHS
#REF!	SJD	Rathfinland Road Site	11	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65277	93271?	04/04/2018	WHS
#REF!	SJD	Rathfinland Road Site	11	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65278	93271?	04/04/2018	WHS
#REF!	SJD	Rathfinland Road Site	11	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65279	93271?	04/04/2018	WHS
#REF!	SJD	Rathfinland Road Site	11	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65280	93271?	04/04/2018	WHS
#REF!	SJD	Rathfinland Road Site	11	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65281	93271?	04/04/2018	WHS
#REF!	SJD	Rathfinland Road Site	11	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65282	93271?	04/04/2018	WHS
#REF!	SJD	Rathfinland Road Site	11	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65283	93271?	04/04/2018	WHS
#REF!	SJD	Rathfinland Road Site	11	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65284	93271?	04/04/2018	WHS
#REF!	SJD	Rathfinland Road Site	11	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65285	93271?	04/04/2018	WHS
#REF!	SJD	Rathfinland Road Site	11	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65286	93271?	04/04/2018	WHS
#REF!	SJD	Rathfinland Road Site	11	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65287	93271?	04/04/2018	WHS
#REF!	SJD	Rathfinland Road Site	11	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65288	93271?	04/04/2018	WHS
#REF!	SJD	Rathfinland Road Site	11	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65289	93271?	04/04/2018	WHS
#REF!	SJD	Rathfinland Road Site	11	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65290	93271?	04/04/2018	WHS
#REF!	SJD	Rathfinland Road Site	11	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65291	93271?	04/04/2018	WHS
#REF!	SJD	Rathfinland Road Site	11	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65292	93271?	04/04/2018	WHS
#REF!	SJD	Rathfinland Road Site	11	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65293	93271?	04/04/2018	WHS
#REF!	SJD	Rathfinland Road Site	11	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65294	93271?	04/04/2018	WHS
#REF!	SJD	Rathfinland Road Site	11	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65295	93271?	04/04/2018	WHS
#REF!	SJD	Rathfinland Road Site	11	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65296	93271?	04/04/2018	WHS
#REF!	SJD	Rathfinland Road Site	11	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65297	93271?	04/04/2018	WHS
#REF!	SJD	Rathfinland Road Site	11	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65298	93271?	04/04/2018	WHS
#REF!	SJD	Rathfinland Road Site	11	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65299	93271?	04/04/2018	WHS
#REF!	SJD	Rathfinland Road Site	11	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65300	93271?	04/04/2018	WHS
#REF!	SJD	Rathfinland Road Site	11	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65301	93271?	04/04/2018	WHS
#REF!	SJD	Rathfinland Road Site	10	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65302	93271?	04/04/2018	WHS
#REF!	SJD	Rathfinland Road Site	10	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65303	93271?	04/04/2018	WHS
#REF!	SJD	Rathfinland Road Site	10	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65304	93271?	04/04/2018	WHS
#REF!	SJD	Rathfinland Road Site	10	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65305	93271?	04/04/2018	WHS
#REF!	SJD	Rathfinland Road Site	10	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65306	93271?	04/04/2018	WHS
#REF!	SJD	Rathfinland Road Site	10	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65307	93271?	04/04/2018	WHS
#REF!	SJD	Rathfinland Road Site	10	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65308	93271?	04/04/2018	WHS
#REF!	SJD	Rathfinland Road Site	10	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65309	93271?	04/04/2018	WHS
#REF!	SJD	Rathfinland Road Site	10	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65310	93271?	04/04/2018	WHS
#REF!	SJD	Rathfinland Road Site	10	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65311	93271?	04/04/2018	WHS
#REF!	SJD	Rathfinland Road Site	10	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65312	93271?	04/04/2018	WHS
#REF!	SJD	Rathfinland Road Site	10	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65313	93271?	04/04/2018	WHS
#REF!	SJD	Rathfinland Road Site	10	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65314	93271?	04/04/2018	WHS
#REF!	SJD	Rathfinland Road Site	10	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65315	93271?	04/04/2018	WHS
#REF!	SJD	Rathfinland Road Site	10	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65316	93271?	04/04/2018	WHS
#REF!	SJD	Rathfinland Road Site	10	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65317	93271?	04/04/2018	WHS
#REF!	SJD	Rathfinland Road Site	10	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65318	93271?	04/04/2018	WHS
#REF!	SJD	Rathfinland Road Site	10	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65319	93271?	04/04/2018	WHS
#REF!	SJD	Rathfinland Road Site	10	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65320	93271?	04/04/2018	WHS
#REF!	SJD	Rathfinland Road Site	10	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65321	93271?	04/04/2018	WHS
#REF!	SJD	Rathfinland Road Site	10	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65322	93271?	04/04/2018	WHS
#REF!	SJD	Rathfinland Road Site	10	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65323	93271?	04/04/2018	WHS
#REF!	SJD	Rathfinland Road Site	10	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65324	93271?	04/04/2018	WHS
#REF!	SJD	Rathfinland Road Site	10	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65325	93271?	04/04/2018	WHS
#REF!	SJD	Rathfinland Road Site	10	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65326	93271?	04/04/2018	WHS
#REF!	SJD	Rathfinland Road Site	10	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65327	93271?	04/04/2018	WHS
#REF!	SJD	Rathfinland Road Site	10	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65328	93271?	04/04/2018	WHS
#REF!	SJD	Rathfinland Road Site	10	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65329	93271?	04/04/2018	WHS
#REF!	SJD	Rathfinland Road Site	10	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65330	93271?	04/04/2018	WHS
#REF!	SJD	Rathfinland Road Site	10	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65331	93271?	04/04/2018	WHS
#REF!	SJD	Rathfinland Road Site	10	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65332	93271?	04/04/2018	WHS
#REF!	SJD	Rathfinland Road Site	10	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65333	93271?	04/04/2018	WHS
#REF!	SJD	Rathfinland Road Site	10	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65334	93271?	04/04/2018	WHS
#REF!	SJD	Rathfinland Road Site	10	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65335	93271?	04/04/2018	WHS
#REF!	SJD	Rathfinland Road Site	10	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65336	93271?	04/04/2018	WHS
#REF!	SJD	Rathfinland Road Site	10	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65337	93271?	04/04/2018	WHS
#REF!	SJD	Rathfinland Road Site	10	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65338	93271?	04/04/2018	WHS
#REF!	SJD	Rathfinland Road Site	10	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65339	93271?	04/04/2018	WHS
#REF!	SJD	Rathfinland Road Site	10	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65340	93271?	04/04/2018	WHS
#REF!	SJD	Rathfinland Road Site	10	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65341	93271?	04/04/2018	WHS
#REF!	SJD	Rathfinland Road Site	10	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65342	93271?	04/04/2018	WHS
#REF!	SJD	Rathfinland Road Site	10	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65343	93271?	04/04/2018	WHS
#REF!	SJD	Rathfinland Road Site	10	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65344	93271?	04/04/2018	WHS
#REF!	SJD	Rathfinland Road Site	10	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65345	93271?	04/04/2018	WHS

#REF!	SJD	Rathfriland Road Site	10	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65346	9327/17	04/04/2018	WHS
#REF!	SJD	Rathfriland Road Site	10	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65347	9327/17	04/04/2018	WHS
#REF!	SJD	Rathfriland Road Site	10	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65348	9327/17	04/04/2018	WHS
#REF!	SJD	Rathfriland Road Site	10	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65349	9327/17	04/04/2018	WHS
#REF!	SJD	Rathfriland Road Site	10	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65350	9327/17	04/04/2018	WHS
#REF!	SJD	Rathfriland Road Site	10	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65351	9327/17	04/04/2018	WHS
#REF!	SJD	Rathfriland Road Site	10	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65352	9327/17	04/04/2018	WHS
#REF!	SJD	Rathfriland Road Site	10	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65353	9327/17	04/04/2018	WHS
#REF!	SJD	Rathfriland Road Site	10	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65354	9327/17	04/04/2018	WHS
#REF!	SJD	Rathfriland Road Site	10	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65355	9327/17	04/04/2018	WHS
#REF!	SJD	Rathfriland Road Site	10	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65356	9327/17	04/04/2018	WHS
#REF!	SJD	Rathfriland Road Site	10	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65357	9327/17	04/04/2018	WHS
#REF!	SJD	Rathfriland Road Site	10	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65358	9327/17	04/04/2018	WHS
#REF!	SJD	Rathfriland Road Site	10	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65359	9327/17	04/04/2018	WHS
#REF!	SJD	Rathfriland Road Site	10	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65360	9327/17	04/04/2018	WHS
#REF!	SJD	Rathfriland Road Site	10	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65361	9327/17	04/04/2018	WHS
#REF!	SJD	Rathfriland Road Site	10	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65362	9327/17	04/04/2018	WHS
#REF!	SJD	Rathfriland Road Site	10	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65363	9327/17	04/04/2018	WHS
#REF!	SJD	Rathfriland Road Site	10	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65364	9327/17	04/04/2018	WHS
#REF!	SJD	Rathfriland Road Site	10	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65365	9327/17	04/04/2018	WHS
#REF!	SJD	Rathfriland Road Site	10	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65366	9327/17	04/04/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65367	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65368	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65369	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65370	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65371	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65372	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65373	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65374	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65375	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65376	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65377	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65378	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65379	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65380	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65381	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65382	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65383	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65384	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65385	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65386	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65387	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65388	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65389	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65390	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65391	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65392	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65393	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65394	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65395	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65396	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65397	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65398	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65399	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65400	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65401	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65402	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65403	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65404	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65405	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65406	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65407	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65408	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65409	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65410	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65411	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65412	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65413	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65414	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65415	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65416	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65417	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65418	9506/18	20/03/2019	WHS

#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65419	950/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65420	950/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65421	950/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65422	950/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65423	950/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65424	950/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65425	950/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65426	950/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65427	950/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65428	950/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65429	950/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65430	950/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65431	950/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65432	950/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65433	950/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65434	950/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65435	950/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65436	950/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65437	950/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65438	950/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65439	950/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65440	950/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65441	950/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65442	950/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65443	950/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65444	950/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65445	950/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65446	950/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65447	950/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65448	950/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65449	950/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65450	950/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65451	950/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65452	950/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65453	950/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65454	950/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65455	950/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65456	950/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65457	950/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65458	950/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65459	950/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65460	950/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65461	950/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65462	950/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65463	950/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65464	950/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65465	950/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65466	950/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65467	950/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65468	950/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65469	950/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65470	950/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65471	950/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65472	950/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65473	950/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65474	950/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65475	950/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65476	950/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65477	950/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65478	950/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65479	950/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65480	950/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65481	950/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65482	950/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65483	950/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65484	950/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65485	950/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65486	950/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65487	950/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65488	950/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65489	950/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65490	950/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	No Asbestos Detected	65491	950/18	20/03/2019	WHS

#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	65492	950/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	65493	950/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	65494	950/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	65495	950/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	65496	950/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	65497	950/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	65498	950/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	65499	950/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	65500	950/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	65501	950/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	65502	950/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	65503	950/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	65504	950/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	65505	950/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	65506	950/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	65507	950/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	65508	950/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	65509	950/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	65510	950/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	65511	950/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	65512	950/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	65513	950/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	65514	950/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	65515	950/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	65516	950/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	65517	950/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	65518	950/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	23/09/2011	No Asbestos Detected	65519	950/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	65520	950/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	65521	950/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	65522	950/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	65523	950/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	65524	950/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	65525	950/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	65526	950/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	65527	950/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	65528	950/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	65529	950/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	65530	950/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	65531	950/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	65532	950/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	65533	950/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	65534	950/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	65535	950/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	65536	950/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	65537	950/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	65538	950/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	65539	950/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	65540	950/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	65541	950/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	65542	950/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	65543	950/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	65544	950/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	65545	950/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	65546	950/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	65547	950/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	65548	950/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	65549	950/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	65550	950/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	65551	950/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	65552	950/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	65553	950/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	65554	950/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	65555	950/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	65556	950/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	65557	950/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	65558	950/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	65559	950/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	65560	950/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	65561	950/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	65562	950/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	65563	950/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		No Asbestos Detected	65564	950/18	20/03/2019	WHS

#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	65565		9506/18	20/03/2019	WHS
#REF!	SBD	Newtownhamilton Health Centre	01	White Floor Tiles		Reinforced Composites	NO ASBESTOS	Composite Materials	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	Asbestos Removed	65566	A72388	9327/17	04/04/2018	WHS
#REF!	SBD	Newtownhamilton Health Centre	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	65567		9327/17	04/04/2018	WHS
#REF!	SBD	Newtownhamilton Health Centre	01	Biege Floor Tiles		Reinforced Composites	NO ASBESTOS	Composite Materials	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	Asbestos Removed	65568	A72387	9327/17	04/04/2018	WHS
#REF!	SBD	Newtownhamilton Health Centre	01	Blue Floor Tiles		Reinforced Composites	NO ASBESTOS	Composite Materials	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Previously Identified	Asbestos Removed	65569	A72397	9327/17	04/04/2018	WHS
#REF!	SBD	Newtownhamilton Health Centre	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	65570		9327/17	04/04/2018	WHS
#REF!	SBD	Newtownhamilton Health Centre	01	Ceiling Board		Insulating Board	Amosite (Amphibole)	Encapsulated Spray or Lagoing/Unsealed AIB	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Medium Risk	7	12/03/2023	Identified	Medium Risk	65571	A72404	9300/22	02/09/2022	WHS
#REF!	SBD	Newtownhamilton Health Centre	01	Door Panel		Insulating Board	Amosite (Amphibole)	Enclosed Spray or	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Low Risk	6	04/04/2019	Identified	Medium Risk	65572	A72395	9327/17	04/04/2018	WHS
#REF!	SBD	Newtownhamilton Health Centre	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	65573		9327/17	04/04/2018	WHS
#REF!	SBD	Newtownhamilton Health Centre	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	65574		9327/17	04/04/2018	WHS
#REF!	SBD	Newtownhamilton Health Centre	01	Sink / Drainer Pads		Reinforced Composites	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	65575	A72394	9327/17	04/04/2018	WHS
#REF!	SBD	Newtownhamilton Health Centre	01	Fascia / Soffit to eaves	ROOF OF BICYCLE SHELTER	Insulating Board	NO ASBESTOS	Enclosed Spray or Lagoing/Sealed AIB	High	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	65576	A45112	9327/17	04/04/2018	WHS
#REF!	SBD	Newtownhamilton Health Centre	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	65577		9327/17	04/04/2018	WHS
#REF!	SBD	Newtownhamilton Health Centre	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	65578		9327/17	04/04/2018	WHS
#REF!	SBD	Newtownhamilton Health Centre	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	65579		9327/17	04/04/2018	WHS
#REF!	SBD	Newtownhamilton Health Centre	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	65580		9327/17	04/04/2018	WHS
#REF!	SBD	Newtownhamilton Health Centre	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	65581		9327/17	04/04/2018	WHS
#REF!	SBD	Newtownhamilton Health Centre	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	65582		9327/17	04/04/2018	WHS
#REF!	SBD	Newtownhamilton Health Centre	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	65583		9327/17	04/04/2018	WHS
#REF!	SBD	Newtownhamilton Health Centre	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	65584		9327/17	04/04/2018	WHS
#REF!	SBD	Newtownhamilton Health Centre	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	65585		9327/17	04/04/2018	WHS
#REF!	SBD	Newtownhamilton Health Centre	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	65586		9327/17	04/04/2018	WHS
#REF!	SBD	Newtownhamilton Health Centre	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	65587		9327/17	04/04/2018	WHS
#REF!	SBD	Newtownhamilton Health Centre	01	Board to top of Trap door		Insulating Board	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	65588	A72391	9327/17	04/04/2018	WHS
#REF!	SBD	Newtownhamilton Health Centre	01	Orange Floor Tiles		Reinforced Composites	NO ASBESTOS	Composite Materials	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	Asbestos Removed	65589	A72389	9327/17	04/04/2018	WHS
#REF!	SBD	Newtownhamilton Health Centre	01	Stair Nosing	stair nosing	Reinforced Composites	NO ASBESTOS	Composite Materials	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	Asbestos Removed	65590	A72393	9327/17	04/04/2018	WHS
#REF!	SBD	Newtownhamilton Health Centre	01	Flue Pipe		Cement Products	NO ASBESTOS	Composite Materials	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	Asbestos Removed	65591	A72396	9327/17	04/04/2018	WHS
#REF!	SBD	Newtownhamilton Health Centre	01	Toilet Cistern		Reinforced Composites	NO ASBESTOS	Composite Materials	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	Asbestos Removed	65592	A72399	9327/17	04/04/2018	WHS
#REF!	SBD	Newtownhamilton Health Centre	01	Gaskets		Gaskets	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	2	12/09/2023	Identified	Very Low Risk	65593	A72405	9300/22	02/09/2022	WHS
#REF!	SBD	Newtownhamilton Health Centre	01	Ceiling Board	ROOF OF BICYCLE SHELTER	Insulating Board	NO ASBESTOS	Encapsulated Spray or Lagoing/Unsealed AIB	High	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	Asbestos Removed	65594	A45113	9327/17	04/04/2018	WHS
#REF!	SBD	Newtownhamilton Health Centre	01	Undercloak to verge	ROOF OF BICYCLE SHELTER	Insulating Board	Amosite/Chrysotile	Encapsulated Spray or Lagoing/Unsealed AIB	Low	Label & Manage	Re-inspection	HSG227	Unchecked	Medium Risk	7	12/03/2023	Identified	Very Low Risk	65595	A45114	9300/22	02/09/2022	WHS
#REF!	SBD	Newtownhamilton Health Centre	01	Soffit to eaves	MAIN BUILDING ROOF	Insulating Board	Amosite/Chrysotile	Enclosed Spray or	Low	Encapsulate, label and manage	Re-inspection	HSG227	Unchecked	Low Risk	6	12/09/2023	Identified	Low Risk	65596	A45115	9300/22	02/09/2022	WHS
#REF!	SBD	Newtownhamilton Health Centre	01	Undercloak to Verge	MAIN BUILDING FRONT PROJECTION ROOF	Insulating Board	Amosite/Chrysotile	Enclosed Spray or Lagoing/Sealed AIB	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Low Risk	6	12/09/2023	Identified	Low Risk	65597	A45116	9300/22	02/09/2022	WHS
#REF!	SBD	Newtownhamilton Health Centre	01	Soffit to eaves	MAIN BUILDING ROOF	Insulating Board	Amosite/Chrysotile	Enclosed Spray or	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Low Risk	6	12/09/2023	Identified	Low Risk	65598	A45117	9300/22	02/09/2022	WHS
#REF!	SBD	Newtownhamilton Health Centre	01	Soffit to eaves	MAIN BUILDING ROOF	Insulating Board	Amosite/Chrysotile	Enclosed Spray or	Low	Label & Manage	Re-inspection	HSG227	Unchecked	Low Risk	6	12/09/2023	Identified	Low Risk	65599	A45119	9300/22	02/09/2022	WHS
#REF!	SBD	Newtownhamilton Health Centre	01	Undercloak to Verge	VERGE TO RHS GABLE OF MAIN BUILDING	Insulating Board	Amosite/Chrysotile	Enclosed Spray or Lagoing/Sealed AIB	Low	Label & Manage	Re-inspection	HSG227	Unchecked	Low Risk	6	12/09/2023	Identified	Medium Risk	65600	A45118	9300/22	02/09/2022	WHS
#REF!	SBD	Newtownhamilton Health Centre	01	Ceiling Board	CEILING TO EXTERNAL LOBBY OF REAR DOOR	Insulating Board	Amosite/Chrysotile	Enclosed Spray or Lagoing/Sealed AIB	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Low Risk	6	12/09/2023	Identified	Medium Risk	65601	A45120	9300/22	02/09/2022	WHS
#REF!	SBD	Newtownhamilton Health Centre	01	Undercloak to Verge	VERGE TO LHS GABLE OF MAIN BUILDING	Insulating Board	Amosite/Chrysotile	Enclosed Spray or Lagoing/Sealed AIB	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Low Risk	6	12/09/2023	Identified	Low Risk	65602	A45121	9300/22	02/09/2022	WHS
#REF!	SBD	Newtownhamilton Health Centre	01	Biege Floor Tiles	BEHIND RECEPTION DESK	Reinforced Composites	NO ASBESTOS	Composite Materials	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed	Asbestos Removed	65603	A72387-E	9327/17	04/04/2018	WHS
#REF!	SBD	Newtownhamilton Health Centre	01	Biege Floor Tiles		Reinforced Composites	NO ASBESTOS	Composite Materials	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed	Asbestos Removed	65604	A72387-E	9327/17	04/04/2018	WHS
#REF!	SBD	Newtownhamilton Health Centre	01	Biege Floor Tiles		Reinforced Composites	NO ASBESTOS	Composite Materials	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed	Asbestos Removed	65605	A72387-E	9327/17	04/04/2018	WHS
#REF!	SBD	Newtownhamilton Health Centre	01	Biege Floor Tiles		Reinforced Composites	NO ASBESTOS	Composite Materials	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed	Asbestos Removed	65606	A72387-E	9327/17	04/04/2018	WHS
#REF!	SBD	Newtownhamilton Health Centre	01	Biege Floor Tiles		Reinforced Composites	NO ASBESTOS	Composite Materials	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	Asbestos Removed	65607	A72387-E	9327/17	04/04/2018	WHS
#REF!	SBD	Newtownhamilton Health Centre	01	Biege Floor Tiles		Reinforced Composites	NO ASBESTOS	Composite Materials	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed	Asbestos Removed	65608	A72387-E	9327/17	04/04/2018	WHS
#REF!	SBD	Newtownhamilton Health Centre	01	Biege Floor Tiles		Reinforced Composites	NO ASBESTOS	Composite Materials	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed	Asbestos Removed	65609	A72387-E	9327/17	04/04/2018	WHS
#REF!	SBD	Newtownhamilton Health Centre	01	Biege Floor Tiles		Reinforced Composites	NO ASBESTOS	Composite Materials	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed	Asbestos Removed	65610	A72387-E	9327/17	04/04/2018	WHS
#REF!	SBD	Newtownhamilton Health Centre	01	White Floor Tiles		Reinforced Composites	NO ASBESTOS	Composite Materials	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed	Asbestos Removed	65611	A72388-E	9327/17	04/04/2018	WHS
#REF!	SBD	Newtownhamilton Health Centre	01	White Floor Tiles		Reinforced Composites	NO ASBESTOS	Composite Materials	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed	Asbestos Removed	65612	A72388-E	9327/17	04/04/2018	WHS
#REF!	SBD	Newtownhamilton Health Centre	01	White Floor Tiles		Reinforced Composites	NO ASBESTOS	Composite Materials	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed	Asbestos Removed	65613	A72388-E	9327/17	04/04/2018	WHS
#REF!	SBD	Newtownhamilton Health Centre	01	White Floor Tiles	floor covering	Reinforced Composites	Chrysotile	Composite Materials	Low	Re-Survey	Re-inspection	HSG227	Checked	High Risk	3	12/12/2022	Strongly Presumed	Very Low Risk	65614	A72388-E	9327/17	02/09/2022	WHS
#REF!	SBD	Newtownhamilton Health Centre	01	White Floor Tiles		Reinforced Composites	NO ASBESTOS	Composite Materials	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed	Asbestos Removed	65615	A72388-E	9327/17	04/04/2018	WHS
#REF!	SBD	Newtownhamilton Health Centre	01	White Floor Tiles		Reinforced Composites	NO ASBESTOS	Composite Materials	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed	Asbestos Removed	65616	A72388-E	9327/17	04/04/2018	WHS
#REF!	SBD	Newtownhamilton Health Centre	01	White Floor Tiles		Reinforced Composites	NO ASBESTOS	Composite Materials	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed	Asbestos Removed	65617	A72388-E	9327/17	04/04/2018	WHS
#REF!	SBD	Newtownhamilton Health Centre	01	White Floor Tiles		Reinforced Composites	NO ASBESTOS	Composite Materials	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed	Asbestos Removed	65618	A72388-E	9327/17	04/04/2018	WHS
#REF!	SBD	Newtownhamilton Health Centre	01	White Floor Tiles		Reinforced Composites	NO ASBESTOS	Composite Materials	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed	Asbestos Removed	65619	A72388-E	9327/17	04/04/2018	WHS
#REF!	SBD	Newtownhamilton Health Centre	01	White Floor Tiles		Reinforced Composites	NO ASBESTOS	Composite Materials	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed	Asbestos Removed	65620	A72388-E	9327/17	04/04/2018	WHS
#REF!	SBD	Newtownhamilton Health Centre	01	White Floor Tiles		Reinforced Composites	NO ASBESTOS	Composite Materials	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed	Asbestos Removed	65621	A72388-E	9327/17	04/04/2018	WHS
#REF!	SBD	Newtownhamilton Health Centre	01	White Floor Tiles		Reinforced Composites	NO ASBESTOS	Composite Materials	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed	Asbestos Removed	65622	A72388-E	9327/17	04/04/2018	WHS
#REF!	SBD	Newtownhamilton Health Centre	01	White Floor Tiles		Reinforced Composites	NO ASBESTOS	Composite Materials	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed	Asbestos Removed	65623	A72388-E	9327/17	04/04/2018	WHS
#REF!	SBD	Newtownhamilton Health Centre	01	White Floor Tiles		Reinforced Composites	NO ASBESTOS	Composite Materials	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed	Asbestos Removed	65624	A72388-E	9327/17	04/04/2018	WHS
#REF!	SBD	Newtownhamilton Health Centre	01	White Floor Tiles		Reinforced Composites	NO ASBESTOS	Composite Materials	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed	Asbestos Removed	65625	A72388-E	9327/17	04/04/2018	WHS
#REF!	SBD	Newtownhamilton Health Centre	01	Orange Floor Tiles		Reinforced Composites	NO ASBESTOS	Composite Materials	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed	Asbestos Removed	65626	A72389-E	9327/17	04/04/2018	WHS
#REF!	SBD	Newtownhamilton Health Centre	01	Orange Floor Tiles		Reinforced Composites	NO ASBESTOS	Composite Materials	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed	Asbestos Removed	65627	A72389-E	9327/17	04/04/2018	WHS
#REF!	SBD	Newtownhamilton Health Centre	01	Orange Floor Tiles		Reinforced Composites	NO ASBESTOS	Composite Materials	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed	Asbestos Removed	65628	A72389-E	9327/17	04/04/2018	WHS
#REF!	SBD	Newtownhamilton Health Centre	01	Orange Floor Tiles		Reinforced Composites	NO ASBESTOS	Composite Materials	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed	Asbestos Removed	65629	A72389-E	9327/17	04/04/2018	WHS
#REF!	SBD	Newtownhamilton Health Centre	01	Orange Floor Tiles		Reinforced Composites	NO ASBESTOS	Composite Materials	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed	Asbestos Removed	65630	A72389-E	9327/17	04/04/2018	WHS
#REF!	SBD	Newtownhamilton Health Centre	01	Orange Floor Tiles		Reinforced Composites	NO ASBESTOS	Composite Materials	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed	Asbestos Removed	65631	A72389-E	9327/17	04/04/2018	WHS
#REF!	SBD	Newtownhamilton Health Centre	01	Board to top of Trap door		Insulating Board	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	65632	A72391-E	9327/17	04/04/2018	WHS
#REF!	SBD	Newtownhamilton Health Centre	01	Board to top of Trap door		Insulating Board	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	65633	A72391-E	9327/17	04/04/2018	WHS
#REF!	SBD	Newtownhamilton Health Centre	01	Biege Floor Tiles		Reinforced Composites	NO ASBESTOS	Composite Materials	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed	Asbestos Removed	65634	A72392-E	9327/17	04/04/2018	WHS
#REF!	SBD	Newtownhamilton Health Centre	01	Biege Floor Tiles		Reinforced Composites	NO ASBESTOS	Composite Materials	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed	Asbestos Removed	65635	A72392-E	9327/17	04/04/2018	WHS
#REF!	SBD	Newtownhamilton Health Centre	01	Biege Floor Tiles		Reinforced Composites	NO ASBESTOS	Composite Materials	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed	Asbestos Removed	65636	A72392-E	9327/17	04/04/2018	WHS
#REF!	SBD	Newtownhamilton Health Centre	01	Sink / Drainer Pads		Reinforced Composites	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed	No Asbestos Detected	65637	A72394-E	9327/17	04/04/2018	WHS
#REF!	SBD	Newtownhamilton Health Centre	01	Sink / Drainer Pads		Reinforced Composites	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	65638	A72394-E	9327/17	04/04/2018	WHS
#REF!	SBD	Newtownhamilton Health Centre	01	Sink / Drainer Pads		Reinforced Composites	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	65639	A72394-E	9327/17	04/04/2018	WHS
#REF!	SBD	Newtownhamilton Health Centre	01	Sink / Drainer Pads		Reinforced Composites	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	65640	A72394-E	9327/17	04/04/2018	WHS

#REF!	SBD	Newtownhamilton Health Centre	01	Sink / Drainer Pads		Reinforced Composites	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	65641	A72394-E	9327/17	04/04/2018	WHS
#REF!	SBD	Newtownhamilton Health Centre	01	Sink / Drainer Pads		Reinforced Composites	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	65642	A72394-E	9327/17	04/04/2018	WHS
#REF!	SBD	Newtownhamilton Health Centre	01	Door Panel		Insulating Board	Amosite (Amphibole)	Enclosed Spray or Lagoins/Sealed AIB	Low	No further action required (Asbestos removed)	Re-inspection	HSG227	Unchecked	Low Risk	6	12/09/2023	Strongly Presumed	Medium Risk	65643	A72395-E	9300/22	02/09/2022	WHS
#REF!	SBD	Newtownhamilton Health Centre	01	Door Panel		Insulating Board	NO ASBESTOS	Enclosed Spray or Lagoins/Sealed AIB	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed	Asbestos Removed	65644	A72395-E	9327/17	04/04/2018	WHS
#REF!	SBD	Newtownhamilton Health Centre	01	Blue Floor Tiles		Reinforced Composites	NO ASBESTOS	Composite Materials	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed	Asbestos Removed	65645	A72397-E	9327/17	04/04/2018	WHS
#REF!	SBD	Newtownhamilton Health Centre	01	Blue Floor Tiles		Reinforced Composites	NO ASBESTOS	Composite Materials	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed	Asbestos Removed	65646	A72397-E	9327/17	04/04/2018	WHS
#REF!	SBD	Newtownhamilton Health Centre	01	Blue Floor Tiles		Reinforced Composites	NO ASBESTOS	Composite Materials	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed	Asbestos Removed	65647	A72397-E	9327/17	04/04/2018	WHS
#REF!	SBD	Newtownhamilton Health Centre	01	Fawn Floor Tiles		Reinforced Composites	NO ASBESTOS	Composite Materials	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed	Asbestos Removed	65648	A72398-E	9327/17	04/04/2018	WHS
#REF!	SBD	Newtownhamilton Health Centre	01	Fawn Floor Tiles		Reinforced Composites	NO ASBESTOS	Composite Materials	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed	Asbestos Removed	65649	A72398-E	9327/17	04/04/2018	WHS
#REF!	SBD	Newtownhamilton Health Centre	01	Fawn Floor Tiles		Reinforced Composites	NO ASBESTOS	Composite Materials	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed	Asbestos Removed	65650	A72398-E	9327/17	04/04/2018	WHS
#REF!	SBD	Newtownhamilton Health Centre	01	Fawn Floor Tiles		Reinforced Composites	NO ASBESTOS	Composite Materials	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed	Asbestos Removed	65651	A72398-E	9327/17	04/04/2018	WHS
#REF!	SBD	Newtownhamilton Health Centre	01	Fawn Floor Tiles		Reinforced Composites	NO ASBESTOS	Composite Materials	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed	Asbestos Removed	65652	A72398-E	9327/17	04/04/2018	WHS
#REF!	SBD	Newtownhamilton Health Centre	01	Fawn Floor Tiles		Reinforced Composites	NO ASBESTOS	Composite Materials	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed	Asbestos Removed	65653	A72398-E	9327/17	04/04/2018	WHS
#REF!	SBD	Newtownhamilton Health Centre	01	Fawn Floor Tiles		Reinforced Composites	NO ASBESTOS	Composite Materials	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed	Asbestos Removed	65654	A72398-E	9327/17	04/04/2018	WHS
#REF!	SBD	Newtownhamilton Health Centre	01	Fawn Floor Tiles		Reinforced Composites	NO ASBESTOS	Composite Materials	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed	Asbestos Removed	65655	A72398-E	9327/17	04/04/2018	WHS
#REF!	SBD	Newtownhamilton Health Centre	01	Fawn Floor Tiles		Reinforced Composites	NO ASBESTOS	Composite Materials	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	Asbestos Removed	65656	A72398-E	9327/17	04/04/2018	WHS
#REF!	SBD	Newtownhamilton Health Centre	01	Toilet Cistern		Reinforced Composites	NO ASBESTOS	Composite Materials	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed	Asbestos Removed	65657	A72399-E	9327/17	04/04/2018	WHS
#REF!	SBD	Newtownhamilton Health Centre	01	Toilet Cistern		Reinforced Composites	NO ASBESTOS	Composite Materials	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed	Asbestos Removed	65658	A72399-E	9327/17	04/04/2018	WHS
#REF!	SBD	Newtownhamilton Health Centre	01	Grey Floor Tiles		Reinforced Composites	NO ASBESTOS	Composite Materials	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed	Asbestos Removed	65659	A72401-E	9327/17	04/04/2018	WHS
#REF!	SBD	Newtownhamilton Health Centre	01	Grey Floor Tiles		Reinforced Composites	NO ASBESTOS	Composite Materials	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed	Asbestos Removed	65660	A72401-E	9327/17	04/04/2018	WHS
#REF!	SBD	Newtownhamilton Health Centre	01	Grey Floor Tiles		Reinforced Composites	NO ASBESTOS	Composite Materials	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed	Asbestos Removed	65661	A72403-E	9327/17	04/04/2018	WHS
#REF!	SBD	Newtownhamilton Health Centre	01	Grey Floor Tiles		Reinforced Composites	NO ASBESTOS	Composite Materials	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed	Asbestos Removed	65662	A72403-E	9327/17	04/04/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	Sink Pad		Reinforced Composites	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	65725	A75013	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	Gasket Seal		Reinforced Composites	NO ASBESTOS	Composite Materials	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	21/05/2020	Identified	Asbestos Removed	65726	A75015	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	Soffit Boards	SOFFITS TO COURTYARD BETWEEN ROOMS 099 AND 101	Cement Products	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	65727	A75016	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	Ceiling Board	LOADING BAY CEILING ADJACENT ROOMS 054 - 059	Insulating Board	Amosite (Amphibole)	Enclosed Spray or Lagoins/Sealed AIB	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Low Risk	6	13/12/2023	Identified	Low Risk	65728	A75020	9300/22	13/12/2022	WHS
#REF!	SHA	Drumalane Estate	08				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	65729		9327/17	04/04/2018	WHS
#REF!	SHA	Drumalane Estate	08				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	65730		9327/17	04/04/2018	WHS
#REF!	SHA	Drumalane Estate	08				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	65731		9327/17	04/04/2018	WHS
#REF!	SHA	Drumalane Estate	08							Re-Survey	Review – No Change	HSG227	Checked	High Risk	0	10/07/2021			65732		9512/1	12/09/2019	WH Stephens
#REF!	SHA	Drumalane Estate	08	Corrugated Roof Sheet		Cement Products	Chrysotile	Cement Sheets	Low	Re-Survey	Re-inspection	HSG227	Unchecked	Very Low Risk	4	14/09/2023	Identified	Low Risk	65733		9300/22	06/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	22				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	65734		9327/17	19/04/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	22				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	65735		9327/17	19/04/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	22				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	65736		9327/17	19/04/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	22				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	65737		9327/17	19/04/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	22				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	65738		9327/17	19/04/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	22				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	65739		9327/17	19/04/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	22				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	65740		9327/17	19/04/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	22				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	65741		9327/17	19/04/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	22				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	65742		9327/17	19/04/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	22				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	65743		9327/17	19/04/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	22				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	65744		9327/17	19/04/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	22				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	65745		9327/17	19/04/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	22				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	65746		9327/17	19/04/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	22				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	65747		9327/17	19/04/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	22				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	65748		9327/17	19/04/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	22				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	65749		9327/17	19/04/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	22				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	65750		9327/17	19/04/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	22				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	65751		9327/17	19/04/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	22				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	65752		9327/17	19/04/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	22				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	65753		9327/17	19/04/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	22				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	65754		9327/17	19/04/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	22				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	65755		9327/17	19/04/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	22	Roof Slate	ROOF SLATE TO MAIN ROOF	Reinforced Composites	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	65756	A74981	9327/17	19/04/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	Sink Pad		Reinforced Composites	NO ASBESTOS	Composite Materials	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	Asbestos Removed	65757	A74979	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	Paint	PAINT FINISH TO INTERNAL FACE OF LIFT DOOR	Paint Finish	NO ASBESTOS		Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	65758	A74980	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	65759		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	65760		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	65761		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	65762		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	65763		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	Stair Nosing		Reinforced Composites	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	65764	A74671	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	Sink Pad		Reinforced Composites	NO ASBESTOS	Composite Materials	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed	Asbestos Removed	65765	A74674-E	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	Sink Pad		Reinforced Composites	NO ASBESTOS	Composite Materials	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed	Asbestos Removed	65766	A74674-E	9506/18	20/03/2019	WHS
#REF!	QAA	Craigavon Hospital	02	Gaskets		Textiles & Paper	Chrysotile	Encapsulated Spray or Lagoins/Unsealed AIB	Low	Apply Caution when Maintaining	Re-inspection	HSG227	Unchecked	Low Risk	6	17/01/2024	Identified	Low Risk	65774	BA3294/01	9202/22	12/10/2022	WHS
#REF!	QAA	Craigavon Hospital	02	Gaskets		Textiles & Paper	NO ASBESTOS	Encapsulated Spray or Lagoins/Unsealed AIB	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	Asbestos Removed	65775	BA3294/01	9326/17	17/04/2018	WHS
#REF!	QAA	Craigavon Hospital	02	Gaskets		Textiles & Paper	Chrysotile	Encapsulated Spray or Lagoins/Unsealed AIB	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Low Risk	6	17/01/2024	Strongly Presumed Similar to	Low Risk	65776	BA3294/01	9202/22	12/10/2022	WHS
#REF!	QAA	Craigavon Hospital	02	Toilet Cistern		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	Asbestos Removed	65777	BA3294/02	9326/17	17/04/2018	WHS
#REF!	QAA	Craigavon Hospital	02	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	17/01/2024	Identified	Very Low Risk	65778	BA3294/03	9202/22	12/10/2022	WHS
#REF!	QAA	Craigavon Hospital	02	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	17/01/2024	Strongly Presumed Similar to	Very Low Risk	65779	BA3294/03	9202/22	12/10/2022	WHS
#REF!	QAA	Craigavon Hospital	02	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	17/01/2024	Stronnly Presumed Similar to	Very Low Risk	65780	BA3294/03	9202/22	12/10/2022	WHS
#REF!	QAA	Craigavon Hospital	02	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	17/01/2024	Stronnly Presumed Similar to	Very Low Risk	65781	BA3294/03	9202/22	12/10/2022	WHS
#REF!	QAA	Craigavon Hospital	02	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	17/01/2024	Strongly Presumed Similar to	Very Low Risk	65782	BA3294/03	9202/22	12/10/2022	WHS
#REF!	QAA	Craigavon Hospital	02	Sink Pad		Composite Material	Chrysotile	Composite Materials	Low	Apply Caution when Maintaining	Re-inspection	HSG227	Unchecked	Very Low Risk	3	17/01/2024	Stronnly Presumed	Low Risk	65783		9202/22	12/10/2022	WHS
#REF!	QAA	Craigavon Hospital	02	NO ASBESTOS		NO ASBESTOS	NO ASBESTOS	Encapsulated Spray or Lagoins/Unsealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	65784	BA3294/04	9326/17	17/04/2018	WHS
#REF!	QAA	Craigavon Hospital	02	NO ASBESTOS		NO ASBESTOS	NO ASBESTOS	Enclosed Pipework Insulation Residue	Loose asbestos debris or residue	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	65785	BA3294/05	9326/17	17/04/2018	WHS
#REF!	QAA	Craigavon Hospital	02	Boiler Lagging		Thermal Insulation	Presumed Asbestos	Encapsulated Spray or Lagoins/Unsealed ACM	Significant areas of damage or	Further investigation Required	Re-inspection	HSG227	Unchecked	High Risk	11	19/07/2023	Presumed	High Risk	65786		9202/22	12/10/2022	WHS

#REF!	QAA	Craigavon Hospital	02	Pipe Residue		Thermal Insulation	NO ASBESTOS	Encapsulated Spray or Lagoin/Unsealed ACM	Significant areas of damage or	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Presumed	Asbestos Removed	65787		9326/17	17/04/2018	WHS
#REF!	QAA	Craigavon Hospital	02	Pipe Residue		Thermal Insulation	Presumed Asbestos	Encapsulated Spray or Lagoin/Unsealed ACM	Significant areas of damage or	Further investigation Required	Re-inspection	HSG227	Unchecked	High Risk	11	18/04/2023	Presumed	High Risk	65788		9202.22	12/10/2022	WHS
#REF!	QAA	Craigavon Hospital	02	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	65789	BA3294/06	9326/17	17/04/2018	WHS
#REF!	QAA	Craigavon Hospital	02	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	Asbestos Removed	65790	BA3294/07	9326/17	17/04/2018	WHS
#REF!	QAA	Craigavon Hospital	02	Plastics	Storage Unit to back wall of Boiler House	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	65791	BA3294/08	9326/17	17/04/2018	WHS
#REF!	QAA	Craigavon Hospital	02	Thermal Insulation		Thermal Insulation	Presumed Asbestos	Encapsulated Spray or Lagoin/Unsealed ACM	Medium	Further investigation Required	Re-inspection	HSG227	Unchecked	High Risk	10	17/01/2024	Presumed	High Risk	65792		9202.22	12/10/2022	WHS
#REF!	QAA	Craigavon Hospital	02	Ropes	Wrapped around Pipework on Rear wall of Boiler House	Textiles & Paper	Chrysotile	Unsealed Rope	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Low Risk	6	17/01/2024	Identified	Low Risk	65793	BA3294/09	9202/22	06/01/2020	WHS
#REF!	QAA	Craigavon Hospital	02	Flash Guard		Textiles & Paper	NO ASBESTOS	Enclosed Fuse Flash Guards	Medium	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	06/12/2019	Presumed	Asbestos Removed	65794		9326/17	17/04/2018	WHS
#REF!	QAA	Craigavon Hospital	02	Flash Guard		Textiles & Paper	NO ASBESTOS	Enclosed Fuse Flash Guards	Medium	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	06/12/2019	Presumed	Asbestos Removed	65795		9326/17	17/04/2018	WHS
#REF!	QAA	Craigavon Hospital	02	Bitumen Felt		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	65796	BA3294/10	9326/17	17/04/2018	WHS
#REF!	QAA	Craigavon Hospital	02	Rope Seal		Textiles & Paper	NO ASBESTOS	Encapsulated Spray or Lagoin/Unsealed ACM	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	65797	BA3294/11	9326/17	17/04/2018	WHS
#REF!	QAA	Craigavon Hospital	02	Woven Asbestos Textile		Textiles & Paper	Chrysotile	Unsealed Rope	Low	Apply caution when maintaining and affix ID labels	Re-inspection	HSG227	Unchecked	Low Risk	6	17/01/2024	Identified	Low Risk	65798	BA3294/12	9202.22	12/10/2022	WHS
#REF!	QAA	Craigavon Hospital	02	Woven Asbestos Textile		Textiles & Paper	Chrysotile	Unsealed Rope	Low	Programme for removal	Re-inspection	HSG227	Unchecked	Low Risk	6	17/01/2024	Strongly Presumed Similar to	Low Risk	65799	BA3294/12	9202.22	12/10/2022	WHS
#REF!	QAA	Craigavon Hospital	02	Flash Guard		Textiles & Paper	Presumed Asbestos	Enclosed Fuse Flash Guards	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Medium Risk	8	19/07/2023	Presumed	Medium Risk	65800		9202.22	12/10/2022	WHS
#REF!	QAA	Craigavon Hospital	02	Rope Seal		Textiles & Paper	Presumed Asbestos	Unsealed Rope	Low	Apply caution when maintaining and affix ID labels	Re-inspection	HSG227	Unchecked	Medium Risk	8	17/01/2024	Presumed	Medium Risk	65801		9202.22	06/01/2020	WHS
#REF!	QAA	Craigavon Hospital	02	Thermal Insulation		Thermal Insulation	Presumed Asbestos	Encapsulated Spray or Lagoin/Unsealed ACM	Medium	Apply caution when maintaining and affix ID labels	Re-inspection	HSG227	Unchecked	High Risk	10	18/04/2023	Presumed	High Risk	65802		9202.22	12/10/2022	WHS
#REF!	QAA	Craigavon Hospital	08	Bitumen Felt		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	06/09/2023	Identified	Very Low Risk	65803	BA3295/01	9202.22	18/10/2022	WHS
#REF!	QHB	Crozier House	02	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	65804	BA3336/01	9326/17	04/11/2018	WHS
#REF!	QHB	Crozier House	02	Door Panel		Insulating Board	NO ASBESTOS	Encapsulated Spray or Lagoin/Unsealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	65805	BA3336/02	9326/17	04/11/2018	WHS
#REF!	QHB	Crozier House	02	Bitumen Adhesive		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	65806	BA3336/03	9326/17	04/11/2018	WHS
#REF!	QHB	Crozier House	02	Bitumen Felt		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	65807	BA3336/04	9326/17	04/11/2018	WHS
#REF!	QHB	Crozier House	02	Door Panel		Insulating Board	NO ASBESTOS	Encapsulated Spray or Lagoin/Unsealed ACM	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	65808	BA3336/05	9326/17	04/11/2018	WHS
#REF!	QAA	Craigavon Hospital	08	Bitumen Felt		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	65809	BA3295/02	9326/17	04/10/2018	WHS
#REF!	QAA	Craigavon Hospital	08	Bitumen Felt		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	65810	BA3295/02	9326/17	04/10/2018	WHS
#REF!	QAA	Craigavon Hospital	08	Bitumen Felt		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	65811	BA3295/03	9326/17	04/10/2018	WHS
#REF!	QAA	Craigavon Hospital	08	Gaskets		Textiles & Paper	NO ASBESTOS	Encapsulated Spray or Lagoin/Unsealed ACM	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	65812	BA3295/04	9326/17	04/10/2018	WHS
#REF!	QAA	Craigavon Hospital	08	Gaskets		Textiles & Paper	NO ASBESTOS	Encapsulated Spray or Lagoin/Unsealed ACM	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	65813	BA3295/04	9326/17	04/10/2018	WHS
#REF!	QAA	Craigavon Hospital	08	Infill Panel	Outside the door to the Water Treatment Room	Insulating Board	NO ASBESTOS	Enclosed Spray or Lagoin/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	65814	BA3295/05	9326/17	04/10/2018	WHS
#REF!	QAA	Craigavon Hospital	08	Brake Pads	Lift Plant	Reinforced Comosstos	Presumed Asbestos	Encapsulated Spray or Lagoin/Unsealed AIB	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Medium Risk	8	08/03/2023	Presumed	Medium Risk	65815		9302/22	18/10/2022	WHS
#REF!	QAA	Craigavon Hospital	08	Ceiling Panelling		Insulating Board	NO ASBESTOS	Enclosed Spray or Lagoin/Sealed ACM	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	65816	BA3295/06	9326/17	04/10/2018	WHS
#REF!	QAA	Craigavon Hospital	08	Ropes		Textiles & Paper	Chrysotile	Encapsulated Spray or Lagoin/Unsealed AIB	Low	Apply caution when maintaining and affix ID labels	Re-inspection	HSG227	Unchecked	Low Risk	6	06/09/2023	Identified	Low Risk	65817	BA3295/07	9302/22	18/10/2022	WHS
#REF!	QAA	Craigavon Hospital	08	NO ASBESTOS		NO ASBESTOS		Encapsulated Spray or Lagoin/Unsealed ACM	Low	No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	Asbestos Removed	65818	BA3295/07	9811/19	07/01/2020	WH Stephens
#REF!	QAA	Craigavon Hospital	08	Fuse Flash Guards		Textiles & Paper	Presumed Asbestos	Encapsulated Spray or Lagoin/Unsealed AIB	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Medium Risk	9	06/09/2023	Presumed	Medium Risk	65819		9302/22	18/10/2022	WHS
#REF!	QAA	Craigavon Hospital	08	Fuse Flash Guards		Textiles & Paper	Presumed Asbestos	Encapsulated Spray or Lagoin/Unsealed AIB	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Medium Risk	9	08/03/2023	Presumed	Medium Risk	65820		9302/22	18/10/2022	WHS
#REF!	QAA	Craigavon Hospital	08	Fuse Flash Guards		Textiles & Paper	Presumed Asbestos	Encapsulated Spray or Lagoin/Unsealed AIB	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Medium Risk	9	08/03/2023	Presumed	Medium Risk	65821		9302/22	18/10/2022	WHS
#REF!	QAA	Craigavon Hospital	08	NO ASBESTOS		NO ASBESTOS		Enclosed Spray or Lagoin/Sealed ACM	Medium	No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0		Identified	Asbestos Removed	65822	BA3295/08	9811/19	07/01/2020	WH Stephens
#REF!	QAA	Craigavon Hospital	08	NO ASBESTOS		NO ASBESTOS		Enclosed Spray or Lagoin/Sealed ACM	Medium	No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	Asbestos Removed	65823	BA3295/08	9811/19	07/01/2020	WH Stephens
#REF!	QAA	Craigavon Hospital	08	Toilet Cistern		Composite Material	Amosite	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	4	06/09/2023	Identified	Very Low Risk	65824	BA3295/09	9302/22	18/10/2022	WHS
#REF!	QAA	Craigavon Hospital	08	Floor Tiles		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	06/09/2023	Identified	Very Low Risk	65825	BA3295/10	9302/22	18/10/2022	WHS
#REF!	QAA	Craigavon Hospital	08	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	65826	BA3295/11	9326/17	04/10/2018	WHS
#REF!	QAA	Craigavon Hospital	08	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	65827	BA3295/12	9326/17	04/10/2018	WHS
#REF!	QAA	Craigavon Hospital	08	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	65829	BA3295/13	9326/17	04/10/2018	WHS
#REF!	QAA	Craigavon Hospital	08	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	65830	BA3295/14	9326/17	04/10/2018	WHS
#REF!	QAA	Craigavon Hospital	08	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	65831	BA3295/15	9326/17	04/10/2018	WHS
#REF!	QAA	Craigavon Hospital	08	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	65832	BA3295/16	9326/17	04/10/2018	WHS
#REF!	QAA	Craigavon Hospital	08	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	65833	BA3295/17	9326/17	04/10/2018	WHS
#REF!	QAA	Craigavon Hospital	08	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	65834	BA3295/18	9326/17	04/10/2018	WHS
#REF!	QAA	Craigavon Hospital	08	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	65835	BA3295/18	9326/17	04/10/2018	WHS
#REF!	QAA	Craigavon Hospital	08	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	65836	BA3295/18	9326/17	04/10/2018	WHS
#REF!	QAA	Craigavon Hospital	08	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	65837	BA3295/18	9326/17	04/10/2018	WHS
#REF!	QAA	Craigavon Hospital	08	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	65838	BA3295/19	9326/17	04/10/2018	WHS
#REF!	QAA	Craigavon Hospital	08	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	65839	BA3295/19	9326/17	04/10/2018	WHS
#REF!	QAA	Craigavon Hospital	08	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	65840	BA3295/20	9326/17	04/10/2018	WHS
#REF!	QAA	Craigavon Hospital	08	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	65841	BA3295/21	9326/17	04/10/2018	WHS
#REF!	QAA	Craigavon Hospital	08	Insulating Board		Insulating Board	NO ASBESTOS	Enclosed Spray or Lagoin/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	65842	BA3295/22	9326/17	04/10/2018	WHS
#REF!	QAA	Craigavon Hospital	08	Ceiling Board		Insulating Board	NO ASBESTOS	Enclosed Spray or Lagoin/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	65843	BA3295/23	9326/17	04/10/2018	WHS
#REF!	QAA	Craigavon Hospital	08	NO ASBESTOS		NO ASBESTOS		Encapsulated Spray or Lagoin/Unsealed ACM	Significant areas of damage or	No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0		Presumed	Asbestos Removed	65844		9811/19	07/01/2020	WH Stephens
#REF!	QAA	Craigavon Hospital	08	Cylinder insulation		Thermal Insulation	NO ASBESTOS	Enclosed Spray or Lagoin/Sealed AIB	Areas of damage or deterioration	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	12/12/2018	Identified	Asbestos Removed	65845	BA3295/24	9326/17	04/10/2018	WHS
#REF!	QAA	Craigavon Hospital	08	NO ASBESTOS		NO ASBESTOS		Unsealed Spray / Lagging / Duct Debris	Loose asbestos debris or residue	No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0		Identified	Asbestos Removed	65846	BA3295/25	9811/19	07/01/2020	WH Stephens
#REF!	QAA	Craigavon Hospital	08	NO ASBESTOS		NO ASBESTOS				No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0		Identified	Asbestos Removed	65847	BA3295/26	9811/19	07/01/2020	WH Stephens
#REF!	QAA	Craigavon Hospital	08	NO ASBESTOS		NO ASBESTOS		Encapsulated Spray or Lagoin/Unsealed ACM	Medium	No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	Asbestos Removed	65848	BA3295/26	9811/19	07/01/2020	WH Stephens
#REF!	QAA	Craigavon Hospital	08	General Debris		General Debris	NO ASBESTOS	Unsealed Spray / Lagging / Duct Debris	Significant areas of damage or	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	65849	BA3295/27	9326/17	04/10/2018	WHS
#REF!	QAA	Craigavon Hospital	08	Cylinder insulation		Thermal Insulation	NO ASBESTOS	Enclosed Spray or Lagoin/Sealed ACM	Minor damage or deterioration	No further action required (Asbestos removed)	ACM Removed	HSG227	Unchecked	NO ASBESTOS	0	06/12/2019	Strongly Presumed Similar to	Asbestos Removed	65850	BA3295/24	9326/17	04/10/2018	WHS
#REF!	OAA	Craigavon Hospital	18	Underdeck to Roof Verge		Cement Products	Chrysotile	Cement Sheets	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	4	24/06/2023	Strongly Presumed	Very Low Risk	65885		9302/22	24/06/2022	WHS
#REF!	OAA	Craigavon Hospital	18	Cement Flat Sheet		Cement Products	Chrysotile	Cement Sheets	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	4	24/06/2023	Identified	Very Low Risk	65886	BA3359/01	9302/22	24/06/2022	WHS
#REF!	QAA	Craigavon Hospital	18	Cement Flat Sheet		Cement Products	Chrysotile	Cement Sheets	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	4	24/06/2023	Strongly Presumed Similar to	Very Low Risk	65887	BA3359/01	9302/22	24/06/2022	WHS
#REF!	RAA	South Tyrone Hospital	09	Anti Vibration Pads	Above Suspended Ceilino	Textiles & Paper	Chrysotile	Enclosed Spray or	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Low Risk	5	15/12/2023	Identified	Low Risk	65888	BA3319/05	9302/22	15/12/2022	WHS
#REF!	RAA	South Tyrone Hospital	09	Wall Panels	Rear Wall	Insulating Board	NO ASBESTOS	Unsealed Asbestos Insulation Board		No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	65889	BA3319/01	9506/18	12/05/2018	WHS
#REF!	RAA	South Tyrone Hospital	09	Pipe Insulation	Throughout	Thermal Insulation	NO ASBESTOS	Insulation		No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	65890	BA3319/02	9506/18	12/05/2018	WHS
#REF!	RAA	South Tyrone Hospital	09	Pipe Insulation	Throughout	Thermal Insulation	NO ASBESTOS	Insulation		No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	65891	BA3319/02	9506/18	12/05/2018	WHS
#REF!	RAA	South Tyrone Hospital	09	Fuse Flash Bands		Textiles & Paper	Presumed Asbestos	Enclosed Fuse Flash Guards	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Medium Risk	8	15/12/2023	Presumed	Low Risk	65892		9302/22	15/12/2022	WHS
#REF!	RAA	South Tyrone Hospital	09	Fuse Flash Guards		Textiles & Paper	Presumed Asbestos	Enclosed Fuse Flash Guards	Medium	Further investigation Required	Re-inspection	HSG227	Unchecked	Medium Risk	8	15/12/2023	Presumed	Low Risk	65893		9302/22	15/12/2022	WHS
#REF!	RAA	South Tyrone Hospital	09	Flash Guard	Fuse flash ouards	Textiles & Paper	Chrysotile	Enclosed Fuse Flash Guards	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Low Risk	6	15/12/2023	Identified	Low Risk	65894	BA9344	9302/22	15/12/2022	WHS
#REF!	RAA	South Tyrone Hospital	09	Fuse Flash Guards		Textiles & Paper	Presumed Asbestos	Enclosed Fuse Flash Guards	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Medium Risk	8	15/12/2023	Presumed	Medium Risk	65895		9302/22	15/12/2022	WHS
#REF!	RAA	South Tyrone Hospital	09	Fuse Flash Guards		Textiles & Paper	Presumed Asbestos	Enclosed Fuse Flash Guards	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Medium Risk	8	15/12/2023	Presumed	Medium Risk	65896		9302/22	15/12/2022	WHS
#REF!	RAA	South Tyrone Hospital	09	Fire Break Panel	Above suspended ceiling	Insulating Board	NO ASBESTOS	Unsealed Asbestos Insulation Board		No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	65897	BA3319/03	9506/18	12/05/2018	WHS
#REF!	RAA	South Tyrone Hospital	09	Fire Break Panel	Above Suspended Ceiling	Insulating Board	NO ASBESTOS	Unsealed Asbestos Insulation Board		No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	65898	BA3319/03	9506/18	12/05/2018	WHS
#REF!	RAA	South Tyrone Hospital	09	Anti Vibration Pads	Above Suspended Ceiling	Textiles & Paper	Chrysotile	Enclosed Woven Textile	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Low Risk	5	15/12/2023	Strongly Presumed Similar to	Low Risk	65899	BA3319/04	9302/22	15/12/2022	WHS
#REF!	RAA	South Tyrone Hospital	09	Stair Nosing	Stairs	Composite Material	NO ASBESTOS	Composite Materials		No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	65900	BA3319/05	9506/18	12/05/2018	WHS
#REF!	RAA	South Tyrone Hospital	09	Stair Nosing		Composite Material	NO ASBESTOS	Composite Materials		No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	65901	BA3319/05	9506/18	12/05/2018	WHS

#REF!	RAA	South Tyrone Hospital	09	Gaskets		Textiles & Paper	NO ASBESTOS	Composite Materials		No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	65902	BA3319/06	9509/18	12/05/2018	WHS
#REF!	RAA	South Tyrone Hospital	09	Bitumen Felt	Packers Above Suspended Ceiling	Composite Material	Chrysotile	Composite Materials	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	4	15/12/2023	Identified	Very Low Risk	65903	BA3319/07	9302/2	15/12/2022	WHS
#REF!	RAA	South Tyrone Hospital	09	Bitumen Felt	Packers Above Suspended Ceiling	Composite Material	Chrysotile	Composite Materials	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	4	15/12/2023	Strongly Presumed Similar to	Very Low Risk	65904	BA3319/07	9302/2	15/12/2022	WHS
#REF!	RAA	South Tyrone Hospital	09	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials		No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	65905	BA3319/08	9509/18	12/05/2018	WHS
#REF!	RAA	South Tyrone Hospital	09	Fire Break Panel	Above Suspended Ceiling	Insulating Board	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	65906	BA3319/09	9509/18	12/05/2018	WHS
#REF!	RAA	South Tyrone Hospital	09	Boardino	Wall vents	Cement Products	Chrysotile	Sealed Cement Encapsulated Asbestos Insulation Board	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	4	15/12/2023	Identified	Very Low Risk	65907	BA3319/10	9302/2	15/12/2022	WHS
#REF!	RAA	South Tyrone Hospital	09	Soffit Boards	External lobby Physiotherapy	Insulating Board	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	65909	BA3319/11	9509/18	12/05/2018	WHS
#REF!	RAA	South Tyrone Hospital	09	Damo Proof Course	External	Composite Material	Chrysotile	Composite Materials	Very Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	2	15/12/2023	Identified	Very Low Risk	65910	BA3319/12	9302/2	15/12/2022	WHS
#REF!	QAA	Craigavon Hospital	18	Fuse Flash Guards		Textiles & Paper	NO ASBESTOS	Enclosed Fuse Flash Guards	Very Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	24/07/2018	Presumed	Asbestos Removed	65918		9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	20	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	65988	BA3332/01	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	20	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	65989	BA3332/01	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	20	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	65990	BA3332/01	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	20	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	65991	BA3332/01	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	20	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	65992	BA3332/01	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	20	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	65993	BA3332/01	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	20	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	65994	BA3332/01	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	20	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	65995	BA3332/01	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	20	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	65996	BA3332/01	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	20	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	65997	BA3332/01	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	20	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	65998	BA3332/01	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	20	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	65999	BA3332/01	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	20	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66000	BA3332/01	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	20	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66001	BA3332/02	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	20	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66002	BA3332/02	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	20	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66003	BA3332/02	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	20	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66004	BA3332/02	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	20	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66005	BA3332/02	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	20	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66006	BA3332/02	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	20	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66007	BA3332/02	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	20	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66008	BA3332/02	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	20	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66009	BA3332/02	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	20	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66010	BA3332/02	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	20	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66011	BA3332/02	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	20	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66012	BA3332/02	9724/17	05/09/2017	WHS
#REF!	OAA	Craigavon Hospital	20	Flash Guard		Textiles & Paper	Presumed Asbestos	Enclosed Fuse Flash Guards	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Medium Risk	8	24/06/2023	Presumed	Medium Risk	66013		9302/2	24/06/2022	WHS
#REF!	OAA	Craigavon Hospital	20	Flash Guard		Textiles & Paper	Presumed Asbestos	Enclosed Fuse Flash Guards	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Medium Risk	8	24/12/2022	Presumed	Medium Risk	66014		9302/2	24/06/2022	WHS
#REF!	QAA	Craigavon Hospital	20	Flash Guard		Textiles & Paper	Presumed Asbestos	Enclosed Fuse Flash Guards	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Medium Risk	8	24/12/2022	Presumed	Medium Risk	66015		9302/2	24/06/2022	WHS
#REF!	QAA	Craigavon Hospital	20	Stair Nosing		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66016	BA3332/07	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	20	Floor Tiles	Below Carpet	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66017	BA3332/08	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	20	Floor Tiles	Below Carpet	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66018	BA3332/08	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	20	Floor Tiles	Below Carpet	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66019	BA3332/08	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	20	Floor Tiles	Below Carpet	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66020	BA3332/08	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	20	Floor Tiles	Below Carpet	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66021	BA3332/08	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	20	Floor Tiles	Below Carpet	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66022	BA3332/08	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	20	Floor Tiles	Below Carpet	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66023	BA3332/08	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	20	Floor Tiles	Below Carpet	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66024	BA3332/08	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	20	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66025	BA3332/08	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	20	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66026	BA3332/08	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	20	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66027	BA3332/09	9724/17	05/09/2017	WHS
#REF!	OAA	Craigavon Hospital	20	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	None	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	2	24/06/2023	Identified	Very Low Risk	66028	BA3332/10	9302/2	24/06/2022	WHS
#REF!	OAA	Craigavon Hospital	20	Sink Pad		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	24/06/2023	Identified	Very Low Risk	66029	BA3332/11	9302/2	24/06/2022	WHS
#REF!	QHB	Crozier House	01	Board		Insulating Board	NO ASBESTOS	Encapsulated Spray or Laqoino/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66030	BA3345/01	9326/17	04/04/2018	WHS
#REF!	QHB	Crozier House	01	Bitumen Felt		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66031	BA3345/02	9326/17	04/04/2018	WHS
#REF!	QHB	Crozier House	01	Toilet Cistern		Composite Material	Amosite	Composite Materials	Low	Apply Caution when Maintaining	Re-inspection	HSG227	Unchecked	Very Low Risk	4	06/10/2021	Identified	Very Low Risk	66032	BA3345/03	9811/19	17/12/2019	WH Stephens
#REF!	QHB	Crozier House	01	Toilet Cistern		Composite Material	Amosite	Composite Materials	Low	Apply Caution when Maintaining	Review – No Change	HSG227	Unchecked	Very Low Risk	4	06/10/2021	Strongly Presumed Similar to	Very Low Risk	66033	BA3345/03	9811/19	17/12/2019	WH Stephens
#REF!	QHB	Crozier House	01	Toilet Cistern		Composite Material	Amosite	Composite Materials	Low	Apply Caution when Maintaining	Review – No Change	HSG227	Unchecked	Very Low Risk	4	06/10/2021	Strongly Presumed Similar to	Very Low Risk	66034	BA3345/03	9811/19	17/12/2019	WH Stephens
#REF!	QHB	Crozier House	01	Gaskets		Textiles & Paper	Chrysotile	Encapsulated Spray or Laqoino/Unsealed AIB	Low	Apply Caution when Maintaining	Re-inspection	HSG227	Unchecked	Low Risk	6	06/10/2021	Identified	Low Risk	66035	BA3345/04	9811/19	17/12/2019	WH Stephens
#REF!	QAA	Craigavon Hospital	20	Fire Break Panel		Insulating Board	NO ASBESTOS	Encapsulated Spray or Laqoino/Unsealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66036	BA3332/03	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	20	Fire Break Panel		Insulating Board	NO ASBESTOS	Encapsulated Spray or Laqoino/Unsealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66037	BA3332/03	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	20	Fire Break Panel		Insulating Board	NO ASBESTOS	Encapsulated Spray or Laqoino/Unsealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66038	BA3332/03	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	20	Insulating Debris		General Debris	NO ASBESTOS	Encapsulated Spray or Laqoino/Unsealed AIB	Loose asbestos debris or residue	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66039	BA3332/04	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	20	Roofing Felts		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66040	BA3332/05	9724/17	05/09/2017	WHS
#REF!	OAA	Craigavon Hospital	20	Soffit Boards		Cement Products	Chrysotile	Cement Sheets	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	4	24/06/2023	Identified	Very Low Risk	66041	BA3332/06	9302/2	24/06/2022	WHS
#REF!	QAA	Craigavon Hospital	20	Verge Cloak		Cement Products	Presumed Asbestos	Cement Sheets	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Low Risk	6	24/06/2023	Presumed	Low Risk	66042		9302/2	24/06/2022	WHS
#REF!	QHB	Crozier House	01	Insulating Board		Insulating Board	NO ASBESTOS	Encapsulated Spray or Laqoino/Unsealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66043	BA3345/05	9326/17	04/04/2018	WHS
#REF!	QHB	Crozier House	01	Back Board		Insulating Board	NO ASBESTOS	Encapsulated Spray or Laqoino/Unsealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66044	BA3345/06	9326/17	04/04/2018	WHS
#REF!	QHB	Crozier House	01	Ceiling Board		Insulating Board	NO ASBESTOS	Encapsulated Spray or Laqoino/Unsealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66045	BA3345/07	9326/17	04/04/2018	WHS
#REF!	QHB	Crozier House	01	Insulating Board		Insulating Board	NO ASBESTOS	Enclosed Spray or Laqoino/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66046	BA3345/08	9326/17	04/04/2018	WHS
#REF!	QHB	Crozier House	01	Insulating Board		Insulating Board	NO ASBESTOS	Enclosed Spray or Laqoino/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66047	BA3345/08	9326/17	04/04/2018	WHS
#REF!	QHB	Crozier House	01	Insulating Board		Insulating Board	NO ASBESTOS	Enclosed Spray or Laqoino/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66048	BA3345/08	9326/17	04/04/2018	WHS
#REF!	QHB	Crozier House	01	Insulating Board		Insulating Board	NO ASBESTOS	Enclosed Spray or Laqoino/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66049	BA3345/08	9326/17	04/04/2018	WHS
#REF!	QHB	Crozier House	01	Insulating Board		Insulating Board	NO ASBESTOS	Enclosed Spray or Laqoino/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66050	BA3345/08	9326/17	04/04/2018	WHS
#REF!	QHB	Crozier House	01	Insulating Board		Insulating Board	NO ASBESTOS	Enclosed Spray or Laqoino/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66051	BA3345/08	9326/17	04/04/2018	WHS
#REF!	QHB	Crozier House	01	Insulating Board		Insulating Board	NO ASBESTOS	Enclosed Spray or Laqoino/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66052	BA3345/08	9326/17	04/04/2018	WHS
#REF!	QHB	Crozier House	01	Insulating Board		Insulating Board	NO ASBESTOS	Enclosed Spray or Laqoino/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66053	BA3345/08	9326/17	04/04/2018	WHS
#REF!	QHB	Crozier House	01	Insulating Board		Insulating Board	NO ASBESTOS	Enclosed Spray or Laqoino/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66054	BA3345/08	9326/17	04/04/2018	WHS
#REF!	QHB	Crozier House	01	Insulating Board		Insulating Board	NO ASBESTOS	Enclosed Spray or Laqoino/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66055	BA3345/08	9326/17	04/04/2018	WHS
#REF!	QHB	Crozier House	01	Insulating Board		Insulating Board	NO ASBESTOS	Enclosed Spray or Laqoino/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66056	BA3345/08	9326/17	04/04/2018	WHS
#REF!	QHB	Crozier House	01	Roofing Felts		Reinforced Composites	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66057	BA3345/09	9326/17	04/04/2018	WHS
#REF!	QHB	Crozier House	01	Roofing Felts		Reinforced Composites	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66058	BA3345/10	9326/17	04/04/2018	WHS

#REF!	QHB	Crozier House	01	Door Panel	Insulating Board	Amosite/Chrysotile	Enclosed Spray or	Low	Apply Caution when Maintaining	Review – No Change	HSG227	Unchecked	Low Risk	6	06/10/2021	Identified	Low Risk	66059	BA3345/11	9811/1	17/12/2019	WH Stephens
#REF!	QHB	Crozier House	01	Door Panel	Insulating Board	Amosite/Chrysotile	Enclosed Spray or	Low	Apply Caution when Maintaining	Review – No Change	HSG227	Unchecked	Low Risk	6	06/10/2021	Strongly Presumed Similar to	Low Risk	66060	BA3345/11	9811/1	17/12/2019	WH Stephens
#REF!	OHB	Crozier House	01	Floor Tile and Bitumen Adhesive	Composite Material	Chrysotile	Composite Materials	Low	Apply Caution when Maintaining	Review – No Change	HSG227	Unchecked	Very Low Risk	3	06/10/2021	Identified	Very Low Risk	66061	BA3345/12	9811/1	17/12/2019	WH Stephens
#REF!	QHB	Crozier House	01	Floor Tile and Bitumen Adhesive	Composite Material	Chrysotile	Composite Materials	Low	Apply caution when maintaining and affix ID labels	Review – No Change	HSG227	Unchecked	Very Low Risk	3	06/10/2021	Strongly Presumed Similar to	Very Low Risk	66062	BA3345/12	9811/1	17/12/2019	WH Stephens
#REF!	QHB	Crozier House	01	Floor Tile and Bitumen Adhesive	Composite Material	Chrysotile	Composite Materials	Low	Apply caution when maintaining and affix ID labels	Review – No Change	HSG227	Unchecked	Very Low Risk	3	06/10/2021	Strongly Presumed Similar to	Very Low Risk	66063	BA3345/12	9811/1	17/12/2019	WH Stephens
#REF!	QHB	Crozier House	01	Floor Tile and Bitumen Adhesive	Composite Material	Chrysotile	Composite Materials	Low	Apply Caution when Maintaining	Review – No Change	HSG227	Unchecked	Very Low Risk	3	06/10/2021	Strongly Presumed Similar to	Very Low Risk	66064	BA3345/12	9811/1	17/12/2019	WH Stephens
#REF!	QHB	Crozier House	01	Insulating Board	Insulating Board	NO ASBESTOS	Encapsulated Spray or Lagging/Unsealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66065	BA3345/13	9326/1	04/04/2018	WHS
#REF!	QHB	Crozier House	01	Insulating Board	Insulating Board	NO ASBESTOS	Encapsulated Spray or Lagging/Unsealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66066	BA3345/14	9326/1	04/04/2018	WHS
#REF!	QHB	Crozier House	01	Insulating Board	Insulating Board	NO ASBESTOS	Encapsulated Spray or Lagging/Unsealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66067	BA3345/14	9326/1	04/04/2018	WHS
#REF!	QHB	Crozier House	01	Sink Pad	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66068	BA3345/15	9326/1	04/04/2018	WHS
#REF!	QHB	Crozier House	01	Insulating Board	Insulating Board	NO ASBESTOS	Enclosed Spray or Lagging/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66069	BA3345/16	9326/1	04/04/2018	WHS
#REF!	QHB	Crozier House	01	Insulating Board	Insulating Board	NO ASBESTOS	Enclosed Spray or Lagging/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66070	BA3345/16	9326/1	04/04/2018	WHS
#REF!	QHB	Crozier House	01	Insulating Board	Insulating Board	NO ASBESTOS	Enclosed Spray or Lagging/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66071	BA3345/16	9326/1	04/04/2018	WHS
#REF!	QHB	Crozier House	01	Insulating Board	Insulating Board	NO ASBESTOS	Enclosed Spray or Lagging/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66072	BA3345/17	9326/1	04/04/2018	WHS
#REF!	QAA	Craigavon Hospital	18						Re-Survey	Review – No Change	HSG227	Checked	High Risk	0				66073		9326/1	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	18						Re-Survey	Review – No Change	HSG227	Checked	High Risk	0				66074		9326/1	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	18							Review – No Change	HSG227	Checked	High Risk	0				66075		9326/1	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	18							Review – No Change	HSG227	Checked	High Risk	0	24/07/2018			66076		9326/1	05/09/2017	WHS
#REF!	QHB	Crozier House	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	66077		9326/1	04/04/2018	WHS
#REF!	QHB	Crozier House	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	66078		9326/1	04/04/2018	WHS
#REF!	OHB	Crozier House	01						Further investigation Received	Review – No Change	HSG227	Checked	High Risk	0				66079		9326/1	04/04/2018	WHS
#REF!	QHF	Skeagh House	01	Roofing Felts	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66080	BA3346/01	9326/1	04/04/2018	WHS
#REF!	QHF	Skeagh House	01	Back Board	Insulating Board	Amosite/Chrysotile	Encapsulated Spray or Lagging/Unsealed AIB	Low	Remove	Re-inspection	HSG227	Unchecked	Medium Risk	7	10/03/2023	Identified	Medium Risk	66081	BA3346/02	9299/2	11/04/2022	WHS
#REF!	QHF	Skeagh House	01	Lino Flooring	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66082	BA3346/03	9326/1	04/04/2018	WHS
#REF!	QHF	Skeagh House	01	Lino Flooring	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66083	BA3346/03	9326/1	04/04/2018	WHS
#REF!	QHF	Skeagh House	01	Lino Flooring	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66084	BA3346/03	9326/1	04/04/2018	WHS
#REF!	QHF	Skeagh House	01	Lino Flooring	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66085	BA3346/03	9326/1	04/04/2018	WHS
#REF!	QHF	Skeagh House	01	Lino Flooring	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66086	BA3346/03	9326/1	04/04/2018	WHS
#REF!	QHF	Skeagh House	01	Sink Pad	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66087	BA3346/04	9326/1	04/04/2018	WHS
#REF!	QHF	Skeagh House	01	Sink Pad	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66088	BA3346/04	9326/1	04/04/2018	WHS
#REF!	QHF	Skeagh House	01	Sink Pad	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66089	BA3346/04	9326/1	04/04/2018	WHS
#REF!	QHF	Skeagh House	01	Sink Pad	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66090	BA3346/05	9326/1	04/04/2018	WHS
#REF!	QHF	Skeagh House	01	Lino Flooring	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66091	BA3346/06	9326/1	04/04/2018	WHS
#REF!	QHF	Skeagh House	01	Sink Pad	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66092	BA3346/07	9326/1	04/04/2018	WHS
#REF!	QHF	Skeagh House	01	Stair Nosing	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66093	BA3346/08	9326/1	04/04/2018	WHS
#REF!	QHF	Skeagh House	01	Lino Flooring	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66094	BA3346/03	9326/1	04/04/2018	WHS
#REF!	QHF	Skeagh House	01	Lino Flooring	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66095	BA3346/03	9326/1	04/04/2018	WHS
#REF!	QHF	Skeagh House	01	Lino Flooring	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66096	BA3346/03	9326/1	04/04/2018	WHS
#REF!	QHF	Skeagh House	01	Lino Flooring	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66097	BA3346/03	9326/1	04/04/2018	WHS
#REF!	QHF	Skeagh House	01	Lino Flooring	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66098	BA3346/03	9326/1	04/04/2018	WHS
#REF!	QHF	Skeagh House	01	Sink Pad	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66099	BA3346/09	9326/1	04/04/2018	WHS
#REF!	QHF	Skeagh House	01	Back Board	Insulating Board	Amosite/Chrysotile	Encapsulated Spray or Lagging/Unsealed AIB	Low	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	Medium Risk	7	10/03/2023	Identified	Medium Risk	66100	BA3346/10	9299/2	11/04/2022	WHS
#REF!	QHF	Skeagh House	01	Ceiling Board	Insulating Board	Amosite/Chrysotile	Enclosed Spray or	Low	Label & Manage	Re-inspection	HSG227	Unchecked	Low Risk	6	08/09/2023	Identified	Low Risk	66101	BA3346/11	9299/2	11/04/2022	WHS
#REF!	QHF	Skeagh House	01	Ceiling Board	Insulating Board	Amosite/Chrysotile	Encapsulated Spray or Lagging/Unsealed AIB	Low	Encapsulate, label and manage	Re-inspection	HSG227	Unchecked	Medium Risk	7	08/09/2023	Identified	Low Risk	66102	BA3346/12	9299/2	11/04/2022	WHS
#REF!	QHF	Skeagh House	01	Fuse Flash Guards	Textiles & Paper	Presumed Asbestos	Encapsulated Spray or Lagging/Unsealed AIB	Medium	Apply caution when maintaining and affix ID labels	Re-inspection	HSG227	Unchecked	Medium Risk	9	10/03/2023	Presumed	Medium Risk	66103		9299/2	11/04/2022	WHS
#REF!	QHF	Skeagh House	01	Verge Cloak	Cement Products	Chrysotile	Cement Sheets	Low	Apply caution when maintaining and affix ID labels	Re-inspection	HSG227	Unchecked	Very Low Risk	4	09/09/2023	Identified	Very Low Risk	66104	BA3346/13	9299/2	11/04/2022	WHS
#REF!	QHF	Skeagh House	02	Sink Pad	Composite Material	NO ASBESTOS	Composite Materials	Medium	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66105	BA3720/01	9326/1	04/04/2018	WHS
#REF!	QHF	Skeagh House	02	Ceiling Board	Insulating Board	Amosite/Chrysotile	Encapsulated Spray or Lagging/Unsealed AIB	Low	Encapsulate, Manage & Affix ID Labels	Re-inspection	HSG227	Unchecked	Medium Risk	7	09/03/2023	Identified	Medium Risk	66106	BA3720/02	9299/2	11/04/2022	WHS
#REF!	QHF	Skeagh House	02	Roofing Felts	Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66107	BA3720/03	9326/1	04/04/2018	WHS
#REF!	QHF	Skeagh House	02	Back Board	Insulating Board	Amosite	Encapsulated Spray or Lagging/Unsealed AIB	Low	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	Medium Risk	7	09/03/2023	Identified	Medium Risk	66108	BA3720/05	9299/2	11/04/2022	WHS
#REF!	QHF	Skeagh House	02	Cement Flat Sheet	Cement Products	Chrysotile	Enclosed Spray or	Low	Encapsulate, Manage & Affix ID Labels	Re-inspection	HSG227	Unchecked	Very Low Risk	4	09/09/2023	Identified	Very Low Risk	66109	BA3720/04	9299/2	11/04/2022	WHS
#REF!	RHA	Roxborough Site	01	Roofing Felts	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66110	BA3390/01	9327/1	18/04/2018	WH Stephens
#REF!	RHA	Roxborough Site	01	Roofing Felts	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66111	BA3390/01	9327/1	18/04/2018	WH Stephens
#REF!	RHA	Roxborough Site	01	Insulating Board	Insulating Board	NO ASBESTOS	Encapsulated Spray or Lagging/Unsealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66112	BA3390/02	9327/1	18/04/2018	WH Stephens
#REF!	RHA	Roxborough Site	01	Debris	Insulating Board	NO ASBESTOS	Encapsulated Spray or Lagging/Unsealed AIB	Loose asbestos debris or residue	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66113	BA3390/03	9327/1	18/04/2018	WH Stephens
#REF!	RHA	Roxborough Site	01	Back Board	Insulating Board	NO ASBESTOS	Encapsulated Spray or Lagging/Unsealed AIB	Medium	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66114	BA3390/04	9327/1	18/04/2018	WH Stephens
#REF!	RHA	Roxborough Site	01	Back Board	Insulating Board	NO ASBESTOS	Encapsulated Spray or Lagging/Unsealed AIB	Medium	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66115	BA3390/04	9327/1	18/04/2018	WH Stephens
#REF!	RHA	Roxborough Site	01	Back Board	Insulating Board	NO ASBESTOS	Encapsulated Spray or Lagging/Unsealed AIB	Medium	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66116	BA3390/04	9327/1	18/04/2018	WH Stephens
#REF!	RHA	Roxborough Site	01	Back Board	Insulating Board	NO ASBESTOS	Encapsulated Spray or Lagging/Unsealed AIB	Medium	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66117	BA3390/04	9327/1	18/04/2018	WH Stephens
#REF!	RHA	Roxborough Site	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66118	BA3390/05	9327/1	18/04/2018	WH Stephens
#REF!	RHA	Roxborough Site	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66119	BA3390/05	9327/1	18/04/2018	WH Stephens
#REF!	RHA	Roxborough Site	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66120	BA3390/05	9327/1	18/04/2018	WH Stephens
#REF!	RHA	Roxborough Site	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66121	BA3390/05	9327/1	18/04/2018	WH Stephens
#REF!	RHA	Roxborough Site	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66122	BA3390/05	9327/1	18/04/2018	WH Stephens
#REF!	RHA	Roxborough Site	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66123	BA3390/05	9327/1	18/04/2018	WH Stephens
#REF!	RHA	Roxborough Site	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66124	BA3390/05	9327/1	18/04/2018	WH Stephens
#REF!	RHA	Roxborough Site	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66125	BA3390/05	9327/1	18/04/2018	WH Stephens
#REF!	RHA	Roxborough Site	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66126	BA3390/05	9327/1	18/04/2018	WH Stephens
#REF!	RHA	Roxborough Site	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66127	BA3390/05	9327/1	18/04/2018	WH Stephens
#REF!	RHA	Roxborough Site	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66128	BA3390/05	9327/1	18/04/2018	WH Stephens
#REF!	RHA	Roxborough Site	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66129	BA3390/05	9327/1	18/04/2018	WH Stephens
#REF!	RHA	Roxborough Site	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66130	BA3390/05	9327/1	18/04/2018	WH Stephens
#REF!	RHA	Roxborough Site	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66131	BA3390/05	9327/1	18/04/2018	WH Stephens
#REF!	RHA	Roxborough Site	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66132	BA3390/05	9327/1	18/04/2018	WH Stephens
#REF!	RHA	Roxborough Site	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66133	BA3390/05	9327/1	18/04/2018	WH Stephens
#REF!	RHA	Roxborough Site	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66134	BA3390/05	9327/1	18/04/2018	WH Stephens
#REF!	RHA	Roxborough Site	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66135	BA3390/05	9327/1	18/04/2018	WH Stephens
#REF!	RHA	Roxborough Site	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66136	BA3390/05	9327/1	18/04/2018	WH Stephens

#REF!	RHA	Roxborough Site	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66137	BA339/05	9327/17	18/04/2018	WH Stephens
#REF!	RHA	Roxborough Site	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66138	BA339/05	9327/17	18/04/2018	WH Stephens
#REF!	RHA	Roxborough Site	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66139	BA339/05	9327/17	18/04/2018	WH Stephens
#REF!	RHA	Roxborough Site	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66140	BA339/05	9327/17	18/04/2018	WH Stephens
#REF!	RHA	Roxborough Site	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66141	BA339/05	9327/17	18/04/2018	WH Stephens
#REF!	RHA	Roxborough Site	01	Textured Coatings		Decorative Coatings	NO ASBESTOS	Enclosed Spray or Lagging/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66142	BA339/06	9327/17	18/04/2018	WH Stephens
#REF!	RHA	Roxborough Site	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66143	BA339/07	9327/17	18/04/2018	WH Stephens
#REF!	RHA	Roxborough Site	01	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66144	BA339/08	9327/17	18/04/2018	WH Stephens
#REF!	RHA	Roxborough Site	01	Back Board		Insulating Board	NO ASBESTOS	Encapsulated Spray or Lagging/Unsealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66145	BA339/09	9327/17	18/04/2018	WH Stephens
#REF!	RHA	Roxborough Site	01	Stair Nosing		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66146	BA339/10	9327/17	18/04/2018	WH Stephens
#REF!	RHA	Roxborough Site	01	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	08/04/2021	Identified	Very Low Risk	66147	BA339/11	9327/17	14/11/2019	WH Stephens
#REF!	RHA	Roxborough Site	01	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	08/04/2021	Strongly Presumed Similar to	Very Low Risk	66148	BA339/11	9327/17	14/11/2019	WH Stephens
#REF!	RHA	Roxborough Site	01	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Low	Further investigation Required	Re-inspection	HSG227	Unchecked	Very Low Risk	3	08/04/2021	Strongly Presumed Similar to	Very Low Risk	66149	BA339/11	9327/17	14/11/2019	WH Stephens
#REF!	RHA	Roxborough Site	01	Fuse Flash Guards		Textiles & Paper	Presumed Asbestos	Encapsulated Spray or Lagging/Unsealed AIB	Medium	Further investigation Required	Re-inspection	HSG227	Unchecked	Medium Risk	9	08/04/2021	Presumed	Medium Risk	66150		9811/19	14/11/2019	WH Stephens
#REF!	RHA	Roxborough Site	01	Fuse Flash Guards		Textiles & Paper	Presumed Asbestos	Encapsulated Spray or Lagging/Unsealed AIB	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Medium Risk	9	08/04/2021	Presumed	Medium Risk	66151		9811/19	14/11/2019	WH Stephens
#REF!	RHA	Roxborough Site	01	Fuse Flash Guards		Textiles & Paper	Presumed Asbestos	Encapsulated Spray or Lagging/Unsealed AIB	Medium	Apply caution when maintaining and affix ID labels	Re-inspection	HSG227	Unchecked	Medium Risk	9	08/04/2021	Presumed	Medium Risk	66152		9811/19	14/11/2019	WH Stephens
#REF!	RHA	Roxborough Site	01	Fuse Flash Guards		Textiles & Paper	Presumed Asbestos	Encapsulated Spray or Lagging/Unsealed AIB	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Medium Risk	9	08/04/2021	Presumed	Medium Risk	66153		9811/19	14/11/2019	WH Stephens
#REF!	RHA	Roxborough Site	01	Fuse Flash Guards		Textiles & Paper	Presumed Asbestos	Encapsulated Spray or Lagging/Unsealed AIB	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Medium Risk	9	08/04/2021	Presumed	Medium Risk	66154		9811/19	14/11/2019	WH Stephens
#REF!	RHA	Roxborough Site	01	Fuse Flash Guards		Textiles & Paper	Presumed Asbestos	Encapsulated Spray or Lagging/Unsealed AIB	Medium	Conduct annual routine inspections	Review – No Change	HSG227	Unchecked	Medium Risk	9	23/04/2019	Presumed	Medium Risk	66155		9327/17	18/04/2018	WH Stephens
#REF!	RHA	Roxborough Site	01	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	08/04/2021	Identified	Very Low Risk	66156	BA339/12	9811/19	14/11/2019	WH Stephens
#REF!	RHA	Roxborough Site	01	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	08/04/2021	Strongly Presumed Similar to	Very Low Risk	66157	BA339/12	9811/19	14/11/2019	WH Stephens
#REF!	RHA	Roxborough Site	01	Sink Pad		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	08/04/2021	Identified	Very Low Risk	66158	BA339/13	9811/19	14/11/2019	WH Stephens
#REF!	RHA	Roxborough Site	01	Boiler Lagging		Thermal Insulation	NO ASBESTOS	Encapsulated Spray or Lagging/Unsealed AIB	Medium	No further action required (Asbestos removed)	Re-inspection	HSG227	Unchecked	NO ASBESTOS	0	08/04/2021	Presumed	Asbestos Removed	66159		9811/19	14/11/2019	WH Stephens
#REF!	RHA	Roxborough Site	01	Gaskets		Textiles & Paper	NO ASBESTOS	Encapsulated Spray or Lagging/Unsealed AIB	Medium	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66160	BA390/14	9327/17	18/04/2018	WH Stephens
#REF!	RHA	Roxborough Site	01	Pipe Insulation		Thermal Insulation	NO ASBESTOS	Unsealed Spray / Lagging / Dust Debris	Medium	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66161	BA339/15	9327/17	18/04/2018	WH Stephens
#REF!	RHA	Roxborough Site	01	Soffit Boards		Cement Products	NO ASBESTOS	Cement Sheets	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66162	BA339/16	9327/17	18/04/2018	WH Stephens
#REF!	RHA	Roxborough Site	01	Veroe Cloak		Cement Products	Chrysotile	Cement Sheets	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	4	08/04/2021	Identified	Very Low Risk	66163	BA339/17	9811/19	14/11/2019	WH Stephens
#REF!	RHA	Roxborough Site	01	Insulating Board	Board to Fuse Cupboard	Insulating Board	NO ASBESTOS	Encapsulated Spray or Lagging/Unsealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66164	BA339/18	9327/17	18/04/2018	WH Stephens
#REF!	SHC	Sleeve Roe	01	Veroe Cloak		Cement Products	Chrysotile	Encapsulated Spray or	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	4	12/09/2023	Identified	Very Low Risk	66165	BA332/01	9300/22	30/08/2022	WHS
#REF!	SHC	Sleeve Roe	01	Bitumen Felt		Composite Material	NO ASBESTOS	Composite Materials	Medium	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66166	BA322/02	9327/17	04/04/2018	WHS
#REF!	SHC	Sleeve Roe	01	Bitumen Felt		Composite Material	NO ASBESTOS	Composite Materials	Medium	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66167	BA322/02	9327/17	04/04/2018	WHS
#REF!	SHC	Sleeve Roe	01	Damp Proof Course		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66168	BA322/03	9327/17	04/04/2018	WHS
#REF!	SHC	Sleeve Roe	01	Ceiling Board		Insulating Board	NO ASBESTOS	Enclosed Spray or Lagging/Sealed AIB	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	03/09/2013	Identified	Asbestos Removed	66169	BA322/04	9327/17	04/04/2018	WHS
#REF!	SHC	Sleeve Roe	01	Ceiling Board		Insulating Board	NO ASBESTOS	Enclosed Spray or Lagging/Sealed AIB	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	Asbestos Removed	66170	BA322/04	9327/17	04/04/2018	WHS
#REF!	SHC	Sleeve Roe	01	Ceiling Board		Insulating Board	NO ASBESTOS	Enclosed Spray or Lagging/Sealed AIB	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	Asbestos Removed	66171	BA322/04	9327/17	04/04/2018	WHS
#REF!	SHC	Sleeve Roe	01	Ceiling Board		Insulating Board	NO ASBESTOS	Enclosed Spray or Lagging/Sealed AIB	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	Asbestos Removed	66172	BA322/04	9327/17	04/04/2018	WHS
#REF!	SHC	Sleeve Roe	01	Ceiling Board		Insulating Board	NO ASBESTOS	Encapsulated Spray or Lagging/Unsealed AIB	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	Asbestos Removed	66173	BA322/04	9327/17	04/04/2018	WHS
#REF!	SHC	Sleeve Roe	01	Insulating Board		Insulating Board	NO ASBESTOS	Encapsulated Spray or Lagging/Unsealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66174	BA322/05	9327/17	04/04/2018	WHS
#REF!	SHC	Sleeve Roe	01	Gaskets		Textiles & Paper	Chrysotile	Encapsulated Spray or Lagging/Unsealed AIB	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Low Risk	6	12/09/2023	Identified	Low Risk	66175	BA322/06	9300/22	30/08/2022	WHS
#REF!	SHC	Sleeve Roe	01	Gaskets		Textiles & Paper	NO ASBESTOS	Encapsulated Spray or Lagging/Unsealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66176	BA322/07	9327/17	04/04/2018	WHS
#REF!	SHC	Sleeve Roe	01	Cylinder insulation		Thermal Insulation	NO ASBESTOS	Unsealed Spray or Lagging	Medium	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66177	BA322/08	9327/17	04/04/2018	WHS
#REF!	SHC	Sleeve Roe	01	Back Board		Insulating Board	NO ASBESTOS	Encapsulated Spray or Lagging/Unsealed AIB	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	Asbestos Removed	66178	BA322/09	9327/17	04/04/2018	WHS
#REF!	SHC	Sleeve Roe	01	Back Board		Insulating Board	Amosite/Chrysotile	Encapsulated Spray or Lagging/Unsealed AIB	Low	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	Medium Risk	7	12/03/2023	Strongly Presumed Similar to	Medium Risk	66179	BA322/09	9300/22	30/08/2022	WHS
#REF!	SHC	Sleeve Roe	01	Back Board		Insulating Board	Amosite/Chrysotile	Encapsulated Spray or Lagging/Unsealed AIB	Low	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	Medium Risk	7	12/03/2023	Strongly Presumed Similar to	Medium Risk	66180	BA322/09	9300/22	30/08/2022	WHS
#REF!	SHC	Sleeve Roe	01	Back Board		Insulating Board	NO ASBESTOS	Encapsulated Spray or Lagging/Unsealed AIB	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	Asbestos Removed	66181	BA322/09	9327/17	04/04/2018	WHS
#REF!	SHC	Sleeve Roe	01	Back Board		Insulating Board	NO ASBESTOS	Encapsulated Spray or Lagging/Unsealed AIB	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	Asbestos Removed	66182	BA322/09	9327/17	04/04/2018	WHS
#REF!	SHC	Sleeve Roe	01	Back Board		Insulating Board	NO ASBESTOS	Encapsulated Spray or Lagging/Unsealed AIB	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	Asbestos Removed	66183	BA322/09	9327/17	04/04/2018	WHS
#REF!	SHC	Sleeve Roe	01	Back Board		Insulating Board	Amosite/Chrysotile	Encapsulated Spray or Lagging/Unsealed AIB	Low	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	Medium Risk	7	12/03/2023	Strongly Presumed Similar to	Medium Risk	66184	BA322/09	9300/22	30/08/2022	WHS
#REF!	SHC	Sleeve Roe	01	Lino Flooring		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66185	BA322/10	9327/17	04/04/2018	WHS
#REF!	SHC	Sleeve Roe	01	Lino Flooring		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66186	BA322/10	9327/17	04/04/2018	WHS
#REF!	SHC	Sleeve Roe	01	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66187	BA322/11	9327/17	04/04/2018	WHS
#REF!	SHC	Sleeve Roe	01	Door Panel		Cement Products	NO ASBESTOS	Enclosed Spray or Lagging/Sealed AIB	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66188	BA322/12	9327/17	04/04/2018	WHS
#REF!	SHC	Sleeve Roe	01	Lino Flooring		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66189	BA322/13	9327/17	04/04/2018	WHS
#REF!	SHC	Sleeve Roe	01	Lino Flooring		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66190	BA322/13	9327/17	04/04/2018	WHS
#REF!	SHC	Sleeve Roe	01	Sink Pad		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	12/09/2023	Identified	Very Low Risk	66191	BA322/14	9300/22	30/08/2022	WHS
#REF!	SHC	Sleeve Roe	01	Insulating Board		Insulating Board	NO ASBESTOS	Enclosed Spray or Lagging/Sealed AIB	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66192	BA322/15	9327/17	04/04/2018	WHS
#REF!	SHC	Sleeve Roe	01	Insulating Board		Insulating Board	NO ASBESTOS	Enclosed Spray or Lagging/Sealed AIB	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66193	BA322/15	9327/17	04/04/2018	WHS
#REF!	SHC	Sleeve Roe	01	Textured Coatings		Decorative Coatings	NO ASBESTOS	Textured Coating	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66194	BA322/16	9327/17	04/04/2018	WHS
#REF!	SHC	Sleeve Roe	01	Textured Coatings		Decorative Coatings	NO ASBESTOS	Textured Coating	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66195	BA322/16	9327/17	04/04/2018	WHS
#REF!	SHC	Sleeve Roe	01	Textured Coatings		Decorative Coatings	NO ASBESTOS	Textured Coating	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66196	BA322/16	9327/17	04/04/2018	WHS
#REF!	SHC	Sleeve Roe	01	Textured Coatings		Decorative Coatings	NO ASBESTOS	Textured Coating	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66197	BA322/16	9327/17	04/04/2018	WHS
#REF!	SHC	Sleeve Roe	01	Textured Coatings		Decorative Coatings	NO ASBESTOS	Textured Coating	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66198	BA322/16	9327/17	04/04/2018	WHS
#REF!	SHC	Sleeve Roe	01	Textured Coatings		Decorative Coatings	NO ASBESTOS	Textured Coating	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66199	BA322/16	9327/17	04/04/2018	WHS
#REF!	SHC	Sleeve Roe	01	Textured Coatings		Decorative Coatings	NO ASBESTOS	Textured Coating	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66200	BA322/16	9327/17	04/04/2018	WHS
#REF!	SHC	Sleeve Roe	01	Textured Coatings		Decorative Coatings	NO ASBESTOS	Textured Coating	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66201	BA322/16	9327/17	04/04/2018	WHS
#REF!	SHC	Sleeve Roe	01	Textured Coatings		Decorative Coatings	NO ASBESTOS	Textured Coating	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66202	BA322/16	9327/17	04/04/2018	WHS
#REF!	SHC	Sleeve Roe	01	Insulating Board Below Window		Insulating Board	NO ASBESTOS	Enclosed Spray or Lagging/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66203	BA322/17	9327/17	04/04/2018	WHS
#REF!	SHC	Sleeve Roe	01	Door Panel		Insulating Board	NO ASBESTOS	Enclosed Spray or Lagging/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66204	BA322/17	9327/17	04/04/2018	WHS
#REF!	SHC	Sleeve Roe	01	Door Panel		Insulating Board	NO ASBESTOS	Enclosed Spray or Lagging/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66205	BA322/17	9327/17	04/04/2018	WHS
#REF!	SHC	Sleeve Roe	01	Door Panel		Insulating Board	NO ASBESTOS	Enclosed Spray or Lagging/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66206	BA322/17	9327/17	04/04/2018	WHS
#REF!	SHC	Sleeve Roe	01	Door Panel		Insulating Board	NO ASBESTOS	Enclosed Spray or Lagging/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66207	BA322/17	9327/17	04/04/2018	WHS
#REF!	SHC	Sleeve Roe	01	Door Panel		Insulating Board	NO ASBESTOS	Enclosed Spray or Lagging/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66208	BA322/17	9327/17	04/04/2018	WHS
#REF!	SHC	Sleeve Roe	01	Insulating Board Below Window		Insulating Board	NO ASBESTOS	Enclosed Spray or Lagging/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66209	BA322/17	9327/17	04/04/2018	WHS
#REF!	SHC	Sleeve Roe	01	Door Panel		Insulating Board	NO ASBESTOS	Enclosed Spray or Lagging/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66210	BA322/18	9327/17	04/04/2018	WHS
#REF!	SHC	Sleeve Roe	01	Door Panel		Insulating Board	NO ASBESTOS	Enclosed Spray or Lagging/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66211	BA322/18	9327/17	04/04/2018	WHS
#REF!	SHC	Sleeve Roe	01	Door Panel		Insulating Board	NO ASBESTOS	Enclosed Spray or Lagging/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66212	BA322/18	9327/17	04/04/2018	WHS
#REF!	SHC	Sleeve Roe	01	Door Panel		Insulating Board	NO ASBESTOS	Enclosed Spray or Lagging/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66213	BA322/18	9327/17	04/04/2018	WHS

#REF!	SHC	Sleve Roe	01	Door Panel	Insulating Board	NO ASBESTOS	Enclosed Spray or Laosino/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66214	BA322/18	932?1?7	04/04/2018	WHS
#REF!	SHC	Sleve Roe	01	Door Panel	Insulating Board	NO ASBESTOS	Enclosed Spray or Laosino/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66215	BA322/18	932?1?7	04/04/2018	WHS
#REF!	SHC	Sleve Roe	01	Door Panel	Insulating Board	NO ASBESTOS	Enclosed Spray or Laosino/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66216	BA322/18	932?1?7	04/04/2018	WHS
#REF!	SHC	Sleve Roe	01	Door Panel	Insulating Board	NO ASBESTOS	Enclosed Spray or Laosino/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66217	BA322/18	932?1?7	04/04/2018	WHS
#REF!	SHC	Sleve Roe	01	Door Panel	Insulating Board	NO ASBESTOS	Enclosed Spray or Laosino/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66218	BA322/18	932?1?7	04/04/2018	WHS
#REF!	SHC	Sleve Roe	01	Door Panel	Insulating Board	NO ASBESTOS	Enclosed Spray or Laosino/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66219	BA322/18	932?1?7	04/04/2018	WHS
#REF!	SHC	Sleve Roe	01	Door Panel	Insulating Board	NO ASBESTOS	Enclosed Spray or Laosino/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66220	BA322/18	932?1?7	04/04/2018	WHS
#REF!	SHC	Sleve Roe	01	Door Panel	Insulating Board	NO ASBESTOS	Enclosed Spray or Laosino/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66221	BA322/18	932?1?7	04/04/2018	WHS
#REF!	SHC	Sleve Roe	01	Sink Pad	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66222	BA322/19	932?1?7	04/04/2018	WHS
#REF!	SHC	Sleve Roe	01	Sink Pad	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66223	BA322/20	932?1?7	04/04/2018	WHS
#REF!	SHC	Sleve Roe	01	Back Board	Insulating Board	NO ASBESTOS	Encapsulated Spray or Laosino/Unsealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66224	BA322/21	932?1?7	04/04/2018	WHS
#REF!	SHC	Sleve Roe	01	Ceiling Board	Insulating Board	NO ASBESTOS	Encapsulated Spray or Laosino/Unsealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66225	BA322/22	932?1?7	04/04/2018	WHS
#REF!	SHC	Sleve Roe	01	Fire Break Panel	Insulating Board	NO ASBESTOS	Encapsulated Spray or Laosino/Unsealed AIB	High	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	Asbestos Removed	66226	BA322/23	932?1?7	04/04/2018	WHS
#REF!	SHC	Sleve Roe	01	Fire Break Panel	Insulating Board	NO ASBESTOS	Encapsulated Spray or Laosino/Unsealed AIB	High	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	Asbestos Removed	66227	BA322/23	932?1?7	04/04/2018	WHS
#REF!	SHC	Sleve Roe	01	Roofing Felts	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66228	BA322/24	932?1?7	04/04/2018	WHS
#REF!	SHC	Sleve Roe	01	Back Board	Insulating Board	NO ASBESTOS	Encapsulated Spray or Laosino/Unsealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66229	BA322/25	932?1?7	04/04/2018	WHS
#REF!	SHC	Sleve Roe	01	Back Board	Insulating Board	NO ASBESTOS	Encapsulated Spray or Laosino/Unsealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66230	BA322/25	932?1?7	04/04/2018	WHS
#REF!	SHC	Sleve Roe	01	Back Board	Insulating Board	NO ASBESTOS	Encapsulated Spray or Laosino/Unsealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66231	BA322/25	932?1?7	04/04/2018	WHS
#REF!	SHC	Sleve Roe	01	Back Board	Insulating Board	NO ASBESTOS	Encapsulated Spray or Laosino/Unsealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66232	BA322/25	932?1?7	04/04/2018	WHS
#REF!	SHC	Sleve Roe	01	Back Board	Insulating Board	NO ASBESTOS	Encapsulated Spray or Laosino/Unsealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66233	BA322/25	932?1?7	04/04/2018	WHS
#REF!	SHC	Sleve Roe	01	Back Board	Insulating Board	NO ASBESTOS	Encapsulated Spray or Laosino/Unsealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66234	BA322/25	932?1?7	04/04/2018	WHS
#REF!	SHC	Sleve Roe	01	Back Board	Insulating Board	NO ASBESTOS	Encapsulated Spray or Laosino/Unsealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66235	BA322/25	932?1?7	04/04/2018	WHS
#REF!	SHC	Sleve Roe	01	Debris	Insulating Board	NO ASBESTOS	Unsealed Spray / Lagging / Dust Debris	High	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	Asbestos Removed	66236	BA322/26	932?1?7	04/04/2018	WHS
#REF!	SHC	Sleve Roe	01	Debris	Insulating Board	NO ASBESTOS	Unsealed Spray / Lagging / Dust Debris	High	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	Asbestos Removed	66237	BA322/26	932?1?7	04/04/2018	WHS
#REF!	SHC	Sleve Roe	01	Fuse Flash Guards	Textiles & Paper	Presumed Asbestos	Encapsulated Spray or Laosino/Unsealed AIB	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Medium Risk	9	12/03/2023	Presumed	Medium Risk	66238		930?2?2	30/08/2022	WHS
#REF!	SHC	Sleve Roe	01	Insulation	Thermal Insulation	Presumed Asbestos	Encapsulated Spray or Laosino/Unsealed AIB	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	High Risk	10	12/12/2022	Presumed	High Risk	66239		930?2?2	30/08/2022	WHS
#REF!	SHC	Sleve Roe	01						Re-Survey	Re-inspection	HSG227	Checked	High Risk	0	12/12/2022			66240		930?2?2	30/08/2022	WHS
#REF!	SHC	Sleve Roe	01						Re-Survey	Re-inspection	HSG227	Checked	High Risk	0	12/12/2022			66241		930?2?2	30/08/2022	WHS
#REF!	SHC	Sleve Roe	01						Re-Survey	Re-inspection	HSG227	Checked	High Risk	0	14/03/2023			66242		930?2?2	30/08/2022	WHS
#REF!	QAA	Craigavon Hospital	19	Roofing Felts	Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66243	BA337/4/01	972/4/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	19	Fire Break Panel	Insulating Board	NO ASBESTOS	Encapsulated Spray or Laosino/Unsealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66244	BA337/4/02	972/4/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	19	Debris	Cement Products	NO ASBESTOS	Enclosed Spray or Laosino/Sealed AIB	Loose asbestos debris or residue	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	Asbestos Removed	66245	BA337/4/03	972/4/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	19	Debris	Insulating Board	NO ASBESTOS	Encapsulated Spray or Laosino/Unsealed AIB	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66246	BA337/4/04	972/4/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	19	Fire Break Panel	Insulating Board	NO ASBESTOS	Encapsulated Spray or Laosino/Unsealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66247	BA337/4/05	972/4/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	19	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66248	BA337/4/06	972/4/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	19	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66249	BA337/4/06	972/4/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	19	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66250	BA337/4/06	972/4/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	19	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66251	BA337/4/06	972/4/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	19	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66252	BA337/4/06	972/4/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	19	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66253	BA337/4/06	972/4/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	19	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66254	BA337/4/06	972/4/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	19	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66255	BA337/4/06	972/4/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	19	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66256	BA337/4/06	972/4/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	19	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66257	BA337/4/06	972/4/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	19	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66258	BA337/4/06	972/4/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	19	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66259	BA337/4/06	972/4/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	19	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66260	BA337/4/06	972/4/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	19	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66261	BA337/4/06	972/4/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	19	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66262	BA337/4/06	972/4/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	19	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66263	BA337/4/06	972/4/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	19	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66264	BA337/4/06	972/4/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	19	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66265	BA337/4/06	972/4/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	19	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66266	BA337/4/06	972/4/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	19	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66267	BA337/4/06	972/4/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	19	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66268	BA337/4/06	972/4/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	19	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66269	BA337/4/06	972/4/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	19	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66270	BA337/4/06	972/4/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	19	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66271	BA337/4/06	972/4/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	19	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66272	BA337/4/06	972/4/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	19	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66273	BA337/4/06	972/4/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	19	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66274	BA337/4/06	972/4/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	19	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66275	BA337/4/06	972/4/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	19	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66276	BA337/4/06	972/4/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	19	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66277	BA337/4/07	972/4/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	19	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66278	BA337/4/07	972/4/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	19	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66279	BA337/4/07	972/4/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	19	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66280	BA337/4/07	972/4/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	19	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66281	BA337/4/07	972/4/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	19	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66282	BA337/4/07	972/4/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	19	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66283	BA337/4/07	972/4/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	19	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66284	BA337/4/07	972/4/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	19	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66285	BA337/4/07	972/4/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	19	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66286	BA337/4/07	972/4/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	19	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66287	BA337/4/07	972/4/17	05/09/2017	WHS

#REF!	QAA	Craigavon Hospital	19	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66288	BA3374/07	9724/17	05/09/2017	WHS	
#REF!	QAA	Craigavon Hospital	19	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66289	BA3374/07	9724/17	05/09/2017	WHS	
#REF!	QAA	Craigavon Hospital	19	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66290	BA3374/07	9724/17	05/09/2017	WHS	
#REF!	QAA	Craigavon Hospital	19	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66291	BA3374/07	9724/17	05/09/2017	WHS	
#REF!	QAA	Craigavon Hospital	19	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66292	BA3374/07	9724/17	05/09/2017	WHS	
#REF!	QAA	Craigavon Hospital	19	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66293	BA3374/07	9724/17	05/09/2017	WHS	
#REF!	QAA	Craigavon Hospital	19	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66294	BA3374/07	9724/17	05/09/2017	WHS	
#REF!	QAA	Craigavon Hospital	19	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66295	BA3374/07	9724/17	05/09/2017	WHS	
#REF!	QAA	Craigavon Hospital	19	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66296	BA3374/07	9724/17	05/09/2017	WHS	
#REF!	QAA	Craigavon Hospital	19	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66297	BA3374/07	9724/17	05/09/2017	WHS	
#REF!	QAA	Craigavon Hospital	19	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66298	BA3374/07	9724/17	05/09/2017	WHS	
#REF!	QAA	Craigavon Hospital	19	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66299	BA3374/07	9724/17	05/09/2017	WHS	
#REF!	QAA	Craigavon Hospital	19	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66300	BA3374/07	9724/17	05/09/2017	WHS	
#REF!	QAA	Craigavon Hospital	19	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66301	BA3374/07	9724/17	05/09/2017	WHS	
#REF!	QAA	Craigavon Hospital	19	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66302	BA3374/07	9724/17	05/09/2017	WHS	
#REF!	QAA	Craigavon Hospital	19	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66303	BA3374/07	9724/17	05/09/2017	WHS	
#REF!	QAA	Craigavon Hospital	19	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66304	BA3374/07	9724/17	05/09/2017	WHS	
#REF!	QAA	Craigavon Hospital	19	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66305	BA3374/07	9724/17	05/09/2017	WHS	
#REF!	QAA	Craigavon Hospital	19	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66306	BA3374/08	9724/17	05/09/2017	WHS	
#REF!	QAA	Craigavon Hospital	19	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66307	BA3374/08	9724/17	05/09/2017	WHS	
#REF!	QAA	Craigavon Hospital	19	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66308	BA3374/08	9724/17	05/09/2017	WHS	
#REF!	QAA	Craigavon Hospital	19	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66309	BA3374/08	9724/17	05/09/2017	WHS	
#REF!	QAA	Craigavon Hospital	19	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66310	BA3374/08	9724/17	05/09/2017	WHS	
#REF!	QAA	Craigavon Hospital	19	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66311	BA3374/08	9724/17	05/09/2017	WHS	
#REF!	QAA	Craigavon Hospital	19	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66312	BA3374/09	9724/17	05/09/2017	WHS	
#REF!	QAA	Craigavon Hospital	19	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66313	BA3374/09	9724/17	05/09/2017	WHS	
#REF!	QAA	Craigavon Hospital	19	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66314	BA3374/10	9724/17	05/09/2017	WHS	
#REF!	QAA	Craigavon Hospital	19	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66315	BA3374/11	9724/17	05/09/2017	WHS	
#REF!	QAA	Craigavon Hospital	19	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66316	BA3374/12	9724/17	05/09/2017	WHS	
#REF!	QAA	Craigavon Hospital	19	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	Asbestos Removed	66317	BA3374/13	9724/17	05/09/2017	WHS	
#REF!	QAA	Craigavon Hospital	19	Sink Pad		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	24/06/2023	Strongly Presumed Similar to	Very Low Risk	66318	BA3374/13	9302/2	24/06/2022	WHS	
#REF!	QAA	Craigavon Hospital	19	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66319	BA3374/14	9724/17	05/09/2017	WHS	
#REF!	QAA	Craigavon Hospital	19	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66320	BA3374/15	9724/17	05/09/2017	WHS	
#REF!	QAA	Craigavon Hospital	19	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66321	BA3374/15	9724/17	05/09/2017	WHS	
#REF!	QAA	Craigavon Hospital	19	Stair Nosing		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66322	BA3374/16	9724/17	05/09/2017	WHS	
#REF!	QAA	Craigavon Hospital	19	Stair Nosing		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66323	BA3374/16	9724/17	05/09/2017	WHS	
#REF!	QAA	Craigavon Hospital	19	Infill Panel		Insulating Board	NO ASBESTOS	Encapsulated Spray or Laconio/Unsealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66324	BA3374/17	9724/17	05/09/2017	WHS	
#REF!	QAA	Craigavon Hospital	19	Infill Panel		Insulating Board	NO ASBESTOS	Encapsulated Spray or Laconio/Unsealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66325	BA3374/17	9724/17	05/09/2017	WHS	
#REF!	QAA	Craigavon Hospital	19	Infill Panel		Insulating Board	NO ASBESTOS	Encapsulated Spray or Laconio/Unsealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66326	BA3374/17	9724/17	05/09/2017	WHS	
#REF!	QAA	Craigavon Hospital	19	Infill Panel		Insulating Board	NO ASBESTOS	Encapsulated Spray or Laconio/Unsealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66327	BA3374/17	9724/17	05/09/2017	WHS	
#REF!	QAA	Craigavon Hospital	19	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	24/06/2023	Identified	Very Low Risk	66328	BA3374/18	9302/2	24/06/2022	WHS	
#REF!	QAA	Craigavon Hospital	19	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Review – No Change	HSG227	Unchecked	Very Low Risk	3	10/08/2021	Identified	Very Low Risk	66329	BA3374/19	9811/1	15/01/2020	WH Stephens	
#REF!	QAA	Craigavon Hospital	19	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	24/06/2023	Identified	Very Low Risk	66330	BA3374/20	9302/2	24/06/2022	WHS	
#REF!	QAA	Craigavon Hospital	19	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	24/06/2023	Identified	Very Low Risk	66331	BA3374/21	9302/2	24/06/2022	WHS	
#REF!	QAA	Craigavon Hospital	19	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Low	Apply caution when maintaining and affix ID labels	Re-inspection	HSG227	Unchecked	Very Low Risk	3	24/06/2023	Strongly Presumed Similar to	Very Low Risk	66332	BA3374/21	9302/2 2	24/06/2022	WHS	
#REF!	QAA	Craigavon Hospital	19	Infill Panel		Insulating Board	NO ASBESTOS	Enclosed Spray or Laconio/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66333	BA3374/22	9724/17	05/09/2017	WHS	
#REF!	QAA	Craigavon Hospital	19	Infill Panel		Insulating Board	NO ASBESTOS	Enclosed Spray or Laconio/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66334	BA3374/22	9724/17	05/09/2017	WHS	
#REF!	QAA	Craigavon Hospital	19	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66335	BA3374/23	9724/17	05/09/2017	WHS	
#REF!	QAA	Craigavon Hospital	19	Bitumen Felt		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66336	BA3374/24	9724/17	05/09/2017	WHS	
#REF!	QAA	Craigavon Hospital	19	Bitumen Felt		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66337	BA3374/25	9724/17	05/09/2017	WHS	
#REF!	QAA	Craigavon Hospital	19	Ceiling Board		Insulating Board	NO ASBESTOS	Enclosed Spray or Laconio/Sealed AIB	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66338	BA3374/26	9724/17	05/09/2017	WHS	
#REF!	QAA	Craigavon Hospital	19	Gaskets		Textiles & Paper	Chrysotile	Encapsulated Spray or Laconio/Unsealed AIB	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Low Risk	6	24/06/2023	Identified	Low Risk	66339	BA3374/27	9302/2 2	24/06/2022	WHS	
#REF!	QAA	Craigavon Hospital	19	Soffit Boards		Cement Products	Chrysotile	Cement Sheets	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	4	24/06/2023	Identified	Very Low Risk	66340	BA3374/28	9302/2 2	24/06/2022	WHS	
#REF!	QAA	Craigavon Hospital	19	Fuse Flash Guards		Textiles & Paper	Presumed Asbestos	Encapsulated Spray or Laconio/Unsealed AIB	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Medium Risk	9	24/12/2022	Presumed	Medium Risk	66341		9302/2 2	24/06/2022	WHS	
#REF!	QAA	Craigavon Hospital	19	Fuse Flash Guards		Textiles & Paper	Presumed Asbestos	Encapsulated Spray or Laconio/Unsealed AIB	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Medium Risk	9	24/12/2022	Presumed	Medium Risk	66342		9302/2 2	24/06/2022	WHS	
#REF!	QAA	Craigavon Hospital	19	Cowl		Cement Products	Presumed Asbestos	Encapsulated Spray or	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Low Risk	6	24/06/2023	Presumed	Low Risk	66343		9302/2	24/06/2022	WHS	
#REF!	QAA	Craigavon Hospital	19	Verge Cloak		Cement Products	Presumed Asbestos	Cement Sheets	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Low Risk	6	24/06/2023	Presumed	Low Risk	66344		9302/2	24/06/2022	WHS	
#REF!	QAA	Craigavon Hospital	19	Floor Tile and Bitumen Adhesive	Small White Vinyl Floor Tiles and Bitumen Adhesive	Composite Material	Presumed Asbestos	Composite Material	Low	Conduct annual routine inspections	Re-inspection	HSG227	Checked	High Risk	5	24/06/2023	Strongly Presumed Similar to	High Risk	66345		9302/2 2	24/06/2022	WHS	
#REF!	RAA	South Tyrone Hospital	02	Floor Tiles		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	15/12/2023	Identified	Very Low Risk	66346	BA3331/01	9302/2	15/12/2022	WHS	
#REF!	QHF	Sleagh House	01	Ceiling Panel		Insulating Board	Amosite/Chrysotile	Encapsulated Spray or Laconio/Unsealed AIB	Low	Encapsulate, label and manage	Re-inspection	HSG227	Unchecked	Medium Risk	7	08/09/2023	Strongly Presumed Similar to	Low Risk	66347	BA3346/12	9299/22 2	11/04/2022	WHS	
#REF!	QHF	Sleagh House	01	Ceiling Board		Insulating Board	Amosite/Chrysotile	Encapsulated Spray or Laconio/Unsealed AIB	Low	Encapsulate, label and manage	Re-inspection	HSG227	Unchecked	Medium Risk	7	08/09/2023	Strongly Presumed Similar to	Low Risk	66348	BA3346/12	9299/22 2	11/04/2022	WHS	
#REF!	QHF	Sleagh House	01	Ceiling Board		Insulating Board	Amosite/Chrysotile	Encapsulated Spray or Laconio/Unsealed AIB	Low	Encapsulate, label and manage	Re-inspection	HSG227	Unchecked	Medium Risk	7	08/09/2023	Strongly Presumed Similar to	Low Risk	66349	BA3346/12	9299/22 2	11/04/2022	WHS	
#REF!	RAA	South Tyrone Hospital	02	Floor Tiles		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	15/12/2023	Strongly Presumed Similar to	Very Low Risk	66350	BA3331/01	9302/2	15/12/2022	WHS	
#REF!	QAA	Craigavon Hospital	17	Roofing Felts		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66351	BA3373/01	9506/18	13/11/2018	WHS	
#REF!	RAA	South Tyrone Hospital	02	Floor Tiles	Cream vinyl floor tile	Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	15/12/2023	Identified	Very Low Risk	66352	BA9308	9302/2	15/12/2022	WHS	
#REF!	QAA	Craigavon Hospital	17	Debris		Cement Products	NO ASBESTOS	Enclosed Spray or Laconio/Sealed AIB	Loose asbestos debris or residue	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	26/11/2019	Identified	Asbestos Removed	66353	BA3373/02	9506/18	13/11/2018	WHS	
#REF!	QAA	Craigavon Hospital	17	Fire Break Panel		Insulating Board	NO ASBESTOS	Encapsulated Spray or Laconio/Unsealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66354	BA3373/03	9506/18	13/11/2018	WHS	
#REF!	QAA	Craigavon Hospital	17	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66355	BA3373/04	9506/18	13/11/2018	WHS	
#REF!	QAA	Craigavon Hospital	17	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66356	BA3373/04	9506/18	13/11/2018	WHS	
#REF!	QAA	Craigavon Hospital	17	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66357	BA3373/04	9506/18	13/11/2018	WHS	
#REF!	QAA	Craigavon Hospital	17	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66358	BA3373/04	9506/18	13/11/2018	WHS	
#REF!	QAA	Craigavon Hospital	17	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66359	BA3373/04	9506/18	13/11/2018	WHS	
#REF!	QAA	Craigavon Hospital	17	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66360	BA3373/04	9506/18	13/11/2018	WHS	
#REF!	QAA	Craigavon Hospital	17	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66361	BA3373/04	9506/18	13/11/2018	WHS	
#REF!	QAA	Craigavon Hospital	17	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66362	BA3373/04	9506/18	13/11/2018	WHS	
#REF!	QAA	Craigavon Hospital	17	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66363	BA3373/04	9506/18	13/11/2018	WHS	
#REF!	QAA	Craigavon Hospital	17	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66364	BA3373/04	9506/18	13/11/2018	WHS	
#REF!	QAA	Craigavon Hospital	17	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66365	BA3373/04	9506/18	13/11/2018	WHS	

#REF!	QAA	Craigavon Hospital	17	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66366	BA337/3/04	9506/18	13/11/2018	WHS	
#REF!	QAA	Craigavon Hospital	17	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66367	BA337/3/04	9506/18	13/11/2018	WHS	
#REF!	QAA	Craigavon Hospital	17	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66368	BA337/3/04	9506/18	13/11/2018	WHS	
#REF!	QAA	Craigavon Hospital	17	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66369	BA337/3/04	9506/18	13/11/2018	WHS	
#REF!	QAA	Craigavon Hospital	17	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66370	BA337/3/04	9506/18	13/11/2018	WHS	
#REF!	QAA	Craigavon Hospital	17	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66371	BA337/3/04	9506/18	13/11/2018	WHS	
#REF!	QAA	Craigavon Hospital	17	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66372	BA337/3/04	9506/18	13/11/2018	WHS	
#REF!	QAA	Craigavon Hospital	17	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66373	BA337/3/04	9506/18	13/11/2018	WHS	
#REF!	QAA	Craigavon Hospital	17	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66374	BA337/3/04	9506/18	13/11/2018	WHS	
#REF!	QAA	Craigavon Hospital	17	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66375	BA337/3/04	9506/18	13/11/2018	WHS	
#REF!	QAA	Craigavon Hospital	17	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66376	BA337/3/04	9506/18	13/11/2018	WHS	
#REF!	QAA	Craigavon Hospital	17	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66377	BA337/3/04	9506/18	13/11/2018	WHS	
#REF!	QAA	Craigavon Hospital	17	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66378	BA337/3/04	9506/18	13/11/2018	WHS	
#REF!	QAA	Craigavon Hospital	17	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66379	BA337/3/04	9506/18	13/11/2018	WHS	
#REF!	QAA	Craigavon Hospital	17	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66380	BA337/3/04	9506/18	13/11/2018	WHS	
#REF!	QAA	Craigavon Hospital	17	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66381	BA337/3/04	9506/18	13/11/2018	WHS	
#REF!	QAA	Craigavon Hospital	17	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66382	BA337/3/04	9506/18	13/11/2018	WHS	
#REF!	QAA	Craigavon Hospital	17	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66383	BA337/3/05	9506/18	13/11/2018	WHS	
#REF!	RAA	South Tyrone Hospital	02	Floor Tiles	Cream vinyl floor tile	Composite Material	Chrysotile	Composite Material	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	15/12/2023	Identified	Very Low Risk	66384	BA9308	9302.2	15/12/2022	WHS	
#REF!	QAA	Craigavon Hospital	17	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66385	BA337/3/05	9506/18	13/11/2018	WHS	
#REF!	QAA	Craigavon Hospital	17	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66386	BA337/3/05	9506/18	13/11/2018	WHS	
#REF!	QAA	Craigavon Hospital	17	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66387	BA337/3/05	9506/18	13/11/2018	WHS	
#REF!	QAA	Craigavon Hospital	17	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66388	BA337/3/05	9506/18	13/11/2018	WHS	
#REF!	RAA	South Tyrone Hospital	02	Floor Tiles	Cream vinyl floor tile	Composite Material	Chrysotile	Composite Material	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	15/12/2023	Identified	Very Low Risk	66389	BA9308	9302.2	15/12/2022	WHS	
#REF!	QAA	Craigavon Hospital	17	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66390	BA337/3/05	9506/18	13/11/2018	WHS	
#REF!	QAA	Craigavon Hospital	17	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66391	BA337/3/05	9506/18	13/11/2018	WHS	
#REF!	QAA	Craigavon Hospital	17	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66392	BA337/3/05	9506/18	13/11/2018	WHS	
#REF!	QAA	Craigavon Hospital	17	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66393	BA337/3/05	9506/18	13/11/2018	WHS	
#REF!	RAA	South Tyrone Hospital	02	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	Further investigation Required	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	26/11/2019	Strongly Presumed Similar to	Asbestos Removed	66394	BA3331/01	9302.2	20/11/2018	WHS	
#REF!	QAA	Craigavon Hospital	17	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66395	BA337/3/05	9506/18	13/11/2018	WHS	
#REF!	QAA	Craigavon Hospital	17	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66396	BA337/3/05	9506/18	13/11/2018	WHS	
#REF!	QAA	Craigavon Hospital	17	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66397	BA337/3/05	9506/18	13/11/2018	WHS	
#REF!	QAA	Craigavon Hospital	17	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66398	BA337/3/05	9506/18	13/11/2018	WHS	
#REF!	QAA	Craigavon Hospital	17	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66399	BA337/3/05	9506/18	13/11/2018	WHS	
#REF!	QAA	Craigavon Hospital	17	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66400	BA337/3/05	9506/18	13/11/2018	WHS	
#REF!	RAA	South Tyrone Hospital	02	Floor Tiles	Cream vinyl floor tile	Composite Material	Chrysotile	Composite Material	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	15/12/2023	Identified	Very Low Risk	66401	BA9308	9302.2	15/12/2022	WHS	
#REF!	QAA	Craigavon Hospital	17	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66402	BA337/3/05	9506/18	13/11/2018	WHS	
#REF!	QAA	Craigavon Hospital	17	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66403	BA337/3/05	9506/18	13/11/2018	WHS	
#REF!	QAA	Craigavon Hospital	17	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66404	BA337/3/05	9506/18	13/11/2018	WHS	
#REF!	QAA	Craigavon Hospital	17	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66405	BA337/3/05	9506/18	13/11/2018	WHS	
#REF!	RAA	South Tyrone Hospital	02	Floor Tiles	Cream vinyl floor tile	Composite Material	Chrysotile	Composite Material	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	15/12/2023	Identified	Very Low Risk	66406	BA9308	9302.2	15/12/2022	WHS	
#REF!	QAA	Craigavon Hospital	17	Sink Pad		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	24/06/2023	Identified	Very Low Risk	66407	BA337/3/06	9302.2	24/06/2022	WHS	
#REF!	QAA	Craigavon Hospital	17	Sink Pad		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	24/06/2023	Strongly Presumed Similar to	Very Low Risk	66408	BA337/3/06	9302.2	24/06/2022	WHS	
#REF!	QAA	Craigavon Hospital	17	Sink Pad		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	24/06/2023	Stronnly Presumed Similar to	Very Low Risk	66409	BA337/3/06	9302.2	24/06/2022	WHS	
#REF!	QAA	Craigavon Hospital	17	Sink Pad		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	24/06/2023	Stronnly Presumed Similar to	Very Low Risk	66410	BA337/3/06	9302.2	24/06/2022	WHS	
#REF!	QAA	Craigavon Hospital	17	Sink Pad		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	24/06/2023	Strongly Presumed Similar to	Very Low Risk	66411	BA337/3/06	9302.2	24/06/2022	WHS	
#REF!	QAA	Craigavon Hospital	17	Sink Pad		Composite Material	Chrysotile	Composite Materials	Low	Apply caution when maintaining and affix ID labels	Re-inspection	HSG227	Unchecked	Very Low Risk	3	24/06/2023	Strongly Presumed Similar to	Very Low Risk	66412	BA337/3/06	9302.2	24/06/2022	WHS	
#REF!	QAA	Craigavon Hospital	17	Sink Pad		Composite Material	Chrysotile	Composite Materials	Medium	Apply caution when maintaining and affix ID labels	Review – No Change	HSG227	Unchecked	Very Low Risk	4	10/08/2021	Strongly Presumed Similar to	Very Low Risk	66413	BA337/3/06	9811/19	15/01/2020	WH Stephens	
#REF!	QAA	Craigavon Hospital	17	Sink Pad		Composite Material	Chrysotile	Composite Materials	High	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Low Risk	5	24/06/2023	Strongly Presumed Similar to	Very Low Risk	66414	BA337/3/06	9302.2	24/06/2022	WHS	
#REF!	QAA	Craigavon Hospital	17	Sink Pad		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Review – No Change	HSG227	Unchecked	Very Low Risk	3	10/08/2021	Strongly Presumed Similar to	Very Low Risk	66415	BA337/3/06	9811/19	15/01/2020	WH Stephens	
#REF!	QAA	Craigavon Hospital	17	Sink Pad		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	24/06/2023	Stronnly Presumed Similar to	Very Low Risk	66416	BA337/3/06	9302.2	24/06/2022	WHS	
#REF!	RAA	South Tyrone Hospital	02	Stair Nosing		Composite Material	NO ASBESTOS		None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66417	BA3311/02	9506/18	20/11/2018	WHS	
#REF!	QAA	Craigavon Hospital	17	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66418	BA337/3/07	9506/18	13/11/2018	WHS	
#REF!	RAA	South Tyrone Hospital	02	Stair Nosing	Duct	Composite Material	NO ASBESTOS		None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66419	BA3331/03	9506/18	20/11/2018	WHS	
#REF!	QAA	Craigavon Hospital	17	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66420	BA337/3/07	9506/18	13/11/2018	WHS	
#REF!	QAA	Craigavon Hospital	17	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66421	BA337/3/07	9506/18	13/11/2018	WHS	
#REF!	QAA	Craigavon Hospital	17	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66422	BA337/3/07	9506/18	13/11/2018	WHS	
#REF!	QAA	Craigavon Hospital	17	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66423	BA337/3/07	9506/18	13/11/2018	WHS	
#REF!	QAA	Craigavon Hospital	17	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66424	BA337/3/07	9506/18	13/11/2018	WHS	
#REF!	QAA	Craigavon Hospital	17	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66425	BA337/3/07	9506/18	13/11/2018	WHS	
#REF!	RAA	South Tyrone Hospital	02	Pipe Insulation	Duct	Thermal Insulation	NO ASBESTOS		None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66426	BA3331/03	9506/18	20/11/2018	WHS	
#REF!	QAA	Craigavon Hospital	17	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66427	BA337/3/07	9506/18	13/11/2018	WHS	
#REF!	QAA	Craigavon Hospital	17	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66428	BA337/3/07	9506/18	13/11/2018	WHS	
#REF!	QAA	Craigavon Hospital	17	Cement Flat Sheet		Cement Products	Chrysotile	Cement Sheets	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	4	24/06/2023	Identified	Very Low Risk	66429	BA337/3/08	9302.2	24/06/2022	WHS	
#REF!	QAA	Craigavon Hospital	17	Cement Flat Sheet		Cement Products	Chrysotile	Cement Sheets	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	4	24/06/2023	Strongly Presumed Similar to	Very Low Risk	66430	BA337/3/08	9302.2	24/06/2022	WHS	
#REF!	QAA	Craigavon Hospital	17	Cement Flat Sheet		Cement Products	Chrysotile	Cement Sheets	Low	Apply caution when maintaining and affix ID labels	Re-inspection	HSG227	Unchecked	Very Low Risk	4	24/06/2023	Strongly Presumed Similar to	Very Low Risk	66431	BA337/3/08	9302.2	24/06/2022	WHS	
#REF!	QAA	Craigavon Hospital	17	Cement Flat Sheet		Cement Products	Chrysotile	Cement Sheets	Low	Apply caution when maintaining and affix ID labels	Review – No Change	HSG227	Unchecked	Very Low Risk	4	10/08/2021	Strongly Presumed Similar to	Very Low Risk	66432	BA337/3/08	9811/19	15/01/2020	WH Stephens	
#REF!	QAA	Craigavon Hospital	17	Cement Flat Sheet		Cement Products	Chrysotile	Cement Sheets	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	4	24/06/2023	Strongly Presumed Similar to	Very Low Risk	66433	BA337/3/08	9302.2	24/06/2022	WHS	
#REF!	QAA	Craigavon Hospital	17	Cement Flat Sheet		Cement Products	Chrysotile	Cement Sheets	Low	Apply caution when maintaining and affix ID labels	Re-inspection	HSG227	Unchecked	Very Low Risk	4	24/06/2023	Strongly Presumed Similar to	Very Low Risk	66434	BA337/3/08	9302.2	24/06/2022	WHS	
#REF!	QAA	Craigavon Hospital	17	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66435	BA337/3/09	9506/18	13/11/2018	WHS	
#REF!	QAA	Craigavon Hospital	17	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66436	BA337/3/10	9506/18	13/11/2018	WHS	
#REF!	QAA	Craigavon Hospital	17	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66437	BA337/3/10	9506/18	13/11/2018	WHS	
#REF!	QAA	Craigavon Hospital	17	Stair Nosing		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66438	BA337/3/11	9506/18	13/11/2018	WHS	
#REF!	QAA	Craigavon Hospital	17	Stair Nosing		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66439	BA337/3/11	9506/18	13/11/2018	WHS	
#REF!	QAA	Craigavon Hospital	17	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66440	BA337/3/12	9506/18	13/11/2018	WHS	
#REF!	QAA	Craigavon Hospital	17	Infill Panel		Insulating Board	NO ASBESTOS	Encapsulated Spray or Lagging/Unsealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66441	BA337/3/13	9506/18	13/11/2018	WHS	
#REF!	QAA	Craigavon Hospital	17	Infill Panel		Insulating Board	NO ASBESTOS	Encapsulated Spray or Lagging/Unsealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66442	BA337/3/13	9506/18	13/11/2018	WHS	
#REF!	QAA	Craigavon Hospital	17	Infill Panel		Insulating Board	NO ASBESTOS	Encapsulated Spray or Lagging/Unsealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66443	BA337/3/13	9506/18	13/11/2018	WHS	
#REF!	QAA	Craigavon Hospital	17	Infill Panel		Insulating Board	NO ASBESTOS	Encapsulated Spray or Lagging/Unsealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66444	BA337/3/13	9506/18	13/11/2018	WHS	
#REF!	QAA	Craigavon Hospital	17	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	24/06/2023	Identified	Very Low Risk	66445	BA337/3/14	9302.2	24/06/2022	WHS	
#REF!	QAA	Craigavon Hospital	17	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	24/06/2023	Identified	Very Low Risk	66446	BA337/3/15	9302.2	24/06/2022	WHS	

#REF!	QAA	Craigavon Hospital	17	Infill Panel		Insulating Board	NO ASBESTOS	Enclosed Spray or Lagging/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66447	BA3373/16	9506/18	13/11/2018	WHS
#REF!	QAA	Craigavon Hospital	17	Infill Panel		Insulating Board	NO ASBESTOS	Enclosed Spray or Lagging/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66448	BA3373/16	9506/18	13/11/2018	WHS
#REF!	QAA	Craigavon Hospital	17	General Debris	Hose Reel Enclosure	General Debris	NO ASBESTOS	Unsealed Spray / Lagging / Dust Debris	Loose asbestos debris or residue	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66449	BA3373/17	9506/18	13/11/2018	WHS
#REF!	QAA	Craigavon Hospital	17	Bitumen Felt	Front Canopy	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66450	BA3373/18	9506/18	13/11/2018	WHS
#REF!	QAA	Craigavon Hospital	17	Bitumen Felt		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66451	BA3373/19	9506/18	13/11/2018	WHS
#REF!	QAA	Craigavon Hospital	17	Ceiling Panel		Insulating Board	NO ASBESTOS	Enclosed Spray or Lagging/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66452	BA3373/20	9506/18	13/11/2018	WHS
#REF!	QAA	Craigavon Hospital	17	Gaskets		Textiles & Paper	Chrysotile	Composite Materials	Low	Apply Caution when Maintaining	Re-inspection	HSG227	Unchecked	Very Low Risk	4	24/06/2023	Identified	Very Low Risk	66453	BA3373/21	9302/2	24/06/2022	WHS
#REF!	QAA	Craigavon Hospital	17	Soffit Boards		Cement Products	Chrysotile	Cement Sheets	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	4	24/06/2023	Identified	Very Low Risk	66454	BA3373/22	9302/2	24/06/2022	WHS
#REF!	QAA	Craigavon Hospital	17	Fuse Flash Guards		Textiles & Paper	Presumed Asbestos	Encapsulated Spray or Lagging/Unsealed AIB	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Medium Risk	9	24/06/2023	Presumed	Medium Risk	66455		9302/2	24/06/2022	WHS
#REF!	RAA	South Tyrone Hospital	02	Flash Guard	Duct	Textiles & Paper	Presumed Asbestos	Enclosed Fuse Flash Guards	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Medium Risk	8	15/12/2023	Presumed	Medium Risk	66456		9302/2	15/12/2022	WHS
#REF!	QAA	Craigavon Hospital	17	Cowl		Cement Products	Presumed Asbestos	Enclosed Spray or	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Medium Risk	7	24/06/2023	Presumed	Medium Risk	66457		9302/2	24/06/2022	WHS
#REF!	QAA	Craigavon Hospital	17	Verge Cloak		Cement Products	Presumed Asbestos	Cement Sheets	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Low Risk	6	24/06/2023	Presumed	Low Risk	66458		9302/2	24/06/2022	WHS
#REF!	RAA	South Tyrone Hospital	02	Fuse Flash Guards	Duct	Textiles & Paper	Presumed Asbestos	Enclosed Fuse Flash Guards	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Medium Risk	8	15/12/2023	Presumed	Medium Risk	66459		9302/2	15/12/2022	WHS
#REF!	QAA	Craigavon Hospital	17	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66460	BA3373/23	9506/18	13/11/2018	WHS
#REF!	QAA	Craigavon Hospital	17	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66461	BA3373/23	9506/18	13/11/2018	WHS
#REF!	RAA	South Tyrone Hospital	02	Sink Pad		Composite Material	NO ASBESTOS		None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66462	BA3331-04	9506/18	20/11/2018	WHS
#REF!	QAA	Craigavon Hospital	17		Store outside A-032 Toilet		NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	66463		9506/18	13/11/2018	WHS
#REF!	RAA	South Tyrone Hospital	02	Sink Pad		Composite Material	NO ASBESTOS		None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66464	BA3331/04	9506/18	20/11/2018	WHS
#REF!	RAA	South Tyrone Hospital	02	Sink Pad		Composite Material	NO ASBESTOS		None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66465	BA3331/04	9506/18	20/11/2018	WHS
#REF!	RAA	South Tyrone Hospital	02	Sink Pad		Composite Material	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66466	BA3331/04	9506/18	20/11/2018	WHS
#REF!	RAA	South Tyrone Hospital	02	NO ASBESTOS		NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66467	BAA331/05	9506/18	20/11/2018	WHS
#REF!	RAA	South Tyrone Hospital	02	Board	Attic Hatch	Insulating Board	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66468	BA3331/06	9506/18	20/11/2018	WHS
#REF!	RAA	South Tyrone Hospital	02	Damp Proof Course		Composite Material	NO ASBESTOS		None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66469	BA3331/07	9506/18	20/11/2018	WHS
#REF!	QAA	Craigavon Hospital	16	Roofing Felts		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66470	BA3360/01	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	16	Debris		Cement Products	NO ASBESTOS	Unsealed Spray / Lagging / Dust Debris	Loose asbestos debris or residue	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	Asbestos Removed	66471	BA3360/02	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	16	Fire Break Panel		Insulating Board	NO ASBESTOS	Encapsulated Spray or Lagging/Unsealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66472	BA3360/03	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	16	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66473	BA3360/04	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	16	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66474	BA3360/04	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	16	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66475	BA3360/04	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	16	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66476	BA3360/04	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	16	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66477	BA3360/04	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	16	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66478	BA3360/04	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	16	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66479	BA3360/05	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	16	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66481	BA3360/05	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	16	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66482	BA3360/05	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	16	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66483	BA3360/05	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	16	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66484	BA3360/05	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	16	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66485	BA3360/06	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	16	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	Asbestos Removed	66486	BA3360/07	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	16	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	Asbestos Removed	66490	BA3360/08	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	16	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66492	BA3360/09	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	16	Insulating Board		Insulating Board	NO ASBESTOS	Enclosed Spray or Lagging/Sealed AIB	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66493	BA3360/10	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	16	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	Asbestos Removed	66495	BA3360/11	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	16	Cement Flat Sheet		Cement Products	NO ASBESTOS	Enclosed Spray or Lagging/Sealed AIB	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	Asbestos Removed	66496	BA3360/12	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	16	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66497	BA3360/13	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	16	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66498	BA3360/14	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	16	Infill Panel		Insulating Board	NO ASBESTOS	Enclosed Spray or Lagging/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66499	BA3360/15	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	16	Infill Panel		Insulating Board	NO ASBESTOS	Enclosed Spray or Lagging/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66500	BA3360/15	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	16	Infill Panel		Insulating Board	NO ASBESTOS	Enclosed Spray or Lagging/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66501	BA3360/15	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	16	Infill Panel		Insulating Board	NO ASBESTOS	Enclosed Spray or Lagging/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66502	BA3360/15	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	16	Stair Nosing		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66503	BA3360/16	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	16	Stair Nosing		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66504	BA3360/16	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	16	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Medium	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	24/07/2018	Identified	Asbestos Removed	66505	BA3360/17	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	16	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66506	BA3360/18	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	16	Floor Tile and Bitumen Adhesive		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	24/07/2018	Identified	Asbestos Removed	66507	BA3360/19	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	16	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Review – No Change	HSG227	Unchecked	Very Low Risk	3	10/07/2021	Identified	Very Low Risk	66508	BA3360/20	9611/1	01/08/2020	WH Stephens
#REF!	QAA	Craigavon Hospital	16	Infill Panel		Insulating Board	NO ASBESTOS	Enclosed Spray or Lagging/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66509	BA3360/21	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	16	Infill Panel		Insulating Board	NO ASBESTOS	Enclosed Spray or Lagging/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66510	BA3360/21	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	16	Sink Pad		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	24/06/2023	Identified	Very Low Risk	66511	BA3360/22	9302/2	24/06/2022	WHS
#REF!	QAA	Craigavon Hospital	16	Ceiling Board		Insulating Board	NO ASBESTOS	Enclosed Spray or Lagging/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66512	BA3360/23	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	16	Gaskets		Textiles & Paper	Presumed Asbestos	Encapsulated Spray or Lagging/Unsealed AIB	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Medium Risk	8	24/06/2023	Presumed	Medium Risk	66513		9302/22	24/06/2022	WHS
#REF!	QAA	Craigavon Hospital	16	Bitumen Felt		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66514	BA3360/24	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	16	Bitumen Felt		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66515	BA3360/25	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	16	Soffit Boards		Cement Products	Chrysotile	Cement Sheets	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	4	24/06/2023	Identified	Very Low Risk	66516	BA3360/26	9302/2	24/06/2022	WHS
#REF!	QAA	Craigavon Hospital	16	Fuse Flash Guards	Hose Reel Electrical Cupboards	Textiles & Paper	NO ASBESTOS	Encapsulated Spray or Lagging/Unsealed AIB	Medium	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	24/07/2018	Presumed	Asbestos Removed	66517		9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	16	Fuse Flash Guards		Textiles & Paper	Presumed Asbestos	Encapsulated Spray or Lagging/Unsealed AIB	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Medium Risk	9	24/12/2022	Presumed	Medium Risk	66518		9302/22	24/06/2022	WHS
#REF!	QAA	Craigavon Hospital	16	Cowl		Cement Products	Presumed Asbestos	Enclosed Spray or	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Medium Risk	7	24/12/2022	Presumed	Medium Risk	66519		9611/1	24/06/2022	WHS
#REF!	QAA	Craigavon Hospital	16	Verge Cloak		Cement Products	Presumed Asbestos	Enclosed Spray or	Medium	Conduct annual routine inspections	Review – No Change	HSG227	Unchecked	Medium Risk	7	10/07/2021	Presumed	Medium Risk	66520		9611/1	01/08/2020	WH Stephens
#REF!	QAA	Craigavon Hospital	16	NO ASBESTOS		NO ASBESTOS	NO ASBESTOS	Composite Material	Very Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66521	BS146333	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	16							Re-Survey	Review – No Change	HSG227	Checked	Hoh Risk	0	24/07/2018			66522		9724/17	05/09/2017	WHS
#REF!	RAE	Drumglass Site	02	Pipe Insulation		Thermal Insulation	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66523	BA3333/01	9506/18	31/01/2019	WHS
#REF!	RAE	Drumglass Site	02	Floor Tiles		Composite Material	Chrysotile	Composite Materials	Low	Apply Caution when Maintaining	Re-inspection	HSG227	Unchecked	Very Low Risk	3	03/01/2024	Identified	Very Low Risk	66524	BA3333/02	9302/2	03/01/2023	WHS
#REF!	RAE	Drumglass Site	02	Floor Tiles		Composite Material	Chrysotile	Composite Materials	Low	Apply Caution when Maintaining	Re-inspection	HSG227	Unchecked	Very Low Risk	3	03/01/2024	Identified	Very Low Risk	66525	BA3333/03	9302/2	03/01/2023	WHS
#REF!	RAE	Drumglass Site	02	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Very Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66526	BA3333/04	9506/18	31/01/2019	WHS
#REF!	RAE	Drumglass Site	02	Sink Pad		Composite Material	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66527	BA3333/04	9506/18	31/01/2019	WHS
#REF!	RAE	Drumglass Site	02	Stair Nosing		Composite Material	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66528	BA3333/05	9506/18	31/01/2019	WHS
#REF!	RAE	Drumglass Site	02	Stair Nosing		Composite Material	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66529	BA3333/05	9506/18	31/01/2019	WHS
#REF!	RAE	Drumglass Site	02	Floor Tiles		Composite Material	Chrysotile	Composite Materials	Very Low	Apply Caution when Maintaining	Re-inspection	HSG227	Unchecked	Very Low Risk	2	03/01/2024	Identified	Very Low Risk	66530	BA3333/06	9302/2	03/01/2023	WHS
#REF!	RAE	Drumglass Site	02	Floor Tiles		Composite Material	Chrysotile	Composite Materials	Very Low	Apply Caution when Maintaining	Re-inspection	HSG227	Unchecked	Very Low Risk	2	03/01/2024	Stronnly Presumed Similar to	Very Low Risk	66531	BA3333/06	9302/2	03/01/2023	WHS
#REF!	RAE	Drumglass Site	02	Floor Tiles		Composite Material	Chrysotile	Composite Materials	Very Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	2	03/01/2024	Stronnly Presumed Similar to	Very Low Risk	66532	BA3333/06	9302/2	03/01/2023	WHS
#REF!	RAE	Drumglass Site	02	Floor Tiles		Composite Material	Chrysotile	Composite Materials	Very Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	2	03/01/2024	Stronnly Presumed Similar to	Very Low Risk	66533	BA3333/06	9302/2	03/01/2023	WHS

#REF!	RAE	Drumglass Site	02	Fuse Flash Guards		Textiles & Paper	NO ASBESTOS	Enclosed Fuse Flash Guards	Medium	Apply caution when maintaining and affix ID labels	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	02/05/2020	Presumed	No Asbestos Detected	66534		9506/18	31/01/2019	WHS
#REF!	RAE	Drumglass Site	02	Wall Panels		Insulating Board	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66535	BA3333/07	9506/18	31/01/2019	WHS
#REF!	RAE	Drumglass Site	02	Board	Cavity Closer	Insulating Board	Amosite/Chrysotile	Unsealed Board	Medium	Inspect on a regular basis	Re-inspection	HSG227	Unchecked	Medium Risk	8	03/01/2024	Identified	Medium Risk	66536	BA3333/08	9302.22	03/01/2023	WHS
#REF!	RAE	Drumglass Site	02	Bitumen Felt		Composite Material	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66537	BA3333/09	9506/18	31/01/2019	WHS
#REF!	RAE	Drumglass Site	02				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66538	BA3333/10	9506/18	31/01/2019	WHS
#REF!	RAE	Drumglass Site	02	Floor Tiles		Composite Material	Chrysotile	Composite Materials	Very Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	2	03/01/2024	Identified	Very Low Risk	66539	BA3333/11	9302.22	03/01/2023	WHS
#REF!	RAE	Drumglass Site	02	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Very Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	Asbestos Removed	66540	BA3333/11	9506/18	31/01/2019	WHS
#REF!	RAE	Drumglass Site	02	Partition Panel		Insulating Board	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66541	BA3333/12	9506/18	31/01/2019	WHS
#REF!	RAE	Drumglass Site	02	Partition Panel		Insulating Board	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66542	BA3333/12	9506/18	31/01/2019	WHS
#REF!	RAE	Drumglass Site	02	Sink Pad		Composite Material	Chrysotile	Composite Materials	Very Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	2	03/01/2024	Identified	Very Low Risk	66543	BA3333/13	9302.22	03/01/2023	WHS
#REF!	RAE	Drumglass Site	02	Gaskets	Burner on Boiler No.2	Textiles & Paper	Chrysotile	Unsealed	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Medium Risk	7	03/01/2024	Identified	Medium Risk	66544	BA3333/14	9302.22	03/01/2023	WHS
#REF!	RAE	Drumglass Site	02	Ropes	Rope Gasket to Boiler 2 Burner	Textiles & Paper	Chrysotile	Unsealed Rope	Low	Apply caution when maintaining and affix ID labels	Re-inspection	HSG227	Unchecked	Low Risk	6	03/01/2024	Identified	Low Risk	66545	BA3333/15	9302.22	03/01/2023	WHS
#REF!	RAE	Drumglass Site	02	Ceiling Panelling		Insulating Board	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66546	BA3333/16	9506/18	31/01/2019	WHS
#REF!	RAE	Drumglass Site	02		Rope Gasket to Boiler Flue	Textiles & Paper	Chrysotile	Unsealed Rope	Low	Apply caution when maintaining and affix ID labels	Re-inspection	HSG227	Unchecked	Low Risk	6	03/01/2024	Identified	Low Risk	66547	BA3333/17	9302.22	03/01/2023	WHS
#REF!	RAE	Drumglass Site	02	Insulation Blocks	Internal Insulation to Boilers	Insulating Board	Presumed Asbestos	Encased beneath overlaying non-asbestos insulation	Medium	Apply caution when maintaining and affix ID labels	Re-inspection	HSG227	Unchecked	High Risk	10	03/01/2024	Presumed	High Risk	66548		9302.22	03/01/2023	WHS
#REF!	RAE	Drumglass Site	02	Fuse Flash Guards	Electrical Equipment	Textiles & Paper	Presumed Asbestos	Enclosed Fuse Flash Guards	Medium	Apply caution when maintaining and affix ID labels	Re-inspection	HSG227	Unchecked	Medium Risk	8	03/01/2024	Presumed	Medium Risk	66549		9302.22	03/01/2023	WHS
#REF!	RAE	Drumglass Site	02	Ceiling Panelling		Insulating Board	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66550	BA3333/18	9506/18	31/01/2019	WHS
#REF!	RAE	Drumglass Site	02	Ceiling Panelling		Insulating Board	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66551	BA3333/18	9506/18	31/01/2019	WHS
#REF!	RAE	Drumglass Site	02	Ceiling Panelling		Insulating Board	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66552	BA3333/18	9506/18	31/01/2019	WHS
#REF!	RAE	Drumglass Site	02	Ceiling Panelling		Insulating Board	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66553	BA3333/18	9506/18	31/01/2019	WHS
#REF!	RAE	Drumglass Site	02	Panel	Wall Vents	Insulating Board	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66554	BA4333/19	9506/18	31/01/2019	WHS
#REF!	RAE	Drumglass Site	02	Roge Seal	Generator Exhaust	Textiles & Paper	Chrysotile	Unsealed Roge	Medium	Encapsulate and Monitor	Re-inspection	HSG227	Unchecked	Medium Risk	7	03/01/2024	Identified	Medium Risk	66555	BA3333/20	9302.22	03/01/2023	WHS
#REF!	RAE	Drumglass Site	02	Soffit Boards	External	Insulating Board	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66556	BA3333/21	9506/18	31/01/2019	WHS
#REF!	RAE	Drumglass Site	02	Bitumen Felt		Composite Material	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66557	BA3333/22	9506/18	31/01/2019	WHS
#REF!	RAE	Drumglass Site	02	Undercloak to Roof Verge		Cement Products	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66558	BA3333/23	9506/18	31/01/2019	WHS
#REF!	RAE	Drumglass Site	06	Insulating Board	Broken Board	Insulating Board	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66559	BA3389/01	9506/18	31/01/2019	WHS
#REF!	RAE	Drumglass Site	06	Undercloak to Roof Verge		Cement Products	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66560	BA3389/02	9506/18	31/01/2019	WHS
#REF!	RAE	Drumglass Site	06	Textured Coatings	Walls	Decorative Coatings	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66561	BA3389/03	9506/18	31/01/2019	WHS
#REF!	RAE	Drumglass Site	06	Insulation Blocks	Internal Insulation to Boiler	Insulating Board	Presumed Asbestos	Encased beneath overlaying non-asbestos insulation	Medium	Apply caution when maintaining and affix ID labels	Re-inspection	HSG227	Unchecked	High Risk	10	27/03/2021	Presumed	High Risk	66562		9811/19	19/11/2019	WHS
#REF!	RAE	Drumglass Site	06	Pipe Insulation		Thermal Insulation	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66563	BA3389/04	9506/18	31/01/2019	WHS
#REF!	RAE	Drumglass Site	01	Ceiling Tiles		Insulating Board	NO ASBESTOS	Unsealed Board	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66575	BA3388/01	9506/18	29/01/2019	WHS
#REF!	RAE	Drumglass Site	01	Ceiling Tiles		Insulating Board	NO ASBESTOS	Unsealed Board	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66577	BA3388/01	9506/18	29/01/2019	WHS
#REF!	RAE	Drumglass Site	01	Stair Nosing	Stairs to Store	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66579	BA3388/02	9506/18	29/01/2019	WHS
#REF!	RAE	Drumglass Site	01	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Very Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66580	BA3388/03	9506/18	29/01/2019	WHS
#REF!	RAE	Drumglass Site	01	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Very Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66581	BA3388/03	9506/18	29/01/2019	WHS
#REF!	RAE	Drumglass Site	01	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66583	BA3388/04	9506/18	29/01/2019	WHS
#REF!	RAE	Drumglass Site	01	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66584	BA3388/04	9506/18	29/01/2019	WHS
#REF!	RAE	Drumglass Site	01	Rope Seal	Fire Safe	Textiles & Paper	NO ASBESTOS	Unsealed Rope	Medium	Apply caution when maintaining and affix ID labels	ACM Removed	HSG227	Unchecked	NO ASBESTOS	0	20/08/2016	Presumed	Asbestos Removed	66587		9506/18	29/01/2019	WHS
#REF!	RAE	Drumglass Site	01	Insulation Blocks	Basement Boiler Room	Insulating Board	NO ASBESTOS	Consealed Asbestos Insulation Board	Medium	Apply caution when maintaining and affix ID labels	Re-inspection	HSG227	Unchecked	NO ASBESTOS	0	20/08/2016	Presumed	No Asbestos Detected	66589		9506/18	29/01/2019	WHS
#REF!	RAE	Drumglass Site	01	Fuse Flash Bands	Electrical Equipment	Textiles & Paper	Presumed Asbestos	Enclosed Fuse Flash Guards	Medium	Apply caution when maintaining and affix ID labels	Re-inspection	HSG227	Unchecked	Medium Risk	8	27/03/2021	Presumed	Medium Risk	66590		9811/19	19/11/2019	WHS
#REF!	RAE	Drumglass Site	01	Rope Seal	Rope Gasket to Boiler	Textiles & Paper	NO ASBESTOS	Unsealed Rope	Very Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66592	BA3388/05	9506/18	29/01/2019	WHS
#REF!	RAE	Drumglass Site	01	Wall Panels	Corridor	Insulating Board	NO ASBESTOS	Unsealed Board	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66593	BA3388/06	9506/18	29/01/2019	WHS
#REF!	RAE	Drumglass Site	01	Wall Panels		Insulating Board	NO ASBESTOS	Unsealed Board	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66594	BA3388/06	9506/18	29/01/2019	WHS
#REF!	RAE	Drumglass Site	01	Textured Coatings	Wall Coating Pre-Fab	Decorative Coatings	NO ASBESTOS	Textured Coating	Very Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66595	BA3388/07	9506/18	29/01/2019	WHS
#REF!	RAE	Drumglass Site	01	Bitumen Felt	Flat Roof	Composite Material	NO ASBESTOS	Composite Materials	Very Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66596	BA3388/08	9506/18	29/01/2019	WHS
#REF!	RAE	Drumglass Site	01	Roof Slate	Roof	Cement Products	Chrysotile	Cement Sheets	Low	Apply caution when maintaining and affix ID labels	Re-inspection	HSG227	Unchecked	Very Low Risk	4	27/03/2021	Identified	Very Low Risk	66597	BA3388/09	9811/19	19/11/2019	WHS
#REF!	RAE	Drumglass Site	01	Soffit Boards	Small Gable Wall	Insulating Board	Chrysotile	Encapsulated Asbestos Insulation Board	Low	Apply caution when maintaining and affix ID labels	Re-inspection	HSG227	Unchecked	Low Risk	5	27/03/2021	Identified	Low Risk	66599	BA3388/10	9811/19	19/11/2019	WHS
#REF!	RAA	South Tyrone Hospital	17	Brake Pads		Textiles & Paper	Presumed Asbestos	Other Materials	Medium	Apply caution when maintaining and affix ID labels	Re-inspection	HSG227	Unchecked	High Risk	10	14/12/2023	Presumed	High Risk	66687		9302.22	14/12/2022	WHS
#REF!	RAA	South Tyrone Hospital	17	Fuse Flash Guards		Textiles & Paper	Presumed Asbestos	Enclosed Fuse Flash Guards	Medium	Apply caution when maintaining and affix ID labels	Re-inspection	HSG227	Unchecked	Medium Risk	8	14/12/2023	Presumed	Medium Risk	66688		9302.22	14/12/2022	WHS
#REF!	RAA	South Tyrone Hospital	17	Fuse Flash Guards		Textiles & Paper	Chrysotile	Enclosed Fuse Flash Guards	Medium	Apply caution when maintaining and affix ID labels	Re-inspection	HSG227	Unchecked	Low Risk	6	14/12/2023	Strongly Presumed Similar to	Low Risk	66689	BS136669	9302.22	14/12/2022	WHS
#REF!	RAA	South Tyrone Hospital	17	Fuse Flash Guards		Textiles & Paper	Chrysotile	Enclosed Fuse Flash Guards	Medium	Apply caution when maintaining and affix ID labels	Re-inspection	HSG227	Unchecked	Low Risk	6	14/12/2023	Strongly Presumed Similar to	Low Risk	66691	BS136669	9302.22	14/12/2022	WHS
#REF!	RAA	South Tyrone Hospital	17	Fuse Flash Guards		Textiles & Paper	Chrysotile	Enclosed Fuse Flash Guards	Medium	Apply caution when maintaining and affix ID labels	Re-inspection	HSG227	Unchecked	Low Risk	6	14/12/2023	Strongly Presumed Similar to	Low Risk	66692	BS136669	9302.22	14/12/2022	WHS
#REF!	RAA	South Tyrone Hospital	17	Fuse Flash Guards		Textiles & Paper	Chrysotile	Enclosed Fuse Flash Guards	Medium	Apply caution when maintaining and affix ID labels	Re-inspection	HSG227	Unchecked	Low Risk	6	14/12/2023	Strongly Presumed Similar to	Low Risk	66693	BS136669	9302.22	14/12/2022	WHS
#REF!	RAA	South Tyrone Hospital	17	Fuse Flash Guards		Textiles & Paper	Chrysotile	Enclosed Fuse Flash Guards	Medium	Apply caution when maintaining and affix ID labels	Re-inspection	HSG227	Unchecked	Low Risk	6	14/12/2023	Strongly Presumed Similar to	Low Risk	66694	BS136669	9302.22	14/12/2022	WHS
#REF!	RAA	South Tyrone Hospital	17	Fuse Flash Guards		Textiles & Paper	Chrysotile	Enclosed Fuse Flash Guards	Medium	Apply caution when maintaining and affix ID labels	Re-inspection	HSG227	Unchecked	Low Risk	6	13/12/2023	Strongly Presumed Similar to	Low Risk	66695	BS136669	9302.22	13/12/2022	WHS
#REF!	RAA	South Tyrone Hospital	17	Fuse Flash Guards		Textiles & Paper	Chrysotile	Enclosed Fuse Flash Guards	Medium	Apply caution when maintaining and affix ID labels	Re-inspection	HSG227	Unchecked	Low Risk	6	13/12/2023	Strongly Presumed Similar to	Low Risk	66696	BS136669	9302.22	13/12/2022	WHS
#REF!	RAA	South Tyrone Hospital	17	Fuse Flash Guards		Textiles & Paper	Chrysotile	Enclosed Fuse Flash Guards	Medium	Apply caution when maintaining and affix ID labels	Re-inspection	HSG227	Unchecked	Low Risk	6	13/12/2023	Strongly Presumed Similar to	Low Risk	66698		9302.22	13/12/2022	WHS
#REF!	RAA	South Tyrone Hospital	17	Fuse Flash Guards	Fuse flash guards	Textiles & Paper	Chrysotile	Enclosed Fuse Flash Guards	Medium	Apply caution when maintaining and affix ID labels	Re-inspection	HSG227	Unchecked	Low Risk	6	13/12/2023	Identified	Low Risk	66699	BA9345	9302.22	13/12/2022	WHS
#REF!	RAA	South Tyrone Hospital	17	Fuse Flash Guards		Textiles & Paper	NO ASBESTOS	Enclosed Fuse Flash Guards	Medium	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Presumed	Asbestos Removed	66701		9506/18	12/05/2018	WHS
#REF!	RAA	South Tyrone Hospital	17	Fuse Flash Guards	Fuse flash guard	Textiles & Paper	Presumed Asbestos	Enclosed Fuse Flash Guards	Medium	Apply caution when maintaining and affix ID labels	Re-inspection	HSG227	Unchecked	Medium Risk	8	13/12/2023	Identified	Medium Risk	66702	BA9345	9302.22	13/12/2022	WHS
#REF!	RAA	South Tyrone Hospital	17	Fuse Flash Guards		Textiles & Paper	Chrysotile	Enclosed Fuse Flash Guards	Medium	Apply caution when maintaining and affix ID labels	Re-inspection	HSG227	Unchecked	Low Risk	6	13/12/2023	Identified	Low Risk	66704	BS136669	9302.22	13/12/2022	WHS
#REF!	RAA	South Tyrone Hospital	17	Fuse Flash Guards		Textiles & Paper	Chrysotile	Enclosed Fuse Flash Guards	Medium	Apply caution when maintaining and affix ID labels	Re-inspection	HSG227	Unchecked	Low Risk	6	13/12/2023	Strongly Presumed Similar to	Low Risk	66705	BS136669	9302.22	13/12/2022	WHS
#REF!	RAA	South Tyrone Hospital	17	Fuse Flash Guards		Textiles & Paper	NO ASBESTOS	Enclosed Fuse Flash Guards	Medium	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Presumed	Asbestos Removed	66706		9506/18	12/05/2018	WHS
#REF!	RAA	South Tyrone Hospital	17	Fuse Flash Guards		Textiles & Paper	Presumed Asbestos	Enclosed Fuse Flash Guards	Medium	Apply caution when maintaining and affix ID labels	Re-inspection	HSG227	Unchecked	Medium Risk	8	13/12/2023	Strongly Presumed Similar to	Medium Risk	66707		9302.22	13/12/2022	WHS
#REF!	RAA	South Tyrone Hospital	17	Fuse Flash Guards		Textiles & Paper	NO ASBESTOS	Enclosed Fuse Flash Guards	Medium	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Presumed	Asbestos Removed	66708		9506/18	12/05/2018	WHS
#REF!	RAA	South Tyrone Hospital	17	Air Conditioning Brackets		Textiles & Paper	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66709	BA3413/01	9506/18	12/05/2018	WHS
#REF!	RAA	South Tyrone Hospital	17	Pipe Lagging	Throughout G Floor	Thermal Insulation	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66711	BA3413/02	9506/18	12/05/2018	WHS
#REF!	RAA	South Tyrone Hospital	17	Pipe Lagging	Throughout above suspended ceiling	Thermal Insulation	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66713	BA3413/02	9506/18	12/05/2018	WHS
#REF!	RAA	South Tyrone Hospital	17	Pipe Lagging	Throughout E Floor above suscended ceilins	Thermal Insulation	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66714	BA3413/02	9506/18	12/05/2018	WHS
#REF!	RAA	South Tyrone Hospital	17	Pipe Lagging	Throughout D Floor above suscended ceilins	Thermal Insulation	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66715	BA3413/02	9506/18	12/05/2018	WHS
#REF!	RAA	South Tyrone Hospital	17	Pipe Lagging	Throughout C Floor above suspended ceilins	Thermal Insulation	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66716	BA3413/02	9506/18	12/05/2018	WHS
#REF!	RAA	South Tyrone Hospital	17	Pipe Lagging	Throughout B Floor above suspended ceilins	Thermal Insulation	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66717	BA3413/02	9506/18	12/05/2018	WHS
#REF!	RAA	South Tyrone Hospital	17	Pipe Lagging	Throughout A Floor	Thermal Insulation	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66718	BA3413/02	9506/18	12/05/2018	WHS
#REF!	RAA	South Tyrone Hospital	17	Rope Seal	High Level-Pipe extract	Textiles & Paper	Chrysotile	Unsealed Rope	Low	Further investigation Required	Re-inspection	HSG227	Unchecked	Low Risk	6	14/12/2023	Identified	Low Risk	66719	BA3413/03	9302.22	14/12/2022	WHS
#REF!	RAA	South Tyrone Hospital	17	Floor Tiles		Composite Material	Chrysotile	Composite Materials	Low	Apply caution when maintaining and affix ID labels	Re-inspection	HSG227	Unchecked	Very Low Risk	3	14/12/2023	Identified	Very Low Risk	66725	BA3413/04	9302.22	14/12/2022	WHS
#REF!	RAA	South Tyrone Hospital	17	Floor Tiles		Composite Material	Chrysotile	Composite Materials	Low	Apply caution when maintaining and affix ID labels	Re-inspection	HSG227	Unchecked	Very Low Risk	3	14/12/2023	Identified	Very Low Risk	66726	BA3413/04	9302.22	14/12/2022	WHS

#REF!	RAA	South Tyrone Hospital	17	Floor Tiles		Composite Material	Chrysotile	Composite Materials	Low	Apply caution when maintaining and affix ID labels	Re-inspection	HSG227	Unchecked	Very Low Risk	3	14/12/2023	Identified	Very Low Risk	66727	BA3413/04	9302.22	14/12/2022	WHS
#REF!	RAA	South Tyrone Hospital	17	Floor Tiles		Composite Material	Chrysotile	Composite Materials	Low	Apply caution when maintaining and affix ID labels	Re-inspection	HSG227	Unchecked	Very Low Risk	3	14/12/2023	Identified	Very Low Risk	66728	BA3413/04	9302.22	14/12/2022	WHS
#REF!	RAA	South Tyrone Hospital	17	Floor Tiles		Composite Material	Chrysotile	Composite Materials	Low	Apply caution when maintaining and affix ID labels	Re-inspection	HSG227	Unchecked	Very Low Risk	3	13/12/2023	Identified	Very Low Risk	66729	BA3413/04	9302.22	13/12/2022	WHS
#REF!	RAA	South Tyrone Hospital	17	Floor Tiles	Store	Composite Material	Chrysotile	Composite Materials	Low	Further investigation Required	Re-inspection	HSG227	Unchecked	Very Low Risk	3	13/12/2023	Identified	Very Low Risk	66730	BA3413/04	9302.22	13/12/2022	WHS
#REF!	RAA	South Tyrone Hospital	17	Floor Tiles	Under carpet	Composite Material	Chrysotile	Composite Materials	Low	Apply Caution when Maintaining	Re-inspection	HSG227	Unchecked	Very Low Risk	3	14/12/2023	Identified	Very Low Risk	66731	BA3413/05	9302.22	14/12/2022	WHS
#REF!	RAA	South Tyrone Hospital	17	Floor Tiles		Composite Material	Chrysotile	Composite Materials	Low	Apply Caution when Maintaining	Re-inspection	HSG227	Unchecked	Very Low Risk	3	13/12/2023	Stronnly Presumed Similar to	Very Low Risk	66732	BA3413/05	9302.22	13/12/2022	WHS
#REF!	RAA	South Tyrone Hospital	17	Insulating Debris		General Debris	NO ASBESTOS	Loose Asbestos Debris	Loose asbestos debris or residue	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66733	BA3413/06	9506/18	12/05/2018	WHS
#REF!	RAA	South Tyrone Hospital	17	Insulating Debris		General Debris	NO ASBESTOS	Loose Asbestos Debris	Loose asbestos debris or residue	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66734	BA3413/06	9506/18	12/05/2018	WHS
#REF!	RAA	South Tyrone Hospital	17	Insulating Debris		General Debris	NO ASBESTOS	Loose Asbestos Debris	Loose asbestos debris or residue	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66735	BA3413/06	9506/18	12/05/2018	WHS
#REF!	RAA	South Tyrone Hospital	17	Stair Nosing		Composite Material	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66736	BA3413/07	9506/18	12/05/2018	WHS
#REF!	RAA	South Tyrone Hospital	17	Stair Nosing		Composite Material	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Stronnly Presumed Similar to	No Asbestos Detected	66737	BA3413/07	9506/18	12/05/2018	WHS
#REF!	RAA	South Tyrone Hospital	17	Stair Nosing		Composite Material	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Stronnly Presumed Similar to	No Asbestos Detected	66738	BA3413/07	9506/18	12/05/2018	WHS
#REF!	RAA	South Tyrone Hospital	17	Stair Nosing		Composite Material	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Stronnly Presumed Similar to	No Asbestos Detected	66739	BA3413/07	9506/18	12/05/2018	WHS
#REF!	RAA	South Tyrone Hospital	17	Stair Nosing		Composite Material	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Stronnly Presumed Similar to	No Asbestos Detected	66740	BA3413/07	9506/18	12/05/2018	WHS
#REF!	RAA	South Tyrone Hospital	17	Stair Nosing		Composite Material	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Stronnly Presumed Similar to	No Asbestos Detected	66741	BA3413/07	9506/18	12/05/2018	WHS
#REF!	RAA	South Tyrone Hospital	17	Insulating Board	Tube Cupboard	Insulating Board	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66742	BA3413/08	9506/1a	12/05/2018	WHS
#REF!	RAA	South Tyrone Hospital	17	Insulating Board	Tube Cupboard	Insulating Board	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Stronnly Presumed Similar to	No Asbestos Detected	66743	BA3413/08	9506/18	12/05/2018	WHS
#REF!	RAA	South Tyrone Hospital	17	Insulating Board	Tube Cupboard	Insulating Board	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Stronnly Presumed Similar to	No Asbestos Detected	66744	BA3413/08	9506/18	12/05/2018	WHS
#REF!	RAA	South Tyrone Hospital	17	Insulating Board	Tube Cupboard	Insulating Board	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Stronnly Presumed Similar to	No Asbestos Detected	66745	BA3413/08	9506/1a	12/05/2018	WHS
#REF!	RAA	South Tyrone Hospital	17	Floor Tiles		Composite Material	Chrysotile	Composite Materials	Very Low	Apply caution when maintaining and affix ID labels	Re-inspection	HSG227	Unchecked	Very Low Risk	2	14/12/2023	Identified	Very Low Risk	66746	BA3413/09	9302.22	14/12/2022	WHS
#REF!	RAA	South Tyrone Hospital	17	Floor Tiles		Composite Material	Chrysotile	Composite Materials	Very Low	Apply caution when maintaining and affix ID labels	Re-inspection	HSG227	Unchecked	Very Low Risk	2	14/12/2023	Stronnly Presumed Similar to	Very Low Risk	66747	BA3413/09	9302.22	14/12/2022	WHS
#REF!	RAA	South Tyrone Hospital	17	Floor Tiles		Composite Material	Chrysotile	Composite Materials	Very Low	Apply caution when maintaining and affix ID labels	Re-inspection	HSG227	Unchecked	Very Low Risk	2	13/12/2023	Identified	Very Low Risk	66748	BA3413/09	9302.22	13/12/2022	WHS
#REF!	RAA	South Tyrone Hospital	17	Floor Tiles		Composite Material	Chrysotile	Composite Materials	Very Low	Apply caution when maintaining and affix ID labels	Re-inspection	HSG227	Unchecked	Very Low Risk	2	13/12/2023	Stronnly Presumed Similar to	Very Low Risk	66749	BA3413/09	9302.22	13/12/2022	WHS
#REF!	RAA	South Tyrone Hospital	17	Floor Tiles		Composite Material	Chrysotile	Composite Materials	Very Low	Apply caution when maintaining and affix ID labels	Re-inspection	HSG227	Unchecked	Very Low Risk	2	14/12/2023	Identified	Very Low Risk	66750	BA3413/10	9302.22	14/12/2022	WHS
#REF!	RAA	South Tyrone Hospital	17	Lino Flooring	under carpet	Composite Material	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66751	BA3413/11	9506/18	12/05/2018	WHS
#REF!	RAA	South Tyrone Hospital	17	Lino Flooring	Under carpet	Composite Material	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66752	BA3413/11	9506/18	12/05/2018	WHS
#REF!	RAA	South Tyrone Hospital	17	Lino Flooring	Under Carpet	Composite Material	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66753	BA3413/11	9506/18	12/05/2018	WHS
#REF!	RAA	South Tyrone Hospital	17	Lino Flooring	Under Carpet	Composite Material	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Stronnly Presumed Similar to	No Asbestos Detected	66754	BA3413/11	9506/18	12/05/2018	WHS
#REF!	RAA	South Tyrone Hospital	17	Sink Pad		Composite Material	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66755	BA3413/12	9506/18	12/05/2018	WHS
#REF!	RAA	South Tyrone Hospital	17	Sink Pad		Composite Material	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Stronnly Presumed Similar to	No Asbestos Detected	66756	BA3413/12	9506/18	12/05/2018	WHS
#REF!	RAA	South Tyrone Hospital	17	Sink Pad		Composite Material	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66757	BA3413/12	9506/1a	12/05/2018	WHS
#REF!	RAA	South Tyrone Hospital	17	Sink Pad		Composite Material	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Stronnly Presumed Similar to	No Asbestos Detected	66758	BA3413/12	9506/18	12/05/2018	WHS
#REF!	RAA	South Tyrone Hospital	17	Sink Pad		Composite Material	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Stronnly Presumed Similar to	No Asbestos Detected	66759	BA3413/12	9506/18	12/05/2018	WHS
#REF!	RAA	South Tyrone Hospital	17	Sink Pad		Composite Material	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Stronnly Presumed Similar to	No Asbestos Detected	66760	BA3413/12	9506/1a	12/05/2018	WHS
#REF!	RAA	South Tyrone Hospital	17	Fire Proof Panel	Above suspended ceiling	Insulating Board	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66761	BA3413/13	9506/18	12/05/2018	WHS
#REF!	RAA	South Tyrone Hospital	17	Fire Proof Panel		Insulating Board	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Stronnly Presumed Similar to	No Asbestos Detected	66764	BA3413/13	9506/18	12/05/2018	WHS
#REF!	RAA	South Tyrone Hospital	17	Fire Proof Panel		Insulating Board	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66765	BA3413/13	9506/1a	12/05/2018	WHS
#REF!	RAA	South Tyrone Hospital	17	Fire Proof Panel		Insulating Board	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66767	BA3413/13	9506/18	12/05/2018	WHS
#REF!	RAA	South Tyrone Hospital	17	Fire Proof Panel		Insulating Board	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Stronnly Presumed Similar to	No Asbestos Detected	66768	BA3413/13	9506/18	12/05/2018	WHS
#REF!	RAA	South Tyrone Hospital	17	Fire Proof Panel	Above suspended ceiling	Insulating Board	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66770	BA3413/13	9506/18	12/05/2018	WHS
#REF!	RAA	South Tyrone Hospital	17	Fire Proof Panel		Insulating Board	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Stronnly Presumed Similar to	No Asbestos Detected	66771	BA3413/13	9506/18	12/05/2018	WHS
#REF!	RAA	South Tyrone Hospital	17	Fire Proof Panel		Insulating Board	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Stronnly Presumed Similar to	No Asbestos Detected	66772	BA3413/13	9506/18	12/05/2018	WHS
#REF!	RAA	South Tyrone Hospital	17	Fire Proof Panel	Above suspended ceiling	Insulating Board	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Stronnly Presumed Similar to	No Asbestos Detected	66775	BA3413/13	9506/1a	12/05/2018	WHS
#REF!	RAA	South Tyrone Hospital	17	Fire Proof Panel		Insulating Board	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Stronnly Presumed Similar to	No Asbestos Detected	66776	BA3413/13	9506/18	12/05/2018	WHS
#REF!	RAA	South Tyrone Hospital	17	Fire Proof Panel	Above suspended ceiling	Insulating Board	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Stronnly Presumed Similar to	No Asbestos Detected	66778	BA3413/13	9506/18	12/05/2018	WHS
#REF!	RAA	South Tyrone Hospital	17	Fire Proof Panel	Above suspended ceiling	Insulating Board	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Stronnly Presumed Similar to	No Asbestos Detected	66780	BA3413/13	9506/1a	12/05/2018	WHS
#REF!	RAA	South Tyrone Hospital	17	Floor Tiles		Composite Material	Chrysotile	Composite Materials	Medium	Apply Caution when Maintaining	Re-inspection	HSG227	Unchecked	Very Low Risk	4	14/12/2023	Identified	Very Low Risk	66784	BA3413/14	9302.22	14/12/2022	WHS
#REF!	RAA	South Tyrone Hospital	17	Floor Tiles		Composite Material	Chrysotile	Composite Materials	Medium	Apply Caution when Maintaining	Re-inspection	HSG227	Unchecked	Very Low Risk	4	14/12/2023	Stronnly Presumed Similar to	Very Low Risk	66786	BA3413/14	9302.22	14/12/2022	WHS
#REF!	RAA	South Tyrone Hospital	17	Floor Tiles		Composite Material	Chrysotile	Composite Materials	Medium	Apply Caution when Maintaining	Re-inspection	HSG227	Unchecked	Very Low Risk	4	14/12/2023	Stronnly Presumed Similar to	Very Low Risk	66787	BA3413/14	9302.22	14/12/2022	WHS
#REF!	RAA	South Tyrone Hospital	17	Floor Tiles		Composite Material	Chrysotile	Composite Materials	Medium	Apply Caution when Maintaining	Re-inspection	HSG227	Unchecked	Very Low Risk	4	14/12/2023	Stronnly Presumed Similar to	Very Low Risk	66788	BA3413/14	9302.22	14/12/2022	WHS
#REF!	RAA	South Tyrone Hospital	17	Floor Tiles		Composite Material	Chrysotile	Composite Materials	Medium	Apply Caution when Maintaining	Re-inspection	HSG227	Unchecked	Very Low Risk	4	13/12/2023	Identified	Very Low Risk	66789	BA3413/14	9302.22	13/12/2022	WHS
#REF!	RAA	South Tyrone Hospital	17	Floor Tiles		Composite Material	Chrysotile	Composite Materials	Medium	Apply Caution when Maintaining	Re-inspection	HSG227	Unchecked	Very Low Risk	4	13/12/2023	Stronnly Presumed Similar to	Very Low Risk	66790	BA3413/14	9302.22	13/12/2022	WHS
#REF!	RAA	South Tyrone Hospital	17	Floor Tiles		Composite Material	Chrysotile	Composite Materials	Medium	Apply Caution when Maintaining	Re-inspection	HSG227	Unchecked	Very Low Risk	4	13/12/2023	Stronnly Presumed Similar to	Very Low Risk	66791	BA3413/14	9302.22	13/12/2022	WHS
#REF!	RAA	South Tyrone Hospital	17	Floor Tiles		Composite Material	Chrysotile	Composite Materials	Medium	Apply Caution when Maintaining	Re-inspection	HSG227	Unchecked	Very Low Risk	4	13/12/2023	Stronnly Presumed Similar to	Very Low Risk	66792	BA3413/14	9302.22	13/12/2022	WHS
#REF!	RAA	South Tyrone Hospital	17	Floor Tiles		Composite Material	Chrysotile	Composite Materials	Medium	Apply Caution when Maintaining	Re-inspection	HSG227	Unchecked	Very Low Risk	4	13/12/2023	Stronnly Presumed Similar to	Very Low Risk	66793	BA3413/14	9302.22	13/12/2022	WHS
#REF!	RAA	South Tyrone Hospital	17	Floor Tiles		Composite Material	Chrysotile	Composite Materials	Medium	Apply Caution when Maintaining	Re-inspection	HSG227	Unchecked	Very Low Risk	4	13/12/2023	Identified	Very Low Risk	66794	BA3413/14	9302.22	13/12/2022	WHS
#REF!	RAA	South Tyrone Hospital	17	Floor Tiles		Composite Material	Chrysotile	Composite Materials	Medium	Apply Caution when Maintaining	Re-inspection	HSG227	Unchecked	Very Low Risk	4	13/12/2023	Stronnly Presumed Similar to	Very Low Risk	66795	BA3413/14	9302.22	13/12/2022	WHS
#REF!	RAA	South Tyrone Hospital	17	Floor Tiles	Vinyl floor tiles	Composite Material	Chrysotile	Composite Materials	Medium	Apply Caution when Maintaining	Re-inspection	HSG227	Unchecked	Very Low Risk	4	13/12/2023	Identified	Very Low Risk	66796	BA6345	9302.22	13/12/2022	WHS
#REF!	RAA	South Tyrone Hospital	17	Wall Panels		Insulating Board	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66797	BA3413/15	9506/18	12/05/2018	WHS
#REF!	RAA	South Tyrone Hospital	17	Woven Asbestos Textile	Above suspended ceiling-Textile around ciswork	Textiles & Paper	Chrysotile	Enclosed Woven Textile	Low	Further investigation Required	Re-inspection	HSG227	Unchecked	Low Risk	5	13/12/2023	Identified	Low Risk	66799	BA3413/16	9302.22	13/12/2022	WHS
#REF!	RAA	South Tyrone Hospital	17	Lino Flooring	Under carpet	Composite Material	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66800	BA3413/17	9506/18	12/05/2018	WHS
#REF!	RAA	South Tyrone Hospital	17	Lino Flooring	Under carpet	Composite Material	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Stronnly Presumed Similar to	No Asbestos Detected	66801	BA3413/17	9506/18	12/05/2018	WHS
#REF!	RAA	South Tyrone Hospital	17	Debris Material		Loose Asbestos	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66802	BA3413/18	9506/18	12/05/2018	WHS
#REF!	RAA	South Tyrone Hospital	17	Ceiling Tiles		Insulating Board	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66803	BA3413/19	9506/18	12/05/2018	WHS
#REF!	RAA	South Tyrone Hospital	17	Ceiling Tiles		Insulating Board	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Stronnly Presumed Similar to	No Asbestos Detected	66804	BA3413/19	9506/18	12/05/2018	WHS
#REF!	RAA	South Tyrone Hospital	17	Ceiling Tiles		Insulating Board	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Stronnly Presumed Similar to	No Asbestos Detected	66805	BA3413/19	9506/18	12/05/2018	WHS
#REF!	RAA	South Tyrone Hospital	17	Ceiling Tiles		Insulating Board	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Stronnly Presumed Similar to	No Asbestos Detected	66807	BA3413/19	9506/18	12/05/2018	WHS
#REF!	RAA	South Tyrone Hospital	17	Ceiling Tiles		Insulating Board	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Stronnly Presumed Similar to	No Asbestos Detected	66808	BA3413/19	9506/18	12/05/2018	WHS
#REF!	RAA	South Tyrone Hospital	17	Sink Pad		Composite Material	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66810	BA3413/20	9506/18	12/05/2018	WHS
#REF!	RAA	South Tyrone Hospital	17	Stair Nosing		Composite Material	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66812	BA3413/21	9506/18	12/05/2018	WHS
#REF!	RAA	South Tyrone Hospital	17	Stair Nosing		Composite Material	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Stronnly Presumed Similar to	No Asbestos Detected	66813	BA3413/21	9506/18	12/05/2018	WHS
#REF!	RAA	South Tyrone Hospital	17	Stair Nosing		Composite Material	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Stronnly Presumed Similar to	No Asbestos Detected	66815	BA3413/21	9506/18	12/05/2018	WHS
#REF!	RAA	South Tyrone Hospital	17	Stair Nosing	Black Stair Nosings	Composite Material	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66816	BA3413/22	9506/18	12/05/2018	WHS
#REF!	RAA	South Tyrone Hospital	17	Stair Nosing	Black Stair Nosings	Composite Material	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Stronnly Presumed Similar to	No Asbestos Detected	66817	BA3413/22	9506/18	12/05/2018	WHS
#REF!	RAA	South Tyrone Hospital	17	Anti Vibration Pads	Above suspended ceiling	Textiles & Paper	Chrysotile	Unsealed	Low	Apply Caution when Maintaining	Re-inspection	HSG227	Unchecked	Medium Risk	7	13/12/2023	Identified	Medium Risk	66819	BA3413/23	9302.22	13/12/2022	WHS
#REF!	RAA	South Tyrone Hospital	17	Anti Vibration Pads		Textiles & Paper	Chrysotile	Unsealed	Low	Apply Caution when Maintaining	Re-inspection	HSG227	Unchecked	Medium Risk	7	13/12/2023	Stronnly Presumed Similar to	Medium Risk	66820	BA3413/23	9302.22	13/12/2022	WHS
#REF!	RAA	South Tyrone Hospital	17	Anti Vibration Pads	Above suspended ceiling	Textiles & Paper	Chrysotile	Unsealed	Low	Apply Caution when Maintaining	Re-inspection	HSG227	Unchecked	Medium Risk	7	13/12/2023	Stronnly Presumed Similar to	Medium Risk	66821	BA3413/23	9302.22	13/12/2022	WHS
#REF!	RAA	South Tyrone Hospital	17	Anti Vibration Pads	Above suspended ceiling	Textiles & Paper	Chrysotile	Unsealed	Low	Apply Caution when Maintaining	Re-inspection	HSG227	Unchecked	Medium Risk	7	13/12/2023	Stronnly Presumed Similar to	Medium Risk	66822	BA3413/23	9302.22	13/12/2022	WHS
#REF!	RAA	South Tyrone Hospital	17	Anti Vibration Pads	Above suspended ceiling	Textiles & Paper	Chrysotile	Unsealed	Low	Apply Caution when Maintaining	Re-inspection	HSG227	Unchecked	Medium Risk	7	13/12/2023	Stronnly Presumed Similar to	Medium Risk	66823	BA3413/23	9302.22	13/12/2022	WHS
#REF!	RAA	South Tyrone Hospital	17	Fire Break Panel	Above suspended ceiling	Insulating Board	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66824	BA3413/24	9506/18	12/05/2018	WHS
#REF!	RAA	South Tyrone Hospital	17	Wall Panels		Insulating Board	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66825	BA3413/25	9506/1a	12/05/2018	WHS
#REF!	RAA	South Tyrone Hospital	17	Wall Panels		Insulating Board	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66826	BA3413/25	9506/18	12/05/2018	WHS

#REF!	RAA	South Tyrone Hospital	17	Wall Panels		Insulating Board	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66828	BA3413/25	9506/18	12/05/2018	WHS	
#REF!	RAA	South Tyrone Hospital	17	Wall Panels		Insulating Board	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66829	BA3413/25	9506/18	12/05/2018	WHS	
#REF!	RAA	South Tyrone Hospital	17	Wall Panels		Insulating Board	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66831	BA3413/25	9506/18	12/05/2018	WHS	
#REF!	RAA	South Tyrone Hospital	17	Wall Panels		Insulating Board	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66832	BA3413/25	9506/18	12/05/2018	WHS	
#REF!	RAA	South Tyrone Hospital	17	Packing	Wall	Thermal Insulation	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66834	BA3413/26	9506/18	12/05/2018	WHS	
#REF!	RAA	South Tyrone Hospital	17	Gaskets	Old Calorifier	Textiles & Paper	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66835	BA3413/27	9506/18	12/05/2018	WHS	
#REF!	RAA	South Tyrone Hospital	17	Pipe Lagging		Thermal Insulation	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66836	BA3413/28	9506/18	12/05/2018	WHS	
#REF!	RAA	South Tyrone Hospital	17	Fanlight Panel	Above Plastic Door	Insulating Board	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66837	BA3413/29	9506/18	12/05/2018	WHS	
#REF!	RAA	South Tyrone Hospital	17	Gaskets	Soil Pipes	Textiles & Paper	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66838	BA3413 Issue 01	9506/18	12/05/2018	WHS	
#REF!	RAA	South Tyrone Hospital	17	Insulating Board Below Window	Behind Window Freeze	Insulating Board	NO ASBESTOS	Conseaked Asbestos Insulation Board	Medium	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Presumed	Asbestos Removed	66839		9506/18	12/05/2018	WHS	
#REF!	RAA	South Tyrone Hospital	17	Insulating Board Below Window		Insulating Board	NO ASBESTOS	Conseaked Asbestos Insulation Board	Medium	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Presumed	Asbestos Removed	66840		9506/18	12/05/2018	WHS	
#REF!	RAA	South Tyrone Hospital	17	Bitumen Felt		Composite Material	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66841	BA3413/31	9506/18	12/05/2018	WHS	
#REF!	RAA	South Tyrone Hospital	17	Bitumen Felt	At Front Door	Composite Material	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66842	BA3413/31	9506/18	12/05/2018	WHS	
#REF!	RAA	South Tyrone Hospital	01	Pipe Insulation	Duct	Thermal Insulation	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66843	BA3447/01	9506/18	11/12/2018	WHS	
#REF!	RAA	South Tyrone Hospital	01	Pipe Insulation	Duct	Thermal Insulation	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66844	BA3447/01	9506/18	11/12/2018	WHS	
#REF!	RAA	South Tyrone Hospital	01	Pipe Insulation	Duct	Thermal Insulation	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66845	BA3447/01	9506/18	11/12/2018	WHS	
#REF!	RAA	South Tyrone Hospital	01	Pipe Insulation		Thermal Insulation	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66846	BA3447/01	9506/18	11/12/2018	WHS	
#REF!	RAA	South Tyrone Hospital	01	Pipe Insulation		Thermal Insulation	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66847	BA3447/01	9506/18	11/12/2018	WHS	
#REF!	RAA	South Tyrone Hospital	01	Pipe Insulation		Thermal Insulation	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66848	BA3447/01	9506/18	11/12/2018	WHS	
#REF!	RAA	South Tyrone Hospital	01	Pipe Insulation		Thermal Insulation	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66849	BA3447/01	9506/18	11/12/2018	WHS	
#REF!	RAA	South Tyrone Hospital	01	Pipe Insulation	Duct	Thermal Insulation	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66850	BA3447/01	9506/18	11/12/2018	WHS	
#REF!	RAA	South Tyrone Hospital	01	Pipe Insulation	Duct	Thermal Insulation	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66851	BA3447/01	9506/18	11/12/2018	WHS	
#REF!	RAA	South Tyrone Hospital	01	Pipe Insulation	Duct	Thermal Insulation	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66852	BA3447/01	9506/18	11/12/2018	WHS	
#REF!	RAA	South Tyrone Hospital	01	Fuse Flash Guards	Duct	Textiles & Paper	Presumed Asbestos	Enclosed Fuse Flash Guards	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Medium Risk	8	15/12/2023	Presumed	Medium Risk	66855		9506/18	15/12/2022	WHS	
#REF!	RAA	South Tyrone Hospital	01	Fuse Flash Guards	Duct	Textiles & Paper	Presumed Asbestos	Enclosed Fuse Flash Guards	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Medium Risk	8	15/12/2023	Presumed	Medium Risk	66856		9506/18	15/12/2022	WHS	
#REF!	RAA	South Tyrone Hospital	01	Fuse Flash Guards	Duct	Textiles & Paper	Presumed Asbestos	Enclosed Fuse Flash Guards	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Medium Risk	8	15/12/2023	Presumed	Medium Risk	66858		9506/18	15/12/2022	WHS	
#REF!	RAA	South Tyrone Hospital	01	Fuse Flash Guards		Textiles & Paper	Presumed Asbestos	Enclosed Fuse Flash Guards	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Medium Risk	8	15/12/2023	Presumed	Medium Risk	66860		9506/18	15/12/2022	WHS	
#REF!	RAA	South Tyrone Hospital	01	Fuse Flash Guards	Duct	Textiles & Paper	Presumed Asbestos	Enclosed Fuse Flash Guards	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Medium Risk	8	15/12/2023	Presumed	Medium Risk	66861		9506/18	15/12/2022	WHS	
#REF!	RAA	South Tyrone Hospital	01	Fuse Flash Guards	Duct	Textiles & Paper	Presumed Asbestos	Enclosed Fuse Flash Guards	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Medium Risk	8	15/12/2023	Presumed	Medium Risk	66862		9506/18	15/12/2022	WHS	
#REF!	RAA	South Tyrone Hospital	01	Fuse Flash Guards	Duct	Textiles & Paper	Presumed Asbestos	Enclosed Fuse Flash Guards	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Medium Risk	8	15/12/2023	Presumed	Medium Risk	66864		9506/18	15/12/2022	WHS	
#REF!	RAA	South Tyrone Hospital	01	Floor Tiles		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	15/12/2023	Identified	Very Low Risk	66865	BA3447/02	9506/18	15/12/2022	WHS	
#REF!	RAA	South Tyrone Hospital	01	Floor Tiles	Vinyl floor tile	Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	15/12/2023	Identified	Very Low Risk	66867	BA9309	9506/18	15/12/2022	WHS	
#REF!	RAA	South Tyrone Hospital	01	Floor Tiles	Vinyl floor tile	Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	15/12/2023	Identified	Very Low Risk	66868	BA9309	9506/18	15/12/2022	WHS	
#REF!	RAA	South Tyrone Hospital	01	Floor Tiles	Vinyl floor tile	Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	15/12/2023	Identified	Very Low Risk	66869	BA9309	9506/18	15/12/2022	WHS	
#REF!	RAA	South Tyrone Hospital	01	Floor Tiles	Vinyl floor tile	Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	15/12/2023	Identified	Very Low Risk	66870	BA9309	9506/18	15/12/2022	WHS	
#REF!	RAA	South Tyrone Hospital	01	NO ASBESTOS	Vinyl floor tile	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Re-inspection	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66871	BA9309	9811/19	11/12/2018	WHS	
#REF!	RAA	South Tyrone Hospital	01	Floor Tiles	Vinyl floor tile	Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	15/12/2022	Identified	Very Low Risk	66872	BA9309	9506/18	15/12/2022	WHS	
#REF!	RAA	South Tyrone Hospital	01	Floor Tiles	Vinyl floor tile	Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	15/12/2023	Identified	Very Low Risk	66873	BA9309	9506/18	15/12/2022	WHS	
#REF!	RAA	South Tyrone Hospital	01	Floor Tiles	Vinyl floor tile	Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	15/12/2023	Identified	Very Low Risk	66874	BA9309	9506/18	15/12/2022	WHS	
#REF!	RAA	South Tyrone Hospital	01	Floor Tiles	Vinyl floor tile	Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	15/12/2023	Identified	Very Low Risk	66875	BA9309	9506/18	15/12/2022	WHS	
#REF!	RAA	South Tyrone Hospital	01	Floor Tiles	Vinyl floor tile	Composite Material	Chrysotile	Composite Materials	Medium	Remove	Re-inspection	HSG227	Unchecked	Very Low Risk	4	15/12/2023	Identified	Very Low Risk	66876	BA9309	9506/18	15/12/2022	WHS	
#REF!	RAA	South Tyrone Hospital	01	Floor Tiles		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	15/12/2023	Identified	Very Low Risk	66877	BA3447/02	9506/18	15/12/2022	WHS	
#REF!	RAA	South Tyrone Hospital	01	Floor Tiles	Vinyl floor tile	Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	15/12/2023	Identified	Very Low Risk	66878	BA9309	9506/18	15/12/2022	WHS	
#REF!	RAA	South Tyrone Hospital	01	Floor Tiles	Vinyl floor tile	Composite Material	Chrysotile	Composite Materials	Medium	Remove	Re-inspection	HSG227	Unchecked	Very Low Risk	4	15/12/2023	Identified	Very Low Risk	66879	BA9309	9506/18	15/12/2022	WHS	
#REF!	RAA	South Tyrone Hospital	01	Floor Tiles	Vinyl floor tile	Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	15/12/2023	Identified	Very Low Risk	66880	BA9309	9506/18	15/12/2022	WHS	
#REF!	RAA	South Tyrone Hospital	01	Floor Tiles	Vinyl floor tile	Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	15/12/2023	Identified	Very Low Risk	66881	BA9309	9506/18	15/12/2022	WHS	
#REF!	RAA	South Tyrone Hospital	01	Floor Tiles	Vinyl floor tile	Composite Material	Chrysotile	Composite Materials	Low	Apply Caution when Maintainino	Re-inspection	HSG227	Unchecked	Very Low Risk	3	15/12/2023	Identified	Very Low Risk	66882	BA9309	9506/18	15/12/2022	WHS	
#REF!	RAA	South Tyrone Hospital	01	Floor Tiles	Vinyl floor tile	Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	15/12/2023	Identified	Very Low Risk	66883	BA9309	9506/18	15/12/2022	WHS	
#REF!	RAA	South Tyrone Hospital	01	Floor Tiles	Vinyl floor tile	Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	15/12/2023	Identified	Very Low Risk	66884	BA9309	9506/18	14/12/2022	WHS	
#REF!	RAA	South Tyrone Hospital	01	Floor Tiles		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	15/12/2023	Stronnly Presumed Similar to	Very Low Risk	66885	BA3447/02	9506/18	15/12/2022	WHS	
#REF!	RAA	South Tyrone Hospital	01	Floor Tiles	Vinyl floor tile	Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	15/12/2023	Stronnly Presumed Similar to	Very Low Risk	66886	BA9309	9506/18	15/12/2022	WHS	
#REF!	RAA	South Tyrone Hospital	01	Sink Pad		Composite Material	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66887	BA3447/03	9506/18	11/12/2018	WHS	
#REF!	RAA	South Tyrone Hospital	01	Sink Pad		Composite Material	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66888	BA3447/03	9506/18	11/12/2018	WHS	
#REF!	RAA	South Tyrone Hospital	01	Sink Pad		Composite Material	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66889	BA3447/03	9506/18	11/12/2018	WHS	
#REF!	RAA	South Tyrone Hospital	01	Sink Pad		Composite Material	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66890	BA3447/03	9506/18	11/12/2018	WHS	
#REF!	RAA	South Tyrone Hospital	01	Sink Pad		Composite Material	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66891	BA3447/03	9506/18	11/12/2018	WHS	
#REF!	RAA	South Tyrone Hospital	01	Stair Nosing	Stair nosing	Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	15/12/2023	Identified	Very Low Risk	66893	BA9309	9506/18	15/12/2022	WHS	
#REF!	RAA	South Tyrone Hospital	01	Stair Nosing	Stair nosing	Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	15/12/2023	Identified	Very Low Risk	66894	BA9309	9506/18	15/12/2022	WHS	
#REF!	RAA	South Tyrone Hospital	01	Stair Nosing		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	15/12/2023	Stronnly Presumed Similar to	Very Low Risk	66896	BA3447/04	9506/18	15/12/2022	WHS	
#REF!	RAA	South Tyrone Hospital	01	Stair Nosing	Stair nosing	Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	15/12/2023	Identified	Very Low Risk	66897	BA9309	9506/18	15/12/2022	WHS	
#REF!	RAA	South Tyrone Hospital	01	Sink Pad		Composite Material	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66898	BA3447/05	9506/18	11/12/2018	WHS	
#REF!	RAA	South Tyrone Hospital	01	General Debris		General Debris	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66899	BA3447/06	9506/18	11/12/2018	WHS	
#REF!	RAA	South Tyrone Hospital	07	Fuse Flash Guards		Textiles & Paper	NO ASBESTOS	Enclosed Fuse Flash Guards	Medium	Apply caution when maintaining and affix ID labels	Re-inspection	HSG227	Unchecked	NO ASBESTOS	0	06/08/2016	Presumed	No Asbestos Detected	66900		9811/19	04/12/2019	WHS	
#REF!	RAA	South Tyrone Hospital	07	Sink Pad		Composite Material	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66901	BA3395/01	9506/18	20/11/2018	WHS	
#REF!	RAA	South Tyrone Hospital	07	Damp Proof Course	Walls	Composite Material	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66903	BA3395/02	9506/18	20/11/2018	WHS	
#REF!	RAA	South Tyrone Hospital	07	Bitumen Felt	Roof	Composite Material	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66904	BA3395/03	9506/18	20/11/2018	WHS	
#REF!	RAA	South Tyrone Hospital	10	General Debris	Floor	General Debris	NO ASBESTOS			No further action required (No Asbestos Detected)	Original Survey Data	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66905	BA3442/01				
#REF!	RAA	South Tyrone Hospital	10	Pipe Lagging		Thermal Insulation	NO ASBESTOS			No further action required (No Asbestos Detected)	Original Survey Data	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66906	BA3442/02				
#REF!	RAA	South Tyrone Hospital	10	Pipe Lagging		Thermal Insulation	NO ASBESTOS			No further action required (No Asbestos Detected)	Original Survey Data	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66907	BA3442/02				
#REF!	RAA	South Tyrone Hospital	10	Pipe Lagging		Thermal Insulation	NO ASBESTOS			No further action required (No Asbestos Detected)	Original Survey Data	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66908	BA3442/02				
#REF!	RAA	South Tyrone Hospital	10	Fuse Flash Guards		Textiles & Paper	NO ASBESTOS	Enclosed Fuse Flash Guards	Medium	No further action required (Asbestos removed)	Re-inspection	HSG227	Unchecked	NO ASBESTOS	0		Presumed	Asbestos Removed	66909			06/08/2015		
#REF!	RAA	South Tyrone Hospital	10	Sink Pad		Composite Material	NO ASBESTOS			No further action required (No Asbestos Detected)	Original Survey Data	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66910	BA3442/03				
#REF!	RAA	South Tyrone Hospital	10	Blanket Material	Wrap around Pumps	Textiles & Paper	NO ASBESTOS			No further action required (No Asbestos Detected)	Original Survey Data	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66911	BA3442/04				
#REF!	RAA	South Tyrone Hospital	10	Damp Proof Course		Composite Material	NO ASBESTOS			No further action required (No Asbestos Detected)	Original Survey Data	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66912	BA3442/05				
#REF!	RAA	South Tyrone Hospital	21	Bitumen Felt		Composite Material	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66913	BA3414/01	9506/18	21/11/2018	WHS	
#REF!	RAA	South Tyrone Hospital	21	Sink Pad		Composite Material	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66914	BA3414/02	9506/18	21/11/2018	WHS	
#REF!	RAA	South Tyrone Hospital	21	Sink Pad		Composite Material	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66915	BA3414/02	9506/18	21/11/2018	WHS	
#REF!	RAA	South Tyrone Hospital	21	Stair Nosing		Composite Material	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66916	BA3414/03	9506/18	21/11/2018	WHS	
#REF!	RAA	South Tyrone Hospital	21	Floor Tiles	Cream VFT	Composite Material	Chrysotile	Composite Materials	Low	Apply Caution when Maintaining	Re-inspection	HSG227	Unchecked	Very Low Risk	3	15/12/2023	Identified	Very Low Risk	66917	BA3414/04	9506/18	15/12/2022	WHS	
#REF!	RAA	South Tyrone Hospital	21	Floor Tiles	Brown VFT	Composite Material	Chrysotile	Composite Materials	Low	Apply Caution when Maintaining	Re-inspection	HSG227	Unchecked	Very Low Risk	3	15/12/2023	Identified	Very Low Risk	66918	BA3414/05	9506/18	15/12/2022	WHS	
#REF!	RAA	South Tyrone Hospital	21	Fuse Flash Guards		Textiles & Paper	NO ASBESTOS	Enclosed Fuse Flash Guards	Medium	No further action required (No Asbestos Detected)	Re-inspection	HSG227	Unchecked	NO ASBESTOS	0	04/03/2021	Presumed	No Asbestos Detected	66919		9811/19	26/11/2019	WHS	
#REF!	RAA	South Tyrone Hospital	21	Undercloak to Roof Veroe		Cement Products	Presumed Asbestos	Composite Materials	Low	Apply Caution when Maintainino	Re-inspection	HSG227	Unchecked	Low Risk	5	15/12/2023	Stronnly Presumed	Low Risk	66920		9506/18	15/12/2022	WHS	
#REF!	RJA	Willowbank Resource Centre	01	Sink Pad		Composite Material	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66921	BA3448/01	9327/17	18/04/2018	WH Stephens	
#REF!	RJA	Willowbank Resource Centre	01	Sink Pad		Composite Material	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66922	BA3448/01	9327/17	18/04/2018	WH Stephens	
#REF!	RJA	Willowbank Resource Centre	01	Lino Flooring		Composite Material	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66923	BA3448/02	9327/17	18/04/2018	WH Stephens	
#REF!	RJA	Willowbank Resource Centre	01	Soffit Boards	Front Porch	Insulating Board	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66924	BA3448/03	9327/17	18/04/2018	WH Stephens	
#REF!	RJA	Willowbank Resource Centre	01	Textured Coatings	Wall	Decorative Coatings	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66925	BA3448/04	9327/17	18/04/2018	WH Stephens	
#REF!	RJA	Willowbank Resource Centre	01	Bitumen Felt	Roof	Composite Material	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66926	BA3448/05	9327/17	18/04/2018	WH Stephens	
#REF!	RJA	Willowbank Resource Centre	01	Floor Tiles		Composite Material	Chrysotile	Composite Materials	Low	Apply Caution when Maintaining	Re-inspection	HSG227	Unchecked	Very Low Risk	3	27/03/2021	Identified	Very Low Risk	66927	BA3448/06	9327/17	20/01/2020	WH Stephens	

#REF!	RJA	Willowbank Resource Centre	01	Fuse Flash Guards		Textiles & Paper	Presumed Asbestos	Enclosed Fuse Flash Guards	Medium	Apply caution when maintaining and affix ID labels	Re-inspection	HSG227	Unchecked	Medium Risk	8	27/03/2021	Presumed	Medium Risk	66928		9811/19	20/01/2020	WH Stephens
#REF!	RJA	Willowbank Resource Centre	01	Insulation Blocks	Internal to Boiler	Insulating Board	Presumed Asbestos	Enclosed Asbestos Insulation Board	Medium	Apply caution when maintaining and affix ID labels	Re-inspection	HSG227	Unchecked	Medium Risk	8	27/03/2021	Presumed	Medium Risk	66929		9811/19	20/01/2020	WH Stephens
#REF!	RJA	Willowbank Resource Centre	01	Wall Panels		Insulating Board	Chrysotile	Unsealed Asbestos Insulation Board	Low	Apply caution when maintaining and affix ID labels	Re-inspection	HSG227	Unchecked	Low Risk	6	27/03/2021	Identified	Low Risk	66930	BA3448/07	9811/19	20/01/2020	WH Stephens
#REF!	RAA	South Tyrone Hospital	03	Stair Nosing		Composite Material	NO ASBESTOS			No further action required (No Asbestos Detected)	Original Survey Data	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66931	BA3399/01			
#REF!	RAA	South Tyrone Hospital	03	Sink Pad		Composite Material	NO ASBESTOS			No further action required (No Asbestos Detected)	Original Survey Data	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66932	BA3399/02			
#REF!	RAA	South Tyrone Hospital	03	Bitumen Felt		Composite Material	NO ASBESTOS			No further action required (No Asbestos Detected)	Original Survey Data	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66933	BA3399/03			
#REF!	RAA	South Tyrone Hospital	06	Soffit Boards		Insulating Board	NO ASBESTOS			No further action required (No Asbestos Detected)	Original Survey Data	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66940	BA3398/01			
#REF!	RAA	South Tyrone Hospital	06	Bitumen Felt		Composite Material	NO ASBESTOS			No further action required (No Asbestos Detected)	Original Survey Data	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66941	BA3398/02			
#REF!	RAA	South Tyrone Hospital	18	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	15/12/2023	Identified	Very Low Risk	66942	BA3412/01	9302.2	15/12/2022	WHS
#REF!	RAA	South Tyrone Hospital	18	Sink Pad		Composite Material	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66943	BA3412/02	9506/18	22/11/2018	WHS
#REF!	RAA	South Tyrone Hospital	18	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	15/12/2023	Identified	Very Low Risk	66944	BA3412/03	9302.2	15/12/2022	WHS
#REF!	RAA	South Tyrone Hospital	18	Soffit Boards		Cement Products	Chrysotile	Cement Sheets	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	4	15/12/2023	Identified	Very Low Risk	66945	BA3412/04	9302.2	15/12/2022	WHS
#REF!	RAA	South Tyrone Hospital	18	Bitumen Felt	Roof	Composite Material	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66947	BA3412/05	9506/18	22/11/2018	WHS
#REF!	RAA	South Tyrone Hospital	20	Bitumen Felt		Composite Material	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66949	BA3411/01	9506/18	20/11/2018	WHS
#REF!	RAA	South Tyrone Hospital	20	Pipe Insulation		Thermal Insulation	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66951	BA3411/02	9506/18	20/11/2018	WHS
#REF!	RAA	South Tyrone Hospital	20	Fanlight Panel	Above Door	Insulating Board	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66952	BA3411/03	9506/1a	20/11/2018	WHS
#REF!	RAA	South Tyrone Hospital	20	Fuse Flash Guards		Textiles & Paper	NO ASBESTOS	Enclosed Fuse Flash Guards	Medium	No further action required (No Asbestos Detected)	Re-inspection	HSG227	Unchecked	NO ASBESTOS	0	26/11/2019	Presumed	No Asbestos Detected	66954		9506/18	20/11/2018	WHS
#REF!	RAA	South Tyrone Hospital	20	Undercloak to Roof Verge		Cement Products	Presumed Asbestos	Cement Sheets	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Low Risk	6	15/12/2023	Stronnlv Presumed	Low Risk	66955		9302.2	15/12/2022	WHS
#REF!	RAA	South Tyrone Hospital	28	Ceiling Board		Insulating Board	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66956	BA3397/01	9506/18	21/11/2018	WHS
#REF!	RAA	South Tyrone Hospital	28	Ceiling Board		Insulating Board	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66957	BA3397/01	9506/18	21/11/2018	WHS
#REF!	RAA	South Tyrone Hospital	28	Gaskets		Textiles & Paper	NO ASBESTOS	Composite Materials	Low	No further action required (Asbestos removed)	Re-inspection	HSG227	Unchecked	NO ASBESTOS	0	04/03/2021	Identified	Asbestos Removed	66958	BA3397/02	9811/19	26/11/2019	WHS
#REF!	RAA	South Tyrone Hospital	28	Gaskets		Textiles & Paper	Chrysotile	Composite Materials	Low	Apply caution when maintaining and affix ID labels	Re-inspection	HSG227	Unchecked	Very Low Risk	4	15/12/2023	Strongly Presumed Similar to	Very Low Risk	66959	BA3397/02	9302.2	15/12/2022	WHS
#REF!	RAA	South Tyrone Hospital	28	Fuse Flash Guards		Textiles & Paper	NO ASBESTOS	Enclosed Fuse Flash Guards	Medium	No further action required (No Asbestos Detected)	Re-inspection	HSG227	Unchecked	NO ASBESTOS	0	04/03/2021	Presumed	No Asbestos Detected	66960		9811/19	26/11/2019	WHS
#REF!	RAA	South Tyrone Hospital	28	Damp Proof Course		Composite Material	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66961	BA3397/03	9506/18	21/11/2018	WHS
#REF!	RAA	South Tyrone Hospital	28	Fanlight Panel		Insulating Board	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66962	BA3397/04	9506/18	21/11/2018	WHS
#REF!	RSA	Dungannon Clinic	01	Floor Tiles	Raised olatform to left	Composite Material	Chrvsotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Verv Low Risk	3	03/04/2021	Identified	Verv Low Risk	66963	BA3443/01	9811/19	19/11/2019	WHS
#REF!	RSA	Dungannon Clinic	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	28/11/2019	Strongly Presumed Similar to	Asbestos Removed	66964	BA3443/01	9506/18	11/05/2018	WHS
#REF!	RSA	Dungannon Clinic	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	28/11/2019	Identified	Asbestos Removed	66965	BA3443/01	9506/18	11/05/2018	WHS
#REF!	RSA	Dungannon Clinic	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (Asbestos removed)	ACM Removed	HSG227	Unchecked	NO ASBESTOS	0	28/11/2019	Strongly Presumed Similar to	Asbestos Removed	66966	BA3443/01	9506/1a	11/05/2018	WHS
#REF!	RSA	Dungannon Clinic	01	Lino Flooring		Composite Material	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66967	BA3443/02	9506/18	11/05/2018	WHS
#REF!	RSA	Dungannon Clinic	01	Lino Flooring		Composite Material	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66968	BA3443/02	9506/18	11/05/2018	WHS
#REF!	RSA	Dungannon Clinic	01	Lino Flooring		Composite Material	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66969	BA3443/02	9506/1a	11/05/2018	WHS
#REF!	RSA	Dungannon Clinic	01	Lino Flooring		Composite Material	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66970	BA3443/02	9506/18	11/05/2018	WHS
#REF!	RSA	Dungannon Clinic	01	Lino Flooring	Under Carpet	Composite Material	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66971	BA3443/02	9506/18	11/05/2018	WHS
#REF!	RSA	Dungannon Clinic	01	Lino Flooring		Composite Material	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66972	BA3443/02	9506/1a	11/05/2018	WHS
#REF!	RSA	Dungannon Clinic	01	Lino Flooring		Composite Material	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66973	BA3443/02	9506/18	11/05/2018	WHS
#REF!	RSA	Dungannon Clinic	01	Lino Flooring		Composite Material	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66974	BA3443/02	9506/18	11/05/2018	WHS
#REF!	RSA	Dungannon Clinic	01	Ceiling Tiles		Insulating Board	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66975	BA3443/03	9506/1a	11/05/2018	WHS
#REF!	RSA	Dungannon Clinic	01	Ceiling Tiles		Insulating Board	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66976	BA3443/03	9506/18	11/05/2018	WHS
#REF!	RSA	Dungannon Clinic	01	Ceiling Tiles		Insulating Board	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66977	BA3443/03	9506/18	11/05/2018	WHS
#REF!	RSA	Dungannon Clinic	01	Ceiling Tiles		Insulating Board	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66978	BA3443/03	9506/1a	11/05/2018	WHS
#REF!	RSA	Dungannon Clinic	01	Ceiling Tiles		Insulating Board	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66979	BA3443/03	9506/18	11/05/2018	WHS
#REF!	RSA	Dungannon Clinic	01	Ceiling Tiles		Insulating Board	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66980	BA3443/03	9506/18	11/05/2018	WHS
#REF!	RSA	Dungannon Clinic	01	Ceiling Tiles		Insulating Board	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66981	BA3443/03	9506/1a	11/05/2018	WHS
#REF!	RSA	Dungannon Clinic	01	Ceiling Tiles		Insulating Board	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66982	BA3443/03	9506/18	11/05/2018	WHS
#REF!	RSA	Dungannon Clinic	01	Ceiling Tiles		Insulating Board	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66983	BA3443/03	9506/18	11/05/2018	WHS
#REF!	RSA	Dungannon Clinic	01	Lino Flooring		Composite Material	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66984	BA3443/04	9506/1a	11/05/2018	WHS
#REF!	RSA	Dungannon Clinic	01	Fanlight Panel		Insulating Board	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66985	BA3443/05	9506/18	11/05/2018	WHS
#REF!	RSA	Dungannon Clinic	01	Fire Break Panel	Ceiling Void	Insulating Board	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66986	BA3443/05	9506/18	11/05/2018	WHS
#REF!	RSA	Dungannon Clinic	01	Fanlight Panel		Insulating Board	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66987	BA3443/05	9506/1a	11/05/2018	WHS
#REF!	RSA	Dungannon Clinic	01	Fire Break Panel	Ceiling Void	Insulating Board	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66988	BA3443/05	9506/18	11/05/2018	WHS
#REF!	RSA	Dungannon Clinic	01	Sink Pad		Composite Material	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66989	BA3443/06	9506/18	11/05/2018	WHS
#REF!	RSA	Dungannon Clinic	01	Sink Pad		Composite Material	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	66990	BA3443/06	9506/1a	11/05/2018	WHS
#REF!	RSA	Dungannon Clinic	01	Stair Nosing		Composite Material	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66991	BA3443/07	9506/18	11/05/2018	WHS
#REF!	RSA	Dungannon Clinic	01	Fuse Flash Guards		Textiles & Paper	Presumed Asbestos	Enclosed Fuse Flash Guards	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Medium Risk	8	03/04/2021	Presumed	Medium Risk	66992		9811/19	19/11/2019	WHS
#REF!	RSA	Dungannon Clinic	01	Sink Pad		Composite Material	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	66993	BA3443/08	9506/18	11/05/2018	WHS
#REF!	RSA	Dungannon Clinic	01	Stair Nosing		Composite Material	Chrysotile	Composite Material	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	03/04/2021	Identified	Very Low Risk	66994	BA3443/09	9811/19	19/11/2019	WHS
#REF!	RSA	Dungannon Clinic	01	Stair Nosing		Composite Material	Chrysotile	Composite Material	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	03/04/2021	Strongly Presumed Similar to	Very Low Risk	66995	BA3443/09	9811/19	19/11/2019	WHS
#REF!	RSA	Dungannon Clinic	01	Stair Nosing		Composite Material	Chrysotile	Composite Material	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	03/04/2021	Strongly Presumed Similar to	Very Low Risk	66996	BA3443/09	9811/19	19/11/2019	WHS
#REF!	RSA	Dungannon Clinic	01	Fuse Flash Guards		Textiles & Paper	Presumed Asbestos	Enclosed Fuse Flash Guards	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Medium Risk	8	03/04/2021	Presumed	Medium Risk	66997		9811/19	19/11/2019	WHS
#REF!	RSA	Dungannon Clinic	01	Fuse Flash Guards		Textiles & Paper	Presumed Asbestos	Enclosed Fuse Flash Guards	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Medium Risk	8	03/04/2021	Presumed	Medium Risk	66998		9811/19	19/11/2019	WHS
#REF!	RSA	Dungannon Clinic	01	Sink Pad		Composite Material	Chrysotile	Composite Material	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	03/04/2021	Identified	Very Low Risk	66999	BA3443/10	9506/18	19/11/2019	WHS
#REF!	RSA	Dungannon Clinic	01	Ceiling Tiles		Insulating Board	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67000	BA3443/11	9506/18	11/05/2018	WHS
#REF!	RSA	Dungannon Clinic	01	Ceiling Tiles		Insulating Board	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67001	BA3443/11	9506/18	11/05/2018	WHS
#REF!	RSA	Dungannon Clinic	01	Ceiling Tiles		Insulating Board	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67002	BA3443/11	9506/18	11/05/2018	WHS
#REF!	RSA	Dungannon Clinic	01	Ceiling Tiles		Insulating Board	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67003	BA3443/11	9506/18	11/05/2018	WHS
#REF!	RSA	Dungannon Clinic	01	Ceiling Tiles		Insulating Board	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67004	BA3443/11	9506/18	11/05/2018	WHS
#REF!	RSA	Dungannon Clinic	01	Ceiling Tiles		Insulating Board	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67005	BA3443/11	9506/18	11/05/2018	WHS
#REF!	RSA	Dungannon Clinic	01	Ceiling Tiles		Insulating Board	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67006	BA3443/11	9506/18	11/05/2018	WHS
#REF!	RSA	Dungannon Clinic	01	Ceiling Tiles		Insulating Board	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67007	BA3443/11	9506/18	11/05/2018	WHS
#REF!	RSA	Dungannon Clinic	01	Ceiling Tiles		Insulating Board	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67008	BA3443/11	9506/18	11/05/2018	WHS
#REF!	RSA	Dungannon Clinic	01	Ceiling Tiles		Insulating Board	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67009	BA3443/11	9506/18	11/05/2018	WHS
#REF!	RSA	Dungannon Clinic	01	Ceiling Tiles		Insulating Board	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67010	BA3443/11	9506/18	11/05/2018	WHS
#REF!	RSA	Dungannon Clinic	01	Ceiling Tiles		Insulating Board	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67011	BA3443/11	9506/18	11/05/2018	WHS
#REF!	RSA	Dungannon Clinic	01	Ceiling Tiles		Insulating Board	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67012	BA3443/11	9506/18	11/05/2018	WHS
#REF!	RSA	Dungannon Clinic	01	Ceiling Tiles		Insulating Board	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67013	BA3443/11	9506/18	11/05/2018	WHS
#REF!	RSA	Dungannon Clinic	01	Ceiling Tiles		Insulating Board	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67014	BA3443/11	9506/18	11/05/2018	WHS
#REF!	RSA	Dungannon Clinic	01	Ceiling Tiles		Insulating Board	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67015	BA3443/11	9506/18	11/05/2018	WHS
#REF!	RSA	Dungannon Clinic	01	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Material	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	03/04/2021	Identified	Very Low Risk	67016	BA3443/12	9811/19	19/11/2019	WHS
#REF!	RSA	Dungannon Clinic	01	Floor Tile and Bitumen Adhesive		Composite Material	Chrvsotile	Composite Material	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Verv Low Risk	3	03/04/2021	Stronnlv Presumed Similar to	Very Low Risk	67017	BA3443/12	9811/19	19/11/2019	WHS

#REF!	RSA	Dungannon Clinic	01	Floor Tile and Bitumen Adhesive	under carpet	Composite Material	Chrysotile	Composite Material	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	03/04/2021	Identified	Very Low Risk	67018	BA3443/13	[illegible]	19/11/2019	WHS
#REF!	RSA	Dungannon Clinic	01	Toilet Cistern		Composite Material	Amosite	Composite Material	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	4	03/04/2021	Identified	Very Low Risk	67019	BA3443/14	[illegible]	19/11/2019	WHS
#REF!	RSA	Dungannon Clinic	01	Vessel	Internal insulation to Boiler	Thermal Insulation	Presumed Asbestos	Concealed	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Medium Risk	9	03/04/2021	Presumed	Medium Risk	67020		[illegible]	19/11/2019	WHS
#REF!	RSA	Dungannon Clinic	01	Pipe Lagging		Thermal Insulation	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67021	BA3443/15	9509/18	11/05/2018	WHS
#REF!	RSA	Dungannon Clinic	01	Blanket Material	Textile Wrap to Pumps	Textiles & Paper	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67022	BA3443/16	9509/18	11/05/2018	WHS
#REF!	RSA	Dungannon Clinic	01	Board	At Flue Extracts	Insulating Board	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67023	BA3443/17	9509/18	11/05/2018	WHS
#REF!	RSA	Dungannon Clinic	01	Bitumen Felt	Rear Flat Roof	Composite Material	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67024	BA3443/18	9509/18	11/05/2018	WHS
#REF!	RSA	Dungannon Clinic	01	Soffit Boards		Insulating Board	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67025	BA3443/19	9509/18	11/05/2018	WHS
#REF!	RSA	Dungannon Clinic	01	Damp Proof Course		Composite Material	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67026	BA3443/20	9509/18	11/05/2018	WHS
#REF!	RSA	Dungannon Clinic	01	Artificial Slate	Roof	Cement Products	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67027	BA3443/21	9509/18	11/05/2018	WHS
#REF!	RAA	South Tyrone Hospital	15	Bitumen Felt		Composite Material	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67028	BA3445/01	9509/18	22/11/2018	WHS
#REF!	RAA	South Tyrone Hospital	15	Lino Flooring		Composite Material	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67029	BA3445/02	9509/18	22/11/2018	WHS
#REF!	RAA	South Tyrone Hospital	15	Lino Flooring		Composite Material	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67030	BA3445/02	9509/18	22/11/2018	WHS
#REF!	RAA	South Tyrone Hospital	15	Lino Flooring		Composite Material	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67031	BA3445/02	9509/18	22/11/2018	WHS
#REF!	RAA	South Tyrone Hospital	15	Lino Flooring		Composite Material	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67032	BA3445/02	9509/18	22/11/2018	WHS
#REF!	RAA	South Tyrone Hospital	15	Lino Flooring	under carpet	Composite Material	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67033	BA3445/02	9509/18	22/11/2018	WHS
#REF!	RAA	South Tyrone Hospital	15	Toilet Cistern		Composite Material	Amosite	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	4	15/12/2023	Identified	Very Low Risk	67034	BA3445/03	[illegible]	15/12/2022	WHS
#REF!	RAA	South Tyrone Hospital	15	NO ASBESTOS	Brake shoes to lift plant	NO ASBESTOS	NO ASBESTOS			Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	NO ASBESTOS	0	26/11/2019	Identified	No Asbestos Detected	67035	BA9324	[illegible]	26/11/2018	WHS
#REF!	RAA	South Tyrone Hospital	15	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	15/12/2023	Identified	Very Low Risk	67036	BA3445/04	[illegible]	15/12/2022	WHS
#REF!	RAA	South Tyrone Hospital	15	Stair Nosino		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	15/12/2023	Identified	Very Low Risk	67037	BA3445/05	[illegible]	15/12/2022	WHS
#REF!	RAA	South Tyrone Hospital	15	Sink Pad		Composite Material	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67038	BA3445/06	9509/18	22/11/2018	WHS
#REF!	RAA	South Tyrone Hospital	15	Lino Flooring		Composite Material	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67039	BA3445/07	9509/18	22/11/2018	WHS
#REF!	RAA	South Tyrone Hospital	15	Bitumen Felt	Rear Flat Roof	Composite Material	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67040	BA3445/08	9509/18	22/11/2018	WHS
#REF!	RAA	South Tyrone Hospital	15	Artificial Slate	Roof	Cement Products	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67041	BA3445/09	9509/18	22/11/2018	WHS
#REF!	RAA	South Tyrone Hospital	15	Fuse Flash Guards		Textiles & Paper	NO ASBESTOS	Enclosed Fuse Flash Guards	Medium	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Presumed	Asbestos Removed	67042		9509/18	22/11/2018	WHS
#REF!	RAA	South Tyrone Hospital	19	Pipe Lagging		Thermal Insulation	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67043	BA3410/01	9509/18	20/11/2018	WHS
#REF!	RAA	South Tyrone Hospital	19	Pipe Lagging		Thermal Insulation	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67044	BA3410/01	9509/18	20/11/2018	WHS
#REF!	RAA	South Tyrone Hospital	19	Lino Flooring		Composite Material	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67045	BA3410/02	9509/18	20/11/2018	WHS
#REF!	RAA	South Tyrone Hospital	19	Textured Coatinos	Ceilino	Decorative Coatinos	Chrysotile	Textured Coatino	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	4	15/12/2023	Identified	Very Low Risk	67046	BA3410/03	[illegible]	15/12/2022	WHS
#REF!	RAA	South Tyrone Hospital	19	Floor Tiles	Under Lino	Composite Material	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67047	BA3410/04	9509/18	20/11/2018	WHS
#REF!	RAA	South Tyrone Hospital	19	Lino Flooring		Composite Material	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67048	BA3410/05	9509/18	20/11/2018	WHS
#REF!	RAA	South Tyrone Hospital	19	Soffit Boards		Insulating Board	Chrysotile	[illegible]	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Low Risk	5	15/12/2023	Identified	Low Risk	67049	BA3410/06	[illegible]	15/12/2022	WHS
#REF!	RAA	South Tyrone Hospital	19	Bitumen Felt	Flat Roof	Composite Material	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67050	BA3410/07	9509/18	20/11/2018	WHS
#REF!	RAA	South Tyrone Hospital	16	Lino Flooring	Under Carpet	Composite Material	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67051	BA3449/01	9509/18	12/05/2018	WHS
#REF!	RAA	South Tyrone Hospital	16	Lino Flooring	Under Carpet	Composite Material	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67052	BA3449/01	9509/18	12/05/2018	WHS
#REF!	RAA	South Tyrone Hospital	16	Textured Coatinos	Ceilino	Decorative Coatinos	Chrysotile	Textured Coatino	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	4	15/12/2023	Identified	Very Low Risk	67053	BA3449/02	[illegible]	15/12/2022	WHS
#REF!	RAA	South Tyrone Hospital	16	Textured Coatinos	Ceilino	Decorative Coatinos	Chrysotile	Textured Coatino	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	4	15/12/2023	Strongly Presumed Similar to	Low Risk	67054	BA3449/02	[illegible]	15/12/2022	WHS
#REF!	RAA	South Tyrone Hospital	16	Textured Coatinos	[illegible]	Decorative Coatinos	Chrysotile	Textured Coatino	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	4	15/12/2023	Identified	Very Low Risk	67055	BA9343	[illegible]	15/12/2022	WHS
#REF!	RAA	South Tyrone Hospital	16	Textured Coatinos	Textured coatino to practice manaber's office ceilino	Decorative Coatinos	Chrysotile	Textured Coatino	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	4	15/12/2023	Identified	Very Low Risk	67056	BA9343	9302.2	15/12/2022	WHS
#REF!	RAA	South Tyrone Hospital	16	Textured Coatinos	[illegible]	Decorative Coatinos	Chrysotile	Textured Coatino	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	4	15/12/2023	Identified	Very Low Risk	67057	BA9343	[illegible]	15/12/2022	WHS
#REF!	RAA	South Tyrone Hospital	16	Textured Coatinos	Textured coatino to reception ceilino	Decorative Coatinos	Chrysotile	Textured Coatino	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	4	15/12/2023	Identified	Very Low Risk	67058	BA9343	[illegible]	15/12/2022	WHS
#REF!	RAA	South Tyrone Hospital	16	Sink Pad		Composite Material	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67059	BA3449/03	9509/18	12/05/2018	WHS
#REF!	RAA	South Tyrone Hospital	16	Wall Panels		Insulating Board	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67060	BA3449/04	9509/18	12/05/2018	WHS
#REF!	RAA	South Tyrone Hospital	16	Wall Panels		Insulating Board	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67061	BA3449/04	9509/18	12/05/2018	WHS
#REF!	RAA	South Tyrone Hospital	16	Exterior Cladding	Red Wall Cladding	Cement Products	Chrysotile	Cement Sheets	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	4	15/12/2023	Identified	Very Low Risk	67062	BA3449/05	[illegible]	15/12/2022	WHS
#REF!	RAA	South Tyrone Hospital	16	Bitumen Felt	Roof	Composite Material	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67063	BA3449/06	9509/18	12/05/2018	WHS
#REF!	RAA	South Tyrone Hospital	16	Fuse Flash Guards		Textiles & Paper	Presumed Asbestos	Enclosed Fuse Flash Guards	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Medium Risk	8	15/12/2023	Presumed	Medium Risk	67064		[illegible]	15/12/2022	WHS
#REF!	RAA	South Tyrone Hospital	14	Stair Nosing		Composite Material	NO ASBESTOS	Composite Materials	Low	Apply Caution when Maintaining	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67065	BS132712	[illegible]	21/11/2018	WHS
#REF!	RAA	South Tyrone Hospital	14	Stair Nosing		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67066	BS132710	9509/18	21/11/2018	WHS
#REF!	RAA	South Tyrone Hospital	14	Stair Nosing		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67067	BA3444/01	9509/18	21/11/2018	WHS
#REF!	RAA	South Tyrone Hospital	14	Ceiling Board		Insulating Board	Chrysotile	[illegible]	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Low Risk	5	15/12/2023	Identified	Low Risk	67068	BA3444/02	[illegible]	15/12/2022	WHS
#REF!	RAA	South Tyrone Hospital	14	Ceilino Board		Insulating Board	Chrysotile	[illegible]	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Low Risk	5	15/12/2023	Stronoly Presumed Similar to	Low Risk	67069	BA3444/02	[illegible]	15/12/2022	WHS
#REF!	RAA	South Tyrone Hospital	14	Bitumen Felt		Composite Material	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67070	BA3444/03	9509/18	21/11/2018	WHS
#REF!	RAA	South Tyrone Hospital	11	Fuse Flash Guards		Textiles & Paper	NO ASBESTOS	Enclosed Fuse Flash Guards	Medium	No further action required (Asbestos removed)	Re-inspection	HSG227	Unchecked	NO ASBESTOS	0	05/08/2016	Presumed	Asbestos Removed	67071		9811/19	04/12/2019	WHS
#REF!	RAA	South Tyrone Hospital	11	Bitumen Felt	Roof	Composite Material	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67072	BA3446/01	9509/18	21/11/2018	WHS
#REF!	RAB	Longstone/Mullinure	07	Fire Break Panel	Above suspended ceiling	Insulating Board	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67073	BA3470/01	9509/18	11/07/2018	WHS
#REF!	RAB	Longstone/Mullinure	07	Fire Break Panel	Above suspended ceiling	Insulating Board	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67074	BA3470/01	9509/18	11/07/2018	WHS
#REF!	RAB	Longstone/Mullinure	07	Fire Break Panel	Above suspended ceiling	Insulating Board	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67075	BA3470/01	9509/18	11/07/2018	WHS
#REF!	RAB	Longstone/Mullinure	07	Fuse Flash Guards		Textiles & Paper	Presumed Asbestos	Enclosed Fuse Flash Guards	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Medium Risk	8	27/03/2021	Presumed	Medium Risk	67076		[illegible]	27/11/2019	WHS
#REF!	RAB	Longstone/Mullinure	07	fascia board	Front Porch Red Fascia	Cement Products	Amosite/Chrysotile	Cement Sheets	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Low Risk	5	27/03/2021	Identified	Very Low Risk	67077	BA3470/02	[illegible]	27/11/2019	WHS
#REF!	RAB	Longstone/Mullinure	07	Bitumen Felt	Roof	Composite Material	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67078	BA3470/03	9509/18	11/07/2018	WHS
#REF!	RAB	Longstone/Mullinure	07	fascia board	Rear Porch Fascia	Cement Products	Amosite/Chrysotile	Cement Sheets	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Low Risk	5	27/03/2021	Identified	Very Low Risk	67079	BA3470/04	[illegible]	27/11/2019	WHS
#REF!	RAB	Longstone/Mullinure	08	Fire Break Panel	Above suspended ceiling	Insulating Board	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67080	BA3471/01	9509/18	11/07/2018	WHS
#REF!	RAB	Longstone/Mullinure	08	Fire Break Panel	Above suspended ceiling	Insulating Board	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67081	BA3471/01	9509/18	11/07/2018	WHS
#REF!	RAB	Longstone/Mullinure	08	Fire Break Panel	Above suspended ceiling	Insulating Board	NO ASBESTOS			No further action required (No Asbestos Detected)	Review of Incident	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67082	BA3471/01	9509/18	11/07/2018	WHS
#REF!	RAB	Longstone/Mullinure	08	Fuse Flash Guards		Textiles & Paper	Presumed Asbestos	Enclosed Fuse Flash Guards	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Medium Risk	8	27/03/2021	Presumed	Medium Risk	67083		[illegible]	27/11/2019	WHS
#REF!	RAB	Longstone/Mullinure	08	Fuse Flash Guards		Textiles & Paper	Presumed Asbestos	Enclosed Fuse Flash Guards	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Medium Risk	8	27/03/2021	Presumed	Medium Risk	67084		[illegible]	27/11/2019	WHS
#REF!	RAB	Longstone/Mullinure	08	Fuse Flash Guards		Textiles & Paper	Presumed Asbestos	Enclosed Fuse Flash Guards	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Medium Risk	8	27/03/2021	Presumed	Medium Risk	67085		[illegible]	27/11/2019	WHS
#REF!	RAB	Longstone/Mullinure	08	Lino Flooring		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	27/03/2021	Identified	Very Low Risk	67086	BA3471/02	[illegible]	27/11/2019	WHS
#REF!	RAB	Longstone/Mullinure	08	Sink Pad		Composite Material	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67087	BA3471/03	9509/18	11/07/2018	WHS
#REF!	RAB	Longstone/Mullinure	08	fascia board	Front Porch Fascia	Cement Products	Amosite/Chrysotile	Cement Sheets	Low	Apply caution when maintaining and affix ID labels	Re-inspection	HSG227	Unchecked	Low Risk	5	27/03/2021	Identified	Very Low Risk	67088	BA3471/04	9811/19	27/11/2019	WHS
#REF!	RAB	Longstone/Mullinure	08	fascia board	Rear Fascia	Cement Products	Amosite/Chrysotile	Cement Sheets	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Low Risk	5	27/03/2021	Strongly Presumed Similar to	Very Low Risk	67089	BA3471/04	[illegible]	27/11/2019	WHS
#REF!	RAB	Longstone/Mullinure	08	Bitumen Felt	Roof	Composite Material	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67090	BA3471/05	9509/18	11/07/2018	WHS
#REF!	RAB	Longstone/Mullinure	08	Artificial Slate	RHS	Cement Products	Chrysotile	Cement Sheets	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	4	27/03/2021	Identified	Very Low Risk	67091	BA3471/06	[illegible]	27/11/2019	WHS
#REF!	RAB	Longstone/Mullinure	08	Artificial Slate	Shelter Roof	Cement Products	Chrysotile	Cement Sheets	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	4	27/03/2021	Stronoly Presumed Similar to	Very Low Risk	67092	BA3471/06	[illegible]	27/11/2019	WHS
#REF!	RAB	Longstone/Mullinure	08	Artificial Slate	Rear Roof	Cement Products	Chrysotile	Cement Sheets	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	4	27/03/2021	Strongly Presumed Similar to	Very Low Risk	67093	BA3471/06	[illegible]	27/11/2019	WHS
#REF!	QAA	Craigavon Hospital	19	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67147	BA3374/06	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	19	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67150	BA3374/07	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	17	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67152	BA3373/04	9509/18	13/11/2018	WHS
#REF!	QAA	Craigavon Hospital	17	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67153	BA3373/05	9509/18	13/11/2018	WHS
#REF!	QAA	Craigavon Hospital	18	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67155	BA3217/05	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	18	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67156	BA3217/04	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	16	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67167	BA3360/06	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	16	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67168	BA3360/06	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	16	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67169	BA3360/06	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	16	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67170	BA3360/06	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	16	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67171	BA3360/06	9724/17	05/09/2017	WHS

#REF!	QAA	Craigavon Hospital	16	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67172	BA3360/06	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	16	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67173	BA3360/06	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	16	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67175	BA3360/06	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	16	Sink Pad	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	Asbestos Removed	67176	BA3360/08	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	16	Sink Pad	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	Asbestos Removed	67178	BA3360/08	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	16	Sink Pad	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	24/07/2018	Strongly Presumed Similar to	Asbestos Removed	67179	BA3360/08	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	16	Sink Pad	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	Asbestos Removed	67180	BA3360/08	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	16	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67182	BA3360/09	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	16	Insulating Board	Insulating Board	NO ASBESTOS	Enclosed Spray or Lagging/Sealed AIB	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67184	BA3360/10	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	16	Sink Pad	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	Asbestos Removed	67186	BA3360/11	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	16	Cement Flat Sheet	Cement Products	NO ASBESTOS	Enclosed Spray or Lagging/Sealed AIB	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	Asbestos Removed	67187	BA3360/12	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	16	Cement Flat Sheet	Cement Products	NO ASBESTOS	Enclosed Spray or Lagging/Sealed AIB	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	Asbestos Removed	67188	BA3360/12	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	16	Cement Flat Sheet	Cement Products	NO ASBESTOS	Enclosed Spray or Lagging/Sealed AIB	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	Asbestos Removed	67189	BA3360/12	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	16	Cement Flat Sheet	Cement Products	NO ASBESTOS	Enclosed Spray or Lagging/Sealed AIB	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	Asbestos Removed	67191	BA3360/12	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	16	Cement Flat Sheet	Cement Products	NO ASBESTOS	Enclosed Spray or Lagging/Sealed AIB	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	Asbestos Removed	67192	BA3360/12	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	16	Cement Flat Sheet	Cement Products	NO ASBESTOS	Enclosed Spray or Lagging/Sealed AIB	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	Asbestos Removed	67193	BA3360/12	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	16	Cement Flat Sheet	Cement Products	NO ASBESTOS	Enclosed Spray or Lagging/Sealed AIB	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	Asbestos Removed	67195	BA3360/12	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	16	Cement Flat Sheet	Cement Products	Chrysotile	Enclosed Spray or Lagging/Sealed AIB	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	4	24/06/2023	Strongly Presumed Similar to	Very Low Risk	67196	BA3360/12	9724/17	24/06/2022	WHS
#REF!	QAA	Craigavon Hospital	16	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67198	BA3360/04	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	16	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67199	BA3360/04	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	16	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67200	BA3360/04	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	16	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67201	BA3360/04	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	16	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67202	BA3360/04	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	16	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67203	BA3360/04	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	16	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67204	BA3360/04	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	16	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67206	BA3360/04	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	16	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67207	BA3360/04	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	16	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67208	BA3360/04	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	16	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67209	BA3360/04	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	16	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67210	BA3360/04	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	16	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67211	BA3360/04	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	16	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67213	BA3360/04	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	16	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67214	BA3360/04	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	16	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67215	BA3360/04	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	16	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67217	BA3360/04	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	16	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67218	BA3360/04	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	16	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67219	BA3360/04	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	16	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67220	BA3360/04	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	16	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67221	BA3360/04	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	16	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67222	BA3360/04	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	16	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67223	BA3360/04	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	16	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67224	BA3360/04	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	16	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67225	BA3360/04	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	16	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67226	BA3360/04	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	16	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67227	BA3360/04	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	16	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67229	BA3360/04	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	16	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67230	BA3360/04	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	16	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67231	BA3360/04	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	16	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67232	BA3360/04	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	16	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67233	BA3360/05	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	16	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67234	BA3360/05	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	16	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67235	BA3360/05	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	16	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67236	BA3360/05	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	16	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67237	BA3360/05	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	16	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67238	BA3360/05	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	16	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67239	BA3360/05	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	16	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67240	BA3360/05	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	16	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67241	BA3360/05	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	16	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67242	BA3360/05	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	16	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67243	BA3360/05	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	16	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67245	BA3360/05	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	16	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67246	BA3360/05	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	16	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67247	BA3360/05	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	16	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67248	BA3360/05	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	16	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67249	BA3360/05	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	16	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67250	BA3360/05	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	16	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67252	BA3360/05	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	16	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67253	BA3360/05	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	16	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67254	BA3360/05	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	16	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67255	BA3360/05	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	16	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67256	BA3360/05	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	16	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67257	BA3360/05	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	16	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67258	BA3360/05	9724/17	05/09/2017	WHS

#REF!	QAC	Lurgan Hospital	01	Stair Nosing		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67260	BA3472/10	9506/18	11/08/2018	WHS
#REF!	QAC	Lurgan Hospital	01	Roofing Felts		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67270	BA3472/01	9506/18	11/08/2018	WHS
#REF!	QAC	Lurgan Hospital	01	Cement Products		Cement Products	NO ASBESTOS	Enclosed Spray or Lagging/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67271	BA3472/02	9506/18	11/08/2018	WHS
#REF!	QAC	Lurgan Hospital	01	Fire Break Panel		Insulating Board	NO ASBESTOS	Encapsulated Spray or Lagging/Unsealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67272	BA3472/03	9506/18	11/08/2018	WHS
#REF!	QAC	Lurgan Hospital	01	Fire Break Panel		Insulating Board	NO ASBESTOS	Encapsulated Spray or Lagging/Unsealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67273	BA3472/03	9506/18	11/08/2018	WHS
#REF!	QAC	Lurgan Hospital	01	Board	West Wing	Insulating Board	NO ASBESTOS	Encapsulated Spray or Lagging/Unsealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67274	BA3472/04	9506/18	11/08/2018	WHS
#REF!	QAC	Lurgan Hospital	01	General Debris		General Debris	NO ASBESTOS	Encapsulated Spray or Lagging/Unsealed AIB	High	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67275	BA3472/05	9506/18	11/08/2018	WHS
#REF!	QAC	Lurgan Hospital	01	General Debris		General Debris	NO ASBESTOS	Encapsulated Spray or Lagging/Unsealed AIB	High	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67276	BA3472/06	9506/18	11/08/2018	WHS
#REF!	QAC	Lurgan Hospital	01	Bitumen Felt		Composite Material	Presumed Asbestos	Composite Materials	None	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	4	29/07/2021	Presumed	Very Low Risk	67277		9811/18	22/07/2020	WHS
#REF!	QAC	Lurgan Hospital	01	Fire Break Panel		Insulating Board	NO ASBESTOS	Enclosed Spray or Lagging/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67278	BA3472/07	9506/18	11/08/2018	WHS
#REF!	QAC	Lurgan Hospital	01	Fire Lining Board		Cement Products	Chrysotile	Enclosed Spray or	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	4	29/07/2021	Identified	Very Low Risk	67279	BA3472/08	9811/18	22/07/2020	WHS
#REF!	QAC	Lurgan Hospital	01	Roofing Felts		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67280	BA3472/09	9506/18	11/08/2018	WHS
#REF!	QAC	Lurgan Hospital	01	Roofing Felts		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67281	BA3472/09	9506/18	11/08/2018	WHS
#REF!	QAC	Lurgan Hospital	01	Cowl		Cement Products	Presumed Asbestos	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Low Risk	5	29/07/2021	Presumed	Low Risk	67282		9811/18	22/07/2020	WHS
#REF!	QAC	Lurgan Hospital	01	Brake Pads	Lift Plant Room	Textiles & Paper	Presumed Asbestos	Unsealed	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	High Risk	10	29/07/2021	Presumed	High Risk	67283		9811/18	22/07/2020	WHS
#REF!	QAC	Lurgan Hospital	01	Stair Nosing		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67284	BA3472/10	9506/18	11/08/2018	WHS
#REF!	QAC	Lurgan Hospital	01	Lino Flooring		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67285	BA3472/11	9506/18	11/08/2018	WHS
#REF!	QAC	Lurgan Hospital	01	Lino Flooring		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67286	BA3472/11	9506/18	11/08/2018	WHS
#REF!	QAC	Lurgan Hospital	01	Lino Flooring		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67287	BA3472/11	9506/18	11/08/2018	WHS
#REF!	QAC	Lurgan Hospital	01	Lino Flooring		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67288	BA3472/11	9506/18	11/08/2018	WHS
#REF!	QAC	Lurgan Hospital	01	Lino Flooring		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67289	BA3472/11	9506/18	11/08/2018	WHS
#REF!	QAC	Lurgan Hospital	01	Lino Flooring		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67290	BA3472/11	9506/18	11/08/2018	WHS
#REF!	QAC	Lurgan Hospital	01	Lino Flooring		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67291	BA3472/12	9506/18	11/08/2018	WHS
#REF!	QAC	Lurgan Hospital	01	Lino Flooring		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67292	BA3472/12	9506/18	11/08/2018	WHS
#REF!	QAC	Lurgan Hospital	01	Lino Flooring		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67293	BA3472/12	9506/18	11/08/2018	WHS
#REF!	QAC	Lurgan Hospital	01	Lino Flooring		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67294	BA3472/12	9506/18	11/08/2018	WHS
#REF!	QAC	Lurgan Hospital	01	Lino Flooring		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67295	BA3472/12	9506/18	11/08/2018	WHS
#REF!	QAC	Lurgan Hospital	01	Lino Flooring		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67296	BA3472/12	9506/18	11/08/2018	WHS
#REF!	QAC	Lurgan Hospital	01	Lino Flooring		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67297	BA3472/12	9506/18	11/08/2018	WHS
#REF!	QAC	Lurgan Hospital	01	Lino Flooring		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67298	BA3472/12	9506/18	11/08/2018	WHS
#REF!	QAC	Lurgan Hospital	01	Lino Flooring		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67299	BA3472/12	9506/18	11/08/2018	WHS
#REF!	QAC	Lurgan Hospital	01	Lino Flooring		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67300	BA3472/12	9506/18	11/08/2018	WHS
#REF!	QAC	Lurgan Hospital	01	Lino Flooring		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67301	BA3472/12	9506/18	11/08/2018	WHS
#REF!	QAC	Lurgan Hospital	01	Lino Flooring		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67302	BA3472/13	9506/18	11/08/2018	WHS
#REF!	QAC	Lurgan Hospital	01	Lino Flooring		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67303	BA3472/13	9506/18	11/08/2018	WHS
#REF!	QAC	Lurgan Hospital	01	Lino Flooring		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67304	BA3472/13	9506/18	11/08/2018	WHS
#REF!	QAC	Lurgan Hospital	01	Lino Flooring		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67305	BA3472/13	9506/18	11/08/2018	WHS
#REF!	QAC	Lurgan Hospital	01	Lino Flooring		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67306	BA3472/13	9506/18	11/08/2018	WHS
#REF!	QAC	Lurgan Hospital	01	Lino Flooring		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67307	BA3472/13	9506/18	11/08/2018	WHS
#REF!	QAC	Lurgan Hospital	01	Lino Flooring		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67308	BA3472/13	9506/18	11/08/2018	WHS
#REF!	QAC	Lurgan Hospital	01	Lino Flooring		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67309	BA3472/13	9506/18	11/08/2018	WHS
#REF!	QAC	Lurgan Hospital	01	Lino Flooring		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67310	BA3472/13	9506/18	11/08/2018	WHS
#REF!	QAC	Lurgan Hospital	01	Lino Flooring		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67311	BA3472/13	9506/18	11/08/2018	WHS
#REF!	QAC	Lurgan Hospital	01	Lino Flooring		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67312	BA3472/13	9506/18	11/08/2018	WHS
#REF!	QAC	Lurgan Hospital	01	Lino Flooring		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67313	BA3472/13	9506/18	11/08/2018	WHS
#REF!	QAC	Lurgan Hospital	01	Lino Flooring		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67314	BA3472/13	9506/18	11/08/2018	WHS
#REF!	QAC	Lurgan Hospital	01	Lino Flooring		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67315	BA3472/13	9506/18	11/08/2018	WHS
#REF!	QAC	Lurgan Hospital	01	Lino Flooring		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67316	BA3472/13	9506/18	11/08/2018	WHS
#REF!	QAC	Lurgan Hospital	01	Lino Flooring		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67317	BA3472/13	9506/18	11/08/2018	WHS
#REF!	QAC	Lurgan Hospital	01	Lino Flooring		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67318	BA3472/13	9506/18	11/08/2018	WHS
#REF!	QAC	Lurgan Hospital	01	Lino Flooring		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67319	BA3472/14	9506/18	11/08/2018	WHS
#REF!	QAC	Lurgan Hospital	01	Lino Flooring		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67320	BA3472/14	9506/18	11/08/2018	WHS
#REF!	QAC	Lurgan Hospital	01	Lino Flooring		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67321	BA3472/14	9506/18	11/08/2018	WHS
#REF!	QAC	Lurgan Hospital	01	Lino Flooring		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67322	BA3472/14	9506/18	11/08/2018	WHS
#REF!	QAC	Lurgan Hospital	01	Fire Break Panel		Insulating Board	Amosite/Chrysotile	Enclosed Spray or	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Low Risk	6	29/07/2021	Identified	Low Risk	67323	BA3472/15	9811/18	22/07/2020	WHS
#REF!	QAC	Lurgan Hospital	01	Fire Break Panel		Insulating Board	Amosite/Chrysotile	Enclosed Spray or	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Low Risk	6	29/07/2021	Strongly Presumed Similar to	Low Risk	67324	BA3472/15	9811/18	22/07/2020	WHS
#REF!	QAC	Lurgan Hospital	01	Fire Break Panel		Insulating Board	Amosite/Chrysotile	Enclosed Spray or	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Low Risk	6	29/07/2021	Strongly Presumed Similar to	Low Risk	67325	BA3472/15	9811/18	22/07/2020	WHS
#REF!	QAC	Lurgan Hospital	01	Lino Flooring		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67326	BA3472/16	9506/18	11/08/2018	WHS
#REF!	QAC	Lurgan Hospital	01	Lino Flooring		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67327	BA3472/16	9506/18	11/08/2018	WHS
#REF!	QAC	Lurgan Hospital	01	Lino Flooring		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67328	BA3472/16	9506/18	11/08/2018	WHS
#REF!	QAC	Lurgan Hospital	01	Lino Flooring		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67329	BA3472/16	9506/18	11/08/2018	WHS
#REF!	QAC	Lurgan Hospital	01	Textured Coatings	QAC01C074	Decorative Coatings	NO ASBESTOS	Encapsulated Spray or Lagging/Unsealed ACM	High	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67330	BA3472/17	9506/18	11/08/2018	WHS
#REF!	QAC	Lurgan Hospital	01	Insulating Debris	QAC01C074	General Debris	NO ASBESTOS	Encapsulated Spray or Lagging/Unsealed AIB	Loose asbestos debris or residue	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67331	BA3472/18	9506/18	11/08/2018	WHS
#REF!	QAC	Lurgan Hospital	01	Roofing Felts	QAC01C074	Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67332	BA3472/19	9506/18	11/08/2018	WHS
#REF!	QAC	Lurgan Hospital	01	Stair Nosing		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67333	BA3472/20	9506/18	11/08/2018	WHS
#REF!	QAC	Lurgan Hospital	01	Pipe Insulation		Thermal Insulation	NO ASBESTOS	Unsealed Spray or Lagging	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67334	BA3472/21	9506/18	11/08/2018	WHS
#REF!	QAC	Lurgan Hospital	01	Boarding		Cement Products	Chrysotile	Enclosed Spray or	None	Conduct annual routine inspections	Corrective previous data entry error	HSG227	Unchecked	Very Low Risk	3	29/07/2021	Identified	Very Low Risk	67335	BA3472/22	9811/18	22/07/2020	WHS
#REF!	QAC	Lurgan Hospital	01	Ceiling Panelling		Insulating Board	NO ASBESTOS	Encapsulated Spray or Lagging/Unsealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67336	BA3472/23	9506/18	11/08/2018	WHS
#REF!	QAC	Lurgan Hospital	01	Ceiling Panelling		Insulating Board	NO ASBESTOS	Encapsulated Spray or Lagging/Unsealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67337	BA3472/23	9506/18	11/08/2018	WHS
#REF!	QAC	Lurgan Hospital	01	Ceiling Panelling		Insulating Board	NO ASBESTOS	Encapsulated Spray or Lagging/Unsealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67338	BA3472/23	9506/18	11/08/2018	WHS
#REF!	QAC	Lurgan Hospital	01	Ceiling Panelling		Insulating Board	NO ASBESTOS	Encapsulated Spray or Lagging/Unsealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67339	BA3472/23	9506/18	11/08/2018	WHS
#REF!	QAC	Lurgan Hospital	01	Bitumen Felt		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67340	BA3472/24	9506/18	11/08/2018	WHS
#REF!	QAC	Lurgan Hospital	01	Bitumen Felt		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67341	BA3472/24	9506/18	11/08/2018	WHS
#REF!	QAC	Lurgan Hospital	01	Door Beading		Insulating Board	NO ASBESTOS	Encapsulated Spray or Lagging/Unsealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67342	BA3472/25	9506/18	11/08/2018	WHS
#REF!	QAC	Lurgan Hospital	01	Board		Insulating Board	Presumed Asbestos	Encapsulated Spray or Lagging/Unsealed AIB	Medium	Conduct further investigation prior to relevant ma	Re-inspection	HSG227	Unchecked	Medium Risk	9	29/07/2021	Presumed	Medium Risk	67343		9811/18	22/07/2020	WHS
#REF!	QAC	Lurgan Hospital	01	Down Pipe		Cement Products	Chrysotile	Enclosed Spray or	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	4	29/07/2021	Identified	Very Low Risk	67344	BA3472/26	9811/18	22/07/2020	WHS
#REF!	QAC	Lurgan Hospital	01	Bitumen Felt		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67345	BA3472/27	9506/18	11/08/2018	WHS

#REF!	QAC	Lurgan Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67346	BA3472/28	9506/18	11/08/2018	WHS
#REF!	QAC	Lurgan Hospital	01	Floor Screed		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67347	BA3472/29	9506/18	11/08/2018	WHS
#REF!	QAC	Lurgan Hospital	01	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67348	BA3472/30	9506/18	11/08/2018	WHS
#REF!	QAC	Lurgan Hospital	01	Fire Break Panel		Insulating Board	NO ASBESTOS	Encapsulated Spray or Laqoino/Unsealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67349	BA3472/31	9506/18	11/08/2018	WHS
#REF!	QAC	Lurgan Hospital	01	Fire Break Panel		Insulating Board	NO ASBESTOS	Encapsulated Spray or Laqoino/Unsealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67350	BA3472/31	9506/18	11/08/2018	WHS
#REF!	QAC	Lurgan Hospital	01	Fire Break Panel		Insulating Board	NO ASBESTOS	Encapsulated Spray or Laqoino/Unsealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67351	BA3472/31	9506/18	11/08/2018	WHS
#REF!	QAC	Lurgan Hospital	01	Fire Break Panel		Insulating Board	NO ASBESTOS	Encapsulated Spray or Laqoino/Unsealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67352	BA3472/31	9506/18	11/08/2018	WHS
#REF!	QAC	Lurgan Hospital	01	Fire Break Panel		Insulating Board	NO ASBESTOS	Encapsulated Spray or Laqoino/Unsealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67353	BA3472/31	9506/18	11/08/2018	WHS
#REF!	QAC	Lurgan Hospital	01	Fire Break Panel		Insulating Board	NO ASBESTOS	Encapsulated Spray or Laqoino/Unsealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67354	BA3472/31	9506/18	11/08/2018	WHS
#REF!	QAC	Lurgan Hospital	01		Flat Roof of Lift Plant		NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	67355		9506/18	11/08/2018	WHS
#REF!	QAC	Lurgan Hospital	01							No action required	Review of Incident	HSG227	Unchecked	Cannot Calculate	0				67356		9506/18	11/08/2018	WHS
#REF!	QAC	Lurgan Hospital	01							No action required	Review of Incident	HSG227	Unchecked	Cannot Calculate	0				67357		9506/18	11/08/2018	WHS
#REF!	QAC	Lurgan Hospital	01							No action required	Re-inspection	HSG227	Unchecked	Cannot Calculate	0				67358		9514/18	22/07/2020	WHS
#REF!	QAC	Lurgan Hospital	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	67359		9506/18	11/08/2018	WHS
#REF!	QAC	Lurgan Hospital	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	67360		9506/18	11/08/2018	WHS
#REF!	QAC	Lurgan Hospital	01							No action required	Review of Incident	HSG227	Unchecked	Cannot Calculate	0	20/11/2019			67361		9506/18	11/08/2018	WHS
#REF!	QAC	Lurgan Hospital	01							Further Investion Reauired	Review – No Change	HSG227	Unchecked	Cannot Calculate	0	20/11/2019			67362		9506/18	11/08/2018	WHS
#REF!	QAC	Lurgan Hospital	01				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	67363		9506/18	11/08/2018	WHS
#REF!	QAC	Lurgan Hospital	01	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67364	BA3472/32	9506/18	11/08/2018	WHS
#REF!	QAC	Lurgan Hospital	01	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67365	BA3472/32	9506/18	11/08/2018	WHS
#REF!	QAC	Lurgan Hospital	01	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67366	BA3472/32	9506/18	11/08/2018	WHS
#REF!	QAC	Lurgan Hospital	01	Duct Access Panels		Insulating Board	NO ASBESTOS	Encapsulated Spray or Laqoino/Unsealed AIB	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67367	BA3472/33	9506/18	11/08/2018	WHS
#REF!	QAC	Lurgan Hospital	01	Duct Access Panels		Insulating Board	NO ASBESTOS	Encapsulated Spray or Laqoino/Unsealed AIB	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67368	BA3472/33	9506/18	11/08/2018	WHS
#REF!	QAC	Lurgan Hospital	01	Duct Access Panels		Insulating Board	NO ASBESTOS	Encapsulated Spray or Laqoino/Unsealed AIB	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67369	BA3472/33	9506/18	11/08/2018	WHS
#REF!	QAC	Lurgan Hospital	01	Stair Nosing		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67370	BA3472/34	9506/18	11/08/2018	WHS
#REF!	QAC	Lurgan Hospital	01	Stair Nosing		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67371	BA3472/35	9506/18	11/08/2018	WHS
#REF!	QAC	Lurgan Hospital	01	Ceiling Panel		Insulating Board	NO ASBESTOS	Enclosed Spray or Laqoino/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67372	BA3472/36	9506/18	11/08/2018	WHS
#REF!	QAC	Lurgan Hospital	01	Ceiling Panel		Insulating Board	NO ASBESTOS	Enclosed Spray or Laqoino/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67373	BA3472/36	9506/18	11/08/2018	WHS
#REF!	QAC	Lurgan Hospital	01	Ceiling Panel		Insulating Board	NO ASBESTOS	Enclosed Spray or Laqoino/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67374	BA3472/36	9506/18	11/08/2018	WHS
#REF!	QAC	Lurgan Hospital	01	Roofing Felts		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67375	BA3472/37	9506/18	11/08/2018	WHS
#REF!	QAC	Lurgan Hospital	01	Roofing Felts		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67376	BA3472/38	9506/18	11/08/2018	WHS
#REF!	QAC	Lurgan Hospital	01	Roofing Felts		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67377	BA3472/38	9506/18	11/08/2018	WHS
#REF!	QAC	Lurgan Hospital	01	Roofing Felts		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67378	BA3472/38	9506/18	11/08/2018	WHS
#REF!	QAC	Lurgan Hospital	01	Roofing Felts		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67379	BA3472/38	9506/18	11/08/2018	WHS
#REF!	QAC	Lurgan Hospital	01	Roofing Felts		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67380	BA3472/38	9506/18	11/08/2018	WHS
#REF!	QAC	Lurgan Hospital	01	Roofing Felts		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67381	BA3472/38	9506/18	11/08/2018	WHS
#REF!	QAC	Lurgan Hospital	01	Roofing Felts		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67382	BA3472/38	9506/18	11/08/2018	WHS
#REF!	QAC	Lurgan Hospital	01	Roofing material		Cement Products	NO ASBESTOS	Enclosed Spray or Laqoino/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67383	BA3472/39	9506/18	11/08/2018	WHS
#REF!	QAC	Lurgan Hospital	01	Roof Slate		Cement Products	Chrysotile	Enclosed Spray or	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	4	29/07/2021	Identified	Very Low Risk	67384	BA3472/40	9514/18	22/07/2020	WHS
#REF!	QAC	Lurgan Hospital	01	Profiled Roof Sheeting		Cement Products	Chrysotile	Enclosed Spray or	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	4	29/07/2021	Identified	Very Low Risk	67385	BA3472/41	9514/18	22/07/2020	WHS
#REF!	QAC	Lurgan Hospital	01	Fire Break Panel		Insulating Board	NO ASBESTOS	Encapsulated Spray or Laqoino/Unsealed AIB	Medium	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67386	BA3472/44	9506/18	11/08/2018	WHS
#REF!	QAC	Lurgan Hospital	01	Ceiling Board		Insulating Board	NO ASBESTOS	Enclosed Spray or Laqoino/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67387	BA3472/45	9506/18	11/08/2018	WHS
#REF!	QAC	Lurgan Hospital	01	Duct Access Panels		Insulating Board	NO ASBESTOS	Encapsulated Spray or Laqoino/Unsealed AIB	Areas of damage or deterioration	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67388	BA3472/46	9506/18	11/08/2018	WHS
#REF!	QAC	Lurgan Hospital	01	Duct Access Panels		Insulating Board	NO ASBESTOS	Encapsulated Spray or Laqoino/Unsealed AIB	Areas of damage or deterioration	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67389	BA3472/46	9506/18	11/08/2018	WHS
#REF!	QAC	Lurgan Hospital	01	Duct Access Panels		Insulating Board	NO ASBESTOS	Encapsulated Spray or Laqoino/Unsealed AIB	Areas of damage or deterioration	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67390	BA3472/46	9506/18	11/08/2018	WHS
#REF!	QAC	Lurgan Hospital	01	Duct Access Panels		Insulating Board	NO ASBESTOS	Encapsulated Spray or Laqoino/Unsealed AIB	Areas of damage or deterioration	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67391	BA3472/46	9506/18	11/08/2018	WHS
#REF!	QAC	Lurgan Hospital	01	Duct Access Panels		Insulating Board	NO ASBESTOS	Encapsulated Spray or Laqoino/Unsealed AIB	Areas of damage or deterioration	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67392	BA3472/46	9506/18	11/08/2018	WHS
#REF!	QAC	Lurgan Hospital	01	Duct Access Panels		Insulating Board	NO ASBESTOS	Encapsulated Spray or Laqoino/Unsealed AIB	Areas of damage or deterioration	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67393	BA3472/46	9506/18	11/08/2018	WHS
#REF!	QAC	Lurgan Hospital	01	Duct Access Panels		Insulating Board	NO ASBESTOS	Encapsulated Spray or Laqoino/Unsealed AIB	Areas of damage or deterioration	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67394	BA3472/46	9506/18	11/08/2018	WHS
#REF!	QAC	Lurgan Hospital	01	Duct Access Panels		Insulating Board	NO ASBESTOS	Encapsulated Spray or Laqoino/Unsealed AIB	Areas of damage or deterioration	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67395	BA3472/46	9506/18	11/08/2018	WHS
#REF!	QAC	Lurgan Hospital	01	Duct Access Panels		Insulating Board	NO ASBESTOS	Encapsulated Spray or Laqoino/Unsealed AIB	Areas of damage or deterioration	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67396	BA3472/46	9506/18	11/08/2018	WHS
#REF!	QAC	Lurgan Hospital	01	Duct Access Panels		Insulating Board	NO ASBESTOS	Encapsulated Spray or Laqoino/Unsealed AIB	Areas of damage or deterioration	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67397	BA3472/46	9506/18	11/08/2018	WHS
#REF!	QAC	Lurgan Hospital	01	Duct Access Panels		Insulating Board	NO ASBESTOS	Encapsulated Spray or Laqoino/Unsealed AIB	Areas of damage or deterioration	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67398	BA3472/46	9506/18	11/08/2018	WHS
#REF!	QAC	Lurgan Hospital	01	Duct Access Panels		Insulating Board	NO ASBESTOS	Encapsulated Spray or Laqoino/Unsealed AIB	Areas of damage or deterioration	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67399	BA3472/46	9506/18	11/08/2018	WHS
#REF!	QAC	Lurgan Hospital	01	Infill Panel	Board to Wall behind Key Storage	Insulating Board	NO ASBESTOS	Enclosed Spray or Laqoino/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67400	BA3472/47	9506/18	11/08/2018	WHS
#REF!	QAC	Lurgan Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67401	BA3472/48	9506/18	11/08/2018	WHS
#REF!	QAC	Lurgan Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67402	BA3472/49	9506/18	11/08/2018	WHS
#REF!	QAC	Lurgan Hospital	01	Sink Pad		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	29/07/2021	Identified	Very Low Risk	67403	BA3472/50	9514/18	22/07/2020	WHS
#REF!	QAC	Lurgan Hospital	01	Sink Pad		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	29/07/2021	Identified	Very Low Risk	67404	BA3472/51	9514/18	22/07/2020	WHS
#REF!	QAC	Lurgan Hospital	01	Insulating Board		Insulating Board	NO ASBESTOS	Encapsulated Spray or Laqoino/Unsealed AIB	Areas of damage or deterioration	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67405	BA3472/52	9506/18	11/08/2018	WHS
#REF!	QAC	Lurgan Hospital	01	Insulating Board Below Window		Insulating Board	NO ASBESTOS	Enclosed Spray or Laqoino/Sealed AIB	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67406	BA3472/53	9506/18	11/08/2018	WHS
#REF!	QAC	Lurgan Hospital	01	Duct Access Panels		Insulating Board	NO ASBESTOS	Encapsulated Spray or Laqoino/Unsealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67407	BA3472/54	9506/18	11/08/2018	WHS
#REF!	QAC	Lurgan Hospital	01	Duct Access Panels		Insulating Board	NO ASBESTOS	Encapsulated Spray or Laqoino/Unsealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67408	BA3472/54	9506/18	11/08/2018	WHS
#REF!	QAC	Lurgan Hospital	01	Duct Access Panels		Insulating Board	NO ASBESTOS	Encapsulated Spray or Laqoino/Unsealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67409	BA3472/54	9506/18	11/08/2018	WHS
#REF!	QAC	Lurgan Hospital	01	Duct Access Panels		Insulating Board	NO ASBESTOS	Encapsulated Spray or Laqoino/Unsealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67410	BA3472/54	9506/18	11/08/2018	WHS
#REF!	QAC	Lurgan Hospital	01	Duct Access Panels		Insulating Board	NO ASBESTOS	Encapsulated Spray or Laqoino/Unsealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67411	BA3472/54	9506/18	11/08/2018	WHS
#REF!	QAC	Lurgan Hospital	01	Duct Access Panels		Insulating Board	NO ASBESTOS	Encapsulated Spray or Laqoino/Unsealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67412	BA3472/54	9506/18	11/08/2018	WHS
#REF!	QAC	Lurgan Hospital	01	Duct Access Panels		Insulating Board	NO ASBESTOS	Encapsulated Spray or Laqoino/Unsealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67413	BA3472/54	9506/18	11/08/2018	WHS
#REF!	QAC	Lurgan Hospital	01	Duct Access Panels		Insulating Board	NO ASBESTOS	Encapsulated Spray or Laqoino/Unsealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67414	BA3472/54	9506/18	11/08/2018	WHS
#REF!	QAC	Lurgan Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67415	BA3472/55	9506/18	11/08/2018	WHS
#REF!	QAC	Lurgan Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67416	BA3472/55	9506/18	11/08/2018	WHS
#REF!	QAC	Lurgan Hospital	01	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67417	BA3472/56	9506/18	11/08/2018	WHS
#REF!	QAC	Lurgan Hospital	01	NO ASBESTOS	Fuse flash guards	NO ASBESTOS	NO ASBESTOS			Conduct annual routine inspections	Review of Incident	HSG227	Unchecked	NO ASBESTOS	0	20/11/2019	Presumed	No Asbestos Detected	67418		9514/18	11/08/2018	WHS
#REF!	QAC	Lurgan Hospital	01	Fuse Flash Guards		Textiles & Paper	Presumed Asbestos	Unsealed	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	High Risk	10	29/07/2021	Presumed	High Risk	67419		9514/18	22/07/2020	WHS
#REF!	QAC	Lurgan Hospital	01	Fire Proof Panel		Insulating Board	Presumed Asbestos	Unsealed	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	High Risk	10	29/07/2021	Presumed	High Risk	67420		9514/18	22/07/2020	WHS
#REF!	QAA	Craigavon Hospital	05	Textured Coatings		Decorative Coatings	NO ASBESTOS	Enclosed Spray or Laqoino/Sealed AIB	High	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67466	BA3490/01	9326/17	17/04/2018	WHS
#REF!	QAA	Craigavon Hospital	05	Roofing Felts		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67467	BA3490/02	9326/17	17/04/2018	WHS
#REF!	QAA	Craigavon Hospital	05	Back Board		Insulating Board	NO ASBESTOS	Enclosed Spray or Laqoino/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67468	BA3490/03	9326/17	17/04/2018	WHS
#REF!	QAA	Craigavon Hospital	05	Back Board		Insulating Board	NO ASBESTOS	Enclosed Spray or Laqoino/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67469	BA3490/03	9326/17	17/04/2018	WHS

#REF!	QAA	Craigavon Hospital	05	Back Board		Insulating Board	NO ASBESTOS	Enclosed Spray or Lagoing/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67470	BA3490/03	9326/17	17/04/2018	WHS	
#REF!	QAA	Craigavon Hospital	05	Back Board		Insulating Board	NO ASBESTOS	Enclosed Spray or Lagoing/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67471	BA3490/03	9326/17	17/04/2018	WHS	
#REF!	QAA	Craigavon Hospital	05	Back Board		Insulating Board	NO ASBESTOS	Enclosed Spray or Lagoing/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67472	BA3490/03	9326/17	17/04/2018	WHS	
#REF!	QAA	Craigavon Hospital	05	Back Board		Insulating Board	NO ASBESTOS	Enclosed Spray or Lagoing/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67473	BA3490/03	9326/17	17/04/2018	WHS	
#REF!	QAA	Craigavon Hospital	05	Back Board		Insulating Board	NO ASBESTOS	Enclosed Spray or Lagoing/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67474	BA3490/03	9326/17	17/04/2018	WHS	
#REF!	QAA	Craigavon Hospital	05	Back Board		Insulating Board	NO ASBESTOS	Enclosed Spray or Lagoing/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67475	BA3490/03	9326/17	17/04/2018	WHS	
#REF!	QAA	Craigavon Hospital	05	Back Board		Insulating Board	NO ASBESTOS	Enclosed Spray or Lagoing/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67476	BA3490/03	9326/17	17/04/2018	WHS	
#REF!	QAA	Craigavon Hospital	13	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67477	BA3499/03	9506/18	28/02/2019	WHS	
#REF!	QAA	Craigavon Hospital	13	Roofing Felts		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67478	BA3499/01	9506/18	28/02/2019	WHS	
#REF!	QAA	Craigavon Hospital	13	Textured Coatings		Decorative Coatings	NO ASBESTOS	Enclosed Spray or Lagoing/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67479	BA3499/02	9506/18	28/02/2019	WHS	
#REF!	QAA	Craigavon Hospital	13	Ceiling Board		Insulating Board	NO ASBESTOS	Encapsulated Spray or Lagoing/Unsealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67480	BA3499/04	9506/18	28/02/2019	WHS	
#REF!	QAA	Craigavon Hospital	13	Bitumen Felt		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67481	BA3499/05	9506/18	28/02/2019	WHS	
#REF!	QAA	Craigavon Hospital	13	Fuse Flash Guards		Textiles & Paper	NO ASBESTOS	Encapsulated Spray or Lagoin/Unsealed AIB	Medium	Conduct annual routine inspections	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	14/05/2020	Presumed	No Asbestos Detected	67482		9506/18	28/02/2019	WHS	
#REF!	QAA	Craigavon Hospital	10	Bitumen Felt		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67483	BA3498/01	9326/17	04/11/2018	WHS	
#REF!	QAA	Craigavon Hospital	22	Bitumen Felt		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67484	BA3497/01	9326/17	25/04/2018	WHS	
#REF!	QAA	Craigavon Hospital	22	Lining Panels		Insulating Board	Amosite/Chrysotile	Encapsulated Spray or Lagoin/Unsealed AIB	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Medium Risk	7	18/04/2023	Identified	Medium Risk	67485	BA3497/02	9302.22	17/10/2022	WHS	
#REF!	QAA	Craigavon Hospital	22	Lining Panels		Insulating Board	Amosite/Chrysotile	Encapsulated Spray or Lagoin/Unsealed AIB	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Medium Risk	7	18/04/2023	Strongly Presumed Similar to	Medium Risk	67486	BA3497/02	9302.22	17/10/2022	WHS	
#REF!	QAA	Craigavon Hospital	22	Gaskets		Textiles & Paper	NO ASBESTOS	Encapsulated Spray or Lagoin/Unsealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67487	BA3497/03	9326/17	25/04/2018	WHS	
#REF!	QAA	Craigavon Hospital	22	Gaskets		Textiles & Paper	NO ASBESTOS	Encapsulated Spray or Lagoin/Unsealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67488	BA3497/03	9326/17	25/04/2018	WHS	
#REF!	QAA	Craigavon Hospital	22	Fuse Flash Guards		Textiles & Paper	Presumed Asbestos	Encapsulated Spray or Lagoin/Unsealed AIB	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Medium Risk	9	08/10/2021	Presumed	Medium Risk	67489		9811/19	08/01/2020	WH Stephens	
#REF!	QAA	Craigavon Hospital	22	Fuse Flash Guards		Textiles & Paper	Presumed Asbestos	Encapsulated Spray or Lagoin/Unsealed AIB	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Medium Risk	9	18/04/2023	Presumed	Medium Risk	67490		9302.22	17/10/2022	WHS	
#REF!	QAA	Craigavon Hospital	22	Bitumen Wrap to cables		Composite Material	Presumed Asbestos	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Low Risk	5	17/10/2023	Presumed	Low Risk	67491		9302.22	17/10/2022	WHS	
#REF!	QAA	Craigavon Hospital	26	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67496	BA3500/03	9326/17	04/12/2018	WHS	
#REF!	QAA	Craigavon Hospital	26	Bitumen Felt		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67497	BA3500/01	9326/17	04/12/2018	WHS	
#REF!	QAA	Craigavon Hospital	26	Textured Coatings		Decorative Coatings	NO ASBESTOS	Textured Coating	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67498	BA3500/02	9326/17	04/12/2018	WHS	
#REF!	QAA	Craigavon Hospital	26	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67499	BA3500/03	9326/17	04/12/2018	WHS	
#REF!	QAA	Craigavon Hospital	26	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67500	BA3500/03	9326/17	04/12/2018	WHS	
#REF!	QAA	Craigavon Hospital	26	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67501	BA3500/03	9326/17	04/12/2018	WHS	
#REF!	QAA	Craigavon Hospital	26	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67502	BA3500/04	9326/17	04/12/2018	WHS	
#REF!	QAA	Craigavon Hospital	26	Lining Panels		Insulating Board	NO ASBESTOS	Encapsulated Spray or Lagoin/Unsealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67503	BA3500/05	9326/17	04/12/2018	WHS	
#REF!	QAA	Craigavon Hospital	26	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67504	BA3500/06	9326/17	04/12/2018	WHS	
#REF!	QAA	Craigavon Hospital	26	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67505	BA3500/07	9326/17	04/12/2018	WHS	
#REF!	QAA	Craigavon Hospital	26	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67506	BA3500/08	9326/17	04/12/2018	WHS	
#REF!	QAA	Craigavon Hospital	06	Bitumen Felt		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67507	BA3489/01	9506/19	20/02/2019	WHS	
#REF!	QAA	Craigavon Hospital	06	Bitumen Wrap to cables		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67508	BA3489/02	9506/19	20/02/2019	WHS	
#REF!	QAA	Craigavon Hospital	06	Bitumen Felt		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67509	BA3489/03	9506/19	20/02/2019	WHS	
#REF!	QAA	Craigavon Hospital	06	Fanlight Panel	Ceiling Void	Insulating Board	NO ASBESTOS	Enclosed Spray or Lagoing/Sealed AIB	Low	No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	13/04/2022	Identified	Asbestos Removed	67510	BA3489/04	9811/19	07/01/2020	WH Stephens	
#REF!	QAA	Craigavon Hospital	06	Fuse Flash Guards		Textiles & Paper	Presumed Asbestos	Encapsulated Spray or Lagoin/Unsealed AIB	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Medium Risk	9	13/12/2023	Presumed	Medium Risk	67511		9302.22	22/06/2022	WH Stephens	
#REF!	QAA	Craigavon Hospital	06	Fuse Flash Guards		Textiles & Paper	Presumed Asbestos	Encapsulated Spray or Lagoin/Unsealed AIB	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Medium Risk	9	14/06/2023	Presumed	Medium Risk	67512		9302.22	22/06/2022	WH Stephens	
#REF!	QAA	Craigavon Hospital	06	Fuse Flash Guards		Textiles & Paper	Presumed Asbestos	Encapsulated Spray or Lagoin/Unsealed AIB	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Medium Risk	9	14/06/2023	Presumed	Medium Risk	67513		9302.22	22/06/2022	WH Stephens	
#REF!	QAA	Craigavon Hospital	06	Fuse Flash Guards		Textiles & Paper	Presumed Asbestos	Encapsulated Spray or Lagoin/Unsealed AIB	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Medium Risk	9	13/12/2023	Presumed	Medium Risk	67514		9302.22	22/06/2022	WH Stephens	
#REF!	QAA	Craigavon Hospital	06	Cement Products		Cement Products	NO ASBESTOS	Enclosed Spray or Lagoing/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67515	BA3489/05	9506/19	20/02/2019	WHS	
#REF!	QAA	Craigavon Hospital	06	Cement Products		Cement Products	NO ASBESTOS	Enclosed Spray or Lagoing/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67516	BA3489/06	9506/19	20/02/2019	WHS	
#REF!	QAA	Craigavon Hospital	06	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67517	BA3489/07	9506/19	20/02/2019	WHS	
#REF!	QAA	Craigavon Hospital	06	Gaskets		Textiles & Paper	NO ASBESTOS	Encapsulated Spray or Lagoin/Unsealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67518	BA3489/08	9506/19	20/02/2019	WHS	
#REF!	QAA	Craigavon Hospital	06	Woven Asbestos Textile		Textiles & Paper	Chrysotile	Encapsulated Spray or Lagoin/Unsealed AIB	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Low Risk	6	13/12/2023	Identified	Low Risk	67519	BA3489/09	9302.22	22/06/2022	WH Stephens	
#REF!	QAA	Craigavon Hospital	06	Ceiling Board		Insulating Board	NO ASBESTOS	Encapsulated Spray or Lagoin/Unsealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67520	BA3489/10	9506/19	20/02/2019	WHS	
#REF!	QAA	Craigavon Hospital	06	Gaskets		Textiles & Paper	NO ASBESTOS	Encapsulated Spray or Lagoin/Unsealed AIB	Medium	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	14/05/2020	Identified	Asbestos Removed	67521	BA3489/11	9506/19	20/02/2019	WHS	
#REF!	QAA	Craigavon Hospital	06	Bitumen Wrap to cables		Composite Material	Presumed Asbestos	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Low Risk	5	13/12/2023	Presumed	Low Risk	67522		9302.22	22/06/2022	WH Stephens	
#REF!	QAA	Craigavon Hospital	06	Rope Seal		Textiles & Paper	Presumed Asbestos	Encapsulated Spray or Lagoin/Unsealed AIB	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Medium Risk	8	14/06/2023	Presumed	Medium Risk	67523		9302.22	05/09/2022	WH Stephens	
#REF!	QAA	Craigavon Hospital	09	Roofing Felts		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67568	BA3516/01	9326/17	17/04/2018	WHS	
#REF!	QAA	Craigavon Hospital	03	General Debris		General Debris	NO ASBESTOS	Encapsulated Spray or Lagoin/Unsealed AIB	High	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67673	BA3564/01	9326/17	19/04/2018	WHS	
#REF!	QAA	Craigavon Hospital	03	Gaskets		Textiles & Paper	Chrysotile	Encapsulated Spray or Lagoin/Unsealed AIB	Low	Apply caution when maintaining and affix ID labels	Re-inspection	HSG227	Unchecked	Low Risk	6	05/09/2023	Identified	Low Risk	67674	BA3564/02	9302.22	06/02/2023	WHS	
#REF!	QAA	Craigavon Hospital	03	Fuse Flash Guards		Textiles & Paper	NO ASBESTOS	Encapsulated Spray or Lagoin/Unsealed AIB	Medium	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	06/12/2019	Presumed	Asbestos Removed	67675		9326/17	19/04/2018	WHS	
#REF!	QAA	Craigavon Hospital	03	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67676	BA3564/04	9326/17	19/04/2018	WHS	
#REF!	QAA	Craigavon Hospital	03	Woven Asbestos Textile		Textiles & Paper	Chrysotile	Encapsulated Spray or Lagoin/Unsealed AIB	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Low Risk	6	05/09/2023	Identified	Low Risk	67677	BA3564/04	9302.22	06/02/2023	WHS	
#REF!	QAA	Craigavon Hospital	03	Cement Products		Cement Products	NO ASBESTOS	Enclosed Spray or Lagoing/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67678	BA3564/05	9326/17	19/04/2018	WHS	
#REF!	QAA	Craigavon Hospital	03	Roof Slate		Cement Products	NO ASBESTOS	Enclosed Spray or Lagoing/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67679	BA3564/06	9326/17	19/04/2018	WHS	
#REF!	QAA	Craigavon Hospital	03	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	05/09/2023	Identified	Very Low Risk	67680	BA3564/07	9302.22	06/02/2023	WHS	
#REF!	QAA	Craigavon Hospital	03	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	05/09/2023	Stronnly Presumed Similar to	Very Low Risk	67681	BA3564/07	9302.22	06/02/2023	WHS	
#REF!	QAA	Craigavon Hospital	03	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	05/09/2023	Stronnly Presumed Similar to	Very Low Risk	67682	BA3564/07	9302.22	06/02/2023	WHS	
#REF!	QAA	Craigavon Hospital	03	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67683	BA3564/08	9326/17	19/04/2018	WHS	
#REF!	QAA	Craigavon Hospital	03	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	05/09/2023	Identified	Very Low Risk	67684	BA3564/09	9302.22	06/02/2023	WHS	
#REF!	QAA	Craigavon Hospital	03	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	05/09/2023	Identified	Very Low Risk	67685	BA3564/10	9302.22	06/02/2023	WHS	
#REF!	QAA	Craigavon Hospital	05	Textured Coatings		Decorative Coatings	NO ASBESTOS	Enclosed Spray or Lagoing/Sealed AIB	High	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67686	BA3567/01	9326/17	17/04/2018	WHS	
#REF!	QAA	Craigavon Hospital	05	Textured Coatings		Decorative Coatings	NO ASBESTOS	Enclosed Spray or Lagoing/Sealed AIB	High	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67687	BA3567/02	9326/17	17/04/2018	WHS	
#REF!	QAA	Craigavon Hospital	05	Textured Coatings		Decorative Coatings	NO ASBESTOS	Enclosed Spray or Lagoing/Sealed AIB	High	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67688	BA3567/03	9326/17	17/04/2018	WHS	
#REF!	QAA	Craigavon Hospital	05	Textured Coatings		Decorative Coatings	NO ASBESTOS	Enclosed Spray or Lagoing/Sealed AIB	High	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67689	BA3567/04	9326/17	17/04/2018	WHS	
#REF!	QAA	Craigavon Hospital	07	Bitumen Felt		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67690	BA3566/01	9326/17	04/12/2018	WHS	
#REF!	QAA	Craigavon Hospital	07	General Debris		General Debris	NO ASBESTOS	Encapsulated Spray or Lagoin/Unsealed AIB	High	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67691	BA3566/02	9326/17	04/12/2018	WHS	
#REF!	QAA	Craigavon Hospital	07								Review – No Change	HSG227	Checked	Hoh Risk	0				67692		9326/17	04/12/2018	WHS	
#REF!	QAA	Craigavon Hospital	07	Gaskets		Textiles & Paper	Presumed Asbestos	Encapsulated Spray or Lagoin/Unsealed AIB	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Medium Risk	8	13/12/2023	Presumed	Medium Risk	67693		9302.22	05/09/2022	WH Stephens	
#REF!	QAA	Craigavon Hospital	07	Gaskets		Textiles & Paper	Presumed Asbestos	Encapsulated Spray or Lagoin/Unsealed AIB	Low	Conduct annual routine inspections	Review – No Change	HSG227	Unchecked	Medium Risk	8	14/06/2023	Presumed	Medium Risk	67694		9302.22	05/09/2022	WHS	
#REF!	QAA	Craigavon Hospital	34	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Original Survey Data	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67695	BA3568/01				
#REF!	QAA	Craigavon Hospital	09	Board		Insulating Board	NO ASBESTOS	Encapsulated Spray or Lagoin/Unsealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67696	BA3516/02	9326/17	17/04/2018	WHS	
#REF!	QAA	Craigavon Hospital	09	Board		Insulating Board	NO ASBESTOS	Encapsulated Spray or Lagoin/Unsealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67697	BA3516/02	9326/17	17/04/2018	WHS	
#REF!	QAA	Craigavon Hospital	09	Cylinder insulation		Thermal Insulation	NO ASBESTOS	Encapsulated Spray or Lagoin/Unsealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67698	BA3516/03	9326/17	17/04/2018	WHS	

#REF!	QAA	Craigavon Hospital	09	Pipework Insulation		Thermal Insulation	NO ASBESTOS	Encapsulated Spray or Lagging/Unsealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67699	BA3516/04	9326/17	17/04/2018	WHS
#REF!	QAA	Craigavon Hospital	09	Boiler Lagging		Thermal Insulation	NO ASBESTOS	Encapsulated Spray or Lagging/Unsealed AIB	Medium	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Presumed	Asbestos Removed	67700		9326/17	17/04/2018	WHS
#REF!	QAA	Craigavon Hospital	09	Gaskets		Textiles & Paper	NO ASBESTOS	Encapsulated Spray or Lagging/Unsealed AIB	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Presumed	No Asbestos Detected	67701		9326/17	17/04/2018	WHS
#REF!	QAA	Craigavon Hospital	09	Rope Seal		Textiles & Paper	NO ASBESTOS	Encapsulated Spray or Lagging/Unsealed AIB	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Presumed	Asbestos Removed	67702		9326/17	17/04/2018	WHS
#REF!	QAA	Craigavon Hospital	09	Fuse Flash Guards		Textiles & Paper	Presumed Asbestos	Encapsulated Spray or Lagging/Unsealed AIB	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Medium Risk	9	14/06/2023	Presumed	Medium Risk	67703		9302/22	05/09/2022	WHS
#REF!	QAA	Craigavon Hospital	09	Bitumen Wrap to cables		Composite Material	Presumed Asbestos	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Low Risk	5	13/12/2023	Presumed	Low Risk	67704		9326/17	05/09/2022	WHS
#REF!	QAA	Craigavon Hospital	09	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67705	BA3516/05	9326/17	17/04/2018	WHS
#REF!	QAA	Craigavon Hospital	12	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67706	BA3545/01	9326/17	23/04/2018	WHS
#REF!	QAA	Craigavon Hospital	12	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67707	BA3545/02	9326/17	23/04/2018	WHS
#REF!	QAA	Craigavon Hospital	12	Wall Panels		Insulating Board	NO ASBESTOS	Enclosed Spray or Lagging/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67708	BA3545/03	9326/17	23/04/2018	WHS
#REF!	QAA	Craigavon Hospital	12	Gaskets		Textiles & Paper	NO ASBESTOS	Encapsulated Spray or Lagging/Unsealed AIB	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	06/12/2019	Identified	Asbestos Removed	67709	BA3545/04	9326/17	23/04/2018	WHS
#REF!	QAA	Craigavon Hospital	12	Expansion Joint		Textiles & Paper	NO ASBESTOS	Enclosed Spray or Lagging/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67710	BA3545/05	9326/17	23/04/2018	WHS
#REF!	QAA	Craigavon Hospital	12	Bitumen Felt		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	13/12/2023	Identified	Very Low Risk	67711	BA3545/06	9302/22	05/09/2022	WH Stephens
#REF!	QAA	Craigavon Hospital	12	General Debris		General Debris	NO ASBESTOS	Encapsulated Spray or Lagging/Unsealed AIB	High	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67712	BA3545/07	9326/17	23/04/2018	WHS
#REF!	QAA	Craigavon Hospital	12	Cement Products		Cement Products	NO ASBESTOS	Enclosed Spray or Lagging/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67713	BA3545/08	9326/17	23/04/2018	WHS
#REF!	QAA	Craigavon Hospital	12	Roof Slate		Cement Products	NO ASBESTOS	Enclosed Spray or Lagging/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67714	BA3545/09	9326/17	23/04/2018	WHS
#REF!	QAA	Craigavon Hospital	12	Fuse Flash Guards		Textiles & Paper	NO ASBESTOS	Encapsulated Spray or Lagging/Unsealed AIB	Medium	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Presumed	Asbestos Removed	67715		9326/17	23/04/2018	WHS
#REF!	QAA	Craigavon Hospital	25	Soffit Boards		Cement Products	Chrysotile	Enclosed Spray or	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	4	17/10/2023	Identified	Very Low Risk	67716	BA3515/01	9302/22	17/10/2022	WHS
#REF!	QAA	Craigavon Hospital	25	Bitumen Felt		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67717	BA3515/02	9506/18	11/12/2018	WHS
#REF!	QAA	Craigavon Hospital	25	Bitumen Felt		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67718	BA3515/03	9506/18	11/12/2018	WHS
#REF!	QAA	Craigavon Hospital	25	Pipe Insulation		Textiles & Paper	NO ASBESTOS	Encapsulated Spray or Lagging/Unsealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67719	BA3515/04	9506/18	11/12/2018	WHS
#REF!	QAA	Craigavon Hospital	25	Wall Panels		Insulating Board	NO ASBESTOS	Encapsulated Spray or Lagging/Unsealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67720	BA3515/05	9506/18	11/12/2018	WHS
#REF!	QAA	Craigavon Hospital	25	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67721	BA3515/06	9506/18	11/12/2018	WHS
#REF!	QAA	Craigavon Hospital	25	Boiler Lagging		Thermal Insulation	NO ASBESTOS	Encapsulated Spray or Lagging/Unsealed AIB	Medium	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	26/11/2019	Presumed	Asbestos Removed	67722		9506/18	11/12/2018	WHS
#REF!	QAA	Craigavon Hospital	25	Fuse Flash Guards		Textiles & Paper	NO ASBESTOS	Encapsulated Spray or Lagging/Unsealed AIB	Medium	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	26/11/2019	Presumed	Asbestos Removed	67723		9506/18	11/12/2018	WHS
#REF!	QAA	Craigavon Hospital	25		Cupboard below Stairs					Re-Survey	Review – No Change	HSG227	Checked	High Risk	0				67724		9506/18	11/12/2018	WHS
#REF!	QAA	Craigavon Hospital	25								Review – No Change	HSG227	Checked	High Risk	0			High Risk	67725		9506/18	11/12/2018	WHS
#REF!	QAA	Craigavon Hospital	24	Pipe Insulation		Textiles & Paper	NO ASBESTOS	Encapsulated Spray or Lagging/Unsealed AIB	Medium	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67726	BA3565/01	9506/18	15/11/2018	WHS
#REF!	QAA	Craigavon Hospital	24	Bitumen Felt		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67727	BA3565/02	9506/18	15/11/2018	WHS
#REF!	QAA	Craigavon Hospital	24	Bitumen Felt		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67728	BA3565/03	9506/18	15/11/2018	WHS
#REF!	QAA	Craigavon Hospital	24	Toilet Cistern		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	17/10/2023	Identified	Asbestos Removed	67729	BA3565/04	9302/22	15/11/2018	WHS
#REF!	QAA	Craigavon Hospital	24	Fuse Flash Guards		Textiles & Paper	Presumed Asbestos	Encapsulated Spray or Lagging/Unsealed AIB	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Medium Risk	9	18/04/2023	Presumed	Medium Risk	67730		9302/22	17/10/2022	WHS
#REF!	QAA	Craigavon Hospital	24	Soffit Boards		Cement Products	Presumed Asbestos	Enclosed Spray or	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Low Risk	6	17/10/2023	Presumed	Low Risk	67731		9302/22	17/10/2022	WHS
#REF!	QAA	Craigavon Hospital	24	Bitumen Paints		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67732	BA3565/05	9506/18	15/11/2018	WHS
#REF!	QAA	Craigavon Hospital	24	Damp Proof Course		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67733	BA3565/06	9506/18	15/11/2018	WHS
#REF!	QAA	Craigavon Hospital	24	Corrugated Roof Sheet		Cement Products	Chrysotile	Enclosed Spray or Lagging/Sealed AIB	Low	Apply caution when maintaining and affix ID labels	Re-inspection	HSG227	Unchecked	Very Low Risk	4	17/10/2023	Identified	Very Low Risk	67734	BA3565/07	9302/22	17/10/2022	WHS
#REF!	QAA	Craigavon Hospital	24	Verge Cloak		Cement Products	NO ASBESTOS	Enclosed Spray or Lagging/Sealed AIB	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67735	BA3565/08	9506/18	15/11/2018	WHS
#REF!	QAA	Craigavon Hospital	23	Soffit Boards		Cement Products	Chrysotile	Enclosed Spray or	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	4	17/01/2024	Identified	Very Low Risk	67736	BA3522/01	9302/22	05/09/2022	WHS
#REF!	QAA	Craigavon Hospital	15	Verge Cloak		Cement Products	Chrysotile	Enclosed Spray or	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	4	13/12/2023	Identified	Very Low Risk	67737	BA3481/01	9302/22	05/09/2022	WH Stephens
#REF!	QAA	Craigavon Hospital	14	Infill Panel		Insulating Board	NO ASBESTOS	Enclosed Spray or Lagging/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67738	BA3517/01	9506/18	11/09/2018	WHS
#REF!	QAA	Craigavon Hospital	14	Infill Panel		Insulating Board	NO ASBESTOS	Enclosed Spray or Lagging/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67739	BA3517/01	9506/18	11/09/2018	WHS
#REF!	QAA	Craigavon Hospital	14	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67740	BA3517/02	9506/18	11/09/2018	WHS
#REF!	QAA	Craigavon Hospital	14	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67741	BA3517/02	9506/18	11/09/2018	WHS
#REF!	QAA	Craigavon Hospital	14	Ceiling Panelling		Insulating Board	NO ASBESTOS	Enclosed Spray or	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67742	BA3517/03	9506/18	11/09/2018	WHS
#REF!	QAA	Craigavon Hospital	14	Roofing Felts		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67743	BA3517/04	9506/18	11/09/2018	WHS
#REF!	QAA	Craigavon Hospital	14	Lining Paper		Textiles & Paper	NO ASBESTOS	Encapsulated Spray or Lagging/Unsealed AIB	Medium	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67744	BA3517/05	9506/18	11/09/2018	WHS
#REF!	QAA	Craigavon Hospital	14	Lining Paper		Textiles & Paper	NO ASBESTOS	Encapsulated Spray or Lagging/Unsealed AIB	Medium	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67745	BA3517/05	9506/18	11/09/2018	WHS
#REF!	QAA	Craigavon Hospital	14	Ceiling Tiles		Insulating Board	NO ASBESTOS	Encapsulated Spray or Lagging/Unsealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67746	BA3517/06	9506/18	11/09/2018	WHS
#REF!	QAA	Craigavon Hospital	14	Ceiling Tiles		Insulating Board	NO ASBESTOS	Encapsulated Spray or Lagging/Unsealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67747	BA3517/06	9506/18	11/09/2018	WHS
#REF!	QAA	Craigavon Hospital	14	Ceiling Board		Insulating Board	NO ASBESTOS	Enclosed Spray or Lagging/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67748	BA3517/07	9506/18	11/09/2018	WHS
#REF!	QAA	Craigavon Hospital	14	Ceiling Board		Insulating Board	NO ASBESTOS	Enclosed Spray or Lagging/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67749	BA3517/07	9506/18	11/09/2018	WHS
#REF!	QAA	Craigavon Hospital	14	Ceiling Board		Insulating Board	NO ASBESTOS	Enclosed Spray or Lagging/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67750	BA3517/07	9506/18	11/09/2018	WHS
#REF!	QAA	Craigavon Hospital	14	Sink Pad		Composite Material	Chrysotile	Composite Materials	Low	Apply caution when maintaining and affix ID labels	Re-inspection	HSG227	Unchecked	Very Low Risk	3	13/12/2023	Identified	Very Low Risk	67751	BA3517/08	9302/22	22/06/2022	WH Stephens
#REF!	QAA	Craigavon Hospital	14	Sink Pad		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	13/12/2023	Identified	Very Low Risk	67752	BA3517/09	9302/22	22/06/2022	WH Stephens
#REF!	QAA	Craigavon Hospital	14	Stair Nosing		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67753	BA3517/10	9506/18	11/09/2018	WHS
#REF!	QAA	Craigavon Hospital	14	Board		Insulating Board	NO ASBESTOS	Encapsulated Spray or Lagging/Unsealed AIB	Medium	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67754	BA3517/11	9506/18	11/09/2018	WHS
#REF!	QAA	Craigavon Hospital	14	Panel		Insulating Board	NO ASBESTOS	Encapsulated Spray or Lagging/Unsealed AIB	Significant areas of damage or	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67755	BA3517/12	9506/18	11/09/2018	WHS
#REF!	QAA	Craigavon Hospital	14	Ceiling Panelling		Insulating Board	NO ASBESTOS	Encapsulated Spray or Lagging/Unsealed AIB	Significant areas of damage or	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67756	BA3517/13	9506/18	11/09/2018	WHS
#REF!	QAA	Craigavon Hospital	14	Ceiling Panelling		Insulating Board	NO ASBESTOS	Encapsulated Spray or Lagging/Unsealed AIB	Medium	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67757	BA3517/13	9506/18	11/09/2018	WHS
#REF!	QAA	Craigavon Hospital	14	Damp Proof Course		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67758	BA3517/14	9506/18	11/09/2018	WHS
#REF!	QAA	Craigavon Hospital	14	Ceiling Board		Insulating Board	NO ASBESTOS	Encapsulated Spray or Lagging/Unsealed AIB	Medium	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67759	BA3517/15	9506/18	11/09/2018	WHS
#REF!	QAA	Craigavon Hospital	14	Ceiling Board		Insulating Board	NO ASBESTOS	Encapsulated Spray or Lagging/Unsealed AIB	Medium	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67760	BA3517/15	9506/18	11/09/2018	WHS
#REF!	QAA	Craigavon Hospital	14	Rope Seal		Textiles & Paper	NO ASBESTOS	Encapsulated Spray or Lagging/Unsealed AIB	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	Asbestos Removed	67761	BA3517/16	9506/18	11/09/2018	WHS
#REF!	QAA	Craigavon Hospital	14	Gaskets		Textiles & Paper	NO ASBESTOS	Encapsulated Spray or Lagging/Unsealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67762	BA3517/17	9506/18	11/09/2018	WHS
#REF!	QAA	Craigavon Hospital	14	Fuse Flash Guards		Textiles & Paper	Presumed Asbestos	Encapsulated Spray or Lagging/Unsealed AIB	Medium	Apply Caution when Maintaining	Re-inspection	HSG227	Unchecked	Medium Risk	9	13/12/2023	Presumed	Medium Risk	67763		9302/22	22/06/2022	WH Stephens
#REF!	QAA	Craigavon Hospital	14	Board		Insulating Board	Presumed Asbestos	Encapsulated Spray or Lagging/Unsealed AIB	Medium	Apply Caution when Maintaining	Review – No Change	HSG227	Unchecked	Medium Risk	9	10/07/2021	Presumed	Medium Risk	67764		9811/19	01/06/2020	WH Stephens
#REF!	QAA	Craigavon Hospital	14	Board		Insulating Board	Presumed Asbestos	Encapsulated Spray or Lagging/Unsealed AIB	Medium	Apply Caution when Maintaining	Re-inspection	HSG227	Unchecked	Medium Risk	9	14/06/2023	Presumed	Medium Risk	67765		9302/22	22/06/2022	WH Stephens
#REF!	QAA	Craigavon Hospital	14	Boiler Lagging		Thermal Insulation	NO ASBESTOS	Encapsulated Spray or Lagging/Unsealed AIB	Medium	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Presumed	Asbestos Removed	67766		9506/18	11/09/2018	WHS
#REF!	QAA	Craigavon Hospital	14	Cylinder insulation		Thermal Insulation	NO ASBESTOS	Encapsulated Spray or Lagging/Unsealed AIB	Medium	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Presumed	Asbestos Removed	67767		9506/18	11/09/2018	WHS
#REF!	QAA	Craigavon Hospital	14	Verge Cloak		Cement Products	NO ASBESTOS	Enclosed Spray or Lagging/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67768	BA3517/18	9506/18	11/09/2018	WHS
#REF!	QAA	Craigavon Hospital	23	Verge Cloak		Cement Products	Chrysotile	Enclosed Spray or	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	4	17/01/2024	Identified	Very Low Risk	67769	BA3522/02	9302/22	05/09/2022	WHS
#REF!	QAA	Craigavon Hospital	23	Pipe Insulation		Thermal Insulation	NO ASBESTOS	Encapsulated Spray or Lagging/Unsealed AIB	Medium	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67770	BA3522/03	9326/17	19/04/2018	WHS
#REF!	QAA	Craigavon Hospital	23	Gaskets		Textiles & Paper	NO ASBESTOS	Encapsulated Spray or Lagging/Unsealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67771	BA3522/04	9326/17	19/04/2018	WHS
#REF!	QAA	Craigavon Hospital	23	Gaskets		Textiles & Paper	NO ASBESTOS	Encapsulated Spray or Lagging/Unsealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67772	BA3522/04	9326/17	19/04/2018	WHS
#REF!	QAA	Craigavon Hospital	23	Woven Asbestos Textile		Textiles & Paper	Chrysotile	Encapsulated Spray or	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Low Risk	6	17/01/2024	Identified	Low Risk	67773	BA3522/05	9302/22	05/09/2022	WHS
#REF!	QAA	Craigavon Hospital	23	General Debris		General Debris	NO ASBESTOS	Encapsulated Spray or Lagging/Unsealed AIB	High	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67774	BA3522/06	9326/17	19/04/2018	WHS
#REF!	QAA	Craigavon Hospital	23	General Debris		General Debris	NO ASBESTOS	Encapsulated Spray or Lagging/Unsealed AIB	High	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67775	BA3522/07	9326/17	19/04/2018	WHS
#REF!	QAA	Craigavon Hospital	23	Back Board		Insulating Board	NO ASBESTOS	Encapsulated Spray or Lagging/Unsealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67776	BA3522/08	9326/17	19/04/2018	WHS
#REF!	QAA	Craigavon Hospital	23	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	17/01/2024	Identified	Very Low Risk	67777	BA3522/09	9302/22	05/09/2022	WHS

#REF!	QAA	Craigavon Hospital	23	Stair Nosing		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67778	BA3522/10	9326/17	19/04/2018	WHS
#REF!	QAA	Craigavon Hospital	23	Stair Nosing		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	17/01/2024	Identified	Very Low Risk	67779	BA3522/11	9326/22	05/09/2022	WHS
#REF!	QAA	Craigavon Hospital	23	Stair Nosing		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	17/01/2024	Strongly Presumed Similar to	Very Low Risk	67780	BA3522/11	9326/22	05/09/2023	WHS
#REF!	QAA	Craigavon Hospital	23	Stair Nosing		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	13/12/2023	Strongly Presumed Similar to	Very Low Risk	67781	BA3522/11	9326/22	08/01/2020	WH Stephens
#REF!	QAA	Craigavon Hospital	23	Bitumen Wrao to cables		Composite Material	Presumed Asbestos	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Low Risk	5	17/01/2024	Presumed	Low Risk	67782		9326/22	05/09/2022	WHS
#REF!	QAA	Craigavon Hospital	23	Cowl		Cement Products	Presumed Asbestos	Encapsulated Spray or Laconio/Unsealed AIB	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Low Risk	6	17/01/2024	Presumed	Low Risk	67783		9326/22	05/09/2022	WHS
#REF!	QAA	Craigavon Hospital	23	Fuse Flash Guards		Textiles & Paper	Presumed Asbestos	Encapsulated Spray or Laconio/Unsealed AIB	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Medium Risk	9	19/07/2023	Presumed	Medium Risk	67784		9320/22	05/09/2022	WHS
#REF!	QAA	Craigavon Hospital	23	Stair Nosing		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67785	BA3522/12	9326/17	19/04/2018	WHS
#REF!	QAA	Craigavon Hospital	23	Board		Insulating Board	NO ASBESTOS	Enclosed Spray or Laconio/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67786	BA3522/13	9326/17	19/04/2018	WHS
#REF!	QAA	Craigavon Hospital	23	Board		Insulating Board	NO ASBESTOS	Encapsulated Spray or Laconio/Unsealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67787	BA3522/14	9326/17	19/04/2018	WHS
#REF!	QAA	Craigavon Hospital	23	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67788	BA3522/15	9326/17	19/04/2018	WHS
#REF!	QAA	Craigavon Hospital	23	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67789	BA3522/15	9326/17	19/04/2018	WHS
#REF!	QAA	Craigavon Hospital	23	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67790	BA3522/16	9326/17	19/04/2018	WHS
#REF!	QAA	Craigavon Hospital	23	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67791	BA3522/16	9326/17	19/04/2018	WHS
#REF!	QAA	Craigavon Hospital	23	Fire Break Panel		Insulating Board	NO ASBESTOS	Enclosed Spray or Laconio/Sealed AIB	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67792	BA3522/17	9326/17	19/04/2018	WHS
#REF!	QAA	Craigavon Hospital	23	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	17/01/2024	Identified	Very Low Risk	67793	BA3522/18	9326/22	05/09/2022	WHS
#REF!	QAA	Craigavon Hospital	23	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	17/01/2024	Identified	Very Low Risk	67794	BA3522/19	9326/22	08/01/2020	WHS
#REF!	QAA	Craigavon Hospital	23	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	17/01/2024	Identified	Very Low Risk	67795	BA3522/20	9326/22	05/09/2022	WHS
#REF!	QAA	Craigavon Hospital	23	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	17/01/2024	Strongly Presumed Similar to	Very Low Risk	67796	BA3522/20	9326/22	05/09/2022	WHS
#REF!	QAA	Craigavon Hospital	23	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	17/01/2024	Identified	Very Low Risk	67797	BA3522/21	9326/22	05/09/2022	WHS
#REF!	QAA	Craigavon Hospital	23	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	17/01/2024	Strongly Presumed Similar to	Very Low Risk	67798	BA3522/21	9326/22	05/09/2022	WHS
#REF!	QAA	Craigavon Hospital	23	Stair Nosing		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67799	BA3522/22	9326/17	19/04/2018	WHS
#REF!	QAA	Craigavon Hospital	23	Roofspace						Re-Survey	Review – No Change	HSG227	Checked	High Risk	0				67800		9326/17	19/04/2018	WHS
#REF!	QAA	Craigavon Hospital	15	Cowl		Cement Products	Presumed Asbestos	Enclosed Spray or	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Low Risk	6	13/12/2023	Presumed	Low Risk	67801		9326/22	05/09/2022	WH Stephens
#REF!	QAA	Craigavon Hospital	15	Back Board		Insulating Board	NO ASBESTOS	Encapsulated Spray or Laconio/Unsealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67802	BA3481/02	9326/17	04/12/2018	WHS
#REF!	QAA	Craigavon Hospital	15	Gaskets		Textiles & Paper	NO ASBESTOS	Encapsulated Spray or Laconio/Unsealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67803	BA3481/03	9326/17	04/12/2018	WHS
#REF!	QAA	Craigavon Hospital	15	Roofing Felts		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67804	BA3481/04	9326/17	04/12/2018	WHS
#REF!	QAA	Craigavon Hospital	15	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67805	BA3481/05	9326/17	04/12/2018	WHS
#REF!	QAA	Craigavon Hospital	15	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67806	BA3481/05	9326/17	04/12/2018	WHS
#REF!	QAA	Craigavon Hospital	15	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67807	BA3481/05	9326/17	04/12/2018	WHS
#REF!	QAA	Craigavon Hospital	15	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67808	BA3481/05	9326/17	04/12/2018	WHS
#REF!	QAA	Craigavon Hospital	15	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67809	BA3481/05	9326/17	04/12/2018	WHS
#REF!	QAA	Craigavon Hospital	15	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67810	BA3481/05	9326/17	04/12/2018	WHS
#REF!	QAA	Craigavon Hospital	15	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67811	BA3481/05	9326/17	04/12/2018	WHS
#REF!	QAA	Craigavon Hospital	15	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67812	BA3481/05	9326/17	04/12/2018	WHS
#REF!	QAA	Craigavon Hospital	15	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67813	BA3481/05	9326/17	04/12/2018	WHS
#REF!	QAA	Craigavon Hospital	15	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67814	BA3481/05	9326/17	04/12/2018	WHS
#REF!	QAA	Craigavon Hospital	15	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67815	BA3481/05	9326/17	04/12/2018	WHS
#REF!	QAA	Craigavon Hospital	15	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67816	BA3481/05	9326/17	04/12/2018	WHS
#REF!	QAA	Craigavon Hospital	15	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67817	BA3481/05	9326/17	04/12/2018	WHS
#REF!	QAA	Craigavon Hospital	15	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67818	BA3481/05	9326/17	04/12/2018	WHS
#REF!	QAA	Craigavon Hospital	15	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67819	BA3481/05	9326/17	04/12/2018	WHS
#REF!	QAA	Craigavon Hospital	15	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67820	BA3481/05	9326/17	04/12/2018	WHS
#REF!	QAA	Craigavon Hospital	15	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67821	BA3481/05	9326/17	04/12/2018	WHS
#REF!	QAA	Craigavon Hospital	15	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67822	BA3481/05	9326/17	04/12/2018	WHS
#REF!	QAA	Craigavon Hospital	15	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67823	BA3481/05	9326/17	04/12/2018	WHS
#REF!	QAA	Craigavon Hospital	15	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67824	BA3481/05	9326/17	04/12/2018	WHS
#REF!	QAA	Craigavon Hospital	15	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67825	BA3481/05	9326/17	04/12/2018	WHS
#REF!	QAA	Craigavon Hospital	15	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67826	BA3481/05	9326/17	04/12/2018	WHS
#REF!	QAA	Craigavon Hospital	15	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67827	BA3481/05	9326/17	04/12/2018	WHS
#REF!	QAA	Craigavon Hospital	15	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67828	BA3481/05	9326/17	04/12/2018	WHS
#REF!	QAA	Craigavon Hospital	15	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67829	BA3481/05	9326/17	04/12/2018	WHS
#REF!	QAA	Craigavon Hospital	15	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67830	BA3481/05	9326/17	04/12/2018	WHS
#REF!	QAA	Craigavon Hospital	15	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67831	BA3481/05	9326/17	04/12/2018	WHS
#REF!	QAA	Craigavon Hospital	15	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67832	BA3481/05	9326/17	04/12/2018	WHS
#REF!	QAA	Craigavon Hospital	15	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67833	BA3481/05	9326/17	04/12/2018	WHS
#REF!	QAA	Craigavon Hospital	15	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	13/12/2023	Identified	Very Low Risk	67834	BA3481/06	9326/22	05/09/2022	WH Stephens
#REF!	QAA	Craigavon Hospital	15	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	13/12/2023	Stronmly Presumed Similar to	Very Low Risk	67835	BA3481/06	9326/22	05/09/2022	WH Stephens
#REF!	QAA	Craigavon Hospital	15	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	13/12/2023	Identified	Very Low Risk	67836	BA3481/06	9326/22	05/09/2022	WHS
#REF!	QAA	Craigavon Hospital	15	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67837	BA3481/07	9326/17	04/12/2018	WHS
#REF!	QAA	Craigavon Hospital	15	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67838	BA3481/07	9326/17	04/12/2018	WHS
#REF!	QAA	Craigavon Hospital	15	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67839	BA3481/07	9326/17	04/12/2018	WHS
#REF!	QAA	Craigavon Hospital	15	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67840	BA3481/07	9326/17	04/12/2018	WHS
#REF!	QAA	Craigavon Hospital	15	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67841	BA3481/07	9326/17	04/12/2018	WHS
#REF!	QAA	Craigavon Hospital	15	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67842	BA3481/07	9326/17	04/12/2018	WHS
#REF!	QAA	Craigavon Hospital	15	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67843	BA3481/07	9326/17	04/12/2018	WHS
#REF!	QAA	Craigavon Hospital	15	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67844	BA3481/07	9326/17	04/12/2018	WHS
#REF!	QAA	Craigavon Hospital	15	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67845	BA3481/07	9326/17	04/12/2018	WHS
#REF!	QAA	Craigavon Hospital	15	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67846	BA3481/07	9326/17	04/12/2018	WHS
#REF!	QAA	Craigavon Hospital	15	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67847	BA3481/07	9326/17	04/12/2018	WHS
#REF!	QAA	Craigavon Hospital	15	Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	13/12/2023	Identified	Very Low Risk	67848	BA3481/08	9326/22	05/09/2022	WHS
#REF!	QAA	Craigavon Hospital	15	Sink Pad		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	13/12/2023	Identified	Very Low Risk	67849	BA3481/09	9326/22	05/09/2022	WHS
#REF!	QAA	Craigavon Hospital	15	Sink Pad		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	13/12/2023	Strongly Presumed Similar to	Very Low Risk	67850	BA3481/09	9326/22	05/09/2022	WH Stephens
#REF!	QAA	Craigavon Hospital	15	Sink Pad		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	13/12/2023	Stronmly Presumed Similar to	Very Low Risk	67851	BA3481/09	9326/22	05/09/2022	WH Stephens
#REF!	QAA	Craigavon Hospital	15	Sink Pad		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	13/12/2023	Strongly Presumed Similar to	Very Low Risk	67852	BA3481/09	9326/22	05/09/2022	WHS
#REF!	QAA	Craigavon Hospital	15	Ceiling Board		Insulating Board	NO ASBESTOS	Encapsulated Spray or Laconio/Unsealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67853	BA3481/10	9326/17	04/12/2018	WHS
#REF!	QAA	Craigavon Hospital	15	Blanket Material		Textiles & Paper	NO ASBESTOS	Encapsulated Spray or Laconio/Unsealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67854	BA3481/11	9326/17	04/12/2018	WHS
#REF!	QAA	Craigavon Hospital	15	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67855	BA3481/12	9326/17	04/12/2018	WHS
#REF!	QAA	Craigavon Hospital	15	Fire Break Panel		Insulating Board	NO ASBESTOS	Encapsulated Spray or Laconio/Unsealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67856	BA3481/13	9326/17	04/12/2018	WHS
#REF!	QAA	Craigavon Hospital	15	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Low	Apply caution when maintaining and affix ID labels	Re-inspection	HSG227	Unchecked	Very Low Risk	3	08/10/2021	Identified	Very Low Risk	67857	BA3481/14	9811/16	15/01/2020	WH Stephens
#REF!	QAA	Craigavon Hospital	15	Fuse Flash Guards		Textiles & Paper	Presumed Asbestos	Encapsulated Spray or Laconio/Unsealed AIB	Medium	Further Investion Required	Re-inspection	HSG227	Unchecked	Medium Risk	9	14/06/2023	Presumed	Medium Risk	67858		9302/22	05/09/2022	WH Stepehsn
#REF!	QAA	Craigavon Hospital	21	Gaskets		Textiles & Paper	NO ASBESTOS	Encapsulated Spray or Laconio/Unsealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67859	BA3593/01	9326/17	20/04/2018	WHS
#REF!	QAA	Craigavon Hospital	21	Damp Proof Course		Composite Material	Chrysotile	Composite Materials	Low	Apply Caution when Maintaining	Re-inspection	HSG227	Unchecked	Very Low Risk	3	17/10/2023	Identified	Very Low Risk	67860	BA3593/02	9326/17	17/10/2022	WHS

#REF!	QAA	Craigavon Hospital	21	Roofing Felts		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67861	BA3593/03	9326/17	20/04/2018	WHS
#REF!	QAA	Craigavon Hospital	21	Bitumen Paints		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67862	BA3593/04	9326/17	20/04/2018	WHS
#REF!	QAA	Craigavon Hospital	21	Stair Nosing		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67863	BA3593/05	9326/17	20/04/2018	WHS
#REF!	QAA	Craigavon Hospital	21	Lining Panels		Insulating Board	NO ASBESTOS	Enclosed Spray or Lagging/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67864	BA3593/06	9326/17	20/04/2018	WHS
#REF!	QAA	Craigavon Hospital	21	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	06/12/2019	Identified	Asbestos Removed	67865	BA3593/07	9326/17	20/04/2018	WHS
#REF!	QAA	Craigavon Hospital	21	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67866	BA3593/08	9326/17	20/04/2018	WHS
#REF!	QAA	Craigavon Hospital	21	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67867	BA3593/09	9326/17	20/04/2018	WHS
#REF!	QAA	Craigavon Hospital	21	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67868	BA3593/10	9326/17	20/04/2018	WHS
#REF!	QAA	Craigavon Hospital	21	Lining Panels		Insulating Board	NO ASBESTOS	Enclosed Spray or Lagging/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67869	BA3593/11	9326/17	20/04/2018	WHS
#REF!	QAA	Craigavon Hospital	21	Lining Panels		Insulating Board	NO ASBESTOS	Enclosed Spray or Lagging/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67870	BA3593/12	9326/17	20/04/2018	WHS
#REF!	QAA	Craigavon Hospital	21	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67871	BA3593/13	9326/17	20/04/2018	WHS
#REF!	QAA	Craigavon Hospital	21	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67872	BA3593/13	9326/17	20/04/2018	WHS
#REF!	QAA	Craigavon Hospital	21	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67873	BA3593/14	9326/17	20/04/2018	WHS
#REF!	QAA	Craigavon Hospital	21	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67874	BA3593/14	9326/17	20/04/2018	WHS
#REF!	QAA	Craigavon Hospital	21	Lining Panels		Insulating Board	NO ASBESTOS	Enclosed Spray or Lagging/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67875	BA3593/15	9326/17	20/04/2018	WHS
#REF!	QAA	Craigavon Hospital	21	Lining Panels		Insulating Board	NO ASBESTOS	Encapsulated Spray or Lagging/Unsealed AIB	Medium	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67876	BA3593/16	9326/17	20/04/2018	WHS
#REF!	QAA	Craigavon Hospital	21	Pipe Insulation		Thermal Insulation	NO ASBESTOS	Encapsulated Spray or Lagging/Unsealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67877	BA3593/17	9326/17	20/04/2018	WHS
#REF!	QAA	Craigavon Hospital	21	Gaskets		Textiles & Paper	NO ASBESTOS	Encapsulated Spray or Lagging/Unsealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67878	BA3593/18	9326/17	20/04/2018	WHS
#REF!	QAA	Craigavon Hospital	21	Woven Asbestos Textile		Textiles & Paper	Chrysotile	Encapsulated Spray or Lagging/Unsealed AIB	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Low Risk	6	17/10/2023	Identified	Low Risk	67879	BA3593/19	9203/22	17/10/2022	WHS
#REF!	QAA	Craigavon Hospital	21	General Debris		General Debris	NO ASBESTOS	Unsealed Spray / Lagging / Dust Debris	Significant areas of damage or	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67880	BA3593/20	9326/17	20/04/2018	WHS
#REF!	QAA	Craigavon Hospital	21	General Debris		General Debris	NO ASBESTOS	Unsealed Spray / Lagging / Dust Debris	Significant areas of damage or	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67881	BA3593/21	9326/17	20/04/2018	WHS
#REF!	QAA	Craigavon Hospital	21	General Debris		General Debris	NO ASBESTOS	Unsealed Spray / Lagging / Dust Debris	Significant areas of damage or	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67882	BA3593/22	9326/17	20/04/2018	WHS
#REF!	QAA	Craigavon Hospital	21	General Debris		General Debris	NO ASBESTOS	Unsealed Spray / Lagging / Dust Debris	Significant areas of damage or	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67883	BA3593/23	9326/17	20/04/2018	WHS
#REF!	QAA	Craigavon Hospital	21	General Debris		General Debris	NO ASBESTOS	Unsealed Spray / Lagging / Dust Debris	Significant areas of damage or	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67884	BA3593/24	9326/17	20/04/2018	WHS
#REF!	QAA	Craigavon Hospital	21	Verge Cloak		Cement Products	Presumed Asbestos	Enclosed Spray or Lagging/Sealed AIB	Low	Apply Caution when Maintaining	Re-inspection	HSG227	Unchecked	Low Risk	6	17/10/2023	Presumed	Low Risk	67885		9203/22	17/10/2022	WHS
#REF!	QAA	Craigavon Hospital	21	Fuse Flash Guards		Textiles & Paper	Presumed Asbestos	Encapsulated Spray or Lagging/Unsealed AIB	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Medium Risk	9	18/04/2023	Presumed	Medium Risk	67886		9203/22	17/10/2022	WHS
#REF!	QAA	Craigavon Hospital	21	Lining Panels		Insulating Board	NO ASBESTOS	Enclosed Spray or Lagging/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Presumed	No Asbestos Detected	67887	BS146291	9326/17	20/04/2018	WHS
#REF!	QAA	Craigavon Hospital	21	Lining Panels		Insulating Board	NO ASBESTOS	Enclosed Spray or Lagging/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Presumed	No Asbestos Detected	67888	BS146291	9326/17	20/04/2018	WHS
#REF!	QAA	Craigavon Hospital	21	Lining Panels		Insulating Board	NO ASBESTOS	Enclosed Spray or Lagging/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Presumed	No Asbestos Detected	67889	BS146291	9326/17	20/04/2018	WHS
#REF!	QAA	Craigavon Hospital	21	Lining Panels		Insulating Board	NO ASBESTOS	Enclosed Spray or Lagging/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Presumed	No Asbestos Detected	67890	BS146291	9326/17	20/04/2018	WHS
#REF!	QAA	Craigavon Hospital	21	Lining Panels		Insulating Board	NO ASBESTOS	Enclosed Spray or Lagging/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Presumed	No Asbestos Detected	67891	BS146291	9326/17	20/04/2018	WHS
#REF!	QAA	Craigavon Hospital	21	Lining Panels		Insulating Board	NO ASBESTOS	Enclosed Spray or Lagging/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Presumed	No Asbestos Detected	67892	BS146291	9326/17	20/04/2018	WHS
#REF!	QAA	Craigavon Hospital	21	Lining Panels		Insulating Board	NO ASBESTOS	Enclosed Spray or Lagging/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Presumed	No Asbestos Detected	67893	BS146291	9326/17	20/04/2018	WHS
#REF!	QAA	Craigavon Hospital	21	Lining Panels		Insulating Board	NO ASBESTOS	Enclosed Spray or Lagging/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67894	BS146291	9326/17	20/04/2018	WHS
#REF!	QAA	Craigavon Hospital	21	Lining Panels	Board above Kitchen Door	Insulating Board	Presumed Asbestos	Enclosed Spray or	Low	Further investigation Required	Re-inspection	HSG227	Unchecked	Medium Risk	7	17/10/2023	Presumed	Medium Risk	67895		9203/22	17/10/2022	WHS
#REF!	QAA	Craigavon Hospital	21	Cylinder insulation		Thermal Insulation	Presumed Asbestos	Encapsulated Spray or Lagging/Unsealed AIB	Medium	Further investigation Required	Re-inspection	HSG227	Unchecked	High Risk	10	17/10/2023	Presumed	Medium Risk	67896		9203/22	17/10/2022	WHS
#REF!	QAA	Craigavon Hospital	21	Bitumen Wrao to cables		Composite Material	Presumed Asbestos	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Low Risk	5	17/10/2023	Presumed	Low Risk	67897		9203/22	17/10/2022	WHS
#REF!	QAA	Craigavon Hospital	27	Lino Flooring		Composite Material	NO ASBESTOS	Composite Materials	Medium	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67898	BA3594/01	9506/18	19/12/2018	WHS
#REF!	QAA	Craigavon Hospital	27	Fuse Flash Guards		Textiles & Paper	Presumed Asbestos	Encapsulated Spray or Lagging/Unsealed AIB	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Medium Risk	9	18/04/2023	Presumed	Medium Risk	67899		9302/22	17/10/2022	WHS
#REF!	RAB	Longstone/Mullinure	03	Lino Flooring		Composite Material	NO ASBESTOS	Composite Materials	Low	Apply caution when maintaining and affix ID labels	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	Asbestos Removed	67944	BA3534/01	9506/18	11/08/2018	WHS
#REF!	RAB	Longstone/Mullinure	03	Lino Flooring		Composite Material	NO ASBESTOS	Composite Materials	Low	Apply caution when maintaining and affix ID labels	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	Asbestos Removed	67945	BA3534/01	9506/18	11/08/2018	WHS
#REF!	RAB	Longstone/Mullinure	03	Lino Flooring		Composite Material	NO ASBESTOS	Composite Materials	Low	Apply caution when maintaining and affix ID labels	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	Asbestos Removed	67946	BA3534/01	9506/18	11/08/2018	WHS
#REF!	RAB	Longstone/Mullinure	03	Lino Flooring		Composite Material	NO ASBESTOS	Composite Materials	Low	Apply caution when maintaining and affix ID labels	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	Asbestos Removed	67947	BA3534/01	9506/18	11/08/2018	WHS
#REF!	RAB	Longstone/Mullinure	03	Fuse Flash Guards		Textiles & Paper	NO ASBESTOS	Enclosed Fuse Flash Guards	Medium	Apply caution when maintaining and affix ID labels	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Presumed	Asbestos Removed	67948		9506/18	11/08/2018	WHS
#REF!	RAB	Longstone/Mullinure	03	Fuse Flash Guards		Textiles & Paper	NO ASBESTOS	Enclosed Fuse Flash Guards	Medium	Apply caution when maintaining and affix ID labels	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Presumed	Asbestos Removed	67949		9506/18	11/08/2018	WHS
#REF!	RAB	Longstone/Mullinure	03	Fuse Flash Guards		Textiles & Paper	NO ASBESTOS	Enclosed Fuse Flash Guards	Medium	Apply caution when maintaining and affix ID labels	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Presumed	Asbestos Removed	67950		9506/18	11/08/2018	WHS
#REF!	RAB	Longstone/Mullinure	03	Fuse Flash Guards		Textiles & Paper	NO ASBESTOS	Enclosed Fuse Flash Guards	Medium	Apply caution when maintaining and affix ID labels	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Presumed	Asbestos Removed	67951		9506/18	11/08/2018	WHS
#REF!	RAB	Longstone/Mullinure	03	Anti Vibration Pads	To Ventilation Duct	Textiles & Paper	NO ASBESTOS	Composite Materials	Minor damage or deterioration	Apply caution when maintaining and affix ID labels	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	Asbestos Removed	67952	BA3534/03	9506/18	11/08/2018	WHS
#REF!	RAB	Longstone/Mullinure	03	Verge Cloak	Roof	Cement Products	Amosite/Chrysotile	Cement Sheets	Very Low	Further investigation Required	Re-inspection	HSG227	Unchecked	Very Low Risk	4	27/03/2021	Identified	Very Low Risk	67953	BA3534/04	9506/18	27/11/2019	WHS
#REF!	RAB	Longstone/Mullinure	09	Fire Break Panel	Above suspended ceiling	Insulating Board	NO ASBESTOS	Unsealed Board	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67954	BA3536/01	9506/18	11/07/2018	WHS
#REF!	RAB	Longstone/Mullinure	09	Fire Break Panel	Above suspended ceiling	Insulating Board	NO ASBESTOS	Unsealed Board	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67955	BA3536/02	9506/18	11/07/2018	WHS
#REF!	RAB	Longstone/Mullinure	09	Fire Break Panel	Above suspended ceiling at room 049	Insulating Board	NO ASBESTOS	Unsealed Board	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67956	BA3536/02	9506/18	11/07/2018	WHS
#REF!	RAB	Longstone/Mullinure	09	Fuse Flash Guards		Textiles & Paper	NO ASBESTOS	Enclosed Fuse Flash Guards	Medium	Conduct annual routine inspections	ACM Removed	HSG227	Unchecked	NO ASBESTOS	0	11/12/2019	Presumed	Asbestos Removed	67957		9506/18	11/07/2018	WHS
#REF!	RAB	Longstone/Mullinure	09	Fuse Flash Guards		Textiles & Paper	NO ASBESTOS	Enclosed Fuse Flash Guards	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	NO ASBESTOS	0	11/12/2019	Presumed	No Asbestos Detected	67958		9506/18	11/07/2018	WHS
#REF!	RAB	Longstone/Mullinure	09	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Very Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67959	BA3536/03	9506/18	11/07/2018	WHS
#REF!	RAB	Longstone/Mullinure	09	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Very Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67960	BA3536/03	9506/18	11/07/2018	WHS
#REF!	RAB	Longstone/Mullinure	09	fascia board	Rear	Cement Products	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	25/03/2021	Identified	Very Low Risk	67961	BA3536/04	9506/18	27/11/2019	WHS
#REF!	RAB	Longstone/Mullinure	09	Bitumen Felt	Roof	Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67962	BA3536/05	9506/18	11/07/2018	WHS
#REF!	RAB	Longstone/Mullinure	04	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Very Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67963	BA3529/01	9506/18	11/08/2018	WHS
#REF!	RAB	Longstone/Mullinure	04	Fuse Flash Guards		Textiles & Paper	Chrysotile	Enclosed Fuse Flash Guards	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Low Risk	6	25/03/2021	Identified	Medium Risk	67964		9506/18	27/11/2019	WHS
#REF!	RAB	Longstone/Mullinure	04	Fuse Flash Guards		Textiles & Paper	Presumed Asbestos	Enclosed Fuse Flash Guards	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Medium Risk	8	25/03/2021	Presumed	Medium Risk	67965		9506/18	27/11/2019	WHS
#REF!	RAB	Longstone/Mullinure	04	Sink Pad		Composite Material	NO ASBESTOS	Composite Material	Very Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67966	BA3529/02	9506/18	11/08/2018	WHS
#REF!	RAB	Lonestone/Mullinure	04	Lino Floorino		Composite Material	Chrvsotile	Composite Materials	Minor damage or	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	25/03/2021	Identified	Very Low Risk	67967	BA3529/03	9506/18	27/11/2019	WHS
#REF!	RAB	Longstone/Mullinure	04	Insulating Board		Insulating Board	NO ASBESTOS	Unsealed Board	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67968	BA3529/04	9506/18	11/08/2018	WHS
#REF!	RAB	Longstone/Mullinure	04	Ceiling Board		Insulating Board	NO ASBESTOS	Unsealed Board	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67969	BA3529/05	9506/18	11/08/2018	WHS
#REF!	RAB	Longstone/Mullinure	04	Verge Cloak	Front Porch	Cement Products	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67970	BA3529/06	9506/18	11/08/2018	WHS
#REF!	RAB	Longstone/Mullinure	04	Bitumen Felt	Roof	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67971	BA3529/07	9506/18	11/08/2018	WHS
#REF!	NAB	St.Lukes	27	Roofing Felts	Roof	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67972	BA3537/01	9506/18	18/07/2018	WHS
#REF!	NAB	St.Lukes	27	Roofing Felts	Roof	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67973	BA3537/01	9506/18	18/07/2018	WHS
#REF!	NAB	St.Lukes	27	Artificial Slate	Roof	Cement Products	Chrysotile	Concealed Cement	Very Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	2	24/02/2021	Identified	Very Low Risk	67974	BA3537/02	9506/18	03/12/2020	WHS
#REF!	RAB	Longstone/Mullinure	02	Lino Flooring		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67975	BA3533/01	9506/18	13/11/2018	WHS
#REF!	RAB	Longstone/Mullinure	02	Lino Flooring		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67976	BA3533/01	9506/18	13/11/2018	WHS
#REF!	RAB	Longstone/Mullinure	02	Lino Flooring		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67977	BA3533/01	9506/18	13/11/2018	WHS
#REF!	RAB	Longstone/Mullinure	02	Lino Flooring		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67978	BA3533/01	9506/18	13/11/2018	WHS
#REF!	RAB	Longstone/Mullinure	02	Ceiling Tiles		Insulating Board	NO ASBESTOS	Unsealed Board	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67979	BA3533/02	9506/18	13/11/2018	WHS
#REF!	RAB	Longstone/Mullinure	02	Ceiling Tiles		Insulating Board	NO ASBESTOS	Unsealed Board	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67980	BA3533/02	9506/18	13/11/2018	WHS
#REF!	RAB	Longstone/Mullinure	02	Ceiling Tiles		Insulating Board	NO ASBESTOS	Unsealed Board	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67981	BA3533/02	9506/18	13/11/2018	WHS
#REF!	RAB	Longstone/Mullinure	02	Ceiling Tiles		Insulating Board	NO ASBESTOS	Unsealed Board	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67982	BA3533/02	9506/18	13/11/2018	WHS

#REF!	RAB	Longstone/Mullinure	02	Ceiling Tiles		Insulating Board	NO ASBESTOS	Unsealed Board	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67983	BA3533/02	9506/18	13/11/2018	WHS
#REF!	RAB	Longstone/Mullinure	02	Ceiling Tiles		Insulating Board	NO ASBESTOS	Unsealed Board	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67984	BA3533/02	9506/18	13/11/2018	WHS
#REF!	RAB	Longstone/Mullinure	02	Ceiling Tiles		Insulating Board	NO ASBESTOS	Unsealed Board	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67985	BA3533/02	9506/18	13/11/2018	WHS
#REF!	RAB	Longstone/Mullinure	02	Ceiling Tiles		Insulating Board	NO ASBESTOS	Unsealed Board	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67986	BA3533/02	9506/18	13/11/2018	WHS
#REF!	RAB	Longstone/Mullinure	02	Stair Nosing		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67987	BA3533/03	9506/18	13/11/2018	WHS
#REF!	RAB	Longstone/Mullinure	02	Stair Nosing	Stairs	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67988	BA3533/03	9506/18	13/11/2018	WHS
#REF!	RAB	Longstone/Mullinure	02	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Very Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67989	BA3533/04	9506/18	13/11/2018	WHS
#REF!	RAB	Longstone/Mullinure	02	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Very Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67990	BA3533/04	9506/18	13/11/2018	WHS
#REF!	RAB	Longstone/Mullinure	02	Fuse Flash Guards		Textiles & Paper	Presumed Asbestos	Enclosed Fuse Flash Guards	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Medium Risk	8	27/03/2021	Presumed	Medium Risk	67991		9811/1	20/01/2020	WHS
#REF!	RAB	Longstone/Mullinure	02	Fuse Flash Guards		Textiles & Paper	NO ASBESTOS	Enclosed Fuse Flash Guards	Medium	Conduct annual routine inspections	ACM Removed	HSG227	Unchecked	NO ASBESTOS	0	20/11/2019	Identified	Asbestos Removed	67992	BS14399	9506/1	13/11/2018	WHS
#REF!	RAB	Longstone/Mullinure	02	Pipe Insulation		Thermal Insulation	NO ASBESTOS	Concealed Pipework Insulation	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67993	BA3533/05	9506/18	13/11/2018	WHS
#REF!	RAB	Longstone/Mullinure	02	Rope Seal	Rope to Pipe Insulation	Textiles & Paper	NO ASBESTOS	Unsealed Rope	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67994	BA3533/06	9506/18	13/11/2018	WHS
#REF!	RAB	Longstone/Mullinure	02	Ceiling Board		Insulating Board	NO ASBESTOS	Unsealed Board	Very Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67995	BA3533/07	9506/18	13/11/2018	WHS
#REF!	RAB	Longstone/Mullinure	02	Verge Cloak	Front Porch	Cement Products	NO ASBESTOS	Cement Sheets	Very Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67996	BA3533/08	9506/18	13/11/2018	WHS
#REF!	RAB	Longstone/Mullinure	02	Bitumen Felt	Roof	Composite Material	NO ASBESTOS	Composite Materials	Very Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67997	BA3533/09	9506/18	13/11/2018	WHS
#REF!	RAB	Longstone/Mullinure	02	Bitumen Felt	Rear	Composite Material	NO ASBESTOS	Composite Materials	Very Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	67998	BA3533/09	9506/18	13/11/2018	WHS
#REF!	RAB	Longstone/Mullinure	01	Lino Flooring		Composite Material	NO ASBESTOS	Composite Materials	Very Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	67999	BA3532/01	9506/18	13/11/2018	WHS
#REF!	RAB	Longstone/Mullinure	01	Stair Nosing		Composite Material	NO ASBESTOS	Composite Materials	Very Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68000	BA3532/02	9506/18	13/11/2018	WHS
#REF!	RAB	Longstone/Mullinure	01	Stair Nosing	Stairs	Composite Material	NO ASBESTOS	Composite Materials	Very Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68001	BA3532/02	9506/18	13/11/2018	WHS
#REF!	RAB	Longstone/Mullinure	01	Lino Flooring	Under Carpet	Composite Material	NO ASBESTOS	Composite Materials	Very Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68002	BA3532/03	9506/18	13/11/2018	WHS
#REF!	RAB	Longstone/Mullinure	01	Lino Flooring	Under Carpet	Composite Material	NO ASBESTOS	Composite Materials	Very Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68003	BA3532/03	9506/18	13/11/2018	WHS
#REF!	RAB	Longstone/Mullinure	01	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68004	BA3532/04	9506/18	13/11/2018	WHS
#REF!	RAB	Longstone/Mullinure	01	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68005	BA3532/04	9506/18	13/11/2018	WHS
#REF!	RAB	Longstone/Mullinure	01	Fuse Flash Guards		Textiles & Paper	Presumed Asbestos	Enclosed Fuse Flash Guards	Medium	Conduct annual routine inspections	Review – No Change	HSG227	Unchecked	Medium Risk	8	20/11/2019	Presumed	Medium Risk	68008		9506/1	13/11/2018	WHS
#REF!	RAB	Longstone/Mullinure	01	Fuse Flash Guards		Textiles & Paper	Chrysotile	Enclosed Fuse Flash Guards	Medium	Conduct annual routine inspections	Review – No Change	HSG227	Unchecked	Low Risk	6	20/11/2019	Identified	Medium Risk	68007	BS314401	9506/1	13/11/2018	WHS
#REF!	RAB	Longstone/Mullinure	01	Pipe Insulation		Thermal Insulation	NO ASBESTOS	Partially Exposed Pipework Insulation	Very Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68008	BA3532/05	9506/18	13/11/2018	WHS
#REF!	RAB	Longstone/Mullinure	01	Rope Seal	Rope to Pipework Insulation	Textiles & Paper	NO ASBESTOS	Unsealed Rope	Very Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68009	BA3532/06	9506/18	13/11/2018	WHS
#REF!	RAB	Longstone/Mullinure	01	Bitumen Felt	Roof	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68010	BA3532/07	9506/18	13/11/2018	WHS
#REF!	NAB	St.Lukes	14	Boiler Lagging	Internal Insulation to Boiler	Thermal Insulation	Presumed Asbestos	Lagging Asbestos Insulation	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Medium Risk	9	24/02/2021	Presumed	Medium Risk	68011		9811/1	03/12/2019	WHS
#REF!	NAB	St.Lukes	32	Roofing Felts		Reinforced Composites	NO ASBESTOS	Composite Materials	Very Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68012	BA3538/01	9506/18	15/07/2018	WHS
#REF!	NAB	St.Lukes	32	Boardino	Flat 3 Roofspace	Cement Products	Chrysotile	Unsealed Board	High	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	Medium Risk	7	24/02/2021	Identified	Medium Risk	68013	BA3538/02	9811/1	06/12/2019	WHS
#REF!	NAB	St.Lukes	32	Boardino	Flat 2 Roofspace	Cement Products	Chrysotile	Unsealed Board	High	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	Medium Risk	7	24/02/2021	Strongly Presumed Similar to	Medium Risk	68014	BA3538/02	9811/1	06/12/2019	WHS
#REF!	NAB	St.Lukes	32	Boarding	Flat 1 Roofspace	Cement Products	Chrysotile	Unsealed Board	High	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	Medium Risk	7	24/02/2021	Strongly Presumed Similar to	Medium Risk	68015	BA3538/02	9811/1	06/12/2019	WHS
#REF!	NAB	St.Lukes	32	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Very Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	2	24/02/2021	Identified	Very Low Risk	68016	BA3538/03	9811/1	06/12/2019	WHS
#REF!	NAB	St.Lukes	32	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Very Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	2	24/02/2021	Strongly Presumed Similar to	Very Low Risk	68017	BA3538/03	9811/1	06/12/2019	WHS
#REF!	NAB	St.Lukes	32	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Very Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	2	24/02/2021	Strongly Presumed Similar to	Very Low Risk	68018	BA3538/03	9811/1	06/12/2019	WHS
#REF!	NAB	St.Lukes	32	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Very Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68019	BA3538/04	9506/18	15/07/2018	WHS
#REF!	NAB	St.Lukes	32	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Very Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68020	BA3538/04	9506/18	15/07/2018	WHS
#REF!	NAB	St.Lukes	32	Soffit Boarding	External	Cement Products	Chrysotile	Cement Sheets	Very Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	24/02/2021	Identified	Very Low Risk	68021	BA3538/05	9811/1	20/01/2020	WHS
#REF!	NAB	St.Lukes	32	Bitumen Felt	Front Porches	Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68022	BA3538/06	9506/18	15/07/2018	WHS
#REF!	NAB	St.Lukes	32	Bitumen Felt	Rear Sheds	Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68023	BA3538/06	9506/18	15/07/2018	WHS
#REF!	NAB	St.Lukes	32	Damp Proof Course		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68024	BA3538/07	9506/18	15/07/2018	WHS
#REF!	NAB	St.Lukes	25	Wall Panels	Above Door	Insulating Board	NO ASBESTOS	Unsealed Board	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68033	BA3535/01	9506/18	26/06/2018	WHS
#REF!	NAB	St.Lukes	25	Wall Panels	Above Ceiling	Insulating Board	NO ASBESTOS	Unsealed Board	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68034	BA3535/01	9506/18	26/06/2018	WHS
#REF!	NAB	St.Lukes	25	Wall Panels		Insulating Board	NO ASBESTOS	Unsealed Board	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68035	BA3535/01	9506/18	26/06/2018	WHS
#REF!	NAB	St.Lukes	25	Wall Panels		Insulating Board	NO ASBESTOS	Sealed Asbestos Insulation Board	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68036	BA3535/02	9506/18	26/06/2018	WHS
#REF!	NAB	St.Lukes	25	Wall Panels		Insulating Board	NO ASBESTOS	Sealed Asbestos Insulation Board	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68037	BA3535/02	9506/18	26/06/2018	WHS
#REF!	NAB	St.Lukes	25	Wall Panels		Insulating Board	NO ASBESTOS	Unsealed Board	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68038	BA3535/03	9506/18	26/06/2018	WHS
#REF!	NAB	St.Lukes	25	Wall Panels		Insulating Board	NO ASBESTOS	Unsealed Board	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68039	BA3535/03	9506/18	26/06/2018	WHS
#REF!	NAB	St.Lukes	25	Wall Panels		Insulating Board	NO ASBESTOS	Unsealed Board	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68040	BA3535/03	9506/18	26/06/2018	WHS
#REF!	NAB	St.Lukes	25	Wall Panels		Insulating Board	NO ASBESTOS	Unsealed Board	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68041	BA3535/03	9506/18	26/06/2018	WHS
#REF!	NAB	St.Lukes	25	Wall Panels		Insulating Board	NO ASBESTOS	Unsealed Board	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68042	BA3535/03	9506/18	26/06/2018	WHS
#REF!	NAB	St.Lukes	25	Wall Panels		Insulating Board	NO ASBESTOS	Unsealed Board	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68043	BA3535/03	9506/18	26/06/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	07	Roofing Felts		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68044	BA3277/01	9506/18	19/11/2018	WHS
#REF!	QAA	Craigavon Hospital	11	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68045	BA3613/01	9326/17	04/03/2018	WHS
#REF!	QAA	Craigavon Hospital	11	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	06/09/2023	Identified	Very Low Risk	68046	BA3613/02	9326/2	18/10/2022	WHS
#REF!	QAA	Craigavon Hospital	11	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68047	BA3613/01	9326/17	04/03/2018	WHS
#REF!	QAA	Craigavon Hospital	11	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	06/09/2023	Strongly Presumed Similar to	Very Low Risk	68048	BA3613/02	9326/2	18/10/2022	WHS
#REF!	QAA	Craigavon Hospital	11	Woven Asbestos Textile		Textiles & Paper	NO ASBESTOS	Encapsulated Spray or Laoaino/Unsealed AIB	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	06/12/2019	Presumed	Asbestos Removed	68049		9326/17	04/03/2018	WHS
#REF!	QAA	Craigavon Hospital	11	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68050	BA3613/03	9326/17	04/03/2018	WHS
#REF!	QAA	Craigavon Hospital	11	Boarding		Cement Products	NO ASBESTOS	Enclosed Spray or Laoaino/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review of Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68051	BA3613/04	9326/17	04/03/2018	WHS
#REF!	QAA	Craigavon Hospital	11	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68052	BA3613/05	9326/17	04/03/2018	WHS
#REF!	QAA	Craigavon Hospital	11	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68053	BA3613/05	9326/17	04/03/2018	WHS
#REF!	NAB	St.Lukes	25	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Very Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68054	BA3535/04	9506/18	26/06/2018	WHS
#REF!	NAB	St.Lukes	25	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Very Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68055	BA3535/04	9506/18	26/06/2018	WHS
#REF!	NAB	St.Lukes	25	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Very Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68056	BA3535/04	9506/18	26/06/2018	WHS
#REF!	NAB	St.Lukes	25	Toilet Cistern		Cement Products Reinforced	Amosite	Concealed Cement	Very Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	02/03/2021	Identified	Very Low Risk	68057	BA3535/05	9811/1	03/01/2020	WHS
#REF!	NAB	St.Lukes	25				Amosite	Composite Material	Very Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	02/03/2021	Strongly Presumed Similar to	Very Low Risk	68058	BA3535/05	9811/1	03/01/2020	WHS
#REF!	NAB	St.Lukes	25	Ceiling Board		Insulating Board	NO ASBESTOS	Sealed Asbestos Insulation Board	Very Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68059	BA3535/06	9506/18	26/06/2018	WHS
#REF!	NAB	St.Lukes	25	Ceiling Tiles	Telephone Cupboard	Insulating Board	Amosite	Encapsulated Asbestos	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Low Risk	6	02/03/2021	Identified	Low Risk	68060	BA3535/07	9811/1	03/01/2020	WHS
#REF!	NAB	St.Lukes	25	Fire Proof Panel	Insulation to Kiln	Insulating Board	Presumed Asbestos	Encased beneath overlaying non asbestos installati	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	High Risk	10	02/03/2021	Presumed	Medium Risk	68061		9811/1	03/01/2020	WHS
#REF!	NAB	St.Lukes	25	Fuse Flash Guards		Textiles & Paper	Presumed Asbestos	Enclosed Fuse Flash Guards	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Medium Risk	8	02/03/2021	Presumed	Medium Risk	68062		9811/1	03/01/2020	WHS
#REF!	NAB	St.Lukes	25	Ceiling Board		Insulating Board	Amosite	Unsealed Board	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Medium Risk	7	02/03/2021	Identified	Medium Risk	68063	BA3535/08	9811/1	03/01/2020	WHS
#REF!	NAB	St.Lukes	25	Ceiling Board		Insulating Board	Amosite	Unsealed Board	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Medium Risk	7	02/03/2021	Strongly Presumed Similar to	Medium Risk	68064	BA3535/08	9811/1	03/01/2020	WHS
#REF!	NAB	St.Lukes	25	Ceiling Board		Insulating Board	Amosite	Unsealed Board	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Medium Risk	7	02/03/2021	Strongly Presumed Similar to	Medium Risk	68065	BA3535/08	9811/1	03/01/2020	WHS
#REF!	NAB	St.Lukes	25	Ceiling Board	Smoke Room	Insulating Board	NO ASBESTOS	Concealed Asbestos Insulation Board	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68066	BA3535/09	9506/18	26/06/2018	WHS
#REF!	NAB	St.Lukes	25	Ceiling Board		Insulating Board	NO ASBESTOS	Concealed Asbestos Insulation Board	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68067	BA3535/09	9506/18	26/06/2018	WHS
#REF!	NAB	St.Lukes	25	Ceiling Board		Insulating Board	NO ASBESTOS	Concealed Asbestos Insulation Board	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68068	BA3535/09	9506/18	26/06/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	03	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68069	BA3276/01	9327/17	21/03/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	03	Stair Nosing		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68070	BA3276/02	9327/17	21/03/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	03	Stair Nosing		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68071	BA3276/02	9327/17	21/03/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	03	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68072	BA3276/03	9327/17	21/03/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	03	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68073	BA3276/03	9327/17	21/03/2018	WHS

#REF!	SAA	Daisy Hill Hospital Estate	03	Roofing Felts		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68074	BA3276/04	932717	21/03/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	03	Roofing Felts		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68075	BA3276/04	932717	21/03/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	03	Verge Cloak		Cement Products	NO ASBESTOS	Enclosed Spray or Lagging/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68076	BA3276/05	932717	21/03/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	03				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	06/12/2019		No Asbestos Detected	68077		932717	21/03/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	03				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	68078		932717	21/03/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	04	Sink Pad		Composite Material	Chrysotile	Composite Materials	Low	Label & Manage	Re-inspection	HSG227	Unchecked	Very Low Risk	3	14/09/2023	Identified	Very Low Risk	68079	BA3298/01	932424	22/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	04	Sink Pad		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	14/09/2023	Strongly Presumed Similar to	Very Low Risk	68080	BA3298/01	932424	22/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	04	Seal		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68081	BA3298/02	950918	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	04	Seal		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68082	BA3298/02	950918	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	04	Seal		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68083	BA3298/02	950918	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	04	Seal		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68084	BA3298/02	950918	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	04	Seal		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68085	BA3298/02	950918	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	04	Seal		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68086	BA3298/02	950918	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	04	Seal		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68087	BA3298/02	950918	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	04	Lining Panels		Insulating Board	Presumed Asbestos	Encapsulated Spray or Lagging/Unsealed AIB	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Medium Risk	9	14/03/2023	Presumed	Medium Risk	68088		930922	22/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	04	Fuse Flash Guards		Textiles & Paper	Presumed Asbestos	Encapsulated Spray or Lagging/Unsealed AIB	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Medium Risk	9	14/03/2023	Presumed	Medium Risk	68089		930922	22/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	04	Seal		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68090	BA3298/02	950918	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	04	Seal		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68091	BA3298/02	950918	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	04	Seal		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68092	BA3298/02	950918	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	04	Seal		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68093	BA3298/02	950918	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	04	Seal		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68094	BA3298/02	950918	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	04	Seal		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68095	BA3298/02	950918	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	04	Seal		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68096	BA3298/02	950918	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	04	Bitumen Felt		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68097	BA3298/03	950918	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	04	Soffit Boards		Insulating Board	Amosite/Chrysotile	Enclosed Spray or Lagging/Sealed AIB	High	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	Medium Risk	8	14/03/2023	Identified	Medium Risk	68098	BA3298/04	932424	22/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	04	Damp Proof Course		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68099	BA3298/05	950918	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	04	Ceiling Panellins		Cement Products	Chrysotile	Enclosed Spray or Lagging/Sealed AIB	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	4	14/09/2023	Identified	Very Low Risk	68100	BA3298/06	932424	22/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	04	Wall Panels		Insulating Board	NO ASBESTOS	Enclosed Spray or Lagging/Sealed AIB	Medium	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	Asbestos Removed	68101	BA3298/07	950918	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	04	Wall Panels		Insulating Board	NO ASBESTOS	Enclosed Spray or Lagging/Sealed AIB	Medium	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	Asbestos Removed	68102	BA3298/08	950918	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	04	Wall Panels		Insulating Board	NO ASBESTOS	Enclosed Spray or Lagging/Sealed AIB	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	Asbestos Removed	68103	BA3298/09	950918	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	04				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	68104		950918	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	07	Stair Nosing		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68105	BA3277/02	950918	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	07	Back Board	Roofspace Hatch	Insulating Board	Amosite/Chrysotile	Enclosed Spray or Lagging/Sealed AIB	High	Encapsulate and label as asbestos	Re-inspection	HSG227	Unchecked	Medium Risk	8	14/03/2023	Identified	Medium Risk	68106	BA3277/03	932424	07/09/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	07	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Medium	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68107	BA3277/04	950918	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	07	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68108	BA3277/05	950918	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	07	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68109	BA3277/06	950918	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	07	Verge Cloak		Cement Products	Presumed Asbestos	Enclosed Spray or Lagging/Sealed AIB	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Low Risk	6	14/09/2023	Presumed	Low Risk	68110		932424	07/09/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	10	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68111	BA3276/01	950918	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	10	Wall Panels		Insulating Board	NO ASBESTOS	Enclosed Spray or Lagging/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68112	BA3276/02	950918	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	10	Wall Panels		Insulating Board	NO ASBESTOS	Enclosed Spray or Lagging/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68113	BA3276/03	950918	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	10	Insulating Board		Insulating Board	NO ASBESTOS	Encapsulated Spray or Lagging/Unsealed AIB	Medium	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68114	BA3276/04	950918	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	10	Pipe Insulation		Thermal Insulation	NO ASBESTOS	Unsealed Spray or Lagging	High	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68115	BA3276/05	950918	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	10	Textured Coatings		Decorative Coatings	Chrysotile	Enclosed Spray or Lagging/Sealed AIB	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	4	15/09/2023	Identified	Very Low Risk	68116	BA3278/06	932424	20/04/2022	WHS
#REF!	NAB	St.Lukes	28	Textured Coatings	Portacabin Walls	Decorative Coatings	NO ASBESTOS	Textured Coating	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68117	BA3603/01	934417	20/09/2017	WHS
#REF!	NAB	St.Lukes	28	Corrugated Roof Sheet	Hotel Services Store Roof under new roof	Cement Products	Chrysotile	Concealed Cement	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	04/03/2021	Identified	Very Low Risk	68118	BA3603/02	981171	03/01/2020	WHS
#REF!	NAB	St.Lukes	28	Corrugated Roof Sheet	File Stores under new roof	Cement Products	Chrysotile	Concealed Cement	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	04/03/2021	Strongly Presumed Similar to	Very Low Risk	68119	BA3603/02	981171	03/01/2020	WHS
#REF!	NAB	St.Lukes	28	Heating Panel	Storage Heater	Insulating Board	NO ASBESTOS	Enclosed Spray or Lagging/Sealed AIB	Medium	Conduct annual routine inspections	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	22/09/2018	Presumed	Asbestos Removed	68120		934417	20/09/2017	WHS
#REF!	NAB	St.Lukes	28	Heating Panel		Insulating Board	NO ASBESTOS	Enclosed Spray or Lagging/Sealed AIB	Medium	Conduct annual routine inspections	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	22/09/2018	Presumed	Asbestos Removed	68121		934417	20/09/2017	WHS
#REF!	NAB	St.Lukes	28	Heating Panel	Storage Heater	Insulating Board	NO ASBESTOS	Enclosed Spray or Lagging/Sealed AIB	Medium	Conduct annual routine inspections	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	22/09/2018	Presumed	Asbestos Removed	68122		934417	20/09/2017	WHS
#REF!	NAB	St.Lukes	28	Heating Panel	Storage Heater	Insulating Board	NO ASBESTOS	Enclosed Spray or Lagging/Sealed AIB	Medium	Conduct annual routine inspections	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	22/09/2018	Presumed	Asbestos Removed	68123		934417	20/09/2017	WHS
#REF!	NAB	St.Lukes	28	Heating Panel	Storage Heater	Insulating Board	Presumed Asbestos	Enclosed Spray or Lagging/Unsealed AIB	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Medium Risk	8	04/03/2021	Presumed	Medium Risk	68124		981171	03/01/2020	WHS
#REF!	NAB	St.Lukes	28	Lino Flooring		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68125	BA3603/03	934417	20/09/2017	WHS
#REF!	NAB	St.Lukes	28	Board	Floor	Insulating Board	NO ASBESTOS	Unsealed Board	High	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68126	BA3603/04	934417	20/09/2017	WHS
#REF!	NAB	St.Lukes	28	Bitumen Felt	Portacabin Roof	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified		68127	BA3603/05	934417	20/09/2017	WHS
#REF!	NAB	St.Lukes	28	Fuse Flash Guards		Textiles & Paper	Presumed Asbestos	Enclosed Fuse Flash Guards	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Medium Risk	8	04/03/2021	Presumed	Medium Risk	68128		981171	03/01/2020	WHS
#REF!	NAB	St.Lukes	19	Fire Break Panel	Board to Roof	Insulating Board	NO ASBESTOS	Unsealed Board	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68129	BA3528/01	950918	19/07/2018	WHS
#REF!	NAB	St.Lukes	19	Roofing Felts		Composite Material	NO ASBESTOS	Composite Material	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68130	BA3528/02	950918	19/07/2018	WHS
#REF!	NAB	St.Lukes	19	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Very Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68131	BA3528/03	950918	19/07/2018	WHS
#REF!	NAB	St.Lukes	19	Fuse Flash Guards		Textiles & Paper	Presumed Asbestos	Enclosed Fuse Flash Guards	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Medium Risk	8	24/02/2021	Presumed	Medium Risk	68132		981171	20/01/2020	WHS
#REF!	NAB	St.Lukes	19	Fuse Flash Guards		Textiles & Paper	Presumed Asbestos	Enclosed Fuse Flash Guards	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Medium Risk	8	24/02/2021	Presumed	Medium Risk	68133		981171	20/01/2020	WHS
#REF!	NAB	St.Lukes	19	Toilet Cistern		Cement Products	NO ASBESTOS	Concealed Cement	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68134	BA3528/04	950918	19/07/2018	WHS
#REF!	NAB	St.Lukes	19	Toilet Cistern		Cement Products	NO ASBESTOS	Concealed Cement	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68135	BA3528/04	950918	19/07/2018	WHS
#REF!	NAB	St.Lukes	19	Floor Tiles	Under Carpet	Composite Material	Chrysotile	Composite Material	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	24/02/2021	Identified	Very Low Risk	68136	BA3528/05	981171	20/01/2020	WHS
#REF!	NAB	St.Lukes	19	Floor Tiles	under carpet	Composite Material	Chrysotile	Composite Material	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	24/02/2021	Strongly Presumed Similar to	Very Low Risk	68137	BA3528/05	981171	20/01/2020	WHS
#REF!	NAB	St.Lukes	19	Floor Tiles	under carpet	Composite Material	Chrysotile	Composite Material	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	24/02/2021	Strongly Presumed Similar to	Very Low Risk	68138	BA3528/05	981171	20/01/2020	WHS
#REF!	NAB	St.Lukes	19	Floor Tiles	Under Carpet	Composite Material	Chrysotile	Composite Material	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	24/02/2021	Strongly Presumed Similar to	Very Low Risk	68139	BA3528/05	981171	20/01/2020	WHS
#REF!	NAB	St.Lukes	19	Floor Tiles	Under Carpet	Composite Material	Chrysotile	Composite Material	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	24/02/2021	Strongly Presumed Similar to	Very Low Risk	68140	BA3528/05	981171	20/01/2020	WHS
#REF!	NAB	St.Lukes	19	Floor Tiles		Composite Material	Chrysotile	Composite Material	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	24/02/2021	Strongly Presumed Similar to	Very Low Risk	68141	BA3528/05	981171	20/01/2020	WHS
#REF!	NAB	St.Lukes	19	Floor Tiles		Composite Material	Chrysotile	Composite Material	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	24/02/2021	Strongly Presumed Similar to	Very Low Risk	68142	BA3528/05	981171	20/01/2020	WHS
#REF!	NAB	St.Lukes	19	Floor Tiles	Under caroet	Composite Material	Chrysotile	Composite Material	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	24/02/2021	Strongly Presumed Similar to	Very Low Risk	68143	BA3528/05	981171	20/01/2020	WHS
#REF!	NAB	St.Lukes	19	Floor Tiles		Composite Material	Chrysotile	Composite Material	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	24/02/2021	Strongly Presumed Similar to	Very Low Risk	68144	BA3528/05	981171	20/01/2020	WHS
#REF!	NAB	St.Lukes	19	Floor Tiles	Under carpet	Composite Material	Chrysotile	Composite Material	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	24/02/2021	Strongly Presumed Similar to	Very Low Risk	68145	BA3528/05	981171	20/01/2020	WHS
#REF!	NAB	St.Lukes	19	Floor Tiles	Under carpet	Composite Material	Chrysotile	Composite Material	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	24/02/2021	Strongly Presumed Similar to	Very Low Risk	68146	BA3528/05	981171	20/01/2020	WHS
#REF!	NAB	St.Lukes	19	Floor Tiles	Under carpet	Composite Material	Chrysotile	Composite Material	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	24/02/2021	Strongly Presumed Similar to	Very Low Risk	68147	BA3528/05	981171	20/01/2020	WHS
#REF!	NAB	St.Lukes	19	Floor Tiles	Under Carpet	Composite Material	Chrysotile	Composite Material	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	24/02/2021	Strongly Presumed Similar to	Very Low Risk	68148	BA3528/05	981171	20/01/2020	WHS
#REF!	NAB	St.Lukes	19	Gaskets		Textiles & Paper	Chrysotile	Sealed	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	4	24/02/2021	Identified	Low Risk	68149	BA3529/06	981171	20/01/2020	WHS
#REF!	NAB	St.Lukes	19	Door Panel	Back of Door	Insulating Board	NO ASBESTOS	Unsealed Board	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68150	BA3528/07	950918	19/07/2018	WHS
#REF!	NAB	St.Lukes	19	Verge Cloak		Cement Products	NO ASBESTOS	Cement Sheets	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68151	BA3528/08	950918	19/07/2018	WHS
#REF!	NAB	St.Lukes	19	Artificial Slate	Boiler House Roof	Cement Products	NO ASBESTOS	Cement Sheets	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68152	BA3528/09	950918	19/07/2018	WHS
#REF!	NAB	St.Lukes	19	Ceiling Board		Insulating Board	NO ASBESTOS	Unsealed Board	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68153	BA3528/10	950918	19/07/2018	WHS
#REF!	RAB	Longstone/Mullinure	05	Fire Break Panel	At High Level	Insulating Board	NO ASBESTOS	Unsealed Board	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68154	BA3530/01	950918	11/08/2018	WHS
#REF!	RAB	Longstone/Mullinure	05	Fuse Flash Guards		Textiles & Paper	Presumed Asbestos	Enclosed Fuse Flash Guards	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Medium Risk	8	25/03/2021	Presumed	Medium Risk	68155		981171	27/11/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	13	Roofing Felts		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68156	BS042992	932717	23/02/2018	WHS
#REF!	RAB	Longstone/Mullinure	05	Gaskets	Generator Exhaust	Textiles & Paper	Chrysotile	Sealed	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	4	25/03/2021	Identified	Very Low Risk	68157	BA3530/02	981171	27/11/2019	WHS
#REF!	RAB	Longstone/Mullinure	05	Packing	Generator Exhaust Packing	Thermal Insulation	Amosite/Chrysotile	Unsealed	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	High Risk	10	25/03/2021	Identified	Medium Risk	68158	BA3530/03	981171	27/11/2019	WHS
#REF!	RAB	Longstone/Mullinure	05	Bitumen Felt	Roof	Composite Material	NO ASBESTOS	Composite Materials	Very Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68159	BA3530/04	950918	11/08/2018	WHS
#REF!	RAB	Longstone/Mullinure	05		NIE Sub Station					Further investigation Required	Re-inspection	HSG227	Checked	High Risk	0				68160		981171	27/11/2019	WHS
#REF!	NAB	St.Lukes	29	Gaskets	Generator Exhaust	Textiles & Paper	Chrysotile	Sealed	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	4	24/02/2021	Identified	Very Low Risk	68161	BA3659/01	981171	03/01/2020	WHS
#REF!	SAA	Daisy Hill Hospital Estate	13	Board		Insulating Board	NO ASBESTOS	Encapsulated Spray or Lagging/Unsealed AIB	High	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68162	BS042993	932717	23/02/2018	WHS
#REF!	RAC	Tower Hill Site	06	Fuse Flash Guards		Textiles & Paper	Presumed Asbestos	Enclosed Fuse Flash Guards	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Medium Risk	8	25/03/2021	Presumed	Medium Risk	68163		981171	20/01/2020	WH Steohens

#REF!	RAC	Tower Hill Site	06	Gaskets	Generator Exhaust	Textiles & Paper	Chrysotile	Sealed	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	4	25/03/2021	Identified	Very Low Risk	68164	BA3505/01	9344/17	20/01/2020	WH Stephens
#REF!	SAA	Daisy Hill Hospital Estate	13	Floor Tiles		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Refurbishment Survey Uploaded	HSG227	Unchecked	Very Low Risk	3	26/09/2023	Identified	Very Low Risk	68165	BS042994	9300.2	20/04/2022	WHS
#REF!	RAC	Tower Hill Site	06	Damp Proof Course		Composite Material	NO ASBESTOS	Composite Material	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68166	BA3505/02	9344/17	04/06/2018	WH Stephens
#REF!	SAA	Daisy Hill Hospital Estate	13	Floor Tiles		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	26/09/2023	Strongly Presumed Similar to	Very Low Risk	68167	BS042994	9300.2	20/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	13	Floor Tiles		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	26/09/2023	Strongly Presumed Similar to	Very Low Risk	68168	BS042994	9300.2	20/04/2022	WHS
#REF!	RAC	Tower Hill Site	06	DPC Lining	Oil Tank Skids	Reinforced Composites	NO ASBESTOS	Composite Material	Medium	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68169	BA3505/03	9344/17	04/06/2018	WH Stephens
#REF!	SAA	Daisy Hill Hospital Estate	13	Floor Tiles		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	26/09/2023	Strongly Presumed Similar to	Very Low Risk	68170	BS042994	9300.2	20/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	13	Floor Tiles		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	26/09/2023	Strongly Presumed Similar to	Very Low Risk	68171	BS042994	9300.2	20/04/2022	WHS
#REF!	RAC	Tower Hill Site	06	Bitumen Felt	Roof	Composite Material	NO ASBESTOS	Composite Material	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68172	BA3505/04	9344/17	04/06/2018	WH Stephens
#REF!	SAA	Daisy Hill Hospital Estate	13	Floor Tiles		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	26/09/2023	Identified	Very Low Risk	68173	BS042995	9300.2	20/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	13	Floor Tiles		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	26/09/2023	Strongly Presumed Similar to	Very Low Risk	68174	BS042995	9300.2	20/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	13	Floor Tiles		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	26/09/2023	Strongly Presumed Similar to	Very Low Risk	68175	BS042995	9300.2	20/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	13	Floor Tiles		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	26/09/2023	Strongly Presumed Similar to	Very Low Risk	68176	BS042995	9300.2	20/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	13	Floor Tiles		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	26/09/2023	Strongly Presumed Similar to	Very Low Risk	68177	BS042995	9300.2	20/04/2022	WHS
#REF!	NAB	St.Lukes	16	Ceiling Board		Insulating Board	NO ASBESTOS	Partially Sealed Asbestos Insulation Board	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68178	BA3509/01	9506/18	19/07/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	13	Sink Pad		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	26/09/2023	Identified	Very Low Risk	68179	BS042996	9300.2	20/04/2022	WHS
#REF!	NAB	St.Lukes	16	Ceiling Board	Store	Insulating Board	NO ASBESTOS	Partially Sealed Asbestos Insulation Board	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68180	BA3509/01	9506/18	19/07/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	13	Sink Pad		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	26/09/2023	Strongly Presumed Similar to	Medium Risk	68181	BS042996	9300.2	20/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	13	Sink Pad		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	26/09/2023	Strongly Presumed Similar to	Very Low Risk	68182	BS042996	9300.2	20/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	13	Sink Pad		Composite Material	Chrysotile	Composite Materials	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	4	26/09/2023	Strongly Presumed Similar to	Very Low Risk	68183	BS042996	9300.2	20/04/2022	WHS
#REF!	NAB	St.Lukes	16	Fuse Flash Guards	Switch Room	Textiles & Paper	Presumed Asbestos	Enclosed Fuse Flash Guards	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Medium Risk	8	24/02/2021	Presumed	Medium Risk	68184		9512/1	03/01/2020	WHS
#REF!	SAA	Daisy Hill Hospital Estate	13	Toilet Cistern		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	Environtec	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68185	BS042997	9327/17	23/02/2018	WHS
#REF!	NAB	St.Lukes	16	Soffit Boards		Cement Products	Chrysotile	Cement Sheets	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	4	24/02/2021	Identified	Low Risk	68186	BA3509/02	9512/1	03/01/2020	WHS
#REF!	SAA	Daisy Hill Hospital Estate	13	Floor Tiles		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	26/09/2023	Strongly Presumed Similar to	Very Low Risk	68187	BS042995	9300.2	20/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	13	Floor Tiles		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	26/09/2023	Strongly Presumed Similar to	Very Low Risk	68188	BS042995	9300.2	20/04/2022	WHS
#REF!	NAB	St.Lukes	16	Bitumen Felt	Front Porch	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68189	BA3509/03	9506/18	19/07/2018	WHS
#REF!	NAB	St.Lukes	16	Bitumen Felt	Rear Porch	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68190	BA3509/03	9506/18	19/07/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	13	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	Asbestos Removed	68191	BS042995	9327/17	23/02/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	13	Floor Tiles		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	26/09/2023	Strongly Presumed Similar to	Very Low Risk	68192	BS042995	9300.2	20/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	13	Floor Tiles		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	20/09/2023	Strongly Presumed Similar to	Very Low Risk	68193	BS042995	9300.2	20/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	13	Floor Tiles		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	26/09/2023	Strongly Presumed Similar to	Very Low Risk	68194	BS042994	9300.2	20/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	13	Floor Tiles		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	26/09/2023	Strongly Presumed Similar to	Very Low Risk	68195	BS042994	9300.2	20/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	13	Floor Tiles		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	26/09/2023	Strongly Presumed Similar to	Very Low Risk	68196	BS042994	9300.2	20/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	13	Floor Tiles		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	26/09/2023	Strongly Presumed Similar to	Very Low Risk	68197	BS042994	9300.2	20/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	13	Floor Tiles		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	26/12/2022	Strongly Presumed Similar to	Very Low Risk	68198	BS042994	9300.2	20/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	13	Floor Tiles		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	26/09/2023	Strongly Presumed Similar to	Very Low Risk	68199	BS042994	9300.2	20/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	13	Floor Tiles		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	26/09/2023	Strongly Presumed Similar to	Very Low Risk	68200	BS042994	9300.2	20/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	13	Floor Tiles		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	26/09/2023	Identified	Very Low Risk	68201	BS042998	9300.2	20/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	13	Floor Tiles		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	26/12/2022	Strongly Presumed Similar to	Very Low Risk	68202	BS042998	9300.2	20/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	13	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	22/03/2014	Strongly Presumed Similar to	Asbestos Removed	68203	BS042995	9327/17	23/02/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	13	Floor Tiles		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	26/09/2023	Strongly Presumed Similar to	Very Low Risk	68204	BS042995	9300.2	20/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	13	Floor Tiles		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	26/09/2023	Strongly Presumed Similar to	Very Low Risk	68205	BS042995	9300.2	20/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	13	Floor Tiles		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	26/09/2023	Strongly Presumed Similar to	Very Low Risk	68206	BS042995	9300.2	20/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	13	Floor Tiles		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	26/09/2023	Strongly Presumed Similar to	Very Low Risk	68207	BS042995	9300.2	20/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	13	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	Asbestos Removed	68208	BS042995	9327/17	23/02/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	13	Gaskets		Textiles & Paper	NO ASBESTOS	Encapsulated Spray or Laconin/Unsealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68209	BS042999	9327/17	23/02/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	13	Verge Cloak		Cement Products	Presumed Asbestos	Encased Spray or	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Low Risk	6	26/09/2023	Presumed	Low Risk	68210		9300.2	20/04/2022	WHS
#REF!	RAB	Lonpstone/Mullinure	10	Artificial Slate	Roof	Cement Products	Chrysotile	Cement Sheets	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	4	27/03/2021	Identified	Very Low Risk	68211	BA3531/01	9512/1	27/11/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	13	Bitumen Felt		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68212	BS043000	9327/17	23/02/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	13	Fuse Flash Guards		Textiles & Paper	Presumed Asbestos	Encapsulated Spray or Laconin/Unsealed AIB	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Medium Risk	9	26/03/2023	Presumed	Medium Risk	68213		9300.2	20/04/2022	WHS
#REF!	RJC	Armagh Resource Centre	01	Ceiling Tiles		Insulating Board	NO ASBESTOS	Unsealed Board	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68216	BA3605/01	9506/18	28/02/2019	WHS
#REF!	RJC	Armagh Resource Centre	01	Ceiling Tiles		Insulating Board	NO ASBESTOS	Unsealed Board	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68217	BA3605/01	9506/18	28/02/2019	WHS
#REF!	RJC	Armagh Resource Centre	01	Ceiling Tiles		Insulating Board	NO ASBESTOS	Unsealed Board	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68218	BA3605/01	9506/18	28/02/2019	WHS
#REF!	RJC	Armagh Resource Centre	01	Ceiling Tiles		Insulating Board	NO ASBESTOS	Unsealed Board	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68219	BA3605/01	9506/18	28/02/2019	WHS
#REF!	RJC	Armagh Resource Centre	01	Ceiling Tiles		Insulating Board	NO ASBESTOS	Unsealed Board	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68220	BA3605/01	9506/18	28/02/2019	WHS
#REF!	RJC	Armagh Resource Centre	01	Ceiling Tiles		Insulating Board	NO ASBESTOS	Unsealed Board	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68221	BA3605/01	9506/18	28/02/2019	WHS
#REF!	RJC	Armagh Resource Centre	01	Ceiling Tiles		Insulating Board	NO ASBESTOS	Unsealed Board	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68222	BA3605/01	9506/18	28/02/2019	WHS
#REF!	RJC	Armagh Resource Centre	01	Ceiling Tiles		Insulating Board	NO ASBESTOS	Unsealed Board	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68223	BA3605/01	9506/18	28/02/2019	WHS
#REF!	RJC	Armagh Resource Centre	01	Ceiling Tiles		Insulating Board	NO ASBESTOS	Unsealed Board	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68224	BA3605/01	9506/18	28/02/2019	WHS
#REF!	RJC	Armagh Resource Centre	01	Fuse Flash Guards		Textiles & Paper	Chrysotile	Enclosed Fuse Flash Guards	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Low Risk	6	03/04/2021	Identified	Low Risk	68225	BA9520	9512/1	20/11/2019	WHS
#REF!	RJC	Armagh Resource Centre	01	Fuse Flash Guards		Textiles & Paper	Presumed Asbestos	Enclosed Fuse Flash Guards	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Medium Risk	8	03/04/2021	Presumed	Medium Risk	68226		9512/1	20/11/2019	WHS
#REF!	RJC	Armagh Resource Centre	01	Fuse Flash Guards		Textiles & Paper	Presumed Asbestos	Enclosed Fuse Flash Guards	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Medium Risk	8	03/04/2021	Presumed	Medium Risk	68227		9512/1	20/11/2019	WHS
#REF!	RJC	Armagh Resource Centre	01	Door Panel	Board to Back of Door	Insulating Board	NO ASBESTOS	Encapsulated Spray or Laconin/Unsealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68228	BA3605/02	9506/18	28/02/2019	WHS
#REF!	RJC	Armagh Resource Centre	01	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68229	BA3605/03	9506/18	28/02/2019	WHS
#REF!	RJC	Armagh Resource Centre	01	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68230	BA3605/03	9506/18	28/02/2019	WHS
#REF!	RJC	Armagh Resource Centre	01	Cylinder insulation		Thermal Insulation	NO ASBESTOS	Unsealed	Medium	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68231	BA3605/04	9506/18	28/02/2019	WHS
#REF!	RJC	Armagh Resource Centre	01	Ceiling Board		Insulating Board	NO ASBESTOS	Unsealed Board	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68232	BA3605/05	9506/18	28/02/2019	WHS
#REF!	RJC	Armagh Resource Centre	01	Ceiling Board		Insulating Board	NO ASBESTOS	Unsealed Board	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68233	BA3605/05	9506/18	28/02/2019	WHS
#REF!	RJC	Armagh Resource Centre	01	Wall Panels		Insulating Board	NO ASBESTOS	Unsealed Board	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68234	BA3605/06	9506/18	28/02/2019	WHS
#REF!	RJC	Armagh Resource Centre	01	Wall Panels		Insulating Board	NO ASBESTOS	Unsealed Board	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68235	BA3605/06	9506/18	28/02/2019	WHS
#REF!	RJC	Armagh Resource Centre	01	Stair Nosing		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68236	BA3605/07	9506/18	28/02/2019	WHS
#REF!	RJC	Armagh Resource Centre	01	Thermal Insulation	Internal Insulation to Boiler	Thermal Insulation	Presumed Asbestos	Encased	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Medium Risk	8	03/04/2021	Presumed	Medium Risk	68237		9512/1	20/11/2019	WHS
#REF!	RJC	Armagh Resource Centre	01	Gaskets	To Pipework	Textiles & Paper	Chrysotile	Sealed	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	4	03/04/2021	Identified	Very Low Risk	68238	BA3605/08	9512/1	20/11/2019	WHS
#REF!	RJC	Armagh Resource Centre	01	Ceiling Board		Insulating Board	NO ASBESTOS	Unsealed Board	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68239	BA3605/09	9506/18	28/02/2019	WHS
#REF!	RAB	Lonpstone/Mullinure	39	Fuse Flash Guards	Floor /Loose\	Textiles & Paper	Chrysotile	Unsealed	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Medium Risk	7	25/03/2021	Identified	Medium Risk	68240	BA3596/01	9512/1	27/11/2019	WHS
#REF!	SBB	Crossmaglen Health Centre	01	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	4	21/09/2023	Identified	Very Low Risk	68241	BA3409/01	9300.2	01/06/2022	WHS
#REF!	SBB	Crossmaglen Health Centre	01	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	21/09/2023	Strongly Presumed Similar to	Very Low Risk	68242	BA3409/01	9300.2	01/06/2022	WHS
#REF!	SBB	Crossmaglen Health Centre	01	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	21/09/2023	Strongly Presumed Similar to	Very Low Risk	68243	BA3409/01	9300.2	01/06/2022	WHS
#REF!	SBB	Crossmaglen Health Centre	01	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	21/09/2023	Strongly Presumed Similar to	Very Low Risk	68244	BA3409/01	9300.2	01/06/2022	WHS
#REF!	SBB	Crossmaglen Health Centre	01	Floor Tile and Bitumen Adhesive		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	Asbestos Removed	68245	BA3409/01	9327/17	04/04/2018	WHS
#REF!	SBB	Crossmaglen Health Centre	01	Floor Tile and Bitumen Adhesive	Male WC changed to store	Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	21/09/2023	Strongly Presumed Similar to	Very Low Risk	68246	BA3409/01	9300.2	01/06/2022	WHS
#REF!	SBB	Crossmaglen Health Centre	01	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	21/09/2023	Strongly Presumed Similar to	Very Low Risk	68247	BA3409/01	9300.2	01/06/2022	WHS
#REF!	SBB	Crossmaglen Health Centre	01	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	21/09/2023	Strongly Presumed Similar to	Very Low Risk	68248	BA3409/01	9300.2	01/06/2022	WHS
#REF!	SBB	Crossmaglen Health Centre	01	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	21/09/2023	Strongly Presumed Similar to	Very Low Risk	68249	BA3409/01	9300.2	01/06/2022	WHS
#REF!	SBB	Crossmaglen Health Centre	01	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	21/09/2023	Strongly Presumed Similar to	Very Low Risk	68250	BA3409/01	9300.2	01/06/2022	WHS
#REF!	SBB	Crossmaglen Health Centre	01	Floor Tile and Bitumen Adhesive		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	04/04/2019	Strongly Presumed Similar to	Asbestos Removed	68251	BA3409/01	9327/17	04/04/2018	WHS
#REF!	SBB	Crossmaglen Health Centre	01	Lino Flooring		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68252	BA3409/02	9327/17	04/04/2018	WHS
#REF!	SBB	Crossmaglen Health Centre	01	Sink Pad		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	21/09/2023	Identified	Very Low Risk	68253	BA3409/03	9300.2	01/06/2022	WHS
#REF!	SBB	Crossmaglen Health Centre	01	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	04/04/2019	Strongly Presumed Similar to	Asbestos Removed	68254	BA3409/03	9327/17	04/04/2018	WHS
#REF!	SBB	Crossmaglen Health Centre	01	Stair Nosing		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	21/09/2023	Identified	Very Low Risk	68255	BA3409/04	9300.2	01/06/2022	WHS
#REF!	SBB	Crossmaglen Health Centre	01	Debris	Tank Room	Insulating Board	NO ASBESTOS	Encapsulated Spray or Laconin/Unsealed AIB	Loose asbestos debris or residue	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	10/04/2018	Identified	Asbestos Removed	68256	BA3409/05	9327/17	04/04/2018	WHS
#REF!	SBB	Crossmaglen Health Centre	01	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	21/09/2023	Identified	Very Low Risk	68257	BA3409/06	9300.2	01/06/2022	WHS
#REF!	SBB	Crossmaglen Health Centre	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68258	BA3409/07	9327/17	04/04/2018	WHS
#REF!	SBB	Crossmaglen Health Centre	01	Sink Pad		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	21/09/2023	Identified	Very Low Risk	68259	BA3409/08	9300.2	01/06/2022	WHS
#REF!	SBB	Crossmaglen Health Centre	01	Floor Tile and Bitumen Adhesive		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	Asbestos Removed	68260	BA3409/09	9327/17	04/04/2018	WHS
#REF!	SBB	Crossmaglen Health Centre	01	Floor Tile and Bitumen Adhesive		Composite Material	NO ASBESTOS

#REF!	SBB	Crossmaglen Health Centre	01	Floor Tile and Bitumen Adhesive	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	Asbestos Removed	68265	BA3409/10	93271/7	04/04/2018	WHS
#REF!	SBB	Crossmaglen Health Centre	01	Floor Tile and Bitumen Adhesive	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	04/04/2019	Identified	Asbestos Removed	68266	BA3409/11	93271/7	04/04/2018	WHS
#REF!	SBB	Crossmaglen Health Centre	01	Sink Pad	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68267	BA3409/12	93271/7	04/04/2018	WHS
#REF!	SBB	Crossmaglen Health Centre	01	Sink Pad	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	Asbestos Removed	68268	BA3409/13	93271/7	04/04/2018	WHS
#REF!	SBB	Crossmaglen Health Centre	01	Toilet Cistern	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	Asbestos Removed	68269	BA3409/14	93271/7	04/04/2018	WHS
#REF!	SBB	Crossmaglen Health Centre	01	Sink Pad	Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	21/09/2023	Identified	Very Low Risk	68270	BA3409/15	93271/7	12/09/2022	WHS
#REF!	SBB	Crossmaglen Health Centre	01	Sink Pad	Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	21/09/2023	Stronnly Presumed Similar to	Very Low Risk	68271	BA3409/15	93271/7	01/06/2022	WHS
#REF!	SBB	Crossmaglen Health Centre	01	Floor Tile and Bitumen Adhesive	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	Asbestos Removed	68272	BA3409/09	93271/7	04/04/2018	WHS
#REF!	SBB	Crossmaglen Health Centre	01	Floor Tile and Bitumen Adhesive	Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	21/09/2023	Stronnly Presumed Similar to	Very Low Risk	68273	BA3409/09	93271/7	01/06/2022	WHS
#REF!	SBB	Crossmaglen Health Centre	01	Floor Tile and Bitumen Adhesive	Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	21/09/2023	Strongly Presumed Similar to	Very Low Risk	68274	BA3409/09	93271/7	01/06/2022	WHS
#REF!	SBB	Crossmaglen Health Centre	01	Bitumen Felt	Composite Material	NO ASBESTOS	Composite Materials	Medium	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68275	BA3409/16	93271/7	04/04/2018	WHS
#REF!	SBE	Rathfriland Health Centre & Library	01	Sink Pad	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68276	BA3401/01	93271/7	23/04/2018	WH Stephens
#REF!	SBE	Rathfriland Health Centre & Library	01	Seal	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68277	BA3401/02	93271/7	23/04/2018	WH Stephens
#REF!	SBE	Rathfriland Health Centre & Library	01	Seal	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68278	BA3401/02	93271/7	23/04/2018	WH Stephens
#REF!	SBE	Rathfriland Health Centre & Library	01	Seal	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68279	BA3401/02	93271/7	23/04/2018	WH Stephens
#REF!	SBE	Rathfriland Health Centre & Library	01	Seal	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68280	BA3401/02	93271/7	23/04/2018	WH Stephens
#REF!	SBE	Rathfriland Health Centre & Library	01	Seal	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68281	BA3401/02	93271/7	23/04/2018	WH Stephens
#REF!	SBE	Rathfriland Health Centre & Library	01	Seal	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68282	BA3401/02	93271/7	23/04/2018	WH Stephens
#REF!	SBE	Rathfriland Health Centre & Library	01	Sink Pad	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68283	BA3401/03	93271/7	23/04/2018	WH Stephens
#REF!	SBE	Rathfriland Health Centre & Library	01	Sink Pad	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68284	BA3401/03	93271/7	23/04/2018	WH Stephens
#REF!	SBE	Rathfriland Health Centre & Library	01	Seal	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68285	BA3401/02	93271/7	23/04/2018	WH Stephens
#REF!	SBE	Rathfriland Health Centre & Library	01	Seal	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68286	BA3401/02	93271/7	23/04/2018	WH Stephens
#REF!	SBE	Rathfriland Health Centre & Library	01	Seal	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68287	BA3401/02	93271/7	23/04/2018	WH Stephens
#REF!	SBE	Rathfriland Health Centre & Library	01	Seal	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68288	BA3401/02	93271/7	23/04/2018	WH Stephens
#REF!	SBE	Rathfriland Health Centre & Library	01	Seal	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68289	BA3401/02	93271/7	23/04/2018	WH Stephens
#REF!	SBE	Rathfriland Health Centre & Library	01	Gaskets	Textiles & Paper	NO ASBESTOS	Encapsulated Spray or Lagoino/Unsealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68290	BA3401/04	93271/7	23/04/2018	WH Stephens
#REF!	SBE	Rathfriland Health Centre & Library	01	Ceiling Board	Insulating Board	NO ASBESTOS	Encapsulated Spray or Lagoino/Unsealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68291	BA3401/05	93271/7	23/04/2018	WH Stephens
#REF!	SBE	Rathfriland Health Centre & Library	01	Fuse Flash Guards	Textiles & Paper	Presumed Asbestos	Encapsulated Spray or Lagoino/Unsealed AIB	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Medium Risk	9	12/03/2023	Presumed	Medium Risk	68292		93092/2	07/09/2022	WHS
#REF!	SBE	Rathfriland Health Centre & Library	01	Lining Panels	Insulating Board	Presumed Asbestos	Encapsulated Spray or Lagoino/Unsealed AIB	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Medium Risk	9	12/03/2023	Presumed	Medium Risk	68293		93092/2	02/09/2022	WHS
#REF!	SBE	Rathfriland Health Centre & Library	01						Re-Survey	Re-inspection	HSG227	Checked	High Risk	0	12/12/2022			68294		93092/2	07/09/2022	WHS
#REF!	SBE	Rathfriland Health Centre & Library	01	NO ASBESTOS	NO ASBESTOS	NO ASBESTOS	Composite Material	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	26/04/2019	Identified	No Asbestos Detected	68295		93271/7	23/04/2018	WH Stephens
#REF!	SBE	Rathfriland Health Centre & Library	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	68296		93271/7	23/04/2018	WH Stephens
#REF!	SBE	Rathfriland Health Centre & Library	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	68297		93271/7	23/04/2018	WH Stephens
#REF!	SBE	Rathfriland Health Centre & Library	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	68298		93271/7	23/04/2018	WH Stephens
#REF!	SBE	Rathfriland Health Centre & Library	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	68299		93271/7	23/04/2018	WH Stephens
#REF!	SBE	Rathfriland Health Centre & Library	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	68300		93271/7	23/04/2018	WH Stephens
#REF!	SBF	Warrenpoint Health Centre & Library	01	Seal	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68301	BA3400/01	95061/8	07/10/2018	WHS
#REF!	SBF	Warrenpoint Health Centre & Library	01	Seal	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68302	BA3400/01	95061/8	07/10/2018	WHS
#REF!	SBF	Warrenpoint Health Centre & Library	01	Seal	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68303	BA3400/01	95061/8	07/10/2018	WHS
#REF!	SBF	Warrenpoint Health Centre & Library	01	Seal	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68304	BA3400/01	95061/8	07/10/2018	WHS
#REF!	SBF	Warrenpoint Health Centre & Library	01	Seal	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68305	BA3400/01	95061/8	07/10/2018	WHS
#REF!	SBF	Warrenpoint Health Centre & Library	01	Seal	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68306	BA3400/01	95061/8	07/10/2018	WHS
#REF!	SBF	Warrenpoint Health Centre & Library	01	Sink Pad	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68307	BA3400/02	95061/8	07/10/2018	WHS
#REF!	SBF	Warrenpoint Health Centre & Library	01	Stair Nosing	Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	09/11/2023	Identified	Very Low Risk	68308	BA3400/03	93092/2	01/06/2022	WHS
#REF!	SBF	Warrenpoint Health Centre & Library	01	Seal	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68309	BA3400/01	95061/8	07/10/2018	WHS
#REF!	SBF	Warrenpoint Health Centre & Library	01	Seal	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68310	BA3400/01	95061/8	07/10/2018	WHS
#REF!	SBF	Warrenpoint Health Centre & Library	01	Seal	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68311	BA3400/01	95061/8	07/10/2018	WHS
#REF!	SBF	Warrenpoint Health Centre & Library	01	Seal	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68312	BA3400/01	95061/8	07/10/2018	WHS
#REF!	SBF	Warrenpoint Health Centre & Library	01	Seal	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68313	BA3400/01	95061/8	07/10/2018	WHS
#REF!	SBF	Warrenpoint Health Centre & Library	01	Seal	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68314	BA3400/01	95061/8	07/10/2018	WHS
#REF!	SBF	Warrenpoint Health Centre & Library	01	Toilet Cistern	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68315	BA3400/04	95061/8	07/10/2018	WHS
#REF!	SBF	Warrenpoint Health Centre & Library	01	Sink Pad	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68316	BA3400/05	95061/8	07/10/2018	WHS
#REF!	SBF	Warrenpoint Health Centre & Library	01	Bitumen Felt	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68317	BA3400/06	95061/8	07/10/2018	WHS
#REF!	SBF	Warrenpoint Health Centre & Library	01						Further investisation Recuired	Review – No Change	HSG227	Checked	High Risk	0				68318		95061/8	13/11/2019	WH Stephens
#REF!	SJJ	Cedar Grove Site	02	Undercloak	Cement Products	Presumed Asbestos	Cement Sheets	None	Label & Manage	Re-inspection	HSG227	Unchecked	Low Risk	5	14/09/2023	Presumed	Low Risk	68319		93092/2	31/08/2022	WHS
#REF!	SJJ	Cedar Grove Site	02	Undercloak	Cement Products	Presumed Asbestos	Cement Sheets	None	Apply Caution when Maintaining	Re-inspection	HSG227	Unchecked	Low Risk	5	14/09/2023	Presumed	Low Risk	68320		93092/2	31/08/2022	WHS
#REF!	SJD	Rathfriland Road Site	05	Roof Slate	Cement Products	Chrysotile	Cement Sheets	None	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	13/09/2023	Identified	Very Low Risk	68321	BA3557/01	93092/2	31/08/2022	WHS
#REF!	SJD	Rathfriland Road Site	03	Stair Nosing	Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68322	BA3556/01	93271/7	04/04/2018	WHS
#REF!	SJD	Rathfriland Road Site	03	Sink Pad	Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68323	BA3556/02	93271/7	04/04/2018	WHS
#REF!	SJD	Rathfriland Road Site	03	Ceiling Board	Insulating Board	NO ASBESTOS	Encapsulated Spray or Lagoino/Unsealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68324	BA3556/03	93271/7	04/04/2018	WHS
#REF!	SHC	Sleve Roe	02	Board	Insulating Board	NO ASBESTOS	Encapsulated Spray or Lagoino/Unsealed AIB	Significant areas of damage or	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	Asbestos Removed	68325	BA3572/01	95061/8	14/02/2019	WHS
#REF!	SHC	Sleve Roe	02	Undercloak	Cement Products	Chrysotile	Cement Sheets	None	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	12/09/2023	Identified	Very Low Risk	68326	BA3572/02	93092/2	30/08/2022	WHS
#REF!	SHC	Sleve Roe	02	Sink Pad	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68327	BA3572/03	95061/8	14/02/2019	WHS
#REF!	SHA	Drumalane Estate	09	Wall Panels	Insulating Board	NO ASBESTOS	Enclosed Spray or Lagoino/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68328	BA3320-01	93271/7	26/04/2018	WH Stephens
#REF!	SHA	Drumalane Estate	09	Toilet Cistern	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (Asbestos removed)	ACM Removed	HSG227	Unchecked	NO ASBESTOS	0		Identified	Asbestos Removed	68329	BA3320-02	93271/7	26/04/2018	WH Stephens
#REF!	SHA	Drumalane Estate	09	Sash Cord	Textiles & Paper	NO ASBESTOS	Encapsulated Spray or Lagoino/Unsealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68330	BA3320-03	93271/7	26/04/2018	WH Stephens
#REF!	SHA	Drumalane Estate	09	Bitumen Paints	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68331	BA3320-04	93271/7	26/04/2018	WH Stephens
#REF!	SHA	Drumalane Estate	09	Stair Nosing	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68332	BA3320-05	93271/7	26/04/2018	WH Stephens
#REF!	SHA	Drumalane Estate	09	Toilet Cistern	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68333	BA3320-06	93271/7	26/04/2018	WH Stephens
#REF!	SHA	Drumalane Estate	09	Toilet Cistern	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68334	BA3320-06	93271/7	26/04/2018	WH Stephens
#REF!	SHA	Drumalane Estate	09	Door Panel	Insulating Board	NO ASBESTOS	Enclosed Spray or Lagoino/Sealed AIB	Low	No further action required (Asbestos removed)	ACM Removed	HSG227	Unchecked	NO ASBESTOS	0		Identified	Asbestos Removed	68335	BA3320-07	93271/7	26/04/2018	WH Stephens
#REF!	SHA	Drumalane Estate	09	Door Panel	Insulating Board	Amosite	Enclosed Spray or	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Low Risk	6	14/09/2023	Strongly Presumed Similar to	Low Risk	68336	BA3320-07	93092/2	06/04/2022	WHS
#REF!	SHA	Drumalane Estate	09	Door Panel	Insulating Board	Amosite	Enclosed Spray or Lagoino/Sealed AIB	Low	Label and Remove if likely to be disturbed	Re-inspection	HSG227	Unchecked	Low Risk	6	14/09/2023	Strongly Presumed Similar to	Low Risk	68337	BA3320-07	93092/2	06/04/2022	WHS
#REF!	SHA	Drumalane Estate	09	Door Panel	Insulating Board	Amosite	Enclosed Spray or	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Low Risk	6	14/09/2023	Strongly Presumed Similar to	Low Risk	68338	BA3320-07	93092/2	06/04/2022	WHS
#REF!	SHA	Drumalane Estate	09	Door Panel	Insulating Board	Amosite	Enclosed Spray or	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Low Risk	6	14/09/2023	Strongly Presumed Similar to	Low Risk	68339	BA3320-07	93092/2	06/04/2022	WHS
#REF!	SHA	Drumalane Estate	09	Fire Linino Board	Cement Products	Chrysotile	Enclosed Spray or	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	4	14/09/2023	Identified	Very Low Risk	68340	BA3320-08	93092/2	06/04/2022	WHS
#REF!	SHA	Drumalane Estate	09	Back Board	Insulating Board	NO ASBESTOS	Encapsulated Spray or Lagoino/Unsealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68341	BA3320-09	93271/7	26/04/2018	WH Stephens
#REF!	SHA	Drumalane Estate	09	Stair Nosing	Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	14/09/2023	Identified	Very Low Risk	68342	BA3320-10	93092/2	06/04/2022	WHS
#REF!	SHA	Drumalane Estate	09	Door Panel	Insulating Board	Amosite	Enclosed Spray or	Low	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	Low Risk	6	14/09/2023	Identified	Low Risk	68343	BA3320-11	93092/2	12/11/2019	WHS
#REF!	SHA	Drumalane Estate	09	Door Panel	Insulating Board	Amosite		Low	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	Low Risk	6	14/09/2023	Stronnly Presumed Similar to	Low Risk	68344	BA3320-11	93092/2	06/04/2022	WHS
#REF!	SHA	Drumalane Estate	09	Fire Door	Insulating Board	Presumed Asbestos	Encapsulated Spray or Lagoino/Unsealed AIB	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Medium Risk	9	14/03/2023	Presumed	Medium Risk	68345		93092/2	06/04/2022	WHS

#REF!	SJJ	Cedar Grove Site	01	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68346	BA3570/01	9327/17	04/08/2018	WH Stephens
#REF!	SJJ	Cedar Grove Site	01	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68347	BA3570/01	9327/17	04/08/2018	WH Stephens
#REF!	SJJ	Cedar Grove Site	01	Gaskets		Textiles & Paper	NO ASBESTOS	Encapsulated Spray or Lagoins/Unsealed AIB	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68348	BA3570/02	9327/17	04/08/2018	WH Stephens
#REF!	SJJ	Cedar Grove Site	01	Undercloak		Cement Products	NO ASBESTOS	Cement Sheets	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68349	BA3570/03	9327/17	04/08/2018	WH Stephens
#REF!	SHA	Drumalaire Estate	02	Board	Pipe Crawl Space	Insulating Board	Amosite/Chrysotile	Encapsulated Spray or Lagoins/Unsealed AIB	Significant areas of damage or	Repair, Encapsulate & Manage	Review – No Change	HSG227	Unchecked	Medium Risk	9	10/07/2021	Identified	Medium Risk	68350	BA3559/01	9811/19	11/11/2019	WH Stephens
#REF!	SHA	Drumalaire Estate	02	Board		Insulating Board	Amosite/Chrysotile	Encapsulated Spray or Lagoins/Unsealed AIB	Significant areas of damage or	Encapsulate exposed surfaces and remove debris	Review – No Change	HSG227	Unchecked	Medium Risk	9	10/07/2021	Identified	Medium Risk	68351	BA3559/02	9811/19	11/11/2019	WH Stephens
#REF!	SAA	Daisy Hill Hospital Estate	00	Pipe Insulation		Thermal Insulation	NO ASBESTOS	Unsealed Spray / Lagging / Dust Debris	High	No further action required (No Asbestos Detected)	Original Survey Data	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68352	BA3289/01			
#REF!	SAA	Daisy Hill Hospital Estate	00	Insulating Debris		General Debris	NO ASBESTOS	Unsealed Spray / Lagging / Dust Debris	High	No further action required (No Asbestos Detected)	Original Survey Data	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68353	BA3289/02			
#REF!	SAA	Daisy Hill Hospital Estate	00	Gaskets		Textiles & Paper	NO ASBESTOS	Encapsulated Spray or Lagoins/Unsealed AIB	Medium	No further action required (No Asbestos Detected)	Original Survey Data	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68354	BA3289/03			
#REF!	SHC	Sliewe Roe	03	Ceiling Board		Insulating Board	Amosite/Chrysotile	Encapsulated Spray or Lagoins/Unsealed AIB	High	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	Medium Risk	9	12/12/2022	Identified	High Risk	68355	BA3558/01	9309/22	30/08/2022	WHS
#REF!	SHC	Sliewe Roe	03	Duct Access Panels		Insulating Board	Amosite/Chrysotile	Encapsulated Spray or Lagoins/Unsealed AIB	Medium	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	Medium Risk	8	12/12/2022	Strongly Presumed Similar to	High Risk	68356	BA3558/01	9309/22	30/08/2022	WHS
#REF!	SHC	Sliewe Roe	03	Undercloak		Cement Products	Chrysotile	Encapsulated Spray or	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	4	12/09/2023	Identified	Very Low Risk	68357	BA3558/02	9309/22	30/08/2022	WHS
#REF!	SHC	Sliewe Roe	03	Roofing Felts		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68358	BA3558/03	9506/18	14/03/2019	WHS
#REF!	SBA	John Mitchel Place	01	Back Board		Insulating Board	NO ASBESTOS	Encapsulated Spray or Lagoins/Unsealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68359	BA3630/01	9506/18	27/07/2018	WHS
#REF!	SBA	John Mitchel Place	01	Toilet Cistern		Composite Material	Amosite	Composite Materials	Low	Conduct annual routine inspections	Review – No Change	HSG227	Unchecked	Very Low Risk	4	06/10/2021	Identified	Very Low Risk	68360	BA3630/02	9811/19	27/01/2020	WH Stephens
#REF!	SBA	John Mitchel Place	01	Toilet Cistern		Composite Material	Amosite	Composite Materials	Low	Conduct annual routine inspections	Review – No Change	HSG227	Unchecked	Very Low Risk	4	06/10/2021	Strongly Presumed Similar to	Very Low Risk	68361	BA3630/02	9811/19	27/01/2020	WH Stephens
#REF!	SBA	John Mitchel Place	01	Toilet Cistern		Composite Material	Amosite	Composite Materials	Low	Conduct annual routine inspections	Review – No Change	HSG227	Unchecked	Very Low Risk	4	06/10/2021	Strongly Presumed Similar to	Very Low Risk	68362	BA3630/02	9811/19	27/01/2020	WH Stephens
#REF!	SBA	John Mitchel Place	01	Toilet Cistern		Composite Material	Amosite	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	4	15/09/2023	Strongly Presumed Similar to	Very Low Risk	68363	BA3630/02	9309/22	06/04/2022	WHS
#REF!	SBA	John Mitchel Place	01	Toilet Cistern		Composite Material	Amosite	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	4	15/09/2023	Strongly Presumed Similar to	Very Low Risk	68364	BA3630/02	9309/22	06/04/2022	WHS
#REF!	SBA	John Mitchel Place	01	Toilet Cistern		Composite Material	Amosite	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	4	15/09/2023	Strongly Presumed Similar to	Very Low Risk	68365	BA3630/02	9309/22	06/04/2022	WHS
#REF!	SBA	John Mitchel Place	01	Toilet Cistern		Composite Material	Amosite	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	4	15/09/2023	Strongly Presumed Similar to	Very Low Risk	68366	BA3630/02	9309/22	06/04/2022	WHS
#REF!	SBA	John Mitchel Place	01	Toilet Cistern		Composite Material	Amosite	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	4	15/09/2023	Strongly Presumed Similar to	Very Low Risk	68367	BA3630/02	9309/22	06/04/2022	WHS
#REF!	SBA	John Mitchel Place	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	08/02/2019	Identified	Asbestos Removed	68368	BA3630/03	9506/18	27/07/2018	WHS
#REF!	SBA	John Mitchel Place	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	08/02/2019	Identified	Asbestos Removed	68369	BA3630/03	9506/18	27/07/2018	WHS
#REF!	SBA	John Mitchel Place	01	Floor Tiles		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Review – No Change	HSG227	Unchecked	Very Low Risk	3	06/10/2021	Identified	Very Low Risk	68370	BA3630/03	9811/19	27/01/2020	WH Stephens
#REF!	SBA	John Mitchel Place	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	08/02/2019	Identified	Asbestos Removed	68371	BA3630/03	9506/18	27/07/2018	WHS
#REF!	SBA	John Mitchel Place	01	Floor Tiles		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Review – No Change	HSG227	Unchecked	Very Low Risk	3	06/10/2021	Identified	Very Low Risk	68372	BA3630/03	9811/19	27/01/2020	WH Stephens
#REF!	SBA	John Mitchel Place	01	Floor Tiles		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Review – No Change	HSG227	Unchecked	Very Low Risk	3	06/10/2021	Identified	Very Low Risk	68373	BA3630/03	9811/19	27/01/2020	WH Stephens
#REF!	SBA	John Mitchel Place	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	08/02/2019	Identified	Asbestos Removed	68374	BA3630/03	9506/18	27/07/2018	WHS
#REF!	SBA	John Mitchel Place	01	Ceiling Panelling		Insulating Board	NO ASBESTOS	Encapsulated Spray or Lagoins/Unsealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68375	BA3630/04	9506/18	27/07/2018	WHS
#REF!	SBA	John Mitchel Place	01	Floor Tiles		Composite Material	Chrysotile	Composite Materials	Low	Re-Survey	Review – No Change	HSG227	Checked	High Risk	3	06/10/2021	Identified	Very Low Risk	68376	BA3630/05	9811/19	27/01/2020	WH Stephens
#REF!	SBA	John Mitchel Place	01	Floor Tiles		Composite Material	Chrysotile	Composite Materials	Low	Re-Survey	Review – No Change	HSG227	Checked	High Risk	3	06/10/2021	Identified	Very Low Risk	68377	BA3630/06	9811/19	27/01/2020	WH Stephens
#REF!	SBA	John Mitchel Place	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	08/02/2019	Identified	Asbestos Removed	68378	BA3630/07	9506/18	27/07/2018	WHS
#REF!	SBA	John Mitchel Place	01	Stair Nosing		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68379	BA3630/08	9506/18	27/07/2018	WHS
#REF!	SBA	John Mitchel Place	01	Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	15/09/2023	Identified	Very Low Risk	68380	BA3630/09	9309/22	06/04/2022	WHS
#REF!	SBA	John Mitchel Place	01	Panel		Cement Products	Chrysotile	Cement Sheets	Medium	Conduct annual routine inspections	Review – No Change	HSG227	Unchecked	Low Risk	5	06/10/2021	Identified	Low Risk	68381	BA3630/10	9811/19	27/01/2020	WH Stephens
#REF!	SBA	John Mitchel Place	01	Ceiling Board		Insulating Board	NO ASBESTOS	Enclosed Spray or Lagoins/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68382	BA3630/11	9506/18	27/07/2018	WHS
#REF!	SBA	John Mitchel Place	01	Ceiling Board		Insulating Board	NO ASBESTOS	Enclosed Spray or Lagoins/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68383	BA3630/11	9506/18	27/07/2018	WHS
#REF!	SBA	John Mitchel Place	01	Ceiling Board		Insulating Board	NO ASBESTOS	Enclosed Spray or Lagoins/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68384	BA3630/11	9506/18	27/07/2018	WHS
#REF!	SBA	John Mitchel Place	01	Ceiling Board		Insulating Board	NO ASBESTOS	Enclosed Spray or Lagoins/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68385	BA3630/11	9506/18	27/07/2018	WHS
#REF!	SBA	John Mitchel Place	01	Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	15/09/2023	Identified	Very Low Risk	68386	BA3630/12	9309/22	06/04/2022	WH Stephens
#REF!	SBA	John Mitchel Place	01	Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	15/09/2023	Strongly Presumed Similar to	Very Low Risk	68387	BA3630/12	9309/22	06/04/2022	WH Stephens
#REF!	SBA	John Mitchel Place	01	Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	15/09/2023	Strongly Presumed Similar to	Very Low Risk	68388	BA3630/12	9309/22	06/04/2022	WH Stephens
#REF!	SBA	John Mitchel Place	01	Floor Tiles		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	15/09/2023	Identified	Very Low Risk	68389	BA3630/13	9309/22	06/04/2022	WHS
#REF!	SBA	John Mitchel Place	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68390	BA3630/14	9506/18	27/07/2018	WHS
#REF!	SBA	John Mitchel Place	01	Floor Tiles		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	15/09/2023	Identified	Very Low Risk	68391	BA3630/15	9309/22	06/04/2022	WHS
#REF!	SBA	John Mitchel Place	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68392	BA3630/16	9506/18	27/07/2018	WHS
#REF!	SBA	John Mitchel Place	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68393	BA3630/17	9506/18	27/07/2018	WHS
#REF!	SBA	John Mitchel Place	01	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68394	BA3630/18	9506/18	27/07/2018	WHS
#REF!	SBA	John Mitchel Place	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68395	BA3630/19	9506/18	27/07/2018	WHS
#REF!	SBA	John Mitchel Place	01	Lining Panels		Insulating Board	NO ASBESTOS	Encapsulated Spray or Lagoins/Unsealed AIB	High	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68396	BA3630/20	9506/18	27/07/2018	WHS
#REF!	SBA	John Mitchel Place	01	Gaskets		Textiles & Paper	Chrysotile	Encapsulated Spray or Lagoins/Unsealed AIB	Low	Label and Remove if likely to be disturbed	Re-inspection	HSG227	Unchecked	Low Risk	6	15/09/2023	Identified	Low Risk	68397	BA3630/21	9309/22	06/04/2022	WHS
#REF!	SBA	John Mitchel Place	01	Soffit Boards		Cement Products	Chrysotile	Encapsulated Spray or	Low	Conduct annual routine inspections	Review – No Change	HSG227	Unchecked	Very Low Risk	4	06/10/2021	Identified	Very Low Risk	68398	BA3630/22	9309/22	27/01/2020	WH Stephens
#REF!	SAA	Daisy Hill Hospital Estate	09	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	4	11/10/2023	Identified	Very Low Risk	68399	BA3585/01	9309/22	20/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	09	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	4	11/10/2023	Strongly Presumed Similar to	Very Low Risk	68400	BA3585/01	9309/22	20/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	09	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	4	11/10/2023	Strongly Presumed Similar to	Very Low Risk	68401	BA3585/01	9309/22	20/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	09	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	4	11/10/2023	Strongly Presumed Similar to	Very Low Risk	68402	BA3585/01	9309/22	20/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	09	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Medium	Further investigation Required	Re-inspection	HSG227	Unchecked	Very Low Risk	4	11/10/2023	Strongly Presumed Similar to	Very Low Risk	68403	BA3585/01	9309/22	20/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	09	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	4	11/10/2023	Strongly Presumed Similar to	Very Low Risk	68404	BA3585/01	9309/22	20/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	09	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	11/10/2023	Identified	Very Low Risk	68405	BA3585/02	9309/22	20/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	09	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	11/10/2023	Strongly Presumed Similar to	Very Low Risk	68406	BA3585/02	9309/22	20/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	09	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	11/10/2023	Strongly Presumed Similar to	Very Low Risk	68407	BA3585/02	9309/22	20/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	09	Floor Tile and Bitumen Adhesive		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	06/12/2019	Strongly Presumed Similar to	Asbestos Removed	68408	BA3585/02	9327/17	19/02/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	09	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	11/10/2023	Identified	Very Low Risk	68409	BA3585/03	9309/22	20/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	09	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	11/10/2023	Strongly Presumed Similar to	Very Low Risk	68410	BA3585/03	9309/22	20/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	09	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	None	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	2	12/10/2023	Identified	Very Low Risk	68411	BA3585/04	9309/22	20/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	09	Boarding		Cement Products	NO ASBESTOS	Enclosed Spray or Lagoins/Sealed AIB	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	Asbestos Removed	68412	BA3586/06	9327/17	19/02/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	09	Boarding		Cement Products	NO ASBESTOS	Enclosed Spray or Lagoins/Sealed AIB	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	Asbestos Removed	68413	BA3586/06	9327/17	19/02/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	09	Boarding		Cement Products	NO ASBESTOS	Enclosed Spray or Lagoins/Sealed AIB	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	Asbestos Removed	68414	BA3586/06	9327/17	19/02/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	09	Boarding		Cement Products	NO ASBESTOS	Enclosed Spray or Lagoins/Sealed AIB	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	Asbestos Removed	68415	BA3586/06	9327/17	19/02/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	09	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	4	11/10/2023	Identified	Very Low Risk	68416	BA3586/07	9309/22	20/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	09	Floor Tile and Bitumen Adhesive		Composite Material	NO ASBESTOS	Composite Materials	Medium	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	Asbestos Removed	68417	BA3586/07	9327/17	19/02/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	09	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	4	12/10/2023	Identified	Very Low Risk	68418	BA3586/08	9309/22	20/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	09	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	4	12/10/2023	Strongly Presumed Similar to	Very Low Risk	68419	BA3586/08	9309/22	20/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	09	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	4	12/10/2023	Strongly Presumed Similar to	Very Low Risk	68420	BA3586/08	9309/22	20/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	09	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	4	12/10/2023	Strongly Presumed Similar to	Very Low Risk	68421	BA3586/08	9309/22	20/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	09	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	4	12/10/2023	Strongly Presumed Similar to	Very Low Risk	68422	BA3586/08	9309/22	20/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	09	Floor Tile and Bitumen Adhesive		Composite Material	NO ASBESTOS	Composite Materials	Medium	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	Asbestos Removed	68423	BA3586/09	9327/17	19/02/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	09	Floor Tile and Bitumen Adhesive		Composite Material	NO ASBESTOS	Composite Materials	Medium	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	17/05/2014	Strongly Presumed Similar to	Asbestos Removed	68424	BA3586/09	9327/17	19/02/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	09	Floor Tile and Bitumen Adhesive		Composite Material	NO ASBESTOS	Composite Materials	Medium	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	17/05/2014	Strongly Presumed Similar to	Asbestos Removed	68425	BA3586/09	9327/17	19/02/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	09	Floor Tile and Bitumen Adhesive		Composite Material	NO ASBESTOS	Composite Materials	Medium	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	17/05/2014	Strongly Presumed Similar to	Asbestos Removed	68426	BA3586/09	9327/17	19/02/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	09	Floor Tile and Bitumen Adhesive		Composite Material	NO ASBESTOS	Composite Materials	Medium	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	17/05/2014	Strongly Presumed Similar to	Asbestos Removed	68427	BA3586/09	9327/17	19/02/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	09	Floor Tile and Bitumen Adhesive		Composite Material	NO ASBESTOS	Composite Materials	Medium	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	17/05/2014	Strongly Presumed Similar to	Asbestos Removed	68428	BA3586/09	9327/17	19/02/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	09	Floor Tile and Bitumen Adhesive		Composite Material	NO ASBESTOS	Composite Materials	Medium	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	17/05/2014	Strongly Presumed Similar to	Asbestos Removed	68429	BA3586/09	9327/17	19/02/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	09	Floor Tile and Bitumen Adhesive		Composite Material	NO ASBESTOS	Composite Materials	Medium	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	17/05/2014	Strongly Presumed Similar to	Asbestos Removed	68430	BA3586/09	9327/17	19/02/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	09	Floor Tile and Bitumen Adhesive		Composite Material	NO ASBESTOS	Composite Materials	Medium	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	17/05/2014	Strongly Presumed Similar to	Asbestos Removed	68431	BA3586/09	9327/17	19/02/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	09	Floor Tile and Bitumen Adhesive		Composite Material	NO ASBESTOS	Composite Materials	Medium	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	Asbestos Removed	68432	BA3586/09	9327/17	19/02/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	09	Floor Tile and Bitumen Adhesive		Composite Material	NO ASBESTOS	Composite Materials	Medium	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	17/05/2014	Identified	Asbestos Removed	68433	BA3586/10	9327/17	19/02/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	09	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	12/10/2023	Identified	Very Low Risk	68434	BA3586/11	9309/22	20/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	09	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	12/10/2023	Strongly Presumed Similar to	Very Low Risk	68435	BA3586/11	9309/22	20/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	09	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	12/10/2023	Strongly Presumed Similar to	Very Low Risk	68436	BA3586/11	9309/22	20/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	09	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	12/10/2023	Strongly Presumed Similar to	Very Low Risk	68437	BA3586/11	9309/22	20/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	09	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	12/10/2023	Strongly Presumed Similar to	Very Low Risk	68438	BA3586/11	9309/22	20/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	09	Boarding		Cement Products	Chrysotile	Enclosed Spray or	High	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	Low Risk	6	12

#REF!	SAA	Daisy Hill Hospital Estate	09	Back Board		Insulating Board	Amosite/Chrysotile	Encapsulated Spray or Lagged/Unsealed AIB	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Medium Risk	7	26/03/2023	Identified	Medium Risk	68441	BA3586/13	9300.2	20/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	09	Floor Tiles		Composite Material	Chrysotile	Composite Materials	None	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	2	11/10/2023	Identified	Very Low Risk	68442	BA3629/01	9300.2	20/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	09	Floor Tiles		Composite Material	Chrysotile	Composite Materials	None	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	2	11/10/2023	Strongly Presumed Similar to	Very Low Risk	68443	BA3629/01	9300.2	20/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	09	Floor Tiles		Composite Material	Chrysotile	Composite Materials	None	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	2	28/08/2021	Identified	Very Low Risk	68444	BA3629/02	9811/1	27/07/2020	WHS
#REF!	SAA	Daisy Hill Hospital Estate	09	Floor Tiles		Composite Material	Chrysotile	Composite Materials	None	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	2	11/10/2023	Stronnlv Presumed Similar to	Very Low Risk	68445	BA3629/02	9300.2	20/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	09	Floor Tiles		Composite Material	Chrysotile	Composite Materials	None	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	2	11/10/2023	Strongly Presumed Similar to	Very Low Risk	68446	BA3629/02	9300.2	20/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	09	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68447	BA3629/03	9327/1	19/02/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	09	Floor Tiles		Composite Material	Chrysotile	Composite Materials	None	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	2	11/10/2023	Identified	Very Low Risk	68448	BA3629/04	9300.2	20/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	09	Floor Tile and Bitumen Adhesive		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	Asbestos Removed	68449	BA3629/05	9327/1	19/02/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	09	Floor Tile and Bitumen Adhesive		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	Asbestos Removed	68450	BA3629/05	9327/1	19/02/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	09	Floor Tile and Bitumen Adhesive		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	Asbestos Removed	68451	BA3629/05	9327/1	19/02/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	09	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	None	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	2	11/10/2023	Identified	Very Low Risk	68452	BA3629/06	9300.2	20/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	09	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	None	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	2	11/10/2023	Stronnlv Presumed Similar to	Very Low Risk	68453	BA3629/06	9300.2	20/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	09	Floor Tile and Bitumen Adhesive		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	Asbestos Removed	68454	BA3629/06	9327/1	19/02/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	09	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	None	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	2	11/10/2023	Identified	Very Low Risk	68455	BA3629/07	9300.2	20/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	09	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	None of damage or	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	Very Low Risk	4	11/10/2023	Strongly Presumed Similar to	Very Low Risk	68456	BA3629/07	9300.2	20/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	09	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	None	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	2	11/10/2023	Stronnlv Presumed Similar to	Very Low Risk	68457	BA3629/07	9300.2	20/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	09	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68458	BA3629/08	9327/1	19/02/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	09	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68459	BA3629/08	9327/1	19/02/2018	WHS
#REF!	RAB	Longstone/Mullinure	39	Rope Seal	Oven Door	Textiles & Paper	Chrysotile	Unsealed Rope	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Low Risk	6	25/03/2021	Identified	Medium Risk	68460	BA3596/02	9300.2	27/11/2019	WHS
#REF!	RAB	Longstone/Mullinure	39	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68461	BA3596/03	9506/1	11/08/2018	WHS
#REF!	RAB	Longstone/Mullinure	39	Ceiling Tiles		Insulating Board	NO ASBESTOS	Partially Sealed Asbestos Insulation Board	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68462	BA3596/04	9506/1	11/08/2018	WHS
#REF!	RAB	Longstone/Mullinure	39	Ceiling Tiles		Insulating Board	NO ASBESTOS	Partially Sealed Asbestos Insulation Board	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68463	BA3596/04	9506/1	11/08/2018	WHS
#REF!	RAB	Longstone/Mullinure	39	Ceiling Tiles		Insulating Board	NO ASBESTOS	Partially Sealed Asbestos Insulation Board	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68464	BA3596/04	9506/1	11/08/2018	WHS
#REF!	RAB	Longstone/Mullinure	39	Ceiling Tiles		Insulating Board	NO ASBESTOS	Partially Sealed Asbestos Insulation Board	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68465	BA3596/04	9506/1	11/08/2018	WHS
#REF!	RAB	Longstone/Mullinure	39	Ceiling Tiles		Insulating Board	NO ASBESTOS	Partially Sealed Asbestos Insulation Board	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68466	BA3596/04	9506/1	11/08/2018	WHS
#REF!	RAB	Longstone/Mullinure	39	Ceiling Tiles		Insulating Board	NO ASBESTOS	Partially Sealed Asbestos Insulation Board	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68467	BA3596/04	9506/1	11/08/2018	WHS
#REF!	RAB	Longstone/Mullinure	39	Ceiling Tiles		Insulating Board	NO ASBESTOS	Partially Sealed Asbestos Insulation Board	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68468	BA3596/04	9506/1	11/08/2018	WHS
#REF!	RAB	Longstone/Mullinure	39	Ceiling Tiles		Insulating Board	NO ASBESTOS	Partially Sealed Asbestos Insulation Board	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68469	BA3596/04	9506/1	11/08/2018	WHS
#REF!	RAB	Longstone/Mullinure	39	Ceiling Tiles		Insulating Board	NO ASBESTOS	Partially Sealed Asbestos Insulation Board	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68470	BA3596/04	9506/1	11/08/2018	WHS
#REF!	RAB	Longstone/Mullinure	39	Ceiling Tiles		Insulating Board	NO ASBESTOS	Partially Sealed Asbestos Insulation Board	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68471	BA3596/04	9506/1	11/08/2018	WHS
#REF!	RAB	Longstone/Mullinure	39	Ceiling Tiles		Insulating Board	NO ASBESTOS	Partially Sealed Asbestos Insulation Board	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68472	BA3596/04	9506/1	11/08/2018	WHS
#REF!	RAB	Longstone/Mullinure	39	Fanlight Panel		Insulating Board	NO ASBESTOS	Unsealed Board	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68473	BA3596/05	9506/1	11/08/2018	WHS
#REF!	RAB	Longstone/Mullinure	39	Wall Panels		Insulating Board	NO ASBESTOS	Unsealed Board	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68474	BA3596/06	9506/1	11/08/2018	WHS
#REF!	RAB	Longstone/Mullinure	39	Rope Seal	Rope Gasket on Boiler	Textiles & Paper	NO ASBESTOS	Unsealed Rope	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68475	BA3596/07	9506/1	11/08/2018	WHS
#REF!	RAB	Longstone/Mullinure	39	Rope Seal	Exhaust	Textiles & Paper	NO ASBESTOS	Unsealed Rope	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68476	BA3596/07	9506/1	11/08/2018	WHS
#REF!	RAB	Longstone/Mullinure	39	Boiler Lagging	Internal Insulation to Boiler	Thermal Insulation	Presumed Asbestos	Encased	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Medium Risk	8	25/03/2021	Presumed	Medium Risk	68477		9300.2	27/11/2019	WHS
#REF!	NAB	St.Lukes	18	Ceiling Board		Insulating Board	NO ASBESTOS	Partially Sealed Asbestos Insulation Board	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68478	BA3511/01	9506/1	07/10/2018	WHS
#REF!	NAB	St.Lukes	18	Ceiling Board		Insulating Board	NO ASBESTOS	Partially Sealed Asbestos Insulation Board	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68479	BA3511/01	9506/1	07/10/2018	WHS
#REF!	NAB	St.Lukes	18	Fuse Flash Guards		Textiles & Paper	Presumed Asbestos	Enclosed Fuse Flash Guards	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Medium Risk	8	24/02/2021	Presumed	Medium Risk	68480		9811/1	03/12/2019	WHS
#REF!	NAB	St.Lukes	18	Soffit Boards		Insulating Board	Chrysotile	Partially Exposed Asbestos Insulation Board	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Low Risk	6	24/02/2021	Identified	Low Risk	68481	BA3511/02	9811/1	03/12/2019	WHS
#REF!	NAB	St.Lukes	18	Bitumen Felt	Rear Porch	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68482	BA3511/03	9506/1	07/10/2018	WHS
#REF!	NAB	St.Lukes	18	Bitumen Felt	Front Porch	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68483	BA3511/03	9506/1	07/10/2018	WHS
#REF!	NAB	St.Lukes	24	Fire Lining Board	Heater	Cement Products	Chrysotile	Cement Sheets	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	4	24/02/2021	Identified	Very Low Risk	68484	BA3597/01	9811/1	03/12/2019	WHS
#REF!	NAB	St.Lukes	24	Fuse Flash Guards	Low floor switchroom	Textiles & Paper	Presumed Asbestos	Enclosed Fuse Flash Guards	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Medium Risk	8	24/02/2021	Presumed	Medium Risk	68485		9811/1	03/12/2020	WHS
#REF!	RAC	Tower Hill Site	02	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68486	BA3506/01	9344/1	04/06/2018	WH Stephens
#REF!	RAC	Tower Hill Site	02	Roofing Felts		Composite Material	Chrysotile	Composite Material	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	27/03/2021	Identified	Very Low Risk	68487	BA3506/02	9811/1	20/11/2020	WH Stephens
#REF!	RAC	Tower Hill Site	02	Roofing Felts		Composite Material	Chrysotile	Composite Material	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	27/03/2021	Strongly Presumed Similar to	Very Low Risk	68488	BA3506/02	9811/1	20/11/2019	WH Stephens
#REF!	RAC	Tower Hill Site	02	Artificial Slate	Courtyard Replacement Slates	Cement Products	Chrysotile	Cement Sheets	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	4	27/03/2021	Identified	Very Low Risk	68489	BA3506/03	9811/1	20/11/2019	WH Stephens
#REF!	RAC	Tower Hill Site	13	Roofing Felts		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Original Survey Data	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68490	BA3512/01			
#REF!	RAC	Tower Hill Site	13	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Original Survey Data	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68491	BA3512/02			
#REF!	RAC	Tower Hill Site	13	Lino Flooring		Composite Material	NO ASBESTOS	Composite Materials	Very Low	No further action required (No Asbestos Detected)	Original Survey Data	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68492	BA3512/03			
#REF!	RAC	Tower Hill Site	13	Lino Flooring		Composite Material	NO ASBESTOS	Composite Materials	Very Low	No further action required (No Asbestos Detected)	Original Survey Data	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68493	BA3512/03			
#REF!	RAC	Tower Hill Site	13	Lino Flooring		Composite Material	NO ASBESTOS	Composite Materials	Very Low	No further action required (No Asbestos Detected)	Original Survey Data	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68494	BA3512/03			
#REF!	RAC	Tower Hill Site	13	Lino Flooring		Composite Material	NO ASBESTOS	Composite Materials	Very Low	No further action required (No Asbestos Detected)	Original Survey Data	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68495	BA3512/03			
#REF!	RAC	Tower Hill Site	13	Lino Flooring		Composite Material	NO ASBESTOS	Composite Materials	Very Low	No further action required (No Asbestos Detected)	Original Survey Data	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68496	BA3512/03			
#REF!	RAC	Tower Hill Site	13	Lino Flooring		Composite Material	NO ASBESTOS	Composite Materials	Very Low	No further action required (No Asbestos Detected)	Original Survey Data	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68497	BA3512/03			
#REF!	RAC	Tower Hill Site	13	Lino Flooring		Composite Material	NO ASBESTOS	Composite Materials	Very Low	No further action required (No Asbestos Detected)	Original Survey Data	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68498	BA3512/03			
#REF!	RAC	Tower Hill Site	14	Stair Nosing	Stairs	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Original Survey Data	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68499	BA3507/01			
#REF!	RAC	Tower Hill Site	04	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Original Survey Data	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68500	BA3510/01			
#REF!	RAC	Tower Hill Site	04	Lino Flooring	under carpet	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Original Survey Data	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68501	BA3510/02			
#REF!	RAC	Tower Hill Site	04	Lino Flooring	Under Carpet	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Original Survey Data	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68502	BA3510/02			
#REF!	RAC	Tower Hill Site	04	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Very Low	No further action required (No Asbestos Detected)	Original Survey Data	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68503	BA3510/03			
#REF!	RAC	Tower Hill Site	04	Pipe Insulation		Thermal Insulation	NO ASBESTOS	Unsealed Friable Pipework Insulation	Low	No further action required (No Asbestos Detected)	Original Survey Data	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68504	BA3510/04			
#REF!	RAC	Tower Hill Site	04	Bitumen Felt	Front Porch	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Original Survey Data	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68505	BA3510/05			
#REF!	RAC	Tower Hill Site	04	Ceiling Board	Small Store at Entrance	Insulating Board	NO ASBESTOS	Unsealed Board	Low	No further action required (No Asbestos Detected)	Original Survey Data	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68506	BA3510/06			
#REF!	RCB	Clogher Health Clinic	01	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Very Low	No further action required (No Asbestos Detected)	Original Survey Data	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68507	BA3505/01			
#REF!	RCB	Clogher Health Clinic	01	Textured Coatings	Ceiling	Decorative Coatings	NO ASBESTOS	Textured Coating	Very Low	No further action required (No Asbestos Detected)	Original Survey Data	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68508	BA3505/02			
#REF!	RCB	Clogher Health Clinic	01	Fire Break Panel		Insulating Board	NO ASBESTOS	Unsealed Board	Low	No further action required (No Asbestos Detected)	Original Survey Data	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68509	BA3505/03			
#REF!	RCB	Clogher Health Clinic	01							No action required	Re-inspection	HSG227	Unchecked	[illegible]	0				68510			20/08/2015	
#REF!	RAC	Tower Hill Site	09	Lino Flooring		Composite Material	NO ASBESTOS	Composite Materials	Very Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68511	BA3508/01	9344/1	28/02/2018	WHS
#REF!	RAC	Tower Hill Site	09	Lino Flooring		Composite Material	NO ASBESTOS	Composite Materials	Very Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68512	BA3508/01	9344/1	28/02/2018	WHS
#REF!	RAC	Tower Hill Site	09	Lino Flooring		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68513	BA3508/02	9344/1	28/02/2018	WHS
#REF!	RAC	Tower Hill Site	09	Bitumen Adhesive	Floor	Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	27/03/2021	Identified	Low Risk	68514	BA3508/03	9811/1	28/11/2019	WHS
#REF!	RAC	Tower Hill Site	09	Roofing Felts		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68515	BA3508/04	9344/1	28/02/2018	WHS
#REF!	RAC	Tower Hill Site	09	Artificial Slate	Roof	Cement Products	Chrysotile	Cement Sheets	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	4	27/03/2021	Identified	Very Low Risk	68516	BA3508/05	9811/1	28/11/2019	WHS
#REF!	NAB	St.Lukes	15	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68520	BA3604/01	9506/1	30/06/2018	WHS
#REF!	NAB	St.Lukes	15	Fuse Flash Guards		Textiles & Paper	Presumed Asbestos	Enclosed Fuse Flash Guards	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Medium Risk	8	24/02/2021	Presumed	Medium Risk	68521		9811/1	06/12/2019	WHS
#REF!	NAB	St.Lukes	34	Fuse Flash Guards		Textiles & Paper	Presumed Asbestos	Enclosed Fuse Flash Guards	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Medium Risk	8	24/02/2021	Presumed	Medium Risk	68522		9811/1	06/12/2019	WHS
#REF!	NAB	St.Lukes	20	Gaskets	Old Pipework	Textiles & Paper	Chrysotile	Composite Materials	Very Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	24/02/2021	Identified	Very Low Risk	68523	BA3601/01	9300.2	05/12/2019	WHS
#REF!	NAB	St.Lukes	20	Pipe Insulation	Water Tank	Thermal Insulation	NO ASBESTOS	Partialled Sealed Pipework Insulation	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68524	BA3601/02	9344/1	20/09/2017	WHS
#REF!	NAB	St.Lukes	20	Damp Proof Course		Composite Material	Chrysotile	Composite Materials	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	4	24/02/2021	Identified	Very Low Risk	68525	BA3601/03	9300.2	05/12/2019	WHS
#REF!	NAB	St.Lukes	20	Bitumen Wrap to cables	Electrical Intake Pipe Wrap	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68526	BA3601/04	9344/1	20/09/2017	WHS
#REF!	NAB	St.Lukes	20	Artificial Slate	Roof	Cement Products	Chrysotile	Cement Sheets	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	4	24/02/2021	Identified	Very Low Risk	68527	BA3601/05	9811/1	05/12/2019	WHS
#REF!	NAB	St.Lukes	40	Concrete Downpipes		Cement Products	Chrysotile	Concealed Cement	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	24/02/2021	Identified	Very Low Risk	68528	BA3600/01	9811/1	03/12/2019	WHS
#REF!	NAB	St.Lukes	40	Fuse Flash Guards		Textiles & Paper	Presumed Asbestos	Enclosed Fuse Flash Guards	Medium	Apply caution when maintaining and affix ID labels	Re-inspection	HSG227	Unchecked	Medium Risk	8	24/02/2021	Presumed	Medium Risk	68529		9811/1	03/12/2019	WHS

#REF!	NAB	St.Lukes	40	Bitumen Wrap to cables	Electrical Intake Cable	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68530	BA3600/02	9506/18	06/12/2018	WHS
#REF!	NAB	St.Lukes	40	Bitumen Felt	Roof	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68531	BA3600/03	9506/18	06/12/2018	WHS
#REF!	NAB	St.Lukes	21	Floor Tiles	Brown VFT	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68536	BA3602/01	9506/18	16/07/2018	WHS
#REF!	NAB	St.Lukes	21	Floor Tiles	Blue VFT	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68538	BA3602/02	9506/18	16/07/2018	WHS
#REF!	NAB	St.Lukes	21	Floor Tiles	Cream VFT	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68539	BA3602/03	9506/18	16/07/2018	WHS
#REF!	NAB	St.Lukes	21	Fuse Flash Guards		Textiles & Paper	Presumed Asbestos	Enclosed Fuse Flash Guards	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Medium Risk	8	24/02/2021	Presumed	Medium Risk	68540		9512/18	03/12/2019	WHS
#REF!	NAB	St.Lukes	21	Damp Proof Course		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68541	BA3602/04	9506/18	16/07/2018	WHS
#REF!	NAB	St.Lukes	13	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68546	BA3504/01	9506/18	19/06/2018	WHS
#REF!	NAB	St.Lukes	13	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68547	BA3504/01	9506/18	19/06/2018	WHS
#REF!	RJJ	Appleby S.E.C.	01	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68554	BA3599/01	9506/18	21/01/2019	WHS
#REF!	RJJ	Appleby S.E.C.	01	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68555	BA3599/01	9506/18	21/01/2019	WHS
#REF!	RJJ	Appleby S.E.C.	01	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68556	BA3599/01	9506/18	21/01/2019	WHS
#REF!	RJJ	Appleby S.E.C.	01	Ceiling Panel		Insulating Board	NO ASBESTOS	Unsealed Board	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68557	BA3599/02	9506/18	21/01/2019	WHS
#REF!	RJJ	Appleby S.E.C.	01	Ceiling Panel		Insulating Board	NO ASBESTOS	Unsealed Board	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68558	BA3599/02	9506/18	21/01/2019	WHS
#REF!	RJJ	Appleby S.E.C.	01	Ceiling Panel		Insulating Board	NO ASBESTOS	Unsealed Board	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68559	BA3599/02	9506/18	21/01/2019	WHS
#REF!	RJJ	Appleby S.E.C.	01	Roofing Felts		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68560	BA3599/03	9506/18	21/01/2019	WHS
#REF!	RJJ	Appleby S.E.C.	01	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68561	BA3599/04	9506/18	21/01/2019	WHS
#REF!	RJJ	Appleby S.E.C.	01	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68562	BA3599/04	9506/18	21/01/2019	WHS
#REF!	RJJ	Appleby S.E.C.	01	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68563	BA3599/04	9506/18	21/01/2019	WHS
#REF!	RJJ	Appleby S.E.C.	01	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68564	BA3599/04	9506/18	21/01/2019	WHS
#REF!	RJJ	Appleby S.E.C.	01	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68565	BA3599/04	9506/18	21/01/2019	WHS
#REF!	RJJ	Appleby S.E.C.	01	Lino Flooring	Orange Vinyl	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68566	BA3599/05	9506/18	21/01/2019	WHS
#REF!	RJJ	Appleby S.E.C.	01	Ceiling Board		Insulating Board	NO ASBESTOS	Unsealed Board	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68567	BA3599/06	9506/18	21/01/2019	WHS
#REF!	RJJ	Appleby S.E.C.	01	Ceiling Board		Insulating Board	NO ASBESTOS	Unsealed Board	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68568	BA3599/06	9506/18	21/01/2019	WHS
#REF!	RJJ	Appleby S.E.C.	01	Gaskets	Gaskets to Boiler Burner	Textiles & Paper	NO ASBESTOS	Unsealed	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68569	BA3599/07	9506/18	21/01/2019	WHS
#REF!	RJJ	Appleby S.E.C.	01	Boiler Lagging	Internal Insulation to Boiler	Thermal Insulation	Presumed Asbestos	Encased	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Medium Risk	8	27/03/2021	Presumed	Medium Risk	68570		9512/18	28/11/2019	WHS
#REF!	RJJ	Appleby S.E.C.	01	Gaskets	Loose Burner Gasket	Textiles & Paper	NO ASBESTOS	Unsealed	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68571	BA3599/08	9506/18	21/01/2019	WHS
#REF!	RJJ	Appleby S.E.C.	01	Rope Seal	To Boiler Flue	Textiles & Paper	NO ASBESTOS	Unsealed Rope	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68572	BA3599/09	9506/18	21/01/2019	WHS
#REF!	RJJ	Appleby S.E.C.	01	Soffit Boards	Courtyard	Insulating Board	NO ASBESTOS	Unsealed Board	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68573	BA3599/10	9506/18	21/01/2019	WHS
#REF!	RJJ	Appleby S.E.C.	01	Soffit Boards	Front Porch	Insulating Board	NO ASBESTOS	Unsealed Board	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68574	BA3599/10	9506/18	21/01/2019	WHS
#REF!	RJJ	Appleby S.E.C.	01	Soffit Boards	Side Door	Insulating Board	NO ASBESTOS	Unsealed Board	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68575	BA3599/10	9506/18	21/01/2019	WHS
#REF!	RJJ	Appleby S.E.C.	01	Soffit Boards	Rear Entrance	Insulating Board	NO ASBESTOS	Unsealed Board	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68576	BA3599/10	9506/18	21/01/2019	WHS
#REF!	RAB	Longstone/Mullinure	38	Brake Pads	Machinery	Textiles & Paper	NO ASBESTOS	Sealed	Medium	No further action required (No Asbestos Detected)	Review of Incident	HSG227	Unchecked	NO ASBESTOS	0	20/11/2019	Presumed	No Asbestos Detected	68577		9506/18	13/11/2018	WHS
#REF!	RAB	Longstone/Mullinure	38	Ceiling Board		Insulating Board	NO ASBESTOS	Unsealed Board	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68578	BA3539/01	9506/18	13/11/2018	WHS
#REF!	RAB	Longstone/Mullinure	38	Fuse Flash Guards		Textiles & Paper	Presumed Asbestos	Enclosed Fuse Flash Guards	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Medium Risk	8	25/03/2021	Presumed	Medium Risk	68579		9512/18	28/11/2019	WHS
#REF!	RAB	Longstone/Mullinure	38	Fuse Flash Guards	Electric Cupboard	Textiles & Paper	Presumed Asbestos	Enclosed Fuse Flash Guards	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Medium Risk	8	25/03/2021	Presumed	Medium Risk	68580		9512/18	28/11/2019	WHS
#REF!	RAB	Longstone/Mullinure	38	Fuse Flash Guards	Electric Cupboard	Textiles & Paper	Presumed Asbestos	Enclosed Fuse Flash Guards	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Medium Risk	8	25/03/2021	Presumed	Medium Risk	68581		9512/18	28/11/2019	WHS
#REF!	RAB	Longstone/Mullinure	38	Fuse Flash Guards	Electric Cupboard	Textiles & Paper	Presumed Asbestos	Enclosed Fuse Flash Guards	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Medium Risk	8	25/03/2021	Presumed	Medium Risk	68582		9512/18	28/11/2019	WHS
#REF!	RAB	Longstone/Mullinure	38	Fuse Flash Guards		Textiles & Paper	Presumed Asbestos	Enclosed Fuse Flash Guards	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Medium Risk	8	25/03/2021	Presumed	Medium Risk	68583		9512/18	28/11/2019	WHS
#REF!	RAB	Longstone/Mullinure	38	Fuse Flash Guards		Textiles & Paper	Presumed Asbestos	Enclosed Fuse Flash Guards	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Medium Risk	8	25/03/2021	Presumed	Medium Risk	68584		9512/18	28/11/2019	WHS
#REF!	RAB	Longstone/Mullinure	38	Fuse Flash Guards	Electric Cupboard	Textiles & Paper	Presumed Asbestos	Enclosed Fuse Flash Guards	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Medium Risk	8	25/03/2021	Presumed	Medium Risk	68585		9512/18	28/11/2019	WHS
#REF!	RAB	Longstone/Mullinure	38	Fire Proof Panel	Casing to Beams	Insulating Board	NO ASBESTOS	Unsealed Board	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68586	BA3539/02	9506/18	13/11/2018	WHS
#REF!	RAB	Longstone/Mullinure	38	Fire Proof Panel		Insulating Board	NO ASBESTOS	Unsealed Board	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68587	BA3539/02	9506/18	13/11/2018	WHS
#REF!	RAB	Longstone/Mullinure	38	Stair Nosing	Stairs	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68588	BA3539/03	9506/18	13/11/2018	WHS
#REF!	RAB	Longstone/Mullinure	38	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68589	BA3539/04	9506/18	13/11/2018	WHS
#REF!	RAB	Longstone/Mullinure	38	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68590	BA3539/04	9506/18	13/11/2018	WHS
#REF!	RAB	Longstone/Mullinure	38	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68591	BA3539/04	9506/18	13/11/2018	WHS
#REF!	RAB	Longstone/Mullinure	38	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68592	BA3539/05	9506/18	13/11/2018	WHS
#REF!	RAB	Longstone/Mullinure	38	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68593	BA3539/05	9506/18	13/11/2018	WHS
#REF!	RAB	Longstone/Mullinure	38	Soffit Boards		Insulating Board	NO ASBESTOS	Sealed	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68594	BA3539/06	9506/18	13/11/2018	WHS
#REF!	RAB	Longstone/Mullinure	38	fascia board		Cement Products	NO ASBESTOS	Unsealed Board	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68595	BA3539/07	9506/18	13/11/2018	WHS
#REF!	RAB	Longstone/Mullinure	38	Artificial Slate	Roof	Cement Products	NO ASBESTOS	Cement Sheets	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68596	BA3539/08	9506/18	13/11/2018	WHS
#REF!	RAC	Tower Hill Site	03	Wall Panels		Insulating Board	NO ASBESTOS	Unsealed Board	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68600	BA3513/01	9344/17	21/03/2018	WHS
#REF!	RAC	Tower Hill Site	03	Wall Panels	Outside Plant Room	Insulating Board	NO ASBESTOS	Unsealed Board	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68601	BA3513/01	9344/17	21/03/2018	WHS
#REF!	RAC	Tower Hill Site	03	Fuse Flash Guards		Textiles & Paper	Presumed Asbestos	Enclosed Fuse Flash Guards	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Medium Risk	8	27/03/2021	Presumed	Medium Risk	68605		9512/18	28/11/2019	WHS
#REF!	RAC	Tower Hill Site	03	Ceiling Tiles		Insulating Board	NO ASBESTOS	Unsealed Board	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	08/05/2014	Identified	No Asbestos Detected	68606	BA3513/02	9344/17	21/03/2018	WHS
#REF!	NAB	St.Lukes	13	Lino Flooring	Below Carpet	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68609	BA3504/02	9506/18	19/06/2018	WHS
#REF!	NAB	St.Lukes	13	Lino Flooring	Below Carpet	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68610	BA3504/02	9506/18	19/06/2018	WHS
#REF!	NAB	St.Lukes	13	Lino Flooring	Below Carpet	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68611	BA3504/02	9506/18	19/06/2018	WHS
#REF!	NAB	St.Lukes	13	Lino Flooring	Below Carpet	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68612	BA3504/02	9506/18	19/06/2018	WHS
#REF!	NAB	St.Lukes	13	Lino Flooring	Belwo Carpet	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68613	BA3504/02	9506/18	19/06/2018	WHS
#REF!	NAB	St.Lukes	13	Lino Flooring	Below Carpet	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68614	BA3504/02	9506/18	19/06/2018	WHS
#REF!	NAB	St.Lukes	13	Lino Flooring	Blue Vinyl below carpet	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68615	BA3504/03	9506/18	19/06/2018	WHS
#REF!	NAB	St.Lukes	13	Lino Flooring	Blue Vinyl Below carpet	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68616	BA3504/03	9506/18	19/06/2018	WHS
#REF!	NAB	St.Lukes	13	Lino Flooring	Blue Vinyl Below Carpet	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68617	BA3504/03	9506/18	19/06/2018	WHS
#REF!	NAB	St.Lukes	13	Lino Flooring	Blue Vinyl Below Carpet	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68618	BA3504/03	9506/18	19/06/2018	WHS
#REF!	NAB	St.Lukes	13	Stair Nosing		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68619	BA3504/04	9506/18	19/06/2018	WHS
#REF!	NAB	St.Lukes	13	Stair Nosing		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68620	BA3504/04	9506/18	19/06/2018	WHS
#REF!	NAB	St.Lukes	13	Lino Flooring	Orange Vinyl	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68621	BA3504/05	9506/18	19/06/2018	WHS
#REF!	NAB	St.Lukes	13	Lino Flooring	Orange Vinyl	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68622	BA3504/05	9506/18	19/06/2018	WHS
#REF!	NAB	St.Lukes	13	Lino Flooring	Below Carpet	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68623	BA3504/06	9506/18	19/06/2018	WHS
#REF!	NAB	St.Lukes	13	Lino Flooring	Below Carpet	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68624	BA3504/06	9506/18	19/06/2018	WHS
#REF!	NAB	St.Lukes	13	Lino Flooring	Below Carpet	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68625	BA3504/06	9506/18	19/06/2018	WHS
#REF!	NAB	St.Lukes	13	Fuse Flash Guards		Textiles & Paper	NO ASBESTOS	Enclosed Fuse Flash Guards	Medium	No further action required (Asbestos removed)	ACM Removed	HSG227	Unchecked	NO ASBESTOS	0	19/07/2019	Presumed	Asbestos Removed	68626		9506/18	19/06/2018	WHS
#REF!	NAB	St.Lukes	13	Fuse Flash Guards		Textiles & Paper	NO ASBESTOS	Enclosed Fuse Flash Guards	Medium	Conduct annual routine inspections	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	19/07/2019	Presumed	Asbestos Removed	68627		9512/18	19/06/2018	WHS
#REF!	NAB	St.Lukes	13	Fuse Flash Guards		Textiles & Paper	Presumed Asbestos	Enclosed Fuse Flash Guards	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Medium Risk	8	27/01/2021	Presumed	Medium Risk	68628		9512/18	03/01/2020	WHS
#REF!	NAB	St.Lukes	13	Fuse Flash Guards		Textiles & Paper	NO ASBESTOS	Enclosed Fuse Flash Guards	Medium	Conduct annual routine inspections	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	19/07/2019	Presumed	Asbestos Removed	68629		9512/18	19/06/2018	WHS
#REF!	NAB	St.Lukes	13	Fuse Flash Guards		Textiles & Paper	Presumed Asbestos	Enclosed Fuse Flash Guards	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Medium Risk	8	27/01/2021	Presumed	Medium Risk	68630		9512/18	03/01/2020	WHS
#REF!	NAB	St.Lukes	13	Stair Nosing		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68631	BA3504/07	9506/18	19/06/2018	WHS
#REF!	NAB	St.Lukes	13	Wall Panels	Wall Board behind fridge	Insulating Board	Amosite/Chrysotile	Encased	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Low Risk	6	27/01/2021	Identified	Medium Risk	68632	BA3504/08	9512/18	03/01/2020	WHS

#REF!	NAB	St.Lukes	13	Stair Nosing	Steps	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68633	BA3504/09	9506/18	19/06/2018	WHS
#REF!	NAB	St.Lukes	13	Fanlight Panel		Insulating Board	NO ASBESTOS	Unsealed Board	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68634	BA3504/10	9506/18	19/06/2018	WHS
#REF!	NAB	St.Lukes	13	Artificial Slate	Medical records	Cement Products	Chrysotile	Cement Sheets	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	4	27/01/2021	Identified	Very Low Risk	68635	BA3504/11	9811/19	03/01/2020	WHS
#REF!	NAB	St.Lukes	13	Bitumen Felt	Rear Flat Roof	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68636	BA3504/12	9506/18	19/06/2018	WHS
#REF!	RAB	Longstone/Mullinure	06	Lino Flooring	Green Vinyl	Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	27/03/2021	Identified	Very Low Risk	68639	BA3575/01	9811/19	27/11/2019	WHS
#REF!	RAC	Tower Hill Site	03	Floor Tiles	Green VFT	Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	27/03/2021	Identified	Very Low Risk	68670	BA3513/03	9811/19	28/11/2019	WHS
#REF!	RAC	Tower Hill Site	03	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Very Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68671	BA3513/04	9344/17	21/03/2018	WHS
#REF!	RAC	Tower Hill Site	03	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Very Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68672	BA3513/04	9344/17	21/03/2018	WHS
#REF!	RAC	Tower Hill Site	03	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Very Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68673	BA3513/04	9344/17	21/03/2018	WHS
#REF!	RAC	Tower Hill Site	03	Floor Tiles	[illegible]	Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	27/03/2021	Identified	Very Low Risk	68674	BA3513/05	9811/19	28/11/2019	WHS
#REF!	RAC	Tower Hill Site	03	Floor Tiles	Store	Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	27/03/2021	Stronmly Presumed Similar to	Very Low Risk	68675	BA3513/05	9811/19	28/11/2019	WHS
#REF!	RAC	Tower Hill Site	03	Floor Tiles	Dark Green VFT	Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	27/03/2021	Identified	Very Low Risk	68676	BA3513/06	9811/19	28/11/2019	WHS
#REF!	RAC	Tower Hill Site	03	Lino Flooring		Composite Material	NO ASBESTOS	Composite Materials	Very Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68677	BA3513/07	9344/17	21/03/2018	WHS
#REF!	RAC	Tower Hill Site	03	Floor Tiles	Blue VFT	Composite Material	NO ASBESTOS	Composite Materials	Very Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68678	BA3513/08	9344/17	21/03/2018	WHS
#REF!	RAC	Tower Hill Site	03	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Very Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68679	BA3513/08	9344/17	21/03/2018	WHS
#REF!	RAC	Tower Hill Site	03	Pipe Insulation	Duct	Thermal Insulation	NO ASBESTOS	Partially Exposed Pipework Insulation	Very Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68680	BA3513/09	9344/17	21/03/2018	WHS
#REF!	RAC	Tower Hill Site	03	Floor Tiles	Duct - Grev VFT	Composite Material	Chrysotile	Composite Materials	Very Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	2	27/03/2021	Identified	Very Low Risk	68681	BA3513/10	9811/19	28/11/2019	WHS
#REF!	RAC	Tower Hill Site	03	Board	Plant Room	Insulating Board	Amosite/Chrysotile	Unsealed Board	High	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	Medium Risk	9	27/03/2021	Identified	High Risk	68682	BS136/70	9344/17	28/11/2019	WHS
#REF!	RAC	Tower Hill Site	03	Bitumen Felt	Tank Room Roof	Composite Material	NO ASBESTOS	Composite Materials	Very Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68683	BA3513/12	9344/17	21/03/2018	WHS
#REF!	RHA	Roxborough Site	02	Floor Tile and Bitumen Adhesive		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	23/04/2019	Identified	Asbestos Removed	68684	BA3658/01	9327/17	18/04/2018	WH Stephens
#REF!	RHA	Roxborough Site	02	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	07/10/2021	Stronmly Presumed Similar to	Very Low Risk	68685	BA3658/01	9811/19	20/01/2020	WH Stephens
#REF!	RHA	Roxborough Site	02	Floor Tile and Bitumen Adhesive		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	Asbestos Removed	68686	BA3658/01	9327/17	18/04/2018	WH Stephens
#REF!	RHA	Roxborough Site	02	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68687	BA3658/02	9327/17	18/04/2018	WH Stephens
#REF!	RHA	Roxborough Site	02	Roofing Felts		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68688	BA3658/03	9327/17	18/04/2018	WH Stephens
#REF!	RHA	Roxborough Site	02	Soffit Boards		Insulating Board	NO ASBESTOS	Unsealed Board	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68689	BA3658/04	9327/17	18/04/2018	WH Stephens
#REF!	NAB	St.Lukes	17	Ceiling Board		Insulating Board	NO ASBESTOS	Unsealed Board	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68690	BA3503/01	9506/18	30/06/2018	WHS
#REF!	NAB	St.Lukes	17	Ceiling Board		Insulating Board	NO ASBESTOS	Unsealed Board	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68691	BA3503/01	9506/18	30/06/2018	WHS
#REF!	NAB	St.Lukes	17	Pipe Insulation	Above Ceiling	Thermal Insulation	NO ASBESTOS	Partially Exposed Pipework Insulation	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68692	BA3503/02	9506/18	30/06/2018	WHS
#REF!	NAB	St.Lukes	17	Pipe Insulation	Duct	Thermal Insulation	NO ASBESTOS	Partially Exposed Pipework Insulation	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68693	BA3503/02	9506/18	30/06/2018	WHS
#REF!	NAB	St.Lukes	17	Soffit Boards		Insulating Board	Chrysotile	Unsealed Board	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Low Risk	6	24/02/2021	Identified	Low Risk	68694	BA3503/03	9811/19	03/12/2019	WHS
#REF!	NAB	St.Lukes	17	Bitumen Felt	Front Porch Roof	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68695	BA3503/04	9506/18	30/06/2018	WHS
#REF!	NAB	St.Lukes	17	Bitumen Felt	Rear Flat Roof	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68696	BA3503/04	9506/18	30/06/2018	WHS
#REF!	NAB	St.Lukes	17	Fuse Flash Guards		Textiles & Paper	Presumed Asbestos	Enclosed Fuse Flash Guards	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Medium Risk	8	24/02/2021	Presumed	Medium Risk	68697	BA3503/05	9811/19	03/12/2019	WHS
#REF!	RAB	Longstone/Mullinure	06	Lino Flooring	Green Vinyl Floor Tile Under Carpet	Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	27/03/2021	Stronmly Presumed Similar to	Very Low Risk	68705	BA3575/01	9811/19	27/11/2019	WHS
#REF!	RAB	Longstone/Mullinure	06	Lino Flooring	Green Vinyl	Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	27/03/2021	Stronmly Presumed Similar to	Very Low Risk	68706	BA3575/01	9811/19	27/11/2019	WHS
#REF!	RAB	Longstone/Mullinure	06	Lino Flooring	Grey Vinyl	Composite Material	Chrysotile	Composite Materials	Very Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	2	27/03/2021	Identified	Very Low Risk	68707	BA3575/02	9811/19	27/11/2019	WHS
#REF!	RAB	Longstone/Mullinure	06	Lino Flooring	Grev Vinyl	Composite Material	Chrysotile	Composite Materials	Very Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	2	27/03/2021	Stronmly Presumed Similar to	Very Low Risk	68708	BA3575/02	9811/19	27/11/2019	WHS
#REF!	RAB	Longstone/Mullinure	06	Lino Flooring	Grey Vinyl	Composite Material	Chrysotile	Composite Materials	Very Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	2	27/03/2021	Stronmly Presumed Similar to	Very Low Risk	68709	BA3575/02	9811/19	27/11/2019	WHS
#REF!	RAB	Longstone/Mullinure	06	Ceiling Board	Duct	Insulating Board	Amosite/Chrysotile	Unsealed Board	Areas of damage or Programme for removal	Re-inspection	HSG227	Unchecked	Medium Risk	8	27/03/2021	Identified	Medium Risk	68710	BA3575/03	9811/19	27/11/2019	WHS
#REF!	RAB	Longstone/Mullinure	06	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Very Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68711	BA3575/04	9506/18	11/08/2018	WHS
#REF!	RAB	Longstone/Mullinure	06	Fuse Flash Guards		Textiles & Paper	Presumed Asbestos	Enclosed Fuse Flash Guards	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Medium Risk	8	27/03/2021	Presumed	Medium Risk	68712		9811/19	27/11/2019	WHS
#REF!	RAB	Longstone/Mullinure	06	Bitumen Felt	Roof	Composite Material	NO ASBESTOS	Composite Materials	Very Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68713	BA3575/05	9506/18	11/08/2018	WHS
#REF!	RAB	Lonsstone/Mullinure	06	fascia board		Cement Products	Chrysotile	Cement Sheets	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	4	27/03/2021	Identified	Very Low Risk	68714	BA3575/06	9811/19	27/11/2019	WHS
#REF!	RAC	Tower Hill Site	01	Roofing Felts		Composite Material	NO ASBESTOS	Composite Materials	Very Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68715	BA3668/01	9344/17	21/02/2018	WHS
#REF!	RAC	Tower Hill Site	01	Board		Insulating Board	NO ASBESTOS	Unsealed Board	Medium	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68716	BA3668/02	9344/17	21/02/2018	WHS
#REF!	RAC	Tower Hill Site	01	Artificial Slate	LHS & RHS Roofs	Cement Products	NO ASBESTOS	Cement Sheets	Very Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	08/05/2014	Identified	No Asbestos Detected	68717	BA3668/03	9344/17	21/02/2018	WHS
#REF!	RAC	Tower Hill Site	01	Stair Nosing		Composite Material	NO ASBESTOS	Composite Materials	Very Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68718	BA3668/04	9344/17	21/02/2018	WHS
#REF!	RAC	Tower Hill Site	01	Board	Casing to Beams	Insulating Board	NO ASBESTOS	Unsealed Board	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68719	BA3668/05	9344/17	21/02/2018	WHS
#REF!	RAC	Tower Hill Site	01	Gaskets	Gasket to Boiler Burner	Textiles & Paper	NO ASBESTOS	Unsealed	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68720	BA3668/06	9344/17	21/02/2018	WHS
#REF!	RAC	Tower Hill Site	01	Boiler Lagging	Internal insulation to Boiler	Thermal Insulation	Presumed Asbestos	Encased	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Medium Risk	8	27/03/2021	Presumed	Medium Risk	68721		9811/19	28/11/2019	WHS
#REF!	NAB	St.Lukes	29	Fuse Flash Guards		Textiles & Paper	Presumed Asbestos	Enclosed Fuse Flash Guards	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Medium Risk	8	24/02/2021	Presumed	Medium Risk	68722		9811/19	03/01/2020	WHS
#REF!	RBB	Ballygawley Health Centre	01	Roofing Felts		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68723	BA3667/01	9327/17	18/04/2018	WH Stephens
#REF!	RBB	Ballygawley Health Centre	01	Board	Board to Attic Hatch	Insulating Board	NO ASBESTOS	Unsealed Board	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68724	BA3667/02	9327/17	18/04/2018	WH Stephens
#REF!	RBB	Ballygawley Health Centre	01	Verge Cloak	Roof	Cement Products	Chrysotile	Cement Sheets	Low	Apply caution when maintaining and affix ID labels	Re-inspection	HSG227	Unchecked	Very Low Risk	4	03/04/2021	Identified	Very Low Risk	68725	BA3667/03	9811/19	18/11/2019	WH Stephens
#REF!	RBB	Ballygawley Health Centre	01	Cement Pipe		Cement Products	Chrysotile	Concealed Cement	Low	Apply caution when maintaining and affix ID labels	Re-inspection	HSG227	Unchecked	Very Low Risk	3	03/04/2021	Identified	Very Low Risk	68726	BA3667/04	9811/19	18/11/2019	WH Stephens
#REF!	RBB	Ballygawley Health Centre	01	Bitumen Felt	Flat Roof	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68727	BA3667/05	9327/17	18/04/2018	WH Stephens
#REF!	RBB	Ballygawley Health Centre	01	Ceiling Panel	Ceiling (including above suspended ceiling)	Insulating Board	NO ASBESTOS	Unsealed Board	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	03/06/2014	Identified	No Asbestos Detected	68728	BA3667/06	9327/17	18/04/2018	WH Stephens
#REF!	RBB	Ballygawley Health Centre	01	Ceiling Panel		Insulating Board	NO ASBESTOS	Unsealed Board	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	03/06/2014	Strongly Presumed Similar to	No Asbestos Detected	68729	BA3667/06	9327/17	18/04/2018	WH Stephens
#REF!	RBB	Ballygawley Health Centre	01	Stair Nosing		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68730	BA3667/07	9327/17	18/04/2018	WH Stephens
#REF!	RBB	Ballygawley Health Centre	01	Fuse Flash Guards		Textiles & Paper	Presumed Asbestos	Enclosed Fuse Flash Guards	Medium	Apply caution when maintaining and affix ID labels	Re-inspection	HSG227	Unchecked	Medium Risk	8	03/04/2021	Presumed	Medium Risk	68731		9811/19	18/11/2019	WH Stephens
#REF!	RJK	Oaklands-Victoria Grove	01	Roofing Felts		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68732	BA3661/01	9327/17	22/04/2018	WH Stephens
#REF!	RJK	Oaklands-Victoria Grove	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Very Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68733	BA3661/02	9327/17	22/04/2018	WH Stephens
#REF!	RJK	Oaklands-Victoria Grove	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Very Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68734	BA3661/02	9327/17	22/04/2018	WH Stephens
#REF!	RJK	Oaklands-Victoria Grove	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Very Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68735	BA3661/02	9327/17	22/04/2018	WH Stephens
#REF!	RJK	Oaklands-Victoria Grove	01	Fire Proof Panel	Internal to fire Safe	Insulating Board	Presumed Asbestos	Encased	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Medium Risk	7	27/03/2021	Presumed	Medium Risk	68736		9811/19	20/01/2020	WH Stephens
#REF!	RJK	Oaklands-Victoria Grove	01	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Very Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68737	BA3661/03	9327/17	22/04/2018	WH Stephens
#REF!	RJK	Oaklands-Victoria Grove	01	Door Panel	Meter Cupboard	Insulating Board	NO ASBESTOS	Unsealed Board	Very Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68738	BA3661/04	9327/17	22/04/2018	WH Stephens
#REF!	RJK	Oaklands-Victoria Grove	01	Door Panel	Meter Cupboard	Insulating Board	NO ASBESTOS	Unsealed Board	Very Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68739	BA3661/04	9327/17	22/04/2018	WH Stephens
#REF!	RJK	Oaklands-Victoria Grove	01	Verge Cloak	Front Porches	Cement Products	NO ASBESTOS	Cement Sheets	Very Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68740	BA3661/05	9327/17	22/04/2018	WH Stephens
#REF!	NAB	St.Lukes	12	Pipe Insulation		Thermal Insulation	NO ASBESTOS	Residue Asbestos Pipe Insulation	Very Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68763	BA3657/01	9506/18	07/02/2018	WHS
#REF!	NAB	St.Lukes	12	Pipe Insulation		Thermal Insulation	NO ASBESTOS	Residue Asbestos Pipe Insulation	Very Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68764	BA3657/01	9506/18	07/02/2018	WHS
#REF!	NAB	St.Lukes	12	Pipe Insulation		Thermal Insulation	NO ASBESTOS	Residue Asbestos Pipe Insulation	Very Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68765	BA3657/01	9506/18	07/02/2018	WHS
#REF!	NAB	St.Lukes	12	Pipe Insulation		Thermal Insulation	NO ASBESTOS	Residue Asbestos Pipe Insulation	Very Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68766	BA3657/01	9506/18	07/02/2018	WHS
#REF!	NAB	St.Lukes	12	Pipe Insulation		Thermal Insulation	NO ASBESTOS	Residue Asbestos Pipe Insulation	Very Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68767	BA3657/01	9506/18	07/02/2018	WHS
#REF!	NAB	St.Lukes	12	Pipe Insulation		Thermal Insulation	NO ASBESTOS	Residue Asbestos Pipe Insulation	Very Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68768	BA3657/01	9506/18	07/02/2018	WHS
#REF!	NAB	St.Lukes	12	Pipe Insulation		Thermal Insulation	NO ASBESTOS	Residue Asbestos Pipe Insulation	Very Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68769	BA3657/01	9506/18	07/02/2018	WHS
#REF!	NAB	St.Lukes	12	Pipe Insulation		Thermal Insulation	NO ASBESTOS	Residue Asbestos Pipe Insulation	Very Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68770	BA3657/01	9506/18	07/02/2018	WHS
#REF!	NAB	St.Lukes	12	Pipe Insulation		Thermal Insulation	NO ASBESTOS	Residue Asbestos Pipe Insulation	Very Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68771	BA3657/01	9506/18	07/02/2018	WHS
#REF!	NAB	St.Lukes	12	Pipe Insulation		Thermal Insulation	NO ASBESTOS	Residue Asbestos Pipe Insulation	Very Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68772	BA3657/01	9506/18	07/02/2018	WHS
#REF!	NAB	St.Lukes	12	Pipe Insulation		Thermal Insulation	NO ASBESTOS	Residue Asbestos Pipe Insulation	Very Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68773	BA3657/01	9506/18	07/02/2018	WHS
#REF!	NAB	St.Lukes	12	Pipe Insulation		Thermal Insulation	NO ASBESTOS	Residue Asbestos Pipe Insulation	Very Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68774	BA3657/01	9506/18	07/02/2018	WHS
#REF!	NAB	St.Lukes	12	Pipe Insulation		Thermal Insulation	NO ASBESTOS	Residue Asbestos Pipe Insulation	Very Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68775	BA3657/01	9506/18	07/02/2018	WHS
#REF!	NAB	St.Lukes	12	Pipe Insulation		Thermal Insulation	NO ASBESTOS	Residue Asbestos Pipe Insulation	Very Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68776	BA3657/01	9506/18	07/02/2018	WHS

#REF!	NAB	St.Lukes	12	Pipe Insulation		Thermal Insulation	NO ASBESTOS	Residue Asbestos Pipe Insulation	Very Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68777	BA3657/01	9506/18	07/02/2018	WHS
#REF!	NAB	St.Lukes	12	Pipe Insulation		Thermal Insulation	NO ASBESTOS	Residue Asbestos Pipe Insulation	Very Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68778	BA3657/01	9506/18	07/02/2018	WHS
#REF!	NAB	St.Lukes	12	Pipe Insulation		Thermal Insulation	NO ASBESTOS	Residue Asbestos Pipe Insulation	Very Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68779	BA3657/01	9506/18	07/02/2018	WHS
#REF!	NAB	St.Lukes	12	Pipe Insulation		Thermal Insulation	NO ASBESTOS	Residue Asbestos Pipe Insulation	Very Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68780	BA3657/01	9506/18	07/02/2018	WHS
#REF!	NAB	St.Lukes	12	Pipe Insulation		Thermal Insulation	NO ASBESTOS	Residue Asbestos Pipe Insulation	Very Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68781	BA3657/01	9506/18	07/02/2018	WHS
#REF!	NAB	St.Lukes	12	Pipe Insulation		Thermal Insulation	NO ASBESTOS	Residue Asbestos Pipe Insulation	Very Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68782	BA3657/01	9506/18	07/02/2018	WHS
#REF!	NAB	St.Lukes	12	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Very Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68783	BA3657/02	9506/18	07/02/2018	WHS
#REF!	NAB	St.Lukes	12	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Very Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68784	BA3657/02	9506/18	07/02/2018	WHS
#REF!	NAB	St.Lukes	12	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Very Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68785	BA3657/02	9506/18	07/02/2018	WHS
#REF!	NAB	St.Lukes	12	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Very Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68786	BA3657/02	9506/18	07/02/2018	WHS
#REF!	NAB	St.Lukes	12	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Very Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68787	BA3657/02	9506/18	07/02/2018	WHS
#REF!	NAB	St.Lukes	12	Stair Nosing		Composite Material	NO ASBESTOS	Composite Materials	Very Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68788	BA3657/03	9506/18	07/02/2018	WHS
#REF!	NAB	St.Lukes	12	Stair Nosing		Composite Material	NO ASBESTOS	Composite Materials	Very Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68789	BA3657/03	9506/18	07/02/2018	WHS
#REF!	NAB	St.Lukes	12	Stair Nosing		Composite Material	NO ASBESTOS	Composite Materials	Very Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68790	BA3657/03	9506/18	07/02/2018	WHS
#REF!	NAB	St.Lukes	12	Lino Flooring		Composite Material	NO ASBESTOS	Composite Materials	Very Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68791	BA3657/04	9506/18	07/02/2018	WHS
#REF!	NAB	St.Lukes	12	Lino Flooring		Composite Material	NO ASBESTOS	Composite Materials	Very Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68792	BA3657/04	9506/18	07/02/2018	WHS
#REF!	NAB	St.Lukes	12	Lino Flooring		Composite Material	NO ASBESTOS	Composite Materials	Very Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68793	BA3657/04	9506/18	07/02/2018	WHS
#REF!	NAB	St.Lukes	12	Stair Nosing		Composite Material	NO ASBESTOS	Composite Materials	Very Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68794	BA3657/05	9506/18	07/02/2018	WHS
#REF!	NAB	St.Lukes	12	Stair Nosing		Composite Material	NO ASBESTOS	Composite Materials	Very Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68795	BA3657/05	9506/18	07/02/2018	WHS
#REF!	NAB	St.Lukes	12	Stair Nosing		Composite Material	NO ASBESTOS	Composite Materials	Very Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68796	BA3657/05	9506/18	07/02/2018	WHS
#REF!	NAB	St.Lukes	12	Stair Nosing		Composite Material	NO ASBESTOS	Composite Materials	Very Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68797	BA3657/05	9506/18	07/02/2018	WHS
#REF!	NAB	St.Lukes	12	Stair Nosing		Composite Material	NO ASBESTOS	Composite Materials	Very Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68798	BA3657/05	9506/18	07/02/2018	WHS
#REF!	NAB	St.Lukes	12	Stair Nosing		Composite Material	NO ASBESTOS	Composite Materials	Very Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68799	BA3657/05	9506/18	07/02/2018	WHS
#REF!	NAB	St.Lukes	12	Stair Nosing		Composite Material	NO ASBESTOS	Composite Materials	Very Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68800	BA3657/05	9506/18	07/02/2018	WHS
#REF!	NAB	St.Lukes	12	Stair Nosing		Composite Material	NO ASBESTOS	Composite Materials	Very Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68801	BA3657/05	9506/18	07/02/2018	WHS
#REF!	NAB	St.Lukes	12	Fuse Flash Guards	Electric Cupboard	Textiles & Paper	Presumed Asbestos	Enclosed Fuse Flash Guards	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Medium Risk	8	22/01/2021	Presumed	Medium Risk	68802		9506/18	09/01/2020	WHS
#REF!	NAB	St.Lukes	12	Fuse Flash Guards	Electrics Cupboard	Textiles & Paper	Presumed Asbestos	Enclosed Fuse Flash Guards	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Medium Risk	8	22/01/2021	Presumed	Medium Risk	68803		9506/18	09/01/2020	WHS
#REF!	NAB	St.Lukes	12	Fuse Flash Guards		Textiles & Paper	Presumed Asbestos	Enclosed Fuse Flash Guards	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Medium Risk	8	27/01/2021	Presumed	Medium Risk	68804		9506/18	09/01/2020	WHS
#REF!	NAB	St.Lukes	12	Fuse Flash Guards		Textiles & Paper	Presumed Asbestos	Enclosed Fuse Flash Guards	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Medium Risk	8	22/01/2021	Presumed	Medium Risk	68805		9506/18	09/01/2020	WHS
#REF!	NAB	St.Lukes	12	Fuse Flash Guards		Textiles & Paper	Presumed Asbestos	Enclosed Fuse Flash Guards	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Medium Risk	8	22/01/2021	Presumed	Medium Risk	68806		9506/18	09/01/2020	WHS
#REF!	NAB	St.Lukes	12	Fuse Flash Guards	Electric Cupboard	Textiles & Paper	Presumed Asbestos	Enclosed Fuse Flash Guards	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Medium Risk	8	22/01/2021	Presumed	Medium Risk	68807		9506/18	09/01/2020	WHS
#REF!	NAB	St.Lukes	12	Fuse Flash Guards		Textiles & Paper	Presumed Asbestos	Enclosed Fuse Flash Guards	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Medium Risk	8	25/08/2020	Presumed	Medium Risk	68808		9506/18	09/01/2020	WHS
#REF!	NAB	St.Lukes	12	Fuse Flash Guards		Textiles & Paper	Presumed Asbestos	Enclosed Fuse Flash Guards	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Medium Risk	8	23/07/2020	Presumed	Medium Risk	68809		9506/18	09/01/2020	WHS
#REF!	NAB	St.Lukes	12	Fuse Flash Guards		Textiles & Paper	Presumed Asbestos	Enclosed Fuse Flash Guards	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Medium Risk	8	22/01/2021	Presumed	Medium Risk	68810		9506/18	09/01/2020	WHS
#REF!	NAB	St.Lukes	12	Fuse Flash Guards		Textiles & Paper	Presumed Asbestos	Enclosed Fuse Flash Guards	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Medium Risk	8	22/01/2021	Presumed	Medium Risk	68811		9506/18	09/01/2020	WHS
#REF!	NAB	St.Lukes	12	Fuse Flash Guards		Textiles & Paper	Presumed Asbestos	Enclosed Fuse Flash Guards	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Medium Risk	8	22/01/2021	Presumed	Medium Risk	68812		9506/18	09/01/2020	WHS
#REF!	NAB	St.Lukes	12	Fuse Flash Guards		Textiles & Paper	Presumed Asbestos	Enclosed Fuse Flash Guards	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Medium Risk	8	27/01/2021	Presumed	Medium Risk	68813		9506/18	09/01/2020	WHS
#REF!	NAB	St.Lukes	12	Fuse Flash Guards		Textiles & Paper	Presumed Asbestos	Enclosed Fuse Flash Guards	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Medium Risk	8	27/01/2021	Presumed	Medium Risk	68814		9506/18	09/01/2020	WHS
#REF!	NAB	St.Lukes	12	Fuse Flash Guards		Textiles & Paper	NO ASBESTOS	Enclosed Fuse Flash Guards	Medium	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	08/02/2019	Presumed	Asbestos Removed	68815		9506/18	07/02/2018	WHS
#REF!	NAB	St.Lukes	12	Fuse Flash Guards		Textiles & Paper	Presumed Asbestos	Enclosed Fuse Flash Guards	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Medium Risk	8	22/01/2021	Presumed	Medium Risk	68816		9506/18	09/01/2020	WHS
#REF!	NAB	St.Lukes	12	Wall Panels	Electrical Cupboard	Insulating Board	NO ASBESTOS	Unsealed Board	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68817	BA3657/06	9506/18	07/02/2018	WHS
#REF!	NAB	St.Lukes	12	Wall Panels	Electrical Cupboard	Insulating Board	NO ASBESTOS	Unsealed Board	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68818	BA3657/06	9506/18	07/02/2018	WHS
#REF!	NAB	St.Lukes	12	Wall Panels	Electrics Cupboard	Insulating Board	NO ASBESTOS	Unsealed Board	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68819	BA3657/06	9506/18	07/02/2018	WHS
#REF!	NAB	St.Lukes	12	Stair Nosing		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68820	BA3657/07	9506/18	07/02/2018	WHS
#REF!	NAB	St.Lukes	12	Stair Nosing		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68821	BA3657/07	9506/18	07/02/2018	WHS
#REF!	NAB	St.Lukes	12	Stair Nosing		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68822	BA3657/07	9506/18	07/02/2018	WHS
#REF!	NAB	St.Lukes	12	Stair Nosing		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68823	BA3657/07	9506/18	07/02/2018	WHS
#REF!	NAB	St.Lukes	12	Stair Nosing	To Basement	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review ? No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68824	BA3657/07	9506/18	07/02/2018	WHS
#REF!	NAB	St.Lukes	12	Ceilino Tiles		Insulating Board	Amosite	Unsealed Board	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Medium Risk	7	22/01/2021	Identified	Medium Risk	68825	BA3657/08	9506/18	09/01/2020	WHS
#REF!	NAB	St.Lukes	12	Roofing Felts		Composite Material	NO ASBESTOS	Composite Materials	Very Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68826	BA3657/09	9506/18	07/02/2018	WHS
#REF!	NAB	St.Lukes	12	Roofing Felts		Composite Material	NO ASBESTOS	Composite Materials	Very Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68827	BA3657/09	9506/18	07/02/2018	WHS
#REF!	NAB	St.Lukes	12	Board	Attic Hatch	Insulating Board	NO ASBESTOS	Unsealed Board	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68828	BA3657/10	9506/18	07/02/2018	WHS
#REF!	NAB	St.Lukes	12	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Very Low	No further action required (Asbestos removed)	ACM Removed	HSG227	Unchecked	NO ASBESTOS	0	08/02/2019	Identified	Asbestos Removed	68829	BA3657/11	9506/18	07/02/2018	WHS
#REF!	NAB	St.Lukes	12	Sink Pad		Composite Material	Chrysotile	Composite Materials	Very Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	2	22/01/2021	Strongly Presumed Similar to	Very Low Risk	68830	BA3657/11	9506/18	09/01/2020	WHS
#REF!	NAB	St.Lukes	12	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Very Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	Asbestos Removed	68831	BA3657/11	9506/18	07/02/2018	WHS
#REF!	NAB	St.Lukes	12	Sink Pad		Composite Material	Chrysotile	Composite Materials	Very Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	2	22/01/2021	Strongly Presumed Similar to	Very Low Risk	68832	BA3657/11	9506/18	09/01/2020	WHS
#REF!	NAB	St.Lukes	12	Sink Pad		Composite Material	Chrysotile	Composite Materials	Very Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	2	22/01/2021	Strongly Presumed Similar to	Very Low Risk	68833	BA3657/11	9506/18	09/01/2020	WHS
#REF!	NAB	St.Lukes	12	Sink Pad		Composite Material	Chrysotile	Composite Materials	Very Low	Apply caution when maintaining and affix ID labels	Re-inspection	HSG227	Unchecked	Very Low Risk	2	22/01/2021	Strongly Presumed Similar to	Very Low Risk	68834	BA3657/11	9506/18	09/01/2020	WHS
#REF!	NAB	St.Lukes	12	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Very Low	Conduct annual routine inspections	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	08/02/2019	Strongly Presumed Similar to	Asbestos Removed	68835	BA3657/11	9506/18	07/02/2018	WHS
#REF!	NAB	St.Lukes	12	Lino Flooring		Composite Material	NO ASBESTOS	Composite Materials	Very Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68836	BA3657/12	9506/18	07/02/2018	WHS
#REF!	NAB	St.Lukes	12	Lino Flooring		Composite Material	NO ASBESTOS	Composite Materials	Very Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68837	BA3657/12	9506/18	07/02/2018	WHS
#REF!	NAB	St.Lukes	12	Textured Coatings	Ceiling	Decorative Coatings	NO ASBESTOS	Textured Coating	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68838	BA3657/13	9506/18	07/02/2018	WHS
#REF!	NAB	St.Lukes	12	Insulation Blocks	Freezer Doors	Insulating Board	Presumed Asbestos	Encased	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Medium Risk	7	27/01/2021	Presumed	Medium Risk	68839		9506/18	09/01/2020	WHS
#REF!	NAB	St.Lukes	12	Boiler Lagging	Boiler Insulation	Thermal Insulation	Presumed Asbestos	Encased	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Medium Risk	8	22/01/2021	Presumed	Medium Risk	68840		9506/18	09/01/2020	WHS
#REF!	NAB	St.Lukes	12	Gaskets	Pipework	Textiles & Paper	Chrysotile	Sealed	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	4	22/01/2021	Identified	Very Low Risk	68841	BA3657/14	9506/18	09/01/2020	WHS
#REF!	NAB	St.Lukes	12	Rope Seal	Rear of Boiler	Textiles & Paper	NO ASBESTOS	Unsealed Rope	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68842	BA3657/15	9506/18	07/02/2018	WHS
#REF!	NAB	St.Lukes	12	Door Panel		Insulating Board	NO ASBESTOS	Partially Sealed Asbestos Insulation Board	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68843	BA3657/16	9506/18	07/02/2018	WHS
#REF!	NAB	St.Lukes	12	Door Panel		Insulating Board	NO ASBESTOS	Partially Sealed Asbestos Insulation Board	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68844	BA3657/16	9506/18	07/02/2018	WHS
#REF!	NAB	St.Lukes	12	Duct Access Panels	Board to Duct	Insulating Board	NO ASBESTOS	Unsealed Board	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68845	BA3657/17	9506/18	07/02/2018	WHS
#REF!	NAB	St.Lukes	12	Duct Access Panels		Insulating Board	NO ASBESTOS	Unsealed Board	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68846	BA3657/17	9506/18	07/02/2018	WHS
#REF!	NAB	St.Lukes	12	Wall Panels		Insulating Board	NO ASBESTOS	Unsealed Board	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68847	BA3657/18	9506/18	07/02/2018	WHS
#REF!	NAB	St.Lukes	12	Wall Panels		Insulating Board	NO ASBESTOS	Unsealed Board	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68848	BA3657/18	9506/18	07/02/2018	WHS
#REF!	NAB	St.Lukes	12	Cistern		Cement Products	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68849	BA3657/19	9506/18	07/02/2018	WHS
#REF!	NAB	St.Lukes	12	Brake Pads	Lift Machinerv	Textiles & Paper	Presumed Asbestos	Unsealed	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Hioh Risk	10	27/01/2021	Presumed	Hioh Risk	68850		9506/18	09/01/2020	WHS
#REF!	NAB	St.Lukes	12	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Very Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68851	BA3657/20	9506/18	07/02/2018	WHS
#REF!	NAB	St.Lukes	12	Ceiling Board	Store	Insulating Board	NO ASBESTOS	Unsealed Board	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68852	BA3657/21	9506/18	07/02/2018	WHS
#REF!	NAB	St.Lukes	12	Ceiling Board	Compressor Store	Insulating Board	NO ASBESTOS	Unsealed Board	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68853	BA3657/22	9506/18	07/02/2018	WHS
#REF!	NAB	St.Lukes	12	Toilet Cistern	Toilet Seat	Cement Products	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68854	BA3657/23	9506/18	07/02/2018	WHS
#REF!	NAB	St.Lukes	12		Lift Shaft					Conduct annual routine inspections	Re-inspection	HSG227	Checked	Hioh Risk	0	27/01/2021		Hioh Risk	68855		9506/18	09/01/2020	WHS
#REF!	NAB	St.Lukes	12								Review of Data	HSG227	Checked	High Risk	0	27/01/2021			68856		9506/18	09/01/2020	WHS
#REF!	RBD	Richhill Health Centre	01	Floor Tiles	Edging to Threshold	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68857	BA3662/01	9344/17	20/04/2018	WH Stephens
#REF!	RBD	Richhill Health Centre	01	Floor Tiles	Edging to Threshold	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68858	BA3662/01	9344/17	20/04/2018	WH Stephens
#REF!	RBD	Richhill Health Centre	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68859	BA3662/01	9344/17	20/04/2018	WH Stephens
#REF!	RBD	Richhill Health Centre	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68860	BA3662/01	9344/17	20/04/2018	WH Stephens
#REF!	RBD	Richhill Health Centre	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68861	BA3662/01	9344/17	20/04/2018	WH Stephens

#REF!	RBD	Richhill Health Centre	01	Sink Pad		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	08/04/2021	Identified	Very Low Risk	68862	BA3662/02	9501/18	14/11/2019	WH Stephens
#REF!	RBD	Richhill Health Centre	01	Sink Pad		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	08/04/2021	Strongly Presumed Similar to	Very Low Risk	68863	BA3662/02	9501/18	14/11/2019	WH Stephens
#REF!	RBD	Richhill Health Centre	01	Sink Pad		Composite Material	Chrysotile	Composite Materials	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	4	08/04/2021	Strongly Presumed Similar to	Very Low Risk	68864	BA3662/02	9501/18	14/11/2019	WH Stephens
#REF!	RBD	Richhill Health Centre	01	Ceiling Board	Cupboard	Insulating Board	NO ASBESTOS	Unsealed Board	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68865	BA3662/03	9344/17	20/04/2018	WH Stephens
#REF!	RBD	Richhill Health Centre	01	Cement Flue	In Wall	Cement Products	Chrysotile	Concealed Cement	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	4	08/04/2021	Identified	Very Low Risk	68866	BA3662/04	9501/18	14/11/2019	WH Stephens
#REF!	RBD	Richhill Health Centre	01	Cement Flue		Cement Products	Chrysotile	Concealed Cement	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	08/04/2021	Strongly Presumed Similar to	Very Low Risk	68867	BA3662/04	9501/18	14/11/2019	WH Stephens
#REF!	RBD	Richhill Health Centre	01	Door Panel	Board to Door	Insulating Board	NO ASBESTOS	Unsealed Board	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	Asbestos Removed	68868	BA3662/05	9344/17	20/04/2018	WH Stephens
#REF!	RBD	Richhill Health Centre	01	Fuse Flash Guards		Textiles & Paper	Presumed Asbestos	Enclosed Fuse Flash Guards	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Medium Risk	8	08/04/2021	Presumed	Medium Risk	68869		9501/18	14/11/2019	WH Stephens
#REF!	RBD	Richhill Health Centre	01	Fuse Flash Guards		Textiles & Paper	Presumed Asbestos	Enclosed Fuse Flash Guards	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Medium Risk	8	08/04/2021	Presumed	Medium Risk	68870		9501/18	14/11/2019	WH Stephens
#REF!	RBD	Richhill Health Centre	01	Gaskets	Gasket to Boiler Burner	Textiles & Paper	NO ASBESTOS	Unsealed	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68871	BA3662/06	9344/17	20/04/2018	WH Stephens
#REF!	RBD	Richhill Health Centre	01	Stair Nosing	Stairs	Composite Material	NO ASBESTOS	Composite Material	Very Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68872	BA3662/07	9344/17	20/04/2018	WH Stephens
#REF!	RBD	Richhill Health Centre	01	Ceiling Panels		Cement Products	Chrysotile	Cement Sheets	Low	Apply caution when maintaining and affix ID labels	Re-inspection	HSG227	Unchecked	Very Low Risk	4	08/04/2021	Identified	Very Low Risk	68873	BA3662/08	9811/19	14/11/2019	WH Stephens
#REF!	RBD	Richhill Health Centre	01	Gaskets	Pipework	Textiles & Paper	Chrysotile	Sealed	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	4	08/04/2021	Identified	Very Low Risk	68874	BA3662/09	9501/18	14/11/2019	WH Stephens
#REF!	RBD	Richhill Health Centre	01	Bitumen Felt	Skids on CWST	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68875	BA3662/10	9344/17	20/04/2018	WH Stephens
#REF!	RBD	Richhill Health Centre	01	Verge Cloak	Roof	Cement Products	Presumed Asbestos	Cement Sheets	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Low Risk	6	08/04/2021	Presumed	Low Risk	68876		9501/18	14/11/2019	WH Stephens
#REF!	RBC	Markethill Health Centre	01	Fuse Flash Guards		Textiles & Paper	Presumed Asbestos	Enclosed Fuse Flash Guards	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Medium Risk	8	03/04/2021	Presumed	Medium Risk	68877		9501/18	14/11/2019	WHS
#REF!	RBC	Markethill Health Centre	01	Fuse Flash Guards		Textiles & Paper	Presumed Asbestos	Enclosed Fuse Flash Guards	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Medium Risk	8	03/04/2021	Presumed	Asbestos Removed	68878		9501/18	14/11/2019	WHS
#REF!	RBC	Markethill Health Centre	01	Fuse Flash Guards		Textiles & Paper	NO ASBESTOS	Enclosed Fuse Flash Guards	Medium	No further action required (Asbestos removed)	ACM Removed	HSG227	Unchecked	NO ASBESTOS	0	14/05/2020	Presumed	Asbestos Removed	68879		9506/18	25/01/2019	WHS
#REF!	RBC	Markethill Health Centre	01	Floor Tiles		Composite Material	Chrysotile	Composite Material	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	03/04/2021	Identified	Very Low Risk	68880	BA3663/01	9811/19	14/11/2019	WHS
#REF!	RBC	Markethill Health Centre	01	Bitumen Felt	Skids to CWST	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68881	BA3663/02	9506/18	25/01/2019	WHS
#REF!	RBC	Markethill Health Centre	01	Sink Pad		Composite Material	NO ASBESTOS	Composite Material	Very Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68882	BA3663/03	9506/18	25/01/2019	WHS
#REF!	RBC	Markethill Health Centre	01	Roofing Felts		Composite Material	NO ASBESTOS	Composite Material	Very Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68883	BA3663/04	9506/18	25/01/2019	WHS
#REF!	RBC	Markethill Health Centre	01	Board	Board to Attic Hatch	Insulating Board	Amosite/Chrysotile	Unsealed Board	Medium	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	Medium Risk	7	03/04/2021	Identified	Medium Risk	68884	BA3663/05	9811/19	14/11/2019	WHS
#REF!	RBC	Markethill Health Centre	01	Gaskets	Pipework	Textiles & Paper	Chrysotile	Sealed	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	4	03/04/2021	Identified	Very Low Risk	68885	BA3663/06	9501/18	14/11/2019	WHS
#REF!	RBC	Markethill Health Centre	01	Ceiling Board		Insulating Board	NO ASBESTOS	Unsealed Board	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68886	BA3663/07	9506/18	25/01/2019	WHS
#REF!	RBC	Markethill Health Centre	01	Rope Seal	Front of Boiler	Textiles & Paper	NO ASBESTOS	Unsealed Rope	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68887	BA3663/08	9506/18	25/01/2019	WHS
#REF!	RBC	Markethill Health Centre	01	Sink Pad		Composite Material	NO ASBESTOS	Composite Material	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68888	BA3663/09	9506/18	25/01/2019	WHS
#REF!	RBC	Markethill Health Centre	01	Lino Flooring		Composite Material	NO ASBESTOS	Composite Material	Very Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68889	BA3663/10	9506/18	25/01/2019	WHS
#REF!	RBC	Markethill Health Centre	01	Verge Cloak	Roof	Cement Products	Chrysotile	Cement Sheets	Very Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	03/04/2021	Identified	Very Low Risk	68890	BA3663/11	9501/18	14/11/2019	WHS
#REF!	RBC	Markethill Health Centre	01	Bitumen Felt	Roof	Composite Material	NO ASBESTOS	Composite Material	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68891	BA3663/12	9506/18	25/01/2019	WHS
#REF!	RAA	South Tyrone Hospital	12	Stair Nosing		Composite Material	Chrysotile	Composite Material	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	15/12/2023	Identified	Very Low Risk	68892	BA3664/01	9302/2	15/12/2022	WHS
#REF!	RAA	South Tyrone Hospital	12	Floor Tiles	Black VFT	Composite Material	Chrysotile	Composite Material	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	15/12/2023	Identified	Very Low Risk	68893	BA3664/02	9302/2	15/12/2022	WHS
#REF!	RAA	South Tyrone Hospital	12	Floor Tiles	Vinyl floor tile	Composite Material	Chrysotile	Composite Material	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	15/12/2023	Identified	Very Low Risk	68894	BA9307	9302/2	15/12/2022	WHS
#REF!	RAA	South Tyrone Hospital	12	Wall Panels		Insulating Board	NO ASBESTOS	Unsealed Board	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68895	BA3664/04	9506/18	20/11/2018	WHS
#REF!	RAA	South Tyrone Hospital	12	Fuse Flash Guards		Textiles & Paper	NO ASBESTOS	Enclosed Fuse Flash Guards	Medium	See Report for details	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Presumed	Asbestos Removed	68896		9506/18	20/11/2018	WHS
#REF!	RAA	South Tyrone Hospital	12	Fuse Flash Guards		Textiles & Paper	NO ASBESTOS	Enclosed Fuse Flash Guards	Medium	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	26/11/2019	Presumed	Asbestos Removed	68897		9506/18	20/11/2018	WHS
#REF!	RAA	South Tyrone Hospital	12	Fuse Flash Guards		Textiles & Paper	NO ASBESTOS	Enclosed Fuse Flash Guards	Medium	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Presumed	Asbestos Removed	68898		9506/18	20/11/2018	WHS
#REF!	RAA	South Tyrone Hospital	12	Fuse Flash Guards		Textiles & Paper	Presumed Asbestos	Enclosed Fuse Flash Guards	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Medium Risk	8	15/12/2023	Presumed	Medium Risk	68899		9302/2	15/12/2022	WHS
#REF!	RAA	South Tyrone Hospital	12	Fire Proof Panel	Internal Insulation to Fire Safe	Insulating Board	Presumed Asbestos	Encased	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Medium Risk	7	15/12/2023	Presumed	Medium Risk	68900		9302/2	15/12/2022	WHS
#REF!	RAA	South Tyrone Hospital	12	Floor Tiles	Under Carpet	Composite Material		Composite Material	Low	No further action required (Asbestos removed)	Re-inspection	HSG227	Unchecked	NO ASBESTOS	0	15/12/2023	Identified	Asbestos Removed	68901	BA3664/05	9302/2	15/12/2022	WHS
#REF!	RAA	South Tyrone Hospital	12	Ceiling Tiles		Insulating Board	NO ASBESTOS	Unsealed Board	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68902	BA3664/06	9506/18	20/11/2018	WHS
#REF!	RAA	South Tyrone Hospital	12	Gaskets	Pipework	Textiles & Paper	NO ASBESTOS	Sealed	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	Asbestos Removed	68903	BA3664/07	9506/18	20/11/2018	WHS
#REF!	RAA	South Tyrone Hospital	12	Gaskets	Square Gasket	Textiles & Paper	NO ASBESTOS	Unsealed	Low	No further action required (Asbestos removed)	ACM Removed	HSG227	Unchecked	NO ASBESTOS	0	26/11/2019	Identified	Asbestos Removed	68904	BA3664/08	9506/18	20/11/2018	WHS
#REF!	RAA	South Tyrone Hospital	12	Debris Insulation	Pipework	Loose Asbestos	NO ASBESTOS	Residue Asbestos Pipe Insulation	High	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68905	BA3664/09	9506/18	20/11/2018	WHS
#REF!	RAA	South Tyrone Hospital	12	NO ASBESTOS	Brake shoes	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Re-inspection	HSG227	Unchecked	NO ASBESTOS	0	26/11/2019	Identified	No Asbestos Detected	68906	BA9307	9506/18	20/11/2018	WHS
#REF!	RAA	South Tyrone Hospital	12	Bitumen Felt	Ventilation Plant Shed Roof	Composite Material	NO ASBESTOS	Composite Material	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68907	BA3664/10	9506/18	20/11/2018	WHS
#REF!	RHC1	Lisanally House	01	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68926	BA3666/01	9506/18	11/05/2018	WHS
#REF!	RHC1	Lisanally House	01	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68927	BA3666/01	9506/18	11/05/2018	WHS
#REF!	RHC1	Lisanally House	01	Lino Flooring	Under Carpet	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68928	BA3666/02	9506/18	11/05/2018	WHS
#REF!	RHC1	Lisanally House	01	Lino Flooring	Under Carpet	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68929	BA3666/02	9506/18	11/05/2018	WHS
#REF!	RHC1	Lisanally House	01	Lino Flooring		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68930	BA3666/02	9506/18	11/05/2018	WHS
#REF!	RHC1	Lisanally House	01	Lino Flooring	Under Carpet	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68931	BA3666/02	9506/18	11/05/2018	WHS
#REF!	RHC1	Lisanally House	01	Lino Flooring	Under Carpet	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68932	BA3666/02	9506/18	11/05/2018	WHS
#REF!	RHC1	Lisanally House	01	Lino Flooring	Under Carpet	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68933	BA3666/02	9506/18	11/05/2018	WHS
#REF!	RHC1	Lisanally House	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68934	BA3666/03	9506/18	11/05/2018	WHS
#REF!	RHC1	Lisanally House	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68935	BA3666/03	9506/18	11/05/2018	WHS
#REF!	RHC1	Lisanally House	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68936	BA3666/03	9506/18	11/05/2018	WHS
#REF!	RHC1	Lisanally House	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68937	BA3666/03	9506/18	11/05/2018	WHS
#REF!	RHC1	Lisanally House	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68938	BA3666/03	9506/18	11/05/2018	WHS
#REF!	RHC1	Lisanally House	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68939	BA3666/03	9506/18	11/05/2018	WHS
#REF!	RHC1	Lisanally House	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68940	BA3666/03	9506/18	11/05/2018	WHS
#REF!	RHC1	Lisanally House	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68941	BA3666/03	9506/18	11/05/2018	WHS
#REF!	RHC1	Lisanally House	01	Stair Nosing		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	03/04/2021	Identified	Very Low Risk	68942	BA3666/04	9811/19	18/11/2019	WHS
#REF!	RHC1	Lisanally House	01	Stair Nosing		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	03/04/2021	Strongly Presumed Similar to	Very Low Risk	68943	BA3666/04	9811/19	18/11/2019	WHS
#REF!	RHC1	Lisanally House	01	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68944	BA3666/05	9506/18	11/05/2018	WHS
#REF!	RHC1	Lisanally House	01	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68945	BA3666/05	9506/18	11/05/2018	WHS
#REF!	RHC1	Lisanally House	01	Fuse Flash Guards		Textiles & Paper	Presumed Asbestos	Enclosed Fuse Flash Guards	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Medium Risk	8	03/04/2021	Presumed	Medium Risk	68946		9811/19	18/11/2019	WHS
#REF!	RHC1	Lisanally House	01	Fuse Flash Guards	Fuse flash guard	Textiles & Paper	Chrysotile	Enclosed Fuse Flash Guards	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Low Risk	6	03/04/2021	Identified	Low Risk	68947	BA9276	9811/19	18/11/2019	WHS
#REF!	RHC1	Lisanally House	01	Fuse Flash Guards		Textiles & Paper	Presumed Asbestos	Enclosed Fuse Flash Guards	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Medium Risk	8	03/04/2021	Presumed	Medium Risk	68948		9811/19	18/11/2019	WHS
#REF!	RHC1	Lisanally House	01	Fuse Flash Guards	Fuse flash guard	Textiles & Paper	Chrysotile	Enclosed Fuse Flash Guards	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Low Risk	6	03/04/2021	Identified	Low Risk	68949	BA9276	9811/19	18/11/2019	WHS
#REF!	RHC1	Lisanally House	01	Fuse Flash Guards		Textiles & Paper	Presumed Asbestos	Enclosed Fuse Flash Guards	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Medium Risk	8	03/04/2021	Presumed	Medium Risk	68950		9811/19	18/11/2019	WHS
#REF!	RHC1	Lisanally House	01	Fuse Flash Guards		Textiles & Paper	Presumed Asbestos	Enclosed Fuse Flash Guards	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Medium Risk	8	03/04/2021	Presumed	Medium Risk	68951		9811/19	18/11/2019	WHS
#REF!	RHC1	Lisanally House	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68952	BA3666/06	9506/18	11/05/2018	WHS
#REF!	RHC1	Lisanally House	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68953	BA3666/06	9506/18	11/05/2018	WHS
#REF!	RHC1	Lisanally House	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68954	BA3666/06	9506/18	11/05/2018	WHS
#REF!	RHC1	Lisanally House	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	68955	BA3666/06	9506/18	11/05/2018	WHS
#REF!	RHC1	Lisanally House	01	Cistern		Cement Products	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68956	BA3666/07	9506/18	11/05/2018	WHS
#REF!	RHC1	Lisanally House	01	Lino Flooring		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68957	BA3666/08	9506/18	11/05/2018	WHS
#REF!	RHC1	Lisanally House	01	Bitumen Adhesive	Roofspace-Coating to Floor	Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	03/04/2021	Identified	Very Low Risk	68958	BA3666/09	9811/19	18/11/2019	WHS
#REF!	RHC1	Lisanally House	01	Roofing Felts	Roofspace	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68959	BA3666/10	9506/18	11/05/2018	WHS
#REF!	RHC1	Lisanally House	01	Boiler Lagging	Internal Insulation to Boiler	Thermal Insulation	NO ASBESTOS	Encased	Medium	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Presumed	Asbestos Removed	68960		9506/18	11/05/2018	WHS
#REF!	RHC1	Lisanally House	01	Pipe Lagging		Thermal Insulation	NO ASBESTOS	Partially Exposed Pipework Insulation	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68961	BA3666/11	9506/18	11/05/2018	WHS
#REF!	RHC1	Lisanally House	01	Bitumen Felt	Skids to Oil Tanks	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68962	BA3666/12	9506/18	11/05/2018	WHS
#REF!	RHC1	Lisanally House	01	Ceiling Board		Insulating Board	Amosite/Chrysotile	Unsealed Board	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Medium Risk	7	03/04/2021	Identified	Medium Risk	68963	BA3666/13	9811/19	18/11/2019	WHS
#REF!	RHC1	Lisanally House	01	ND ASBESTOS	Brake shoes	NO ASBESTOS	NO ASBESTOS			Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	NO ASBESTOS	0	30/11/2019	Identified	No Asbestos Detected	68964	BA9276	9506/18	05/11/2018	WHS
#REF!	RHC1	Lisanally House	01	Artificial Slate	Roof	Cement Products	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	03/04/2021	Identified	Very Low Risk	68965	BA3666/14	9811/19	18/11/2019	WHS
#REF!	RHC1	Lisanally House	01	Verge Cloak	Garages	Cement Products	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	68966	BA3666/15	9506/18	11/05/2018	WHS
#REF!	RHC1	Lisanally House	01	Soffit Boards	Garages	Insulating Board	NO ASBESTOS	Unsealed Board	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Previously Identified	No Asbestos Detected	68967	BA3666/16	9506/18	11/05/2018	WHS
#REF!	OBB	Portadown Health & Care Centre	04				NO ASBESTOS				Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	69032		9429/1	14/03/2018	WHS

#REF!	SAA	Daisy Hill Hospital Estate	09	Floor Tiles		Composite Material	Chrysotile	Composite Materials	None	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	2	11/10/2023	Identified	Very Low Risk	69033	BA3584/01	9299/2	20/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	09	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	26/09/2023	Identified	Very Low Risk	69034	BA3584/02	9299/2	20/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	09	Floor Tiles		Composite Material	Chrysotile	Composite Materials	None	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	2	11/10/2023	Identified	Very Low Risk	69035	BA3584/03	9299/2	20/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	09	Floor Tiles		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	11/10/2023	Identified	Very Low Risk	69036	BA3584/04	9299/2	20/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	09	Floor Tiles		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	11/10/2023	Identified	Very Low Risk	69037	BA3584/05	9299/2	20/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	09	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	26/09/2023	Identified	Very Low Risk	69038	BA3584/06	9299/2	20/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	09	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	26/09/2023	Identified	Very Low Risk	69039	BA3586/01	9299/2	20/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	09	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	11/10/2023	Identified	Very Low Risk	69040	BA3586/02	9299/2	20/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	09	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	26/09/2023	Stronnly Presumed Similar to	Very Low Risk	69041	BA3586/02	9299/2	20/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	09	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	11/10/2023	Strongly Presumed Similar to	Very Low Risk	69042	BA3586/02	9299/2	20/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	09	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	11/10/2023	Stronnly Presumed Similar to	Very Low Risk	69043	BA3586/02	9299/2	20/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	09	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	11/10/2023	Identified	Very Low Risk	69044	BA3586/03	9299/2	20/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	09	Floor Tile and Bitumen Adhesive		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	06/12/2019	Strongly Presumed Similar to	Asbestos Removed	69045	BA3586/03	9327/17	19/02/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	09	Floor Tile and Bitumen Adhesive		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	Asbestos Removed	69046	BA3586/03	9327/17	19/02/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	09	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	11/10/2023	Stronnly Presumed Similar to	Very Low Risk	69047	BA3586/03	9299/2	20/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	09	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Low	Further investigation Required	Re-inspection	HSG227	Unchecked	Very Low Risk	3	28/08/2021	Strongly Presumed Similar to	Very Low Risk	69048	BA3586/03	9811/19	27/07/2020	WHS
#REF!	SAA	Daisy Hill Hospital Estate	09	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	Asbestos Removed	69049	BA3586/04	9327/17	19/02/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	09	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	Asbestos Removed	69050	BA3586/04	9327/17	19/02/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	09	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	Asbestos Removed	69051	BA3586/04	9327/17	19/02/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	09	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	17/05/2014	Strongly Presumed Similar to	Asbestos Removed	69052	BA3586/04	9327/17	19/02/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	09	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	17/05/2014	Strongly Presumed Similar to	Asbestos Removed	69053	BA3586/04	9327/17	19/02/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	09	Board		Insulating Board	NO ASBESTOS	Encapsulated Spray or Lagoing/Unsealed AIB	Medium	Remove (Controlled Conditions)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	Asbestos Removed	69054	BA3586/05	9327/17	19/02/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	09	Board		Insulating Board	NO ASBESTOS	Encapsulated Spray or Lagoing/Unsealed AIB	Medium	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	06/12/2019	Strongly Presumed Similar to	Asbestos Removed	69055	BA3586/05	9327/17	19/02/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	09	Board		Insulating Board	NO ASBESTOS	Encapsulated Spray or Lagoing/Unsealed AIB	Medium	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	Asbestos Removed	69056	BA3586/05	9327/17	19/02/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	09	Board		Insulating Board	NO ASBESTOS	Encapsulated Spray or Lagoing/Unsealed AIB	Medium	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	Asbestos Removed	69057	BA3586/05	9327/17	19/02/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	09	Floor Tile and Bitumen Adhesive		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	Asbestos Removed	69058	BA3629/09	9327/17	19/02/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	09	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Minor damage of	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	11/10/2023	Identified	Very Low Risk	69059	BA3629/10	9299/2	20/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	09	Brake Pads	Lift Motor Room	Textiles & Paper	Presumed Asbestos	Encapsulated Spray or Lagoing/Unsealed AIB	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Medium Risk	9	12/04/2023	Presumed	Medium Risk	69060		9300/22	20/04/2022	WHS
#REF!	QAC	Lurgan Hospital	14	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	69061	BA3684/01	9326/17	20/12/2017	WH Stephens
#REF!	QAC	Lurgan Hospital	14	Roofing Felts		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	69062	BA3684/02	9326/17	20/12/2017	WH Stephens
#REF!	QAC	Lurgan Hospital	14	Soffit Boards		Cement Products	Chrysotile	Cement Sheets	None	Apply caution when maintaining and affix ID labels	Review – No Change	HSG227	Unchecked	Very Low Risk	3	20/06/2014	Identified	Very Low Risk	69063	BA3684/03	9326/17	20/12/2017	WH Stephens
#REF!	QGB	Bocombra	02	Board		Insulating Board	NO ASBESTOS	Encapsulated Spray or Lagoing/Unsealed AIB	Medium	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	69064	BA3685/01	9509/18	24/01/2019	WHS
#REF!	OGB	Bocombra	02							Further Investion Required	Review – No Chanoe	HSG227	Checked	Hoh Risk	0				69065		9509/18	24/01/2019	WHS
#REF!	QCC	Dromore Health Clinic	01	Floor Tile and Bitumen Adhesive		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	04/04/2019	Presumed	Asbestos Removed	69071		9326/17	04/04/2018	WHS
#REF!	QCC	Dromore Health Clinic	01	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Low	Apply caution when maintaining and affix ID labels	Re-inspection	HSG227	Unchecked	Very Low Risk	3	09/09/2023	Identified	Very Low Risk	69072	BA3680/02	9299/22	06/04/2022	WHS
#REF!	QCC	Dromore Health Clinic	01	Door Panel		Cement Products	NO ASBESTOS	Enclosed Spray or Lagoing/Sealed AIB	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	69073	BA3680/03	9326/17	04/04/2018	WHS
#REF!	QCC	Dromore Health Clinic	01	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Low	Apply Caution when Maintaining	Re-inspection	HSG227	Unchecked	Very Low Risk	3	09/09/2023	Identified	Very Low Risk	69074	BA3680/04	9299/22	06/04/2022	WHS
#REF!	QCC	Dromore Health Clinic	01	Insulating Board Below Window		Insulating Board	NO ASBESTOS	Enclosed Spray or Lagoing/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	69075	BA3680/05	9326/17	04/04/2018	WHS
#REF!	QBC	Gilford Health Centre	01	Sink Pad		Composite Material	Chrysotile	Composite Materials	Low	Apply caution when maintaining and affix ID labels	Re-inspection	HSG227	Unchecked	Very Low Risk	3	09/09/2023	Identified	Very Low Risk	69076	BA3679/01	9299/22	11/04/2022	WHS
#REF!	QBC	Gilford Health Centre	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	69077	BA3679/02	9509/18	30/01/2019	WHS
#REF!	QBC	Gilford Health Centre	01	Fuse Flash Guards		Textiles & Paper	Presumed Asbestos	Encapsulated Spray or Lagoing/Unsealed AIB	Medium	Label & Manage	Re-inspection	HSG227	Unchecked	Medium Risk	9	09/03/2023	Presumed	Medium Risk	69078		9299/22	11/04/2022	WHS
#REF!	QBC	Gilford Health Centre	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	69079	BA3679/03	9509/18	30/01/2019	WHS
#REF!	QBC	Gilford Health Centre	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	69080	BA3679/03	9509/18	30/01/2019	WHS
#REF!	QBC	Gilford Health Centre	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	69081	BA3679/04	9509/18	30/01/2019	WHS
#REF!	QBC	Gilford Health Centre	01	Roof Slate		Cement Products	Chrysotile	Enclosed Spray or	Minor damage of	Apply Caution when Maintaining	Re-inspection	HSG227	Unchecked	Very Low Risk	4	09/09/2023	Identified	Very Low Risk	69082	BA3679/05	9509/18	11/04/2022	WHS
#REF!	QBC	Gilford Health Centre	01	Roofing Felts		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	69083	BA3679/06	9509/18	30/01/2019	WHS
#REF!	QBC	Gilford Health Centre	01	Soffit Boards		Cement Products	Chrysotile	Enclosed Spray or	None	Label & Manage	Re-inspection	HSG227	Unchecked	Very Low Risk	3	09/09/2023	Identified	Very Low Risk	69084	BA3679/07	9509/18	11/04/2022	WHS
#REF!	QBC	Gilford Health Centre	01	Gaskets		Textiles & Paper	Presumed Asbestos	Encapsulated Spray or Lagoing/Unsealed AIB	Medium	Label & Manage	Re-inspection	HSG227	Unchecked	Medium Risk	9	09/03/2023	Presumed	Medium Risk	69085		9299/22	11/04/2022	WHS
#REF!	QBC	Gilford Health Centre	01	Debris Insulation		Loose Asbestos	Presumed Asbestos	Encapsulated Spray or Lagoing/Unsealed AIB	High	Apply Caution when Maintaining	Re-inspection	HSG227	Unchecked	High Risk	12	09/12/2022	Presumed	High Risk	69086		9299/22	11/04/2022	WHS
#REF!	SAB	Mourne Hospital	12	Fire Door	SAB12 - Store (Previously Tank Room) - Room 2	Insulating Board	Amosite/Chrysotile	Enclosed Spray or Lagoing/Sealed AIB	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Low Risk	6	12/09/2023	Identified	Low Risk	69109	BA3549/01	9300/22	25/05/2022	WHS
#REF!	SAB	Mourne Hospital	12	Woven Asbestos Textile	SAB12 - Boiler Room	Textiles & Paper	NO ASBESTOS	Encapsulated Spray or Lagoing/Unsealed AIB	Medium	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	69110	BA3549/02	9509/18	01/08/2019	WHS
#REF!	SAB	Mourne Hospital	12	Floor Tiles	SAB-12-A-016	Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	12/09/2023	Identified	Very Low Risk	69111	BA3549/03	9299/22	25/05/2022	WHS
#REF!	SAB	Mourne Hospital	12	Resins	SAB12 - Room 13 - Portacabin	Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	69112	BA3549/04	9509/18	01/08/2019	WHS
#REF!	SAB	Mourne Hospital	12	Fire Proof Panel	SAB12 - Electrical Cupboard beside Recestion	Insulating Board	NO ASBESTOS	Enclosed Spray or Lagoing/Sealed AIB	Low	No further action required (Asbestos removed)	Re-inspection	HSG227	Unchecked	NO ASBESTOS	0	13/12/2022	Identified	High Risk	69113	BA3549/05	9300/22	25/05/2022	WHS
#REF!	SAB	Mourne Hospital	12	Roofing Felts	SAB12 - Roofspace	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	69114	BA3549/06	9509/18	01/08/2019	WHS
#REF!	SAB	Mourne Hospital	12	Cement Pipe	SAB12 - Roofspace	Cement Products	Chrysotile	Enclosed Spray or Lagoing/Sealed AIB	Medium	Remove if likely to be disturbed	Re-inspection	HSG227	Unchecked	Low Risk	5	13/09/2023	Identified	Low Risk	69115	BA3549/07	9299/22	25/05/2022	WHS
#REF!	SAB	Mourne Hospital	12	Soffit Boards	SAB12 - External	Cement Products	Presumed Asbestos	Cement Sheets	None	Apply caution when maintaining and affix ID labels	Re-inspection	HSG227	Unchecked	Low Risk	5	13/09/2023	Strongly Presumed	Low Risk	69116		9300/22	25/05/2022	WHS
#REF!	SAB	Mourne Hospital	12	Cement Pipe	SAB12 - Roofspace	Cement Products	Chrysotile	Enclosed Spray or	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Low Risk	5	13/09/2023	Identified	Low Risk	69117	BA3549/07	9299/22	25/05/2022	WHS
#REF!	QJA	Bannvale	03	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Medium	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	69175	BA3723/01	9326/17	25/05/2018	WHS
#REF!	QJA	Bannvale	03	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Medium	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	69176	BA3723/01	9326/17	25/05/2018	WHS
#REF!	QJA	Bannvale	03	Roofing Felts		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	69177	BA3723/02	9326/17	25/05/2018	WHS
#REF!	QJA	Bannvale	03	Undercloak		Cement Products	NO ASBESTOS	Enclosed Spray or Lagoing/Sealed AIB	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	69178	BA3723/03	9326/17	25/05/2018	WHS
#REF!	QJA	Bannvale	03	Soffit Boards		Cement Products	NO ASBESTOS	Enclosed Spray or Lagoing/Sealed AIB	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	69179	BA3723/04	9326/17	25/05/2018	WHS
#REF!	QJA	Bannvale	04	Roofing Felts		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	69181	BA3721/01	9326/17	24/05/2018	WHS
#REF!	QJA	Bannvale	04	Soffit Boards		Cement Products	NO ASBESTOS	Enclosed Spray or Lagoing/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	69182	BA3721/02	9326/17	24/05/2018	WHS
#REF!	QJA	Bannvale	04	Undercloak		Cement Products	NO ASBESTOS	Enclosed Spray or Lagoing/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	69184	BA3721/03	9326/17	24/05/2018	WHS
#REF!	QJA	Bannvale	06	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	69185	BA3689/01	9326/17	24/05/2018	WHS
#REF!	QJA	Bannvale	01	Roofing Felts		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	69187	BA3722/01	9326/17	25/05/2018	WHS
#REF!	QJA	Bannvale	01	Undercloak		Cement Products	NO ASBESTOS	Enclosed Spray or Lagoing/Sealed AIB	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	69188	BA3722/02	9326/17	25/05/2018	WHS
#REF!	QJA	Bannvale	05	Ceiling Board		Insulating Board	NO ASBESTOS	Encapsulated Spray or Lagoing/Unsealed AIB	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	69191	BA3728/01	9509/18	31/01/2019	WHS
#REF!	QJA	Bannvale	05	Gaskets		Textiles & Paper	NO ASBESTOS	Encapsulated Spray or Lagoing/Unsealed AIB	Low	Apply Caution when Maintaining	Re-inspection	HSG227	Unchecked	NO ASBESTOS	0	06/10/2021	Presumed	Asbestos Removed	69193		9811/19	12/11/2019	WH Stephens
#REF!	QJA	Bannvale	05	Ceiling Board		Insulating Board	NO ASBESTOS	Encapsulated Spray or Lagoing/Unsealed AIB	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	69194	BA3728/02	9509/18	31/01/2019	WHS
#REF!	QJA	Bannvale	05	Soffit Boards		Insulating Board	NO ASBESTOS	Encapsulated Spray or Lagoing/Unsealed AIB	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	69195	BA3728/03	9509/18	31/01/2019	WHS
#REF!	QJA	Bannvale	05	Undercloak		Cement Products	NO ASBESTOS	Enclosed Spray or Lagoing/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	69196	BA3728/04	9509/18	31/01/2019	WHS
#REF!	QJA	Bannvale	02	Roofing Felts		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	69198	BA3729/01	9326/17	24/05/2018	WHS
#REF!	QJA	Bannvale	02	Undercloak		Cement Products	NO ASBESTOS	Enclosed Spray or Lagoing/Sealed AIB	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	69199	BA3729/02	9326/17	24/05/2018	WHS
#REF!	QJA	Bannvale	02	Soffit Boards		Insulating Board	NO ASBESTOS	Encapsulated Spray or Lagoing/Unsealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	69200	BA3729/03	9326/17	24/05/2018	WHS
#REF!	QBA	Brownlow Health Centre	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	69201	BA3735/01	9509/18	23/01/2019	WHS
#REF!	QBA	Brownlow Health Centre	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	69202	BA3735/01	9509/18	23/01/2019	WHS
#REF!	QBA	Brownlow Health Centre	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	69203	BA3735/01	9509/18	23/01/2019	WHS
#REF!	QBA	Brownlow Health Centre	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	69204	BA3735/01	9509/18	23/01/2019	WHS
#REF!	QBA	Brownlow Health Centre	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	69205	BA3735/02	9509/18	23/01/2019	WHS
#REF!	QBA	Brownlow Health Centre	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	69206	BA3735/02	9509/18	23/01/2019	WHS
#REF!	QBA	Brownlow Health Centre	01	Rope Seal		Textiles & Paper	Chrysotile	Encapsulated Spray or Lagoing/Unsealed AIB	Low	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	Low Risk	6	13/10/2023	Identified	Low Risk	69207	BA3735/03	9299/22	29/09/2022	WHS

#REF!	QBA	Brownlow Health Centre	01	Downpipe	Cement Products	Chrysotile	Enclosed Spray or Lagoon/Sealed AIB	Low	Apply Caution when Maintaining	Re-inspection	HSG227	Unchecked	Very Low Risk	4	13/10/2023	Identified	Very Low Risk	69208	BA3735/04	29/09/2022	WHS
#REF!	QBA	Brownlow Health Centre	01	Roofing Felts	Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	69209	BA3735/05	23/01/2019	WHS
#REF!	QHF	Skeagh House	02	Underclcoak	Cement Products	Chrysotile	Enclosed Spray or Lagoon/Sealed AIB	Low	Apply caution when maintaining and affix ID labels	Re-inspection	HSG227	Unchecked	Very Low Risk	4	09/09/2023	Identified	Very Low Risk	69210	BA3729/06	11/04/2022	WHS
#REF!	QHF	Skeagh House	03	Underclcoak	Cement Products	Chrysotile	Enclosed Spray or Lagoon/Sealed AIB	Minor damage of	Repair and affix labels	Re-inspection	HSG227	Unchecked	Very Low Risk	4	09/03/2023	Identified	Medium Risk	69211	BA3729/07	11/04/2022	WHS
#REF!	QHF	Skeagh House	03	Roofing Felts	Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	69212	BA3729/08	04/04/2018	WHS
#REF!	QHF	Skeagh House	03	Gasket Debris	Textiles & Paper	NO ASBESTOS	Encapsulated Spray or Lagoon/Unsealed AIB	High	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	69213	BA3729/09	04/04/2018	WHS
#REF!	QAC	Lurgan Hospital	03			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	69348		20/12/2017	WH Stephens
#REF!	QAC	Lurgan Hospital	05			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	69349		20/12/2017	WH Stephens
#REF!	QPB	Manor Centre and Stores	01	Sink Pad	Composite Material	NO ASBESTOS	Composite Materials	Medium	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	02/05/2020	Identified	Asbestos Removed	69350	BA3734/01	29/01/2019	WHS
#REF!	QPB	Manor Centre and Stores	01	Sink Pad	Composite Material	NO ASBESTOS	Composite Materials	Medium	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	02/05/2020	Strongly Presumed Similar to	Asbestos Removed	69351	BA3734/01	29/01/2019	WHS
#REF!	QHA	Moylinn House	03	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	69352	BA3732/01	21/01/2020	WH Stephens
#REF!	QHA	Moylinn House	03	Sink Pad	Composite Material	Chrysotile	Composite Materials	Medium	Apply caution when maintaining and affix ID labels	Review – No Change	HSG227	Unchecked	Very Low Risk	4	10/06/2021	Identified	Very Low Risk	69353	BA3732/02	21/01/2020	WH Stephens
#REF!	QHA	Moylinn House	03	Roofing Felts	Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	69354	BA3732/03	21/01/2020	WH Stephens
#REF!	QHA	Moylinn House	03	Underclcoak	Cement Products	Chrysotile	Enclosed Spray or Lagoon/Sealed AIB	Low	Apply Caution when Maintaining	Review – No Change	HSG227	Unchecked	Very Low Risk	4	10/06/2021	Identified	Very Low Risk	69355	BA3732/04	21/01/2020	WH Stephens
#REF!	QHC	Edenderry House	01	Duct Access Panels	Insulating Board	NO ASBESTOS	Enclosed Spray or Lagoon/Sealed AIB	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	69363	BA3740/01	21/03/2019	WHS
#REF!	QHC	Edenderry House	01	Roofing Felts	Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	69364	BA3740/02	21/03/2019	WHS
#REF!	OHC	Edenderry House	01	Underclcoak	Cement Products	Chrysotile	Enclosed Spray or	Low	Apply Caution when Maintaining	Re-inspection	HSG227	Unchecked	Very Low Risk	4	09/09/2023	Identified	Very Low Risk	69365	BA3740/03	11/04/2022	WHS
#REF!	QHC	Edenderry House	01						Further Investion Required	Re-inspection	HSG227	Checked	High Risk	0	09/12/2022			69366		11/04/2022	WHS
#REF!	OAC	Lurgan Hosoital	06	Soffit Boardino	Cement Products	Chrysotile	Enclosed Spray or	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	4	20/09/2023	Identified	Very Low Risk	69372	BA3741/01	12/09/2022	WHS
#REF!	OAC	Lurgan Hosoital	06	Ceilino boards	Cement Products	Chrysotile	Enclosed Spray or	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Low Risk	5	20/09/2023	Identified	Very Low Risk	69373	BA3741/02	12/09/2022	WHS
#REF!	QAC	Lurgan Hospital	06	Roofing Felts	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	69374	BA3741/03	13/11/2018	WHS
#REF!	QLA	Burnside Family Centre	01	Panel	Insulating Board	Amosite/Chrysotile	Encapsulated Spray or Lagoon/Unsealed AIB	Medium	Restrict access and conduct an environmental clean	Re-inspection	HSG227	Unchecked	Medium Risk	8	15/04/2023	Identified	Medium Risk	69458	BA3755/01	29/09/2022	WHS
#REF!	QLA	Burnside Family Centre	01	Panel	Insulating Board	Amosite/Chrysotile	Encapsulated Spray or Lagoon/Unsealed AIB	Medium	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	Medium Risk	8	15/04/2023	Strongly Presumed Similar to	Medium Risk	69459	BA3755/01	29/09/2022	WHS
#REF!	QLA	Burnside Family Centre	01	Panel	Insulating Board	Amosite/Chrysotile	Encapsulated Spray or Lagoon/Unsealed AIB	Medium	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	Medium Risk	8	15/04/2023	Identified	Medium Risk	69461	BA3755/02	29/09/2022	WHS
#REF!	QLA	Burnside Family Centre	01	Underclcoak	Insulating Board	NO ASBESTOS	Encapsulated Spray or Lagoon/Unsealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	69463	BA3755/03	04/11/2018	WH Stephens
#REF!	QLA	Burnside Family Centre	01	Soffit Boards	Insulating Board	Amosite/Chrysotile	Encapsulated Spray or Lagoon/Unsealed AIB	Low	Encapsulate, Manage & Affix ID Labels	Re-inspection	HSG227	Unchecked	Medium Risk	7	15/04/2023	Identified	Medium Risk	69464	BA3755/04	29/09/2022	WHS
#REF!	QLA	Burnside Family Centre	01	Bitumen Felt	Reinforced Cellulosics	NO ASBESTOS	Composite Material	Very Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified		69465	BS148183	04/11/2018	WH Stephens
#REF!	QLA	Burnside Family Centre	01	Lining Panels	Insulating Board	Presumed Asbestos	Encapsulated Spray or Lagoon/Unsealed AIB	Medium	Apply Caution when Maintaining	Re-inspection	HSG227	Unchecked	Medium Risk	9	14/04/2023	Presumed	Medium Risk	69466		29/09/2022	WHS
#REF!	QLA	Burnside Family Centre	01	Fuse Flash Guards	Textiles & Paper	Presumed Asbestos	Encapsulated Spray or Lagoon/Unsealed AIB	Medium	Apply Caution when Maintaining	Re-inspection	HSG227	Unchecked	Medium Risk	9	13/10/2023	Presumed	Medium Risk	69467		29/09/2022	WHS
#REF!	QLA	Burnside Family Centre	01	Fuse Flash Guards	Textiles & Paper	Presumed Asbestos	Encapsulated Spray or Lagoon/Unsealed AIB	Medium	Apply Caution when Maintaining	Re-inspection	HSG227	Unchecked	Medium Risk	9	15/04/2023	Presumed	Medium Risk	69468		29/09/2022	WHS
#REF!	QPA	Eden SEC	02	Fuse Flash Guards	Textiles & Paper	Presumed Asbestos	Encapsulated Spray or Lagoon/Unsealed AIB	Medium	Apply Caution when Maintaining	Re-inspection	HSG227	Unchecked	Medium Risk	9	13/03/2023	Presumed	Medium Risk	69469		11/04/2022	WHS
#REF!	QVG	Russell Drive	01	Sink Pad	Composite Material	NO ASBESTOS	Composite Materials	Medium	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	69470	BA3753/01	15/05/2018	WHS
#REF!	QVG	Russell Drive	01	Textured Coatings	Decorative Coatings	NO ASBESTOS	Encapsulated Spray or Lagoon/Unsealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	69471	BA3753/02	15/05/2018	WHS
#REF!	QVG	Russell Drive	01	Textured Coatings	Decorative Coatings	NO ASBESTOS	Composite Materials	Medium	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	69472	BA3753/03	15/05/2018	WHS
#REF!	QVG	Russell Drive	01	Textured Coatings	Decorative Coatings	NO ASBESTOS	Composite Materials	Medium	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	69473	BA3753/03	15/05/2018	WHS
#REF!	QVG	Russell Drive	01	Textured Coatings	Decorative Coatings	NO ASBESTOS	Composite Materials	Medium	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	69474	BA3753/03	15/05/2018	WHS
#REF!	QVG	Russell Drive	01	Textured Coatings	Decorative Coatings	NO ASBESTOS	Composite Materials	Medium	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	69475	BA3753/03	15/05/2018	WHS
#REF!	QVG	Russell Drive	01	Textured Coatings	Decorative Coatings	NO ASBESTOS	Composite Materials	Medium	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	69476	BA3753/04	15/05/2018	WHS
#REF!	QVG	Russell Drive	01	Textured Coatings	Decorative Coatings	NO ASBESTOS	Composite Materials	Medium	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	69477	BA3753/04	15/05/2018	WHS
#REF!	QVG	Russell Drive	01	Textured Coatings	Decorative Coatings	NO ASBESTOS	Composite Materials	Medium	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	69478	BA3753/04	15/05/2018	WHS
#REF!	QVG	Russell Drive	01	Roofing Felts	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	69479	BA3753/05	15/05/2018	WHS
#REF!	QAC	Lurgan Hospital	19	Roofing Felts	Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	69486	BA3751/01	20/12/2017	WH Stephens
#REF!	QAB	Banbridge Polyclinic	15	Sink Pad	Composite Material	NO ASBESTOS	Composite Materials	High	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	02/04/2020	Identified	Asbestos Removed	69497	BA3750/01	28/01/2019	WHS
#REF!	QAB	Banbridge Polyclinic	15	Sink Pad	Composite Material	NO ASBESTOS	Composite Materials	Medium	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	69498	BA3750/02	28/01/2019	WHS
#REF!	QAB	Banbridge Polyclinic	15	Sink Pad	Composite Material	NO ASBESTOS	Composite Materials	Medium	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	69500	BA3750/02	28/01/2019	WHS
#REF!	QAB	Banbridge Polyclinic	15	Insulating Board Below Window	Insulating Board	NO ASBESTOS	Enclosed Spray or Lagoon/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	69501	BA3750/03	28/01/2019	WHS
#REF!	QAB	Banbridge Polyclinic	15	Roofing Felts	Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	69503	BA3750/04	28/01/2019	WHS
#REF!	QAB	Banbridge Polyclinic	15	Underclcoak	Cement Products	NO ASBESTOS	Enclosed Spray or Lagoon/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	69504	BA3750/05	28/01/2019	WHS
#REF!	QAB	Banbridge Polyclinic	15	Cylinder insulation	Thermal Insulation	Presumed Asbestos	Encapsulated Spray or Lagoon/Unsealed AIB	None	Further Investigation Required	Re-inspection	HSG227	Unchecked	Medium Risk	8	09/03/2023	Presumed	Medium Risk	69507		06/04/2022	WHS
#REF!	QAB	Banbridge Polyclinic	15	Gaskets	Textiles & Paper	Presumed Asbestos	Encapsulated Spray or Lagoon/Unsealed AIB	None	Apply Caution when Maintaining	Re-inspection	HSG227	Unchecked	Medium Risk	7	09/03/2023	Presumed	Medium Risk	69508		06/04/2022	WHS
#REF!	QAB	Banbridge Polyclinic	15	Fuse Flash Guards	Textiles & Paper	Presumed Asbestos	Encapsulated Spray or Lagoon/Unsealed AIB	None	Apply Caution when Maintaining	Re-inspection	HSG227	Unchecked	Medium Risk	7	09/03/2023	Presumed	Medium Risk	69509		06/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	10	Textured Coatings	Decorative Coatings	NO ASBESTOS	Enclosed Spray or Lagoon/Sealed AIB	Medium	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	69521	BA3762/01	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	10	Textured Coatings	Decorative Coatings	NO ASBESTOS	Enclosed Spray or Lagoon/Sealed AIB	Medium	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	69522	BA3762/04	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	10	Textured Coatings	Decorative Coatings	Chrysotile	Enclosed Spray or	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Low Risk	5	15/09/2023	Identified	Low Risk	69523	BA3762/02	20/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	10	Textured Coatings	Decorative Coatings	Chrysotile	Enclosed Spray or	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	4	15/09/2023	Identified	Very Low Risk	69524	BA3762/03	20/04/2022	WHS
#REF!	QPA	Eden SEC	01	Fuse Flash Guards	Textiles & Paper	Presumed Asbestos	Encapsulated Spray or Lagoon/Unsealed AIB	Medium	Apply Caution when Maintaining	Re-inspection	HSG227	Unchecked	Medium Risk	9	13/09/2023	Presumed	Medium Risk	69701		11/04/2022	WHS
#REF!	QPA	Eden SEC	01	Roof Sheet	Cement Products	Chrysotile	Enclosed Spray or	None	Apply Caution when Maintaining	Re-inspection	HSG227	Unchecked	Very Low Risk	3	13/09/2023	Identified	Very Low Risk	69702	BA3763/01	11/04/2022	WHS
#REF!	QPA	Eden SEC	01	Roof Sheet	Cement Products	Chrysotile	Enclosed Spray or	None	Apply Caution when Maintaining	Re-inspection	HSG227	Unchecked	Very Low Risk	3	13/09/2023	Identified	Very Low Risk	69703	BA3763/01	11/04/2022	WHS
#REF!	QPA	Eden SEC	01	Ceiling boards	Cement Products	NO ASBESTOS	Enclosed Spray or Lagoon/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	69704	BA3763/02	21/01/2020	WH Stephens
#REF!	QPA	Eden SEC	01	Ceiling boards	Cement Products	NO ASBESTOS	Enclosed Spray or Lagoon/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	69705	BA3763/02	21/01/2020	WH Stephens
#REF!	QPA	Eden SEC	01	Ceiling boards	Cement Products	NO ASBESTOS	Enclosed Spray or Lagoon/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	69706	BA3763/02	21/01/2020	WH Stephens
#REF!	QPA	Eden SEC	01	Ceiling boards	Cement Products	NO ASBESTOS	Enclosed Spray or Lagoon/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	69707	BA3763/02	21/01/2020	WH Stephens
#REF!	QPA	Eden SEC	01	Wall Panels	Insulating Board	Amosite	Enclosed Spray or	Low	Label & Manage	Re-inspection	HSG227	Unchecked	Low Risk	6	13/09/2023	Identified	Low Risk	69708	BA3763/03	11/04/2022	WHS
#REF!	QPA	Eden SEC	01	Wall Panels	Insulating Board	Amosite	Enclosed Spray or	Low	Label & Manage	Re-inspection	HSG227	Unchecked	Low Risk	6	13/09/2023	Strongly Presumed Similar to	Low Risk	69709	BA3763/03	11/04/2022	WHS
#REF!	QPA	Eden SEC	01	Wall Panels	Insulating Board	Amosite	Enclosed Spray or	Low	Encapsulate and Monitor	Re-inspection	HSG227	Unchecked	Low Risk	6	13/09/2023	Identified	Low Risk	69710	BA3763/04	11/04/2022	WHS
#REF!	QPA	Eden SEC	01	Corrugated Roof Sheet	Cement Products	Chrysotile	Enclosed Spray or	Low	Apply Caution when Maintaining	Re-inspection	HSG227	Unchecked	Very Low Risk	4	13/09/2023	Identified	Very Low Risk	69711	BA3763/05	11/04/2022	WHS
#REF!	QPA	Eden SEC	01	Wall Board	Cement Products	Chrysotile	Enclosed Spray or	Low	Apply Caution when Maintaining	Re-inspection	HSG227	Unchecked	Very Low Risk	4	13/09/2023	Identified	Very Low Risk	69712	BA3763/06	11/04/2022	WHS
#REF!	QPA	Eden SEC	01	Gutters	Cement Products	Chrysotile	Enclosed Spray or	Low	Apply Caution when Maintaining	Re-inspection	HSG227	Unchecked	Very Low Risk	4	13/09/2023	Identified	Very Low Risk	69713	BA3763/07	11/04/2022	WHS
#REF!	QPA	Eden SEC	01	Downpipe	Cement Products	Chrysotile	Enclosed Spray or	Low	Apply Caution when Maintaining	Re-inspection	HSG227	Unchecked	Very Low Risk	4	13/09/2023	Identified	Very Low Risk	69714	BA3763/08	11/04/2022	WHS
#REF!	QGD	Cherrygrove	01			NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	69715		15/03/2018	WHS
#REF!	QAC	Lurgan Hospital	15	Back Board	Insulating Board	NO ASBESTOS	Enclosed Spray or Lagoon/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	69716	BA3771/01	20/12/2017	WH Stephens
#REF!	QAC	Lurgan Hospital	15	Back Board	Insulating Board	NO ASBESTOS	Enclosed Spray or Lagoon/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	69717	BA3771/01	20/12/2017	WH Stephens
#REF!	QAC	Lurgan Hospital	15	Lining Panels	Insulating Board	NO ASBESTOS	Enclosed Spray or Lagoon/Sealed AIB	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	69718	BA3771/02	20/12/2017	WH Stephens
#REF!	QAC	Lurgan Hospital	15	Sink Pad	Composite Material	NO ASBESTOS	Composite Materials	Medium	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	69719	BA3771/03	20/12/2017	WH Stephens
#REF!	QAC	Lurgan Hospital	15	Fuse Flash Bands	Textiles & Paper	Presumed Asbestos	Encapsulated Spray or Lagoon/Unsealed AIB	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Medium Risk	9	20/03/2023	Presumed	Medium Risk	69720		12/09/2022	WHS
#REF!	OAC	Lurgan Hosoital	15						Further Investion Required	Re-inspection	HSG227	Checked	Hoh Risk	0	20/12/2022			69721		12/09/2022	WHS
#REF!	SJD	Rathfriland Road Site	04	Roofing Felts	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	69722	BA3810/01	04/12/2018	WHS
#REF!	SJD	Rathfriland Road Site	04	Soffit Boardino	Cement Products	Chrysotile	Enclosed Spray or	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Low Risk	5	13/09/2023	Identified	Low Risk	69723	BA3810/02	31/08/2022	WHS
#REF!	SJD	Rathfriland Road Site	04	Roof Sheet	Cement Products	Chrysotile	Enclosed Spray or	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Low Risk	5	13/09/2023	Identified	Low Risk	69724	BA3810/03	31/08/2022	WHS
#REF!	SJD	Rathfriland Road Site	04	Debris	Cement Products	Chrysotile	Enclosed Spray or	Low	Remove	Re-inspection	HSG227	Unchecked	Low Risk	6	13/09/2023	Identified	Low Risk	69725	BA3810/04	31/08/2022	WHS
#REF!	QHA	Moylinn House	01	Woven Asbestos Textile	Textiles & Paper	Chrysotile	Encapsulated Spray or Lagoon/Unsealed AIB	Low	Apply Caution when Maintaining	Re-inspection	HSG227	Unchecked	Low Risk	6	13/10/2023	Identified	Low Risk	69726	BA3770/01	29/09/2022	WHS
#REF!	QHA	Moylinn House	01	Cylinder insulation	Thermal Insulation	NO ASBESTOS	Encapsulated Spray or Lagoon/Unsealed AIB	Medium	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	69727	BA3770/02	04/09/2018	WH Stephens
#REF!	QHA	Moylinn House	01	Gaskets	Textiles & Paper	NO ASBESTOS	Encapsulated Spray or Lagoon/Unsealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	69728	BA3770/03	04/09/2018	WH Stephens

#REF!	QHA	Moylinn House	01	Lino Flooring		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	69729	BA3770/04	9327/17	04/09/2018	WH Stephens
#REF!	QHA	Moylinn House	01	Back Board		Insulating Board	NO ASBESTOS	Encapsulated Spray or Laoinin/Unsealed AIB	Medium	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	69730	BA3770/05	9327/17	04/09/2018	WH Stephens
#REF!	QHA	Moylinn House	01	Roofing Felts		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	69731	BA3770/06	9327/17	04/09/2018	WH Stephens
#REF!	QHA	Moylinn House	01	Roofing Felts		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	69732	BA3770/06	9327/17	04/09/2018	WH Stephens
#REF!	QHA	Moylinn House	01	Lino Flooring		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	69733	BA3770/07	9327/17	04/09/2018	WH Stephens
#REF!	QHA	Moylinn House	01	Undercloak		Cement Products	Chrysotile	Encapsulated Spray or Laoinin/Unsealed AIB	Low	Apply caution when maintaining and affix ID labels	Re-inspection	HSG227	Unchecked	Low Risk	5	13/10/2023	Identified	Low Risk	69734	BA3770/08	9299/22	29/09/2022	WHS
#REF!	QHA	Moylinn House	01	Fuse Flash Guards		Textiles & Paper	Presumed Asbestos	Encapsulated Spray or Laoinin/Unsealed AIB	Medium	Apply Caution when Maintaining	Review – No Change	HSG227	Unchecked	Medium Risk	9	10/08/2021	Presumed	Medium Risk	69735		9811/19	22/01/2020	WH Stephens
#REF!	QHA	Moylinn House	01	Debris Insulation		Loose Asbestos	Presumed Asbestos	Unsealed Spray / Lagging / Dust Debris	Loose asbestos debris or residue	Environmentally Clean (Controlled Conditions)	Re-inspection	HSG227	Unchecked	High Risk	12	12/01/2023	Presumed	High Risk	69736		9299/22	29/09/2022	WHS
#REF!	SCB	Bessbrook Clinic	01				NO ASBESTOS				Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	69785		9327/17	22/04/2018	WH Stephens
#REF!	SHB	Cloushreach House	02				NO ASBESTOS				Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	69786		9327/17	04/04/2018	WH Stephens
#REF!	QGC	Edenvilla	01	Undercloak		Cement Products	NO ASBESTOS	Enclosed Spray or Laoinin/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	69923	BA3856/01	9326/17	03/09/2018	WHS
#REF!	QGC	Edenvilla	01	Gaskets		Textiles & Paper	NO ASBESTOS	Encapsulated Spray or Laoinin/Unsealed AIB	Medium	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	06/11/2019	Presumed	Asbestos Removed	69924		9326/17	03/09/2018	WHS
#REF!	QHD	Transna House	01	Rope Seal		Textiles & Paper	Chrysotile	Encapsulated Spray or Laoinin/Unsealed AIB	None	Apply Caution when Maintaining	Re-inspection	HSG227	Unchecked	Low Risk	5	14/10/2023	Identified	Low Risk	69925	BA3857/01	9299/22	29/09/2022	WHS
#REF!	QHD	Transna House	01	Roofing Felts		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	69926	BA3857/02	9327/17	04/09/2018	WH Stephens
#REF!	QAC	Lurgan Hospital	02	Debris		Thermal Insulation	NO ASBESTOS	Enclosed Spray or Laoinin/Sealed AIB	High	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	69927	BA3858/01	9326/17	20/12/2017	WH Stephens
#REF!	QAC	Lurgan Hospital	02	Roofing Felts		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	69928	BA3858/02	9326/17	20/12/2017	WH Stephens
#REF!	QAC	Lurgan Hospital	02	Board		Insulating Board	NO ASBESTOS	Enclosed Spray or Laoinin/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	69929	BA3858/03	9326/17	20/12/2017	WH Stephens
#REF!	QAC	Lurgan Hospital	02	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	69930	BA3858/04	9326/17	20/12/2017	WH Stephens
#REF!	QAC	Lurgan Hospital	02	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	69931	BA3858/05	9326/17	20/12/2017	WH Stephens
#REF!	QAC	Lurgan Hospital	02	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	High	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	69932	BA3858/06	9326/17	20/12/2017	WH Stephens
#REF!	QAC	Lurgan Hospital	02	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Medium	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	69933	BA3858/07	9326/17	20/12/2017	WH Stephens
#REF!	QAC	Lurgan Hospital	02	Roofing Felts		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	69934	BA3858/08	9326/17	20/12/2017	WH Stephens
#REF!	QAC	Lurgan Hospital	02	Fuse Flash Guards		Textiles & Paper	Presumed Asbestos	Encapsulated Spray or Laoinin/Unsealed AIB	Medium	Label & Manage	Re-inspection	HSG227	Unchecked	Medium Risk	9	20/03/2023	Presumed	Medium Risk	69935		9299/22	12/09/2022	WHS
#REF!	QAC	Lurgan Hospital	02	Ceiling Board		Insulating Board	NO ASBESTOS	Encapsulated Spray or Laoinin/Unsealed AIB	Medium	No action required	Re-inspection	HSG227	Unchecked	NO ASBESTOS	0	05/10/2021	Presumed	No Asbestos Detected	69936		9811/19	24/07/2020	WH Stephens
#REF!	QAC	Lurgan Hospital	02	Ceiling Board		Insulating Board	NO ASBESTOS	Encapsulated Spray or Laoinin/Unsealed AIB	Medium	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	05/03/2019	Strongly Presumed Similar to	Asbestos Removed	69937		9326/17	20/12/2017	WH Stephens
#REF!	QAC	Lurgan Hospital	02	Ceiling Board		Insulating Board	NO ASBESTOS	Encapsulated Spray or Laoinin/Unsealed AIB	Medium	No action required	Re-inspection	HSG227	Unchecked	NO ASBESTOS	0	05/10/2021	Presumed	No Asbestos Detected	69939		9811/19	24/07/2020	WH Stephens
#REF!	OAC	Lurgan Hospital	02							Further investigation Required	Re-inspection	HSG227	Checked	High Risk	0	20/12/2022			69940		9299/22	12/09/2022	WHS
#REF!	QAC	Lurgan Hospital	02				NO ASBESTOS			No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	05/03/2019		Asbestos Removed	69941		9326/17	20/12/2017	WH Stephens
#REF!	QAC	Lurgan Hospital	02				NO ASBESTOS			No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			Asbestos Removed	69942		9326/17	20/12/2017	WH Stephens
#REF!	QAC	Lurgan Hospital	02				NO ASBESTOS			No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			Asbestos Removed	69943		9326/17	20/12/2017	WH Stephens
#REF!	QAC	Lurgan Hospital	02	Brake Pads		Textiles & Paper	Presumed Asbestos	Concealed	None	Apply Caution when Maintaining	Re-inspection	HSG227	Unchecked	Low Risk	6	20/09/2023	Presumed	Low Risk	69944		9299/22	15/09/2022	WHS
#REF!	QAC	Lurgan Hospital	02				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	69945		9326/17	20/12/2017	WH Stephens
#REF!	QAC	Lurgan Hospital	02				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	69946		9326/17	20/12/2017	WH Stephens
#REF!	QAC	Lurgan Hospital	02				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	69947		9326/17	20/12/2017	WH Stephens
#REF!	QAC	Lurgan Hospital	02				NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0			No Asbestos Detected	69948		9326/17	20/12/2017	WH Stephens
#REF!	QGB	Bocombra	01	Ceiling Board		Insulating Board	NO ASBESTOS	Encapsulated Spray or Laoinin/Unsealed AIB	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	02/05/2020	Identified	Asbestos Removed	69951	BA3835/01	9506/18	01/05/2019	WHS
#REF!	QGB	Bocombra	01	Wall Panels		Insulating Board	NO ASBESTOS	Encapsulated Spray or Laoinin/Unsealed AIB	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	02/05/2020	Identified	Asbestos Removed	69952	BA3835/02	9506/18	01/05/2019	WHS
#REF!	QGB	Bocombra	01	Ceiling Board		Insulating Board	NO ASBESTOS	Encapsulated Spray or Laoinin/Unsealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	69953	BA3835/03	9506/18	01/05/2019	WHS
#REF!	QGB	Bocombra	01	Board		Insulating Board	NO ASBESTOS	Encapsulated Spray or Laoinin/Unsealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	69954	BA3835/04	9506/18	01/05/2019	WHS
#REF!	QGB	Bocombra	01	Gaskets		Textiles & Paper	NO ASBESTOS	Encapsulated Spray or Laoinin/Unsealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	69955	BA3835/05	9506/18	01/05/2019	WHS
#REF!	QGB	Bocombra	01					Enclosed Spray or		Further investigation Required	Review – No Change	HSG227	Checked	High Risk	0				69957		9299/22	01/05/2019	WHS
#REF!	QGB	Bocombra	01	Ceiling Board		Insulating Board	Amosite/Chrysotile		Medium	Apply Caution when Maintaining	Re-inspection	HSG227	Unchecked	Medium Risk	7	11/03/2023	Identified	Medium Risk	69958	BA3835/06	9299/22	11/04/2022	WHS
#REF!	QGB	Bocombra	01	Undercloak		Cement Products	Chrysotile	Enclosed Spray or Laoinin/Sealed AIB	Low	Apply caution when maintaining and affix ID labels	Re-inspection	HSG227	Unchecked	Very Low Risk	4	09/09/2023	Identified	Very Low Risk	69959	BA3835/07	9299/22	11/04/2022	WHS
#REF!	QGB	Bocombra	01	Toilet Cistern		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	69960	BA3835/08	9506/18	01/05/2019	WHS
#REF!	QGB	Bocombra	01	Ceiling Board		Insulating Board	NO ASBESTOS	Encapsulated Spray or Laoinin/Unsealed AIB	High	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	02/05/2020	Identified	Asbestos Removed	69961	BA3835/09	9506/18	01/05/2019	WHS
#REF!	QGB	Bocombra	01	Ceiling Board		Insulating Board	NO ASBESTOS	Encapsulated Spray or Laoinin/Unsealed AIB	High	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	02/05/2020	Identified	Asbestos Removed	69962	BA3835/10	9506/18	01/05/2019	WHS
#REF!	QGB	Bocombra	01	Gaskets		Textiles & Paper	NO ASBESTOS	Encapsulated Spray or Laoinin/Unsealed AIB	Medium	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	02/05/2020	Presumed	Asbestos Removed	69963		9506/18	01/05/2019	WHS
#REF!	QGB	Bocombra	01	Flash Guard		Textiles & Paper	Presumed Asbestos	Encapsulated Spray or Laoinin/Unsealed AIB	Medium	Apply Caution when Maintaining	Re-inspection	HSG227	Unchecked	Medium Risk	9	09/03/2023	Presumed	Medium Risk	69964		9299/22	11/04/2022	WHS
#REF!	QGB	Bocombra	01	Ceiling Board		Insulating Board	Presumed Asbestos	Enclosed Spray or Laoinin/Sealed AIB	Low	Apply caution when maintaining and affix ID labels	Re-inspection	HSG227	Unchecked	Medium Risk	7	09/03/2023	Presumed	Medium Risk	69965		9299/22	11/04/2022	WHS
#REF!	OAA	Craigavon Hospital	01	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Review – No Change	HSG227	Unchecked	Very Low Risk	3	07/02/2020	Identified	Very Low Risk	70377	BA3881/01		07/02/2019	
#REF!	OAA	Craigavon Hospital	01	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Review – No Change	HSG227	Unchecked	Very Low Risk	3	07/02/2020	Strongly Presumed Similar to	Very Low Risk	70378	BA3881/01		07/02/2019	
#REF!	OAA	Craigavon Hospital	01	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Review – No Change	HSG227	Unchecked	Very Low Risk	3	07/02/2020	Strongly Presumed Similar to	Very Low Risk	70379	BA3881/01		07/02/2019	
#REF!	OAA	Craigavon Hospital	01	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Review – No Change	HSG227	Unchecked	Very Low Risk	3	07/02/2020	Strongly Presumed Similar to	Very Low Risk	70380	BA3881/01		07/02/2019	
#REF!	OAA	Craigavon Hospital	01	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Review – No Change	HSG227	Unchecked	Very Low Risk	3	07/02/2020	Strongly Presumed Similar to	Very Low Risk	70381	BA3881/01		07/02/2019	
#REF!	OAA	Craigavon Hospital	01	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Review – No Change	HSG227	Unchecked	Very Low Risk	3	07/02/2020	Strongly Presumed Similar to	Very Low Risk	70382	BA3881/01		07/02/2019	
#REF!	OAA	Craigavon Hospital	01	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Review – No Change	HSG227	Unchecked	Very Low Risk	3	07/02/2020	Strongly Presumed Similar to	Very Low Risk	70383	BA3881/01		07/02/2019	
#REF!	OAA	Craigavon Hospital	01	Floor Tile and Bitumen Adhesive	fire hose reel cupboard	Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Review – No Change	HSG227	Unchecked	Very Low Risk	3	07/02/2020	Strongly Presumed Similar to	Very Low Risk	70384	BA3881/01		07/02/2019	
#REF!	OAA	Craigavon Hospital	01	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Review – No Change	HSG227	Unchecked	Very Low Risk	3	07/02/2020	Strongly Presumed Similar to	Very Low Risk	70385	BA3881/01		07/02/2019	
#REF!	OAA	Craigavon Hospital	01	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Review – No Change	HSG227	Unchecked	Very Low Risk	3	07/02/2020	Strongly Presumed Similar to	Very Low Risk	70386	BA3881/01		07/02/2019	
#REF!	OAA	Craigavon Hospital	01	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Review – No Change	HSG227	Unchecked	Very Low Risk	3	07/02/2020	Strongly Presumed Similar to	Very Low Risk	70387	BA3881/01		07/02/2019	
#REF!	OAA	Craigavon Hospital	01	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Review – No Change	HSG227	Unchecked	Very Low Risk	3	07/02/2020	Strongly Presumed Similar to	Very Low Risk	70388	BA3881/01		07/02/2019	
#REF!	QAA	Craigavon Hospital	01	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Medium	Conduct annual routine inspections	Review – No Change	HSG227	Unchecked	Very Low Risk	4	07/02/2020	Strongly Presumed Similar to	Very Low Risk	70389	BA3881/01		07/02/2019	
#REF!	OAA	Craigavon Hospital	01	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Review – No Change	HSG227	Unchecked	Very Low Risk	3	07/02/2020	Strongly Presumed Similar to	Very Low Risk	70390	BA3881/01		07/02/2019	
#REF!	OAA	Craigavon Hospital	01	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Review – No Change	HSG227	Unchecked	Very Low Risk	3	07/02/2020	Strongly Presumed Similar to	Very Low Risk	70391	BA3881/01		07/02/2019	
#REF!	QAA	Craigavon Hospital	01	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Low	Apply caution when maintaining and affix ID labels	Review – No Change	HSG227	Unchecked	Very Low Risk	3	07/02/2020	Strongly Presumed Similar to	Very Low Risk	70392	BA3881/01		07/02/2019	
#REF!	OAA	Craigavon Hospital	01	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Review – No Change	HSG227	Unchecked	Very Low Risk	3	07/02/2020	Strongly Presumed Similar to	Very Low Risk	70393	BA3881/01		07/02/2019	
#REF!	OAA	Craigavon Hospital	01	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Review – No Change	HSG227	Unchecked	Very Low Risk	3	07/02/2020	Identified	Very Low Risk	70394	BA3881/02		07/02/2019	
#REF!	OAA	Craigavon Hospital	01	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Review – No Change	HSG227	Unchecked	Very Low Risk	3	07/02/2020	Strongly Presumed Similar to	Very Low Risk	70395	BA3881/02		07/02/2019	
#REF!	OAA	Craigavon Hospital	01	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Review – No Change	HSG227	Unchecked	Very Low Risk	3	07/02/2020	Strongly Presumed Similar to	Very Low Risk	70396	BA3881/02		07/02/2019	
#REF!	OAA	Craigavon Hospital	01	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Review – No Change	HSG227	Unchecked	Very Low Risk	3	07/02/2020	Strongly Presumed Similar to	Very Low Risk	70397	BA3881/02		07/02/2019	
#REF!	OAA	Craigavon Hospital	01	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Review – No Change	HSG227	Unchecked	Very Low Risk	3	07/02/2020	Strongly Presumed Similar to	Very Low Risk	70398	BA3881/02		07/02/2019	
#REF!	QAA	Craigavon Hospital	01	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Review – No Change	HSG227	Unchecked	Very Low Risk	3	07/02/2020	Strongly Presumed Similar to	Very Low Risk	70399	BA3881/02		07/02/2019	
#REF!	QAA	Craigavon Hospital	01	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Review – No Change	HSG227	Unchecked	Very Low Risk	3	07/02/2020	Strongly Presumed Similar to	Very Low Risk	70400	BA3881/02		07/02/2019	
#REF!	QAA	Craigavon Hospital	01	Floor Tile and Bitumen Adhesive	firehose reel cupboard	Composite Material	Chrysotile	Composite Materials	Low	Apply caution when maintaining and affix ID labels	Review – No Change	HSG227	Unchecked	Very Low Risk	3	07/02/2020	Strongly Presumed Similar to	Very Low Risk	70401	BA3881/02		07/02/2019	
#REF!	QAA	Craigavon Hospital	01	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Review – No Change	HSG227	Unchecked	Very Low Risk	3	07/02/2020	Strongly Presumed Similar to	Very Low Risk	70402	BA3881/02		07/02/2019	
#REF!	QAA	Craigavon Hospital	01	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Review – No Change	HSG227	Unchecked	Very Low Risk	3	07/02/2020	Strongly Presumed Similar to	Very Low Risk	70403	BA3881/02		07/02/2019	
#REF!	QAA	Craigavon Hospital	01	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Review – No Change	HSG227	Unchecked	Very Low Risk	3	07/02/2020	Strongly Presumed Similar to	Very Low Risk	70404	BA3881/02		07/02/2019	
#REF!	QAA	Craigavon Hospital	01	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Review – No Change	HSG227	Unchecked	Very Low Risk	3	07/02/2020	Strongly Presumed Similar to	Very Low Risk	70405	BA3881/02		07/02/2019	
#REF!	OAA	Craigavon Hospital	01	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Review – No Change	HSG227	Unchecked	Very Low Risk	3	07/02/2020	Strongly Presumed Similar to	Very Low Risk	70406	BA3881/02		07/02/2019	
#REF!	OAA	Craigavon Hospital	01	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Review – No Change	HSG227	Unchecked	Very Low Risk	3	07/02/2020	Strongly Presumed Similar to	Very Low Risk	70407	BA3881/02		07/02/2019	
#REF!	OAA	Craigavon Hospital	01	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Review – No Change	HSG227	Unchecked	Very Low Risk	3	07/02/2020	Strongly Presumed Similar to	Very Low Risk	70408	BA3881/02		07/02/2019	
#REF!	OAA	Craigavon Hospital	01	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Review – No Change	HSG227	Unchecked	Very Low Risk	3	07/02/2020	Strongly Presumed Similar to	Very Low Risk	70409	BA3881/02		07/02/2019	
#REF!	OAA	Craigavon Hospital	01	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Review – No Change	HSG227	Unchecked	Very Low Risk	3	07/02/2020	Strongly Presumed Similar to	Very Low Risk	70410	BA3881/02		07/02/2019	
#REF!	OAA	Craigavon Hospital	01	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Review – No Change	HSG227	Unchecked	Very Low Risk	3	07/02/2020	Strongly Presumed Similar to	Very Low Risk	70411	BA3881/02		07/02/2019	
#REF!	OAA	Craigavon Hospital	01	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Review – No Change	HSG227	Unchecked	Very Low Risk	3	07/02/2020	Strongly Presumed Similar to	Very Low Risk	70412	BA3881/02		07/02/2019	
#REF!	QAA	Craigavon Hospital	01	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Low	Encapsulate exposed surfaces and remove debris	Review – No Change	HSG227	Unchecked	Very Low Risk	3	07/02/2020	Strongly Presumed Similar to	Very Low Risk	70413	BA3881/02		07/02/2019	
#REF!	OAA	Craigavon Hospital	01	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Review – No Change	HSG227	Unchecked	Very Low Risk	3	07/02/2020	Strongly Presumed Similar to	Very Low Risk	70414	BA3881/02		07/02/2019	
#REF!	OAA	Craigavon Hospital	01	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Low	Apply Caution when Maintaining	Review – No Change	HSG227	Unchecked	Very Low Risk	3	07/02/2020	Strongly Presumed Similar to	Very Low Risk	70415	BA3881/02		07/02/2019	
#REF!	OAA	Craigavon Hospital	01	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Low	Apply Caution when Maintaining	Review – No Change	HSG227	Unchecked	Very Low Risk	3	07/02/2020	Strongly Presumed Similar to	Very Low Risk	70416	BA3881/02		07/02/2019	
#REF!	QAA	Craigavon Hospital	01	Floor Tile and Bitumen Adhesive		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	07/02/2020	Strongly Presumed Similar to	Asbestos Removed	70417	BA3881/02		07/02/2019	
#REF!	OAA	Craigavon Hospital	01	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Review – No Change	HSG227	Unchecked	Very Low Risk	3	07/02/2020	Strongly Presumed Similar to	Very Low Risk	70418	BA3881/02		07/02/2019	
#REF!	OAA	Craigavon Hospital	01	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Review – No Change	HSG227	Unchecked	Very Low Risk	3	07/02/2020	Strongly Presumed Similar to	Very Low Risk	70419	BA3881/02		07/02/2019	
#REF!	OAA	Craigavon Hospital	01	Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Review – No Change	HSG227	Unchecked	Very Low Risk	3	07/02/2020	Identified	Very Low Risk	70420	BA3881/03		07/02/2019	
#REF!	OAA	Craigavon Hospital	01	Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Review – No Change	HSG227	Unchecked	Very Low Risk	3	07/02/2020	Strongly Presumed Similar to	Very Low Risk	70421	BA3881/03		07/02/2019	
#REF!	QAA	Craigavon Hospital	01	Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Review – No Change	HSG227	Unchecked	Very Low Risk	3	07/02/2020	Strongly Presumed Similar to	Very Low Risk	70422	BA3881/03		07/02/2019	
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	70423	BA3881/04		07/02/2019	

#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70424	BA3881/04		07/02/2019					
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70425	BA3881/04		07/02/2019					
#REF!	QAA	Craigavon Hospital	01	Pipe Brackets		Textiles & Paper	Chrysotile	Encapsulated Spray or Laosino/Unsealed AIB	Low	Conduct annual routine inspections	Review – No Change	HSG227	Unchecked	Low Risk	6	07/02/2020	Identified	Low Risk	70426	BA3881/05		07/02/2019					
#REF!	QAA	Craigavon Hospital	01	Pipe Brackets		Textiles & Paper	Chrysotile	Encapsulated Spray or Laosino/Unsealed AIB	Low	Apply Caution when Maintaining	Review – No Change	HSG227	Unchecked	Low Risk	6	06/08/2014	Strongly Presumed Similar to	Low Risk	70427	BA3881/05		07/02/2019					
#REF!	QAA	Craigavon Hospital	01	Board		Insulating Board	Presumed Asbestos	Encapsulated Spray or Laosino/Unsealed AIB	Medium	Further investigation Required	Review – No Change	HSG227	Unchecked	Medium Risk	9	07/02/2020	Presumed	Medium Risk	70428			07/02/2019					
#REF!	QAA	Craigavon Hospital	01	Packing Strips		Cement Products	NO ASBESTOS	Enclosed Spray or Laosino/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	70429	BA3881/06		07/02/2019					
#REF!	QAA	Craigavon Hospital	01	Boarding		Cement Products	NO ASBESTOS	Enclosed Spray or Laosino/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	70430	BA3881/07		07/02/2019					
#REF!	QAA	Craigavon Hospital	01	Boarding		Cement Products	NO ASBESTOS	Enclosed Spray or Laosino/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70431	BA3881/07		07/02/2019					
#REF!	QAA	Craigavon Hospital	01	Ceiling Tiles		Insulating Board	Amosite/Chrysotile	Enclosed Spray or	Medium	Apply Caution when Maintaining	Review – No Change	HSG227	Unchecked	Medium Risk	7	07/02/2020	Identified	Medium Risk	70432	BA3881/08		07/02/2019					
#REF!	QAA	Craigavon Hospital	01	Ceiling Tiles		Insulating Board	Amosite/Chrysotile	Enclosed Spray or	Medium	Asstv Caution when Maintainino	Review – No Change	HSG227	Unchecked	Medium Risk	7	07/02/2020	Stronnlv Presumed Similar to	Medium Risk	70433	BA3881/08		07/02/2019					
#REF!	QAA	Craigavon Hospital	01	Ceiling Tiles		Insulating Board	Amosite/Chrysotile	Enclosed Spray or	Medium	Conduct annual routine inspections	Review – No Change	HSG227	Unchecked	Medium Risk	7	07/02/2020	Strongly Presumed Similar to	Medium Risk	70434	BA3881/08		07/02/2019					
#REF!	QAA	Craigavon Hospital	01	Boarding		Cement Products	NO ASBESTOS	Enclosed Spray or Laosino/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	70435	BA3881/09		07/02/2019					
#REF!	QAA	Craigavon Hospital	01	Boarding		Cement Products	NO ASBESTOS	Enclosed Spray or Laosino/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70436	BA3881/09		07/02/2019					
#REF!	QAA	Craigavon Hospital	01	Bitumen Adhesive		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	70437	BA3881/10		07/02/2019					
#REF!	QAA	Craigavon Hospital	01	Gaskets		Textiles & Paper	NO ASBESTOS	Encapsulated Spray or Laosino/Unsealed AIB	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	07/02/2020	Identified	Asbestos Removed	70438	BA3881/11		07/02/2019					
#REF!	QAA	Craigavon Hospital	01	Gaskets		Textiles & Paper	Chrysotile	Encapsulated Spray or Laosino/Unsealed AIB	Low	Apply Caution when Maintaining	Review – No Change	HSG227	Unchecked	Low Risk	6	06/08/2014	Strongly Presumed Similar to	Low Risk	70439	BA3881/11		07/02/2019					
#REF!	QAA	Craigavon Hospital	01	Pipe Insulation		Thermal Insulation	NO ASBESTOS	Enclosed Spray or Laosino/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	70440	BA3881/12		07/02/2019					
#REF!	QAA	Craigavon Hospital	01	Pipe Insulation		Thermal Insulation	NO ASBESTOS	Enclosed Spray or Laosino/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70441	BA3881/12		07/02/2019					
#REF!	QAA	Craigavon Hospital	01	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Review – No Change	HSG227	Unchecked	Very Low Risk	3	07/02/2020	Identified	Very Low Risk	70442	BA3881/13		07/02/2019					
#REF!	QAA	Craigavon Hospital	01	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Review – No Change	HSG227	Unchecked	Very Low Risk	3	07/02/2020	Stronnlv Presumed Similar to	Very Low Risk	70443	BA3881/13		07/02/2019					
#REF!	QAA	Craigavon Hospital	01	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Review – No Change	HSG227	Unchecked	Very Low Risk	3	07/02/2020	Strongly Presumed Similar to	Very Low Risk	70444	BA3881/13		07/02/2019					
#REF!	QAA	Craigavon Hospital	01	Floor Tile and Bitumen Adhesive	firehose cupboard	Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	11/10/2023	Strongly Presumed Similar to	Very Low Risk	70445	BA3881/13	[illegible]	11/10/2022	WHS				
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	70446	BA3881/14		07/02/2019					
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70447	BA3881/14		07/02/2019					
#REF!	QAA	Craigavon Hospital	01	Boardino		Cement Products	Chrysotile	Enclosed Spray or	Medium	Repair. Encapsulate & Manage	Review – No Change	HSG227	Unchecked	Low Risk	5	07/02/2020	Identified	Low Risk	70448	BA3881/15		07/02/2019					
#REF!	QAA	Craigavon Hospital	01	Boardino		Cement Products	Chrysotile	Enclosed Spray or	Medium	Conduct annual routine inspections	Review – No Change	HSG227	Unchecked	Low Risk	5	07/02/2020	Strongly Presumed Similar to	Low Risk	70449	BA3881/15		07/02/2019					
#REF!	QAA	Craigavon Hospital	01	Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Review – No Change	HSG227	Unchecked	Very Low Risk	3	07/02/2020	Identified	Very Low Risk	70450	BA3881/16		07/02/2019					
#REF!	QAA	Craigavon Hospital	01	Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Review – No Change	HSG227	Unchecked	Very Low Risk	3	07/02/2020	Identified	Very Low Risk	70451	BA3881/17		07/02/2019					
#REF!	QAA	Craigavon Hospital	01	Board		Insulating Board	NO ASBESTOS	Enclosed Spray or	Medium	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	70452	BA3881/18		07/02/2019					
#REF!	QAA	Craigavon Hospital	01	Boardino		Cement Products	Chrysotile	Enclosed Spray or	Low	Conduct annual routine inspections	Review – No Change	HSG227	Unchecked	Very Low Risk	4	07/02/2020	Identified	Very Low Risk	70453	BA3881/19		07/02/2019					
#REF!	QAA	Craigavon Hospital	01	Debris		Insulating Board	NO ASBESTOS	Encapsulated Spray or Laosino/Unsealed AIB	Medium	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	70454	BA3881/20		07/02/2019					
#REF!	QAA	Craigavon Hospital	01	Board		Insulating Board	NO ASBESTOS	Enclosed Spray or Laosino/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	70455	BA3881/21		07/02/2019					
#REF!	QAA	Craigavon Hospital	01	Debris		Insulating Board	NO ASBESTOS	Encapsulated Spray or Laosino/Unsealed AIB	Medium	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	70456	BA3881/22		07/02/2019					
#REF!	QAA	Craigavon Hospital	01	Bitumen Wrap to cables		Composite Material	Presumed Asbestos	Composite Materials	None	Conduct annual routine inspections	Review – No Change	HSG227	Unchecked	Very Low Risk	4	07/02/2020	Presumed	Very Low Risk	70457			07/02/2019					
#REF!	QAA	Craigavon Hospital	01	Bitumen Wrap to cables		Composite Material	Presumed Asbestos	Composite Materials	None	Conduct annual routine inspections	Review – No Change	HSG227	Unchecked	Very Low Risk	4	07/02/2020	Presumed	Very Low Risk	70458			07/02/2019					
#REF!	QAA	Craigavon Hospital	01	Bitumen Wrap to cables		Composite Material	Presumed Asbestos	Composite Materials	None	Apply Caution when Maintaining	Review – No Change	HSG227	Unchecked	Very Low Risk	4	07/02/2020	Presumed	Very Low Risk	70459			07/02/2019					
#REF!	QAA	Craigavon Hospital	01	Gaskets		Textiles & Paper	NO ASBESTOS	Encapsulated Spray or Laosino/Unsealed AIB	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	Asbestos Removed	70460	BA3881/23		07/02/2019					
#REF!	QAA	Craigavon Hospital	01	Debris		Insulating Board	NO ASBESTOS	Encapsulated Spray or Laosino/Unsealed AIB	High	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	70461	BA3881/24		07/02/2019					
#REF!	QAA	Craigavon Hospital	01	Debris		Insulating Board	NO ASBESTOS	Encapsulated Spray or Laosino/Unsealed AIB	High	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	70462	BA3881/25		07/02/2019					
#REF!	QAA	Craigavon Hospital	01	Rigid Wall Board		Insulating Board	Amosite/Chrysotile	Enclosed Spray or Laosino/Sealed AIB	Low	Apply caution when maintaining and affix ID labels	Review – No Change	HSG227	Unchecked	Low Risk	6	07/02/2020	Identified	Low Risk	70463	BA3881/26		07/02/2019					
#REF!	QAA	Craigavon Hospital	01	Rigid Wall Board		Insulating Board	Amosite/Chrysotile	Enclosed Spray or	Low	Enclose & Manage, Affix ID Labels	Review – No Change	HSG227	Unchecked	Low Risk	6	07/02/2020	Stronnlv Presumed Similar to	Low Risk	70464	BA3881/26		07/02/2019					
#REF!	QAA	Craigavon Hospital	01	Rigid Wall Board		Insulating Board	NO ASBESTOS	Enclosed Spray or Laosino/Sealed AIB	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	07/02/2020	Strongly Presumed Similar to	Asbestos Removed	70465	BA3881/26		07/02/2019					
#REF!	QAA	Craigavon Hospital	01	Rigid Wall Board		Insulating Board	Amosite/Chrysotile	Enclosed Spray or	Low	Conduct annual routine inspections	Review – No Change	HSG227	Unchecked	Low Risk	6	07/02/2020	Strongly Presumed Similar to	Low Risk	70466	BA3881/26		07/02/2019					
#REF!	QAA	Craigavon Hospital	01	Rigid Wall Board		Insulating Board	Amosite/Chrysotile	Enclosed Spray or	Low	Apply Caution when Maintaining	Review – No Change	HSG227	Unchecked	Low Risk	6	07/02/2020	Strongly Presumed Similar to	Low Risk	70467	BA3881/26		07/02/2019					
#REF!	QAA	Craigavon Hospital	01	Rigid Wall Board		Insulating Board	Amosite/Chrysotile	Enclosed Spray or	Low	Further Investion Required	Review – No Change	HSG227	Unchecked	Low Risk	6	07/02/2020	Strongly Presumed Similar to	Low Risk	70468	BA3881/26		07/02/2019					
#REF!	QAA	Craigavon Hospital	01	Rigid Wall Board	service duct	Insulating Board	Amosite/Chrysotile	Enclosed Spray or	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Low Risk	6	11/10/2023	Strongly Presumed Similar to	Low Risk	70469	BA3881/26	[illegible]	11/10/2022	WHS				
#REF!	QAA	Craigavon Hospital	01	Rigid Wall Board		Insulating Board	Amosite/Chrysotile	Enclosed Spray or	Low	Conduct annual routine inspections	Review – No Change	HSG227	Unchecked	Low Risk	6	07/02/2020	Strongly Presumed Similar to	Low Risk	70470	BA3881/26		07/02/2019					
#REF!	QAA	Craigavon Hospital	01	Rigid Wall Board		Insulating Board	Amosite/Chrysotile	Enclosed Spray or	Low	Conduct annual routine inspections	Review – No Change	HSG227	Unchecked	Low Risk	6	07/02/2020	Stronnlv Presumed Similar to	Low Risk	70471	BA3881/26		07/02/2019					
#REF!	QAA	Craigavon Hospital	01	Rigid Wall Board		Insulating Board	Amosite/Chrysotile	Enclosed Spray or Laosino/Sealed AIB	Low	Encapsulate exposed surfaces and remove debris	Review – No Change	HSG227	Unchecked	Low Risk	6	07/02/2020	Strongly Presumed Similar to	Low Risk	70472	BA3881/26		07/02/2019					
#REF!	QAA	Craigavon Hospital	01	Rigid Wall Board		Insulating Board	Amosite/Chrysotile	Enclosed Spray or	Low	Conduct annual routine inspections	Review – No Change	HSG227	Unchecked	Low Risk	6	07/02/2020	Stronnlv Presumed Similar to	Low Risk	70473	BA3881/26		07/02/2019					
#REF!	QAA	Craigavon Hospital	01	Rigid Wall Board		Insulating Board	Amosite/Chrysotile	Enclosed Spray or	Low	Further Investigation Required	Review – No Change	HSG227	Unchecked	Low Risk	6	07/02/2020	Strongly Presumed Similar to	Low Risk	70474	BA3881/26		07/02/2019					
#REF!	QAA	Craigavon Hospital	01	Debris		Cement Products	NO ASBESTOS	Enclosed Spray or Laosino/Sealed AIB	Loose asbestos debris or residue	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	07/02/2020	Identified	Asbestos Removed	70475	BA3881/27		07/02/2019					
#REF!	QAA	Craigavon Hospital	01	Bitumen Felt		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	70476	BA3881/28		07/02/2019					
#REF!	QAA	Craigavon Hospital	01	General Debris		General Debris	NO ASBESTOS	Encapsulated Spray or Laosino/Unsealed AIB	High	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	70477	BA3881/29		07/02/2019					
#REF!	QAA	Craigavon Hospital	01	Debris		Cement Products	NO ASBESTOS	Enclosed Spray or Laosino/Sealed AIB	High	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	70478	BA3881/30		07/02/2019					
#REF!	QAA	Craigavon Hospital	01	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Medium	Encapsulate exposed surfaces and remove debris	Review – No Change	HSG227	Unchecked	Very Low Risk	4	07/02/2020	Identified	Very Low Risk	70479	BA3881/31		07/02/2019					
#REF!	QAA	Craigavon Hospital	01	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Low	Encapsulate exposed surfaces and remove debris	Review – No Change	HSG227	Unchecked	Very Low Risk	3	07/02/2020	Identified	Very Low Risk	70480	BA3881/32		07/02/2019					
#REF!	QAA	Craigavon Hospital	01	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Review – No Change	HSG227	Unchecked	Very Low Risk	3	07/02/2020	Stronnlv Presumed Similar to	Very Low Risk	70481	BA3881/32		07/02/2019					
#REF!	QAA	Craigavon Hospital	01	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Low	Asstv Caution when Maintainino	Review – No Change	HSG227	Unchecked	Very Low Risk	3	07/02/2020	Stronnlv Presumed Similar to	Very Low Risk	70482	BA3881/32		07/02/2019					
#REF!	QAA	Craigavon Hospital	01	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Review – No Change	HSG227	Unchecked	Very Low Risk	3	07/02/2020	Strongly Presumed Similar to	Very Low Risk	70483	BA3881/32		07/02/2019					
#REF!	QAA	Craigavon Hospital	01	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Review – No Change	HSG227	Unchecked	Very Low Risk	3	07/02/2020	Stronnlv Presumed Similar to	Very Low Risk	70484	BA3881/32		07/02/2019					
#REF!	QAA	Craigavon Hospital	01	Debris		Insulating Board	NO ASBESTOS	Encapsulated Spray or Laosino/Unsealed AIB	High	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	70485	BA3881/33		07/02/2019					
#REF!	QAA	Craigavon Hospital	01	Cylinder insulation		Thermal Insulation	NO ASBESTOS	Encapsulated Spray or Laosino/Unsealed AIB	Medium	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	07/02/2020	Presumed	Asbestos Removed	70486			07/02/2019					
#REF!	QAA	Craigavon Hospital	01	Cylinder insulation		Thermal Insulation	Presumed Asbestos	Encapsulated Spray or Laosino/Unsealed AIB	Medium	Conduct annual routine inspections	Review – No Change	HSG227	Unchecked	High Risk	10	07/02/2020	Presumed	High Risk	70487			07/02/2019					
#REF!	QAA	Craigavon Hospital	01	Cylinder insulation		Thermal Insulation	NO ASBESTOS	Encapsulated Spray or Laosino/Unsealed AIB	Medium	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	07/02/2020	Presumed	Asbestos Removed	70488			07/02/2019					
#REF!	QAA	Craigavon Hospital	01	Debris		Insulating Board	Amosite/Chrysotile	Enclosed Spray or Laosino/Sealed AIB	Loose asbestos debris or residue	Environmentally Clean (Controlled Conditions)	Review – No Change	HSG227	Unchecked	Medium Risk	8	07/02/2020	Identified	Medium Risk	70489	BA3881/34		07/02/2019					
#REF!	QAA	Craigavon Hospital	01	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Medium	Conduct annual routine inspections	Review – No Change	HSG227	Unchecked	Very Low Risk	4	07/02/2020	Identified	Very Low Risk	70490	BA3881/35		07/02/2019					
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	70491	BA3881/36		07/02/2019					
#REF!	QAA	Craigavon Hospital	01	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Review – No Change	HSG227	Unchecked	Very Low Risk	3	07/02/2020	Identified	Very Low Risk	70492	BA3881/37		07/02/2019					
#REF!	QAA	Craigavon Hospital	01	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Review – No Change	HSG227	Unchecked	Very Low Risk	3	07/02/2020	Stronnlv Presumed Similar to	Very Low Risk	70493	BA3881/37		07/02/2019					
#REF!	QAA	Craigavon Hospital	01	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	70494	BA3881/38		07/02/2019					
#REF!	QAA	Craigavon Hospital	01	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70495	BA3881/38		07/02/2019					
#REF!	QAA	Craigavon Hospital	01	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70496	BA3881/38		07/02/2019					
#REF!	QAA	Craigavon Hospital	01	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	None	Conduct annual routine inspections	Review – No Change	HSG227	Unchecked	Very Low Risk	2	07/02/2020	Identified	Very Low Risk	70497	BA3881/39		07/02/2019					
#REF!	QAA	Craigavon Hospital	01	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	None	Conduct annual routine inspections	Review – No Change	HSG227	Unchecked	Very Low Risk	2	07/02/2020	Strongly Presumed Similar to	Very Low Risk	70498	BA3881/39		07/02/2019					
#REF!	QAA	Craigavon Hospital	01	General Debris		General Debris	NO ASBESTOS	Encapsulated Spray or Laosino/Unsealed AIB	High	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	70499	BA3881/40		07/02/2019					
#REF!	QAA	Craigavon Hospital	01	Board		Insulating Board	NO ASBESTOS	Encapsulated Spray or Laosino/Unsealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	70500	BA3881/41		07/02/2019					
#REF!	QAA	Craigavon Hospital	01	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Low	Conduct annual routine inspections	Review – No Change	HSG227	Unchecked	Very Low Risk	3	07/02/2020	Identified	Very Low Risk	70501	BA3881/42		07/02/2019					
#REF!	QAA	Craigavon Hospital	01	Fuse Flash Guards		Textiles & Paper	Presumed Asbestos	Encapsulated Spray or Laosino/Unsealed AIB	Medium	Conduct annual routine inspections	Review – No Change	HSG227	Unchecked	Medium Risk	9	07/02/2020	Presumed	Medium Risk	70502			07/02/2019					
#REF!	QAA	Craigavon Hospital	01	Fuse Flash Guards		Textiles & Paper	Presumed Asbestos	Encapsulated Spray or Laosino/Unsealed AIB	Medium	Apply caution when maintaining and affix ID labels	Review – No Change	HSG227	Unchecked	Medium Risk	9	06/08/2014	Presumed	Medium Risk	70503			07/02/2019					
#REF!	QAA	Craigavon Hospital	01	Woven		Textiles & Paper	Presumed Asbestos	Encapsulated Spray or Laosino/Unsealed AIB	Low	Environmentally Clean (Controlled Conditions)	Review – No Change	HSG227	Unchecked	Medium Risk	8	07/02/2020	Presumed	Medium Risk	70504			07/02/2019					
#REF!	QAA	Craigavon Hospital	01	Board		Insulating Board	NO ASBESTOS	Enclosed Spray or Laosino/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	70505	BA3881/43		07/02/2019					
#REF!	QAA	Craigavon Hospital	01	Board		Insulating Board	NO ASBESTOS	Enclosed Spray or	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70506	BA3881/43		07/02/2019					
#REF!	QAA	Craigavon Hospital	01	Board		Insulating Board	NO ASBESTOS	Enclosed Spray or Laosino/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70507	BA3881/43		07/02/2019					
#REF!	QAA	Craigavon Hospital	01	Textured Coatings		Decorative Coatings	NO ASBESTOS	Enclosed Spray or Laosino/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	70508	BA3881/44		07/02/2019					
#REF!	QAA	Craigavon Hospital	01	Debris		Insulating Board	NO ASBESTOS	Encapsulated Spray or	High	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	70509	BA3884/01		07/02/2019					
#REF!	QAA	Craigavon Hospital	01	Board	Hose Reel Cupboard	Insulating Board	NO ASBESTOS	Encapsulated Spray or Laosino/Unsealed AIB	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	70510	BA3884/02		07/02/2019					
#REF!	QAA	Craigavon Hospital	01	Board	Service Duct	Insulating Board	NO ASBESTOS	Encapsulated Spray or Laosino/Unsealed AIB	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70511	BA3884/02		07/02/2019					
#REF!	QAA	Craigavon Hospital	01	Board	Service Duct	Insulating Board	NO ASBESTOS	Encapsulated Spray or	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70512	BA3884/02		07/02/2019					

#REF!	QAA	Craigavon Hospital	01	Board	Service Duct	Insulating Board	NO ASBESTOS	Encapsulated Spray or Lagging/Unsealed AIB	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Strongly Presumed Similar to	No Asbestos Detected	70513	BA3884/02	07/02/2019	
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Identified	No Asbestos Detected	70514	BA3884/03	07/02/2019	
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Strongly Presumed Similar to	No Asbestos Detected	70515	BA3884/03	07/02/2019	
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Strongly Presumed Similar to	No Asbestos Detected	70516	BA3884/03	07/02/2019	
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Strongly Presumed Similar to	No Asbestos Detected	70517	BA3884/03	07/02/2019	
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Strongly Presumed Similar to	No Asbestos Detected	70518	BA3884/03	07/02/2019	
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Strongly Presumed Similar to	No Asbestos Detected	70519	BA3884/03	07/02/2019	
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Strongly Presumed Similar to	No Asbestos Detected	70520	BA3884/03	07/02/2019	
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Hose Reel Cupboard	Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Strongly Presumed Similar to	No Asbestos Detected	70521	BA3884/03	07/02/2019	
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Hose Reel Cupboard	Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Strongly Presumed Similar to	No Asbestos Detected	70522	BA3884/03	07/02/2019	
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Strongly Presumed Similar to	No Asbestos Detected	70523	BA3884/03	07/02/2019	
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Strongly Presumed Similar to	No Asbestos Detected	70524	BA3884/03	07/02/2019	
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Strongly Presumed Similar to	No Asbestos Detected	70525	BA3884/03	07/02/2019	
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Hose Reel Cupboard	Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Strongly Presumed Similar to	No Asbestos Detected	70526	BA3884/03	07/02/2019	
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Strongly Presumed Similar to	No Asbestos Detected	70527	BA3884/03	07/02/2019	
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Strongly Presumed Similar to	No Asbestos Detected	70528	BA3884/03	07/02/2019	
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Hose Reel Cupboard	Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Strongly Presumed Similar to	No Asbestos Detected	70529	BA3884/03	07/02/2019	
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Strongly Presumed Similar to	No Asbestos Detected	70530	BA3884/03	07/02/2019	
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Strongly Presumed Similar to	No Asbestos Detected	70531	BA3884/03	07/02/2019	
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Strongly Presumed Similar to	No Asbestos Detected	70532	BA3884/03	07/02/2019	
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Strongly Presumed Similar to	No Asbestos Detected	70533	BA3884/03	07/02/2019	
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Strongly Presumed Similar to	No Asbestos Detected	70534	BA3884/03	07/02/2019	
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Strongly Presumed Similar to	No Asbestos Detected	70535	BA3884/03	07/02/2019	
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Strongly Presumed Similar to	No Asbestos Detected	70536	BA3884/03	07/02/2019	
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Strongly Presumed Similar to	No Asbestos Detected	70537	BA3884/03	07/02/2019	
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Strongly Presumed Similar to	No Asbestos Detected	70538	BA3884/03	07/02/2019	
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Strongly Presumed Similar to	No Asbestos Detected	70539	BA3884/03	07/02/2019	
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Strongly Presumed Similar to	No Asbestos Detected	70540	BA3884/03	07/02/2019	
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Strongly Presumed Similar to	No Asbestos Detected	70541	BA3884/03	07/02/2019	
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Strongly Presumed Similar to	No Asbestos Detected	70542	BA3884/03	07/02/2019	
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Strongly Presumed Similar to	No Asbestos Detected	70543	BA3884/03	07/02/2019	
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Strongly Presumed Similar to	No Asbestos Detected	70544	BA3884/03	07/02/2019	
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Strongly Presumed Similar to	No Asbestos Detected	70545	BA3884/03	07/02/2019	
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Strongly Presumed Similar to	No Asbestos Detected	70546	BA3884/03	07/02/2019	
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Identified	No Asbestos Detected	70547	BA3884/04	07/02/2019	
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Strongly Presumed Similar to	No Asbestos Detected	70548	BA3884/04	07/02/2019	
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Strongly Presumed Similar to	No Asbestos Detected	70549	BA3884/04	07/02/2019	
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Strongly Presumed Similar to	No Asbestos Detected	70550	BA3884/04	07/02/2019	
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Strongly Presumed Similar to	No Asbestos Detected	70551	BA3884/04	07/02/2019	
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Strongly Presumed Similar to	No Asbestos Detected	70552	BA3884/04	07/02/2019	
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Strongly Presumed Similar to	No Asbestos Detected	70553	BA3884/04	07/02/2019	
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Strongly Presumed Similar to	No Asbestos Detected	70554	BA3884/04	07/02/2019	
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Strongly Presumed Similar to	No Asbestos Detected	70555	BA3884/04	07/02/2019	
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Identified	No Asbestos Detected	70556	BA3884/05	07/02/2019	
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Strongly Presumed Similar to	No Asbestos Detected	70557	BA3884/05	07/02/2019	
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Strongly Presumed Similar to	No Asbestos Detected	70558	BA3884/05	07/02/2019	
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Identified	No Asbestos Detected	70559	BA3884/06	07/02/2019	
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Strongly Presumed Similar to	No Asbestos Detected	70560	BA3884/06	07/02/2019	
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Strongly Presumed Similar to	No Asbestos Detected	70561	BA3884/06	07/02/2019	
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Strongly Presumed Similar to	No Asbestos Detected	70562	BA3884/06	07/02/2019	
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Strongly Presumed Similar to	No Asbestos Detected	70563	BA3884/06	07/02/2019	
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Strongly Presumed Similar to	No Asbestos Detected	70564	BA3884/06	07/02/2019	
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Strongly Presumed Similar to	No Asbestos Detected	70565	BA3884/06	07/02/2019	
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Strongly Presumed Similar to	No Asbestos Detected	70566	BA3884/06	07/02/2019	
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Strongly Presumed Similar to	No Asbestos Detected	70567	BA3884/06	07/02/2019	
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Strongly Presumed Similar to	No Asbestos Detected	70568	BA3884/06	07/02/2019	
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Strongly Presumed Similar to	No Asbestos Detected	70569	BA3884/06	07/02/2019	
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Hose Reel Cupboard	Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Strongly Presumed Similar to	No Asbestos Detected	70570	BA3884/06	07/02/2019	
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Strongly Presumed Similar to	No Asbestos Detected	70571	BA3884/06	07/02/2019	
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Strongly Presumed Similar to	No Asbestos Detected	70572	BA3884/06	07/02/2019	
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Strongly Presumed Similar to	No Asbestos Detected	70573	BA3884/06	07/02/2019	
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Strongly Presumed Similar to	No Asbestos Detected	70574	BA3884/06	07/02/2019	
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Strongly Presumed Similar to	No Asbestos Detected	70575	BA3884/06	07/02/2019	
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Strongly Presumed Similar to	No Asbestos Detected	70576	BA3884/06	07/02/2019	
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Strongly Presumed Similar to	No Asbestos Detected	70577	BA3884/06	07/02/2019	
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Strongly Presumed Similar to	No Asbestos Detected	70578	BA3884/06	07/02/2019	
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Strongly Presumed Similar to	No Asbestos Detected	70579	BA3884/06	07/02/2019	
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Strongly Presumed Similar to	No Asbestos Detected	70580	BA3884/06	07/02/2019	
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Strongly Presumed Similar to	No Asbestos Detected	70581	BA3884/06	07/02/2019	
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Strongly Presumed Similar to	No Asbestos Detected	70582	BA3884/06	07/02/2019	
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Strongly Presumed Similar to	No Asbestos Detected	70583	BA3884/06	07/02/2019	
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Strongly Presumed Similar to	No Asbestos Detected	70584	BA3884/06	07/02/2019	
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Strongly Presumed Similar to	No Asbestos Detected	70585	BA3884/06	07/02/2019	

#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70586	BA3884/06			07/02/2019		
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70587	BA3884/06			07/02/2019		
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70588	BA3884/06			07/02/2019		
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	70589	BA3884/07			07/02/2019		
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70590	BA3884/07			07/02/2019		
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70591	BA3884/07			07/02/2019		
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70592	BA3884/07			07/02/2019		
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70593	BA3884/07			07/02/2019		
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70594	BA3884/07			07/02/2019		
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70595	BA3884/07			07/02/2019		
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70596	BA3884/07			07/02/2019		
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70597	BA3884/07			07/02/2019		
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70598	BA3884/07			07/02/2019		
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70599	BA3884/07			07/02/2019		
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70600	BA3884/07			07/02/2019		
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	70601	BA3884/08			07/02/2019		
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70602	BA3884/08			07/02/2019		
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70603	BA3884/08			07/02/2019		
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70604	BA3884/08			07/02/2019		
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70605	BA3884/08			07/02/2019		
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70606	BA3884/08			07/02/2019		
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	70607	BA3884/09			07/02/2019		
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70608	BA3884/09			07/02/2019		
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70609	BA3884/09			07/02/2019		
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70610	BA3884/09			07/02/2019		
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70611	BA3884/09			07/02/2019		
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70612	BA3884/09			07/02/2019		
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	70613	BA3884/10			07/02/2019		
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70614	BA3884/10			07/02/2019		
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70615	BA3884/10			07/02/2019		
#REF!	QAA	Craigavon Hospital	01	Fanlight Panel		Insulating Board	Amosite/Chrysotile	Enclosed Spray or Laosino/Sealed AIB	Low	Apply caution when maintaining and affix ID labels	Re-inspection	HSG227	Unchecked	Low Risk	6	20/01/2024	Identified	Low Risk	70616	BA3884/11	9302.22	20/01/2023	WHS	
#REF!	QAA	Craigavon Hospital	01	Fanlight Panel		Insulating Board	Amosite/Chrysotile	Enclosed Spray or Laosino/Sealed AIB	Low	Apply caution when maintaining and affix ID labels	Review – No Change	HSG227	Unchecked	Low Risk	6	05/02/2014	Strongly Presumed Similar to	Low Risk	70617	BA3884/11		07/02/2019		
#REF!	QAA	Craigavon Hospital	01	Fanlight Panel		Insulating Board	Amosite/Chrysotile	Enclosed Spray or Laosino/Sealed AIB	Low	Apply caution when maintaining and affix ID labels	Re-inspection	HSG227	Unchecked	Low Risk	6	07/05/2023	Strongly Presumed Similar to	Low Risk	70618	BA3884/11	9302.22	07/05/2022	WHS	
#REF!	QAA	Craigavon Hospital	01	Fanlight Panel		Insulating Board	Amosite/Chrysotile	Enclosed Spray or Laosino/Sealed AIB	Low	Apply caution when maintaining and affix ID labels	Re-inspection	HSG227	Unchecked	Low Risk	6	05/07/2023	Strongly Presumed Similar to	Low Risk	70619	BA3884/11	9302.22	05/07/2022	WHS	
#REF!	QAA	Craigavon Hospital	01	Fanlight Panel		Insulating Board	Amosite/Chrysotile	Enclosed Spray or Laosino/Sealed AIB	Low	Apply caution when maintaining and affix ID labels	Re-inspection	HSG227	Unchecked	Low Risk	6	07/05/2023	Strongly Presumed Similar to	Low Risk	70620	BA3884/11	9302.22	07/05/2022	WHS	
#REF!	QAA	Craigavon Hospital	01	Fanlight Panel		Insulating Board	Amosite/Chrysotile	Enclosed Spray or Laosino/Sealed AIB	Low	Apply caution when maintaining and affix ID labels	Re-inspection	HSG227	Unchecked	Low Risk	6	20/01/2024	Strongly Presumed Similar to	Low Risk	70621	BA3884/11	9302.22	20/01/2023	WHS	
#REF!	QAA	Craigavon Hospital	01	Fanlight Panel		Insulating Board	Amosite/Chrysotile	Enclosed Spray or Laosino/Sealed AIB	Low	Apply caution when maintaining and affix ID labels	Review – No Change	HSG227	Unchecked	Low Risk	6	05/02/2014	Strongly Presumed Similar to	Low Risk	70622	BA3884/11		07/02/2019		
#REF!	QAA	Craigavon Hospital	01	Fanlight Panel		Insulating Board	Amosite/Chrysotile	Enclosed Spray or Laosino/Sealed AIB	Low	Apply caution when maintaining and affix ID labels	Review – No Change	HSG227	Unchecked	Low Risk	6	05/02/2014	Strongly Presumed Similar to	Low Risk	70623	BA3884/11		07/02/2019		
#REF!	QAA	Craigavon Hospital	01	Fanlight Panel		Insulating Board	Amosite/Chrysotile	Enclosed Spray or Laosino/Sealed AIB	Low	Apply caution when maintaining and affix ID labels	Review – No Change	HSG227	Unchecked	Low Risk	6	05/02/2014	Strongly Presumed Similar to	Low Risk	70624	BA3884/11		07/02/2019		
#REF!	QAA	Craigavon Hospital	01	Fanlight Panel		Insulating Board	Amosite/Chrysotile	Enclosed Spray or Laosino/Sealed AIB	Low	Apply caution when maintaining and affix ID labels	Review – No Change	HSG227	Unchecked	Low Risk	6	05/02/2014	Strongly Presumed Similar to	Low Risk	70625	BA3884/11		07/02/2019		
#REF!	QAA	Craigavon Hospital	01	Fanlight Panel		Insulating Board	Amosite/Chrysotile	Enclosed Spray or Laosino/Sealed AIB	Low	Apply caution when maintaining and affix ID labels	Review – No Change	HSG227	Unchecked	Low Risk	6	05/02/2014	Strongly Presumed Similar to	Low Risk	70626	BA3884/11		07/02/2019		
#REF!	QAA	Craigavon Hospital	01	Fanlight Panel		Insulating Board	Amosite/Chrysotile	Enclosed Spray or Laosino/Sealed AIB	Low	Apply caution when maintaining and affix ID labels	Review – No Change	HSG227	Unchecked	Low Risk	6	05/02/2014	Strongly Presumed Similar to	Low Risk	70627	BA3884/11		07/02/2019		
#REF!	QAA	Craigavon Hospital	01	Fanlight Panel		Insulating Board	Amosite/Chrysotile	Enclosed Spray or Laosino/Sealed AIB	Low	Apply caution when maintaining and affix ID labels	Review – No Change	HSG227	Unchecked	Low Risk	6	05/02/2014	Strongly Presumed Similar to	Low Risk	70628	BA3884/11		07/02/2019		
#REF!	QAA	Craigavon Hospital	01	Fanlight Panel		Insulating Board	Amosite/Chrysotile	Enclosed Spray or Laosino/Sealed AIB	Low	Apply caution when maintaining and affix ID labels	Review – No Change	HSG227	Unchecked	Low Risk	6	05/02/2014	Strongly Presumed Similar to	Low Risk	70629	BA3884/11		07/02/2019		
#REF!	QAA	Craigavon Hospital	01	Fanlight Panel		Insulating Board	Amosite/Chrysotile	Enclosed Spray or Laosino/Sealed AIB	Low	Apply caution when maintaining and affix ID labels	Review – No Change	HSG227	Unchecked	Low Risk	6	05/02/2014	Strongly Presumed Similar to	Low Risk	70630	BA3884/11		07/02/2019		
#REF!	QAA	Craigavon Hospital	01	Fanlight Panel		Insulating Board	Amosite/Chrysotile	Enclosed Spray or Laosino/Sealed AIB	Low	Apply caution when maintaining and affix ID labels	Review – No Change	HSG227	Unchecked	Low Risk	6	05/02/2014	Strongly Presumed Similar to	Low Risk	70631	BA3884/11		07/02/2019		
#REF!	QAA	Craigavon Hospital	01	Fanlight Panel		Insulating Board	Amosite/Chrysotile	Enclosed Spray or Laosino/Sealed AIB	Low	Apply caution when maintaining and affix ID labels	Review – No Change	HSG227	Unchecked	Low Risk	6	05/02/2014	Strongly Presumed Similar to	Low Risk	70632	BA3884/11		07/02/2019		
#REF!	QAA	Craigavon Hospital	01	Fanlight Panel		Insulating Board	Amosite/Chrysotile	Enclosed Spray or Laosino/Sealed AIB	Low	Apply caution when maintaining and affix ID labels	Review – No Change	HSG227	Unchecked	Low Risk	6	05/02/2014	Strongly Presumed Similar to	Low Risk	70633	BA3884/11		07/02/2019		
#REF!	QAA	Craigavon Hospital	01	Fanlight Panel		Insulating Board	Amosite/Chrysotile	Enclosed Spray or Laosino/Sealed AIB	Low	Apply caution when maintaining and affix ID labels	Review – No Change	HSG227	Unchecked	Low Risk	6	05/02/2014	Strongly Presumed Similar to	Low Risk	70634	BA3884/11		07/02/2019		
#REF!	QAA	Craigavon Hospital	01	Fanlight Panel		Insulating Board	Amosite/Chrysotile	Enclosed Spray or Laosino/Sealed AIB	Low	Apply caution when maintaining and affix ID labels	Review – No Change	HSG227	Unchecked	Low Risk	6	05/02/2014	Strongly Presumed Similar to	Low Risk	70635	BA3884/11		07/02/2019		
#REF!	QAA	Craigavon Hospital	01	Fanlight Panel		Insulating Board	Amosite/Chrysotile	Enclosed Spray or Laosino/Sealed AIB	Low	Apply caution when maintaining and affix ID labels	Review – No Change	HSG227	Unchecked	Low Risk	6	05/02/2014	Strongly Presumed Similar to	Low Risk	70636	BA3884/11		07/02/2019		
#REF!	QAA	Craigavon Hospital	01	Fanlight Panel		Insulating Board	Amosite/Chrysotile	Enclosed Spray or Laosino/Sealed AIB	Low	Apply caution when maintaining and affix ID labels	Review – No Change	HSG227	Unchecked	Low Risk	6	05/02/2014	Strongly Presumed Similar to	Low Risk	70637	BA3884/11		07/02/2019		
#REF!	QAA	Craigavon Hospital	01	Fanlight Panel		Insulating Board	Amosite/Chrysotile	Enclosed Spray or Laosino/Sealed AIB	Low	Apply caution when maintaining and affix ID labels	Review – No Change	HSG227	Unchecked	Low Risk	6	05/02/2014	Strongly Presumed Similar to	Low Risk	70638	BA3884/11		07/02/2019		
#REF!	QAA	Craigavon Hospital	01	Fanlight Panel		Insulating Board	Amosite/Chrysotile	Enclosed Spray or Laosino/Sealed AIB	Low	Apply caution when maintaining and affix ID labels	Review – No Change	HSG227	Unchecked	Low Risk	6	05/02/2014	Strongly Presumed Similar to	Low Risk	70639	BA3884/11		07/02/2019		
#REF!	QAA	Craigavon Hospital	01	Fanlight Panel		Insulating Board	Amosite/Chrysotile	Enclosed Spray or Laosino/Sealed AIB	Low	Apply caution when maintaining and affix ID labels	Review – No Change	HSG227	Unchecked	Low Risk	6	05/02/2014	Strongly Presumed Similar to	Low Risk	70640	BA3884/11		07/02/2019		
#REF!	QAA	Craigavon Hospital	01	Fanlight Panel		Insulating Board	Amosite/Chrysotile	Enclosed Spray or Laosino/Sealed AIB	Low	Apply caution when maintaining and affix ID labels	Review – No Change	HSG227	Unchecked	Low Risk	6	05/02/2014	Strongly Presumed Similar to	Low Risk	70641	BA3884/11		07/02/2019		
#REF!	QAA	Craigavon Hospital	01	Fanlight Panel		Insulating Board	Amosite/Chrysotile	Enclosed Spray or Laosino/Sealed AIB	Low	Apply caution when maintaining and affix ID labels	Review – No Change	HSG227	Unchecked	Low Risk	6	05/02/2014	Strongly Presumed Similar to	Low Risk	70642	BA3884/11		07/02/2019		
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	70643	BA3884/12			07/02/2019		
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70644	BA3884/12			07/02/2019		
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70645	BA3884/12			07/02/2019		
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70646	BA3884/12			07/02/2019		
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70647	BA3884/12			07/02/2019		
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	70648	BA3884/13			07/02/2019		
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70649	BA3884/13			07/02/2019		
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70650	BA3884/13			07/02/2019		
#REF!	QAA	Craigavon Hospital	01	Debris	Hose Reel Cupboard	Insulating Board	Amosite/Chrysotile	Encapsulated Spray or Laosino/Unsealed AIB	Loose asbestos debris or residue	Environmentally Clean (Controlled Conditions)	Re-inspection	HSG227	Unchecked	Medium Risk	9	05/07/2023	Identified	Medium Risk	70651	BA3884/14	9302.22	05/07/2022	WHS	
#REF!	QAA	Craigavon Hospital	01	Boarding		Cement Products	Chrysotile	Enclosed Spray or Laosino/Sealed AIB	Low	Apply caution when maintaining and affix ID labels	Re-inspection	HSG227	Unchecked	Very Low Risk	4	05/07/2023	Identified	Very Low Risk	70652	BA3881/15	9302.22	05/07/2022	WHS	
#REF!	QAA	Craigavon Hospital	01	Boarding		Cement Products	Chrysotile	Enclosed Spray or Laosino/Sealed AIB	Low	Apply caution when maintaining and affix ID labels	Re-inspection	HSG227	Unchecked	Very Low Risk	4	20/01/2024	Identified	Very Low Risk	70653	BA3881/15	9302.22	20/01/2023	WHS	
#REF!	QAA	Craigavon Hospital	01	Boarding		Cement Products	Chrysotile	Enclosed Spray or Laosino/Sealed AIB	Low	Apply caution when maintaining and affix ID labels	Re-inspection	HSG227	Unchecked	Very Low Risk	4	06/08/2014	Strongly Presumed Similar to	Very Low Risk	70654	BA3881/15	9302.22	07/02/2019	WHS	
#REF!	QAA	Craigavon Hospital	01	Pipe Insulation		Thermal Insulation	NO ASBESTOS	Encapsulated Spray or Laosino/Unsealed AIB	Medium	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	70655	BA3884/16			07/02/2019		
#REF!	QAA	Craigavon Hospital	01	General Debris		General Debris	NO ASBESTOS	Encapsulated Spray or Laosino/Unsealed AIB	High	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	70656	BA3884/17			07/02/2019		
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	70657	BA3884/18			07/02/2019		
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70658	BA3884/18			07/02/2019		

#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70659	BA3884/18		07/02/2019						
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70660	BA3884/18		07/02/2019						
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	70661	BA3884/19		07/02/2019						
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70662	BA3884/19		07/02/2019						
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70663	BA3884/19		07/02/2019						
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70664	BA3884/19		07/02/2019						
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	70665	BA3884/20		07/02/2019						
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70666	BA3884/20		07/02/2019						
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70667	BA3884/20		07/02/2019						
#REF!	QAA	Craigavon Hospital	01	Boarding		Cement Products	NO ASBESTOS	Enclosed Spray or Lagging/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	70668	BA3884/21		07/02/2019						
#REF!	QAA	Craigavon Hospital	01	Boarding		Cement Products	NO ASBESTOS	Enclosed Spray or Lagging/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70669	BA3884/21		07/02/2019						
#REF!	QAA	Craigavon Hospital	01	Board		Insulating Board	NO ASBESTOS	Encapsulated Spray or Lagging/Unsealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	70670	BA3884/22		07/02/2019						
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	70671	BA3884/23		07/02/2019						
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70672	BA3884/23		07/02/2019						
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	70673	BA3884/24		07/02/2019						
#REF!	QAA	Craigavon Hospital	01	Board	Hose Reel Cupboard	Insulating Board	Amosite/Chrysotile	Encapsulated Spray or Lagging/Unsealed AIB	Medium	Encapsulate, Manage & Affix ID Labels	Re-inspection	HSG227	Unchecked	Medium Risk	8	05/01/2023	Identified	Medium Risk	70674	BA3884/25	9302.22	05/07/2022	WHS					
#REF!	QAA	Craigavon Hospital	01	Board		Insulating Board	Amosite/Chrysotile	Encapsulated Spray or Lagging/Unsealed AIB	Medium	Encapsulate, Manage & Affix ID Labels	Review – No Change	HSG227	Unchecked	Medium Risk	8	05/02/2014	Strongly Presumed Similar to	Medium Risk	70675	BA3884/25		07/02/2019						
#REF!	QAA	Craigavon Hospital	01	Board	Hose Reel Cupboard	Insulating Board	NO ASBESTOS	Encapsulated Spray or Lagging/Unsealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	70676	BA3883/01		07/02/2019						
#REF!	QAA	Craigavon Hospital	01	Board		Insulating Board	NO ASBESTOS	Encapsulated Spray or Lagging/Unsealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70677	BA3883/01		07/02/2019						
#REF!	QAA	Craigavon Hospital	01	Board		Insulating Board	NO ASBESTOS	Encapsulated Spray or Lagging/Unsealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70678	BA3883/01		07/02/2019						
#REF!	QAA	Craigavon Hospital	01	Board		Insulating Board	NO ASBESTOS	Encapsulated Spray or Lagging/Unsealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70679	BA3883/01		07/02/2019						
#REF!	QAA	Craigavon Hospital	01	Board	Switchroom	Insulating Board	NO ASBESTOS	Encapsulated Spray or Lagging/Unsealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70680	BA3883/01		07/02/2019						
#REF!	QAA	Craigavon Hospital	01	General Debris		General Debris	NO ASBESTOS	Encapsulated Spray or Lagging/Unsealed AIB	High	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	70681	BA3883/02		07/02/2019						
#REF!	QAA	Craigavon Hospital	01	Pipe Insulation		Thermal Insulation	NO ASBESTOS	Encapsulated Spray or Lagging/Unsealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	70682	BA3883/03		07/02/2019						
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	70683	BA3883/04		07/02/2019						
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70684	BA3883/04		07/02/2019						
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70685	BA3883/04		07/02/2019						
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70686	BA3883/04		07/02/2019						
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Hose Reel Cupboard	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70687	BA3883/04		07/02/2019						
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70688	BA3883/04		07/02/2019						
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70689	BA3883/04		07/02/2019						
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70690	BA3883/04		07/02/2019						
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70691	BA3883/04		07/02/2019						
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70692	BA3883/04		07/02/2019						
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70693	BA3883/04		07/02/2019						
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70694	BA3883/04		07/02/2019						
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70695	BA3883/04		07/02/2019						
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70696	BA3883/04		07/02/2019						
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70697	BA3883/04		07/02/2019						
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70698	BA3883/04		07/02/2019						
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	70699	BA3883/05		07/02/2019						
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70700	BA3883/05		07/02/2019						
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70701	BA3883/05		07/02/2019						
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70702	BA3883/05		07/02/2019						
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70703	BA3883/05		07/02/2019						
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70704	BA3883/05		07/02/2019						
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70705	BA3883/05		07/02/2019						
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70706	BA3883/05		07/02/2019						
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	70707	BA3883/06		07/02/2019						
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70708	BA3883/06		07/02/2019						
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70709	BA3883/06		07/02/2019						
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70710	BA3883/06		07/02/2019						
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70711	BA3883/06		07/02/2019						
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	70712	BA3883/07		07/02/2019						
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70713	BA3883/07		07/02/2019						
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70714	BA3883/07		07/02/2019						
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70715	BA3883/07		07/02/2019						
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70716	BA3883/07		07/02/2019						
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70717	BA3883/07		07/02/2019						
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	70718	BA3883/08		07/02/2019						
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70719	BA3883/08		07/02/2019						
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70720	BA3883/08		07/02/2019						
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70721	BA3883/08		07/02/2019						
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70722	BA3883/08		07/02/2019						
#REF!	QAA	Craigavon Hospital	01	Insulation		Thermal Insulation	NO ASBESTOS	Encapsulated Spray or Lagging/Unsealed AIB	High	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	70723	BA3883/09		07/02/2019						
#REF!	QAA	Craigavon Hospital	01	Bitumen Felt		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	70724	BA3883/10		07/02/2019						
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	70725	BA3883/11		07/02/2019						
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70726	BA3883/11		07/02/2019						
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70727	BA3883/11		07/02/2019						
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70728	BA3883/11		07/02/2019						
#REF!	QAA	Craigavon Hospital	01	Wall Panels		Insulating Board	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	70729	BA3883/12		07/02/2019						
#REF!	QAA	Craigavon Hospital	01	Wall Panels		Insulating Board	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70730	BA3883/12		07/02/2019						
#REF!	QAA	Craigavon Hospital	01	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	70731	BA3883/13		07/02/2019						

#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	70732	BA3883/14	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70733	BA3883/14	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70734	BA3883/14	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70735	BA3883/14	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70736	BA3883/14	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	70737	BA3883/15	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70738	BA3883/15	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70739	BA3883/15	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70740	BA3883/15	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	70741	BA3883/16	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70742	BA3883/16	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70743	BA3883/16	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70744	BA3883/16	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70745	BA3883/16	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	70746	BA3883/17	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70747	BA3883/17	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70748	BA3883/17	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Low	Apply caution when maintaining and affix ID labels	Review – No Change	HSG227	Unchecked	Very Low Risk	3	06/08/2014	Identified	Very Low Risk	70749	BA3883/18	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	70750	BA3883/19	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70751	BA3883/19	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70752	BA3883/19	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70753	BA3883/19	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	70754	BA3883/20	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70755	BA3883/20	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70756	BA3883/20	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Boarding		Cement Products	Chrysotile	Enclosed Spray or Lagging/Sealed AIB	Low	Apply caution when maintaining and affix ID labels	Review – No Change	HSG227	Unchecked	Very Low Risk	4	06/08/2014	Identified	Very Low Risk	70757	BA3883/21	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Boarding		Cement Products	Chrysotile	Enclosed Spray or Lagging/Sealed AIB	Low	Apply caution when maintaining and affix ID labels	Review – No Change	HSG227	Unchecked	Very Low Risk	4	06/08/2014	Strongly Presumed Similar to	Very Low Risk	70758	BA3883/21	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Boarding		Cement Products	Chrysotile	Enclosed Spray or Lagging/Sealed AIB	Low	Apply caution when maintaining and affix ID labels	Review – No Change	HSG227	Unchecked	Very Low Risk	4	06/08/2014	Strongly Presumed Similar to	Very Low Risk	70759	BA3883/21	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Boarding		Cement Products	Chrysotile	Enclosed Spray or Lagging/Sealed AIB	Low	Apply caution when maintaining and affix ID labels	Review – No Change	HSG227	Unchecked	Very Low Risk	4	06/08/2014	Strongly Presumed Similar to	Very Low Risk	70760	BA3883/21	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Boarding		Cement Products	Chrysotile	Enclosed Spray or Lagging/Sealed AIB	Low	Apply caution when maintaining and affix ID labels	Review – No Change	HSG227	Unchecked	Very Low Risk	4	06/08/2014	Strongly Presumed Similar to	Very Low Risk	70761	BA3883/21	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Boarding		Cement Products	Chrysotile	Enclosed Spray or Lagging/Sealed AIB	Low	Apply caution when maintaining and affix ID labels	Review – No Change	HSG227	Unchecked	Very Low Risk	4	06/08/2014	Strongly Presumed Similar to	Very Low Risk	70762	BA3883/21	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Boarding		Cement Products	Chrysotile	Enclosed Spray or Lagging/Sealed AIB	Low	Apply caution when maintaining and affix ID labels	Review – No Change	HSG227	Unchecked	Very Low Risk	4	06/08/2014	Strongly Presumed Similar to	Very Low Risk	70763	BA3883/21	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Boarding		Cement Products	Chrysotile	Enclosed Spray or Lagging/Sealed AIB	Low	Apply caution when maintaining and affix ID labels	Review – No Change	HSG227	Unchecked	Very Low Risk	4	06/08/2014	Strongly Presumed Similar to	Very Low Risk	70764	BA3883/21	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Boarding		Cement Products	Chrysotile	Enclosed Spray or Lagging/Sealed AIB	Low	Apply caution when maintaining and affix ID labels	Review – No Change	HSG227	Unchecked	Very Low Risk	4	06/08/2014	Strongly Presumed Similar to	Very Low Risk	70765	BA3883/21	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Boarding		Cement Products	Chrysotile	Enclosed Spray or Lagging/Sealed AIB	Low	Apply caution when maintaining and affix ID labels	Review – No Change	HSG227	Unchecked	Very Low Risk	4	06/08/2014	Strongly Presumed Similar to	Very Low Risk	70766	BA3883/21	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Boarding		Cement Products	Chrysotile	Enclosed Spray or Lagging/Sealed AIB	Low	Apply caution when maintaining and affix ID labels	Review – No Change	HSG227	Unchecked	Very Low Risk	4	06/08/2014	Strongly Presumed Similar to	Very Low Risk	70767	BA3883/21	07/02/2019
#REF!	QAA	Craigavon Hospital	01	General Debris		General Debris	NO ASBESTOS	Encapsulated Spray or Lagging/Unsealed AIB	High	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	70768	BA3883/22	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	70769	BA3883/23	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	70770	BA3883/24	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70771	BA3883/24	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70772	BA3883/24	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	70773	BA3882/01	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70774	BA3882/01	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70775	BA3882/01	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	70776	BA3882/02	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	70777	BA3882/03	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	70778	BA3882/04	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	70779	BA3882/05	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Ceiling Tiles		Insulating Board	NO ASBESTOS	Encapsulated Spray or Lagging/Unsealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	70780	BA3882/06	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Ceiling Tiles		Insulating Board	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70781	BA3882/06	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Low	Apply caution when maintaining and affix ID labels	Review – No Change	HSG227	Unchecked	Very Low Risk	3	06/08/2014	Identified	Very Low Risk	70782	BA3883/25	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Low	Apply caution when maintaining and affix ID labels	Review – No Change	HSG227	Unchecked	Very Low Risk	3	06/08/2014	Identified	Very Low Risk	70783	BA3883/26	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	WC	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	70784	BA3882/07	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Debris		Cement Products	Chrysotile	Enclosed Spray or	High	Remove	Review – No Change	HSG227	Unchecked	Low Risk	6	06/08/2014	Identified	Low Risk	70785	BA3882/08	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	70786	BA3882/09	07/02/2019
#REF!	QAA	Craigavon Hospital	01	General Debris		General Debris	NO ASBESTOS	Composite Materials	Medium	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	70787	BA3882/10	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Ceiling Tiles		Insulating Board	Amosite/Chrysotile	Encapsulated Spray or Lagging/Unsealed AIB	Medium	Remove (Controlled Conditions)	Review – No Change	HSG227	Unchecked	Medium Risk	8	05/02/2014	Identified	Medium Risk	70788	BA3882/11	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Ceiling Tiles		Insulating Board	Amosite/Chrysotile	Encapsulated Spray or Lagging/Unsealed AIB	Medium	Remove (Controlled Conditions)	Review – No Change	HSG227	Unchecked	Medium Risk	8	05/02/2014	Strongly Presumed Similar to	Medium Risk	70789	BA3882/11	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Ceiling Tiles	Behind Switch at high level	Insulating Board	Amosite/Chrysotile	Encapsulated Spray or Lagging/Unsealed AIB	Medium	Remove (Controlled Conditions)	Review – No Change	HSG227	Unchecked	Medium Risk	8	05/02/2014	Strongly Presumed Similar to	Medium Risk	70790	BA3882/11	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	70791	BA3882/12	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70792	BA3882/12	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70793	BA3882/12	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70794	BA3882/12	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70795	BA3882/12	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70796	BA3882/12	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70797	BA3882/12	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	70798	BA3882/13	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70799	BA3882/13	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	70800	BA3882/14	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	70801	BA3882/15	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70802	BA3882/15	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70803	BA3882/15	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Pipe Insulation		Thermal Insulation	NO ASBESTOS	Encapsulated Spray or Lagging/Unsealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	70804	BA3882/16	07/02/2019

#REF!	QAA	Craigavon Hospital	01	Pipe Insulation		Thermal Insulation	NO ASBESTOS	Encapsulated Spray or Laosinin/Unsealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70805	BA3882/16	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Board		Insulating Board	NO ASBESTOS	Enclosed Spray or Laosinin/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	70806	BA3882/17	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Debris		Cement Products	Chrysotile	Encapsulated Spray or Laosinin/Unsealed AIB	High	Remove (Controlled Conditions)	Review – No Change	HSG227	Unchecked	Low Risk	6	06/08/2014	Identified	Low Risk	70807	BA3882/18	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Debris		Insulating Board	Amosite/Chrysotile	Encapsulated Spray or Laosinin/Unsealed AIB	High	Remove (Controlled Conditions)	Review – No Change	HSG227	Unchecked	Medium Risk	9	05/02/2014	Identified	Medium Risk	70808	BA3882/19	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Insulating Debris		General Debris	NO ASBESTOS	Encapsulated Spray or Laosinin/Unsealed AIB	High	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	70809	BA3882/20	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	70810	BA3882/21	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	70811	BA3882/22	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70812	BA3882/22	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	70813	BA3882/23	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70814	BA3882/23	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70815	BA3882/23	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Switch Room	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70816	BA3882/23	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	70817	BA3882/24	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70818	BA3882/24	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70819	BA3882/24	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70820	BA3882/24	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	70821	BA3882/25	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Switch Room	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70822	BA3882/25	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Wall Panels		Insulating Board	NO ASBESTOS	Encapsulated Spray or Laosinin/Unsealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	70823	BA3882/26	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Fire Cement		Cement Products	NO ASBESTOS	Enclosed Spray or Laosinin/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	70824	BA3882/27	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Fire Cement		Cement Products	NO ASBESTOS	Enclosed Spray or Laosinin/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70825	BA3882/27	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	70826	BA3882/28	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	70827	BA3882/29	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	70828	BA3882/30	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	70829	BA3882/31	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	70830	BA3882/32	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Pipe Brackets		Textiles & Paper	Chrysotile	Encapsulated Spray or Laosinin/Unsealed AIB	Low	Apply Caution when Maintaining	Review – No Change	HSG227	Unchecked	Low Risk	6	06/08/2014	Identified	Low Risk	70831	BA3882/33	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Pipe Brackets		Textiles & Paper	Chrysotile	Encapsulated Spray or Laosinin/Unsealed AIB	Low	Apply Caution when Maintaining	Review – No Change	HSG227	Unchecked	Low Risk	6	06/08/2014	Strongly Presumed Similar to	Low Risk	70832	BA3882/33	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	70833	BA3928/01	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70834	BA3928/01	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70835	BA3928/01	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70836	BA3928/01	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70837	BA3928/01	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70838	BA3928/01	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70839	BA3928/01	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70840	BA3928/01	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70841	BA3928/01	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70842	BA3928/01	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Hose Reel Cupboard	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70843	BA3928/01	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70844	BA3928/01	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70845	BA3928/01	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70846	BA3928/01	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70847	BA3928/01	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70848	BA3928/01	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70849	BA3928/01	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70850	BA3928/01	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70851	BA3928/01	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70852	BA3928/01	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70853	BA3928/01	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70854	BA3928/01	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70855	BA3928/01	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70856	BA3928/01	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70857	BA3928/01	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70858	BA3928/01	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70859	BA3928/01	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70860	BA3928/01	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70861	BA3928/01	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70862	BA3928/01	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70863	BA3928/01	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70864	BA3928/01	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70865	BA3928/01	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	70866	BA3928/02	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70867	BA3928/02	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70868	BA3928/02	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70869	BA3928/02	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70870	BA3928/02	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Hose Reel Cupboard	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70871	BA3928/02	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70872	BA3928/02	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70873	BA3928/02	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70874	BA3928/02	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70875	BA3928/02	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70876	BA3928/02	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70877	BA3928/02	07/02/2019

#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	70878	BA3928/03	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70879	BA3928/03	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70880	BA3928/03	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70881	BA3928/03	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70882	BA3928/03	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70883	BA3928/03	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70884	BA3928/03	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70885	BA3928/03	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70886	BA3928/03	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70887	BA3928/03	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70888	BA3928/03	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70889	BA3928/03	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70890	BA3928/03	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70891	BA3928/03	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70892	BA3928/03	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70893	BA3928/03	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70894	BA3928/03	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70895	BA3928/03	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70896	BA3928/03	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70897	BA3928/03	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70898	BA3928/03	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70899	BA3928/03	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70900	BA3928/03	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70901	BA3928/03	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	70902	BA3928/04	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70903	BA3928/04	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70904	BA3928/04	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70905	BA3928/04	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70906	BA3928/04	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70907	BA3928/04	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70908	BA3928/04	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70909	BA3928/04	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	70910	BA3928/05	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70911	BA3928/05	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70912	BA3928/05	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70913	BA3928/05	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70914	BA3928/05	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70915	BA3928/05	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70916	BA3928/05	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70917	BA3928/05	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70918	BA3928/05	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70919	BA3928/05	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70920	BA3928/05	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Sink Pad	Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	70921	BA3928/06	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Sink Pad	Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70922	BA3928/06	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Sink Pad	Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70923	BA3928/06	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Sink Pad	Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70924	BA3928/06	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Sink Pad	Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70925	BA3928/06	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Sink Pad	Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70926	BA3928/06	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	70927	BA3928/07	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70928	BA3928/07	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70929	BA3928/07	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	70930	BA3928/08	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Wall Panels	Insulating Board	NO ASBESTOS	Encapsulated Spray or Laooino/Unsealed AIB	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	70931	BA3928/09	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	70932	BA3928/10	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Pipe Brackets	Textiles & Paper	Chrysotile	Encapsulated Spray or Laooino/Unsealed AIB	Low	Apply Caution when Maintaining	Review – No Change	HSG227	Unchecked	Low Risk	6	06/08/2014	Identified	Low Risk	70933	BA3928/11	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Pipe Brackets	Textiles & Paper	Chrysotile	Encapsulated Spray or Laooino/Unsealed AIB	Low	Apply Caution when Maintaining	Review – No Change	HSG227	Unchecked	Low Risk	6	06/08/2014	Strongly Presumed Similar to	Low Risk	70934	BA3928/11	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Bitumen Skirting Boards	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	70935	BA3928/12	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	70936	BA3928/13	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70937	BA3928/13	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70938	BA3928/13	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Pipe Insulation	Thermal Insulation	NO ASBESTOS	Encapsulated Spray or Laooino/Unsealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	70939	BA3928/14	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Pipe Insulation	Thermal Insulation	NO ASBESTOS	Encapsulated Spray or Laooino/Unsealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70940	BA3928/14	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Bitumen Paints	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	70941	BA3928/15	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Board	Insulating Board	Amosite/Chrysotile	Enclosed Spray or Laooino/Sealed AIB	Low	Apply caution when maintaining and affix ID labels	Review – No Change	HSG227	Unchecked	Low Risk	6	05/02/2014	Identified	Low Risk	70942	BA3928/16	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Board	Insulating Board	Amosite/Chrysotile	Enclosed Spray or Laooino/Sealed AIB	Low	Apply caution when maintaining and affix ID labels	Review – No Change	HSG227	Unchecked	Low Risk	6	05/02/2014	Identified	Low Risk	70943	BA3928/17	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Board	Insulating Board	Amosite/Chrysotile	Enclosed Spray or Laooino/Sealed AIB	Low	Apply caution when maintaining and affix ID labels	Review – No Change	HSG227	Unchecked	Low Risk	6	05/02/2014	Strongly Presumed Similar to	Low Risk	70944	BA3928/17	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Board	Insulating Board	Amosite/Chrysotile	Enclosed Spray or Laooino/Sealed AIB	Low	Apply caution when maintaining and affix ID labels	Review – No Change	HSG227	Unchecked	Low Risk	6	05/02/2014	Strongly Presumed Similar to	Low Risk	70945	BA3928/17	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Board	Insulating Board	Amosite/Chrysotile	Enclosed Spray or Laooino/Sealed AIB	Low	Apply caution when maintaining and affix ID labels	Review – No Change	HSG227	Unchecked	Low Risk	6	05/02/2014	Strongly Presumed Similar to	Low Risk	70946	BA3928/17	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	70947	BA3928/18	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70948	BA3928/18	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70949	BA3928/18	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70950	BA3928/18	07/02/2019

#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70951	BA3928/18	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70952	BA3928/18	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70953	BA3928/18	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Hose Reel Cupboard	Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70954	BA3928/18	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70955	BA3928/18	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70956	BA3928/18	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70957	BA3928/18	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70958	BA3928/18	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70959	BA3928/18	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70960	BA3928/18	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70961	BA3928/18	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70962	BA3928/18	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70963	BA3928/18	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	70964	BA3928/19	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70965	BA3928/19	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70966	BA3928/19	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70967	BA3928/19	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70968	BA3928/19	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	70969	BA3928/20	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	70970	BA3928/21	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70971	BA3928/21	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Board	Hose Reel Cupboard	Insulating Board	Amosite/Chrysotile	Enclosed Spray or Laosinn/Sealed AIB	Low	Apply caution when maintaining and affix ID labels	Review – No Change	HSG227	Unchecked	Low Risk	6	05/02/2014	Identified	Low Risk	70972	BA3928/22	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Board	Hose Reel Cupboard	Insulating Board	Amosite/Chrysotile	Enclosed Spray or Laosinn/Sealed AIB	Low	Apply caution when maintaining and affix ID labels	Review – No Change	HSG227	Unchecked	Low Risk	6	05/02/2014	Strongly Presumed Similar to	Low Risk	70973	BA3928/22	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	70974	BA3928/23	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70975	BA3928/23	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	Chrysotile	Composite Materials	None	Apply caution when maintaining and affix ID labels	Review – No Change	HSG227	Unchecked	Very Low Risk	2	06/08/2014	Identified	Very Low Risk	70976	BA3928/24	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	Chrysotile	Composite Materials	None	Apply caution when maintaining and affix ID labels	Review – No Change	HSG227	Unchecked	Very Low Risk	2	06/08/2014	Strongly Presumed Similar to	Very Low Risk	70977	BA3928/24	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	Chrysotile	Composite Materials	None	Apply caution when maintaining and affix ID labels	Review – No Change	HSG227	Unchecked	Very Low Risk	2	06/08/2014	Strongly Presumed Similar to	Very Low Risk	70978	BA3928/24	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	Chrysotile	Composite Materials	None	Apply caution when maintaining and affix ID labels	Review – No Change	HSG227	Unchecked	Very Low Risk	2	06/08/2014	Strongly Presumed Similar to	Very Low Risk	70979	BA3928/24	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Pipe Insulation		Thermal Insulation	NO ASBESTOS	Encapsulated Spray or Laosinn/Unsealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	70980	BA3928/25	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Pipe Insulation		Thermal Insulation	NO ASBESTOS	Encapsulated Spray or Laosinn/Unsealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70981	BA3928/25	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	70982	BA3928/26	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70983	BA3928/26	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Board		Insulating Board	NO ASBESTOS	Enclosed Spray or Laosinn/Sealed AIB	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	70984	BA3928/27	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Board		Insulating Board	NO ASBESTOS	Enclosed Spray or Laosinn/Sealed AIB	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70985	BA3928/27	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Board		Insulating Board	NO ASBESTOS	Enclosed Spray or Laosinn/Sealed AIB	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70986	BA3928/27	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Board		Insulating Board	NO ASBESTOS	Enclosed Spray or Laosinn/Sealed AIB	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70987	BA3928/27	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Board		Insulating Board	NO ASBESTOS	Enclosed Spray or Laosinn/Sealed AIB	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70988	BA3928/27	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Board		Insulating Board	NO ASBESTOS	Enclosed Spray or Laosinn/Sealed AIB	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70989	BA3928/27	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Board		Insulating Board	NO ASBESTOS	Enclosed Spray or Laosinn/Sealed AIB	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70990	BA3928/27	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Board		Insulating Board	NO ASBESTOS	Enclosed Spray or Laosinn/Sealed AIB	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70991	BA3928/27	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Board		Insulating Board	NO ASBESTOS	Enclosed Spray or Laosinn/Sealed AIB	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70992	BA3928/27	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	70993	BA3928/28	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70994	BA3928/28	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70995	BA3928/28	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70996	BA3928/28	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70997	BA3928/28	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	70998	BA3928/29	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	70999	BA3928/29	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	71000	BA3928/30	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	71001	BA3928/30	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	71002	BA3928/31	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	71003	BA3928/32	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	71004	BA3928/33	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	71005	BA3928/33	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	71006	BA3928/33	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	71007	BA3928/33	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Hose Reel Cupboard	Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	71008	BA3928/33	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	71009	BA3928/33	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Hose Reel Cupboard	Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	71010	BA3928/33	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	71011	BA3928/33	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	71012	BA3928/34	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	71013	BA3928/34	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Board		Insulating Board	NO ASBESTOS	Enclosed Spray or Laosinn/Sealed AIB	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	71014	BA3928/35	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Board		Insulating Board	NO ASBESTOS	Enclosed Spray or Laosinn/Sealed AIB	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	71015	BA3928/35	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Board		Insulating Board	NO ASBESTOS	Enclosed Spray or Laosinn/Sealed AIB	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	71016	BA3928/35	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Bitumen Skirting Boards	Hose Reel Cupboard	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	71017	BA3928/36	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	71018	BA3928/37	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Wall Panels		Insulating Board	NO ASBESTOS	Enclosed Spray or Laosinn/Sealed AIB	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	71019	BA3928/38	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Wall Panels		Insulating Board	NO ASBESTOS	Enclosed Spray or Laosinn/Sealed AIB	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	71020	BA3928/38	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Wall Panels		Insulating Board	NO ASBESTOS	Enclosed Spray or Laosinn/Sealed AIB	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	71021	BA3928/38	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	71022	BA3928/39	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Board		Insulating Board	NO ASBESTOS	Enclosed Spray or Laosinn/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	72999	BA4034/01	07/02/2019

#REF!	QAA	Craigavon Hospital	01	Board	Insulating Board	NO ASBESTOS	Enclosed Spray or Lagging/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Strongly Presumed Similar to	No Asbestos Detected	73000	BA4034/01	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Board	Insulating Board	NO ASBESTOS	Enclosed Spray or Lagging/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Strongly Presumed Similar to	No Asbestos Detected	73002	BA4034/01	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Board	Insulating Board	NO ASBESTOS	Enclosed Spray or Lagging/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Strongly Presumed Similar to	No Asbestos Detected	73003	BA4034/01	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Board	Insulating Board	NO ASBESTOS	Enclosed Spray or Lagging/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Strongly Presumed Similar to	No Asbestos Detected	73004	BA4034/01	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Board	Insulating Board	NO ASBESTOS	Enclosed Spray or Lagging/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Strongly Presumed Similar to	No Asbestos Detected	73005	BA4034/01	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Identified	No Asbestos Detected	73006	BA4034/02	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Strongly Presumed Similar to	No Asbestos Detected	73007	BA4034/02	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Strongly Presumed Similar to	No Asbestos Detected	73008	BA4034/02	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Strongly Presumed Similar to	No Asbestos Detected	73009	BA4034/02	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Strongly Presumed Similar to	No Asbestos Detected	73010	BA4034/02	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Strongly Presumed Similar to	No Asbestos Detected	73011	BA4034/02	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Strongly Presumed Similar to	No Asbestos Detected	73012	BA4034/02	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Strongly Presumed Similar to	No Asbestos Detected	73013	BA4034/02	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Strongly Presumed Similar to	No Asbestos Detected	73014	BA4034/02	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Strongly Presumed Similar to	No Asbestos Detected	73015	BA4034/02	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Strongly Presumed Similar to	No Asbestos Detected	73017	BA4034/02	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Strongly Presumed Similar to	No Asbestos Detected	73018	BA4034/02	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Strongly Presumed Similar to	No Asbestos Detected	73019	BA4034/02	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Strongly Presumed Similar to	No Asbestos Detected	73020	BA4034/02	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Strongly Presumed Similar to	No Asbestos Detected	73021	BA4034/02	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Strongly Presumed Similar to	No Asbestos Detected	73023	BA4034/02	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Strongly Presumed Similar to	No Asbestos Detected	73024	BA4034/02	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Strongly Presumed Similar to	No Asbestos Detected	73026	BA4034/02	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Strongly Presumed Similar to	No Asbestos Detected	73027	BA4034/02	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Strongly Presumed Similar to	No Asbestos Detected	73028	BA4034/02	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Strongly Presumed Similar to	No Asbestos Detected	73029	BA4034/02	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Strongly Presumed Similar to	No Asbestos Detected	73030	BA4034/02	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Strongly Presumed Similar to	No Asbestos Detected	73031	BA4034/02	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Strongly Presumed Similar to	No Asbestos Detected	73032	BA4034/02	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Identified	No Asbestos Detected	73033	BA4034/03	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Strongly Presumed Similar to	No Asbestos Detected	73034	BA4034/03	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Strongly Presumed Similar to	No Asbestos Detected	73035	BA4034/03	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Strongly Presumed Similar to	No Asbestos Detected	73036	BA4034/03	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Strongly Presumed Similar to	No Asbestos Detected	73037	BA4034/03	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Strongly Presumed Similar to	No Asbestos Detected	73038	BA4034/03	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Strongly Presumed Similar to	No Asbestos Detected	73039	BA4034/03	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Strongly Presumed Similar to	No Asbestos Detected	73041	BA4034/03	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Strongly Presumed Similar to	No Asbestos Detected	73042	BA4034/02	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Strongly Presumed Similar to	No Asbestos Detected	73043	BA4034/03	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Strongly Presumed Similar to	No Asbestos Detected	73046	BA4034/03	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Strongly Presumed Similar to	No Asbestos Detected	73047	BA4034/03	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Strongly Presumed Similar to	No Asbestos Detected	73048	BA4034/03	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Strongly Presumed Similar to	No Asbestos Detected	73050	BA4034/03	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Strongly Presumed Similar to	No Asbestos Detected	73051	BA4034/03	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Strongly Presumed Similar to	No Asbestos Detected	73052	BA4034/03	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Strongly Presumed Similar to	No Asbestos Detected	73054	BA4034/03	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Strongly Presumed Similar to	No Asbestos Detected	73055	BA4034/03	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Strongly Presumed Similar to	No Asbestos Detected	73056	BA4034/03	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Strongly Presumed Similar to	No Asbestos Detected	73057	BA4034/03	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Strongly Presumed Similar to	No Asbestos Detected	73058	BA4034/03	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Strongly Presumed Similar to	No Asbestos Detected	73060	BA4034/03	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Strongly Presumed Similar to	No Asbestos Detected	73061	BA4034/03	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Strongly Presumed Similar to	No Asbestos Detected	73062	BA4034/03	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Strongly Presumed Similar to	No Asbestos Detected	73063	BA4034/03	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Strongly Presumed Similar to	No Asbestos Detected	73065	BA4034/03	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Strongly Presumed Similar to	No Asbestos Detected	73066	BA4034/03	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Strongly Presumed Similar to	No Asbestos Detected	73067	BA4034/03	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Strongly Presumed Similar to	No Asbestos Detected	73068	BA4034/03	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Strongly Presumed Similar to	No Asbestos Detected	73069	BA4034/03	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Strongly Presumed Similar to	No Asbestos Detected	73070	BA4034/03	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Strongly Presumed Similar to	No Asbestos Detected	73071	BA4034/03	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Strongly Presumed Similar to	No Asbestos Detected	73072	BA4034/03	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Strongly Presumed Similar to	No Asbestos Detected	73073	BA4034/03	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Strongly Presumed Similar to	No Asbestos Detected	73074	BA4034/03	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Strongly Presumed Similar to	No Asbestos Detected	73075	BA4034/03	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Strongly Presumed Similar to	No Asbestos Detected	73077	BA4034/03	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Strongly Presumed Similar to	No Asbestos Detected	73078	BA4034/03	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Strongly Presumed Similar to	No Asbestos Detected	73079	BA4034/03	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Strongly Presumed Similar to	No Asbestos Detected	73080	BA4034/03	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Strongly Presumed Similar to	No Asbestos Detected	73081	BA4034/03	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Strongly Presumed Similar to	No Asbestos Detected	73082	BA4034/03	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Strongly Presumed Similar to	No Asbestos Detected	73083	BA4034/03	07/02/2019
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	Strongly Presumed Similar to	No Asbestos Detected	73084	BA4034/03	07/02/2019

#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	73086	BA4034/03		07/02/2019		
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	73087	BA4034/03		07/02/2019		
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	73088	BA4034/03		07/02/2019		
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	73089	BA4034/03		07/02/2019		
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	73090	BA4034/03		07/02/2019		
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	73092	BA4034/03		07/02/2019		
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	73094	BA4034/03		07/02/2019		
#REF!	QAA	Craigavon Hospital	01	Fanlight Panel	Insulating Board	Amosite/Chrysotile	Enclosed Spray or Lagoin/Sealed AIB	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Low Risk	6	15/09/2023	Identified	Low Risk	73096	BA4034/04	9302.2	15/09/2022	WHS	
#REF!	QAA	Craigavon Hospital	01	Fanlight Panel	Insulating Board	Amosite/Chrysotile	Enclosed Spray or	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Low Risk	6	15/09/2023	Strongly Presumed Similar to	Low Risk	73098	BA4034/04	9302.2	15/09/2022	WHS	
#REF!	QAA	Craigavon Hospital	01	Fanlight Panel	Insulating Board	Amosite/Chrysotile	Enclosed Spray or	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Low Risk	6	29/09/2023	Strongly Presumed Similar to	Low Risk	73100	BA4034/04	9302.2	29/09/2022	WHS	
#REF!	QAA	Craigavon Hospital	01	Fanlight Panel	Insulating Board	Amosite/Chrysotile	Enclosed Spray or	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Low Risk	6	15/09/2023	Strongly Presumed Similar to	Low Risk	73102	BA4034/04	9302.2	15/09/2022	WHS	
#REF!	QAA	Craigavon Hospital	01	Fanlight Panel	Insulating Board	Amosite/Chrysotile	Enclosed Spray or	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Low Risk	6	29/09/2023	Strongly Presumed Similar to	Low Risk	73103	BA4034/04	9302.2	29/09/2022	WHS	
#REF!	QAA	Craigavon Hospital	01	Fanlight Panel	Insulating Board	Amosite/Chrysotile	Enclosed Spray or	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Low Risk	6	15/09/2023	Strongly Presumed Similar to	Low Risk	73105	BA4034/04	9302.2	15/09/2022	WHS	
#REF!	QAA	Craigavon Hospital	01	Fanlight Panel	Insulating Board	Amosite/Chrysotile	Enclosed Spray or	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Low Risk	6	15/09/2023	Strongly Presumed Similar to	Low Risk	73106	BA4034/04	9302.2	15/09/2022	WHS	
#REF!	QAA	Craigavon Hospital	01	Fanlight Panel	Insulating Board	Amosite/Chrysotile	Enclosed Spray or	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Low Risk	6	15/09/2023	Strongly Presumed Similar to	Low Risk	73108	BA4034/04	9302.2	15/09/2022	WHS	
#REF!	QAA	Craigavon Hospital	01	Fanlight Panel	Insulating Board	Amosite/Chrysotile	Enclosed Spray or	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Low Risk	6	04/01/2025	Strongly Presumed Similar to	Low Risk	73109	BA4034/04	9302.2	29/09/2022	WHS	
#REF!	QAA	Craigavon Hospital	01	Fanlight Panel	Insulating Board	Amosite/Chrysotile	Enclosed Spray or	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Low Risk	6	29/09/2023	Strongly Presumed Similar to	Low Risk	73110	BA4034/04	9302.2	29/09/2022	WHS	
#REF!	QAA	Craigavon Hospital	01	Fanlight Panel	Insulating Board	Amosite/Chrysotile	Enclosed Spray or	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Low Risk	6	04/01/2025	Strongly Presumed Similar to	Low Risk	73111	BA4034/04	9302.2	07/02/2019	WHS	
#REF!	QAA	Craigavon Hospital	01	Fanlight Panel	Insulating Board	Amosite/Chrysotile	Enclosed Spray or	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Low Risk	6	29/09/2023	Strongly Presumed Similar to	Low Risk	73112	BA4034/04	9302.2	29/09/2022	WHS	
#REF!	QAA	Craigavon Hospital	01	Fanlight Panel	Insulating Board	Amosite/Chrysotile	Enclosed Spray or	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Low Risk	6	15/09/2023	Strongly Presumed Similar to	Low Risk	73113	BA4034/04	9302.2	15/09/2022	WHS	
#REF!	QAA	Craigavon Hospital	01	Fanlight Panel	Insulating Board	Amosite/Chrysotile	Enclosed Spray or	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Low Risk	6	15/09/2023	Strongly Presumed Similar to	Low Risk	73114	BA4034/04	9302.2	15/09/2022	WHS	
#REF!	QAA	Craigavon Hospital	01	Fanlight Panel	Insulating Board	Amosite/Chrysotile	Enclosed Spray or	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Low Risk	6	15/09/2023	Strongly Presumed Similar to	Low Risk	73115	BA4034/04	9302.2	15/09/2022	WHS	
#REF!	QAA	Craigavon Hospital	01	Fanlight Panel	Insulating Board	Amosite/Chrysotile	Enclosed Spray or	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Low Risk	6	15/09/2023	Strongly Presumed Similar to	Low Risk	73116	BA4034/04	9302.2	15/09/2022	WHS	
#REF!	QAA	Craigavon Hospital	01	Fanlight Panel	Insulating Board	Amosite/Chrysotile	Enclosed Spray or	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Low Risk	6	29/09/2023	Strongly Presumed Similar to	Low Risk	73117	BA4034/04	9302.2	29/09/2022	WHS	
#REF!	QAA	Craigavon Hospital	01	Fanlight Panel	Insulating Board	Amosite/Chrysotile	Enclosed Spray or	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Low Risk	6	15/09/2023	Strongly Presumed Similar to	Low Risk	73118	BA4034/04	9302.2	15/09/2022	WHS	
#REF!	QAA	Craigavon Hospital	01	Fanlight Panel	Insulating Board	Amosite/Chrysotile	Enclosed Spray or	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Low Risk	6	15/09/2023	Strongly Presumed Similar to	Low Risk	73119	BA4034/04	9302.2	15/09/2022	WHS	
#REF!	QAA	Craigavon Hospital	01	Fanlight Panel	Insulating Board	Amosite/Chrysotile	Enclosed Spray or	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Low Risk	6	16/09/2023	Strongly Presumed Similar to	Low Risk	73120	BA4034/04	9302.2	16/09/2022	WHS	
#REF!	QAA	Craigavon Hospital	01	Fanlight Panel	Insulating Board	Amosite/Chrysotile	Enclosed Spray or	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Low Risk	6	16/09/2023	Strongly Presumed Similar to	Low Risk	73122	BA4034/04	9302.2	16/09/2022	WHS	
#REF!	QAA	Craigavon Hospital	01	Fanlight Panel	Insulating Board	Amosite/Chrysotile	Enclosed Spray or	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Low Risk	6	16/09/2023	Strongly Presumed Similar to	Low Risk	73123	BA4034/04	9302.2	16/09/2022	WHS	
#REF!	QAA	Craigavon Hospital	01	Fanlight Panel	Insulating Board	Amosite/Chrysotile	Enclosed Spray or	Low	Manage & Affix ID Labels	Re-inspection	HSG227	Unchecked	Low Risk	6	16/09/2023	Strongly Presumed Similar to	Low Risk	73124	BA4034/04	9302.2	16/09/2022	WHS	
#REF!	QAA	Craigavon Hospital	01	Fanlight Panel	Insulating Board	Amosite/Chrysotile	Enclosed Spray or	Low	Manage & Affix ID Labels	Re-inspection	HSG227	Unchecked	Low Risk	6	16/09/2023	Strongly Presumed Similar to	Low Risk	73125	BA4034/04	9302.2	16/09/2022	WHS	
#REF!	QAA	Craigavon Hospital	01	Fanlight Panel	Insulating Board	Amosite/Chrysotile	Enclosed Spray or	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Low Risk	6	16/09/2023	Strongly Presumed Similar to	Low Risk	73126	BA4034/04	9302.2	16/09/2022	WHS	
#REF!	QAA	Craigavon Hospital	01	Fanlight Panel	Insulating Board	Amosite/Chrysotile	Enclosed Spray or	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Low Risk	6	16/09/2023	Strongly Presumed Similar to	Low Risk	73127	BA4034/04	9302.2	16/09/2022	WHS	
#REF!	QAA	Craigavon Hospital	01	Fanlight Panel	Insulating Board	Amosite/Chrysotile	Enclosed Spray or	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Low Risk	6	16/09/2023	Strongly Presumed Similar to	Low Risk	73128	BA4034/04	9302.2	16/09/2022	WHS	
#REF!	QAA	Craigavon Hospital	01	Fanlight Panel	Insulating Board	Amosite/Chrysotile	Enclosed Spray or	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Low Risk	6	16/09/2023	Strongly Presumed Similar to	Low Risk	73129	BA4034/04	9302.2	16/09/2022	WHS	
#REF!	QAA	Craigavon Hospital	01	Fanlight Panel	Insulating Board	Amosite/Chrysotile	Enclosed Spray or	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Low Risk	6	16/09/2023	Strongly Presumed Similar to	Low Risk	73131	BA4034/04	9302.2	16/09/2022	WHS	
#REF!	QAA	Craigavon Hospital	01	Fanlight Panel	Insulating Board	Amosite/Chrysotile	Enclosed Spray or	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Low Risk	6	16/09/2022	Strongly Presumed Similar to	Low Risk	73132	BA4034/04	9302.2	16/09/2022	WHS	
#REF!	QAA	Craigavon Hospital	01	Fanlight Panel	Insulating Board	Amosite/Chrysotile	Enclosed Spray or	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Low Risk	6	16/09/2023	Strongly Presumed Similar to	Low Risk	73133	BA4034/04	9302.2	16/09/2022	WHS	
#REF!	QAA	Craigavon Hospital	01	Fanlight Panel	Insulating Board	Amosite/Chrysotile	Enclosed Spray or	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Low Risk	6	16/09/2023	Strongly Presumed Similar to	Low Risk	73134	BA4034/04	9302.2	16/09/2022	WHS	
#REF!	QAA	Craigavon Hospital	01	Fanlight Panel	Insulating Board	Amosite/Chrysotile	Enclosed Spray or	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Low Risk	6	16/09/2023	Strongly Presumed Similar to	Low Risk	73135	BA4034/04	9302.2	16/09/2022	WHS	
#REF!	QAA	Craigavon Hospital	01	Fanlight Panel	Insulating Board	Amosite/Chrysotile	Enclosed Spray or	Low	Manage & Affix ID Labels	Re-inspection	HSG227	Unchecked	Low Risk	6	16/09/2023	Strongly Presumed Similar to	Low Risk	73137	BA4034/04	9302.2	16/09/2022	WHS	
#REF!	QAA	Craigavon Hospital	01	Fanlight Panel	Insulating Board	Amosite/Chrysotile	Enclosed Spray or	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Low Risk	6	16/09/2023	Strongly Presumed Similar to	Low Risk	73139	BA4034/04	9302.2	16/09/2022	WHS	
#REF!	QAA	Craigavon Hospital	01	Fanlight Panel	Insulating Board	Amosite/Chrysotile	Enclosed Spray or	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Low Risk	6	11/10/2023	Strongly Presumed Similar to	Low Risk	73140	BA4034/04	9302.2	11/10/2022	WHS	
#REF!	QAA	Craigavon Hospital	01	Fanlight Panel	Insulating Board	Amosite/Chrysotile	Enclosed Spray or	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Low Risk	6	11/10/2023	Strongly Presumed Similar to	Low Risk	73142	BA4034/04	9302.2	11/10/2022	WHS	
#REF!	QAA	Craigavon Hospital	01	Fanlight Panel	Insulating Board	Amosite/Chrysotile	Enclosed Spray or	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Low Risk	6	29/09/2023	Strongly Presumed Similar to	Low Risk	73143	BA4034/04	9302.2	29/09/2022	WHS	
#REF!	QAA	Craigavon Hospital	01	Fanlight Panel	Insulating Board	Amosite/Chrysotile	Enclosed Spray or	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Low Risk	6	29/09/2023	Strongly Presumed Similar to	Low Risk	73144	BA4034/04	9302.2	29/09/2022	WHS	
#REF!	QAA	Craigavon Hospital	01	Fanlight Panel	Insulating Board	Amosite/Chrysotile	Enclosed Spray or	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Low Risk	6	29/09/2023	Strongly Presumed Similar to	Low Risk	73146	BA4034/04	9302.2	29/09/2022	WHS	
#REF!	QAA	Craigavon Hospital	01	Fanlight Panel	Insulating Board	Amosite/Chrysotile	Enclosed Spray or	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Low Risk	6	29/09/2023	Strongly Presumed Similar to	Low Risk	73148	BA4034/04	9302.2	29/09/2022	WHS	
#REF!	QAA	Craigavon Hospital	01	Fanlight Panel	Insulating Board	Amosite/Chrysotile	Enclosed Spray or	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Low Risk	6	09/09/2023	Strongly Presumed Similar to	Low Risk	73150	BA4034/04	9302.2	09/09/2022	WHS	
#REF!	QAA	Craigavon Hospital	01	Fanlight Panel	Insulating Board	Amosite/Chrysotile	Enclosed Spray or	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Low Risk	6	29/09/2023	Strongly Presumed Similar to	Low Risk	73151	BA4034/04	9302.2	29/09/2022	WHS	
#REF!	QAA	Craigavon Hospital	01	Fanlight Panel	Insulating Board	Amosite/Chrysotile	Enclosed Spray or	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Low Risk	6	29/09/2023	Strongly Presumed Similar to	Low Risk	73154	BA4034/04	9302.2	29/09/2022	WHS	
#REF!	QAA	Craigavon Hospital	01	Fanlight Panel	Insulating Board	Amosite/Chrysotile	Enclosed Spray or	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Low Risk	6	29/09/2023	Strongly Presumed Similar to	Low Risk	73155	BA4034/04	9302.2	29/09/2022	WHS	
#REF!	QAA	Craigavon Hospital	01	Fanlight Panel	Insulating Board	Amosite/Chrysotile	Enclosed Spray or	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Low Risk	6	29/09/2023	Strongly Presumed Similar to	Low Risk	73156	BA4034/04	9302.2	29/09/2022	WHS	
#REF!	QAA	Craigavon Hospital	01	Fanlight Panel	Insulating Board	Amosite/Chrysotile	Enclosed Spray or	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Low Risk	6	29/09/2023	Strongly Presumed Similar to	Low Risk	73157	BA4034/04	9302.2	29/09/2022	WHS	
#REF!	QAA	Craigavon Hospital	01	Fanlight Panel	Insulating Board	Amosite/Chrysotile	Enclosed Spray or	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Low Risk	6	21/09/2023	Strongly Presumed Similar to	Low Risk	73159	BA4034/04	9302.2	21/09/2022	WHS	
#REF!	QAA	Craigavon Hospital	01	Fanlight Panel	Insulating Board	Amosite/Chrysotile	Enclosed Spray or	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Low Risk	6	21/09/2023	Strongly Presumed Similar to	Low Risk	73161	BA4034/04	9302.2	21/09/2022	WHS	
#REF!	QAA	Craigavon Hospital	01	Fanlight Panel	Insulating Board	Amosite/Chrysotile	Enclosed Spray or	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Low Risk	6	21/09/2023	Strongly Presumed Similar to	Low Risk	73162	BA4034/04	9302.2	21/09/2022	WHS	
#REF!	QAA	Craigavon Hospital	01	Fanlight Panel	Insulating Board	Amosite/Chrysotile	Enclosed Spray or	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Low Risk	6	21/09/2023	Strongly Presumed Similar to	Low Risk	73164	BA4034/04	9302.2	21/09/2022	WHS	
#REF!	QAA	Craigavon Hospital	01	Fanlight Panel	Insulating Board	Amosite/Chrysotile	Enclosed Spray or	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Low Risk	6	21/09/2023	Strongly Presumed Similar to	Low Risk	73165	BA4034/04	9302.2	21/09/2022	WHS	
#REF!	QAA	Craigavon Hospital	01	Fanlight Panel	Insulating Board	Amosite/Chrysotile	Enclosed Spray or	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Low Risk	6	21/09/2023	Strongly Presumed Similar to	Low Risk	73166	BA4034/04	9302.2	21/09/2022	WHS	
#REF!	QAA	Craigavon Hospital	01	Fanlight Panel	Insulating Board	Amosite/Chrysotile	Enclosed Spray or	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Low Risk	6	11/10/2023	Strongly Presumed Similar to	Low Risk	73168	BA4034/04	-	11/10/2022	WHS	
#REF!	QAA	Craigavon Hospital	01	Fanlight Panel	Insulating Board	NO ASBESTOS	Enclosed Spray or Lagoin/Sealed AIB	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	07/02/2020	Strongly Presumed Similar to	Asbestos Removed	73169	BA4034/04	-	07/02/2019		
#REF!	QAA	Craigavon Hospital	01	Fanlight Panel	Insulating Board	Amosite/Chrysotile	Enclosed Spray or	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Low Risk	6	21/09/2023	Strongly Presumed Similar to	Low Risk	73170	BA4034/04	9302.2	21/09/2022	WHS	
#REF!	QAA	Craigavon Hospital	01	Fanlight Panel	Insulating Board	Amosite/Chrysotile	Enclosed Spray or	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Low Risk	6	21/09/2023	Strongly Presumed Similar to	Low Risk	73171	BA4034/04	9302.2	21/09/2022	WHS	
#REF!	QAA	Craigavon Hospital	01	Fanlight Panel	Insulating Board	Amosite/Chrysotile	Enclosed Spray or	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Low Risk	6	21/09/2023	Strongly Presumed Similar to	Low Risk	73173	BA4034/04	9302.2	21/09/2022	WHS	
#REF!	QAA	Craigavon Hospital	01	Fanlight Panel	Insulating Board	Amosite/Chrysotile	Enclosed Spray or	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Low Risk	6	21/09/2023	Strongly Presumed Similar to	Low Risk	73175	BA4034/04	9302.2	21/09/2022	WHS	
#REF!	QAA	Craigavon Hospital	01	Fanlight Panel	Insulating Board	Amosite/Chrysotile	Enclosed Spray or	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Low Risk	6	21/09/2022	Strongly Presumed Similar to	Low Risk	73176	BA4034/04	9302.2	21/09/2022	WHS	
#REF!	QAA	Craigavon Hospital	01	Fanlight Panel	Insulating Board	Amosite/Chrysotile	Enclosed Spray or	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Low Risk	6	21/09/2023	Strongly Presumed Similar to	Low Risk	73179	BA4034/04	9302.2	21/09/2022	WHS	
#REF!	QAA	Craigavon Hospital	01	Fanlight Panel	Insulating Board	Amosite/Chrysotile	Enclosed Spray or	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Low Risk	6	21/09/2023	Strongly Presumed Similar to	Low Risk	73180	BA4034/04	9302.2	21/09/2022	WHS	
#REF!	QAA	Craigavon Hospital	01	Fanlight Panel	Insulating Board	Amosite/Chrysotile	Enclosed Spray or	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Low Risk	6	21/09/2023	Strongly Presumed Similar to	Low Risk	73182	BA4034/04	9302.2	21/09/2022	WHS	
#REF!	QAA	Craigavon Hospital	01	Fanlight Panel	Insulating Board	Amosite/Chrysotile	Enclosed Spray or	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Low Risk	6	21/09/2023	Strongly Presumed Similar to	Low Risk	73184	BA4034/04	9302.2	21/09/2022	WHS	
#REF!	QAA	Craigavon Hospital	01	Fanlight Panel	Insulating Board	Amosite/Chrysotile	Enclosed Spray or	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Low Risk	6	21/09/2023	Strongly Presumed Similar to	Low Risk	73185	BA4034/04	9302.2	21/09/2022	WHS	
#REF!	QAA	Craigavon Hospital	01	Fanlight Panel	Insulating Board	Amosite/Chrysotile	Enclosed Spray or	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Low Risk	6	21/09/2023	Strongly Presumed Similar to	Low Risk	73186	BA4034/04	9302.2	21/09/2022	WHS	
#REF!	QAA	Craigavon Hospital	01	Fanlight Panel	Insulating Board	Amosite/Chrysotile	Enclosed Spray or	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Low Risk	6	11/10/2023	Strongly Presumed Similar to	Low Risk	73188	BA4034/04	9302.2	11/10/2022	WHS	
#REF!	QAA	Craigavon Hospital	01	Fanlight Panel	Insulating Board	Amosite/Chrysotile	Enclosed Spray or	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Low Risk	6	21/09/2023	Strongly Presumed Similar to	Low Risk	73189	BA4034/04	9302.2	21/09/2022	WHS	
#REF!	QAA	Craigavon Hospital	01	Fanlight Panel	Insulating Board	Amosite/Chrysotile	Enclosed Spray or	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Low Risk	6	21/09/2023	Strongly Presumed Similar to	Low Risk	73191	BA4034/04	9302.2	21/09/2022	WHS	
#REF!	QAA	Craigavon Hospital	01	Fanlight Panel	Insulating Board	Amosite/Chrysotile	Enclosed Spray or	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Low Risk	6	21/09/2023	Strongly Presumed Similar to	Low Risk	73192	BA4034/04	9302.2	21/09/2022	WHS	
#REF!	QAA	Craigavon Hospital	01	Fanlight Panel	Insulating Board	Amosite/Chrysotile	Enclosed Spray or	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Low Risk	6	21/09/2023	Strongly Presumed Similar to	Low Risk	73194	BA4034/04	9302.2	21/09/2022	WHS	
#REF!	QAA	Craigavon Hospital	01	Fanlight Panel	Insulating Board	Amosite/Chrysotile	Enclosed Spray or	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Low Risk	6	21/09/2023	Strongly Presumed Similar to	Low Risk	73195	BA4034/04	9302.2	21/09/2022	WHS	
#REF!	QAA	Craigavon Hospital	01	Fanlight Panel	Insulating Board	Amosite/Chrysotile	Enclosed Spray or	Low	Manage & Affix ID Labels	Re-inspection	HSG227	Unchecked	Low Risk	6	21/09/2023	Strongly Presumed Similar to	Low Risk	73197	BA4034/04	9302.2	21/09/2022	WHS	
#REF!	QAA	Craigavon Hospital	01	Fanlight Panel	Insulating Board	Amosite/Chrysotile	Enclosed Spray or	Low	Manage & Affix ID Labels	Re-inspection	HSG227	Unchecked	Low Risk	6	21/09/2023	Strongly Presumed Similar to	Low Risk	73198	BA4034/04	9302.2	21/09/2022	WHS	
#REF!	QAA	Craigavon Hospital	01	Fanlight Panel	Insulating Board	Amosite/Chrysotile	Enclosed Spray or	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Low Risk	6	21/09/2023	Strongly Presumed Similar to	Low Risk	73199	BA4034/04	9302.2	21/09/2022	WHS	
#REF!	QAA	Craigavon Hospital	01	Fanlight Panel	Insulating Board	Amosite/Chrysotile	Enclosed Spray or	Low	Manage & Affix ID Labels	Re-inspection	HSG227	Unchecked	Low Risk	6	21/09/2023	Strongly Presumed Similar to	Low Risk	73200	BA4034/04	9302.2	21/09/2022	WHS	
#REF!	QAA	Craigavon Hospital	01	Fanlight Panel	Insulating Board	Amosite/Chrysotile	Enclosed Spray or	Low	Manage & Affix ID Labels	Re-inspection	HSG227	Unchecked	Low Risk	6	21/09/2023	Strongly Presumed Similar to	Low Risk	73202	BA4034/04	9302.2	21/09/2022	WHS	
#REF!	QAA	Craigavon Hospital	01	Fanlight Panel	Insulating Board	Amosite/Chrysotile	Enclosed Spray or	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Low Risk	6	21/09/2023	Strongly Presumed Similar to	Low Risk	73203	BA4034/04	9302.2	21/09/2022	WHS	
#REF!	QAA	Craigavon Hospital	01	Fanlight Panel	Insulating Board	Amosite/Chrysotile	Enclosed Spray or	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Low Risk	6	21/09/2023	Strongly Presumed Similar to	Low Risk	73204	BA4034/04	9302.2	21/09/2022	WHS	
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	73206	BA4034/05		07/02/2019		
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	73208	BA4034/05		07/02/2019		
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	73209	BA4034/05		07/02/2019		
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	73210	BA4034/05		07/02/2019		
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	73211	BA4034/05		07/02/2019		
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	73212	BA4034/05		07/02/2019		
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	73214	BA4034/05		07/02/2019		
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	73215	BA4034/05		07/02/2019		
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	73216	BA4034/05		07/02/2019		
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Composite Material	NO

#REF!	QAA	Craigavon Hospital	01	Fire Break Panel		Insulating Board	Amosite/Chrysotile	Encapsulated Spray or Lagoon/Unsealed AIB	Areas of damage or deterioration	Restrict access and conduct an environmental clean	Re-inspection	HSG227	Unchecked	Medium Risk	8	16/09/2023	Strongly Presumed Similar to	Medium Risk	73239	BA4034/08	9302.22	16/09/2022	WHS		
#REF!	QAA	Craigavon Hospital	01	Fire Break Panel		Insulating Board	Amosite/Chrysotile	Encapsulated Spray or Lagoon/Unsealed AIB	Areas of damage or deterioration	Restrict access and conduct an environmental clean	Re-inspection	HSG227	Unchecked	Medium Risk	8	29/09/2023	Strongly Presumed Similar to	Medium Risk	73240	BA4034/08	9724/17	29/09/2022	WH Stephens		
#REF!	QAA	Craigavon Hospital	01	Fire Break Panel		Insulating Board	Amosite/Chrysotile	Encapsulated Spray or Lagoon/Unsealed AIB	Areas of damage or deterioration	Restrict access and conduct an environmental clean	Re-inspection	HSG227	Unchecked	Medium Risk	8	16/09/2023	Strongly Presumed Similar to	Medium Risk	73241	BA4034/08	9724/17	16/09/2022	WH Stephens		
#REF!	QAA	Craigavon Hospital	01	Fire Break Panel		Insulating Board	Amosite/Chrysotile	Encapsulated Spray or Lagoon/Unsealed AIB	Areas of damage or deterioration	Restrict access and operate a safe system of work	Re-inspection	HSG227	Unchecked	Medium Risk	8	11/10/2023	Strongly Presumed Similar to	Medium Risk	73242	BA4034/08	9724/17	11/10/2022	WH Stephens		
#REF!	QAA	Craigavon Hospital	01	Fire Break Panel		Insulating Board	Amosite/Chrysotile	Encapsulated Spray or Lagoon/Unsealed AIB	Areas of damage or deterioration	Restrict access and operate a safe system of work	Re-inspection	HSG227	Unchecked	Medium Risk	8	29/09/2023	Strongly Presumed Similar to	Medium Risk	73243	BA4034/08	9302.22	29/09/2022	WHS		
#REF!	QAA	Craigavon Hospital	01	Fire Break Panel		Insulating Board	Amosite/Chrysotile	Encapsulated Spray or Lagoon/Unsealed AIB	Areas of damage or deterioration	Restrict access and conduct an environmental clean	Re-inspection	HSG227	Unchecked	Medium Risk	8	29/09/2023	Strongly Presumed Similar to	Medium Risk	73244	BA4034/08	9302.22	29/09/2022	WHS		
#REF!	QAA	Craigavon Hospital	01	Fire Break Panel		Insulating Board	Amosite/Chrysotile	Encapsulated Spray or Lagoon/Unsealed AIB	Areas of damage or deterioration	Restrict access and conduct an environmental clean	Re-inspection	HSG227	Unchecked	Medium Risk	8	21/09/2023	Strongly Presumed Similar to	Medium Risk	73246	BA4034/08	9302.22	21/09/2022	WHS		
#REF!	QAA	Craigavon Hospital	01	Fire Break Panel		Insulating Board	Amosite/Chrysotile	Encapsulated Spray or Lagoon/Unsealed AIB	Areas of damage or deterioration	Restrict access and conduct an environmental clean	Re-inspection	HSG227	Unchecked	Medium Risk	8	21/09/2023	Strongly Presumed Similar to	Medium Risk	73247	BA4034/08	9302.22	21/09/2022	WHS		
#REF!	QAA	Craigavon Hospital	01	Fire Break Panel		Insulating Board	NO ASBESTOS	Encapsulated Spray or Lagoon/Unsealed AIB	Areas of damage or deterioration	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	13/04/2018	Strongly Presumed Similar to	Asbestos Removed	73248	BA4034/08	9724/17	13/04/2017	WH Stephens		
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	73249	BA4034/09	9724/17	13/04/2017	WH Stephens		
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	73250	BA4034/09	9724/17	13/04/2017	WH Stephens		
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	73251	BA4034/09	9724/17	13/04/2017	WH Stephens		
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	73252	BA4034/09	9724/17	13/04/2017	WH Stephens		
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	73253	BA4034/09	9724/17	13/04/2017	WH Stephens		
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	73254	BA4034/09	9724/17	13/04/2017	WH Stephens		
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	73255	BA4034/09	9724/17	13/04/2017	WH Stephens		
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	73256	BA4034/09	9724/17	13/04/2017	WH Stephens		
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	73257	BA4034/09	9724/17	13/04/2017	WH Stephens		
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	73258	BA4034/09	9724/17	13/04/2017	WH Stephens		
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	73259	BA4034/09	9724/17	13/04/2017	WH Stephens		
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	73260	BA4034/09	9724/17	13/04/2017	WH Stephens		
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	73261	BA4034/09	9724/17	13/04/2017	WH Stephens		
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	73262	BA4034/09	9724/17	13/04/2017	WH Stephens		
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	73263	BA4034/09	9724/17	13/04/2017	WH Stephens		
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	73264	BA4034/09	9724/17	13/04/2017	WH Stephens		
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	73265	BA4034/09	9724/17	13/04/2017	WH Stephens		
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	73267	BA4034/09	9724/17	13/04/2017	WH Stephens		
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	73268	BA4034/09	9724/17	13/04/2017	WH Stephens		
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	73269	BA4034/09	9724/17	13/04/2017	WH Stephens		
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	73270	BA4034/09	9724/17	13/04/2017	WH Stephens		
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	73271	BA4034/10	9724/17	13/04/2017	WH Stephens		
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	73272	BA4034/10	9724/17	13/04/2017	WH Stephens		
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	73273	BA4034/10	9724/17	13/04/2017	WH Stephens		
#REF!	QAA	Craigavon Hospital	01	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Low	Manage & Affix ID Labels	Review – No Change	HSG227	Unchecked	Very Low Risk	3	13/04/2018	Identified	Very Low Risk	73281	BA4034/11	9724/17	13/04/2017	WH Stephens		
#REF!	QAA	Craigavon Hospital	01	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Low	Repair and affix labels	Re-inspection	HSG227	Unchecked	Very Low Risk	3	15/09/2023	Stronolv Presumed Similar to	Very Low Risk	73282	BA4034/11	9302.2	15/09/2022	WHS		
#REF!	QAA	Craigavon Hospital	01	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Low	Asmt- Caution when Maintaining	Re-inspection	HSG227	Unchecked	Very Low Risk	3	16/09/2023	Stronolv Presumed Similar to	Very Low Risk	73283	BA4034/11	9302.2	16/09/2022	WHS		
#REF!	QAA	Craigavon Hospital	01	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Low	Repair, Encapsulate & Manage	Re-inspection	HSG227	Unchecked	Very Low Risk	3	29/09/2023	Stronolv Presumed Similar to	Very Low Risk	73284	BA4034/11	9302.2	29/09/2022	WHS		
#REF!	QAA	Craigavon Hospital	01	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Low	Repair. Encapsulate & Manage	Re-inspection	HSG227	Unchecked	Very Low Risk	3	29/09/2023	Stronolv Presumed Similar to	Very Low Risk	73285	BA4034/11	9302.2	29/09/2022	WHS		
#REF!	QAA	Craigavon Hospital	01	Floor Tile and Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Medium	Repair. Encapsulate & Manage	Re-inspection	HSG227	Unchecked	Very Low Risk	4	21/09/2023	Stronolv Presumed Similar to	Very Low Risk	73286	BA4034/11	9302.2	21/09/2022	WHS		
#REF!	QAA	Craigavon Hospital	01	Ceiling Tiles		Insulating Board	NO ASBESTOS	Enclosed Spray or Lagoon/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	73287	BA4034/12	9724/17	13/04/2017	WH Stephens		
#REF!	QAA	Craigavon Hospital	01	Ceiling Tiles		Insulating Board	NO ASBESTOS	Enclosed Spray or Lagoon/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	73288	BA4034/12	9724/17	13/04/2017	WH Stephens		
#REF!	QAA	Craigavon Hospital	01	Ceiling Tiles		Insulating Board	NO ASBESTOS	Enclosed Spray or Lagoon/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	73289	BA4034/12	9724/17	13/04/2017	WH Stephens		
#REF!	QAA	Craigavon Hospital	01	Ceiling Tiles		Insulating Board	NO ASBESTOS	Enclosed Spray or Lagoon/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	73290	BA4034/12	9724/17	13/04/2017	WH Stephens		
#REF!	QAA	Craigavon Hospital	01	Ceiling Tiles		Insulating Board	NO ASBESTOS	Enclosed Spray or Lagoon/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	73291	BA4034/12	9724/17	13/04/2017	WH Stephens		
#REF!	QAA	Craigavon Hospital	01	Ceiling Tiles		Insulating Board	NO ASBESTOS	Enclosed Spray or Lagoon/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	73292	BA4034/12	9724/17	13/04/2017	WH Stephens		
#REF!	QAA	Craigavon Hospital	01	Ceiling Tiles		Insulating Board	NO ASBESTOS	Enclosed Spray or Lagoon/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	73293	BA4034/12	9724/17	13/04/2017	WH Stephens		
#REF!	QAA	Craigavon Hospital	01	Ceiling Tiles		Insulating Board	NO ASBESTOS	Enclosed Spray or Lagoon/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	73294	BA4034/12	9724/17	13/04/2017	WH Stephens		
#REF!	QAA	Craigavon Hospital	01	Ceiling Tiles		Insulating Board	NO ASBESTOS	Enclosed Spray or Lagoon/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	73295	BA4034/12	9724/17	13/04/2017	WH Stephens		
#REF!	QAA	Craigavon Hospital	01	Ceiling Tiles		Insulating Board	NO ASBESTOS	Enclosed Spray or Lagoon/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	73296	BA4034/12	9724/17	13/04/2017	WH Stephens		
#REF!	QAA	Craigavon Hospital	01	Ceiling Tiles		Insulating Board	NO ASBESTOS	Enclosed Spray or Lagoon/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	73297	BA4034/12	9724/17	13/04/2017	WH Stephens		
#REF!	QAA	Craigavon Hospital	01	Ceiling Tiles		Insulating Board	NO ASBESTOS	Enclosed Spray or Lagoon/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	73298	BA4034/12	9724/17	13/04/2017	WH Stephens		
#REF!	QAA	Craigavon Hospital	01	Ceiling Tiles		Insulating Board	NO ASBESTOS	Enclosed Spray or Lagoon/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	73299	BA4034/12	9724/17	13/04/2017	WH Stephens		
#REF!	QAA	Craigavon Hospital	01	Bitumen Paints		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	73300	BA4034/13	9724/17	13/04/2017	WH Stephens		
#REF!	QAA	Craigavon Hospital	01	Bitumen Paints		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	73301	BA4034/13	9724/17	13/04/2017	WH Stephens		
#REF!	QAA	Craigavon Hospital	01	Bitumen Paints		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	73302	BA4034/13	9724/17	13/04/2017	WH Stephens		
#REF!	QAA	Craigavon Hospital	01	Bitumen Paints		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	73303	BA4034/13	9724/17	13/04/2017	WH Stephens		
#REF!	QAA	Craigavon Hospital	01	Ceiling Board		Insulating Board	NO ASBESTOS	Encapsulated Spray or Lagoon/Unsealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	73304	BA4034/14	9724/17	13/04/2017	WH Stephens		
#REF!	QAA	Craigavon Hospital	01	Ceiling Board		Insulating Board	NO ASBESTOS	Encapsulated Spray or Lagoon/Unsealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	73305	BA4034/14	9724/17	13/04/2017	WH Stephens		
#REF!	QAA	Craigavon Hospital	01	Mortar Residue	Roofspace	Cement Products	NO ASBESTOS	Enclosed Spray or Lagoon/Sealed AIB	Medium	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	73306	BA4034/15	9724/17	13/04/2017	WH Stephens		
#REF!	QAA	Craigavon Hospital	01	Mortar Residue	Roofspace	Cement Products	NO ASBESTOS	Enclosed Spray or Lagoon/Sealed AIB	Medium	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	73307	BA4034/15	9724/17	13/04/2017	WH Stephens		
#REF!	QAA	Craigavon Hospital	01	Mortar Residue	Roofspace	Cement Products	NO ASBESTOS	Enclosed Spray or Lagoon/Sealed AIB	Medium	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	73308	BA4034/15	9724/17	13/04/2017	WH Stephens		
#REF!	QAA	Craigavon Hospital	01	Mortar Residue		Cement Products	NO ASBESTOS	Enclosed Spray or Lagoon/Sealed AIB	Medium	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	73310	BA4034/15	9724/17	13/04/2017	WH Stephens		
#REF!	QAA	Craigavon Hospital	01	Mortar Residue		Cement Products	NO ASBESTOS	Enclosed Spray or Lagoon/Sealed AIB	Medium	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	73311	BA4034/15	9724/17	13/04/2017	WH Stephens		
#REF!	QAA	Craigavon Hospital	01	Mortar Residue	Roof Void	Cement Products	NO ASBESTOS	Enclosed Spray or Lagoon/Sealed AIB	Medium	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	73312	BA4034/15	9724/17	13/04/2017	WH Stephens		
#REF!	QAA	Craigavon Hospital	01	Mortar Residue	Roof Void	Cement Products	NO ASBESTOS	Enclosed Spray or Lagoon/Sealed AIB	Medium	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	73313	BA4034/15	9724/17	13/04/2017	WH Stephens		
#REF!	QAA	Craigavon Hospital	01	Mortar Residue		Cement Products	NO ASBESTOS	Enclosed Spray or Lagoon/Sealed AIB	Medium	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	73314	BA4034/15	9724/17	13/04/2017	WH Stephens		
#REF!	QAA	Craigavon Hospital	01	Wall Panels	Roofspace	Insulating Board	NO ASBESTOS	Encapsulated Spray or Lagoon/Unsealed AIB	Medium	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	73316	BA4034/16	9724/17	13/04/2017	WH Stephens		
#REF!	QAA	Craigavon Hospital	01	Wall Panels	Roofspace	Insulating Board	NO ASBESTOS	Encapsulated Spray or Lagoon/Unsealed AIB	Medium	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	73317	BA4034/16	9724/17	13/04/2017	WH Stephens		
#REF!	QAA	Craigavon Hospital	01	Wall Panels	Roofspace	Insulating Board	NO ASBESTOS	Encapsulated Spray or Lagoon/Unsealed AIB	Medium	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	73318	BA4034/16	9724/17	13/04/2017	WH Stephens		
#REF!	QAA	Craigavon Hospital	01	Wall Panels		Insulating Board	NO ASBESTOS	Encapsulated Spray or Lagoon/Unsealed AIB	Medium	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	73319	BA4034/16	9724/17	13/04/2017	WH Stephens		
#REF!	QAA	Craigavon Hospital	01	Wall Panels	Roof Void	Insulating Board	NO ASBESTOS	Encapsulated Spray or Lagoon/Unsealed AIB	Medium	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	73320	BA4034/16	9724/17	13/04/2017	WH Stephens		
#REF!	QAA	Craigavon Hospital	01	Wall Panels	Roof Void	Insulating Board	NO ASBESTOS	Encapsulated Spray or Lagoon/Unsealed AIB	Medium	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	73321	BA4034/16	9724/17	13/04/2017	WH Stephens		
#REF!	QAA	Craigavon Hospital	01	Back Board		Insulating Board	NO ASBESTOS	Encapsulated Spray or Lagoon/Unsealed AIB	Medium	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	73322	BA4034/17	9724/17	13/04/2017	WH Stephens		
#REF!	QAA	Craigavon Hospital	01	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	73323	BA4034/18	9724/17	13/04/2017	WH Stephens		
#REF!	QAA	Craigavon Hospital	01	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	73324	BA4034/18	9724/17	13/04/2017	WH Stephens		
#REF!	QAA	Craigavon Hospital	01	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	73325	BA4034/18	9724/17	13/04/2017	WH Stephens		

#REF!	QAA	Craigavon Hospital	01	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	73326	BA4034/18	9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	73327	BA4034/18	9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	73328	BA4034/18	9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	73329	BA4034/18	9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	73330	BA4034/18	9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	73331	BA4034/18	9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	73332	BA4034/18	9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	73333	BA4034/18	9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	73334	BA4034/18	9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	73335	BA4034/18	9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	73336	BA4034/18	9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	73337	BA4034/18	9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	Wall Panels		Insulating Board	NO ASBESTOS	Enclosed Spray or Lagging/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	73338	BA4034/19	9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	73339	BA4034/20	9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	73340	BA4034/20	9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	73341	BA4034/20	9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	73342	BA4034/20	9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	73343	BA4034/20	9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	73344	BA4034/20	9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	73345	BA4034/20	9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	73346	BA4034/20	9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	73347	BA4034/20	9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	73348	BA4034/20	9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	73350	BA4034/21	9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Hose Reel Cupboard	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	73351	BA4034/21	9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Hose Reel Cupboard	Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	73352	BA4034/21	9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	Board		Insulating Board	NO ASBESTOS	Encapsulated Spray or Lagging/Unsealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	73354	BA4034/22	9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	Wall Panels		Insulating Board	NO ASBESTOS	Enclosed Spray or Lagging/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	73355	BA4034/23	9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	Ceiling Board		Insulating Board	NO ASBESTOS	Enclosed Spray or Lagging/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	73356	BA4034/24	9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	Ceiling Board	Cupboard	Insulating Board	NO ASBESTOS	Enclosed Spray or Lagging/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	73357	BA4034/24	9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	Debris	Roofspace	Insulating Board	NO ASBESTOS	Encapsulated Spray or Lagging/Unsealed AIB	High	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	73358	BA4034/25	9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	Wall Panels		Insulating Board	NO ASBESTOS	Encapsulated Spray or Lagging/Unsealed AIB	High	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	73359	BA4034/28	9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	Wall Panels	Switchgear Cupboard	Insulating Board	NO ASBESTOS	Encapsulated Spray or Lagging/Unsealed AIB	High	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	73360	BA4034/28	9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	Wall Panels		Insulating Board	Amosite/Chrysotile	Enclosed Spray or	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Low Risk	6	16/09/2023	Identified	Low Risk	73361	BA4034/27	9302.2	16/09/2022	WHS
#REF!	QAA	Craigavon Hospital	01	Wall Panels		Insulating Board	Amosite/Chrysotile	Enclosed Spray or	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Low Risk	6	21/09/2023	Strongly Presumed Similar to	Low Risk	73362	BA4034/27	9302.2	21/09/2022	WHS
#REF!	QAA	Craigavon Hospital	01	Pipe Brackets		Textiles & Paper	Chrysotile	Encapsulated Spray or Lagging/Unsealed AIB	Low	Apply Caution when Maintaining	Re-inspection	HSG227	Unchecked	Low Risk	6	21/09/2023	Identified	Low Risk	73363	BA4034/28	9302.2	21/09/2022	WHS
#REF!	QAA	Craigavon Hospital	01	General Debris		General Debris	NO ASBESTOS	Encapsulated Spray or Lagging/Unsealed AIB	High	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	73365	BA4034/29	9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	Wall Panels		Cement Products	Chrysotile	Enclosed Spray or	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	4	11/10/2023	Identified	Very Low Risk	73366	BA4034/30	9302.2	11/10/2022	WHS
#REF!	QAA	Craigavon Hospital	01	Wall Panels		Cement Products	Chrysotile	Enclosed Spray or	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	4	11/10/2023	Strongly Presumed Similar to	Very Low Risk	73367	BA4034/30	9302.2	11/10/2022	WHS
#REF!	QAA	Craigavon Hospital	01	Wall Panels		Cement Products	Chrysotile	Enclosed Spray or	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	4	11/10/2023	Strongly Presumed Similar to	Very Low Risk	73368	BA4034/30	9724/17	11/10/2022	WH Stephens
#REF!	QAA	Craigavon Hospital	01	Wall Panels		Cement Products	Chrysotile	Enclosed Spray or	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	4	21/09/2023	Strongly Presumed Similar to	Very Low Risk	73369	BA4034/30	9302.2	21/09/2022	WHS
#REF!	QAA	Craigavon Hospital	01	Wall Panels		Cement Products	Chrysotile	Enclosed Spray or Lagging/Sealed AIB	Low	Restrict access and operate a safe system of work	Re-inspection	HSG227	Unchecked	Very Low Risk	4	21/09/2023	Strongly Presumed Similar to	Very Low Risk	73370	BA4034/30	9302.2	21/09/2022	WHS
#REF!	QAA	Craigavon Hospital	01	Ceiling Board		Insulating Board	NO ASBESTOS	Enclosed Spray or Lagging/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	73371	BA4034/31	9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	Wall Panels		Insulating Board	NO ASBESTOS	Enclosed Spray or Lagging/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	73372	BA4034/32	9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	Pipe Brackets	Roof Void	Textiles & Paper	Chrysotile	Encapsulated Spray or Lagging/Unsealed AIB	Low	Apply Caution when Maintaining	Re-inspection	HSG227	Unchecked	Low Risk	6	21/09/2023	Identified	Low Risk	73373	BA4034/33	9302.2	21/09/2022	WHS
#REF!	QAA	Craigavon Hospital	01	Debris	Hose Reel Cupboard	Insulating Board	NO ASBESTOS	Encapsulated Spray or Lagging/Unsealed AIB	Areas of damage or deterioration	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	13/04/2018	Identified	Asbestos Removed	73374	BA4034/34	9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	Bitumen Paints		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	73375	BA4034/35	9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	Bitumen Paints		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	73376	BA4034/35	9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	Bitumen Paints		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	73377	BA4034/35	9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	Bitumen Paints		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	73378	BA4034/35	9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	Bitumen Paints		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	73379	BA4034/35	9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	Bitumen Paints		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	73380	BA4034/35	9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	Bitumen Paints		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	73381	BA4034/35	9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	Bitumen Paints		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	73382	BA4034/35	9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	Bitumen Paints		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	73383	BA4034/35	9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	Ceiling Tiles		Insulating Board	NO ASBESTOS	Enclosed Spray or Lagging/Sealed AIB	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	Asbestos Removed	73384	BA4034/36	9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	Bitumen Paints		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	73385	BA4034/37	9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	Bitumen Paints		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	73386	BA4034/37	9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	Rope Seal	Oven	Textiles & Paper	NO ASBESTOS	Encapsulated Spray or Lagging/Unsealed AIB	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Presumed	Asbestos Removed	73387		9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Medium	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	73388	BA4034/38	9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	Wall Panels		Insulating Board	NO ASBESTOS	Encapsulated Spray or Lagging/Unsealed AIB	High	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	73389	BA4034/39	9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	Floor Tiles		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	73390	BA4034/40	9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	Fanlight Panel		Insulating Board	NO ASBESTOS	Enclosed Spray or Lagging/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	73391	BA4034/41	9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	Fanlight Panel		Insulating Board	NO ASBESTOS	Enclosed Spray or Lagging/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	73392	BA4034/41	9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	Fanlight Panel		Insulating Board	NO ASBESTOS	Enclosed Spray or Lagging/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	73393	BA4034/41	9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	Fanlight Panel		Insulating Board	NO ASBESTOS	Enclosed Spray or Lagging/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	73394	BA4034/41	9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	Fanlight Panel		Insulating Board	NO ASBESTOS	Enclosed Spray or Lagging/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	73395	BA4034/41	9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	Fanlight Panel		Insulating Board	NO ASBESTOS	Enclosed Spray or Lagging/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	73396	BA4034/41	9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	73397	BA4034/42	9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	73398	BA4034/42	9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	73399	BA4034/42	9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	73400	BA4034/42	9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	73401	BA4034/42	9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	73402	BA4034/42	9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	Fanlight Panel		Insulating Board	NO ASBESTOS	Enclosed Spray or Lagging/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	73403	BA4034/43	9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	Fanlight Panel		Insulating Board	NO ASBESTOS	Enclosed Spray or Lagging/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	73404	BA4034/43	9724/17	13/04/2017	WH Stephens

#REF!	QAA	Craigavon Hospital	01	Wall Panels		Insulating Board	NO ASBESTOS	Encapsulated Spray or Laconin/Unsealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	73405	BA4034/44	9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	Ceiling Board		Insulating Board	NO ASBESTOS	Encapsulated Spray or Laconin/Unsealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	73406	BA4034/45	9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	Ceiling Board		Insulating Board	NO ASBESTOS	Encapsulated Spray or Laconin/Unsealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	73407	BA4034/45	9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	Composite Material		Composite Material	NO ASBESTOS	Composite Materials	Medium	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	73408	BA4034/46	9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	Gaskets		Textiles & Paper	NO ASBESTOS	Encapsulated Spray or Laconin/Unsealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	73409	BA4034/47	9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	Wall Panels		Cement Products	Chrysotile	Encapsulated Spray or Laconin/Unsealed AIB	Low	Manage & Affix ID Labels	Re-inspection	HSG227	Unchecked	Very Low Risk	4	21/09/2023	Identified	Very Low Risk	73410	BA4034/48	9724/17	21/09/2022	WHS
#REF!	QAA	Craigavon Hospital	01	Wall Panels		Insulating Board	NO ASBESTOS	Encapsulated Spray or Laconin/Unsealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	73411	BA4034/49	9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	73412	BA4034/50	9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	73413	BA4034/50	9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	73414	BA4034/50	9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	73415	BA4034/50	9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	73416	BA4034/50	9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	Sink Pad		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	73417	BA4034/50	9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	Door Panel		Insulating Board	NO ASBESTOS	Enclosed Spray or Laconin/Sealed AIB	Low	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Presumed	Asbestos Removed	73418		9724/17	13/04/2017	WH Stephens
#REF!	QAC	Lurgan Hospital	02	Debris		Thermal Insulation	NO ASBESTOS	Unsealed Spray / Lagging / Dust Debris	Loose asbestos debris or residue	No further action required (Asbestos removed)	Re-inspection	HSG227	Checked	High Risk	0	20/09/2023	Identified	Asbestos Removed	73419		9299/22	12/09/2022	WHS
#REF!	QAC	Lurgan Hospital	02	Debris		Thermal Insulation	NO ASBESTOS	Unsealed Spray / Lagging / Dust Debris	Loose asbestos debris or residue	No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	Asbestos Removed	73420		9326/17	20/12/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	Bitumen Felt		Composite Material	Chrysotile	Composite Materials	High	Manage & Affix ID Labels	Review – No Change	HSG227	Unchecked	Low Risk	5	06/08/2014	Identified	Low Risk	73421	BA4054/01	9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Medium	Manage & Affix ID Labels	Review – No Change	HSG227	Unchecked	Very Low Risk	4	06/08/2014	Identified	Very Low Risk	73422	BA4054/02	9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Medium	Manage & Affix ID Labels	Review – No Change	HSG227	Unchecked	Very Low Risk	4	06/08/2014	Strongly Presumed Similar to	Very Low Risk	73423	BA4054/02	9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	Bitumen Adhesive		Composite Material	Chrysotile	Composite Materials	Medium	Manage & Affix ID Labels	Review – No Change	HSG227	Unchecked	Very Low Risk	4	06/08/2014	Strongly Presumed Similar to	Very Low Risk	73424	BA4054/02	9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	General Debris		General Debris	NO ASBESTOS	Unsealed Spray / Lagging / Dust Debris	Areas of damage or deterioration	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	73425	BA4054/03	9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	General Debris		General Debris	NO ASBESTOS	Unsealed Spray / Lagging / Dust Debris	Areas of damage or deterioration	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	73426	BA4054/04	9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	Pipe Brackets		Textiles & Paper	Chrysotile	Encapsulated Spray or Laconin/Unsealed AIB	Low	Apply Caution when Maintaining	Review – No Change	HSG227	Unchecked	Low Risk	6	06/08/2014	Identified	Low Risk	73427	BA4054/05	9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	Pipe Brackets		Textiles & Paper	Chrysotile	Encapsulated Spray or Laconin/Unsealed AIB	Low	Apply Caution when Maintaining	Review – No Change	HSG227	Unchecked	Low Risk	6	06/08/2014	Strongly Presumed Similar to	Low Risk	73428	BA4054/05	9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	Door Panel		Insulating Board	NO ASBESTOS	Encapsulated Spray or Laconin/Unsealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	73429	BA4054/06	9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	Wall Panels		Insulating Board	NO ASBESTOS	Encapsulated Spray or Laconin/Unsealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	73430	BA4054/06	9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	Gaskets		Textiles & Paper	Chrysotile	Encapsulated Spray or Laconin/Unsealed AIB	Low	Manage & Affix ID Labels	Review – No Change	HSG227	Unchecked	Low Risk	6	06/08/2014	Identified	Low Risk	73431	BA4054/07	9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	General Debris		General Debris	NO ASBESTOS	Unsealed Spray / Lagging / Dust Debris	Areas of damage or deterioration	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	73432	BA4054/08	9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	General Debris		General Debris	NO ASBESTOS	Unsealed Spray / Lagging / Dust Debris	Areas of damage or deterioration	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	73433	BA4054/09	9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	Bitumen Felt		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	73434	BA4054/10	9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	Bitumen Felt		Composite Material	NO ASBESTOS	Composite Materials	None	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	73435	BA4054/10	9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	Bitumen Paints		Composite Material	NO ASBESTOS	Composite Materials	Areas of damage or deterioration	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	73436	BA4054/11	9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	Bitumen Paints		Composite Material	NO ASBESTOS	Composite Materials	Areas of damage or deterioration	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	73437	BA4054/11	9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	Bitumen Paints		Composite Material	NO ASBESTOS	Composite Materials	Areas of damage or deterioration	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	73438	BA4054/11	9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	Duct Access Panels		Insulating Board	NO ASBESTOS	Encapsulated Spray or Laconin/Unsealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	73439	BA4054/12	9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	Gaskets		Textiles & Paper	Chrysotile	Encapsulated Spray or Laconin/Unsealed AIB	Low	Apply caution when maintaining and affix ID labels	Review – No Change	HSG227	Unchecked	Low Risk	6	06/08/2014	Identified	Low Risk	73440	BA4054/13	9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	Gaskets		Textiles & Paper	Chrysotile	Encapsulated Spray or Laconin/Unsealed AIB	Low	Apply caution when maintaining and affix ID labels	Review – No Change	HSG227	Unchecked	Low Risk	6	06/08/2014	Strongly Presumed Similar to	Low Risk	73441	BA4054/13	9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	Gaskets		Textiles & Paper	NO ASBESTOS	Encapsulated Spray or Laconin/Unsealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	73442	BA4054/14	9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	Wall Board		Cement Products	NO ASBESTOS	Enclosed Spray or Laconin/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	73443	BA4054/15	9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	Bitumen Felt		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	73444	BA4054/16	9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	Bitumen Felt		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	73445	BA4054/16	9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	Bitumen Felt		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	73446	BA4054/16	9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	Bitumen Felt		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	73447	BA4054/17	9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	Bitumen Felt		Composite Material	NO ASBESTOS	Composite Materials	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	73448	BA4054/17	9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	Woven Asbestos Textile		Textiles & Paper	Chrysotile	Encapsulated Spray or Laconin/Unsealed AIB	Low	Apply caution when maintaining and affix ID labels	Review – No Change	HSG227	Unchecked	Low Risk	6	06/08/2014	Identified	Low Risk	73449	BA4054/18	9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	Gaskets		Textiles & Paper	Chrysotile	Encapsulated Spray or Laconin/Unsealed AIB	Low	Apply Caution when Maintaining	Review – No Change	HSG227	Unchecked	Low Risk	6	06/08/2014	Identified	Low Risk	73450	BA4054/19	9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	Wall Board		Cement Products	NO ASBESTOS	Enclosed Spray or Laconin/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	73451	BA4054/20	9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	Wall Board		Cement Products	NO ASBESTOS	Enclosed Spray or Laconin/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	73452	BA4054/20	9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	Wall Board		Cement Products	NO ASBESTOS	Enclosed Spray or Laconin/Sealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	73453	BA4054/20	9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	Door Panel		Insulating Board	NO ASBESTOS	Encapsulated Spray or Laconin/Unsealed AIB	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	73454	BA4054/21	9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	Bitumen Felt		Composite Material	Chrysotile	Composite Materials	Medium	Manage & Affix ID Labels	Review – No Change	HSG227	Unchecked	Very Low Risk	4	06/08/2014	Identified	Very Low Risk	73455	BA4054/22	9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	Bitumen Wrap to cables		Composite Material	Presumed Asbestos	Composite Materials	Low	Apply Caution when Maintaining	Review – No Change	HSG227	Unchecked	Low Risk	5	06/08/2014	Presumed	Low Risk	73456		9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	Fuse Flash Guards		Textiles & Paper	Presumed Asbestos	Encapsulated Spray or Laconin/Unsealed AIB	Medium	Apply caution when maintaining and affix ID labels	Review – No Change	HSG227	Unchecked	Medium Risk	9	06/08/2014	Presumed	Medium Risk	73457		9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	Fuse Flash Guards		Textiles & Paper	Presumed Asbestos	Encapsulated Spray or Laconin/Unsealed AIB	Medium	Apply caution when maintaining and affix ID labels	Review – No Change	HSG227	Unchecked	Medium Risk	9	06/08/2014	Presumed	Medium Risk	73458		9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	Fuse Flash Guards		Textiles & Paper	Presumed Asbestos	Encapsulated Spray or Laconin/Unsealed AIB	Medium	Apply caution when maintaining and affix ID labels	Review – No Change	HSG227	Unchecked	Medium Risk	9	06/08/2014	Presumed	Medium Risk	73459		9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	Fuse Flash Guards		Textiles & Paper	Presumed Asbestos	Encapsulated Spray or Laconin/Unsealed AIB	Medium	Apply caution when maintaining and affix ID labels	Review – No Change	HSG227	Unchecked	Medium Risk	9	06/08/2014	Presumed	Medium Risk	73460		9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	Brake Pads		Textiles & Paper	Presumed Asbestos	Encapsulated Spray or Laconin/Unsealed AIB	Medium	Apply caution when maintaining and affix ID labels	Review – No Change	HSG227	Unchecked	Medium Risk	9	06/08/2014	Presumed	Medium Risk	73461		9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	Fuse Flash Guards	Spares Box	Textiles & Paper	Presumed Asbestos	Encapsulated Spray or Laconin/Unsealed AIB	Medium	Remove	Review – No Change	HSG227	Unchecked	Medium Risk	9	06/08/2014	Presumed	Medium Risk	73462		9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	Brake Pads		Textiles & Paper	Presumed Asbestos	Encapsulated Spray or Laconin/Unsealed AIB	Medium	Apply caution when maintaining and affix ID labels	Review – No Change	HSG227	Unchecked	Medium Risk	9	06/08/2014	Presumed	Medium Risk	73463		9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	Brake Pads		Textiles & Paper	Presumed Asbestos	Encapsulated Spray or Laconin/Unsealed AIB	Medium	Apply caution when maintaining and affix ID labels	Review – No Change	HSG227	Unchecked	Medium Risk	9	06/08/2014	Presumed	Medium Risk	73464		9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	Brake Pads		Textiles & Paper	Presumed Asbestos	Encapsulated Spray or Laconin/Unsealed AIB	Medium	Apply caution when maintaining and affix ID labels	Review – No Change	HSG227	Unchecked	Medium Risk	9	06/08/2014	Presumed	Medium Risk	73465		9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	Debris		Insulating Board	Presumed Asbestos	Encapsulated Spray or Laconin/Unsealed AIB	Medium	Apply Caution when Maintaining	Review – No Change	HSG227	Unchecked	Medium Risk	9	05/02/2014	Presumed	Medium Risk	73466		9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	00	Gaskets		Textiles & Paper	Chrysotile	Encapsulated Spray or Laconin/Unsealed AIB	Low	Apply Caution when Maintaining	Photographs Added	HSG227	Unchecked	Low Risk	6	18/11/2014	Identified	Low Risk	75453	AJ9008/01		18/11/2013	
#REF!	QAA	Craigavon Hospital	00								Original Survey	HSG227	Checked	High Risk	0				75454			18/11/2013	
#REF!	QAA	Craigavon Hospital	00								Original Survey	HSG227	Checked	High Risk	0				75455			18/11/2013	
#REF!	QAA	Craigavon Hospital	00								Original Survey	HSG227	Checked	High Risk	0				75456			18/11/2013	
#REF!	QAA	Craigavon Hospital	00								Original Survey	HSG227	Checked	High Risk	0				75457			18/11/2013	
#REF!	QAA	Craigavon Hospital	00								Original Survey	HSG227	Checked	High Risk	0				75458			18/11/2013	
#REF!	QAA	Craigavon Hospital	00								Original Survey	HSG227	Checked	High Risk	0				75459			18/11/2013	
#REF!	QAA	Craigavon Hospital	00								Original Survey	HSG227	Checked	High Risk	0				75460			18/11/2013	
#REF!	QAA	Craigavon Hospital	00								Original Survey	HSG227	Checked	High Risk	0				75461			18/11/2013	
#REF!	QAA	Craigavon Hospital	00								Original Survey	HSG227	Checked	High Risk	0				75462			18/11/2013	
#REF!	QAA	Craigavon Hospital	00								Original Survey	HSG227	Checked	High Risk	0				75463			18/11/2013	
#REF!	QAA	Craigavon Hospital	00								Original Survey	HSG227	Checked	High Risk	0				75464			18/11/2013	
#REF!	QAA	Craigavon Hospital	00								Original Survey	HSG227	Checked	High Risk	0				75465			18/11/2013	
#REF!	QAA	Craigavon Hospital	00								Original Survey	HSG227	Checked	High Risk	0				75466			18/11/2013	
#REF!	QAA	Craigavon Hospital	00								Original Survey	HSG227	Checked	High Risk	0				75467			18/11/2013	
#REF!	QAA	Craigavon Hospital	00								Original Survey	HSG227	Checked	High Risk	0				75468			18/11/2013	
#REF!	QAA	Craigavon Hospital	00								Original Survey	HSG227	Checked	High Risk	0				75469			18/11/2013	
#REF!	QAA	Craigavon Hospital	00								Original Survey	HSG227	Checked	High Risk	0				75470			18/11/2013	
#REF!	QAA	Craigavon Hospital	00								Original Survey	HSG227	Checked	High Risk	0				75471			18/11/2013	
#REF!	RAC	Tower Hill Site	03	Board	Loose Board	Insulating Board	NO ASBESTOS	Unsealed Board	Medium	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	79867	BA136671	9344/17	21/03/2018	WHS
#REF!	RAC	Tower Hill Site	03	Board	Lower Board to Virtical Duct	Insulating Board	NO ASBESTOS	Unsealed Board		No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	79868	BS136672	9344/17	21/03/2018	WHS
#REF!	RAC	Tower Hill Site	03	Board	Higher board to vertical duct	Insulating Board	NO ASBESTOS	Unsealed Board	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	79869	BS136673	9344/17	21/03/2018	WHS
#REF!	RAC	Tower Hill Site	03	Board	Board to Horizontal Duct	Insulating Board	Amosite/Chrysotile	Unsealed Board	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Medium Risk	8	27/03/2021	Identified	Medium Risk	79870	BS136674	9344/17	28/11/2019	WHS
#REF!	SAB	Mourne Hospital	12	Cement Flat Sheet	SAB12 - Roofspace	Cement Products	Chrysotile	Cement Sheets	Low	Manage & Affix ID Labels	Re-inspection	HSG227	Unchecked	Very Low Risk	4	13/09/2023	Identified	Low Risk	79946	BS222999	9360/17	25/05/2022	WHS

#REF!	SAB	Mourne Hospital	12	Insulating Board	SAB12 - Roofspace	Insulating Board	Chrysotile	Unsealed Asbestos Insulation	High	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	Medium Risk	8	13/12/2022	Identified	High Risk	79947	BS323000	950/18	25/05/2022	WHS
#REF!	QHD	Transna House	01	Gaskets		Textiles & Paper	Presumed Asbestos	Encapsulated Spray or Lagoins/Unsealed AIB	None	Apply Caution when Maintaining	Re-inspection	HSG227	Unchecked	Medium Risk	7	14/10/2023	Presumed	Low Risk	79951		929/02	29/09/2022	WHS
#REF!	QHD	Transna House	01	Textiles & Paper		Textiles & Paper	Presumed Asbestos	Encapsulated Spray or Lagoins/Unsealed AIB	None	Apply Caution when Maintaining	Re-inspection	HSG227	Unchecked	Medium Risk	7	14/06/2023	Presumed	Low Risk	79952		929/02	29/09/2022	WHS
#REF!	QHD	Transna House	01	Door Panel		Insulating Board	Presumed Asbestos	Encapsulated Spray or Lagoins/Unsealed AIB	None	Apply Caution when Maintaining	Re-inspection	HSG227	Unchecked	Low Risk	6	14/10/2023	Presumed	Low Risk	79955		929/02	29/09/2022	WHS
#REF!	QLA	Burnside Family Centre	01	Bitumen Felt		Reinforced Composites	NO ASBESTOS	Composite Material	Very Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified		80068	BS148182	932/17	04/11/2018	WH Stephens
#REF!	QAA	Craigavon Hospital	16	NO ASBESTOS		NO ASBESTOS	NO ASBESTOS	Composite Material	Very Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	80069	BS146332	9724/17	05/09/2017	WHS
#REF!	QAA	Craigavon Hospital	14	NO ASBESTOS	Roof void 1	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	80690	BS190259	950/18	11/09/2018	WHS
#REF!	QAA	Craigavon Hospital	14	NO ASBESTOS	Roof void 1	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	80691	BS190260	950/18	11/09/2018	WHS
#REF!	QAA	Craigavon Hospital	14	NO ASBESTOS	Entrance hall ceiling	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	80692	BS190261	950/18	11/09/2018	WHS
#REF!	QAA	Craigavon Hospital	14	NO ASBESTOS	Office ceiling	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	80693	as Per BS190261	950/18	11/09/2018	WHS
#REF!	QAA	Craigavon Hospital	14	NO ASBESTOS	Office ceiling	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	80694	as Per BS190261	950/18	11/09/2018	WHS
#REF!	QAA	Craigavon Hospital	14	NO ASBESTOS	Office ceiling	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	80695	as Per BS190261	950/18	11/09/2018	WHS
#REF!	QAA	Craigavon Hospital	14	NO ASBESTOS	Office ceiling	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	80696	as Per BS190261	950/18	11/09/2018	WHS
#REF!	QAA	Craigavon Hospital	14	NO ASBESTOS	Store ceiling	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	80697	as Per BS190261	950/18	11/09/2018	WHS
#REF!	QAA	Craigavon Hospital	14	NO ASBESTOS	Corridor ceiling	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	80698	BS190262	950/18	11/09/2018	WHS
#REF!	QAA	Craigavon Hospital	14	NO ASBESTOS	Store ceiling	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	80699	as Per BS190262	950/18	11/09/2018	WHS
#REF!	QAA	Craigavon Hospital	14	NO ASBESTOS	Toilet ceiling	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	80700	as Per BS190262	950/18	11/09/2018	WHS
#REF!	QAA	Craigavon Hospital	14	NO ASBESTOS	Toilet ceiling	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	80701	as Per BS190262	950/18	11/09/2018	WHS
#REF!	QAA	Craigavon Hospital	14	NO ASBESTOS	Disabled toilet ceiling	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	80702	as Per BS190262	950/18	11/09/2018	WHS
#REF!	QAA	Craigavon Hospital	14	NO ASBESTOS	Staff room ceiling	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	80703	as Per BS190262	950/18	11/09/2018	WHS
#REF!	QAA	Craigavon Hospital	14	NO ASBESTOS	Cleaner store ceiling	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	80704	BS190263	950/18	11/09/2018	WHS
#REF!	QAA	Craigavon Hospital	14	NO ASBESTOS	Store ceiling	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	80705	as Per BS190263	950/18	11/09/2018	WHS
#REF!	QAA	Craigavon Hospital	14	NO ASBESTOS	Equipment room ceiling	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	80706	as Per BS190263	950/18	11/09/2018	WHS
#REF!	QAA	Craigavon Hospital	14	NO ASBESTOS	Plant room ceiling	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	80707	as Per BS190263	950/18	11/09/2018	WHS
#REF!	QAA	Craigavon Hospital	14	NO ASBESTOS	Generator room ceiling	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	80708	as Per BS190263	950/18	11/09/2018	WHS
#REF!	QAA	Craigavon Hospital	14	NO ASBESTOS	Oil tank room ceiling	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	80709	as Per BS190263	950/18	11/09/2018	WHS
#REF!	QAA	Craigavon Hospital	14	NO ASBESTOS	Roof void 2	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	80710	BS190264	950/18	11/09/2018	WHS
#REF!	QAA	Craigavon Hospital	14	NO ASBESTOS	Roof void 2	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	80711	BS190270	950/18	11/09/2018	WHS
#REF!	QAA	Craigavon Hospital	14	NO ASBESTOS	Roof void 3	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	80712	as par BS190270	950/18	11/09/2018	WHS
#REF!	QAA	Craigavon Hospital	14	NO ASBESTOS	Roof void 4	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	80713	as par BS190270	950/18	11/09/2018	WHS
#REF!	QAA	Craigavon Hospital	14	NO ASBESTOS	Roof void 2	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	80714	as par BS190269	950/18	11/09/2018	WHS
#REF!	QAA	Craigavon Hospital	14	NO ASBESTOS	Roof void 1	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	80715	BS190269	950/18	11/09/2018	WHS
#REF!	QAA	Craigavon Hospital	14	NO ASBESTOS	Roof void 3	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	80716	as par BS190269	950/18	11/09/2018	WHS
#REF!	QAA	Craigavon Hospital	14	NO ASBESTOS	Roof void 4	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	80717	as par BS190269	950/18	11/09/2018	WHS
#REF!	QAA	Craigavon Hospital	14	NO ASBESTOS	Roof void 5	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	80718	as par BS190269	950/18	11/09/2018	WHS
#REF!	QAA	Craigavon Hospital	14	NO ASBESTOS	Roof void 6	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	80719	as par BS190269	950/18	11/09/2018	WHS
#REF!	QAA	Craigavon Hospital	14	NO ASBESTOS	Store ceiling	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	80720	BS190265	950/18	11/09/2018	WHS
#REF!	QAA	Craigavon Hospital	14	NO ASBESTOS	Training room ceiling	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	80721	BS190267	950/18	11/09/2018	WHS
#REF!	QAA	Craigavon Hospital	14	NO ASBESTOS	Training room ceiling	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	80722	as par BS190267	950/18	11/09/2018	WHS
#REF!	QAA	Craigavon Hospital	14	NO ASBESTOS	Training room ceiling	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	80723	BS190268	950/18	11/09/2018	WHS
#REF!	QAA	Craigavon Hospital	14	NO ASBESTOS	Training room ceiling	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	80724	as par BS190268	950/18	11/09/2018	WHS
#REF!	QAA	Craigavon Hospital	14	NO ASBESTOS	Roof void 3	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	80725	BS190271	950/18	11/09/2018	WHS
#REF!	QAA	Craigavon Hospital	14	NO ASBESTOS	Roof void 5	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	80726	as par BS190271	950/18	11/09/2018	WHS
#REF!	QAA	Craigavon Hospital	14	NO ASBESTOS	Oil tank room floor	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	80727	BS190266	950/18	11/09/2018	WHS
#REF!	QAA	Craigavon Hospital	27	NO ASBESTOS	Cyclinder store ceiling	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	80728	BS190230	950/18	19/12/2018	WHS
#REF!	QAA	Craigavon Hospital	27	NO ASBESTOS	Electrics ceiling	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	80729	as par BS190230	950/18	19/12/2018	WHS
#REF!	QAA	Craigavon Hospital	27	NO ASBESTOS	Store ceiling	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	80730	as par BS190230	950/18	19/12/2018	WHS
#REF!	QAA	Craigavon Hospital	27	NO ASBESTOS	Electrics and store ceiling	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	80731	as par BS190230	950/18	19/12/2018	WHS
#REF!	QAA	Craigavon Hospital	27	NO ASBESTOS	Cyclinder store ceiling	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	80732	BS190231	950/18	19/12/2018	WHS
#REF!	QAA	Craigavon Hospital	27	NO ASBESTOS	Cyclinder rack in store	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	80733	BS190232	950/18	19/12/2018	WHS
#REF!	QAA	Craigavon Hospital	27	NO ASBESTOS	Electrics and store floor	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	80734	BS190233	950/18	19/12/2018	WHS
#REF!	QAA	Craigavon Hospital	27	NO ASBESTOS	Electrics and store ceiling	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	80735	BS190234	950/18	19/12/2018	WHS
#REF!	RAA	South Tyrone Hospital	09	NO ASBESTOS	Corridor Ceiling	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	80736	BS190272	950/18	12/05/2018	WHS
#REF!	RAA	South Tyrone Hospital	09	Bitumen Felt	Corridor Ceiling	Composite Material	Chrysotile	Composite Material	Very Low	Remove if likely to be disturbed	Re-inspection	HSG227	Unchecked	Very Low Risk	2	15/12/2023	Identified	Very Low Risk	80737	BS190273	932/17	15/12/2022	WHS
#REF!	RAA	South Tyrone Hospital	09	NO ASBESTOS	Corridor ceiling	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	80738	BS190274	950/18	12/05/2018	WHS
#REF!	RAA	South Tyrone Hospital	09	NO ASBESTOS	Corridor ceiling	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	80739	as par BS190275	950/18	12/05/2018	WHS
#REF!	RAA	South Tyrone Hospital	09	NO ASBESTOS	Ceiling	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	80740	BS190275	950/18	12/05/2018	WHS
#REF!	RAA	South Tyrone Hospital	09	NO ASBESTOS	Corridor ceiling	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	80741	as par BS190275	950/18	12/05/2018	WHS
#REF!	RAA	South Tyrone Hospital	09	NO ASBESTOS	Corridor ceiling	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to	No Asbestos Detected	80742	as par BS190275	950/18	12/05/2018	WHS
#REF!	RAA	South Tyrone Hospital	09	Rope Seal	Ceilino	Textiles & Paper	Chrysotile	Unsealed Rope	Low	Remove if likely to be disturbed	Re-inspection	HSG227	Unchecked	Low Risk	6	15/12/2023	Identified	Low Risk	80743	BS190276	932/17	15/12/2022	WHS
#REF!	RAA	South Tyrone Hospital	09	Rope Seal	Rope seal to A/C metal trunkino	Textiles & Paper	Chrysotile	Unsealed Rope	Low	Remove if likely to be disturbed	Re-inspection	HSG227	Unchecked	Low Risk	6	15/12/2023	Identified	Low Risk	80744	BA9344	932/17	15/12/2022	WHS
#REF!	RAA	South Tyrone Hospital	09	Rope Seal	Ceiling	Textiles & Paper	Chrysotile	Unsealed Rope	Low	Remove if likely to be disturbed	Re-inspection	HSG227	Unchecked	Low Risk	6	15/12/2023	Identified	Low Risk	80745	BS190279	932/17	15/12/2022	WHS
#REF!	RAA	South Tyrone Hospital	09	Rope Seal	Ceilino	Textiles & Paper	Chrysotile	Unsealed Rope	Low	Remove if likely to be disturbed	Re-inspection	HSG227	Unchecked	Low Risk	6	15/12/2023	Stronolv Presumed Similar to	Low Risk	80746	as oar BS190279	932/17	15/12/2022	WHS
#REF!	RAA	South Tyrone Hospital	09	Bitumen Felt	Ceilino	Composite Material	Chrysotile	Composite Material	Very Low	Remove if likely to be disturbed	Re-inspection	HSG227	Unchecked	Very Low Risk	2	15/12/2023	Identified	Very Low Risk	80747	BS190277	932/17	15/12/2022	WHS
#REF!	RAA	South Tyrone Hospital	09	NO ASBESTOS	Ceiling	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	80748	BS190282	950/18	12/05/2018	WHS
#REF!	RAA	South Tyrone Hospital	09	NO ASBESTOS	Ceiling	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	80749	BS190281	950/18	12/05/2018	WHS
#REF!	RAA	South Tyrone Hospital	09	NO ASBESTOS	Ceiling	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	80750	BS190280	950/18	12/05/2018	WHS
#REF!	RAA	South Tyrone Hospital	09	NO ASBESTOS	Ceiling	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	80751	BS190278	950/18	12/05/2018	WHS
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	White floor tile	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	81244	J036614	9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Light green floor tile	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	81245	J036614	9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Light beige floor tile	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	81246	J036614	9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Grey floor tile	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	81247	J036614	9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Beige floor tile	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	81248	J036614	9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Green floor tile	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	81249	J036614	9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Floor tile beneath screed	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	81250	J036614	9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Floor tile adhesive	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	81251	J036614	9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Floor tile adhesive	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	81252	J036614	9724/17	13/04/2017	WH Stephens

#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Skirting trim	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	81253	J036614	9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Floor tile adhesive	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	81254	J036614	9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Floor tile adhesive	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	81255	J036614	9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Floor tile adhesive	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	81256	J036614	9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Floor tile adhesive	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	81257	J036614	9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Debris to door ledge	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	81258	J036613	9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Debris to door ledge	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	81259	J036613	9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Debris to metal bracket	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	81260	J036613	9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Debris to door ledge	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	81261	J036613	9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Debris to door ledge	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	81262	J036613	9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Debris to door ledge	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	81263	J036613	9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Debris to floor of mezzanine 1	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	81269	J036615	9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Debris to floor at bed lift motor	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	81270	J036615	9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Debris to floor of mezzanine 1	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	81271	J036615	9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Debris to floor of mezzanine 1 at cable trunking	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	81272	J036615	9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Brake shoe N7 to bed lift motors	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	81273	J036615	9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Debris to floor	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Error Entry	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	81277	J036615	9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Debris to floor beneath vent trunking	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	81279	J036615	9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Debris to cable trunking	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	81280	J036615	9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Debris to electric box	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	81282	J036615	9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	Mastic	Mastic to vent trunking	Composite Material	Chrysotile	Composite Material	Low	Manage and monitor	Review – No Change	HSG227	Unchecked	Very Low Risk	3	13/04/2018	Identified	Very Low Risk	81284	J036615	9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Debris to top of large vent trunking	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	81285	J036615	9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Debris to floor beside passenger lift plant NI5	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	81286	J036615	9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Debris to vent trunking beside mezzanine 2	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	81287	J036615	9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	Brake Pads	Brake pad to passenger lift motor	Reinforced	Chrysotile	Composite Material	Low	Manage and monitor	Review – No Change	HSG227	Unchecked	Very Low Risk	3	20/03/2018	Identified	Very Low Risk	81288	J036615	9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	Paper	Paper to redundant flash guard	Textiles & Paper	Chrysotile	Unsealed	Low	Manage and monitor	Review – No Change	HSG227	Unchecked	Medium Risk	7	20/03/2018	Identified	Medium Risk	81289	J036615	9724/17	13/04/2017	WH Stephens
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	DPC to rear wall	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	81291	J036615	9724/17	13/04/2017	WH Stephens
#REF!	QPA	Eden SEC	01	NO ASBESTOS	Vinyl floor covering	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	81612	J037298	9811/19	21/01/2020	WH Stephens
#REF!	QPA	Eden SEC	01	NO ASBESTOS	Vinyl floor covering - dining room	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	81613	J037298	9811/19	21/01/2020	WH Stephens
#REF!	QPA	Eden SEC	01	NO ASBESTOS	Kitchen - Sink pad 1	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	81614	J037298	9811/19	21/01/2020	WH Stephens
#REF!	QPA	Eden SEC	01	NO ASBESTOS	Kitchen - Sink pad 2	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	81615	J037298	9811/19	21/01/2020	WH Stephens
#REF!	QPA	Eden SEC	01	Wall Panels	Wall panel in dining room	Insulating Board	Amosite/Chrysotile	Unsealed Asbestos Insulation Board	Low	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	Medium Risk	7	13/03/2023	Identified	Medium Risk	81616	J037298	9811/19	11/04/2022	WHS
#REF!	QPA	Eden SEC	01	NO ASBESTOS	Kitchen and dining room ceiling tile	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	81617	J037298	9811/19	21/01/2020	WH Stephens
#REF!	QPA	Eden SEC	01	NO ASBESTOS	Wall board above window to rear wall	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	81618	J037298	9811/19	21/01/2020	WH Stephens
#REF!	QPA	Eden SEC	01	NO ASBESTOS	Wall panel to RHS of room	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	81619	J037298	9811/19	21/01/2020	WH Stephens
#REF!	QPA	Eden SEC	01	NO ASBESTOS	Debris to electronic lock	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	81620	J037298	9811/19	21/01/2020	WH Stephens
#REF!	QPA	Eden SEC	01	NO ASBESTOS	Debris to floor RHS of room	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	81621	J037298	9811/19	21/01/2020	WH Stephens
#REF!	QPA	Eden SEC	01	NO ASBESTOS	Board to rear wall at high level	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	81622	J037298	9811/19	21/01/2020	WH Stephens
#REF!	QPA	Eden SEC	01	NO ASBESTOS	Debris to floor	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	81623	J037298	9811/19	21/01/2020	WH Stephens
#REF!	QPA	Eden SEC	01	NO ASBESTOS	Wall Panel	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	81624	J037298	9811/19	21/01/2020	WH Stephens
#REF!	QPA	Eden SEC	01	NO ASBESTOS	firebreak between 014 & 015	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	81625	J037298	9811/19	21/01/2020	WH Stephens
#REF!	QPA	Eden SEC	01	NO ASBESTOS	Debris to light switch	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	81626	J037298	9811/19	21/01/2020	WH Stephens
#REF!	QPA	Eden SEC	01	NO ASBESTOS	Debris to stairs	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	81627	J037298	9811/19	21/01/2020	WH Stephens
#REF!	QPA	Eden SEC	01	NO ASBESTOS	Debris to cable trunking	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	81628	J037298	9811/19	21/01/2020	WH Stephens
#REF!	QPA	Eden SEC	01	NO ASBESTOS	Ceiling tile	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	81629	J037298	9811/19	21/01/2020	WH Stephens
#REF!	QPA	Eden SEC	01	NO ASBESTOS	Wall panel to rear wall at high level	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	81630	J037298	9811/19	21/01/2020	WH Stephens
#REF!	QPA	Eden SEC	01	NO ASBESTOS	Board to back of ceiling hatch	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	81631	J037298	9811/19	21/01/2020	WH Stephens
#REF!	QPA	Eden SEC	01	NO ASBESTOS	Board to back of ceiling hatch	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	81632	J037298	9811/19	21/01/2020	WH Stephens
#REF!	QPA	Eden SEC	01	NO ASBESTOS	Debris to floor	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	81633	J037298	9811/19	21/01/2020	WH Stephens
#REF!	QPA	Eden SEC	01	NO ASBESTOS	Debris to cable trunking	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	81634	J037298	9811/19	21/01/2020	WH Stephens
#REF!	QPA	Eden SEC	01	Roofing material	Inner skin of roof covering	Cement Products	Chrysotile	Cement Sheets	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Very Low Risk	4	05/04/2018	Identified	Very Low Risk	81635	J037298	9811/19	21/01/2020	WHS
#REF!	QPA	Eden SEC	01	NO ASBESTOS	Debris to floor	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	81636	J037298	9811/19	21/01/2020	WH Stephens
#REF!	QPA	Eden SEC	01	NO ASBESTOS	Debris to vent trunking	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	81637	J037298	9811/19	21/01/2020	WH Stephens
#REF!	QPA	Eden SEC	01	NO ASBESTOS	Debris to switchgear	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	81638	J037298	9811/19	21/01/2020	WH Stephens
#REF!	QPA	Eden SEC	01	Wall Panels	Wall Board	Insulating Board	Amosite/Chrysotile	Unsealed Board	Low	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	Medium Risk	7	13/03/2023	Identified	Medium Risk	81639	J037298	9811/19	11/04/2022	WHS
#REF!	QPA	Eden SEC	01	NO ASBESTOS	Floor debris	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	81640	J037298	9811/19	21/01/2020	WH Stephens
#REF!	QPA	Eden SEC	01	NO ASBESTOS	Floor Debris	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	81641	J037298	9811/19	21/01/2020	WH Stephens
#REF!	QPA	Eden SEC	01	NO ASBESTOS	Debris to base of hot water cylinder	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	81642	J037298	9811/19	21/01/2020	WH Stephens
#REF!	QPA	Eden SEC	01	NO ASBESTOS	Debris to metal frame	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	81643	J037298	9811/19	21/01/2020	WH Stephens
#REF!	QPA	Eden SEC	01	NO ASBESTOS	Debris to light switch	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	81644	J037298	9811/19	21/01/2020	WH Stephens
#REF!	QPA	Eden SEC	01	NO ASBESTOS	Plaster snot to wall	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	81645	J037298	9811/19	21/01/2020	WH Stephens
#REF!	QPA	Eden SEC	01	Roofing material	Roof Coverino	Cement Products	Chrysotile	Cement Asbestos	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Very Low Risk	4	13/09/2023	Identified	Very Low Risk	81646	J037298	9811/19	11/04/2022	WHS
#REF!	QPA	Eden SEC	01	Wall Panels	White wall panel to rear	Cement Products	Chrysotile	Cement Asbestos	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Very Low Risk	4	13/09/2023	Identified	Very Low Risk	81647	J037298	9811/19	11/04/2022	WHS
#REF!	QPA	Eden SEC	01	Wall Panels	White wall panel to LHS elevation	Cement Products	Chrysotile	Cement Asbestos	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Very Low Risk	4	13/09/2023	Identified	Very Low Risk	81648	J037298	9811/19	11/04/2022	WHS
#REF!	QPA	Eden SEC	01	Wall Panels	White wall panel to front elevation	Cement Products	Chrysotile	Cement Asbestos	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Very Low Risk	4	13/09/2023	Identified	Very Low Risk	81649	J037298	9811/19	11/04/2022	WHS
#REF!	QPA	Eden SEC	01	Downpipe	Downpipe	Cement Products	Chrysotile	Cement Asbestos	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Very Low Risk	4	13/09/2023	Identified	Very Low Risk	81650	J037298	9811/19	11/04/2022	WHS
#REF!	QPA	Eden SEC	01	Gutters	Guttering	Cement Products	Chrysotile	Cement Asbestos	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Very Low Risk	4	13/09/2023	Identified	Very Low Risk	81651	J037298	9811/19	11/04/2022	WHS
#REF!	QPA	Eden SEC	01	NO ASBESTOS	Mastic between concrete block to too of gable walls	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	81652	J037298	9811/19	21/01/2020	WH Stephens
#REF!	QPA	Eden SEC	01	Roofing Felts	Roof felt to flat roof section over entrance	Composite Material	Chrysotile	Composite Material	Low	Manage and monitor	Review – No Change	HSG227	Unchecked	Very Low Risk	3	13/09/2023	Identified	Very Low Risk	81653	J037298	9299/22	11/04/2022	WHS
#REF!	QAA	Craigavon Hospital	01	Fire Break Panel	Firebreak panel above double doors to room 223	Insulating Board	Amosite/Chrysotile	Unsealed Asbestos Insulation Board	Low	Remove (Controlled Conditions)	New Incident	HSG227	Unchecked	Medium Risk	7	04/11/2017	Identified	Medium Risk	81759	J037971		02/05/2017	
#REF!	QAA	Craigavon Hospital	01	Pipe Insulation	Cloth wrap to pipe bracket in ceiling	Textiles & Paper	Chrysotile	Enclosed Woven Textile	Low	Remove	New Incident	HSG227	Unchecked	Low Risk	5	05/05/2018	Identified	Low Risk	81760	J037971		02/05/2017	
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Concealed white floor tile	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	81761	J037971		02/05/2017	
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Concealed grey floor tile	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	81762	J037971		02/05/2017	
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Floor tile and bitumen	Reinforced	Chrysotile	Composite Material	Very Low	Manage and monitor	New Incident	HSG227	Unchecked	Very Low Risk	2	05/05/2018	Identified	Very Low Risk	81763	J037971		02/05/2017	
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Ceiling tile	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	81764	J037971		02/05/2017	
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Floor tile	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	81765	J037971		02/05/2017	
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Firebreak to panel above doors leading from room 237	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	81766	J037971		02/05/2017	
#REF!	QAA	Craigavon Hospital	01	Fire Break Panel	Firebreak over double doors to corridor 227	Insulating Board	Amosite/Chrysotile	Unsealed Asbestos Insulation Board	Low	Remove (Controlled Conditions)	New Incident	HSG227	Unchecked	Medium Risk	7	04/11/2017	Identified	Medium Risk	81767	J037971		02/05/2017	
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Floor vinyl to room 238	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	81768	J037971		02/05/2017	
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Firebreak to ceiling void between 239 & 241	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	81769	J037971		02/05/2017	

#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Floor tile to fire hose reel cupboard	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	81770	J037971		02/05/2017		
#REF!	QAA	Craigavon Hospital	01	Board	Board to switch cupboard	Insulating Board	Amosite/Chrysotile	Unsealed Board	Medium	Remove (Controlled Conditions)	New Incident	HSG227	Unchecked	Medium Risk	8	04/11/2017	Identified	Medium Risk	81771	J037971		02/05/2017		
#REF!	QAA	Craigavon Hospital	01	Woven Asbestos Textile	Cloth between pipework and	Textiles & Paper	Chrysotile	Unsealed	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Medium Risk	7	15/09/2023	Identified	Medium Risk	81932	J038885	9302.2	15/09/2022	WHS	
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Debris to ceiling void	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	81933	J038885		05/06/2017		
#REF!	QAA	Craigavon Hospital	01	Ropes	Rope between pipework and	Textiles & Paper	Chrysotile	Unsealed Rope	Low	Remove	Re-inspection	HSG227	Unchecked	Low Risk	6	15/09/2023	Identified	Low Risk	81934	J038885	9302.2	15/09/2022	WHS	
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Debris to ceiling void outside room 1011	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	81935	J038885		05/06/2017		
#REF!	QAA	Craigavon Hospital	01	Ropes	Rope between pipework and	Textiles & Paper	Chrysotile	Unsealed Rope	Low	Remove	Re-inspection	HSG227	Unchecked	Low Risk	6	15/09/2023	Identified	Low Risk	81936	J038885	9302.2	15/09/2022	WHS	
#REF!	QAA	Craigavon Hospital	01	Debris Material	Debris to ceiling tile outside room	Loose Asbestos	Chrysotile	Unsealed Spray / Lagging /	Low	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	High Risk	10	15/09/2023	Identified	High Risk	81937	J038885	9302.2	15/09/2022	WHS	
#REF!	QAA	Craigavon Hospital	01	Woven	Cloth between pipework and	Textiles & Paper	Chrysotile	Unsealed	Low	Remove	Re-inspection	HSG227	Unchecked	Medium Risk	7	15/09/2023	Identified	Medium Risk	81938	J038885	9302.2	15/09/2022	WHS	
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Debris to ceiling tile	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	81939	J038885		05/06/2017		
#REF!	QAA	Craigavon Hospital	01	Roxes	Cloth between pipework and	Textiles & Paper	Chrysotile	Unsealed Roxe	Medium	Remove	Re-inspection	HSG227	Unchecked	Medium Risk	7	15/09/2023	Identified	Medium Risk	81940	J038885	9302.2	15/09/2022	WHS	
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Debris to ceiling tile outside 1013	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	81941	J038885		05/06/2017		
#REF!	QAA	Craigavon Hospital	01	Woven	Cloth between pipework and	Textiles & Paper	Chrysotile	Unsealed	Low	Remove	Re-inspection	HSG227	Unchecked	Medium Risk	7	15/09/2023	Identified	Medium Risk	81942	J038885	9302.2	15/09/2022	WHS	
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Debris to ceiling void at firebreak above doors	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	81943	J038885		05/06/2017		
#REF!	QAA	Craigavon Hospital	01	Fire Break Panel	Panel above door	Insulating Board	Amosite	Sealed Asbestos Insulation	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Low Risk	6	29/09/2023	Identified	Low Risk	81944	J038885	9302.2	29/09/2022	WHS	
#REF!	QAA	Craigavon Hospital	01	Fire Break Panel	Firebreak above door to lift lobby	Insulating Board	Chrysotile	Sealed Asbestos Insulation	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Low Risk	5	29/09/2023	Identified	Low Risk	81945	J038885	9302.2	29/09/2022	WHS	
#REF!	QAA	Craigavon Hospital	01	Roxes	Cloth to bracket	Textiles & Paper	Chrysotile	Unsealed Roxe	Low	Remove	Re-inspection	HSG227	Unchecked	Low Risk	6	29/09/2023	Identified	Low Risk	81946	J038885	9302.2	29/09/2022	WHS	
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Debris to ceiling void in lift lobby	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	81947	J038885		05/06/2017		
#REF!	QAA	Craigavon Hospital	01	Roxes	Roxe to slowork in lift lobby	Textiles & Paper	Chrysotile	Unsealed Roxe	Medium	Remove	Re-inspection	HSG227	Unchecked	Medium Risk	7	29/09/2023	Identified	Medium Risk	81948	J038885	9302.2	29/09/2022	WHS	
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Debris to ceiling void in lift lobby	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	81949	J038885		05/06/2017		
#REF!	QAA	Craigavon Hospital	01	Fire Break Panel	Firebreak above door	Insulating Board	Amosite	Sealed Asbestos Insulation	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Low Risk	6	15/09/2023	Identified	Low Risk	81950	J038885	9302.2	15/09/2022	WHS	
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Skirting trim to lift lobby	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	81951	J038885		05/06/2017		
#REF!	QAA	Craigavon Hospital	01	Woven Asbestos Textile	Cloth between pipework and	Textiles & Paper	Chrysotile	Unsealed	Medium	Remove	Re-inspection	HSG227	Unchecked	Medium Risk	8	15/09/2023	Identified	Medium Risk	81952	J038885	9302.2	15/09/2022	WHS	
#REF!	QAA	Craigavon Hospital	01	Woven Asbestos Textile	Cloth between pipework and	Textiles & Paper	Chrysotile	Unsealed	Medium	Remove	Re-inspection	HSG227	Unchecked	Medium Risk	8	15/09/2023	Identified	Medium Risk	81953	J038885	9302.2	15/09/2022	WHS	
#REF!	QAA	Craigavon Hospital	01	Woven Asbestos Textile	Cloth between pipework and	Textiles & Paper	Chrysotile	Unsealed	Medium	Remove	Re-inspection	HSG227	Unchecked	Medium Risk	8	15/09/2023	Identified	Medium Risk	81954	J038885	9302.2	15/09/2022	WHS	
#REF!	QAA	Craigavon Hospital	01	Woven Asbestos Textile	Cloth between pipework and	Textiles & Paper	Chrysotile	Unsealed	Low	Remove	Re-inspection	HSG227	Unchecked	Medium Risk	7	15/09/2023	Identified	Medium Risk	81955	J038885	9302.2	15/09/2022	WHS	
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Debris to ceiling tile	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	81956	J038885		05/06/2017		
#REF!	QAA	Craigavon Hospital	01	Fire Break Panel	Panel over door to Ward 1 Medicine Ramone	Insulating Board	Amosite	Sealed Asbestos Insulation Board	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Low Risk	6	15/09/2023	Identified	Low Risk	81957	J038885	9302.2 2	15/09/2022	WHS	
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Skirting trim	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	81958	J038885		05/06/2017		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Beige vinyl floor tile	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	81959	J038885		05/06/2017		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	White vinyl floor tile	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	81960	J038885		05/06/2017		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Blue vinyl floor tile	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	81961	J038885		05/06/2017		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Firebreak above door	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	81962	J038885		05/06/2017		
#REF!	SAA	Daisy Hill Hospital Estate	09	Brake Pads	Brake pad to lift motor	Textiles & Paper	Chrysotile	Unsealed	Low	Remove	Re-inspection	HSG227	Unchecked	Medium Risk	7	13/04/2023	Identified	Medium Risk	81963	J038543	9302.2	20/04/2022	WHS	
#REF!	SAA	Daisy Hill Hospital Estate	09	Debris Material	Debris to lift motor	Loose Asbestos	Chrysotile	Unsealed Spray / Lagging /	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	High Risk	10	11/01/2023	Identified	High Risk	81964	J038543	9302.2	20/04/2022	WHS	
#REF!	SAA	Daisy Hill Hospital Estate	09	NO ASBESTOS	Debris to lift motor below brake pads	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	81965	J038543	93271 7	19/02/2018	WHS	
#REF!	SAA	Daisy Hill Hospital Estate	09	NO ASBESTOS	Debris to metal frame of lift motor	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	81966	J038543	93271 7	19/02/2018	WHS	
#REF!	SAA	Daisy Hill Hospital Estate	09	NO ASBESTOS	Debris to floor adjacent lift motor	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	81967	J038543	93271 7	19/02/2018	WHS	
#REF!	SAA	Daisy Hill Hospital Estate	09	NO ASBESTOS	Wood wool slab debris to back of lift motor	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	81968	J038543	93271 7	19/02/2018	WHS	
#REF!	SAA	Daisy Hill Hospital Estate	09	Debris Material	Debris to floor to rear of lift motor	Loose Asbestos	Chrysotile	Unsealed Spray / Lagging /	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	High Risk	10	11/01/2023	Identified	High Risk	81969	J038543	9302.2	20/04/2022	WHS	
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Roof void - Paper to timber board	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	81993	J039226		12/06/2017		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Roof void - Bitumen above roof deck	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	81994	J039226		12/06/2017		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Roof void - Redundant board	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	81995	J039226		12/06/2017		
#REF!	QAA	Craigavon Hospital	01	Mastic	Roof void - Mastic to vent trunking	Composite Material	Chrysotile	Composite Material	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Very Low Risk	3	29/09/2023	Identified	Very Low Risk	81996	J039226	9302.2	29/09/2022	WHS	
#REF!	QAA	Craigavon Hospital	01	Textiles & Paper	Roof void - Cloth to oixe brackets	Textiles & Paper	Chrysotile	Unsealed	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Medium Risk	7	29/09/2023	Identified	Medium Risk	81997	J039226	9302.2	29/09/2022	WHS	
#REF!	QAA	Craigavon Hospital	01	Textiles & Paper	Roof void - Cloth to pipe brackets	Textiles & Paper	Chrysotile	Unsealed	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Medium Risk	7	29/09/2023	Identified	Medium Risk	81998	J039226	9302.2	29/09/2022	WHS	
#REF!	QAA	Craigavon Hospital	01	Textiles & Paper	Roof void - Cloth to oixe brackets	Textiles & Paper	Chrysotile	Unsealed	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Medium Risk	7	29/09/2023	Identified	Medium Risk	81999	J039226	9302.2	29/09/2022	WHS	
#REF!	QAA	Craigavon Hospital	01	Board	Board to toe of floor duct	Insulating Board	Amosite/Chrysotile	Unsealed Board	High	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	Medium Risk	9	29/09/2023	Identified	Medium Risk	82000	J039226	9302.2	29/09/2022	WHS	
#REF!	QAA	Craigavon Hospital	01	Debris Material	Debris to floor of floor duct	Loose Asbestos	Amosite/Chrysotile	Unsealed Spray / Lagging /	Low	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	High Risk	11	29/09/2023	Identified	High Risk	82001	J039226	9302.2	29/09/2022	WHS	
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Bitumen to opening of duct	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82002	J039226		12/06/2017		
#REF!	QAA	Craigavon Hospital	01	Board	Board lining to underfloor duct	Insulating Board	Chrysotile	Unsealed Board	Medium	Remove if likely to be disturbed	Re-inspection	HSG227	Unchecked	Medium Risk	7	29/09/2023	Identified	Medium Risk	82003	J039226	9302.2	29/09/2022	WHS	
#REF!	QAA	Craigavon Hospital	01	Mastic	Roof void - Mastic to vent trunking	Composite Material	Chrysotile	Composite Material	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Very Low Risk	3	29/09/2023	Identified	Very Low Risk	82004	J039226	9302.2	29/09/2022	WHS	
#REF!	QAA	Craigavon Hospital	01	Textiles & Paper	Roof Void - Cloth to pipe bracket	Textiles & Paper	Chrysotile	Unsealed	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Medium Risk	7	29/09/2023	Identified	Medium Risk	82005	J039226	9302.2	29/09/2022	WHS	
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Roof Void - Debris to ceiling void	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82006	J039226		12/06/2017		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Roof Void - Firebreak to front elevation	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82007	J039226		12/06/2017		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Roof Void - Board debris to ceiling void	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82008	J039226		12/06/2017		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Roof Void - Redundant board to ceiling void	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82009	J039226		12/06/2017		
#REF!	QAA	Craigavon Hospital	01	Textiles & Paper	Roof Void - Cloth to pipe bracket	Textiles & Paper	Chrysotile	Unsealed	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Medium Risk	7	29/09/2023	Identified	Medium Risk	82010	J039226	9302.2	29/09/2022	WHS	
#REF!	QAA	Craigavon Hospital	01	Textiles & Paper	Roof Void - Cloth to pipe bracket	Textiles & Paper	Chrysotile	Unsealed	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Medium Risk	7	29/09/2023	Identified	Medium Risk	82011	J039226	9302.2	29/09/2022	WHS	
#REF!	QAA	Craigavon Hospital	01	Textiles & Paper	Roof Void - Cloth to oixe brackets	Textiles & Paper	Chrysotile	Unsealed	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Medium Risk	7	29/09/2023	Identified	Medium Risk	82012	J039226	9302.2	29/09/2022	WHS	
#REF!	QAA	Craigavon Hospital	18	NO ASBESTOS	White vinyl floor tile	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82013	J039396	9724/1 7	05/09/2017	WHS	
#REF!	QAA	Craigavon Hospital	18	NO ASBESTOS	Grey vinyl floor tile	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82014	J039396	9724/1 7	05/09/2017	WHS	
#REF!	QAA	Craigavon Hospital	01	Debris	Ceiling tile debris to floor	Insulating Board	Amosite	Loose Asbestos Debris	High	Remove (Controlled Conditions)	New Incident	HSG227	Unchecked	High Risk	10	14/09/2017	Identified	High Risk	82113	J040354		25/05/2017		
#REF!	QAA	Craigavon Hospital	01	Debris	Ceiling tile debris to floor	Insulating Board	Amosite	Loose Asbestos Debris	High	Remove (Controlled Conditions)	New Incident	HSG227	Unchecked	High Risk	10	14/09/2017	Identified	High Risk	82114	J040354		25/05/2017		
#REF!	QAA	Craigavon Hospital	01	Fire Lining Board	Fire break	Cement Products	Chrysotile	Unsealed Cement	Low	Manage and monitor	New Incident	HSG227	Unchecked	Very Low Risk	4	14/09/2017	Identified	Very Low Risk	82115	J040354		25/05/2017		
#REF!	QAA	Craigavon Hospital	21	Woven Asbestos Textile	Cloth to oixe bracket	Textiles & Paper	Chrysotile	Unsealed	Medium	Remove (Controlled Conditions)	Review – No Change	HSG227	Unchecked	Medium Risk	8	24/03/2018	Identified	Medium Risk	82264	J041382	9814.1	01/08/2020	WH Stephens	
#REF!	QAA	Craigavon Hospital	21	NO ASBESTOS	Pipe Lagging	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82265	J041382	9326/1 7	20/04/2018	WHS	
#REF!	QAA	Craigavon Hospital	21	NO ASBESTOS	Debris to metal brack at high level	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82266	J041382	9326/1 7	20/04/2018	WHS	
#REF!	QAA	Craigavon Hospital	21	NO ASBESTOS	Debris to electric conduct	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82267	J041382	9326/1 7	20/04/2018	WHS	
#REF!	QAA	Craigavon Hospital	21	NO ASBESTOS	Debris to blue mikrofill box	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82268	J041382	9326/1 7	20/04/2018	WHS	
#REF!	QAA	Craigavon Hospital	21	NO ASBESTOS	Debris to boxing around valve	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82269	J041382	9326/1 7	20/04/2018	WHS	
#REF!	QAA	Craigavon Hospital	21	Woven Asbestos Textile	Cloth to pipe bracket	Textiles & Paper	Chrysotile	Unsealed	High	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	Medium Risk	9	18/04/2023	Identified	Medium Risk	82270	J041382	9302.2	17/10/2022	WHS	
#REF!	QAA	Craigavon Hospital	21	NO ASBESTOS	Residue to wall	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82271	J041382	9326/1 7	20/04/2018	WHS	
#REF!	QAA	Craigavon Hospital	21	NO ASBESTOS	Debris to pipe work	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82272	J041382	9326/1 7	20/04/2018	WHS	
#REF!	QAA	Craigavon Hospital	21	NO ASBESTOS	Debris to duct	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82273	J041382	9326/1 7	20/04/2018	WHS	
#REF!	QAA	Craigavon Hospital	21	NO ASBESTOS	Debris to floor	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82274	J041382	9326/1 7	20/04/2018	WHS	
#REF!	QAA	Craigavon Hospital	21	NO ASBESTOS	Debris to floor	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82275	J041382	9326/1 7	20/04/2018	WHS	
#REF!	QAA	Craigavon Hospital	21	NO ASBESTOS	Debris to window cill behind gas boilers	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82276	J041382	9326/1 7	20/04/2018	WHS	
#REF!	QAA	Craigavon Hospital	21	NO ASBESTOS	Residue to wall behind gas boilers	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82277	J041382	9326/1 7	20/04/2018	WHS	
#REF!	QAA	Craigavon Hospital	21	NO ASBESTOS	Residue to wall right hand side of gas boilers	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82278	J041382	9326/1 7	20/04/2018	WHS	
#REF!	QAA	Craigavon Hospital	21	NO ASBESTOS	Debris to pipe bracket window	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82279	J041382	9326/1 7	20/04/2018	WHS	
#REF!	QAA	Craigavon Hospital	21	NO ASBESTOS	Residue to wall left hand side of calorifier	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82280	J041382	9326/1 7	20/04/2018	WHS	
#REF!	QAA	Craigavon Hospital	21	NO ASBESTOS	Lagging to calorifier	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82281	J041382	9326/1 7	20/04/2018	WHS	
#REF!	QAA	Craigavon Hospital	21	NO ASBESTOS	Debris to floor at calorifier	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82282	J041382	9326/1 7	20/04/2018	WHS	
#REF!	QAA	Craigavon Hospital	21	NO ASBESTOS	Residue to wall behind calorifier 2	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82283	J041382	9326/1 7	20/04/2018	WHS	
#REF!	QAA	Craigavon Hospital	21	NO ASBESTOS	Residue to wall right hand saide of calorifier	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82284	J041382	9326/1 7	20/04/2018	WHS	
#REF!	QAA	Craigavon Hospital	21	NO ASBESTOS	Residue to rear wall in corner	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82285	J041382	9326/1 7	20/04/2018	WHS	
#REF!	QAA	Craigavon Hospital	21	NO ASBESTOS	Residue to corner of rear wall at high level	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82286	J041382	9326/1 7	20/04/2018	WHS	
#REF!	QAA	Craigavon Hospital	21	Dust	Residue to flange behind calorifier 2	Loose Asbestos	NO ASBESTOS	Unsealed Spray / Lagging /	Low	Remove (Controlled Conditions)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	22/12/2017	Identified	High Risk	82287	J041382	9302.2	20/04/2018	WHS	
#REF!	QAA	Craigavon Hospital	21	NO ASBESTOS	Debris to calorifier 2	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82288	J041382	9326/1 7	20/04/2018	WHS	
#REF!	QAA	Craigavon Hospital	21	NO ASBESTOS	Lagging to calorifier 2	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82289	J041382	9326/1 7	20/04/2018	WHS	

#REF!	QAA	Craigavon Hospital	21	Gaskets	Gasket to flange at calorifier 2	Composite Material	Chrysotile	Composite Material	Medium	Manage and monitor	Re-inspection	HSG227	Unchecked	Very Low Risk	4	17/10/2023	Identified	Very Low Risk	82291	J041382	[illegible]	17/10/2022	WHS
#REF!	QAA	Craigavon Hospital	21	Loose Asbestos	Residue to calorifier 2	Loose Asbestos	Chrysotile	Loose Asbestos Debris	Low/Medium Asbestos	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	High Risk	10	16/01/2023	Identified	High Risk	82292	J041382	[illegible]	17/10/2022	WHS
#REF!	QAA	Craigavon Hospital	21	NO ASBESTOS	Gasket to calorifier 2	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82293	J041382	9326/17	20/04/2018	WHS
#REF!	QAA	Craigavon Hospital	21	NO ASBESTOS	Gasket to calorifier 1	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82294	J041382	9326/17	20/04/2018	WHS
#REF!	QAA	Craigavon Hospital	21	NO ASBESTOS	Debris to metal pipe bracket	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82295	J041382	9326/17	20/04/2018	WHS
#REF!	QAA	Craigavon Hospital	21	NO ASBESTOS	Debris to cable trunking	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82296	J041382	9326/17	20/04/2018	WHS
#REF!	QAA	Craigavon Hospital	21	NO ASBESTOS	Debris to switch gear	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82297	J041382	9326/17	20/04/2018	WHS
#REF!	QAA	Craigavon Hospital	21	NO ASBESTOS	Debris to cable & trunking	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82298	J041382	9326/17	20/04/2018	WHS
#REF!	QAA	Craigavon Hospital	21	NO ASBESTOS	Debris to floor	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82299	J041382	9326/17	20/04/2018	WHS
#REF!	QAA	Craigavon Hospital	21	NO ASBESTOS	Debris to cables below duct on right hand side of wall	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82300	J041382	9326/17	20/04/2018	WHS
#REF!	QAA	Craigavon Hospital	21	NO ASBESTOS	Gasket residue	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82301	J041382	9326/17	20/04/2018	WHS
#REF!	QAA	Craigavon Hospital	21	NO ASBESTOS	Debris to concrete plinth	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82303	J041382	9326/17	20/04/2018	WHS
#REF!	QAA	Craigavon Hospital	21	NO ASBESTOS	Debris to concrete plinth	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82304	J041382	9326/17	20/04/2018	WHS
#REF!	QAA	Craigavon Hospital	21	NO ASBESTOS	Debris to concrete plinth	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82306	J041382	9326/17	20/04/2018	WHS
#REF!	QAA	Craigavon Hospital	21	NO ASBESTOS	Lagging to pipe work in duct left hand side of store	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82307	J041382	9326/17	20/04/2018	WHS
#REF!	QAA	Craigavon Hospital	21	NO ASBESTOS	Store wall board	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82309	J041382	9326/17	20/04/2018	WHS
#REF!	QAA	Craigavon Hospital	21	NO ASBESTOS	Store wall board	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82310	J041382	9326/17	20/04/2018	WHS
#REF!	QAA	Craigavon Hospital	21	NO ASBESTOS	Store ceiling board	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82312	J041382	9326/17	20/04/2018	WHS
#REF!	QAA	Craigavon Hospital	21	NO ASBESTOS	Debris to boxing around flange	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82313	J041382	9326/17	20/04/2018	WHS
#REF!	QAA	Craigavon Hospital	21	NO ASBESTOS	Debris to boxing around flange	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82314	J041382	9326/17	20/04/2018	WHS
#REF!	NAB	St.Lukes	28	Roof Sheet	Board between wall plate and roof	Cement Products	Chrysotile	Unsealed Cement	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Very Low Risk	4	02/03/2021	Identified	Very Low Risk	82317	J041887	[illegible]	03/01/2020	WHS
#REF!	NAB	St.Lukes	28	NO ASBESTOS	Cavity vent liner	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82318	J041887		26/09/2017	
#REF!	NAB	St.Lukes	28	NO ASBESTOS	Debris to furniture	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82319	J041887		26/09/2017	
#REF!	NAB	St.Lukes	28	Loose Asbestos	Debris to floor	Loose Asbestos	Chrysotile	Loose Asbestos Debris	High	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	High Risk	10	04/03/2021	Identified	High Risk	82320	J041887	[illegible]	03/01/2020	WHS
#REF!	NAB	St.Lukes	28	NO ASBESTOS	Debris to shelf	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82321	J041887		26/09/2017	
#REF!	NAB	St.Lukes	28	Roof Sheet	Cement roof sheeting	Cement Products	Chrysotile	Unsealed Cement	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Very Low Risk	4	04/03/2021	Identified	Very Low Risk	82322	J041887	[illegible]	03/01/2020	WHS
#REF!	NAB	St.Lukes	28	Roof Sheet	Cement roof sheeting	Cement Products	Chrysotile	Unsealed Cement	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Very Low Risk	4	02/03/2021	Identified	Very Low Risk	82323	J041887	[illegible]	03/01/2020	WHS
#REF!	NAB	St.Lukes	28	Roof Sheet	Cement roof sheeting	Cement Products	Chrysotile	Unsealed Cement	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Very Low Risk	4	04/03/2021	Previously Identified	Very Low Risk	82324		[illegible]	03/01/2020	WHS
#REF!	NAB	St.Lukes	28	Roof Sheet	Cement roof sheeting	Cement Products	Chrysotile	Unsealed Cement	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Very Low Risk	4	02/03/2021	Stronnly Presumed Similar to	Very Low Risk	82325		[illegible]	03/01/2020	WHS
#REF!	NAB	St.Lukes	28	Roof Sheet	Cement roof sheeting	Cement Products	Chrysotile	Unsealed Cement	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Very Low Risk	4	04/03/2021	Stronnly Presumed Similar to	Very Low Risk	82326		[illegible]	03/01/2020	WHS
#REF!	NAB	St.Lukes	28	Roof Sheet	Cement roof sheet	Cement Products	Chrysotile	Unsealed Cement	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Very Low Risk	4	04/03/2021	Stronnly Presumed Similar to	Very Low Risk	82327		[illegible]	03/01/2020	WHS
#REF!	NAB	St.Lukes	28	Roof Sheet	Cement roof sheet	Cement Products	Chrysotile	Unsealed Cement	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Very Low Risk	4	02/03/2021	Stronnly Presumed Similar to	Very Low Risk	82328		[illegible]	03/01/2020	WHS
#REF!	NAB	St.Lukes	28	Gaskets	Gasket in envelope on shelf	Textiles & Paper	Chrysotile	Other Materials	Low	Remove	Re-inspection	HSG227	Unchecked	Medium Risk	7	04/03/2021	Identified	Medium Risk	82329	J041887	[illegible]	03/01/2020	WHS
#REF!	NAB	St.Lukes	28	Woven Asbestos Textile	Cloth ring on shelf	Textiles & Paper	Chrysotile	Unsealed Rope	Low	Remove	Re-inspection	HSG227	Unchecked	Low Risk	6	04/03/2021	Identified	Low Risk	82330	J041887	[illegible]	03/01/2020	WHS
#REF!	NAB	St.Lukes	28	Gaskets	Gasket debris to floor	Textiles & Paper	Chrysotile	Other Materials	Low	Remove	Re-inspection	HSG227	Unchecked	Medium Risk	7	04/03/2021	Identified	Medium Risk	82331	J041887	[illegible]	03/01/2020	WHS
#REF!	NAB	St.Lukes	28	Debris	Cement debris to floor	Cement Products	Chrysotile	Unsealed Cement	High	Remove	Re-inspection	HSG227	Unchecked	Low Risk	6	04/03/2021	Identified	Low Risk	82332	J041887	[illegible]	03/01/2020	WHS
#REF!	NAB	St.Lukes	28	Loose Asbestos	Debris to floor	Loose Asbestos	Chrysotile	Loose Asbestos Debris	High	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	High Risk	10	04/03/2021	Identified	High Risk	82333	J041887	[illegible]	03/01/2020	WHS
#REF!	NAB	St.Lukes	28	NO ASBESTOS	Debris to floor	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82334	J041887		26/09/2017	
#REF!	NAB	St.Lukes	28	NO ASBESTOS	Debris to floor	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82335	J041887		26/09/2017	
#REF!	NAB	St.Lukes	28	Gaskets	Gasket on shelf	Textiles & Paper	Chrysotile	Other Materials	Low	Remove	Re-inspection	HSG227	Unchecked	Medium Risk	7	02/03/2021	Identified	Medium Risk	82336	J041887	[illegible]	03/01/2020	WHS
#REF!	NAB	St.Lukes	28	Panel	Fiber glass to redundant switch on [illegible]	Cement Products	Chrysotile	Unsealed Cement	Low	Remove	Re-inspection	HSG227	Unchecked	Very Low Risk	4	02/03/2021	Identified	Very Low Risk	82337	J041887	[illegible]	03/01/2020	WHS
#REF!	NAB	St.Lukes	28	Gaskets	Redundant gaskes in box adjacent door to room 002	Textiles & Paper	Chrysotile	Other Materials	Low	Remove	Re-inspection	HSG227	Unchecked	Medium Risk	7	02/03/2021	Identified	Medium Risk	82338	J041887	9811/19	03/01/2020	WHS
#REF!	NAB	St.Lukes	28	NO ASBESTOS	Debris to box adjacent door to room 002	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82339	J041887		26/09/2017	
#REF!	NAB	St.Lukes	28	NO ASBESTOS	Debris to floor	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82340	J041887		26/09/2017	
#REF!	NAB	St.Lukes	28	Loose Asbestos	Debris to floor	Loose Asbestos	Chrysotile	Loose Asbestos Debris	High	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	High Risk	10	02/03/2021	Identified	High Risk	82341	J041887	[illegible]	03/01/2020	WHS
#REF!	NAB	St.Lukes	28	NO ASBESTOS	DPC	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82342	J041887		26/09/2017	
#REF!	RAE	Drumglass Site	02	NO ASBESTOS	Felt packer below window cill	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82343	J041986	9506/18	31/01/2019	WHS
#REF!	RAE	Drumglass Site	02	NO ASBESTOS	Felt packer below window cill	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82344	J041986	9506/18	31/01/2019	WHS
#REF!	RAE	Drumglass Site	02	NO ASBESTOS	Felt packer below window cill	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82345	J041986	9506/18	31/01/2019	WHS
#REF!	NAB	St.Lukes	20	Dame Proof Course	DPC to wall LHS of door	Composite Material	Chrysotile	Composite Material	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Very Low Risk	3	24/02/2021	Identified	Very Low Risk	82346	J042089	[illegible]	05/12/2019	WHS
#REF!	NAB	St.Lukes	20	Cavity Closer	Cavity closer to wall RHS of door	Cement Products	Chrysotile	Unsealed Cement	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Very Low Risk	4	24/02/2021	Identified	Very Low Risk	82347	J042089	[illegible]	05/12/2019	WHS
#REF!	NAB	St.Lukes	20	Thermal Insulation	Residue to wall behind pipe work RHS of door	Thermal Insulation	Crocidolite / Amosite	Unsealed Spray / Lagging / Dust Debris	High	Restrict access and remove under fully controlled	Re-inspection	HSG227	Unchecked	High Risk	12	25/05/2020	Identified	High Risk	82348	J042089	9811/19	05/12/2019	WHS
#REF!	NAB	St.Lukes	20	Thermal Insulation	Residue to wall behind pipe work RHS of door	Thermal Insulation	Crocidolite / Amosite	Unsealed Spray / Lagging / Dust Debris	High	Restrict access and remove under fully controlled	Re-inspection	HSG227	Unchecked	High Risk	12	25/05/2020	Identified	High Risk	82349	J042089	9811/16	05/12/2020	WHS
#REF!	NAB	St.Lukes	20	Thermal Insulation	Residue to wall beside fire alarm panel	Thermal Insulation	Crocidolite / Amosite	Unsealed Spray / Lagging / Dust Debris	High	Restrict access and remove under fully controlled	Re-inspection	HSG227	Unchecked	High Risk	12	25/05/2020	Identified	High Risk	82350	J042089	9811/19	05/12/2019	WHS
#REF!	NAB	St.Lukes	20	Thermal Insulation	Residue to corner of RHS and front wall	Thermal Insulation	Crocidolite / Amosite	Unsealed Spray / Lagging / Dust Debris	High	Restrict access and remove under fully controlled	Re-inspection	HSG227	Unchecked	High Risk	12	25/05/2020	Identified	High Risk	82351	J042089	9811/19	05/12/2020	WHS
#REF!	NAB	St.Lukes	20	Thermal Insulation	Residue to wall below fire alarm panel	Thermal Insulation	Crocidolite	Unsealed Spray / Lagging / Dust Debris	High	Restrict access and remove under fully controlled	Re-inspection	HSG227	Unchecked	High Risk	12	25/05/2020	Identified	High Risk	82352	J042089	9811/16	05/12/2020	WHS
#REF!	NAB	St.Lukes	20	Loose Asbestos	Debris to top of fire alarm panel	Loose Asbestos	Crocidolite	Loose Asbestos Debris	High	Restrict access and remove under fully controlled	Re-inspection	HSG227	Unchecked	High Risk	12	25/05/2020	Identified	High Risk	82353	J042089	9811/19	05/12/2019	WHS
#REF!	NAB	St.Lukes	20	NO ASBESTOS	Debris to floor behind calorifier	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82354	J042089		03/10/2017	
#REF!	NAB	St.Lukes	20	NO ASBESTOS	Residue to low level pipe work behind calorifier	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82355	J042089		03/10/2017	
#REF!	NAB	St.Lukes	20	NO ASBESTOS	Debris to floor at concrete plinth	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82356	J042089		03/10/2017	
#REF!	NAB	St.Lukes	20	Tape	Residue to wll above pin board	Textiles & Paper	Amosite	Unsealed Spray / Lagging / Dust Debris	High	Restrict access and remove under fully controlled	Re-inspection	HSG227	Unchecked	High Risk	10	25/05/2020	Identified	High Risk	82357	J042089	9811/19	05/12/2020	WHS
#REF!	NAB	St.Lukes	20	Thermal Insulation	Residue to redundant pipe bracket	Thermal Insulation	Crocidolite / Amosite	Unsealed Spray / Lagging / Dust Debris	High	Restrict access and remove under fully controlled	Re-inspection	HSG227	Unchecked	High Risk	12	25/05/2020	Identified	High Risk	82358	J042089	9811/16	05/12/2019	WHS
#REF!	NAB	St.Lukes	20	Thermal Insulation	Residue to RHS wall	Thermal Insulation	Crocidolite / Amosite	Unsealed Spray / Lagging / Dust Debris	High	Restrict access and remove under fully controlled	Re-inspection	HSG227	Unchecked	High Risk	12	25/05/2020	Identified	High Risk	82359	J042089	9811/19	05/12/2019	WHS
#REF!	NAB	St.Lukes	20	Thermal Insulation	Residue to RHS wall	Thermal Insulation	Crocidolite / Amosite	Unsealed Spray / Lagging / Dust Debris	High	Restrict access and remove under fully controlled	Re-inspection	HSG227	Unchecked	High Risk	12	25/05/2020	Identified	High Risk	82360	J042089	9811/19	05/12/2019	WHS
#REF!	NAB	St.Lukes	20	Thermal Insulation	Residue to rear wall RHS of pipe work	Thermal Insulation	Crocidolite / Amosite	Unsealed Spray / Lagging / Dust Debris	High	Restrict access and remove under fully controlled	Re-inspection	HSG227	Unchecked	High Risk	12	25/05/2020	Identified	High Risk	82361	J042089	9811/16	05/12/2019	WHS
#REF!	NAB	St.Lukes	20	Thermal Insulation	Residue to rear wall LHS of pipe work	Thermal Insulation	Crocidolite / Amosite	Unsealed Spray / Lagging / Dust Debris	High	Restrict access and remove under fully controlled	Re-inspection	HSG227	Unchecked	High Risk	12	25/05/2020	Identified	High Risk	82362	J042089	9811/19	05/12/2019	WHS
#REF!	NAB	St.Lukes	20	Thermal Insulation	Residue to rear wall at low level	Thermal Insulation	Crocidolite / Amosite	Unsealed Spray / Lagging / Dust Debris	High	Restrict access and remove under fully controlled	Re-inspection	HSG227	Unchecked	High Risk	12	25/05/2020	Identified	High Risk	82363	J042089	9811/19	05/12/2019	WHS
#REF!	NAB	St.Lukes	20	Thermal Insulation	Residue to rear wall at low level	Thermal Insulation	Amosite	Unsealed Spray / Lagging / Dust Debris	High	Restrict access and remove under fully controlled	Re-inspection	HSG227	Unchecked	High Risk	11	25/05/2020	Identified	High Risk	82364	J042089	9811/16	05/12/2019	WHS
#REF!	NAB	St.Lukes	20	Thermal Insulation	Residue to rear wall at low level	Thermal Insulation	Amosite	Unsealed Spray / Lagging / Dust Debris	High	Restrict access and remove under fully controlled	Re-inspection	HSG227	Unchecked	High Risk	11	25/05/2020	Identified	High Risk	82365	J042089	9811/19	05/12/2019	WHS
#REF!	NAB	St.Lukes	20	Thermal Insulation	Residue to LHS wall	Thermal Insulation	Amosite	Unsealed Spray / Lagging / Dust Debris	High	Restrict access and remove under fully controlled	Re-inspection	HSG227	Unchecked	High Risk	11	25/05/2020	Identified	High Risk	82366	J042089	9811/19	05/12/2019	WHS
#REF!	NAB	St.Lukes	20	Thermal Insulation	Residue to LHS wall	Thermal Insulation	Amosite	Unsealed Spray / Lagging / Dust Debris	High	Restrict access and remove under fully controlled	Re-inspection	HSG227	Unchecked	High Risk	11	25/05/2020	Identified	High Risk	82367	J042089	9811/16	05/12/2019	WHS
#REF!	NAB	St.Lukes	20	Damp Proof Course	DPC to rear wall	Composite Material	Chrysotile	Composite Material	Low	Restrict access and remove under fully controlled	Re-inspection	HSG227	Unchecked	Very Low Risk	3	24/02/2021	Identified	Very Low Risk	82368	J042089	9811/19	05/12/2019	WHS
#REF!	NAB	St.Lukes	20	Thermal Insulation	Residue to RHS wall	Thermal Insulation	Crocidolite	Unsealed Spray / Lagging / Dust Debris	High	Restrict access and remove under fully controlled	Re-inspection	HSG227	Unchecked	High Risk	12	25/05/2020	Identified	High Risk	82369	J042089	9811/19	05/12/2019	WHS
#REF!	NAB	St.Lukes	20	Thermal Insulation	Residue to rear wall LHS of switchgear	Thermal Insulation	Crocidolite / Amosite	Unsealed Spray / Lagging / Dust Debris	High	Restrict access and remove under fully controlled	Re-inspection	HSG227	Unchecked	High Risk	12	25/05/2020	Identified	High Risk	82370	J042089	9811/16	05/12/2019	WHS
#REF!	NAB	St.Lukes	20	NO ASBESTOS	Debris to floor	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82371	J042089		03/10/2017	
#REF!	NAB	St.Lukes	20	Loose Asbestos	Residue to red bracket in ceilino	Loose Asbestos	Amosite	Loose Asbestos Debris	High	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	High Risk	11	24/02/2021	Identified	High Risk	82372	J042089	[illegible]	05/12/2019	WHS
#REF!	NAB	St.Lukes	20	NO ASBESTOS	Debris to floor in middle of room	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82373	J042089		03/10/2017	
#REF!	NAB	St.Lukes	20	NO ASBESTOS	Debris to floor below boilers	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82374	J042089		03/10/2017	
#REF!	NAB	St.Lukes	20	Thermal Insulation	Residue to wall beside ladders	Thermal Insulation	Crocidolite / Amosite	Unsealed Spray / Lagging / [illegible]	High	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	High Risk	12	25/05/2020	Identified	High Risk	82375	J042089	[illegible]	05/12/2019	WHS
#REF!	NAB	St.Lukes	20	Thermal Insulation	Residue to otse work on LHS wall	Thermal Insulation	Crocidolite / Amosite	[illegible]	High	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	High Risk	12	25/05/2020	Identified	High Risk	82376	J042089	[illegible]	05/12/2019	WHS
#REF!	NAB	St.Lukes	20	Thermal Insulation	Residue to rear wall in LHS corner at high level	Thermal Insulation	Crocidolite / Amosite	Unsealed Spray / Lagging / Dust Debris	High	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	High Risk	12	25/05/2020	Identified	High Risk	82377	J042089	9811/19	05/12/2019	WHS
#REF!	NAB	St.Lukes	20	Thermal Insulation	Residue to pipe at low level to front of water tank	Thermal Insulation	Crocidolite / Amosite	Unsealed Spray / Lagging / Dust Debris	High	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	High Risk	12	25/05/2020	Identified	High Risk	82378	J042089	9811/19	05/12/2019	WHS
#REF!	NAB	St.Lukes	20	NO ASBESTOS	Gasket to pipe work at front of water tank	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82379	J042089		03/10/2017	
#REF!	NAB	St.Lukes	20	NO ASBESTOS	Ceiling board	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82380	J042089		03/10/2017	

#REF!	NAB	St Lukes	20	NO ASBESTOS	Bitumen to rear window head	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82381	J042089		03/10/2017			
#REF!	NAB	St Lukes	20	Cavity Closer	Cavity closer to rear window head	Cement Products	Chrysotile	Unsealed Cement	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Very Low Risk	4	24/02/2021	Identified	Very Low Risk	82382	J042089	9501/18	05/12/2019	WHS			
#REF!	NAB	St Lukes	20	Cavity Closer	Cavity closer to front window head	Cement Products	Chrysotile	Unsealed Cement	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Very Low Risk	4	24/02/2021	Identified	Very Low Risk	82383	J042089	9501/18	05/12/2019	WHS			
#REF!	NAB	St Lukes	20	NO ASBESTOS	Bitumen to front window head	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82384	J042089		03/10/2017			
#REF!	QAA	Craigavon Hospital	01	Pipe Insulation	Ceiling void - cloth to pipe bracket	Textiles & Paper	Chrysotile	Unsealed	Medium	Programme for removal	Re-inspection	HSG227	Unchecked	Medium Risk	8	16/09/2023	Identified	Medium Risk	82414	J042088	9326/27	16/09/2022	WHS			
#REF!	QAA	Craigavon Hospital	01	Pipe Insulation	Ceiling void - Cloth to pipe work	Textiles & Paper	Chrysotile	Unsealed	Low	Programme for removal	Re-inspection	HSG227	Unchecked	Medium Risk	7	16/09/2023	Identified	Medium Risk	82415	J042088	9326/27	16/09/2022	WHS			
#REF!	QAA	Craigavon Hospital	01	Pipe Brackets	Ceiling void - Cloth to pipe bracket	Textiles & Paper	Chrysotile	Unsealed	Low	Programme for removal	Re-inspection	HSG227	Unchecked	Medium Risk	7	16/09/2023	Identified	Medium Risk	82416	J042088	9326/27	16/09/2022	WHS			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Ceiling Void - Fire break to exterior face	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82417	J042088		03/10/2017			
#REF!	QAA	Craigavon Hospital	01	Mastic	Ceiling void - Mastic to vent trunkino	Composite Material	Chrysotile	Composite Material	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Very Low Risk	3	16/09/2023	Identified	Very Low Risk	82418	J042088	9326/27	16/09/2022	WHS			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Ceiling void - Bitumen to ceiling	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82419	J042088		03/10/2017			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Ceiling void - Debris to beam	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82420	J042088		03/10/2017			
#REF!	QAA	Craigavon Hospital	01	Debris Material	Ceiling void - Debris to roof void	Loose Asbestos	Chrysotile	Loose Asbestos Debris	Loose asbestos	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	High Risk	10	16/09/2023	Identified	High Risk	82421	J042088	9326/27	16/09/2022	WHS			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Ceiling void - fire break within roof void	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82422	J042088		03/10/2017			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Ceiling void - Felt debris	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82423	J042088		03/10/2017			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Ceiling void - Bitumen above metal shuttering	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82424	J042088		03/10/2017			
#REF!	QAA	Craigavon Hospital	01	Gaskets	Ceilino void - Gasket to flanoe	Composite Material	Chrysotile	Composite Material	Medium	Manage and monitor	Re-inspection	HSG227	Unchecked	Very Low Risk	4	16/09/2023	Identified	Very Low Risk	82425	J042088	9326/27	16/09/2022	WHS			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Sink pad	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82426	J042088		03/10/2017			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Grey VFT	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82427	J042088		03/10/2017			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	White VFT	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82428	J042088		03/10/2017			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Cove skirting	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82429	J042088		03/10/2017			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Green VFT	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82430	J042088		03/10/2017			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	White VFT	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82431	J042088		03/10/2017			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Blue VFT	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82432	J042088		03/10/2017			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Beige VFT	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82433	J042088		03/10/2017			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Light Grey VFT	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82434	J042088		03/10/2017			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Brown VFT	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82435	J042088		03/10/2017			
#REF!	QAA	Craigavon Hospital	01	Floor Tile and Bitumen Adhesive	VFT and bitumen	Composite Material	Chrysotile	Composite Material	Medium	Manage and monitor	Re-inspection	HSG227	Unchecked	Very Low Risk	4	16/09/2023	Identified	Very Low Risk	82436	J042088	9326/27	16/09/2022	WHS			
#REF!	QAA	Craigavon Hospital	01	Board	Board to electric cupboard	Insulating Board	Amosite/Chrysotile	Unsealed Amosite Insulation	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Medium Risk	7	16/09/2023	Identified	Medium Risk	82437	J042088	9326/27	16/09/2022	WHS			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Bitumen to floor	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82438	J042088		03/10/2017			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Ceiling void - Felt debris to roof void	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82439	J042088		03/10/2017			
#REF!	OAA	Craigavon Hospital	01									Error Entry	HSG227	Unchecked		0				82440						
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Paper lining to wall panels	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Correcting Previous Data	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82441	J042088		03/10/2017			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Debris to AC Unit	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Correcting Previous Data	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82442	J042088		03/10/2017			
#REF!	OAA	Craigavon Hospital	01	Mastic	Mastic to vent trunkino	Composite Material	Chrysotile	Composite Material	Low	Manage and monitor	Correcting Previous Data	HSG227	Unchecked	Very Low Risk	3	12/10/2018	Identified	Very Low Risk	82443	J042088		03/10/2017				
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Residue to vent trunking	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Correcting Previous Data	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82444	J042088		03/10/2017			
#REF!	OAA	Craigavon Hospital	01	Roze Seal	Cloth seal to ioint in vent trunkino	Textiles & Paper	Chrysotile	Unsealed Roze	Low	Manage and monitor	Correcting Previous Data	HSG227	Unchecked	Low Risk	6	12/10/2018	Identified	Low Risk	82445	J042088		03/10/2017				
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Adhesive to vent trunking	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Correcting Previous Data	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82446	J042088		03/10/2017			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Debris to floor beside AC unit	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Correcting Previous Data	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82447	J042088		03/10/2017			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Debris to concreete plinth of AC unit	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Correcting Previous Data	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82448	J042088		03/10/2017			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Debris to floor	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Correcting Previous Data	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82449	J042088		03/10/2017			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Debris to floor	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Correcting Previous Data	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82450	J042088		03/10/2017			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Debris to floor	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Correcting Previous Data	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82451	J042088		03/10/2017			
#REF!	QAA	Craigavon Hospital	01	Bitumen Felt	Bitumen around skylight	Composite Material	Chrysotile	Unsealed	Low	Manage and monitor	Correcting Previous Data	HSG227	Unchecked	Low Risk	6	12/10/2018	Identified	Low Risk	82452	J042088		03/10/2017				
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Debris to concrete plinth of AC unit	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Correcting Previous Data	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82453	J042088		03/10/2017			
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Insulation behind T & G panelling	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82454	J042186	9506/18	20/03/2019	WHS		
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Paper to plasterboard behind insulation to external facade	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82455	J042186	9506/18	20/03/2019	WHS		
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Fascia board to rear of building	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82456	J042186	9506/18	20/03/2019	WHS		
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Soffit board	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82457	J042186	9506/18	20/03/2019	WHS		
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Wall panel to rear elevation	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82458	J042186	9506/18	20/03/2019	WHS		
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Wall panel to rear elevation	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82459	J042186	9506/18	20/03/2019	WHS		
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Wall panel to rear elevation	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82460	J042186	9506/18	20/03/2019	WHS		
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Wall panel to rear elevation	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82461	J042186	9506/18	20/03/2019	WHS		
#REF!	RAA	South Tyrone Hospital	06	NO ASBESTOS	DPC	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82612	J043170		09/11/2017			
#REF!	RAA	South Tyrone Hospital	06	NO ASBESTOS	Soffit board	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82613	J043170		09/11/2017			
#REF!	RAA	South Tyrone Hospital	06	NO ASBESTOS	Roofing felt	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82614	J043170		09/11/2017			
#REF!	RAA	South Tyrone Hospital	09	NO ASBESTOS	Board to canopy outside A-008	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82615	J043181	9506/18	12/05/2018	WHS		
#REF!	RAA	South Tyrone Hospital	16	NO ASBESTOS	Board lining to wall	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82616	J043184	9506/18	12/05/2018	WHS		
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Board lining to lower LHS wall	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82617	J043375	9506/18	12/05/2018	WHS		
#REF!	QCC	Dromore Health Clinic	01	NO ASBESTOS	Window infill panel outside room 009	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82640	BA8447	9326/17	04/04/2018	WHS		
#REF!	QCC	Dromore Health Clinic	01	NO ASBESTOS	Window infill panel outside room 013	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82641	BA8447	9326/17	04/04/2018	WHS		
#REF!	QCC	Dromore Health Clinic	01	NO ASBESTOS	Window infill panel outside room 017	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82642	BA8447	9326/17	04/04/2018	WHS		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Vinyl floor covering	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82643	J043376		20/11/2017			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Green floor tile	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82644	J043376		20/11/2017			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Light beige floor tile	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82645	J043376		20/11/2017			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Dark beige floor tile	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82646	J043376		20/11/2017			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	White floor tile	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82647	J043376		20/11/2017			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Vinyl to threshold	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82648	J043376		20/11/2017			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Vinyl floor covering below bath	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82649	J043376		20/11/2017			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Hair felt packer to foot of bath	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82650	J043376		20/11/2017			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Ceiling tile	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82651	J043376		20/11/2017			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Brown floor tile	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82652	J043376		20/11/2017			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Grey floor tile	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82653	J043376		20/11/2017			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	White floor tile	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82654	J043376		20/11/2017			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Wall panel	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82655	J043376		20/11/2017			
#REF!	QLA	Burnside Family Centre	01	NO ASBESTOS	Debris to roof void	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82662	J043353	9327/17	04/11/2018	WH Stpehens		
#REF!	QLA	Burnside Family Centre	01	NO ASBESTOS	Debris to roof void	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82663	J043353	9327/17	04/11/2018	WH Stpehens		
#REF!	QLA	Burnside Family Centre	01	NO ASBESTOS	Debris to roof void	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82664	J043353	9327/17	04/11/2018	WH Stpehens		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Beige vinyl floor tile	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82714	J043559		24/11/2017			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	White vinyl floor tile	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82715	J043559		16/11/2017			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Green vinyl floor tile	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82716	J043559		16/11/2017			

#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Blue vinyl floor tile	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82717	J043559		16/11/2017			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Grey vinyl floor tile	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82718	J043559		06/11/2017			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Dark green	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82719	J043559		16/11/2017			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Brown vinyl floor tile	NO ASBESTOS	NO ASBESTOS				No action required	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82720	J043559		16/11/2017			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Dark green vinyl floor tile	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Correcting previous data entry error	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82721	J043559		16/11/2017			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Cover skirting	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82722	J043559		16/11/2017			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Cream vinyl floor tile	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82723	J012449		15/12/2017			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Cream vinyl floor tile	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82724	J012449		15/12/2017			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Beige vinyl floor tile	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82725	J012449		15/12/2017			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Brown vinyl floor tile	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82726	J012449		15/12/2017			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Light blue vinyl floor tile	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82727	J012449		15/12/2017			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Dark blue vinyl floor tile	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82728	J012449		15/12/2017			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Turquoise vinyl floor tile	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82729	J012449		15/12/2017			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Grey vinyl floor tiles	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82730	J012449		15/12/2017			
#REF!	QAA	Craigavon Hospital	01	Floor Tile and Bitumen Adhesive	Brown vinyl floor tile and bitumen	Composite Material	Chrysotile	Composite Material	Minor damage of		Remove	Re-inspection	HSG227	Unchecked	Very Low Risk	3	16/09/2023	Identified	Very Low Risk	82731	J012449		16/09/2022	WHS		
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Debris to vent trunking	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82733	J043169		9509/18	12/05/2018	WHS	
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Debris to vent trunking (high level) adjacent vacuum plant room	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82734	J043169		9509/18	12/05/2018	WHS	
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Debris to switch gear (Thomas Hennins & Co)	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82735	J043169		9509/18	12/05/2018	WHS	
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Debris to trench	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82736	J043169		9509/18	12/05/2018	WHS	
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Debris to trench	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82737	J043169		9509/18	12/05/2018	WHS	
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Residue to wall	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82738	J043169		9509/18	12/05/2018	WHS	
#REF!	RAA	South Tyrone Hospital	17	Loose Asbestos	Residue to left hand side wall	Loose Asbestos	Amosite/Chrysotile	Unsealed Spray / Lagging /	High		Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	High Risk	11	13/12/2023	Identified	High Risk	82739	J043169		9302/22	13/12/2022	WHS	
#REF!	RAA	South Tyrone Hospital	17	Loose Asbestos	Residue to left hand side wall	Loose Asbestos	Amosite/Chrysotile	Unsealed Spray / Lagging /	High		Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	High Risk	11	13/12/2023	Identified	High Risk	82740	J043169		9302/22	13/12/2022	WHS	
#REF!	RAA	South Tyrone Hospital	17	Loose Asbestos	Residue to left hand side wall	Loose Asbestos	Amosite/Chrysotile	Unsealed Spray / Lagging /	High		Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	High Risk	11	13/12/2023	Identified	High Risk	82741	J043169		9302/22	13/12/2022	WHS	
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Residue to rear left hand side corner adjacent door to olenum	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82742	J043169		9509/18	12/05/2018	WHS	
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Packer to door frame of plenum	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82743	J043169		9509/18	12/05/2018	WHS	
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Lagging to pipe work	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82744	J043169		9509/18	12/05/2018	WHS	
#REF!	RAA	South Tyrone Hospital	17	Loose Asbestos	Residue to rear wall	Loose Asbestos	Amosite/Chrysotile	Unsealed Spray / Lagging /	High		Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	High Risk	11	13/12/2023	Identified	High Risk	82745	J043169		9302/22	13/12/2022	WHS	
#REF!	RAA	South Tyrone Hospital	17	Loose Asbestos	Debris to floor adjacent olenum door	Loose Asbestos	Amosite/Chrysotile	Unsealed Spray / Lagging /	High		Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	High Risk	11	13/12/2023	Identified	High Risk	82746	J043169		9302/22	13/12/2022	WHS	
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Paper membrane to plinth below ventilation trunking	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82747	J043169		9509/18	12/05/2018	WHS	
#REF!	RAA	South Tyrone Hospital	17	Loose Asbestos	Debris between plinths to ventilation trunkino	Loose Asbestos	Amosite/Chrysotile	Unsealed Spray / Lagging / Dust Debris	High		Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	High Risk	11	13/12/2023	Identified	High Risk	82748	J043169		9302/22	13/12/2022	WHS	
#REF!	RAA	South Tyrone Hospital	17	Rope Seal	Rope below ventilation plant	Textiles & Paper	Chrysotile	Unsealed Rope	Low		No further action required (No Asbestos Detected)	Re-inspection	HSG227	Unchecked	Low Risk	6	13/12/2023	Identified	Low Risk	82749	J043169		9302/22	13/12/2022	WHS	
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Debris to floor of duct riser	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82750	J043169		9509/18	12/05/2018	WHS	
#REF!	RAA	South Tyrone Hospital	17	Rope Seal	Cloth below ventilation olant to olenth	Textiles & Paper	Chrysotile	Unsealed Rope	Low		Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	Low Risk	6	13/12/2023	Identified	Low Risk	82751	J043169		9302/22	13/12/2022	WHS	
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Debris to plinth wall below extract fan No. 18	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82752	J043169		9509/18	12/05/2018	WHS	
#REF!	RAA	South Tyrone Hospital	17	Loose Asbestos	Debris at base of extract fan no.18	Loose Asbestos	Amosite/Chrysotile	Unsealed Spray / Lagging /	High		Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	High Risk	11	13/12/2023	Identified	High Risk	82753	J043169		9302/22	13/12/2022	WHS	
#REF!	RAA	South Tyrone Hospital	17	Loose Asbestos	Debris to floor at base of asbestos fan	Loose Asbestos	Amosite/Chrysotile	Unsealed Spray / Lagging /	High		Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	High Risk	11	13/12/2023	Identified	High Risk	82754	J043169		9302/22	13/12/2022	WHS	
#REF!	RAA	South Tyrone Hospital	17	Loose Asbestos	Debris to wall at rear of extract No.18 & 19	Loose Asbestos	Amosite/Chrysotile	Unsealed Spray / Lagging / Dust Debris	High		Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	High Risk	11	13/12/2023	Identified	High Risk	82755	J043169		9302/22	13/12/2022	WHS	
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Debris to concrete plinth below ventilation olant	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82756	J043169		9509/18	12/05/2018	WHS	
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Paper debris below DPU 1 extract fan	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82757	J043169		9509/18	12/05/2018	WHS	
#REF!	RAA	South Tyrone Hospital	17	Loose Asbestos	Debris to concrete plinth below ventilation	Loose Asbestos	Amosite/Chrysotile	Unsealed Spray / Lagging / Dust Debris	High		Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	High Risk	11	09/03/2021	Identified	High Risk	82758	J043169		9811/19	19/12/2019	WHS	
#REF!	RAA	South Tyrone Hospital	17	Loose Asbestos	Residue to wall at high level in rear RHS corner	Loose Asbestos	Amosite/Chrysotile	Unsealed Spray / Lagging / Dust Debris	High		Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	High Risk	11	13/12/2023	Identified	High Risk	82759	J043169		9302/22	13/12/2022	WHS	
#REF!	RAA	South Tyrone Hospital	17	Loose Asbestos	Residue to wall at high level in rear RHS corner	Loose Asbestos	Amosite/Chrysotile	Unsealed Spray / Lagging / Dust Debris	High		Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	High Risk	11	13/12/2023	Identified	High Risk	82760	J043169		9302/22	13/12/2022	WHS	
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Board to wall at RHS of entrance	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82761	J043169		9509/18	12/05/2018	WHS	
#REF!	RAA	South Tyrone Hospital	17	Loose Asbestos	Debris to floor of duct (plenum)	Loose Asbestos	NO ASBESTOS	Unsealed Spray / Lagging / Dust Debris	High		No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	24/07/2018	Identified	Asbestos Removed	82762	J043169		9509/18	12/05/2018	WHS	
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Debris to intake duct	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82763	J043169		9509/18	12/05/2018	WHS	
#REF!	RAA	South Tyrone Hospital	17	Loose Asbestos	Debris to floor of extract duct	Loose Asbestos	NO ASBESTOS	Unsealed Spray / Lagging / Dust Debris	High		No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	24/07/2018	Identified	Asbestos Removed	82764	J043169		9509/18	12/05/2018	WHS	
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Paper membrane to brick polinth below induction motor olant	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82765	J043169		9509/18	12/05/2018	WHS	
#REF!	RAA	South Tyrone Hospital	17	Rope Seal	Repair around pipe work adjacent water tanks	Textiles & Paper	Chrysotile	Unsealed Rope	Low		Remove	Re-inspection	HSG227	Unchecked	Low Risk	6	14/12/2023	Identified	Low Risk	82766	J043169		9302/22	14/12/2022	WHS	
#REF!	RAA	South Tyrone Hospital	17	Loose Asbestos	Debris to floor of duct	Loose Asbestos	NO ASBESTOS	Unsealed Spray / Lagging / Dust Debris	High		No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0	24/07/2018	Identified	Asbestos Removed	82767	J043169		9509/18	12/05/2018	WHS	
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Debris to DPU 2 air handling unit	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82768	J002919		9509/18	12/05/2018	WHS	
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Debris to duct of DPU 2 AHU (after filter)	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82769	J002919		9509/18	12/05/2018	WHS	
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Debris to duct of DPU 2 AHU (after filter)	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82770	J002919		9509/18	12/05/2018	WHS	
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Debris to duct of DPU 1 AHU (after filter)	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82771	J002919		9509/18	12/05/2018	WHS	
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Debris to duct of DPU 1 AHU (after filter)	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82772	J002919		9509/18	12/05/2018	WHS	
#REF!	NAB	St.Lukes	13	Dust	Debris at entrance	Loose Asbestos		Unsealed Spray / Lagging / Dust Debris	Loose asbestos debris or residue		No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	30/03/2024	Identified	Asbestos Removed	82829	J043288		9811/19	03/01/2020	WHS	
#REF!	NAB	St.Lukes	13	Debris Material	Debris at entrance	Loose Asbestos		Loose Asbestos Debris	Loose asbestos debris or residue		No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	30/03/2024	Identified	Asbestos Removed	82830	J043288		9811/19	03/01/2020	WHS	
#REF!	NAB	St.Lukes	13	Debris Insulation	Snot to ceiling of duct	Loose Asbestos		Loose Asbestos Debris	Loose asbestos debris or residue		No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	30/03/2024	Identified	Asbestos Removed	82831	J043288		9811/19	03/01/2020	WHS	
#REF!	NAB	St.Lukes	13	NO ASBESTOS	Residue to RHS wall	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82832	J043288		9509/18	19/06/2018	WHS	
#REF!	NAB	St.Lukes	13	NO ASBESTOS	Residue to LHS wall	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82833	J043288		9509/18	19/06/2018	WHS	
#REF!	NAB	St.Lukes	13	NO ASBESTOS	Residue to RHS wall	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82834	J043288		9509/18	19/06/2018	WHS	
#REF!	NAB	St.Lukes	13	Debris Material	Debris to floor at bend in duct	Loose Asbestos		Loose Asbestos Debris	Loose asbestos debris or residue		No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	30/03/2024	Identified	Asbestos Removed	82835	J043288		9811/19	03/01/2020	WHS	
#REF!	NAB	St.Lukes	13	NO ASBESTOS	Debris to floor	NO ASBESTOS	NO ASBESTOS				No further action required (Asbestos removed)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82836	J043288		9509/18	19/06/2018	WHS	
#REF!	NAB	St.Lukes	13	NO ASBESTOS	Residue to LHS wall	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82837	J043288		9509/18	19/06/2018	WHS	
#REF!	NAB	St.Lukes	13	NO ASBESTOS	Debris to floor	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82838	J043288		9509/18	19/06/2018	WHS	
#REF!	NAB	St.Lukes	13	Residue to Walls	Residue to RHS wall	Thermal Insulation		Unsealed	Loose asbestos debris or residue		No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	27/01/2021	Identified	Asbestos Removed	82839	J043288		9811/19	03/01/2020	WHS	
#REF!	NAB	St.Lukes	13	Residue to Walls	Residue to RHS wall	Thermal Insulation		Unsealed	Loose asbestos debris or residue		No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	27/01/2021	Identified	Asbestos Removed	82840	J043288		9811/19	03/01/2020	WHS	
#REF!	NAB	St.Lukes	13	Residue to Walls	Residue to RHS wall	Thermal Insulation		Unsealed	Loose asbestos debris or residue		No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	30/03/2024	Identified	Asbestos Removed	82841	J043288		9811/19	03/01/2020	WHS	
#REF!	NAB	St.Lukes	13	NO ASBESTOS	Residue to RHS wall	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82842	J043288		9509/18	19/06/2018	WHS	
#REF!	NAB	St.Lukes	13	NO ASBESTOS	Residue to RHS wall	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82843	J043288		9509/18	19/06/2018	WHS	
#REF!	NAB	St.Lukes	13	NO ASBESTOS	Residue to LHS wall	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82844	J043288		9509/18	19/06/2018	WHS	
#REF!	NAB	St.Lukes	13	NO ASBESTOS	Residue to LHS wall	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82845	J043288		9509/18	19/06/2018	WHS	
#REF!	NAB	St.Lukes	13	NO ASBESTOS	Residue to RHS wall	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82846	J043288		9509/18	19/06/2018	WHS	
#REF!	NAB	St.Lukes	13	NO ASBESTOS	Residue to RHS wall	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82847	J043288		9509/18	19/06/2018	WHS	
#REF!	NAB	St.Lukes	13	NO ASBESTOS	Residue to LHS wall	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82848	J043288		9509/18	19/06/2018	WHS	
#REF!	NAB	St.Lukes	13	NO ASBESTOS	Residue to LHS wall	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82849	J043288		9509/18	19/06/2018	WHS	
#REF!	NAB	St.Lukes	13	NO ASBESTOS	Residue to pipe work	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82850	J043288		9509/18	19/06/2018	WHS	
#REF!	NAB	St.Lukes	13	NO ASBESTOS	Residue to pipe work	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82851	J043288		9509/18	19/06/2018	WHS	

#REF!	NAB	St.Lukes	13	Debris Insulation	Debris to floor of alcove	Loose Asbestos			Loose Asbestos Debris	Loose asbestos debris or residue	No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	30/03/2024	Identified	Asbestos Removed	82852	J043288	9811/19	03/01/2020	WHS	
#REF!	NAB	St.Lukes	13	Loose Asbestos	Debris to floor of alcove	Loose Asbestos			Loose Asbestos Debris	Loose asbestos debris or residue	No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	30/03/2024	Identified	Asbestos Removed	82853	J043288	9811/19	03/01/2020	WHS	
#REF!	NAB	St.Lukes	13	Dust	Debris to floor	Loose Asbestos			Unsealed Spray / Lagging / Dust Debris	Loose asbestos debris or residue	No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	30/03/2024	Identified	Asbestos Removed	82854	J043288	9811/19	03/01/2020	WHS	
#REF!	NAB	St.Lukes	13	NO ASBESTOS	Residue to LHS wall	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82855	J043288	9506/18	19/06/2018	WHS	
#REF!	NAB	St.Lukes	13	NO ASBESTOS	Residue to wall	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82856	J043288	9506/18	19/06/2018	WHS	
#REF!	NAB	St.Lukes	13	NO ASBESTOS	Residue to wall	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82857	J043288	9506/18	19/06/2018	WHS	
#REF!	NAB	St.Lukes	13	Paper	Paper tp redundant pipe wrok	Textiles & Paper			Unsealed	Medium	No further action required (No Asbestos Detected)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	27/01/2021	Identified	Asbestos Removed	82858	J043288	9811/19	03/01/2020	WHS	
#REF!	NAB	St.Lukes	13	Paper	Paper to floor	Textiles & Paper			Unsealed	High	No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	30/03/2024	Identified	Asbestos Removed	82859	J043288	9811/19	19/06/2018	WHS	
#REF!	NAB	St.Lukes	13	Loose Asbestos	Debris to floor	Loose Asbestos			Loose Asbestos Debris	Loose asbestos debris or residue	Remove (Controlled Conditions)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	30/03/2024	Identified	Asbestos Removed	82860	J043288	9811/19	03/01/2020	WHS	
#REF!	NAB	St.Lukes	13		Debris to floor				Loose Asbestos Debris	None	No further action required (No Asbestos Detected)	Correcting Previous Data	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82861	J043288			WHS	
#REF!	NAB	St.Lukes	13	NO ASBESTOS	Residue to wall	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82862	J043288	9506/18	19/06/2018	WHS	
#REF!	NAB	St.Lukes	13	NO ASBESTOS	Residue to wall	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82863	J043288	9506/18	19/06/2018	WHS	
#REF!	NAB	St.Lukes	13	NO ASBESTOS	Residue to wall	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82864	J043288	9506/18	19/06/2018	WHS	
#REF!	NAB	St.Lukes	13	NO ASBESTOS	Residue to wall	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82865	J043288	9506/18	19/06/2018	WHS	
#REF!	NAB	St.Lukes	13	NO ASBESTOS	Paper debris to floor	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82866	J043288	9506/18	19/06/2018	WHS	
#REF!	NAB	St.Lukes	13	Paper	Paper debris to floor	Textiles & Paper			Unsealed	Loose asbestos debris or residue	No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	30/03/2024	Identified	Asbestos Removed	82867	J043288	9811/19	03/01/2020	WHS	
#REF!	NAB	St.Lukes	13	Paper	Paper debris to floor	Textiles & Paper			Unsealed	Loose asbestos debris or residue	No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	30/03/2024	Identified	Asbestos Removed	82868	J043288	9811/19	03/01/2020	WHS	
#REF!	NAB	St.Lukes	13	NO ASBESTOS	Residue to wall	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82869	J043288	9506/18	19/06/2018	WHS	
#REF!	NAB	St.Lukes	13	Loose Asbestos	Debris to floor	Loose Asbestos			Loose Asbestos Debris	Loose asbestos debris or residue	No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	30/03/2024	Identified	Asbestos Removed	82870	J043288	9811/19	03/01/2020	WHS	
#REF!	NAB	St.Lukes	13	NO ASBESTOS	Debris to floor	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82871	J043288	9506/18	19/06/2018	WHS	
#REF!	NAB	St.Lukes	13	Gutters	Redundant section of guttering	Cement Products			Unsealed Cement	Low	No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0		Identified	Asbestos Removed	82872	J043288		17/10/2022	WHS	
#REF!	NAB	St.Lukes	13	NO ASBESTOS	Floor debris	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82873	J043288	9506/18	19/06/2018	WHS	
#REF!	NAB	St.Lukes	13	NO ASBESTOS	Redundant boards	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82874	J043288	9506/18	19/06/2018	WHS	
#REF!	NAB	St.Lukes	13	NO ASBESTOS	Residue to pipe work	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82875	J043288	9506/18	19/06/2018	WHS	
#REF!	NAB	St.Lukes	13	NO ASBESTOS	Redundant lagging to pipe penetration	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82876	J043288	9506/18	19/06/2018	WHS	
#REF!	NAB	St.Lukes	13	Gutter	Redundant section of guttering	Cement Products			Unsealed Cement	Medium	No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0		Identified	Asbestos Removed	82877	J043288		17/10/2022	WHS	
#REF!	NAB	St.Lukes	13	NO ASBESTOS	Residue to wall	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82878	J043288	9506/18	19/06/2018	WHS	
#REF!	NAB	St.Lukes	13	NO ASBESTOS	Residue to wall	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82879	J043288	9506/18	19/06/2018	WHS	
#REF!	NAB	St.Lukes	13	NO ASBESTOS	Debris to floor	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82880	J043288	9506/18	19/06/2018	WHS	
#REF!	NAB	St.Lukes	13		Debris to floor	NO ASBESTOS			Loose Asbestos Debris	Loose asbestos debris or residue	No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0		Identified	Asbestos Removed	82881	J043288		17/10/2022	WHS	
#REF!	NAB	St.Lukes	13	Residue to Walls	Residue to wall	Thermal Insulation			Unsealed	Loose asbestos debris or residue	No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0		Identified	Asbestos Removed	82882	J043288		17/10/2022	WHS	
#REF!	NAB	St.Lukes	13	Residue to Walls	Residue to wall	Thermal Insulation			Unsealed	Loose asbestos debris or residue	No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	17/10/2023	Identified	Asbestos Removed	82883	J043288		17/10/2022	WHS	
#REF!	NAB	St.Lukes	13	Residue to Walls	Residue to wall	Thermal Insulation			Unsealed	Loose asbestos debris or residue	No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0		Identified	Asbestos Removed	82884	J043288		17/10/2022	WHS	
#REF!	NAB	St.Lukes	13	Residue to Walls	Residue to wall	Thermal Insulation			Unsealed	Loose asbestos debris or residue	No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0		Identified	Asbestos Removed	82885	J043288		17/10/2022	WHS	
#REF!	NAB	St.Lukes	13	Residue to Walls	Residue to wall	Thermal Insulation			Unsealed	Loose asbestos debris or residue	No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0		Identified	Asbestos Removed	82886	J043288		17/10/2022	WHS	
#REF!	NAB	St.Lukes	13	Residue to Walls	Residue to wall	Thermal Insulation			Unsealed	Loose asbestos debris or residue	No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0		Identified	Asbestos Removed	82887	J043288		17/10/2022	WHS	
#REF!	NAB	St.Lukes	13	Residue to Walls	Residue to wall	Thermal Insulation			Unsealed	Loose asbestos debris or residue	No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0		Identified	Asbestos Removed	82888	J043288		17/10/2022	WHS	
#REF!	NAB	St.Lukes	13	Residue to Walls	Residue to wall	Thermal Insulation			Unsealed	Loose asbestos debris or residue	No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0		Identified	Asbestos Removed	82889	J043288		17/10/2022	WHS	
#REF!	NAB	St.Lukes	13	Residue to Walls	Residue to wall	Thermal Insulation			Unsealed	Loose asbestos debris or residue	No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0		Identified	Asbestos Removed	82890	J043288		17/10/2022	WHS	
#REF!	NAB	St.Lukes	13	Residue to Walls	Residue to wall	Thermal Insulation			Unsealed	Loose asbestos debris or residue	No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0		Identified	Asbestos Removed	82891	J043288		17/10/2022	WHS	
#REF!	NAB	St.Lukes	13	Residue to Walls	Residue to wall	Thermal Insulation			Unsealed	Loose asbestos debris or residue	No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0		Identified	Asbestos Removed	82892	J043288		17/10/2022	WHS	
#REF!	NAB	St.Lukes	13	NO ASBESTOS	Residue to metal bracket	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82893	J043288	9506/18	19/06/2018	WHS	
#REF!	NAB	St.Lukes	13	NO ASBESTOS	Residue to ceiling at duct entrance	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82894	J043288	9506/18	19/06/2018	WHS	
#REF!	NAB	St.Lukes	13	NO ASBESTOS	Residue to wall at duct entrance	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82895	J043288	9506/18	19/06/2018	WHS	
#REF!	NAB	St.Lukes	13	NO ASBESTOS	Residue to wall	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82896	J043288	9506/18	19/06/2018	WHS	
#REF!	NAB	St.Lukes	13	Loose Asbestos	Debris to floor	Loose Asbestos			Loose Asbestos Debris	Loose asbestos debris or residue	No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	30/03/2024	Identified	Asbestos Removed	82897	J043288	9811/19	03/01/2020	WHS	
#REF!	NAB	St.Lukes	13	Loose Asbestos	Paper debris to alcove	Loose Asbestos			Loose Asbestos Debris	Loose asbestos debris or residue	No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	30/03/2024	Identified	Asbestos Removed	82898	J043288	9811/19	03/01/2020	WHS	
#REF!	NAB	St.Lukes	13	NO ASBESTOS	Residue to ceiling	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82945	J043288	9506/1A	19/06/2018	WHS	
#REF!	NAB	St.Lukes	13	Dust	Debris to floor	Loose Asbestos			Unsealed Spray / Lagging / Dust Debris	Loose asbestos debris or residue	No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	30/03/2024	Identified	Asbestos Removed	82946	J043288	9811/19	03/01/2020	WHS	
#REF!	NAB	St.Lukes	13	NO ASBESTOS	Residue to wall	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82947	J043288	9506/18	19/06/2018	WHS	
#REF!	NAB	St.Lukes	13	NO ASBESTOS	Residue to wall	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82948	J043288	9506/1A	19/06/2018	WHS	
#REF!	NAB	St.Lukes	13	NO ASBESTOS	Residue to wall	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82949	J043288	9506/18	19/06/2018	WHS	
#REF!	NAB	St.Lukes	13	NO ASBESTOS	Residue to wall	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82950	J043288	9506/18	19/06/2018	WHS	
#REF!	NAB	St.Lukes	13	Residue to Walls	Residue to wall	Thermal Insulation			Unsealed	Loose asbestos debris or residue	No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	30/03/2024	Identified	Asbestos Removed	82951	J043288	9811/1G	03/01/2020	WHS	
#REF!	NAB	St.Lukes	13	NO ASBESTOS	Residue to wall	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82952	J043288	9506/18	19/06/2018	WHS	
#REF!	NAB	St.Lukes	13	NO ASBESTOS	Residue to wall	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82953	J043288	9506/18	19/06/2018	WHS	
#REF!	NAB	St.Lukes	13	NO ASBESTOS	Residue to wall	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82954	J043288	9506/18	19/06/2018	WHS	
#REF!	NAB	St.Lukes	13	NO ASBESTOS	Residue to wall	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82955	J043288	9506/18	19/06/2018	WHS	
#REF!	NAB	St.Lukes	13	NO ASBESTOS	Residue to wall	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82956	J043288	9506/18	19/06/2018	WHS	
#REF!	NAB	St.Lukes	13	NO ASBESTOS	Paper debris to floor	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82957	J043288	9506/18	19/06/2018	WHS	
#REF!	NAB	St.Lukes	13	Debris Material	Paper debris to floor	Loose Asbestos			Loose Asbestos Debris	Loose asbestos debris or residue	No action required	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	30/03/2024	Identified	Asbestos Removed	82958	J043288	9811/1A	03/01/2020	WHS	
#REF!	NAB	St.Lukes	13	Lining Paper	Paper to redundant pipe	Textiles & Paper			Unsealed	High	No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	30/03/2024	Identified	Asbestos Removed	82959	J043288	9811/1A	03/01/2020	WHS	
#REF!	NAB	St.Lukes	13	Debris Insulation	Lagging debris to floor	Loose Asbestos			Loose Asbestos Debris	Loose asbestos debris or residue	No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	30/03/2024	Identified	Asbestos Removed	82960	J043288	9811/19	03/01/2020	WHS	
#REF!	NAB	St.Lukes	13	Debris Insulation	Lagging debris to floor	Loose Asbestos			Loose Asbestos Debris	Loose asbestos debris or residue	No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	30/03/2024	Identified	Asbestos Removed	82961	J043288	9811/19	03/01/2020	WHS	
#REF!	NAB	St.Lukes	13	Debris Material	Paper debris to floor	Loose Asbestos			Loose Asbestos Debris	Loose asbestos debris or residue	No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	30/03/2024	Identified	Asbestos Removed	82962	J043288	9811/1G	19/06/2018	WHS	
#REF!	NAB	St.Lukes	13	NO ASBESTOS	Bitumen debris to floor	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82963	J043288	9506/18	19/06/2018	WHS	
#REF!	NAB	St.Lukes	13	NO ASBESTOS	Residue to wall	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82964	J043288	9506/18	19/06/2018	WHS	
#REF!	NAB	St.Lukes	13	NO ASBESTOS	Residue to wall	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82965	J043288	9506/1A	19/06/2018	WHS	
#REF!	NAB	St.Lukes	13	NO ASBESTOS	Residue to wall	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82966	J043288	9506/18	19/06/2018	WHS	
#REF!	NAB	St.Lukes	13	NO ASBESTOS	Residue to wall	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82967	J043288	9506/18	19/06/2018	WHS	
#REF!	NAB	St.Lukes	13	NO ASBESTOS	Residue to wall	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82968	J043288	9506/1A	19/06/2018	WHS	
#REF!	NAB	St.Lukes	13	NO ASBESTOS	Residue to wall	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82969	J043288	9506/18	19/06/2018	WHS	
#REF!	NAB	St.Lukes	13	NO ASBESTOS	Residue to wall	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82970	J043288	9506/18	19/06/2018	WHS	
#REF!	NAB	St.Lukes	13	NO ASBESTOS	Residue to wall	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82971	J043288	9506/1A	19/06/2018	WHS	

#REF!	NAB	St.Lukes	13	NO ASBESTOS	Residue to wall	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82972	J043288	9506/18	19/06/2018	WHS
#REF!	NAB	St.Lukes	13	NO ASBESTOS	Residue to wall	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82973	J043288	9506/18	19/06/2018	WHS
#REF!	NAB	St.Lukes	13	Dust	Debris to floor	Loose Asbestos		Unsealed Spray / Lagging / Dust Debris	Loose asbestos debris or residue		No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	30/03/2024	Identified	Asbestos Removed	82974	J043288	9811/19	03/01/2020	WHS
#REF!	NAB	St.Lukes	13	Paper	Paper to floor	Textiles & Paper		Unsealed	High		No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	30/03/2024	Identified	Asbestos Removed	82975	J043288S	9811/19	03/01/2020	WHS
#REF!	NAB	St.Lukes	13	Debris Material	Debris to floor	Loose Asbestos		Loose Asbestos Debris	Loose asbestos debris or residue		No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	30/03/2024	Identified	Asbestos Removed	82976	J043288	9811/19	03/01/2020	WHS
#REF!	NAB	St.Lukes	13	Debris Material	Debris to floor	Loose Asbestos		Loose Asbestos Debris	Loose asbestos debris or residue		No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	30/03/2024	Identified	Asbestos Removed	82977	J043288	9811/19	03/01/2020	WHS
#REF!	NAB	St.Lukes	13	Debris Material	Debris to floor	Loose Asbestos		Loose Asbestos Debris	Loose asbestos debris or residue		No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	30/03/2024	Identified	Asbestos Removed	82978	J043288	9811/19	03/01/2020	WHS
#REF!	NAB	St.Lukes	13	Residue to Walls	Residue to wall	Thermal Insulation		Unsealed	Loose asbestos debris or residue		No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0		Identified	Asbestos Removed	82979	J043288		17/10/2022	WHS
#REF!	NAB	St.Lukes	13	Residue to Walls	Residue to wall	Thermal Insulation		Unsealed	Loose asbestos debris or residue		No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0		Identified	Asbestos Removed	82980	J043288		17/10/2022	WHS
#REF!	NAB	St.Lukes	13	Residue to Walls	Residue to wall	Thermal Insulation		Unsealed	Loose asbestos debris or residue		No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0		Identified	Asbestos Removed	82981	J043288		17/10/2022	WHS
#REF!	NAB	St.Lukes	13	Residue to Walls	Residue to wall	Thermal Insulation		Unsealed	Loose asbestos debris or residue		No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0		Identified	Asbestos Removed	82982	J043288		17/10/2022	WHS
#REF!	NAB	St.Lukes	13	Residue to Walls	Residue to wall	Thermal Insulation		Unsealed	Loose asbestos debris or residue		No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0		Identified	Asbestos Removed	82983	J043288		17/10/2022	WHS
#REF!	NAB	St.Lukes	13	Residue to Walls	Residue to wall	Thermal Insulation		Unsealed	Loose asbestos debris or residue		No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0		Identified	Asbestos Removed	82984	J043288	9811/19	17/10/2022	WHS
#REF!	NAB	St.Lukes	13	Residue to Walls	Residue to wall	Thermal Insulation		Unsealed	Loose asbestos debris or residue		No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0		Identified	Asbestos Removed	82985	J043288		17/10/2022	WHS
#REF!	NAB	St.Lukes	13	Residue to Walls	Residue to wall	Thermal Insulation		Unsealed	Loose asbestos debris or residue		No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0		Identified	Asbestos Removed	82986	J043288		17/10/2022	WHS
#REF!	NAB	St.Lukes	13	NO ASBESTOS	Debris to floor	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82987	J043288	9506/18	19/06/2018	WHS
#REF!	NAB	St.Lukes	13	NO ASBESTOS	Debris to floor	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82988	J043288	9506/18	19/06/2018	WHS
#REF!	NAB	St.Lukes	13	Dust	Debris to floor	Loose Asbestos		Unsealed Spray / Lagging / Dust Debris	Loose asbestos debris or residue		No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0		Identified	Asbestos Removed	82989	J043288		17/10/2022	WHS
#REF!	NAB	St.Lukes	13	NO ASBESTOS	Residue to wall	NO ASBESTOS			None		Remove (Controlled Conditions)	Correcting Previous Data	HSG227	Unchecked	NO ASBESTOS	0		Identified	Asbestos Removed	82990	J043288	9811/19	17/01/2022	WHS
#REF!	NAB	St.Lukes	13	NO ASBESTOS	Wrap to high level pipe	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82991	J043288	9506/18	19/06/2018	WHS
#REF!	NAB	St.Lukes	13		Residue to pipe penetration	NO ASBESTOS			None		No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0		Identified	Asbestos Removed	82992	J043288		17/10/2022	WHS
#REF!	NAB	St.Lukes	13	NO ASBESTOS	Debris to floor	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82993	J043288	9506/18	19/06/2018	WHS
#REF!	NAB	St.Lukes	13	NO ASBESTOS	Debris to floor	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82994	J043288	9506/18	19/06/2018	WHS
#REF!	NAB	St.Lukes	13	NO ASBESTOS	Debris to floor	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82995	J043288	9506/18	19/06/2018	WHS
#REF!	NAB	St.Lukes	13	NO ASBESTOS	Residue to ceiling	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82996	J043288	9506/18	19/06/2018	WHS
#REF!	NAB	St.Lukes	13	NO ASBESTOS	Debris to switchgear	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82997	J043288	9506/18	19/06/2018	WHS
#REF!	NAB	St.Lukes	13	NO ASBESTOS	Debris to switchgear	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82998	J043288	9506/18	19/06/2018	WHS
#REF!	NAB	St.Lukes	13	NO ASBESTOS	Debris to window cill	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	82999	J043288	9506/18	19/06/2018	WHS
#REF!	NAB	St.Lukes	13	NO ASBESTOS	Debris to floor	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	83000	J043288	9506/18	19/06/2018	WHS
#REF!	NAB	St.Lukes	13	NO ASBESTOS	Debris to floor	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	83001	J043288	9506/18	19/06/2018	WHS
#REF!	NAB	St.Lukes	13	NO ASBESTOS	Lino beneath comms equipment	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	83002	J043288	9506/18	19/06/2018	WHS
#REF!	NAB	St.Lukes	13	NO ASBESTOS	Debris to floor	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	83003	J043288	9506/18	19/06/2018	WHS
#REF!	NAB	St.Lukes	13	NO ASBESTOS	Debris to floor	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	83004	J043288	9506/18	19/06/2018	WHS
#REF!	NAB	St.Lukes	13	Residue to Walls	Residue to wall	Thermal Insulation		Unsealed	Loose asbestos debris or residue		No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0		Identified	Asbestos Removed	83005	J043288	9811/19	17/10/2022	WHS
#REF!	NAB	St.Lukes	13	Residue to Walls	Residue to wall	Thermal Insulation		Unsealed	Loose asbestos debris or residue		No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0		Identified	Asbestos Removed	83006	J043288	9811/19	17/10/2022	WHS
#REF!	NAB	St.Lukes	13	Residue to Walls	Residue to wall	Thermal Insulation		Unsealed	Loose asbestos debris or residue		No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0		Identified	Asbestos Removed	83007	J043288	9811/19	17/10/2022	WHS
#REF!	NAB	St.Lukes	13	Residue to Walls	Residue to wall	Thermal Insulation		Unsealed	Loose asbestos debris or residue		Remove (Controlled Conditions)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0		Identified	Asbestos Removed	83008	J043288	9811/19	17/10/2022	WHS
#REF!	NAB	St.Lukes	13	Residue to Walls	Residue to wall	Thermal Insulation		Unsealed	Loose asbestos debris or residue		No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0		Identified	Asbestos Removed	83009	J043288	9811/19	17/10/2022	WHS
#REF!	NAB	St.Lukes	13	Residue to Walls	Residue to wall	Thermal Insulation		Unsealed	Loose asbestos debris or residue		Remove (Controlled Conditions)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0		Identified	Asbestos Removed	83010	J043288	9811/19	17/10/2022	WHS
#REF!	NAB	St.Lukes	13	Residue to Walls	Residue to wall	Thermal Insulation		Unsealed	Loose asbestos debris or residue		No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0		Identified	Asbestos Removed	83011	J043288	9811/19	17/10/2022	WHS
#REF!	NAB	St.Lukes	13	Residue to Walls	Residue to wall	Thermal Insulation		Unsealed	Loose asbestos debris or residue		No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0		Identified	Asbestos Removed	83012	J043288		17/10/2022	WHS
#REF!	NAB	St.Lukes	13	Residue to Walls	Residue to wall	Thermal Insulation		Unsealed	Loose asbestos debris or residue		No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0		Identified	Asbestos Removed	83013	J043288		17/10/2022	WHS
#REF!	NAB	St.Lukes	13	Residue to Walls	Residue to wall	Thermal Insulation		Unsealed	Loose asbestos debris or residue		No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0		Identified	Asbestos Removed	83014	J043288		17/10/2022	WHS
#REF!	NAB	St.Lukes	13	NO ASBESTOS	Debris to floor	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	83015	J043288	9506/18	19/06/2018	WHS
#REF!	NAB	St.Lukes	13	NO ASBESTOS	Debris to floor	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	83016	J043288	9506/18	19/06/2018	WHS
#REF!	NAB	St.Lukes	13	NO ASBESTOS	Debris to floor	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	83017	J043288	9506/18	19/06/2018	WHS
#REF!	NAB	St.Lukes	13	NO ASBESTOS	Debris to floor	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	83018	J043288	9506/18	19/06/2018	WHS
#REF!	NAB	St.Lukes	13	NO ASBESTOS	Debris to floor	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	83019	J043288	9506/18	19/06/2018	WHS
#REF!	NAB	St.Lukes	13	NO ASBESTOS	Debris to floor	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	83020	J043288	9506/18	19/06/2018	WHS
#REF!	NAB	St.Lukes	13	NO ASBESTOS	Debris to floor	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	83021	J043288	9506/18	19/06/2018	WHS
#REF!	NAB	St.Lukes	13	NO ASBESTOS	Debris to electrical conduit	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	83022	J043288	9506/18	19/06/2018	WHS
#REF!	NAB	St.Lukes	13	NO ASBESTOS	Debris to electrical conduit	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	83023	J043288	9506/18	19/06/2018	WHS
#REF!	NAB	St.Lukes	13	NO ASBESTOS	Debris to electrical conduit	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	83024	J043288	9506/18	19/06/2018	WHS
#REF!	NAB	St.Lukes	13	Residue to Walls	Residue to wall	Thermal Insulation		Unsealed	Loose asbestos debris or residue		No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0		Identified	Asbestos Removed	83025	J043288		17/10/2022	WHS
#REF!	NAB	St.Lukes	13	Residue to Walls	Residue to wall	Thermal Insulation		Unsealed	Loose asbestos debris or residue		No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0		Identified	Asbestos Removed	83026	J043288		17/10/2022	WHS
#REF!	NAB	St.Lukes	13	Residue to Walls	Residue to wall	Thermal Insulation		Unsealed	Loose asbestos debris or residue		No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0		Identified	Asbestos Removed	83027	J043288		17/10/2022	WHS
#REF!	NAB	St.Lukes	13	Residue to Walls	Residue to wall	Thermal Insulation		Unsealed	Loose asbestos debris or residue		No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0		Identified	Asbestos Removed	83028	J043288		17/10/2022	WHS
#REF!	NAB	St.Lukes	13	Residue to Walls	Residue to wall	Thermal Insulation		Unsealed	Loose asbestos debris or residue		No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0		Identified	Asbestos Removed	83029	J043288		17/10/2022	WHS
#REF!	NAB	St.Lukes	13	Residue to Walls	Residue to wall	Thermal Insulation		Unsealed	Loose asbestos debris or residue		No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0		Identified	Asbestos Removed	83030	J043288		17/10/2022	WHS
#REF!	NAB	St.Lukes	13	NO ASBESTOS	Residue to wall	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	83031	J043288	9506/18	19/06/2018	WHS
#REF!	NAB	St.Lukes	13	Residue to Walls	Residue to wall	Thermal Insulation		Unsealed	Loose asbestos debris or residue		No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0		Identified	Asbestos Removed	83032	J043288		17/10/2022	WHS
#REF!	NAB	St.Lukes	13	Residue to Walls	Residue to wall	Thermal Insulation		Unsealed	Loose asbestos debris or residue		No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0		Identified	Asbestos Removed	83033	J043288		17/10/2022	WHS
#REF!	NAB	St.Lukes	13	NO ASBESTOS	Residue to wall	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	83034	J043288	9506/18	19/06/2018	WHS
#REF!	NAB	St.Lukes	13	Gaskets	Gasket 1 of 2 RHS of door	Composite Material		Composite Material	Medium		No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0		Identified	Asbestos Removed	83035	J043288		17/10/2022	WHS
#REF!	NAB	St.Lukes	13	Gaskets	Gasket 2 of 2 RHs of door	Composite Material		Composite Material	Medium		No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0		Identified	Asbestos Removed	83036	J043288		17/10/2022	WHS
#REF!	NAB	St.Lukes	13	NO ASBESTOS	Redundant gasket material	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	83037	J043288	9506/18	19/06/2018	WHS
#REF!	NAB	St.Lukes	13	Ridge Tiles	Redundant ridge tile	Cement Products		Unsealed	Low		No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0		Identified	Asbestos Removed	83038	J043288		17/10/2022	WHS
#REF!	NAB	St.Lukes	13	NO ASBESTOS	Debris to electrical conduit	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	83039	J043288	9506/18	19/06/2018	WHS
#REF!	NAB	St.Lukes	13	NO ASBESTOS	Debris to floor	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	83040	J043288	9506/18	19/06/2018	WHS
#REF!	NAB	St.Lukes	13	NO ASBESTOS	Debris to floor	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	83041	J043288	9506/18	19/06/2018	WHS
#REF!	NAB	St.Lukes	13	NO ASBESTOS	Debris to floor	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	83042	J043288	9506/18	19/06/2018	WHS
#REF!	NAB	St.Lukes	13	NO ASBESTOS	Debris to floor	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	83043	J043288	9506/18	19/06/2018	WHS
#REF!	NAB	St.Lukes	13	Debris Material	Gasket Debris	Loose Asbestos	Chrysotile	Loose Asbestos Debris	Loose asbestos debris or residue		Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	High Risk	10	27/01/2021	Identified	High Risk	83044	J012868	9811/19	03/01/2020	WHS
#REF!	NAB	St.Lukes	13	Pipe Lagoino	Lagoino to oise LHS	Thermal Insulation	Amosite/Chrysotile	Unsealed Spray / Lagging /	Medium		Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	Hoh Risk	10	27/01/2021	Identified	Hoh Risk	83045	J012868	9811/19	03/01/2020	WHS
#REF!	NAB	St.Lukes	13	Pipe Lagoino	Lagoino to oise RHS	Thermal Insulation	Amosite/Chrysotile	Unsealed Spray / Lagging /	Medium		Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	Hoh Risk	10	27/01/2021	Identified	Hoh Risk	83046	J012868	9811/19	03/01/2020	WHS
#REF!	NAB	St.Lukes	13	Ropes	Rope to electrical cable	Textiles & Paper	Chrysotile	Unsealed Rope	High		Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	Medium Risk	8	27/01/2021	Identified	Medium Risk	83047	J012868	9811/19	03/01/2020	WHS
#REF!	OAC	Lurgan Hospital	15	Residue to Walls	Residue to ceilins above doors	Thermal Insulation	Chrysotile	Unsealed	Loose asbestos debris or residue		Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	Hoh Risk	10	20/12/2022	Identified	Hoh Risk	83048	AB695	-	12/09/2022	WHS

#REF!	QAC	Lurgan Hospital	15	Pipe Residue	Residue to pipe work above doors	Thermal Insulation	Amosite/Chrysotile	Residue Asbestos Type	Loose asbestos	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	High Risk	11	20/12/2022	Identified	High Risk	83049	A8895	9326/17	12/09/2022	WHS
#REF!	QAC	Lurgan Hospital	15	Residue to Walls	Residue to ceiling LHS of doors	Thermal Insulation	Amosite/Chrysotile	Residue Cement	Loose asbestos	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	High Risk	11	20/12/2022	Identified	High Risk	83050	A8895	9326/17	12/09/2022	WHS
#REF!	QAC	Lurgan Hospital	15	Residue to Walls	Residue to ceilino	Thermal Insulation	Amosite/Chrysotile	Residue Cement	Loose asbestos	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	Hioh Risk	11	20/12/2022	Identified	High Risk	83051	A8895	9326/17	12/09/2022	WHS
#REF!	QAC	Lurgan Hospital	15	Pipe Residue	Residue to pipe	Thermal Insulation	Amosite/Chrysotile	Residue Cement Asbestos Type	Loose asbestos	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	High Risk	11	20/12/2022	Identified	High Risk	83052	A8895	9326/17	12/09/2022	WHS
#REF!	QAC	Lurgan Hospital	15	NO ASBESTOS	Debris to floor	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	83053	A8895	9326/17	20/12/2017	WH Stephens
#REF!	QAC	Lurgan Hospital	15	NO ASBESTOS	Debris to floor	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	83054	A8895	9326/17	20/12/2017	WH Stephens
#REF!	QAC	Lurgan Hospital	15	NO ASBESTOS	Debris to floor	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	83055	A8895	9326/17	20/12/2017	WH Stephens
#REF!	QAC	Lurgan Hospital	15	General Debris	Debris to floor	General Debris	Amosite	Loose Asbestos Debris	Loose asbestos	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	Hioh Risk	11	20/12/2022	Identified	High Risk	83056	A8895	9326/17	12/09/2022	WHS
#REF!	QAC	Lurgan Hospital	15	NO ASBESTOS	Debris to pipe work	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	83057	A8895	9326/17	20/12/2017	WH Stephens
#REF!	QAC	Lurgan Hospital	15	NO ASBESTOS	Debris to pipe work	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	83058	A8895	9326/17	20/12/2017	WH Stephens
#REF!	QAC	Lurgan Hospital	15	NO ASBESTOS	Debris to pipe flange	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	83059	A8895	9326/17	20/12/2017	WH Stephens
#REF!	QAC	Lurgan Hospital	15	Residue to Walls	Residue to wall	Thermal Insulation	Amosite/Chrysotile	Residue Cement	Loose asbestos	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	High Risk	11	20/12/2022	Identified	High Risk	83060	A8895	9326/17	12/09/2022	WHS
#REF!	QAC	Lurgan Hospital	15	Residue to Walls	Residue to wall	Thermal Insulation	Amosite/Chrysotile	Unsealed	Loose asbestos	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	High Risk	11	20/12/2022	Identified	High Risk	83061	A8895	9326/17	12/09/2022	WHS
#REF!	QAC	Lurgan Hospital	15	Residue to Walls	Residue to wall	Thermal Insulation	Amosite/Chrysotile	Unsealed	Loose asbestos	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	Hioh Risk	11	20/12/2022	Identified	High Risk	83062	A8895	9326/17	12/09/2022	WHS
#REF!	QAC	Lurgan Hospital	15	Residue to Walls	Residue to wall	Thermal Insulation	Amosite/Chrysotile	Unsealed	Loose asbestos	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	High Risk	11	20/12/2022	Identified	High Risk	83063	A8895	9326/17	12/09/2022	WHS
#REF!	QAC	Lurgan Hospital	15	Residue to Walls	Residue to wall	Thermal Insulation	Amosite/Chrysotile	Unsealed	Loose asbestos	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	High Risk	11	20/12/2022	Identified	High Risk	83064	A8895	9326/17	12/09/2022	WHS
#REF!	QAC	Lurgan Hospital	15	Residue to Walls	Residue to wall	Thermal Insulation	Amosite/Chrysotile	Unsealed	Loose asbestos	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	Hioh Risk	11	20/12/2022	Identified	High Risk	83065	A8895	9326/17	12/09/2022	WHS
#REF!	QAC	Lurgan Hospital	15	Residue to Walls	Residue to wall	Thermal Insulation	Amosite/Chrysotile	Unsealed	Loose asbestos	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	High Risk	11	20/12/2022	Identified	High Risk	83066	A8895	9326/17	12/09/2022	WH
#REF!	QAC	Lurgan Hospital	15	NO ASBESTOS	Debris to boiler	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	83067	A8895	9326/17	20/12/2017	WH Stephens
#REF!	QAC	Lurgan Hospital	15	Pipe Residue	Residue to pipe work	Thermal Insulation	Amosite/Chrysotile	Unsealed	Loose asbestos	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	High Risk	11	20/12/2022	Identified	High Risk	83068	A8895	9326/17	12/09/2022	WHS
#REF!	QAC	Lurgan Hospital	15	Pipe Residue	Residue to pipe work	Thermal Insulation	Amosite	Unsealed	Loose asbestos	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	High Risk	11	20/12/2022	Identified	High Risk	83069	A8895	9326/17	12/09/2022	WHS
#REF!	QAC	Lurgan Hospital	15	Pipe Residue	Residue to pipework	Thermal Insulation	Amosite	Unsealed	Loose asbestos	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	Hioh Risk	11	20/12/2022	Identified	High Risk	83070	A8895	9326/17	12/09/2022	WHS
#REF!	QAC	Lurgan Hospital	15	NO ASBESTOS	Boxing to beam	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	83071	A8895	9326/17	20/12/2017	WH Stephens
#REF!	QAC	Lurgan Hospital	15	NO ASBESTOS	Boxing to column	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	83072	A8895	9326/17	20/12/2017	WH Stephens
#REF!	QAC	Lurgan Hospital	15	NO ASBESTOS	Boxing to beam	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	83073	A8895	9326/17	20/12/2017	WH Stephens
#REF!	QAC	Lurgan Hospital	15	NO ASBESTOS	Panel above door	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	83074	A8895	9326/17	20/12/2017	WH Stephens
#REF!	QAC	Lurgan Hospital	15	Pipe Residue	Residue to pipe work on ceiling	Thermal Insulation	Chrysotile	Unsealed	Loose asbestos	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	High Risk	10	20/12/2022	Identified	High Risk	83075	A8895	9326/17	12/09/2022	WHS
#REF!	QAC	Lurgan Hospital	15	Residue to Walls	Residue to wall	Thermal Insulation	Amosite/Chrysotile	Unsealed	Loose asbestos	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	High Risk	11	20/12/2022	Identified	High Risk	83076	A8895	9326/17	12/09/2022	WHS
#REF!	QAC	Lurgan Hospital	15	Residue to Walls	Residue to wall	Thermal Insulation	Amosite/Chrysotile	Unsealed	Loose asbestos	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	High Risk	11	20/12/2022	Identified	High Risk	83077	A8895	9326/17	12/09/2022	WHS
#REF!	QAC	Lurgan Hospital	15	Residue to Walls	Residue to wall	Thermal Insulation	Amosite/Chrysotile	Unsealed	Loose asbestos	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	High Risk	11	20/12/2022	Identified	High Risk	83078	A8895	9326/17	12/09/2022	WHS
#REF!	QAC	Lurgan Hospital	15	Residue to Walls	Residue to wall	Thermal Insulation	Amosite/Chrysotile	Unsealed	Loose asbestos	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	High Risk	11	20/12/2022	Identified	High Risk	83079	A8895	9326/17	12/09/2022	WHS
#REF!	QAC	Lurgan Hospital	15	Residue to Walls	Residue to wall	Thermal Insulation	Amosite/Chrysotile	Unsealed	Loose asbestos	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	High Risk	11	20/12/2022	Identified	High Risk	83080	A8895	9326/17	12/09/2022	WHS
#REF!	QAC	Lurgan Hospital	15	Residue to Walls	Residue to wall	Thermal Insulation	Amosite/Chrysotile	Unsealed	Loose asbestos	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	Hioh Risk	11	20/12/2022	Identified	High Risk	83081	A8895	9326/17	12/09/2022	WHS
#REF!	QAC	Lurgan Hospital	15	Residue to Walls	Residue to wall	Thermal Insulation	Amosite/Chrysotile	Unsealed	Loose asbestos	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	High Risk	11	20/12/2022	Identified	High Risk	83082	A8895	9326/17	12/09/2022	WHS
#REF!	QAC	Lurgan Hospital	15	Residue to Walls	Residue to wall	Thermal Insulation	Amosite/Chrysotile	Unsealed	Loose asbestos	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	High Risk	11	20/12/2022	Identified	High Risk	83083	A8895	9326/17	12/09/2022	WHS
#REF!	QAC	Lurgan Hospital	15	Residue to Walls	Residue to wall	Thermal Insulation	Amosite/Chrysotile	Unsealed	Loose asbestos	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	Hioh Risk	11	20/12/2022	Identified	High Risk	83084	A8895	9326/17	12/09/2022	WHS
#REF!	QAC	Lurgan Hospital	15	NO ASBESTOS	Debris to bracket	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	83085	A8895	9326/17	20/12/2017	WH Stephens
#REF!	QAC	Lurgan Hospital	15	NO ASBESTOS	Debris to wall	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	83086	A8895	9326/17	20/12/2017	WH Stephens
#REF!	QAC	Lurgan Hospital	15	NO ASBESTOS	Debris to switch box	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	83087	A8895	9326/17	20/12/2017	WH Stephens
#REF!	QAC	Lurgan Hospital	15	Residue to Walls	Residue to wall	Thermal Insulation	Amosite/Chrysotile	Unsealed	Loose asbestos	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	Hioh Risk	11	20/12/2022	Identified	High Risk	83088	A8895	9326/17	12/09/2022	WHS
#REF!	QAC	Lurgan Hospital	15	NO ASBESTOS	Ceiling tile debris to ceiling void	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	83089	A8895	9326/17	20/12/2017	WH Stephens
#REF!	QAC	Lurgan Hospital	15	NO ASBESTOS	Debris to ceiling void	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	83090	A8895	9326/17	20/12/2017	WH Stephens
#REF!	QAC	Lurgan Hospital	15	NO ASBESTOS	Debris to ceiling void	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	83091	A8895	9326/17	20/12/2017	WH Stephens
#REF!	QAC	Lurgan Hospital	15	NO ASBESTOS	Debris to ceiling void	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	83092	A8895	9326/17	20/12/2017	WH Stephens
#REF!	QAC	Lurgan Hospital	15	NO ASBESTOS	Debris to ceiling void	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	83093	A8895	9326/17	20/12/2017	WH Stephens
#REF!	QAC	Lurgan Hospital	15	NO ASBESTOS	Debris to ceiling void	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	83094	A8895	9326/17	20/12/2017	WH Stephens
#REF!	QAC	Lurgan Hospital	15	NO ASBESTOS	Debris to ceiling void	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	83095	A8895	9326/17	20/12/2017	WH Stephens
#REF!	QAC	Lurgan Hospital	15	NO ASBESTOS	Debris to ceiling void	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	83096	A8895	9326/17	20/12/2017	WH Stephens
#REF!	QAC	Lurgan Hospital	15	NO ASBESTOS	Stair nosing	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	83097	A8895	9326/17	20/12/2017	WH Stephens
#REF!	QAC	Lurgan Hospital	15	NO ASBESTOS	Debris to ceiling void	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	83098	A8895	9326/17	20/12/2017	WH Stephens
#REF!	QAC	Lurgan Hospital	15	NO ASBESTOS	Debris to ceiling void	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	83099	A8895	9326/17	20/12/2017	WH Stephens
#REF!	QAC	Lurgan Hospital	15	NO ASBESTOS	Debris to ceiling void	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	83100	A8895	9326/17	20/12/2017	WH Stephens
#REF!	QAC	Lurgan Hospital	15	NO ASBESTOS	Debris to ceiling void	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	83101	A8895	9326/17	20/12/2017	WH Stephens
#REF!	QAC	Lurgan Hospital	15	Fire Break Panel	Fire break above door to 001	Insulating Board	Amosite/Chrysotile	Unsealed Board	High	Manage and monitor	Re-inspection	HSG227	Unchecked	Medium Risk	9	21/03/2023	Identified	Medium Risk	83102	A8895	9326/17	12/09/2022	WHS
#REF!	QAC	Lurgan Hospital	15	General Debris	Debris to ceiling grid	General Debris	Amosite/Chrysotile	Loose Asbestos Debris	Loose asbestos	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	High Risk	11	21/12/2022	Identified	High Risk	83103	A8895	9326/17	12/09/2022	WHS
#REF!	QAC	Lurgan Hospital	15	General Debris	Debris to ceilino arid	General Debris	Amosite/Chrysotile	Loose Asbestos Debris	Loose asbestos	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	Hioh Risk	11	21/12/2022	Identified	High Risk	83104	A8895	9326/17	12/09/2022	WHS
#REF!	QAC	Lurgan Hospital	15	NO ASBESTOS	Debris to ceiling tile grid	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	83105	A8895	9326/17	20/12/2017	WH Stephens
#REF!	QAC	Lurgan Hospital	15	General Debris	Debris to ceilino tile arid	General Debris	Amosite/Chrysotile	Loose Asbestos Debris	Loose asbestos	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	Hioh Risk	11	21/12/2022	Identified	High Risk	83106	A8895	9326/17	12/09/2022	WHS
#REF!	QAC	Lurgan Hospital	15	Fire Break Panel	Fire break above door to room 004	Insulating Board	Amosite/Chrysotile	Unsealed Board	Medium	Manage and monitor	Re-inspection	HSG227	Unchecked	Medium Risk	8	21/03/2023	Identified	Medium Risk	83107	A8895	9326/17	12/09/2022	WHS
#REF!	QAC	Lurgan Hospital	15	General Debris	Debris to ceiling grid	General Debris	Amosite/Chrysotile	Loose Asbestos Debris	Loose asbestos	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	High Risk	11	21/12/2022	Identified	High Risk	83108	A8895	9326/17	12/09/2022	WHS
#REF!	QAC	Lurgan Hospital	15	NO ASBESTOS	Debris to ceiling tile	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	83109	A8895	9326/17	20/12/2017	WH Stephens
#REF!	QAC	Lurgan Hospital	15	NO ASBESTOS	Debris to ceiling tile	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	83110	A8895	9326/17	20/12/2017	WH Stephens
#REF!	QAC	Lurgan Hospital	15	NO ASBESTOS	Debris to ceiling tile	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	83111	A8895	9326/17	20/12/2017	WH Stephens
#REF!	QAC	Lurgan Hospital	15	NO ASBESTOS	Debris to ceiling tile	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	83112	A8895	9326/17	20/12/2017	WH Stephens
#REF!	QAC	Lurgan Hospital	15	NO ASBESTOS	Debris to ceiling tile grid	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	83113	A8895	9326/17	20/12/2017	WH Stephens
#REF!	QAC	Lurgan Hospital	15	NO ASBESTOS	Debris to ceiling tile grid	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	83114	A8895	9326/17	20/12/2017	WH Stephens
#REF!	QAC	Lurgan Hospital	15	NO ASBESTOS	Debris to ceiling tile grid	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	83115	A8895	9326/17	20/12/2017	WH Stephens
#REF!	QAC	Lurgan Hospital	15	NO ASBESTOS	Debris to ceiling tile	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	83116	A8895	9326/17	20/12/2017	WH Stephens
#REF!	QAC	Lurgan Hospital	15	NO ASBESTOS	Debris to ceiling tile	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	83117	A8895	9326/17	20/12/2017	WH Stephens
#REF!	QAC	Lurgan Hospital	15	NO ASBESTOS	Debris to ceiling tile	NO ASBESTOS	NO ASBESTOS	n		No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	83118	A8895	9326/17	20/12/2017	WH Stephens
#REF!	QAC	Lurgan Hospital	15	NO ASBESTOS	Debris to ceiling tile grid	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	83119	A8895	9326/17	20/12/2017	WH Stephens
#REF!	QAC	Lurgan Hospital	15	NO ASBESTOS	Debris to ceiling tile	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	83120	A8895	9326/17	20/12/2017	WH Stephens
#REF!	QAC	Lurgan Hospital	15	NO ASBESTOS	Debris to ceiling tile	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	83121	A8895	9326/17	20/12/2017	WH Stephens
#REF!	QAC	Lurgan Hospital	15	NO ASBESTOS	Wall panel to room E002	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	83122	A8895	9326/17	20/12/2017	WH Stephens
#REF!	QAC	Lurgan Hospital	15	NO ASBESTOS	Fire break around door to room E003	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	83123	A8895	9326/17	20/12/2017	WH Stephens
#REF!	QAC	Lurgan Hospital	15	NO ASBESTOS	Fire break around door to E003	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	83124	A8895	9326/17	20/12/2017	WH Stephens
#REF!	QAC	Lurgan Hospital	15	NO ASBESTOS	Fire break around door to room E001	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	83125	A8895	9326/17	20/12/2017	WH Stephens
#REF!	QAC	Lurgan Hospital	15	NO ASBESTOS	Fire break aound door to room E001	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	83126	A8895	9326/17	20/12/2017	WH Stephens
#REF!	QAC	Lurgan Hospital	15	NO ASBESTOS	Fire break around door to room E004	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	83127	A8895	9326/17	20/12/2017	WH Stephens
#REF!	QAC	Lurgan Hospital	15	NO ASBESTOS	Fire break around door to room E004	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	83128	A8895	9326/17	20/12/2017	WH Stephens
#REF!	QAC	Lurgan Hospital	15	NO ASBESTOS	Debris below water tank	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	83129	A8895	9326/17	20/12/2017	WH Stephens
#REF!	QAC	Lurgan Hospital	15	NO ASBESTOS	Redundant pipe lagging below water tank	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	83130	A8895	9326/17	20/12/2017	WH Stephens
#REF!	QAC	Lurgan Hospital	15	NO ASBESTOS	Fire break around door to room E003	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	83131	A8895	9326/17	20/12/2017	WH Stephens
#REF!	QAC	Lurgan Hospital	15	NO ASBESTOS	Fire break around door to room E003	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	83132	A8895	9326/17	20/12/2017	WH Stephens
#REF!	QAC	Lurgan Hospital	15	NO ASBESTOS	Board to back of roof void access hatch	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	83133	A8895	9326/17	20/12/2017	WH Stephens
#REF!	QAC	Lurgan Hospital	15	NO ASBESTOS	Board to back of roof void hatch	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	83134	A8895	9326/17	20/12/2017	WH Stephens
#REF!	QAC	Lurgan Hospital	15	NO ASBESTOS	Board to RHS wall	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	83135	A8902	9326/17	20/12/2017	WH Stephens
#REF!	QAC	Lurgan Hospital	15	NO ASBESTOS	Lower board to RHS wall	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	83136	A8902	9326/17	20/12/2017	WH Stephens
#REF!	QAC	Lurgan Hospital	15	NO ASBESTOS	Upper board to RHS wall	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	83137	A8902	9326/17	20/12/2017	WH Stephens

#REF!	QAC	Lurgan Hospital	15	NO ASBESTOS	Lower wall board to RHS wall	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	83138	A8902	9326/17	20/12/2017	WH Stephens
#REF!	QAC	Lurgan Hospital	15	NO ASBESTOS	Upper board to RHS wall	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	83139	A8902	9326/17	20/12/2017	WH Stephens
#REF!	QAC	Lurgan Hospital	15	NO ASBESTOS	Ceiling board	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	83140	A8902	9326/17	20/12/2017	WH Stephens
#REF!	QAC	Lurgan Hospital	15	Fuse Flash Guards	Fuse and flash	Textiles & Paper	Presumed Asbestos	Enclosed Fuse Flash Guards	Medium	Manage and monitor		Re-inspection	HSG227	Unchecked	Medium Risk	8	21/03/2023	Strongly Presumed	Medium Risk	83141		9326/17	12/09/2022	WHS
#REF!	QAC	Lurgan Hospital	15	Fuse Flash Guards	Fuse and Flash	Textiles & Paper	Presumed Asbestos	Enclosed Fuse Flash Guards	Medium	Manage and monitor		Re-inspection	HSG227	Unchecked	Medium Risk	8	21/03/2023	Strongly Presumed	Medium Risk	83142		9326/17	12/09/2022	WHS
#REF!	QAC	Lurgan Hospital	15	Fuse Flash Guards	Fuse and Flash	Textiles & Paper	Presumed Asbestos	Enclosed Fuse Flash Guards	Medium	Manage and monitor		Re-inspection	HSG227	Unchecked	Medium Risk	8	21/03/2023	Identified	Medium Risk	83143		9326/17	12/09/2022	WHS
#REF!	QAC	Lurgan Hospital	15	Fuse Flash Guards	Fuse and Flash	Textiles & Paper	Presumed Asbestos	Enclosed Fuse Flash Guards	Medium	Manage and monitor		Re-inspection	HSG227	Unchecked	Medium Risk	8	21/03/2023	Identified	Medium Risk	83144		9326/17	12/09/2022	WHS
#REF!	QAC	Lurgan Hospital	15	Fuse Flash Guards	Fuse and Flash	Textiles & Paper	Presumed Asbestos	Enclosed Fuse Flash Guards	Medium	Manage and monitor		Re-inspection	HSG227	Unchecked	Medium Risk	8	21/03/2023	Stronnlv Presumed	Medium Risk	83145		9326/17	12/09/2022	WHS
#REF!	OHC	Edenderry House	01									Review – No Change	HSG227	Unchecked		0				83203		9326/17	21/03/2019	WHS
#REF!	QAA	Craigavon Hospital	06	NO ASBESTOS	Vinyl floor covering	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	83390	BA8644	9506/19	20/02/2019	WHS
#REF!	QAA	Craigavon Hospital	06	NO ASBESTOS	Cove skirting	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	83391	BA8644	9506/19	20/02/2019	WHS
#REF!	OAA	Craisavon Hospital	06	Floor Tiles	VFT & bitumen at door threshold	Composite Material	Chrvsotile	Composite Material	Verv Low	Manage and monitor		Re-inspection	HSG227	Unchecked	Verv Low Risk	2	13/12/2023	Identified	Verv Low Risk	83392	BA8644	9326/17	22/06/2022	WH Stephens
#REF!	QAA	Craigavon Hospital	06	NO ASBESTOS	Board to door of electric cupboard	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	83393	BA8644	9506/19	20/02/2019	WHS
#REF!	QAA	Craigavon Hospital	06	Board	Board above glazing in ceiling void	Insulating Board	NO ASBESTOS	Unsealed Board	Low	No further action required (Asbestos removed)		Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	13/04/2022	Identified	Asbestos Removed	83394	BA8644	9811/19	07/01/2020	WH Stephens
#REF!	QAA	Craigavon Hospital	06	Discarded Insulation Board	Board debris to ceiling void	Loose Asbestos	NO ASBESTOS	Loose Asbestos Debris	Loose asbestos debris or residue	No further action required (Asbestos removed)		Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	13/04/2022	Identified	Asbestos Removed	83395	BA8644	9811/19	07/01/2020	WH Stephens
#REF!	QAA	Craigavon Hospital	06	Discarded Insulation Board	Debris to ceiling void	Loose Asbestos	NO ASBESTOS	Loose Asbestos Debris	Loose asbestos debris or residue	No further action required (Asbestos removed)		Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	13/04/2022	Identified	Asbestos Removed	83396	BA8644	9811/19	07/01/2020	WH Stephens
#REF!	QAA	Craigavon Hospital	06	NO ASBESTOS	Debris to ledge in ceiling void	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	83397	BA8644	9506/19	20/02/2019	WHS
#REF!	QAA	Craigavon Hospital	06	Gaskets	Spare gasket	Composite Material	NO ASBESTOS	Composite Material	Low	No further action required (Asbestos removed)		ACM Removed	HSG227	Unchecked	NO ASBESTOS	0	05/03/2019	Identified	Asbestos Removed	83398	BA8644	9506/19	20/02/2019	WHS
#REF!	QAA	Craigavon Hospital	06	NO ASBESTOS	Spare gasket	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	83399	BA8644	9506/19	20/02/2019	WHS
#REF!	QAA	Craigavon Hospital	06	NO ASBESTOS	Board to work bench	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	83400	BA8644	9506/19	20/02/2019	WHS
#REF!	QAA	Craigavon Hospital	06	NO ASBESTOS	Ceiling board	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	83401	BA8644	9506/19	20/02/2019	WHS
#REF!	QAA	Craigavon Hospital	07	Gaskets	Gasket to redundant flanee	Composite Material	Chrvsotile	Composite Material	Medium	Manage and monitor		Re-inspection	HSG227	Unchecked	Verv Low Risk	4	13/12/2023	Identified	Verv Low Risk	83402	BA8644	9326/17	05/09/2022	WH Stephens
#REF!	QAA	Craigavon Hospital	07	NO ASBESTOS	DPC	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	83403	BA8644	9326/17	04/12/2018	WHS
#REF!	QAA	Craigavon Hospital	07									Review – No Change	HSG227	Unchecked		0				83404		9326/17	04/12/2018	WHS
#REF!	QAA	Craigavon Hospital	06	Bitumen Adhesive	Concealed bitumen to floor screed throughout	Composite Material	Presumed Asbestos			Manage and monitor		Re-inspection	HSG227	Unchecked	Very Low Risk	4	13/12/2023	Strongly Presumed	Very Low Risk	83405		9302/2	22/06/2022	WH Stephens
#REF!	QAA	Craigavon Hospital	06	Flash Guard	Fuse and flash ouards to electrics	Textiles & Paper	Presumed Asbestos			Manage and monitor		Re-inspection	HSG227	Unchecked	Low Risk	5	13/12/2023	Stronnlv Presumed	Low Risk	83406		9302/2	22/06/2022	WH Stephens
#REF!	QAA	Craigavon Hospital	06	Gaskets	Gaskets to pipe flanges throughout	Composite Material	Presumed Asbestos	Composite Material	Low	Manage and monitor		Re-inspection	HSG227	Unchecked	Low Risk	5	13/12/2023	Strongly Presumed	Low Risk	83453		9302/2	22/06/2022	WH Stephens
#REF!	OAA	Craisavon Hospital	01	Pipe Insulation	Cloth to pipe bracket	Textiles & Paper	Chrvsotile	Unsealed Flash Flaments	Low	Manage and monitor		Re-inspection	HSG227	Unchecked	Medium Risk	7	11/10/2023	Identified	Medium Risk	83454	BA8628	9302/2	11/10/2022	WHS
#REF!	QAA	Craigavon Hospital	01	Pipe Insulation	Cloth to pipe bracket	Textiles & Paper	Chrysotile	Unsealed Flash Flaments	Medium	Manage and monitor		Re-inspection	HSG227	Unchecked	Medium Risk	8	11/10/2023	Identified	Medium Risk	83455	BA8628	9302/2	11/10/2022	WHS
#REF!	QAA	Craigavon Hospital	01	Debris Insulation	Residue to pipe bracket	Loose Asbestos	Chrysotile	Unsealed Flash Flaments	Loose asbestos	Remove (Controlled Conditions)		Re-inspection	HSG227	Unchecked	High Risk	10	11/10/2023	Identified	High Risk	83456	BA8628	9302/2	11/10/2022	WHS
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Cloth inside redundant SVP	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	83457	BA8628		21/02/2018	
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Sevalant to pipe work	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	83458	BA8628		21/02/2018	
#REF!	QAA	Craigavon Hospital	01	Pipe Insulation	Cloth to pipe bracket	Textiles & Paper	Chrysotile	Unsealed Flash Flaments	Low	Manage and monitor		Re-inspection	HSG227	Unchecked	Medium Risk	7	11/10/2023	Identified	Medium Risk	83459	BA8628	9302/2	11/10/2022	WHS
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Lagging to pipework (labelled dead)	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	83519	J043166	9506/18	12/05/2018	WHS
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Debris to top of electrical conduit	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	83520	J043166	9506/18	12/05/2018	WHS
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Debris to floor of duct on LHS	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	83521	J043166	9506/18	12/05/2018	WHS
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Debris to floor of duct on RHS	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	83522	J043166	9506/18	12/05/2018	WHS
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Debris below floor grill	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	83523	J043166	9506/18	12/05/2018	WHS
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Debris to floor grill	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	83524	J043166	9506/18	12/05/2018	WHS
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Debris to top of electrical conduit	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	83525	J043166	9506/18	12/05/2018	WHS
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Debris to low level ledge on LHS wall	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	83526	J043166	9506/18	12/05/2018	WHS
#REF!	RAA	South Tyrone Hospital	17	Dust	Debris to 'FWBB' electrical box	Loose Asbestos	Chrysotile	Unsealed Spray / Lagging /	Loose asbestos	Remove (Controlled Conditions)		Re-inspection	HSG227	Unchecked	High Risk	10	13/12/2023	Identified	High Risk	83527	J043166	9302/2	13/12/2022	WHS
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Debris to top of electrical conduit LHS wall	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	83528	J043166	9506/18	12/05/2018	WHS
#REF!	RAA	South Tyrone Hospital	17	Dust	Debris to concrete floor ledge	Loose Asbestos	Amosite	Unsealed Spray / Lagging /	Loose asbestos	Remove (Controlled Conditions)		Re-inspection	HSG227	Unchecked	High Risk	11	13/12/2023	Identified	High Risk	83529	J043166	9302/2	13/12/2022	WHS
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Debris to floor grill	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	83530	J043166	9506/18	12/05/2018	WHS
#REF!	RAA	South Tyrone Hospital	17	Dust	Debris to low level wall ledge	Loose Asbestos	Chrysotile	Unsealed Spray / Lagging /	Loose asbestos	Remove (Controlled Conditions)		Re-inspection	HSG227	Unchecked	High Risk	10	13/12/2023	Identified	High Risk	83531	J043166	9302/2	13/12/2022	WHS
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Debris to metal wall bracket to rear wall	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	83532	J043166	9506/18	12/05/2018	WHS
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Residue to rear wall	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	83533	J043166	9506/18	12/05/2018	WHS
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Debris to top of electrical conduit on LHS wall	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	83534	J043166	9506/18	12/05/2018	WHS
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Gasket debris below floor grill	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	83535	J043166	9506/18	12/05/2018	WHS
#REF!	RAA	South Tyrone Hospital	17	Dust	Debris to metal ledge low level LHS	Loose Asbestos	Chrysotile	Unsealed Spray / Lagging /	Loose asbestos	Remove (Controlled Conditions)		Re-inspection	HSG227	Unchecked	High Risk	10	14/12/2023	Identified	High Risk	83536	J043166	9302/2	14/12/2022	WHS
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Debris to metal ledge mid level RHS	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	83564	J043166	9506/18	12/05/2018	WHS
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Debris to floor ledge	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	83565	J043166	9506/18	12/05/2018	WHS
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Debris to floor below fire extinguisher	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	83566	J043166	9506/18	12/05/2018	WHS
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Debris to concrete plinth below belt drive no 2	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	83567	J043166	9506/18	12/05/2018	WHS
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Paper to joint of concrete plinth to belt drive no.2	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	83568	J043166	9506/18	12/05/2018	WHS
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Debris to floor beside plinth adjacent of duct	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	83569	J043166	9506/18	12/05/2018	WHS
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Debris to top of brick plinth adjacent of duct	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	83570	J043166	9506/18	12/05/2018	WHS
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Debris to floor at ladder to duct G - 005	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	83571	J043166	9506/18	12/05/2018	WHS
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Wall putty to pipe penetration to duct G -005	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	83572	J043166	9506/18	12/05/2018	WHS
#REF!	RAA	South Tyrone Hospital	17	Dust	Debris to steps to G - 004	Loose Asbestos	Amosite/Chrysotile	Unsealed Spray / Lagging /	Loose asbestos	Remove (Controlled Conditions)		Re-inspection	HSG227	Unchecked	High Risk	11	14/12/2023	Identified	High Risk	83573	J043166	9302/2	14/12/2022	WHS
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Debris below stairs	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	83574	J043166	9506/18	12/05/2018	WHS
#REF!	RAA	South Tyrone Hospital	17	Residue to Walls	Residue to wall to LHS door leading to G - 004	Thermal Insulation	Amosite/Chrysotile	Unsealed	Loose asbestos debris or residue	Remove (Controlled Conditions)		Re-inspection	HSG227	Unchecked	High Risk	11	14/12/2023	Identified	High Risk	83575	J043166	9302/2	14/12/2022	WHS
#REF!	RAA	South Tyrone Hospital	17	Dust	Debris below water tank	Loose Asbestos	Chrysotile	Unsealed Spray / Lagging /	Loose asbestos	Remove (Controlled Conditions)		Re-inspection	HSG227	Unchecked	High Risk	10	14/12/2023	Identified	High Risk	83576	J043166	9302/2	14/12/2022	WHS
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Debris to floor in rear corner	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	83577	J043166	9506/18	12/05/2018	WHS
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Residue to brick plinth of redundant water tank	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	83578	J043166	9506/18	12/05/2018	WHS
#REF!	RAA	South Tyrone Hospital	17	Pipe Insulation	Loose wrap around pipework at rear	Textiles & Paper	Chrysotile	Unsealed	Medium	Remove (Controlled Conditions)		Re-inspection	HSG227	Unchecked	Medium Risk	8	14/12/2023	Identified	Medium Risk	83579	J043166	9302/2	14/12/2022	WHS
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Sealant to electrical switchgear	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	83580	J043166	9506/18	12/05/2018	WHS
#REF!	RAA	South Tyrone Hospital	17	Fuse Flash Guards	Electrical switchoear	Textiles & Paper	Presumed Asbestos	Unsealed	Low	Manage and monitor		Re-inspection	HSG227	Unchecked	Medium Risk	9	13/12/2023	Stronnlv Presumed	Medium Risk	83581		9302/2	13/12/2022	WHS
#REF!	RAA	South Tyrone Hospital	17	Gaskets	Rope seals/ gaskets to all slant	Composite Material	Presumed Asbestos	Unsealed	Medium	Manage and monitor		Re-inspection	HSG227	Unchecked	Medium Risk	9	13/12/2023	Identified	Medium Risk	83582	J043166	9302/2	13/12/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	Gaskets	Gasket to flange to corridor at double doors	Composite Material	Chrysotile	Composite Material	Very Low	Manage and monitor		Re-inspection	HSG227	Unchecked	Very Low Risk	2	13/12/2023	Identified	Very Low Risk	83720	A8903	9309/29	26/10/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Stair nosing	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	83721	A8903	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Board lining to concrete shaft	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	83722	A8903	9506/18	20/03/2019	WHS
#REF!	RAA	South Tyrone Hospital	17	Bitumen Felt	Bitumen to pipe penetration in floor	Composite Material	Chrysotile	Unsealed	Medium	Manage and monitor		Re-inspection	HSG227	Unchecked	Medium Risk	7	13/12/2023	Identified	Medium Risk	83723	BA8613	9302/2	13/12/2022	WHS
#REF!	RAA	South Tyrone Hospital	17	Cement Products	Linino to pipe penetration in floor	Cement Products	Chrysotile	Unsealed	Medium	Manage and monitor		Re-inspection	HSG227	Unchecked	Medium Risk	7	13/12/2023	Identified	Medium Risk	83724	BA8613	9302/2	13/12/2022	WHS
#REF!	NAB	St.Lukes	16	NO ASBESTOS	Board to wall boxing	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	83725	BA8645	9506/18	19/07/2018	WHS
#REF!	NAB	St.Lukes	16	NO ASBESTOS	Board to bottom of electrical cupboard	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	83726	BA8645	9506/18	19/07/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	13	Insulation residue	Snot to LHS wall	Thermal Insulation	Amosite/Chrysotile	Unsealed	Loose asbestos	Conduct annual routine inspections		Re-inspection	HSG227	Unchecked	High Risk	11	26/12/2022	Identified	High Risk	84761	BA8676	9302/2	20/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	13	Insulation residue	Snot to LHS wall	Thermal Insulation	Amosite/Chrysotile	Unsealed	Loose asbestos	Conduct annual routine inspections		Re-inspection	HSG227	Unchecked	High Risk	11	26/12/2022	Identified	High Risk	84762	BA8676	9302/2	20/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	13	Insulation residue	Snot to LHS wall	Thermal Insulation	Amosite/Chrysotile	Unsealed	Loose asbestos	Conduct annual routine inspections		Re-inspection	HSG227	Unchecked	High Risk	11	26/12/2022	Identified	High Risk	84763	BA8676	9302/2	20/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	13	Insulation residue	Snot to rear wall	Thermal Insulation	Amosite/Chrysotile	Unsealed	Loose asbestos	Conduct annual routine inspections		Re-inspection	HSG227	Unchecked	High Risk	11	26/12/2022	Identified	High Risk	84764	BA8676	9302/2	20/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	13	Insulation residue	Snot to rear wall	Thermal Insulation	Amosite/Chrysotile	Unsealed	Loose asbestos	Conduct annual routine inspections		Re-inspection	HSG227	Unchecked	High Risk	11	26/12/2022	Identified	High Risk	84765	BA8676	9302/2	20/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	13	Insulation residue	Snot to rear wall	Thermal Insulation	Amosite/Chrysotile	Unsealed	Loose asbestos	Conduct annual routine inspections		Re-inspection	HSG227	Unchecked	High Risk	11	26/12/2022	Identified	High Risk	84766	BA8676	9302/2	20/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	13	Insulation residue	Snot to rear wall	Thermal Insulation	Amosite/Chrysotile	Unsealed	Loose asbestos	Conduct annual routine inspections		Re-inspection	HSG227	Unchecked	High Risk	11	26/12/2022	Identified	High Risk	84767	BA8676	9302/2	20/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	13	Insulation residue	Snot to RHS wall	Thermal Insulation	Amosite/Chrysotile	Unsealed	Loose asbestos	Conduct annual routine inspections		Re-inspection	HSG227	Unchecked	High Risk	11	26/12/2022	Identified	High Risk	84768	BA8676	9302/2	20/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	13	Insulation residue	Snot to RHS wall	Thermal Insulation	Amosite/Chrysotile	Unsealed	Loose asbestos	Conduct annual routine inspections		Re-inspection	HSG227	Unchecked	High Risk	11	26/12/2022	Identified	High Risk	84769	BA8676	9302/2	20/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	13	Insulation residue	Snot to RHS wall	Thermal Insulation	Amosite/Chrysotile	Unsealed	Loose asbestos	Conduct annual routine inspections		Re-inspection	HSG227	Unchecked	Hioh Risk	11	26/12/2022	Identified	High Risk	84770	BA8676	9302/2	20/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	13	NO ASBESTOS	Debris to upper metal conduit LHS wall	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	84771	BA8676	9327/17	23/02/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	13	Loose Asbestos	Debris to upper metal conduit LHS wall	Loose Asbestos	Amosite	Loose Asbestos Debris	Loose asbestos	Conduct annual routine inspections		Re-inspection	HSG227	Unchecked	Hioh Risk	11	26/12/2022	Identified	High Risk	84772	BA8676	9302/2	20/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	13	NO ASBESTOS	Debris to upper metal conduit rear wall	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	84773	BA8676	9327/17	23/02/2018	WHS

#REF!	SAA	Daisy Hill Hospital Estate	13	NO ASBESTOS	Debris to lower metal conduit rear wall	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	84774	BA8676	9327/17	23/02/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	13	General Debris	Debris to floor	General Debris	Amosite	Loose Asbestos Debris	Loose asbestos	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Hidh Risk	11	26/12/2022	Identified	Hidh Risk	84775	BA8676	9327/17	20/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	13	NO ASBESTOS	Debris to floor	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	84776	BA8676	9327/17	23/02/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	13	NO ASBESTOS	Debris to floor	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	84777	BA8676	9327/17	23/02/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	13	General Debris	Debris to floor	General Debris	Amosite	Loose Asbestos Debris	Loose asbestos	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	High Risk	11	26/12/2022	Identified	High Risk	84778	BA8676	9327/17	20/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	13	NO ASBESTOS	Snot to wall	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	84779	BA8676	9327/17	23/02/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	13	NO ASBESTOS	Snot to LHS wall	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	84780	BA8676	9327/17	23/02/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	13	NO ASBESTOS	Snot to wall	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	84781	BA8676	9327/17	23/02/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	13	NO ASBESTOS	Snot to wall	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	84782	BA8676	9327/17	23/02/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	13	NO ASBESTOS	Snot to wall	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	84789	BA8676	9327/17	23/02/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	13	NO ASBESTOS	Snot to wall	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	84790	BA8676	9327/17	23/02/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	13	NO ASBESTOS	Snot to wall	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	84791	BA8676	9327/17	23/02/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	13	NO ASBESTOS	Snot to wall	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	84792	BA8676	9327/17	23/02/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	13	NO ASBESTOS	Snot to wall	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	84793	BA8676	9327/17	23/02/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	13	NO ASBESTOS	Snot to wall	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	84794	BA8676	9327/17	23/02/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	13	NO ASBESTOS	Snot to wall	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	84795	BA8676	9327/17	23/02/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	13	NO ASBESTOS	Snot to wall	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	84796	BA8676	9327/17	23/02/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	13	Floor Tiles	Redundant floor tiles to oarace	Composite Material	Chrysotile	Composite Material	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Varv Low Risk	4	26/09/2023	Identified	Very Low Risk	84797	BA8676	9327/17	20/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	13	NO ASBESTOS	Skirting trim to stairwell	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	84798	BA8676	9327/17	23/02/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	13	Floor Tiles	Floor tile to stairwell	Composite Material	Chrysotile	Composite Material	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Varv Low Risk	3	26/12/2022	Identified	Very Low Risk	84799	BA8676	9327/17	20/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	13	NO ASBESTOS	DPCto window at landing between ground and 1st floor	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	84800	BA8676	9327/17	23/02/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	13	Floor Tiles	Floor tile to bedroom	Composite Material	Chrysotile	Composite Material	Medium	Manage and monitor	Re-inspection	HSG227	Unchecked	Varv Low Risk	4	26/09/2023	Identified	Very Low Risk	84801	BA8676	9327/17	20/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	13	NO ASBESTOS	Felt packer to skirting board	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	84802	BA8676	9327/17	23/02/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	13	Bitumen Adhesive	Bitumen to floor screed	Composite Material	Chrysotile	Composite Material	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Varv Low Risk	3	26/09/2023	Identified	Very Low Risk	84803	BA8676	9327/17	20/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	13	Sink Pad	Sink pad to kitchen	Composite Material	Chrysotile	Composite Material	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Varv Low Risk	4	26/09/2023	Identified	Very Low Risk	84804	BA8676	9327/17	20/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	13	NO ASBESTOS	Debris at floor of riser toilet	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	84805	BA8676	9327/17	23/02/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	13	Fire Blanket	Fire blanket to kitchen at kitchen	Textiles & Paper	Chrysotile	Unsealed	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Medium Risk	8	26/09/2023	Identified	Medium Risk	84806	BA8676	9327/17	20/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	13	NO ASBESTOS	DPC to window	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	84807	BA8676	9327/17	23/02/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	13	NO ASBESTOS	Board debris below water tank in roof void	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	84808	BA8676	9327/17	23/02/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	13	NO ASBESTOS	Fire breakk within roof void	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	84809	BA8676	9327/17	23/02/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	13	NO ASBESTOS	Gasket to redundant hangers in roof space	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	84810	BA8676	9327/17	23/02/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	09	Floor Tiles	Green vinyl floor tile	Composite Material	Chrysotile	Composite Material	Very Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	2	26/09/2023	Identified	Very Low Risk	84811	BA8676	9327/17	20/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	09	Floor Tiles	Cream vinyl floor tile	Composite Material	Chrysotile	Composite Material	Very Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	2	28/08/2021	Identified	Very Low Risk	84812	BA8676	9327/17	27/07/2020	WHS
#REF!	SAA	Daisy Hill Hospital Estate	09	NO ASBESTOS	Sink pad	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	84813	BA8676	9327/17	19/02/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	09	Back Board	Board to back of roof void access	Insulating Board	Amosite/Chrysotile	Unsealed	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Medium Risk	8	26/03/2023	Identified	Medium Risk	84814	BA8676	9327/17	20/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	09	Floor Tiles	Grey vinyl floor tile	Composite Material	Chrysotile	Composite Material	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	3	26/09/2023	Identified	Very Low Risk	84815	BA8676	9327/17	20/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	09	Floor Tiles	Concealed vinyl floor tile	Composite Material	Chrysotile	concealed	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Low Risk	5	26/09/2023	Identified	Low Risk	84816	BA8676	9327/17	20/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	09	Floor Tiles	Concealed vinyl floor tile	Composite Material	Chrysotile	concealed	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Low Risk	5	11/10/2023	Identified	Low Risk	84817	BA8676	9327/17	20/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	09	Insulation residue	Snot to RHS of wall	Thermal Insulation	Amosite	Unsealed	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	High Risk	11	26/12/2022	Identified	High Risk	84818	BA8676	9327/17	20/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	09	Insulation residue	Snot to RHS of wall	Thermal Insulation	Amosite/Chrysotile	Unsealed	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	High Risk	11	26/12/2022	Identified	High Risk	84819	BA8676	9327/17	20/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	09	Insulation residue	Snot to RHS wall	Thermal Insulation	Amosite	Unsealed	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Hidh Risk	11	26/12/2022	Identified	Hidh Risk	84820	BA8676	9327/17	20/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	09	Insulation residue	Snot to rear wall	Thermal Insulation	Amosite/Chrysotile	Unsealed	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	High Risk	11	26/12/2022	Identified	High Risk	84821	BA8676	9327/17	20/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	09	Insulation residue	Snot to rear wall	Thermal Insulation	Amosite/Chrysotile	Unsealed	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Hidh Risk	11	26/12/2022	Identified	Hidh Risk	84822	BA8676	9327/17	20/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	09	Insulation residue	Snot to LHS of wall	Thermal Insulation	Amosite/Chrysotile	Unsealed	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Hidh Risk	11	26/12/2022	Identified	Hidh Risk	84823	BA8676	9327/17	20/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	09	Insulation residue	Snot to LHS of wall	Thermal Insulation	Amosite/Chrysotile	Unsealed	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	High Risk	11	26/12/2022	Identified	High Risk	84824	BA8676	9327/17	20/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	09	Insulation residue	Snot to front wall	Thermal Insulation	Amosite/Chrysotile	Unsealed	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Hidh Risk	11	26/12/2022	Identified	Hidh Risk	84825	BA8676	9327/17	20/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	09	Insulation residue	Snot to front wall	Thermal Insulation	Amosite/Chrysotile	Unsealed	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Hidh Risk	11	26/12/2022	Identified	Hidh Risk	84826	BA8676	9327/17	20/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	09	Insulation residue	Snot to RHS of wall	Thermal Insulation	Amosite/Chrysotile	Unsealed	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	High Risk	11	26/12/2022	Identified	High Risk	84827	BA8676	9327/17	20/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	09	Insulation residue	Snot to RHS of wall	Thermal Insulation	Amosite/Chrysotile	Unsealed	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Hidh Risk	11	26/12/2022	Identified	Hidh Risk	84828	BA8676	9327/17	20/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	09	Insulation residue	Snot to rear wall	Thermal Insulation	Amosite	Unsealed	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Hidh Risk	11	26/12/2022	Identified	Hidh Risk	84829	BA8676	9327/17	20/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	09	Insulation residue	Snot to rear wall	Thermal Insulation	Amosite/Chrysotile	Unsealed	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	High Risk	11	26/12/2022	Identified	High Risk	84830	BA8676	9327/17	20/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	09	Insulation residue	Snot to LHS wall	Thermal Insulation	Amosite/Chrysotile	Unsealed	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Hidh Risk	11	26/12/2022	Identified	High Risk	84831	BA8676	9327/17	20/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	09	Insulation residue	snot to LHS wall	Thermal Insulation	Amosite/Chrysotile	Unsealed	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	High Risk	11	26/12/2022	Identified	High Risk	84832	BA8676	9327/17	20/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	09	Insulation residue	Snot to wall LHS of duct entrance	Thermal Insulation	Amosite/Chrysotile	Unsealed	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	High Risk	11	26/12/2022	Identified	High Risk	84833	BA8676	9327/17	20/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	09	Insulation residue	Snot to wall at duct entrance	Thermal Insulation	Amosite/Chrysotile	Unsealed	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Hidh Risk	11	29/12/2022	Identified	Hidh Risk	84834	BA8676	9327/17	20/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	09	Insulation residue	Snot to wall of duct	Thermal Insulation	Amosite	Unsealed	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	High Risk	11	26/12/2022	Identified	High Risk	84835	BA8676	9327/17	20/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	09	NO ASBESTOS	Debris to floor of duct	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	84836	BA8676	9327/17	19/02/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	09	NO ASBESTOS	Debris to floor of duct	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	84837	BA8676	9327/17	19/02/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	09	NO ASBESTOS	Debris to floor of duct	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	84838	BA8676	9327/17	19/02/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	09	NO ASBESTOS	Debris to floor of duct	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	84839	BA8676	9327/17	19/02/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	09	NO ASBESTOS	Debris to floor of duct	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	84840	BA8676	9327/17	19/02/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	09	Panel	Panel to ladae	Cement Products	Chrysotile	Unsealed Cement	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Low Risk	5	26/12/2022	Identified	Low Risk	84841	BA8676	9327/17	20/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	09	NO ASBESTOS	Debris to floor of duct	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	84842	BA8676	9327/17	19/02/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	09	NO ASBESTOS	Debris to floor of duct	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	84843	BA8676	9327/17	19/02/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	09	NO ASBESTOS	Debris to floor of duct	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	84844	BA8676	9327/17	19/02/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	09	NO ASBESTOS	Debris to floor of duct	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	84845	BA8676	9327/17	19/02/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	09	NO ASBESTOS	Debris to floor of duct	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	84846	BA8676	9327/17	19/02/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	09	NO ASBESTOS	Debris to floor of duct	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	84847	BA8676	9327/17	19/02/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	09	NO ASBESTOS	Debris to floor of duct	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	84848	BA8676	9327/17	19/02/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	09	NO ASBESTOS	Debris to floor of duct	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	84849	BA8676	9327/17	19/02/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	09	NO ASBESTOS	Debris to floor of duct	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	84850	BA8676	9327/17	19/02/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	09	NO ASBESTOS	Debris to floor of duct	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	84943	BA8676	9327/17	19/02/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	09	NO ASBESTOS	Debris to floor of duct	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	84944	BA8676	9327/17	19/02/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	09	NO ASBESTOS	Debris to floor of duct	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	84945	BA8676	9327/17	19/02/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	09	NO ASBESTOS	Debris to floor of duct	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	84946	BA8676	9327/17	19/02/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	09	NO ASBESTOS	Debris to floor of duct	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	84947	BA8676	9327/17	19/02/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	09	NO ASBESTOS	Debris to floor of duct	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	84948	BA8676	9327/17	19/02/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	09	NO ASBESTOS	Debris to floor of duct	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	84949	BA8676	9327/17	19/02/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	09	NO ASBESTOS	Debris to floor of duct	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	84950	BA8676	9327/17	19/02/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	09	Floor Tiles	Vinyl floor tile	Composite Material	Chrysotile	Composite Material	Very Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	2	11/10/2023	Identified	Very Low Risk	84951	BA8676	9327/17	20/04/2022	WHS
#REF!	QCC	Dromore Health Clinic	01	NO ASBESTOS	Ceiling tile type 1	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	84952	A8905	9326/17	04/04/2018	WHS
#REF!	QCC	Dromore Health Clinic	01	NO ASBESTOS	Ceiling tile type 2	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	84953	A8905	9326/17	04/04/2018	WHS
#REF!	QCC	Dromore Health Clinic	01	NO ASBESTOS	Board to skylight	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	84954	A8905	9326/17	04/04/2018	WHS
#REF!	QCC	Dromore Health Clinic	01	NO ASBESTOS	Paper to skylight	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	84955	A8905	9326/17	04/04/2018	WHS
#REF!	QCC	Dromore Health Clinic	01	NO ASBESTOS	Board to skylight	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	84956	A8905	9326/17	04/04/2018	WHS
#REF!	QCC	Dromore Health Clinic	01	NO ASBESTOS	Board to skylight	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	84957	A8905	9326/17	04/04/2018	WHS
#REF!	QCC	Dromore Health Clinic	01	NO ASBESTOS	Sink pad	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	84958	A8905	9326/17	04/04/2018	WHS
#REF!	QCC	Dromore Health Clinic	01	NO ASBESTOS	Board to skylight	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	84959	A8905	9326/17	04/04/2018	WHS
#REF!	QCC	Dromore Health Clinic	01	NO ASBESTOS	Redundant board	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	84960	A8905	9326/17	04/04/2018	WHS

#REF!	QCC	Dromore Health Clinic	01	Floor Tiles	Vinyl floor tile	Composite Material	Chrysotile	Composite Material	Medium	Manage and monitor	Re-inspection	HSG227	Unchecked	Very Low Risk	4	09/09/2023	Identified	Very Low Risk	84961	A8905	9326/17	06/04/2022	WHS
#REF!	QCC	Dromore Health Clinic	01	NO ASBESTOS	Mineral felt in roof void	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	84962	A8905	9326/17	04/04/2018	WHS
#REF!	QCC	Dromore Health Clinic	01	Paper	Paper to woodwool in roof void	Textiles & Paper	Chrysotile	Unsealed	Medium	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	Medium Risk	8	09/03/2023	Identified	Medium Risk	84963	A8905	9326/17	06/04/2022	WHS
#REF!	QCC	Dromore Health Clinic	01	NO ASBESTOS	Bitumen to roof void	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	84964	A8905	9326/17	04/04/2018	WHS
#REF!	QCC	Dromore Health Clinic	01	NO ASBESTOS	Board to skylight	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	84965	A8905	9326/17	04/04/2018	WHS
#REF!	QCC	Dromore Health Clinic	01	Rope Seal	Rope seal to skylight	Textiles & Paper	Chrysotile	Unsealed	High	Manage and monitor	Re-inspection	HSG227	Unchecked	Medium Risk	9	11/03/2023	Identified	Medium Risk	84966	A8905	9326/17	06/04/2022	WHS
#REF!	QCC	Dromore Health Clinic	01	Loose Asbestos	Debris to floor	Loose Asbestos	Chrysotile	Loose Asbestos Debris	Loose asbestos	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	High Risk	10	09/12/2022	Identified	High Risk	84967	A8905	9326/17	06/04/2022	WHS
#REF!	QCC	Dromore Health Clinic	01	Loose Asbestos	Debris to floor	Loose Asbestos	Chrysotile	Loose Asbestos Debris	Loose asbestos	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	High Risk	10	09/12/2022	Identified	High Risk	84968	A8905	9326/17	06/04/2022	WHS
#REF!	QCC	Dromore Health Clinic	01	Loose Asbestos	Debris to floor	Loose Asbestos	Chrysotile	Loose Asbestos Debris	Loose asbestos	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	High Risk	10	09/12/2022	Identified	High Risk	84969	A8905	9326/17	06/04/2022	WHS
#REF!	QCC	Dromore Health Clinic	01	Bitumen Adhesive	Bitumen to floor	Composite Material	Chrysotile	Composite Material	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Very Low Risk	3	09/09/2023	Identified	Very Low Risk	84970	A8905	9326/17	06/04/2022	WHS
#REF!	QCC	Dromore Health Clinic	01	NO ASBESTOS	Board to skylight	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	84971	A8905	9326/17	04/04/2018	WHS
#REF!	QCC	Dromore Health Clinic	01	NO ASBESTOS	Board to skylight	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	84972	A8905	9326/17	04/04/2018	WHS
#REF!	QCC	Dromore Health Clinic	01	NO ASBESTOS	Board to skylight	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	84973	A8905	9326/17	04/04/2018	WHS
#REF!	QCC	Dromore Health Clinic	01	NO ASBESTOS	Board to skylight	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	84974	A8905	9326/17	04/04/2018	WHS
#REF!	QCC	Dromore Health Clinic	01	NO ASBESTOS	Sink pad	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	84975	A8905	9326/17	04/04/2018	WHS
#REF!	QCC	Dromore Health Clinic	01	NO ASBESTOS	Board to skylight	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	84976	A8905	9326/17	04/04/2018	WHS
#REF!	QCC	Dromore Health Clinic	01	Fuse Flash Guards	Fuse and flash	Textiles & Paper	Presumed Asbestos	Unsealed	Low	Manage & Affix ID Labels	Re-inspection	HSG227	Unchecked	Medium Risk	9	09/03/2023	Stronnly Presumed	Medium Risk	84977		9326/17	06/04/2022	WHS
#REF!	QCC	Dromore Health Clinic	01	Fuse Flash Guards	Fuse and flash	Textiles & Paper	Presumed Asbestos	Unsealed	Low	Manage & Affix ID Labels	Re-inspection	HSG227	Unchecked	Medium Risk	9	09/03/2023	Stronnly Presumed	Medium Risk	84978		9326/17	06/04/2022	WHS
#REF!	QAA	Craigavon Hospital	13	NO ASBESTOS	Newer ceiling panel	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85139	BA8725	9506/18	28/02/2019	WHS
#REF!	QAA	Craigavon Hospital	13	NO ASBESTOS	Older ceiling panel rear right hand corner	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85140	BA8725	9506/18	28/02/2019	WHS
#REF!	QAA	Craigavon Hospital	13	NO ASBESTOS	Broken pieces at corner inside door	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85141	BA8725	9506/18	28/02/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	21	NO ASBESTOS	Debris - column to lift plant room	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85158	BA8717	9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	21	NO ASBESTOS	DPC to lif plant room	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85159	BA8717	9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	21	NO ASBESTOS	Debris to cable tray	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85160	BA8717	9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	21	NO ASBESTOS	Debris to metal beam	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85161	BA8717	9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	21	NO ASBESTOS	Ceiling panel above suspended ceilno	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85162	BA8717	9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	21	NO ASBESTOS	Debris to ceiling tile	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85163	BA8717	9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	21	NO ASBESTOS	Debris to ceiling tile	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85164	BA8717	9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	21	NO ASBESTOS	Infill panel to ceiling void	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85165	BA8717	9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	21	NO ASBESTOS	Panel to underside of former access hatch to ceilino void	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85166	BA8717	9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	21	NO ASBESTOS	Debris to ceiling tile	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85167	BA8717	9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	21	NO ASBESTOS	Fire break above door to corridor	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85168	BA8717	9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	21	NO ASBESTOS	Sealant to pipe work	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85169	BA8717	9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	21	NO ASBESTOS	Debris to ceiling tile	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85170	BA8717	9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	21	NO ASBESTOS	Debris to ceiling tile	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85171	BA8717	9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	21	NO ASBESTOS	Sealant to pipe work	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85172	BA8717	9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	21	NO ASBESTOS	Upper ceiling panel	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85173	BA8717	9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	21	NO ASBESTOS	Debris to ceiling tile	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85174	BA8717	9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	21	NO ASBESTOS	Debris to ceiling tile	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85175	BA8717	9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	21	NO ASBESTOS	Infill panel to upper ceiling	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85176	BA8717	9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	21	NO ASBESTOS	Debris to ceiling tile	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85177	BA8717	9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	21	NO ASBESTOS	Infill panel to upper ceiling	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85178	BA8717	9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	21	NO ASBESTOS	Debris to ceiling tile	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85179	BA8717	9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	21	NO ASBESTOS	Debris from board to upper ceiling	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85180	BA8717	9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	21	NO ASBESTOS	Sealant to pipework through firebreak	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85181	BA8717	9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	21	NO ASBESTOS	Debris to ceiling tile	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85182	BA8717	9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	21	NO ASBESTOS	Debris to ceiling tile	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85183	BA8717	9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	21	NO ASBESTOS	Fire sealant to pipe work	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85184	BA8717	9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	21	NO ASBESTOS	Debris to ceiling tile	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85185	BA8717	9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	21	NO ASBESTOS	Debris to ceiling tile	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85186	BA8717	9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	21	NO ASBESTOS	Debris to ceiling tile	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85189	BA8717	9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	21	Debris Insulation	Debris to concrete beam at high	Loose Asbestos	Chrysotile	Loose Asbestos Debris	Loose asbestos	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	High Risk	10	15/12/2022	Identified	High Risk	85190	BA8717	9326/17	22/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	21	Gaskets	Gasket to redundant flange	Composite Material	Chrysotile	Composite Material	Medium	Remove	Re-inspection	HSG227	Unchecked	Very Low Risk	4	15/09/2023	Identified	Very Low Risk	85191	BA8717	9326/17	22/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	21	Gaskets	Gasket to redundant flange	Textiles & Paper	Chrysotile	Enclosed Woven Textile	Medium	Manage and monitor	Re-inspection	HSG227	Unchecked	Low Risk	6	15/09/2023	Identified	Very Low Risk	85192	BA8717	9326/17	22/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	21	NO ASBESTOS	Debris to pipe support bracket	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85193	BA8717	9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	21	Debris Insulation	Debris to underside of steel beam	Loose Asbestos	Amosite/Chrysotile	Loose Asbestos Debris	Loose asbestos	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	High Risk	11	15/12/2022	Identified	High Risk	85194	BA8717	9326/17	22/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	21	NO ASBESTOS	Residue to pipe work	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85195	BA8717	9506/18	19/11/2018	WHS
#REF!	SAA	Daisy Hill Hospital Estate	21	Gaskets	Gaskets to flanges	Composite Material	Presumed Asbestos	Composite Material	Medium	Manage and monitor	Re-inspection	HSG227	Unchecked	Low Risk	6	15/09/2023	Stronnly Presumed	Low Risk	85196		9326/17	22/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	21	Gaskets	Gaskets to flanges	Composite Material	Presumed Asbestos	Composite Material	Medium	Manage and monitor	Re-inspection	HSG227	Unchecked	Low Risk	6	15/09/2023	Stronnly Presumed	Low Risk	85197		9326/17	22/04/2022	WHS
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Debris to ceiling void	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85210	A8909		13/04/2018	
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Partition above double doors	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85211	A8909		13/04/2018	
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Panel to boxing in roof void	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85212	A8909		13/04/2018	
#REF!	QAA	Craigavon Hospital	01	Rope Seal	Cloth seal to vent trunkino	Textiles & Paper	Chrysotile	Unsealed	Low	Manage and monitor	New Incident	HSG227	Unchecked	Medium Risk	7	16/10/2018	Identified	Medium Risk	85213	A8909		13/04/2018	
#REF!	QAA	Craigavon Hospital	01	Bitumen Felt	Bitumen to skylight	Composite Material	Chrysotile	Composite Material	Medium	Manage and monitor	New Incident	HSG227	Unchecked	Very Low Risk	4	16/04/2019	Identified	Very Low Risk	85214	A8909		13/04/2018	
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Paper to wall panel	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85215	A8909		13/04/2018	
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Mastic to vent trunking	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85216	A8909		13/04/2018	
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Debris to floor	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85217	A8909		13/04/2018	
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Debris to floor	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85218	A8909		13/04/2018	
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Debris to floor	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review of Data	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85219	A8909		13/04/2018	
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Debris to floor	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85220	A8909		13/04/2018	
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Debris to ledge	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85221	A8909		13/04/2018	
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Debris to ledge	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85222	A8909		13/04/2018	
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Debris to ledge	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85223	A8909		13/04/2018	
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Gates to extract AHU	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85224	A8909		13/04/2018	
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Firebreak	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85225	A8909		13/04/2018	
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Board debris	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85226	A8909		13/04/2018	
#REF!	SBA	John Mitchel Place	01	NO ASBESTOS	Floor covering beneath carpet	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85317	BA8745	9506/18	27/07/2018	WHS
#REF!	SBA	John Mitchel Place	01	NO ASBESTOS	Bitumen beneath carpet	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85318	BA8746	9506/18	27/07/2018	WHS
#REF!	SBA	John Mitchel Place	01	NO ASBESTOS	Board to attic hatch	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85319	BA8746	9506/18	27/07/2018	WHS
#REF!	SBA	John Mitchel Place	01	Floor Tile and Bitumen Adhesive	Black vinyl floor tiles and bitumen	Composite Material	Chrysotile	Composite Material	Very Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Very Low Risk	2	15/09/2023	Identified	Very Low Risk	85320	BA8746	9326/17	06/04/2022	WH Stephens
#REF!	SBA	John Mitchel Place	01	Floor Tile and Bitumen Adhesive	Black vinyl floor tiles and bitumen	Composite Material	Chrysotile	Composite Material	Very Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Very Low Risk	2	15/09/2023	Identified	Very Low Risk	85321	BA8746	9326/17	06/04/2022	WH Stephens
#REF!	SBA	John Mitchel Place	01	Floor Tile and Bitumen Adhesive	Black vinyl floor tiles and bitumen	Composite Material	Chrysotile	Composite Material	Very Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Very Low Risk	2	15/09/2023	Identified	Very Low Risk	85322	BA8746	9326/17	06/04/2022	WH Stephens
#REF!	SBA	John Mitchel Place	01	Floor Tile and Bitumen Adhesive	Vinyl floor tile debris and bitumen	Composite Material	Chrysotile	Composite Material	High	Manage and monitor	Re-inspection	HSG227	Unchecked	Low Risk	5	15/09/2023	Identified	Low Risk	85323	BA8746	9326/17	06/04/2022	WHS

#REF!	SBA	John Mitchel Place	01	NO ASBESTOS	Board to underside of stairs	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85324	BA8746	9506/18	27/07/2018	WHS
#REF!	SBA	John Mitchel Place	01	Floor Tile and Bitumen Adhesive	Dark green vinyl floor tiles and	Composite Material	Chrysotile	Composite Material	Medium	Manage and monitor	Re-inspection	HSG227	Unchecked	Very Low Risk	4	15/09/2023	Identified	Very Low Risk	85325	BA8746	9302/2	06/04/2022	WHS
#REF!	SBA	John Mitchel Place	01	Panel	Cement panel	Cement Products	Chrysotile	Cement Asbestos	Medium	Manage and monitor	Re-inspection	HSG227	Unchecked	Low Risk	5	15/09/2023	Identified	Low Risk	85326	BA8746	9302/2	06/04/2022	WHS
#REF!	SBA	John Mitchel Place	01	NO ASBESTOS	Board to underside of stairs	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85327	BA8746	9506/18	27/07/2018	WHS
#REF!	SBA	John Mitchel Place	01	NO ASBESTOS	Ceiling panel to cupboard	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85328	BA8746	9506/18	27/07/2018	WHS
#REF!	SBA	John Mitchel Place	01	Ceilino Panel	Ceilino panel	Insulatino Board	Amosite	Unsealed	Low	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	Medium Risk	8	15/03/2023	Identified	Medium Risk	85329	BA8746	9302/2	06/04/2022	WHS
#REF!	SBA	John Mitchel Place	01	Floor Tile and Bitumen Adhesive	Black vinyl floor tiles and bitumen	Composite Material	Chrysotile	Composite Material	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Very Low Risk	3	15/09/2023	Identified	Very Low Risk	85330	BA8746	9302/2	05/04/2022	WHS
#REF!	SHB	Cloughreagh House	01	NO ASBESTOS	Cream vinyl floor tiles	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85331	BA8729	9327/17	26/03/2018	WHS
#REF!	SHB	Cloughreagh House	01	NO ASBESTOS	Vinyl floor tiles	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85332	BA8729	9327/17	26/03/2018	WHS
#REF!	QHD	Transna House	01	Packing Strips	Cavity closer in switch room within boiler room	Cement Products	Chrysotile	Unsealed	Low	Encapsulate, label and manage	Re-inspection	HSG227	Unchecked	Low Risk	6	15/04/2023	Identified	Low Risk	85333	BA8747	9299/22	29/09/2022	WHS
#REF!	SCB	Bessbrook Clinic	01	Bitumen Adhesive	Bitumen to floor of boiler house	Composite Material	Chrysotile	Composite Material	Medium	Manage and monitor	Re-inspection	HSG227	Unchecked	Very Low Risk	4	12/09/2023	Identified	Very Low Risk	85357	BA8788	9302/2	31/08/2022	WHS
#REF!	SJC	Millview Resource Centre	01	Sink Pad	Pad to servino trolley to kitchen	Composite Material	Chrysotile	Composite Material	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Very Low Risk	3	12/09/2023	Identified	Very Low Risk	85358	BA8789	9302/2	31/08/2022	WHS
#REF!	SJC	Millview Resource Centre	01	NO ASBESTOS	Panelling to flue housing to boiler house roof space	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85359	BA8789		23/04/2018	
#REF!	SJC	Millview Resource Centre	01	NO ASBESTOS	Panel to access hatch to roof space to boiler house	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85360	BA8789		23/04/2018	
#REF!	SBE	Rathfriland Health Centre & Library	01	NO ASBESTOS	Debris to electrical cable tray LHS inside door	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85361	BA8790		23/04/2018	
#REF!	SBE	Rathfriland Health Centre & Library	01	NO ASBESTOS	Debris to electrical switch box LHS inside door	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85362	BA8790		23/04/2018	
#REF!	SBE	Rathfriland Health Centre & Library	01	NO ASBESTOS	Debris to electrical switch box LHS	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85363	BA8790		23/04/2018	
#REF!	SBE	Rathfriland Health Centre & Library	01	NO ASBESTOS	Residue to wall	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85364	BA8790		23/04/2018	
#REF!	SBE	Rathfriland Health Centre & Library	01	Wall Panels	Panel to wall vent to oil tank room	Insulating Board	Amosite/Chrysotile	Unsealed Asbestos Insulation	Low	Encapsulate, label and manage	Re-inspection	HSG227	Unchecked	Medium Risk	7	12/03/2023	Identified	Medium Risk	85365	BA8790	9302/2	02/09/2022	WHS
#REF!	SBE	Rathfriland Health Centre & Library	01	Rope Seals	Rope seals to vent opening	Textiles & Paper	Presumed Asbestos	Unsealed	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Medium Risk	9	12/03/2023	Stronolv Presumed	Medium Risk	85366		9302/2	02/09/2022	WHS
#REF!	SBE	Rathfriland Health Centre & Library	01	Wall Panels	Wall vents throughout	Insulating Board	Presumed Asbestos	Unsealed Asbestos Insulation	Low	Label & Manage	Re-inspection	HSG227	Unchecked	Medium Risk	8	12/03/2023	Stronolv Presumed	Medium Risk	85367		9302/2	02/09/2022	WHS
#REF!	SHA	Drumalane Estate	06	Ceiling Panel	Ceiling panels to boiler room	Insulating Board	Amosite	Unsealed Spray or	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Low Risk	6	14/12/2022	Identified	High Risk	85380	BA8730	9302/2	30/08/2022	WHS
#REF!	SHA	Drumalane Estate	06	Ceilino Panel	Ceilino panels to switch room	Insulatino Board	Amosite	Unsealed Spray or	Low	Repair and affix labels	Re-inspection	HSG227	Unchecked	Medium Risk	7	14/03/2023	Identified	Medium Risk	85381	BA8730	9302/2	30/08/2022	WHS
#REF!	SHA	Drumalane Estate	06	NO ASBESTOS	Sealing strips to ceiling boards to switch room	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85382	BA8730		05/04/2018	
#REF!	SHA	Drumalane Estate	06	NO ASBESTOS	Ceiling panels to store	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85383	BA8730		05/04/2018	
#REF!	SHA	Drumalane Estate	06	NO ASBESTOS	Wall panel to boiler house	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85385	BA8730		05/04/2018	
#REF!	SHA	Drumalane Estate	06	NO ASBESTOS	Ceiling panels to boiler room	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85386	BA8730		05/04/2018	
#REF!	SHA	Drumalane Estate	02	Ceilino Panel	Ceilino panel	Insulatino Board	Amosite	Unsealed Spray or	Low	Manage and monitor	Re-inspection	HSG227	Checked	High Risk	6	14/12/2022	Identified	High Risk	85398	BA8728	9302/2	14/09/2022	WHS
#REF!	SHA	Drumalane Estate	04	Gaskets	Gasket debris at base of calorifier	Composite Material	Chrysotile	Loose Asbestos Debris	Low	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	Medium Risk	8	14/03/2023	Identified	Medium Risk	85411	BA8727	9302/2	30/08/2022	WHS
#REF!	SHA	Drumalane Estate	04	NO ASBESTOS	Redundant rope gasket	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85412	BA8727		05/04/2018	
#REF!	SHA	Drumalane Estate	04	Debris	Panel debris at access hatch to tank room	Insulating Board	Amosite	Loose Asbestos Debris	Loose asbestos debris or residue	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	High Risk	10	14/12/2022	Identified	High Risk	85413	BA8727	9300/22	30/08/2022	WHS
#REF!	SHA	Drumalane Estate	04	Debris	Board debris at entrance to duct	Insulatino Board	Amosite	Loose Asbestos Debris	Loose asbestos debris or residue	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	High Risk	10	14/12/2022	Identified	High Risk	85414	BA8727	9302/2	30/08/2022	WHS
#REF!	SHA	Drumalane Estate	04	NO ASBESTOS	Undercloak to porch at lobby	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85415	BA8727		05/04/2018	
#REF!	RAE	Drumglass Site	02	NO ASBESTOS	Soffit board debris to ground at entrance to store	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85416	BA8612	9506/18	31/01/2019	WHS
#REF!	RAE	Drumglass Site	02	NO ASBESTOS	Soffit board to canopy at entrance to store	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85417	BA8612	9506/18	31/01/2019	WHS
#REF!	RAA	South Tyrone Hospital	18							No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	Cannot Calculate Risk	0				85418		9506/18	22/11/2018	WHS
#REF!	RBB	Ballygawley Health Centre	01	NO ASBESTOS	Ceiling panel	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85419	AB910		23/04/2018	
#REF!	RBB	Ballygawley Health Centre	01	Ceiling Panel	Ceiling panel	Insulating Board	Amosite/Chrysotile	Unsealed	Medium	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	Medium Risk	9	03/04/2021	Identified	Medium Risk	85420	AB910	9302/2	18/11/2019	WHS
#REF!	RHA	Roxborough Site	01	Floor Tiles	Green speckled vinyl floor tiles and bitumen	Composite Material	Chrysotile	Composite Material	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Very Low Risk	3	08/04/2021	Identified	Very Low Risk	85421	AB911	9811/19	14/11/2019	WHS
#REF!	RHA	Roxborough Site	01	Insulating Debris	Debris to boiler house wall	General Debris	Amosite/Chrysotile	Unsealed	Loose asbestos debris or residue	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	High Risk	11	08/04/2021	Identified	High Risk	85422	AB911	9811/19	14/11/2019	WHS
#REF!	RHA	Roxborough Site	01	NO ASBESTOS	Soffit to generator room and store block	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85423	AB911		23/04/2018	
#REF!	RJA	Willowbank Resource Centre	01	Cement Flat Sheet	Durasteel to floor	Cement Products	Chrysotile	Cement Sheets	High	Repair, Encapsulate & Manage	Re-inspection	HSG227	Unchecked	Low Risk	6	27/03/2021	Identified	Low Risk	85424	AB912	9811/19	20/01/2020	WHS
#REF!	RJA	Willowbank Resource Centre	01	General Debris	Debris to timber in boiler house	General Debris	Chrysotile	Loose Asbestos Debris	Loose asbestos debris or residue	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	High Risk	10	27/03/2021	Identified	High Risk	85425	AB912	9811/19	20/01/2020	WHS
#REF!	RJA	Willowbank Resource Centre	01	NO ASBESTOS	Debris to floor in boiler house	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85426	AB912		23/04/2018	
#REF!	QBC	Gilford Health Centre	01	NO ASBESTOS	Green vinyl floor tiles	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85444	AB913	9506/18	30/01/2019	WHS
#REF!	QBC	Gilford Health Centre	01	NO ASBESTOS	Ceiling to switch room	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85445	BA8755	9506/18	30/01/2019	WHS
#REF!	QBC	Gilford Health Centre	01	Ceiling Panel	Porch to lobby - ceiling panel	Insulating Board	Amosite/Chrysotile	Unsealed Asbestos Insulation	None	Manage & Affix ID Labels	Re-inspection	HSG227	Unchecked	Low Risk	5	09/09/2023	Identified	Low Risk	85446	BA8755	9302/2	11/04/2022	WHS
#REF!	QLA	Burnside Family Centre	01	Sink Pad	Sink pad	Composite Material		Composite Material	Very Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Very Low Risk	1	13/10/2023	Identified	Very Low Risk	85447	AB914	9302/2	29/09/2022	WHS
#REF!	QLA	Burnside Family Centre	01	NO ASBESTOS	Textured coating	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85448	AB914		23/04/2018	
#REF!	QLA	Burnside Family Centre	01	NO ASBESTOS	Sink pad	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85449	AB914		23/04/2018	
#REF!	QHA	Moylinn House	01	NO ASBESTOS	Lining panel to doors and inside switch cupboard	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85450	AB916		23/04/2018	
#REF!	QHA	Moylinn House	01	NO ASBESTOS	Debris to boiler house walls	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85451	AB916		23/04/2018	
#REF!	QHA	Moylinn House	01	NO ASBESTOS	Dust to floor of boiler house	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85452	AB916		23/04/2018	
#REF!	QHA	Moylinn House	01	Loose Fill Insulation	Exhaust baffle	Thermal Insulation	Presumed Asbestos	Enclosed Pipework Insulation	Very Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Medium Risk	8	13/10/2023	Stronglv Presumed	Medium Risk	85453		9302/2	29/09/2022	WHS
#REF!	QHA	Moylinn House	01	Gaskets	Gaskets to boilers/burners	Composite Material	Presumed Asbestos	Composite Material	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Low Risk	5	13/10/2023	Stronglv Presumed	Low Risk	85454		9302/2	29/09/2022	WHS
#REF!	QPB	Manor Centre and Stores	01	NO ASBESTOS	Facia panel (lower)	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85458	AB917	9506/18	29/01/2019	WHS
#REF!	QPB	Manor Centre and Stores	01	NO ASBESTOS	Facia panel (upper)	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85459	AB917	9506/18	29/01/2019	WHS
#REF!	QAB	Banbridge Polyclinic	15	Door Panel	Interior panel to door to tank room	Insulating Board	Chrysotile	Unsealed	Very Low	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	Low Risk	6	09/09/2023	Identified	Low Risk	85460	AB915	9302/2	06/04/2022	WHS
#REF!	QAB	Banbridge Polyclinic	15	NO ASBESTOS	Debris to floor	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85461	AB915	9506/18	28/01/2019	WHS
#REF!	RBC	Markethill Health Centre	01	NO ASBESTOS	Sealing strips to boiler room ceiling	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85463	AB918	9506/1A	25/01/2019	WHS
#REF!	RBC	Markethill Health Centre	01	NO ASBESTOS	Ceiling panels to boiler room	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85464	AB918	9506/18	25/01/2019	WHS
#REF!	RBC	Markethill Health Centre	01	NO ASBESTOS	Sink pads to kitchen	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85465	AB918	9506/18	25/01/2019	WHS
#REF!	RBC	Markethill Health Centre	01	NO ASBESTOS	External DPC	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85466	AB918	9506/18	25/01/2019	WHS
#REF!	SJJ	Cedar Grove Site	02	NO ASBESTOS	Undercloak to garage	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85467	BA8754		10/04/2018	
#REF!	QAC	Lurgan Hospital	01	NO ASBESTOS	Pipe lagging	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85468	J012521	9506/18	11/08/2018	WHS
#REF!	QAC	Lurgan Hospital	01	NO ASBESTOS	Ceiling board	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85469	J012521	9506/18	11/08/2018	WHS
#REF!	QAC	Lurgan Hospital	01	NO ASBESTOS	Cowling cover	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85470	J012521	9506/18	11/08/2018	WHS
#REF!	QAC	Lurgan Hospital	02	NO ASBESTOS	Ceiling board	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85471	J012522		20/12/2017	
#REF!	QAC	Lurgan Hospital	02	NO ASBESTOS	Ceiling board	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85472	J012522		20/12/2017	
#REF!	QAC	Lurgan Hospital	02	NO ASBESTOS	Residue to wall	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85473	J012108		04/12/2017	
#REF!	QAC	Lurgan Hospital	02	NO ASBESTOS	Residue to wall	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85474	J012108		04/12/2017	
#REF!	QAC	Lurgan Hospital	02	Residue to Walls	Residue to wall	Thermal Insulation	Amosite/Chrysotile	Unsealed	Loose asbestos debris or residue	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	High Risk	11	20/09/2023	Identified	High Risk	85475	J012108	9302/2	12/09/2022	WHS
#REF!	QAC	Lurgan Hospital	02	NO ASBESTOS	Residue to wall	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85476	J012108		04/12/2017	
#REF!	QAC	Lurgan Hospital	02	Residue to Walls	Residue to wall	Thermal Insulation	Chrysotile	Unsealed	Loose asbestos debris or residue	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	High Risk	10	20/12/2022	Identified	High Risk	85477	J012108	9302/2	12/09/2022	WHS
#REF!	QAC	Lurgan Hospital	02	NO ASBESTOS	Residue to wall	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85478	J012108		04/12/2017	
#REF!	QAC	Lurgan Hospital	02	Residue to Walls	Residue to wall	Thermal Insulation	Amosite/Chrysotile	Unsealed	Loose asbestos debris or residue	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	High Risk	11	20/09/2023	Identified	High Risk	85479	J012108	9302/2	12/09/2022	WHS
#REF!	QAC	Lurgan Hospital	02	Residue to Walls	Residue to wall	Thermal Insulation	Amosite/Chrysotile	Unsealed	Loose asbestos debris or residue	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	High Risk	11	20/12/2022	Identified	High Risk	85480	J012108	9302/2	12/09/2022	WHS
#REF!	RAE	Drumglass Site	02	NO ASBESTOS	Ceiling to boiler house	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85635	BA8857	9506/18	31/01/2019	WHS
#REF!	RAE	Drumglass Site	02	NO ASBESTOS	Ceiling to switch room	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85636	BA8857	9506/18	31/01/2019	WHS
#REF!	RAE	Drumglass Site	02	NO ASBESTOS	Loose broken board resting on pipe work to ceilino void above corridor	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85637	BA8857	9506/18	31/01/2019	WHS
#REF!	RAE	Drumglass Site	02	Board	Exposed soffit/cavity closer to ceilino void above corridor	Insulating Board	Amosite/Chrysotile	Unsealed Board	Loose asbestos debris or residue	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	Medium Risk	9	03/01/2024	Identified	Medium Risk	85638	BA8857	9302/22	03/01/2023	WHS
#REF!	RAE	Drumglass Site	02	NO ASBESTOS	Ceiling to walkway opening	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85639	BA8857	9506/18	31/01/2019	WHS
#REF!	RAE	Drumglass Site	02	NO ASBESTOS	Canopy over deoor opposite stairwell	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85640	BA8857	9506/18	31/01/2019	WHS
#REF!	SBB	Crossmaglen Health Centre	01	NO ASBESTOS	Yellow painted panels to door	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85641	BA8512		12/01/2018	
#REF!	SBB	Crossmaglen Health Centre	01	Floor Tile and Bitumen Adhesive	Floor tile	Composite Material	Chrysotile	Composite Material	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Very Low Risk	3	21/09/2023	Identified	Very Low Risk	85642	BA8512	9302/2	01/06/2022	WHS
#REF!	SBB	Crossmaglen Health Centre	01	NO ASBESTOS	Mastic ceino to CWST above waitino room B-011	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85643	BA8512		12/01/2018	

#REF!	SBB	Crossmaglen Health Centre	01	NO ASBESTOS	Snot to wall	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85644	BAB512		12/01/2018		
#REF!	SBB	Crossmaglen Health Centre	01	NO ASBESTOS	Debris to floor	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85645	BAB512		12/01/2018		
#REF!	SBB	Crossmaglen Health Centre	01	Cement Flue	Cement flue pipe penetration to wall behind tank	Cement Products	Chrysotile	Cement Asbestos	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Very Low Risk	4	21/09/2023	Identified	Very Low Risk	85646	BAB512	9300/22	01/06/2022	WHS	
#REF!	SBD	Newtownhamilton Health Centre	01	NO ASBESTOS	Floor covering	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85647	BAB513		12/01/2018		
#REF!	SBD	Newtownhamilton Health Centre	01	Door Panel	Panel to door	Insulating Board	Amosite	Unsealed	Low	Label & Manage	Re-inspection	HSG227	Unchecked	Medium Risk	8	12/03/2023	Identified	Medium Risk	85648	BAB513	9300/22	02/09/2022	WHS	
#REF!	SBD	Newtownhamilton Health Centre	01	General Debris	Debris to floor behind boiler	General Debris	Amosite	Loose Asbestos Debris	Loose asbestos debris or residue	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	High Risk	11	12/12/2022	Identified	High Risk	85649	BAB513	9300/22	02/09/2022	WHS	
#REF!	SBD	Newtownhamilton Health Centre	01	Pipe Residue	Residue to vertical pipe behind boiler RHS	Thermal Insulation	Amosite	Unsealed	Loose asbestos debris or residue	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	High Risk	11	12/12/2022	Identified	High Risk	85650	BAB513	9300/22	02/09/2022	WHS	
#REF!	SBD	Newtownhamilton Health Centre	01	Pipe Residue	Residue to vertical pipe behind boiler LHS	Thermal Insulation	Amosite	Unsealed	Loose asbestos debris or residue	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	High Risk	11	12/12/2022	Identified	High Risk	85651	BAB513	9300/22	02/09/2022	WHS	
#REF!	SBD	Newtownhamilton Health Centre	01	Debris Material	Gasket debris to floor	Loose Asbestos	Chrysotile	Unsealed	Loose asbestos debris or residue	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	High Risk	10	12/12/2022	Identified	High Risk	85652	BAB513	9300/22	02/09/2022	WHS	
#REF!	SBD	Newtownhamilton Health Centre	01	Residue to Walls	Snot at wall to flue pipe	Thermal Insulation	Amosite	Unsealed	Loose asbestos debris or residue	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	High Risk	11	12/12/2022	Identified	High Risk	85653	BAB513	9300/22	02/09/2022	WHS	
#REF!	SBD	Newtownhamilton Health Centre	01	Residue to Walls	Snot at wall to flue oioe	Thermal Insulation	Amosite	Unsealed	Loose asbestos debris or residue	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	High Risk	11	12/12/2022	Identified	High Risk	85654	BAB513	9300/22	02/09/2022	WHS	
#REF!	SBD	Newtownhamilton Health Centre	01	Cement Flue	Flue oioe to corner behind boiler	Cement Products	Chrysotile	Unsealed	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Low Risk	6	12/09/2023	Identified	Low Risk	85655	BAB513	9300/22	02/09/2022	WHS	
#REF!	SHC	Slieve Roe	01	NO ASBESTOS	Panel to access hatch to roofspace	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85656	AB898		19/01/2018		
#REF!	SHC	Slieve Roe	01	NO ASBESTOS	Panel to access hatch at roofspace	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85657	AB898		19/01/2018		
#REF!	SHC	Slieve Roe	01	NO ASBESTOS	Panel to door at corridor	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85658	AB898		19/01/2018		
#REF!	SHC	Slieve Roe	01	NO ASBESTOS	Door panel at corridor	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85659	AB898		19/01/2018		
#REF!	SHC	Slieve Roe	01	NO ASBESTOS	Insulating board below window at corridor	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85660	AB898		19/01/2018		
#REF!	SHC	Slieve Roe	01	NO ASBESTOS	Door panel at corridor	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85661	AB898		19/01/2018		
#REF!	SHC	Slieve Roe	01	Woven	Debris to floor to kitchen store	Textiles & Paper	Chrysotile	Unsealed	Loose asbestos debris or residue	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	Medium Risk	9	12/12/2022	Identified	High Risk	85662	AB898	9300/22	30/08/2022	WHS	
#REF!	SHA	Drumalane Estate	09	Door Panel	Panel to door	Insulating Board	Amosite	Unsealed Asbestos Insulation Board	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Medium Risk	7	14/03/2023	Identified	Medium Risk	85667	BAB731	9300/22	06/04/2022	WHS	
#REF!	SHA	Drumalane Estate	09	Door Panel	Panel to door	Insulating Board	Amosite	Unsealed Asbestos Insulation Board	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Medium Risk	7	14/03/2023	Identified	Medium Risk	85668	BAB731	9300/22	06/04/2022	WHS	
#REF!	SHA	Drumalane Estate	09	Door Panel	Panel to door	Cement Products	Chrysotile	Unsealed Cement	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Very Low Risk	4	14/09/2023	Identified	Very Low Risk	85669	BAB731	9300/22	06/04/2022	WHS	
#REF!	SHA	Drumalane Estate	09	NO ASBESTOS	Step nosing	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85670	BAB731		05/04/2018		
#REF!	SHA	Drumalane Estate	09	Stair Nosing	Step nosing	Composite Material	Chrysotile	Composite Material	Medium	Manage and monitor	Re-inspection	HSG227	Unchecked	Very Low Risk	4	14/09/2023	Identified	Very Low Risk	85671	BAB731	9300/22	06/04/2022	WHS	
#REF!	SHA	Drumalane Estate	09	Door Panel	Panel to door	Insulating Board	Amosite	Unsealed Asbestos Insulation Board	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Medium Risk	7	14/03/2023	Identified	Medium Risk	85672	BAB731	9300/22	06/04/2022	WHS	
#REF!	SHA	Drumalane Estate	09	NO ASBESTOS	Vinyl floor tiles	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85673	BAB731		05/04/2018		
#REF!	SHA	Drumalane Estate	09	Ceilins Panel	Ceilino panel	Insulating Board	Amosite	Unsealed Asbestos Insulation Board	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Medium Risk	7	14/03/2023	Identified	Medium Risk	85674	BAB731	9300/22	06/04/2022	WHS	
#REF!	RSA	Dungannon Clinic	01	Residue to Walls	Snot to wall	Thermal Insulation	NO ASBESTOS	Unsealed	Loose asbestos debris or residue	No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	13/04/2022	Identified	Asbestos Removed	85676	AB908	9000/21	19/11/2019	WHS	
#REF!	RSA	Dungannon Clinic	01	Residue to Walls	Snot to wall	Thermal Insulation	NO ASBESTOS	Unsealed	Loose asbestos debris or residue	No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	13/04/2022	Identified	Asbestos Removed	85677	AB908	9000/21	19/11/2019	WHS	
#REF!	RSA	Dungannon Clinic	01	Residue to Walls	Snot to wall	Thermal Insulation	NO ASBESTOS	Unsealed	Loose asbestos debris or residue	No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	13/04/2022	Identified	Asbestos Removed	85678	AB908	9000/21	19/11/2019	WHS	
#REF!	NAB	St.Lukes	16	NO ASBESTOS	Ceiling panel to rear entrance lobby	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85679	BAB263	9509/18	19/07/2018	WHS	
#REF!	NAB	St.Lukes	19	Paoer	Backino to low level heatino panels	Textiles & Paoer	Chrysotile	Unsealed	Medium	Manage and monitor	Re-inspection	HSG227	Unchecked	Medium Risk	8	25/08/2020	Identified	Medium Risk	85680	BAB263	9512/21	20/01/2020	WHS	
#REF!	NAB	St.Lukes	19	Paper	Paper to pipe work	Textiles & Paper	Chrysotile	Unsealed	Medium	Manage and monitor	Re-inspection	HSG227	Unchecked	Medium Risk	8	25/08/2020	Identified	Medium Risk	85681	BAB263	9512/21	20/01/2020	WHS	
#REF!	NAB	St.Lukes	25	Ceiling Panel	Ceiling to store room	Insulating Board	Amosite/Chrysotile	Unsealed Asbestos Insulation Board	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Medium Risk	7	02/03/2021	Identified	Medium Risk	85682	BAB263	9512/21	03/01/2020	WHS	
#REF!	NAB	St.Lukes	28	Gaskets	Soare Gasket	Textiles & Paoer	Chrysotile	Unsealed	Medium	Remove	Re-inspection	HSG227	Unchecked	Medium Risk	8	04/03/2021	Identified	Medium Risk	85683	BAB263	9512/21	03/01/2020	WHS	
#REF!	NAB	St.Lukes	28	Gaskets	Spare gasket	Textiles & Paper	Chrysotile	Unsealed	Medium	remove	Re-inspection	HSG227	Unchecked	Medium Risk	8	02/03/2021	Identified	Medium Risk	85684	BAB263	9512/21	03/01/2020	WHS	
#REF!	NAB	St.Lukes	28	Gaskets	Spare gasket	Textiles & Paper	Chrysotile	Unsealed	Medium	Remove	Re-inspection	HSG227	Unchecked	Medium Risk	8	02/03/2021	Identified	Medium Risk	85685	BAB263	9512/21	03/01/2020	WHS	
#REF!	NAB	St.Lukes	28	Fuse Flash Guards	Flash guard to fluorescent switch	Textiles & Paoer	Chrysotile	Unsealed	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Medium Risk	7	02/03/2021	Identified	Medium Risk	85686	BAB263	9512/21	03/01/2020	WHS	
#REF!	NAB	St.Lukes	12	NO ASBESTOS	Panels to doors	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85687	BAB263	9509/18	07/02/2018	WHS	
#REF!	NAB	St.Lukes	13	NO ASBESTOS	Panels either side of doors	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85692	BAB263	9509/18	19/06/2018	WHS	
#REF!	NAB	St.Lukes	13	Pioe Laoaino	Laoaino to oiowork	Thermal Insulation	Chrysotile / Amosite /	Unsealed	Medium	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	High Risk	11	27/01/2021	Identified	High Risk	85693	BAB263	9512/21	03/01/2020	WHS	
#REF!	NAB	St.Lukes	13	Rooes	Rooe to oioe work	Textiles & Paoer	Chrysotile	Unsealed	Medium	Manage and monitor	Review – No Change	HSG227	Unchecked	Medium Risk	8	27/01/2021	Identified	Medium Risk	85694	BAB263	9512/21	03/01/2020	WHS	
#REF!	NAB	St.Lukes	13	Paper	Paper to pipe work debris to duct	Textiles & Paper	Chrysotile	Unsealed	Medium	Remove	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	27/01/2021	Identified	Asbestos Removed	85695	BAB263	9512/21	03/01/2020	WHS	
#REF!	NAB	St.Lukes	20	Residue to Walls	Snot to wall	Thermal Insulation	Chrysotile / Amosite /	Unsealed	Loose asbestos debris or residue	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	High Risk	12	25/05/2020	Identified	High Risk	85696	BAB263	9512/21	05/12/2019	WH Stephens	
#REF!	NAB	St.Lukes	20	Cement Products	Cavity closer	Cement Products	Chrysotile	Cement Asbestos	Medium	Manage and monitor	Re-inspection	HSG227	Unchecked	Low Risk	5	24/02/2021	Identified	Low Risk	85697	BAB263	9512/21	05/12/2019	WHS	
#REF!	RAE	Drumglass Site	01	Roof Slate	Roof slate	Cement Products	Chrysotile	Cement Asbestos	Medium	Manage and monitor	Re-inspection	HSG227	Unchecked	Low Risk	5	27/03/2021	Identified	Low Risk	85699	BSR339	9512/21	19/11/2019	WHS	
#REF!	RBC	Markethill Health Centre	01	Bitumen Adhesive	Bitumen adhesive to floor	Composite Material	NO ASBESTOS	Composite Material	Medium	No further action required (Asbestos removed)	ACM Removed	HSG227	Unchecked	NO ASBESTOS	0	14/06/2019	Identified	Asbestos Removed	85701	BSR311	9509/18	25/01/2019	WHS	
#REF!	RBC	Markethill Health Centre	01	Bitumen Adhesive	Bitumen adhesive to floor	Composite Material	NO ASBESTOS	Composite Material	Medium	No further action required (Asbestos removed)	ACM Removed	HSG227	Unchecked	NO ASBESTOS	0	14/06/2019	Identified	Asbestos Removed	85702	BSR311	9509/18	25/01/2019	WHS	
#REF!	RBC	Markethill Health Centre	01	NO ASBESTOS	Sink pad	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85703	BSR311	9509/18	25/01/2019	WHS	
#REF!	RHC1	Lisanally House	01	NO ASBESTOS	Floor tile	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85704	BSR825	9509/18	11/05/2018	WHS	
#REF!	SAA	Daisy Hill Hospital Estate	07	NO ASBESTOS	Wall board (stud wall)	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85705	BAB745	9509/18	19/11/2018	WHS	
#REF!	SAA	Daisy Hill Hospital Estate	07	NO ASBESTOS	Fibreboard above suspended ceiling	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85706	BAB745	9509/18	19/11/2018	WHS	
#REF!	SAA	Daisy Hill Hospital Estate	07	Board	Board to ceiling hatch	Insulating Board	Amosite	Unsealed Asbestos Insulation Board	Areas of damage or deterioration	Label and Remove if likely to be disturbed	Re-inspection	HSG227	Unchecked	Medium Risk	8	14/03/2023	Identified	Medium Risk	85707	BAB745	9300/22	07/09/2022	WHS	
#REF!	SAA	Daisy Hill Hospital Estate	07	NO ASBESTOS	Fibreboard above suspended ceiling	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85708	BAB745	9509/18	19/11/2018	WHS	
#REF!	QAA	Craigavon Hospital	08	Brake Shoes	Brake pad	Cement Products	NO ASBESTOS	Cement Asbestos	Low	No further action required (Asbestos removed)	ACM Removed	HSG227	Unchecked	NO ASBESTOS	0	15/06/2019	Identified	Asbestos Removed	85709	BAB881		28/05/2018		
#REF!	QAA	Craigavon Hospital	08	Textiles & Paper	Cloth to pipe bracket	Textiles & Paper	NO ASBESTOS	Unsealed	Low	No further action required (Asbestos removed)	ACM Removed	HSG227	Unchecked	NO ASBESTOS	0	15/12/2018	Identified	Asbestos Removed	85710	BAB881		28/05/2018		
#REF!	QAA	Craigavon Hospital	08	NO ASBESTOS	Gasket to redundant pipe flange	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85711	BAB881		28/05/2018		
#REF!	QAA	Craigavon Hospital	08	NO ASBESTOS	Residue to beam at high level	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85712	BAB881		28/05/2018		
#REF!	QAA	Craigavon Hospital	08	Pipe Brackets	Cloth to pipe bracket	Textiles & Paper	NO ASBESTOS	Unsealed	Medium	No further action required (Asbestos removed)	ACM Removed	HSG227	Unchecked	NO ASBESTOS	0	15/12/2018	Identified	Asbestos Removed	85713	BAB881		28/05/2018		
#REF!	QAA	Craigavon Hospital	08	NO ASBESTOS	Debris to floor below switch box	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85714	BAB881		28/05/2018		
#REF!	QAA	Craigavon Hospital	08	Panel	Board above door to room A-021	Insulating Board	NO ASBESTOS	Unsealed Asbestos Insulation Board	Low	No further action required (Asbestos removed)	ACM Removed	HSG227	Unchecked	NO ASBESTOS	0	15/12/2018	Identified	Asbestos Removed	85715	BAB881		28/05/2018		
#REF!	QAA	Craigavon Hospital	08	Board	Board above door to room A-019	Insulating Board	NO ASBESTOS	Unsealed Asbestos Insulation Board	Low	No further action required (Asbestos removed)	ACM Removed	HSG227	Unchecked	NO ASBESTOS	0	15/12/2018	Identified	Asbestos Removed	85716	BAB881		28/05/2018		
#REF!	QAA	Craigavon Hospital	08	NO ASBESTOS	Gasket to flange of RHS calorifier	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85717	BAB881		28/05/2018		
#REF!	QAA	Craigavon Hospital	08	NO ASBESTOS	Residue to flange of RHS calorifier	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85718	BAB881		28/05/2018		
#REF!	QAA	Craigavon Hospital	08	Pipe Residue	Residue to flange between the calorifiers	Thermal Insulation	NO ASBESTOS	Unsealed	Loose asbestos debris or residue	No further action required (Asbestos removed)	ACM Removed	HSG227	Unchecked	NO ASBESTOS	0	14/09/2018	Identified	Asbestos Removed	85719	BAB881		28/05/2018		
#REF!	QAA	Craigavon Hospital	08	General Debris	Debris to duct in front of calorifiers	General Debris	NO ASBESTOS	Loose Asbestos Debris	Loose asbestos debris or residue	No further action required (Asbestos removed)	ACM Removed	HSG227	Unchecked	NO ASBESTOS	0	14/09/2018	Identified	Asbestos Removed	85720	BAB881		28/05/2018		
#REF!	QAA	Craigavon Hospital	08	NO ASBESTOS	Lagging to pipe work in pit LHS of calorifiers	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85721	BAB881		28/05/2018		
#REF!	QAA	Craigavon Hospital	08	NO ASBESTOS	Debris to pit LHSof calorifiers	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85722	BAB881		28/05/2018		
#REF!	QAA	Craigavon Hospital	08	General Debris	Debris to pit LHS of calorifiers	General Debris	NO ASBESTOS	Loose Asbestos Debris	Loose asbestos debris or residue	No further action required (Asbestos removed)	ACM Removed	HSG227	Unchecked	NO ASBESTOS	0	14/09/2018	Identified	Asbestos Removed	85723	BAB881		28/05/2018		
#REF!	QAA	Craigavon Hospital	08	NO ASBESTOS	Debris to pit LhS of calorifiers	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85724	BAB881		28/05/2018		
#REF!	QAA	Craigavon Hospital	08	Residue to Walls	Snot to wall LHS of door	Thermal Insulation	NO ASBESTOS	Unsealed	Loose asbestos debris or residue	No further action required (Asbestos removed)	ACM Removed	HSG227	Unchecked	NO ASBESTOS	0	14/09/2018	Identified	Asbestos Removed	85725	BAB881		28/05/2018		
#REF!	QAA	Craigavon Hospital	08	NO ASBESTOS	Residue to wall of central pit	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85726	BAB881		28/05/2018		
#REF!	QAA	Craigavon Hospital	08	General Debris	Debris to floor of central pit	General Debris	NO ASBESTOS	Loose Asbestos Debris	Loose asbestos debris or residue	No further action required (Asbestos removed)	ACM Removed	HSG227	Unchecked	NO ASBESTOS	0	14/09/2018	Identified	Asbestos Removed	85727	BAB881		28/05/2018		
#REF!	QAA	Craigavon Hospital	08	NO ASBESTOS	Debris to floor of central pit	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85728	BAB881		28/05/2018		
#REF!	QAA	Craigavon Hospital	08	NO ASBESTOS	Debris to green switch box LHS wall	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85729	BAB881		28/05/2018		
#REF!	QAA	Craigavon Hospital	08	NO ASBESTOS	Debris to walsall switch box LHS wall	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85730	BAB881		28/05/2018		
#REF!	QAA	Craigavon Hospital	08	NO ASBESTOS	Debris to switch gear LHS wall	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85731	BAB881		28/05/2018		
#REF!	QAA	Craigavon Hospital	08	NO ASBESTOS	Debris to floor	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85732	BAB881		28/05/2018		
#REF!	QAA	Craigavon Hospital	08	NO ASBESTOS	Debris to switch gear RHS wall	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85733	BAB881		28/05/2018		
#REF!	QAA	Craigavon Hospital	08	NO ASBESTOS	Debristo switch gear RHS wall	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85734	BAB881		28/05/2018		
#REF!	QAA	Craigavon Hospital	08	General Debris	Debris to cable trunking at high level LHS wall	General Debris	NO ASBESTOS	Loose Asbestos Debris	Loose asbestos debris or residue	No further action required (Asbestos removed)	ACM Removed	HSG227	Unchecked	NO ASBESTOS	0	14/09/2018	Identified	Asbestos Removed	85735	BAB881		28/05/2018		
#REF!	QAA	Craigavon Hospital	08	NO ASBESTOS	Vinyl floor covering beneath ohamaae Washers	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85736	BAB881		28/05/2018		
#REF!	QAA	Craigavon Hospital	08	NO ASBESTOS	Board to back of slectrics	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85737	BAB881		28/05/2018		
#REF!	QAA	Craigavon Hospital	08	Board	Board to bulk head at bottom of stairs	Insulating Board	NO ASBESTOS	Unsealed Asbestos Insulation Board	Low	No further action required (Asbestos removed)	ACM Removed	HSG227	Unchecked	NO ASBESTOS	0	15/12/2018	Identified	Asbestos Removed	85738	BAB881		28/05/2018		
#REF!	QAA	Craigavon Hospital	08	Pipe Brackets	Cloth to pipe bracket	Textiles & Paper	NO ASBESTOS	Unsealed	Low	No further action required (Asbestos removed)	ACM Removed	HSG227	Unchecked	NO ASBESTOS	0	25/12/2018	Identified	Asbestos Removed	85739	BAB881		28/05/2018		

#REF!	QAA	Craigavon Hospital	08	NO ASBESTOS	Board to skylight	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85740	BA8881		28/05/2018	
#REF!	QAA	Craigavon Hospital	08	Ceiling Board	Ceiling board outside female barrier room	Insulating Board	NO ASBESTOS	Unsealed Asbestos Insulation Board	Low	No further action required (Asbestos removed)	ACM Removed	HSG227	Unchecked	NO ASBESTOS	0	15/12/2018	Identified	Asbestos Removed	85741	BA8881		28/05/2018	
#REF!	QAA	Craigavon Hospital	08	Ceiling Board	Ceiling board above door to A-001	Insulating Board	NO ASBESTOS	Unsealed Asbestos Insulation Board	Low	No further action required (Asbestos removed)	ACM Removed	HSG227	Unchecked	NO ASBESTOS	0	15/12/2018	Identified	Asbestos Removed	85742	BA8881		28/05/2018	
#REF!	QAA	Craigavon Hospital	08	NO ASBESTOS	Grey vinyl floor tile	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85743	BA8881		28/05/2018	
#REF!	QAA	Craigavon Hospital	08	NO ASBESTOS	White vinyl floor tile	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85744	BA8881		28/05/2018	
#REF!	QAA	Craigavon Hospital	08	NO ASBESTOS	Beige vinyl floor tile	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85745	BA8881		28/05/2018	
#REF!	QAA	Craigavon Hospital	08	Fire Break Panel	Fire break above double doors to A-022	Insulating Board	NO ASBESTOS	Unsealed Asbestos Insulation Board	Low	No further action required (Asbestos removed)	ACM Removed	HSG227	Unchecked	NO ASBESTOS	0	15/12/2018	Identified	Asbestos Removed	85746	BA8881		28/05/2018	
#REF!	QAA	Craigavon Hospital	08	Pipe Brackets	Cloth to oibe bracket	Textiles & Paoer	Chrvsotile	Unsealed	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Medium Risk	7	06/09/2023	Identified	Medium Risk	85747	BA8881	9302.2	18/10/2022	WHS
#REF!	QAA	Craigavon Hospital	08	NO ASBESTOS	Pin board at work station LHS to doors of rear liadino bav	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85748	BA8881		28/05/2018	
#REF!	QAA	Craigavon Hospital	08	NO ASBESTOS	Floor tile	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85749	BA8881		28/05/2018	
#REF!	QAA	Craigavon Hospital	08	NO ASBESTOS	Pin board at work station RHS to doors of rear liadino bav	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85750	BA8881		28/05/2018	
#REF!	QAA	Craigavon Hospital	08	NO ASBESTOS	Felt to roof of main laundry block	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85751	BA8881		28/05/2018	
#REF!	QAA	Craigavon Hospital	08	NO ASBESTOS	Coating to cladding panels to roof too of laundrv	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85752	BA8881		28/05/2018	
#REF!	QAA	Craigavon Hospital	08	NO ASBESTOS	Panel at low level adjacent steps outside B-002	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85753	BA8881		28/05/2018	
#REF!	QAA	Craigavon Hospital	08	NO ASBESTOS	DPc to plant room	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85754	BA8881		28/05/2018	
#REF!	QAA	Craigavon Hospital	08	Mastic	Sealant to water tank panels	Composite Material	Chrvsotile	Composite Material	Areas of damage or deterioration	Manage and monitor	Re-inspection	HSG227	Unchecked	Verv Low Risk	4	06/09/2023	Identified	Verv Low Risk	85755	BA8881	9310.2	18/10/2022	WHS
#REF!	QAA	Craigavon Hospital	08	NO ASBESTOS	Coating to cladding panels of plant room C-001	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85756	BA881		28/05/2018	
#REF!	QAA	Craigavon Hospital	08	Pipe Lagging	hard set lagging to exposed ductwork and	Thermal Insulation	NO ASBESTOS	Unsealed	Medium	No further action required (Asbestos removed)	ACM Removed	HSG227	Unchecked	NO ASBESTOS	0	21/09/2018	Identified	Asbestos Removed	85757	BA8914		12/06/2018	
#REF!	QAA	Craigavon Hospital	08	NO ASBESTOS	Residue to flange top of pit	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85758	BA8914		12/06/2018	
#REF!	RAA	South Tyrone Hospital	19	Residue to Walls	Shot to wall behind fresh air pipe	Thermal Insulation	Amosite/Chrysotile	Unsealed	Loose asbestos	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	High Risk	11	15/12/2023	Identified	High Risk	85759	BA8871	9302.2	15/12/2022	WHS
#REF!	RAA	South Tyrone Hospital	19	Residue to Walls	Snot to wall LHS hish level	Thermal Insulation	Amosite/Chrysotile	Unsealed	Loose asbestos	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	High Risk	11	15/12/2023	Identified	High Risk	85760	BA8871	9302.2	15/12/2022	WHS
#REF!	RAA	South Tyrone Hospital	19	Residue to Walls	Snot to wall LHS hish level	Thermal Insulation	Amosite/Chrysotile	Unsealed	Loose asbestos	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	High Risk	11	15/12/2023	Identified	High Risk	85761	BA8871	9302.2	15/12/2022	WHS
#REF!	RAA	South Tyrone Hospital	19	NO ASBESTOS	Debris to floor LHS	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85762	BA8871		9506/18	20/11/2018	WHS
#REF!	RAA	South Tyrone Hospital	01	NO ASBESTOS	Snot to rear wall	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85763	BA8873		9506/18	11/12/2018	WHS
#REF!	RAA	South Tyrone Hospital	01	NO ASBESTOS	Snot to wall, rear of RHS wall	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85764	BA8873		9506/18	11/12/2018	WHS
#REF!	RAA	South Tyrone Hospital	01	NO ASBESTOS	Debris to sump at front of room	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85765	BA8873		9506/18	11/12/2018	WHS
#REF!	RAA	South Tyrone Hospital	01	NO ASBESTOS	Debris to floor RHS of boiler	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85766	BA8873		9506/18	11/12/2018	WHS
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Snot to RHS wall	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85767	BA8870		9506/18	12/05/2018	WHS
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Flange gasket to angled blanking plate	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85768	BA8870		9506/18	12/05/2018	WHS
#REF!	RAA	South Tyrone Hospital	17	Gaskets	Flange gasket to pump/oipe	Composite Material	Chrvsotile	Composite Material	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Verv Low Risk	3	09/03/2021	Identified	Verv Low Risk	85769	BA8870	9513.2	19/12/2019	WHS
#REF!	RAA	South Tyrone Hospital	15	Residue to Walls	Snot to rear wall	Thermal Insulation	Amosite/Chrysotile	Unsealed	Loose asbestos	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	High Risk	11	15/12/2023	Identified	High Risk	85770	BA8872	9302.2	15/12/2022	WHS
#REF!	RAA	South Tyrone Hospital	15	Residue to Walls	Snot to rear wall	Thermal Insulation	Amosite/Chrysotile	Unsealed	Loose asbestos	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	High Risk	11	15/12/2023	Identified	High Risk	85771	BA8872	9302.2	15/12/2022	WHS
#REF!	RAA	South Tyrone Hospital	15	NO ASBESTOS	Flange gasket to LHS	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85772	BA8872		9506/18	22/11/2018	WHS
#REF!	QAA	Craigavon Hospital	01	Pipe Brackets	Cloth to oibe brackets	Textiles & Paoer	Chrvsotile	Unsealed	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Medium Risk	7	29/09/2023	Identified	Medium Risk	85778	BA8921	9302.2	29/09/2022	WHS
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Vinyl floor tile to cupboard off corridor	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85779	BA8921		18/06/2018	
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Vinyl floor tile	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85780	BA8921		18/06/2018	
#REF!	QAA	Craigavon Hospital	01	Pipe Brackets	Cloth to pipe bracket	Textiles & Paper	Chrysotile	unsealed	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Medium Risk	7	15/09/2023	Identified	Medium Risk	85781	BA8921	9302.2	15/09/2022	WHS
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Panel above doors both sides	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85782	BA8921		18/06/2018	
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Panel above doors both sides	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85783	BA8921		18/06/2018	
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Vinyl floor tile	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85784	BA8921		18/06/2018	
#REF!	QAA	Craigavon Hospital	01	Fuse Flash Guards	Flashouards to electrical fusebox	Textiles & Paoer	Presumed Asbestos	Unsealed	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Medium Risk	9	11/10/2023	Presumed	Medium Risk	85785	BA8921	9302.2	11/10/2022	WHS
#REF!	QAA	Craigavon Hospital	01	Pipe Brackets	Cloth to pipe bracket	Textiles & Paper	Presumed Asbestos	unsealed	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Medium Risk	9	29/09/2023	Identified	Medium Risk	85786	BA8921	9302.2	29/09/2022	WHS
#REF!	QAA	Craigavon Hospital	01	Pipe Brackets	Cloth to pipe bracket throughout entire corridor	Textiles & Paper	Presumed Asbestos	unsealed	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Medium Risk	9	11/10/2023	Strongly Presumed	Medium Risk	85787		9302.2	11/10/2022	WHS
#REF!	QAA	Craigavon Hospital	01	Door Panel	Double doors - both sides to	Insulating Board	Presumed Asbestos	Unsealed Board	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Medium Risk	8	15/09/2023	Identified	Medium Risk	85788	BA8921	9302.2	15/09/2022	WHS
#REF!	QAA	Craigavon Hospital	01	Floor Tiles	Vinyl floor tile	Composite Material	Presumed Asbestos	Composite Material	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Low Risk	5	15/09/2023	Strongly Presumed	Low Risk	85789	BA8921	9302.2	15/09/2022	WHS
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Debris to floor entrance	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85790	A8906		9506/18	12/05/2018	WHS
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Vinyl floor tile at entrance	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85791	A8906		9506/18	12/05/2018	WHS
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Debris to switchboard on LHS wall	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85792	A8906		9506/18	12/05/2018	WHS
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Debris to ledge on LHS wall	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85793	A8906		9506/18	12/05/2018	WHS
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Debris to floor grid	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85794	A8906		9506/18	12/05/2018	WHS
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Lagging to pipe at rear wall	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85795	A8906		9506/18	12/05/2018	WHS
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Residue to SVP	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85796	A8906		9506/18	12/05/2018	WHS
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Debris to door ledge	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85797	A8906		9506/18	12/05/2018	WHS
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Debris to floor grid	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85798	A8906		9506/18	12/05/2018	WHS
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Debris to floor grid	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85799	A8906		9506/18	12/05/2018	WHS
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Debris to electric box	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85800	A8906		9506/18	12/05/2018	WHS
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Debris to pipe bracket	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85801	A8906		9506/18	12/05/2018	WHS
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Partition wall	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85802	BA8882		28/05/2018	
#REF!	QAA	Craigavon Hospital	01	Sink Pad	Sink pad to relatives suite	Composite Material	Chrysotile	Composite Material	Medium		New Incident	HSG227	Unchecked	Very Low Risk	4	27/06/2019	Identified	Very Low Risk	85803	BA8882		28/05/2018	
#REF!	QHD	Transna House	01	NO ASBESTOS	Flange gasket to pipework at rear of boiler 1	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85804	BA8905		08/06/2018	
#REF!	QHD	Transna House	01	Cement Products	Cavity close in switch room within boiler room	Cement Products	Chrysotile	Cement Sheets	Areas of damage or deterioration	Encapsulate, label and manage	Re-inspection	HSG227	Unchecked	Low Risk	5	14/10/2023	Identified	Verv Low Risk	85805	BA8905	9299/22	29/09/2022	WHS
#REF!	QHD	Transna House	01	Ropes	Rope around exhaust vent in aenerator room	Textiles & Paper	Chrysotile	Unsealed	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Medium Risk	7	15/04/2023	Identified	Medium Risk	85806	BA8905	9299/22	29/09/2022	WHS
#REF!	QHD	Transna House	01	NO ASBESTOS	Vertical board above entrance lobby doors	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85807	BA8905		08/06/2018	
#REF!	QHD	Transna House	01	Verge Cloak	Verge undercloak to main roof to	Cement Products	Chrysotile	unsealed	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Low Risk	6	14/10/2023	Identified	Low Risk	85808	BA8905	9299/22	29/09/2022	WHS
#REF!	QHD	Transna House	01	NO ASBESTOS	Panel above fire exit door at annex	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85809	BA8905		28/06/2018	
#REF!	QHD	Transna House	01	NO ASBESTOS	Cladding panel to porch at fire exit door to annex	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85810	BA8905		08/06/2018	
#REF!	QHD	Transna House	01	NO ASBESTOS	Roofing felt to external shed	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85811	BA8905		08/06/2018	
#REF!	QHD	Transna House	01	NO ASBESTOS	Bitumen sink pad to kitchen in annex	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85812	BA8905		08/06/2018	
#REF!	QHD	Transna House	01	NO ASBESTOS	Sarking felt in roof void over annex in kitchen	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85813	BA8905		08/06/2018	
#REF!	QHD	Transna House	01	NO ASBESTOS	Green floor covering	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85814	BA8905		08/06/2018	
#REF!	QHD	Transna House	01	NO ASBESTOS	Sink pad to kitchen	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85815	BA8905		08/06/2018	
#REF!	QHD	Transna House	01	NO ASBESTOS	Door panel to kitchen door	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85816	BA8905		08/06/2018	
#REF!	QHD	Transna House	01	NO ASBESTOS	Bitumen adhesive to floor to store	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85817	BA8905		08/06/2018	
#REF!	QHD	Transna House	01	Sink Pad	Sink oad to kitchen	Composite Material	Chrysotile	Unsealed	High	Manage and monitor	Re-inspection	HSG227	Unchecked	Medium Risk	8	15/04/2023	Identified	Medium Risk	85818	BA8905	9299/22	29/09/2022	WHS
#REF!	QHD	Transna House	01	NO ASBESTOS	Verge undercloak of outside room B-047 to mortuary	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85819	BA8905		08/06/2018	
#REF!	QHD	Transna House	01	Door Panel	Door panel to oil tank room	Insulating Board	Presumed Asbestos	Unsealed Board	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Medium Risk	8	15/04/2023	Presumed	Medium Risk	85820		9299/22	29/09/2022	WHS
#REF!	QHD	Transna House	01	Gaskets	Gaskets	Composite Material	Presumed Asbestos	Composite Material	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Low Risk	5	14/10/2023	Presumed	Low Risk	85821		9299/22	29/09/2022	WHS
#REF!	QHD	Transna House	01	Fuse Flash Guards	Textile fuse oad & flash ouard panel	Textiles & Paper	Presumed Asbestos	Unsealed	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Medium Risk	9	15/04/2023	Presumed	Medium Risk	85822		9299/22	29/09/2022	WHS
#REF!	QHD	Transna House	01	Fuse Flash Guards	Textile fuse oad & flash ouard panel	Textiles & Paper	Presumed Asbestos	unsealed	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Medium Risk	9	15/04/2023	Presumed	Medium Risk	85823		9299/22	29/09/2022	WHS
#REF!	QHD	Transna House	01	Fuse Flash Guards	Textile fuse oad & flash ouard panel	Textiles & Paper	Presumed Asbestos	unsealed	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Medium Risk	9	15/04/2023	Presumed	Medium Risk	85824		9299/22	29/09/2022	WHS
#REF!	QHD	Transna House	01	Fuse Flash Guards	Textile fuse oad & flash ouard panel	Textiles & Paper	Presumed Asbestos	unsealed	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Medium Risk	9	15/04/2023	Presumed	Medium Risk	85825		9299/22	29/09/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Rear panel to heating riser in level 5 plant room in main block	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85826	BA8911		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Front panel to heating riser in level 5 plant room in main block	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85827	BA8911		9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Panel at high level LHS of entrance door	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85855	BA8942		9506/18	20/03/2019	WHS

#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Housing to roller shutter	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85856	BA8942	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Bitumen at high level to corridor outside room	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85857	BA8942	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Insulation to pipe work above suscended ceilins at lobby	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85858	BA8942	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Packer to beam in ceiling void in corridor	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85859	BA8942	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Packer to skylight on corridor, outside room C-314	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85860	BA8942	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Sink pad to staff room	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85861	BA8942	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Fire break above exit door in corridor	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85862	BA8942	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Bitumen to rafter in room	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85863	BA8942	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Packer to beam to store	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85864	BA8942	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Remains of broken fire break	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85865	BA8942	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Board above doors inside electrical cupboard	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85866	BA8942	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Board to existing door opening	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85867	BA8942	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Panel to ceiling in plant room	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85868	BA8942	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Putty to metal frame window in plant room	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85869	BA8942	9506/18	20/03/2019	WHS
#REF!	QAA	Craigavon Hospital	20	NO ASBESTOS	Floor covering to bathroom	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85872	BA8948		02/07/2018	
#REF!	QAA	Craigavon Hospital	20	NO ASBESTOS	Wall panel to room	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85873	BA8948		02/07/2018	
#REF!	QAA	Craigavon Hospital	20	NO ASBESTOS	Bath panel to room	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85874	BA8948		02/07/2018	
#REF!	QAA	Craigavon Hospital	20	NO ASBESTOS	Floor covering to toilet	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85875	BA8948		02/07/2018	
#REF!	QAA	Craigavon Hospital	20	NO ASBESTOS	Floor screed beneath vinyl floor coverino	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85876	BA8948		02/07/2018	
#REF!	QAA	Craigavon Hospital	20	NO ASBESTOS	Floor covering to room	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85877	BA8948		02/07/2018	
#REF!	QAA	Craigavon Hospital	20	NO ASBESTOS	Residue to pipe penetration to room	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85878	BA8948		02/07/2018	
#REF!	QAA	Craigavon Hospital	20	NO ASBESTOS	Floor covering to room	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85879	BA8948		02/07/2018	
#REF!	QAA	Craigavon Hospital	19	NO ASBESTOS	Floor covering to room	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85880	BA8948		02/07/2018	
#REF!	QAA	Craigavon Hospital	19	NO ASBESTOS	Fire break above door	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85881	BA8948		02/07/2018	
#REF!	QAA	Craigavon Hospital	19	NO ASBESTOS	Floor covering to room	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85882	BA8948		02/07/2018	
#REF!	QAA	Craigavon Hospital	19	NO ASBESTOS	Floor screed to room	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85883	BA8948		02/07/2018	
#REF!	QAA	Craigavon Hospital	19	NO ASBESTOS	Fire break above door	NO ASBESTOS	NO ASBESTOS				No further action required (Asbestos removed)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85884	BA8948		02/07/2018	
#REF!	QAA	Craigavon Hospital	19	NO ASBESTOS	Floor covering beneath vinyl floor coverino to room	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85885	BA8948		02/07/2018	
#REF!	QAA	Craigavon Hospital	19	NO ASBESTOS	Floor screed to room	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85886	BA8948		02/07/2018	
#REF!	QAA	Craigavon Hospital	19									Error Entry	HSG227	Unchecked		0				85887				
#REF!	QAA	Craigavon Hospital	17	NO ASBESTOS	Floor covering to bathrioom	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85888	BA8948	9506/18	13/11/2018	WHS
#REF!	QAA	Craigavon Hospital	17	NO ASBESTOS	Floor covering to toilet	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85889	BA8948	9506/18	13/11/2018	WHS
#REF!	QAA	Craigavon Hospital	17	NO ASBESTOS	Floor covering to bathroom	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85890	BA8948	9506/18	13/11/2018	WHS
#REF!	QAA	Craigavon Hospital	17	NO ASBESTOS	Floor covering to toilet	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85891	BA8948	9506/18	13/11/2018	WHS
#REF!	QAA	Craigavon Hospital	23	NO ASBESTOS	Debris to vent trunking at end wall	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85910	BA8975		17/07/2018	
#REF!	QAA	Craigavon Hospital	23	NO ASBESTOS	Roof space insulation	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85911	BA8975		17/07/2018	
#REF!	QAA	Craigavon Hospital	23	NO ASBESTOS	Pipe work laggin	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85912	BA8975		17/07/2018	
#REF!	QAA	Craigavon Hospital	23	NO ASBESTOS	High level pipe work insulation	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85913	BA8975		17/07/2018	
#REF!	QAA	Craigavon Hospital	23	NO ASBESTOS	Insulation to roof	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85914	BA8975		17/07/2018	
#REF!	QAA	Craigavon Hospital	23	NO ASBESTOS	Loose board adjacent to tank	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85915	BA8975		17/07/2018	
#REF!	QAA	Craigavon Hospital	23	NO ASBESTOS	Debris adjacdent to water tank	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85916	BA8975		17/07/2018	
#REF!	QAA	Craigavon Hospital	23	NO ASBESTOS	Debris adjacent to water tank	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85917	BA8975		17/07/2018	
#REF!	QAA	Craigavon Hospital	23	NO ASBESTOS	Debris adjacent to water tank	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85918	BA8975		17/07/2018	
#REF!	QAA	Craigavon Hospital	23	NO ASBESTOS	Sarking felt to roof	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85919	BA8975		17/07/2018	
#REF!	QAA	Craigavon Hospital	23	NO ASBESTOS	Ceiling tile to corridor	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85920	BA8975		17/07/2018	
#REF!	RAA	South Tyrone Hospital	21	NO ASBESTOS	Board to ducting on LHS of entrance	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85921	BA8710	9506/18	21/11/2018	WHS
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Debris to enclosed cable tray to ceilino void	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85922	BA8977		23/07/2018	
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Residue to cable penetration above doors to main entrance room	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85923	BA8977		23/07/2018	
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Debris to ceiling tile outside receation room	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85924	BA8977		23/07/2018	
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Debris to ceiling tile above doors to ED waiting area	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85925	BA8977		23/07/2018	
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Outer wall panel to upper ceiling void above ED waiting room	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85926	BA8977		23/07/2018	
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Debris to walkway to upper ceiling void above ED waiting room	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85927	BA8977		23/07/2018	
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Debris to walkway above corridor	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85928	BA8977		23/07/2018	
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Textured coating to upper ceiling	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85929	BA8977		23/07/2018	
#REF!	QAA	Craigavon Hospital	01	Pipe Brackets	Cloth between pipe work and	Textiles & Paper	Chrysotile	Unsealed	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Medium Risk	7	11/10/2023	Identified	Medium Risk	85930	BA8977	9302/2	11/10/2022	WHS
#REF!	QAA	Craigavon Hospital	01	Panel	Panelling to right hand side of door to room	Cement Products	Chrysotile	Cement Sheets	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Very Low Risk	4	21/09/2023	Identified	Very Low Risk	85931	BA8977	9302/2	21/09/2022	WHS
#REF!	QAA	Craigavon Hospital	01	Panel	Broken panel above door pipe penetration	Cement Products	Chrysotile	Cement Sheets	High	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	Low Risk	6	21/09/2023	Identified	Low Risk	85932	BA8977	9302/2	21/09/2022	WHS
#REF!	QAA	Craigavon Hospital	01	Debris	Debris between metal grid to roof	Cement Products	Chrysotile	Loose Asbestos Debris	Loose asbestos	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	Medium Risk	8	21/09/2023	Identified	Medium Risk	85933	BA8977	9302/2	21/09/2022	WHS
#REF!	QAA	Craigavon Hospital	01	Floor Tile and Bitumen Adhesive	Floor tile to room	Composite Material	Chrysotile	Composite Material	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Very Low Risk	3	29/09/2023	Identified	Very Low Risk	85934	BA8977	9302/2	29/09/2022	WHS
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Debris to enclosed cable tray above door	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85935	BA8977		23/07/2018	
#REF!	QAA	Craigavon Hospital	01	Floor Tile and Bitumen Adhesive	Floor tile to room	Composite Material	Chrysotile	Composite Material	Medium	Manage and monitor	New Incident	HSG227	Unchecked	Very Low Risk	4	01/08/2019	Identified	Very Low Risk	85936	BA8977		23/07/2018	
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Housing to cable penetration	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85937	BA8977		23/07/2018	
#REF!	QAA	Craigavon Hospital	01	Pipe Brackets	Cloth to redundant pipe bracket	Textiles & Paper	Chrysotile	unsealed	Low	Manage and monitor	New Incident	HSG227	Unchecked	Medium Risk	7	31/01/2019	Identified	Medium Risk	85938	BA8977		23/07/2018	
#REF!	QAA	Craigavon Hospital	01	Pipe Brackets	Cloth to redundant pipe bracket	Textiles & Paper	Chrysotile	unsealed	Low	Manage and monitor	New Incident	HSG227	Unchecked	Medium Risk	7	31/01/2019	Identified	Medium Risk	85939	BA8977		23/07/2018	
#REF!	QAA	Craigavon Hospital	01	Pipe Brackets	Cloth to pipe bracket	Textiles & Paper	Chrysotile	unsealed	Low	Manage and monitor	New Incident	HSG227	Unchecked	Medium Risk	7	31/01/2019	Identified	Medium Risk	85940	BA8977		23/07/2018	
#REF!	QAA	Craigavon Hospital	01	Pipe Brackets	Cloth to pipe bracket	Textiles & Paper	Chrysotile	unsealed	Low	Manage and monitor	New Incident	HSG227	Unchecked	Medium Risk	7	31/01/2019	Identified	Medium Risk	85941	BA8977		23/07/2018	
#REF!	QAA	Craigavon Hospital	01	Pipe Brackets	Cloth to pipe bracket	Textiles & Paper	Chrysotile	unsealed	Low	Manage and monitor	New Incident	HSG227	Unchecked	Medium Risk	7	31/01/2019	Identified	Medium Risk	85942	BA8977		23/07/2018	
#REF!	QAA	Craigavon Hospital	01	Pipe Brackets	Cloth to pipe bracket	Textiles & Paper	Chrysotile	unsealed	Low	Manage and monitor	New Incident	HSG227	Unchecked	Medium Risk	7	31/01/2019	Identified	Medium Risk	85943	BA8977		23/07/2018	
#REF!	QAA	Craigavon Hospital	01	Pipe Brackets	Cloth to pipe bracket	Textiles & Paper	Chrysotile	unsealed	Low	Manage and monitor	New Incident	HSG227	Unchecked	Medium Risk	7	31/01/2019	Identified	Medium Risk	85944	BA8977		23/07/2018	
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Board resting to pipe work	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85945	BA8977		23/07/2018	
#REF!	QAA	Craigavon Hospital	01	Pipe Brackets	Cloth to pipe bracket within riser	Textiles & Paper	Chrysotile	unsealed	Low	Manage and monitor	New Incident	HSG227	Unchecked	Medium Risk	7	31/01/2019	Identified	Medium Risk	85946	BA8977		23/07/2018	
#REF!	QAC	Lurgan Hospital	01	NO ASBESTOS	Firebreak	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85947	BA8808	9506/18	11/08/2018	WHS
#REF!	QAC	Lurgan Hospital	01	NO ASBESTOS	Board behind timber panelling to riser	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85948	BA8808	9506/18	11/08/2018	WHS
#REF!	QAA	Craigavon Hospital	00	NO ASBESTOS	Roof slate	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85949	BA8959		05/07/2018	
#REF!	NAB	St.Lukes	25	NO ASBESTOS	Board to wall behind counter	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85950	BA8917	9506/18	26/06/2018	WHS
#REF!	NAB	St.Lukes	12	NO ASBESTOS	Panel to door to lobby from corridor	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85951	BA8941	9506/18	07/02/2018	WHS
#REF!	NAB	St.Lukes	12	NO ASBESTOS	Step nosings	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85952	BA8941	9506/18	07/02/2018	WHS
#REF!	SBA	John Mitchel Place	01	Discarded Insulation Board	Debris to roof of dome reuse as	Loose Asbestos	Amosite	Loose Asbestos Debris	Loose asbestos	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	High Risk	11	15/12/2022	Identified	High Risk	85953	BA8940	9302/2	06/04/2022	WH Stephens
#REF!	SBA	John Mitchel Place	01	Floor Tile and Bitumen Adhesive	Black vinyl floor tiles and bitumen under carpet around audio booth	Composite Material	Chrysotile	Composite Material	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Very Low Risk	3	15/09/2023	Identified	Very Low Risk	85954	BA8940	9300/2	06/04/2022	WH Stephens
#REF!	NAB	St.Lukes	19	Heating Panel	Throughout	Insulating Board	Presumed Asbestos	Unsealed Asbestos Insulation	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Medium Risk	8	25/08/2020	Strongly Presumed	Medium Risk	85955		9501/1	20/01/2020	WHS

#REF!	QAA	Craigavon Hospital	21	NO ASBESTOS	Board	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85964	BA9037		08/08/2018		
#REF!	QAA	Craigavon Hospital	21	NO ASBESTOS	Board to front of room	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85965	BA9037		08/08/2018		
#REF!	QAA	Craigavon Hospital	21	NO ASBESTOS	Board to side of room opposite door	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85966	BA9037		08/08/2018		
#REF!	QAA	Craigavon Hospital	21	Textiles & Paper	Cloth to pipe hanger	Textiles & Paper	Chrysotile	Unsealed	Low	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	Medium Risk	7	18/04/2023	Identified	Medium Risk	85967	BA9037	9303.22	17/10/2022	WHS		
#REF!	QAA	Craigavon Hospital	21	Textiles & Paper	Cloth to pipe hanger	Textiles & Paper	Chrysotile	unsealed	Low	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	Medium Risk	7	18/04/2023	Identified	Medium Risk	85968	BA9037	-	17/10/2022	WHS		
#REF!	QAA	Craigavon Hospital	21	NO ASBESTOS	Pipe lagging	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85969	BA9037		08/08/2018			
#REF!	QAA	Craigavon Hospital	21	NO ASBESTOS	Debris to pipe hanger	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85970	BA9037		08/08/2018			
#REF!	QAA	Craigavon Hospital	21	NO ASBESTOS	Debris to pipe duct	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85971	BA9037		08/08/2018			
#REF!	QAA	Craigavon Hospital	21	NO ASBESTOS	Debris to valve cover	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85972	BA9037		08/08/2018			
#REF!	QAA	Craigavon Hospital	21	Gaskets	Gasket to flange at valve	Composite Material	Chrysotile	Composite Material	Low	Remove	Re-inspection	HSG227	Unchecked	Very Low Risk	3	17/10/2023	Identified	Very Low Risk	85973	BA9037	9303.22	17/10/2022	WHS		
#REF!	QAA	Craigavon Hospital	21	NO ASBESTOS	Debris to floor at rear of new boilers	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85974	BA9037		08/08/2018			
#REF!	QAA	Craigavon Hospital	21	NO ASBESTOS	Debris to window sill to RHS of new boilers	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85975	BA9037		08/08/2018			
#REF!	QAA	Craigavon Hospital	21	NO ASBESTOS	Debris to pipe hanger	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85976	BA9037		08/08/2018			
#REF!	QAA	Craigavon Hospital	21	NO ASBESTOS	Debris to wall	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85977	BA9037		08/08/2018			
#REF!	QAA	Craigavon Hospital	21	NO ASBESTOS	Debris to wall	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85978	BA9037		08/08/2018			
#REF!	QAA	Craigavon Hospital	21	NO ASBESTOS	Debris to top of pipe	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85979	BA9037		08/08/2018			
#REF!	QAA	Craigavon Hospital	21	NO ASBESTOS	Debris to top of valve cover and flange	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85980	BA9037		08/08/2018			
#REF!	QAA	Craigavon Hospital	21	NO ASBESTOS	Insulation debris to calorifier 1	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85981	BA9037		08/08/2018			
#REF!	QAA	Craigavon Hospital	21	Gaskets	Gasket to calorifier 1	Composite Material	Chrysotile	Composite Material	Low	remove	Re-inspection	HSG227	Unchecked	Very Low Risk	3	17/10/2023	Identified	Very Low Risk	85982	BA9037	9303.22	17/10/2022	WHS		
#REF!	QAA	Craigavon Hospital	21	NO ASBESTOS	Insulation debris to calorifier 2	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85983	BA9037		08/08/2018			
#REF!	QAA	Craigavon Hospital	21	Gaskets	Gaskets to calorifier 2	Composite Material	Chrysotile	Composite Material	Low	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	Very Low Risk	3	17/10/2023	Identified	Very Low Risk	85984	BA9037	9303.22	17/10/2022	WHS		
#REF!	QAA	Craigavon Hospital	21	Gaskets	Flange gasket to oumo 1	Composite Material	Chrysotile	Composite Material	Low	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	Very Low Risk	3	17/10/2023	Identified	Very Low Risk	85985	BA9037	9303.22	17/10/2022	WHS		
#REF!	QAA	Craigavon Hospital	21	Gaskets	Flange gasket to oumo 2	Composite Material	Chrysotile	Composite Material	Low	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	Very Low Risk	3	17/10/2023	Identified	Very Low Risk	85986	BA9037	-	17/10/2022	WHS		
#REF!	QAA	Craigavon Hospital	21	NO ASBESTOS	Debris to top of pipes to pump	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85987	BA9037		08/08/2018			
#REF!	QAA	Craigavon Hospital	21	NO ASBESTOS	Debris to base of column at pump 1	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85988	BA9037		08/08/2018			
#REF!	QAA	Craigavon Hospital	21	NO ASBESTOS	Debris to top of grey electrical panel to RHS of calorifier 2	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85989	BA9037		08/08/2018			
#REF!	QAA	Craigavon Hospital	21	NO ASBESTOS	Debros to data cable tray	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85990	BA9037		08/08/2018			
#REF!	QAA	Craigavon Hospital	21	NO ASBESTOS	Debris to floor in corner to RHS of calorifiers	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85991	BA9037		08/08/2018			
#REF!	QAA	Craigavon Hospital	21	NO ASBESTOS	Debris to top of grey telephone junction box	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85992	BA9037		08/08/2018			
#REF!	QAA	Craigavon Hospital	21	NO ASBESTOS	Debris to pipe hanger to upper side of new duct	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85993	BA9037		08/08/2018			
#REF!	QAA	Craigavon Hospital	21	NO ASBESTOS	Insulation debris to valve on redundant pipes to rear of concrete	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85994	BA9037		08/08/2018			
#REF!	QAA	Craigavon Hospital	21	Gaskets	Flange gasket to redundant pipe at rear of concrete plinth	Composite Material	Chrysotile	Composite Material	Low	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	Very Low Risk	3	17/10/2023	Identified	Very Low Risk	85995	BA9037	9303.22	17/10/2022	WHS		
#REF!	QAA	Craigavon Hospital	21	NO ASBESTOS	Redundant gasket to open flange at redundant pipe to rear of concrete	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85996	BA9037		08/08/2018			
#REF!	QAA	Craigavon Hospital	21	NO ASBESTOS	Debris to base of pipe duct 3 to RHS of concrete plinth	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85997	BA9037		08/08/2018			
#REF!	QAA	Craigavon Hospital	21	NO ASBESTOS	Debris to concrete plinth	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85998	BA9037		08/08/2018			
#REF!	QAA	Craigavon Hospital	21	NO ASBESTOS	debris to concrete plinth	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	85999	BA9037		08/08/2018			
#REF!	QAA	Craigavon Hospital	21	NO ASBESTOS	Spray insulation to ceiling of plant room	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86000	BA9037		08/08/2018			
#REF!	QAA	Craigavon Hospital	21	NO ASBESTOS	Bitumen wrap to disused mains cables on cable trav to RHS of	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86001	BA9037		08/08/2018			
#REF!	QAA	Craigavon Hospital	21	NO ASBESTOS	Debris to floor at corner of plant room to LHS of concrete plinth	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86002	BA9037		08/08/2018			
#REF!	QAA	Craigavon Hospital	21	NO ASBESTOS	Debris to pipe work at rear of calorifier	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86003	BA9037		08/08/2018			
#REF!	QAA	Craigavon Hospital	21	Textiles & Paper	Cloth to pipe hanger	Textiles & Paper	Chrysotile	unsealed	Low	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	Medium Risk	7	18/04/2023	Identified	Medium Risk	86004	BA9037	9303.22	17/10/2022	WHS		
#REF!	QAA	Craigavon Hospital	21	Textiles & Paper	Cloth to pipe hanger	Textiles & Paper	Chrysotile	unsealed	Low	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	Medium Risk	7	18/04/2023	Identified	Medium Risk	86005	BA9037	9303.22	17/10/2022	WHS		
#REF!	QAA	Craigavon Hospital	21	Textiles & Paper	Cloth to pipe hanger	Textiles & Paper	Presumed Asbestos	unsealed	Low	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	Medium Risk	9	18/04/2023	Strongly Presumed	Medium Risk	86006		9303.22	17/10/2022	WHS		
#REF!	QAA	Craigavon Hospital	21	Textiles & Paper	Cloth to pipe hanger	Textiles & Paper	Presumed Asbestos	unsealed	Low	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	Medium Risk	9	18/04/2023	Stronnly Presumed	Medium Risk	86007		9303.22	17/10/2022	WHS		
#REF!	QAA	Craigavon Hospital	21	Gaskets	Flange gaskets to pipework	Composite Material	Presumed Asbestos	Composite Material	Low	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	Low Risk	5	16/01/2023	Strongly Presumed	High Risk	86008		9303.22	17/10/2022	WHS		
#REF!	RAA	South Tyrone Hospital	01	floor tile	Floor tile	Composite Material	Chrysotile	Composite Material	Medium	Manage and monitor	Re-inspection	HSG227	Unchecked	Very Low Risk	4	15/12/2023	Identified	Very Low Risk	86009	BA9056	9303.22	15/12/2022	WHS		
#REF!	SJD	Rathfriland Road Site	05	NO ASBESTOS	Ceiling to boiler room	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86048	BA8818		03/05/2018			
#REF!	SJD	Rathfriland Road Site	05	NO ASBESTOS	Insulation to top of calorifier	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86049	BA8818		03/05/2018			
#REF!	SJD	Rathfriland Road Site	05	NO ASBESTOS	Board above ceiling to boiler room	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86050	BA8818		03/05/2018			
#REF!	SJD	Rathfriland Road Site	05	Roof Tiles	roof tiles	Cement Products	Chrysotile	Unsealed	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Low Risk	6	13/09/2023	Identified	Low Risk	86051	BA8818	9303.22	31/08/2022	WHS		
#REF!	SJD	Rathfriland Road Site	05	NO ASBESTOS	Burner gasket	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86052	BA8874		24/05/2018			
#REF!	SJD	Rathfriland Road Site	05	NO ASBESTOS	Flue inner insulation	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86053	BA8874		24/05/2018			
#REF!	SJD	Rathfriland Road Site	05	Gaskets	Flue sealant at boiler rear	Composite Material	Chrysotile	Composite Material	Low	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	Very Low Risk	3	13/09/2023	Identified	Very Low Risk	86054	BA8874	9303.22	31/08/2022	WHS		
#REF!	SJD	Rathfriland Road Site	05	NO ASBESTOS	Pipe flange gasket	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86055	BA8874		24/05/2018			
#REF!	SJD	Rathfriland Road Site	05	Fuse Flash Guards	Electrical switch gear	Textiles & Paper	Presumed Asbestos	Unsealed	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Medium Risk	9	13/03/2023	Strongly Presumed	Medium Risk	86056	BA8874	9303.22	31/08/2022	WHS		
#REF!	SBD	Newtownhamilton Health Centre	01	NO ASBESTOS	Sink pad to kitchen	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86057	BA9067		21/08/2018			
#REF!	SBD	Newtownhamilton Health Centre	01	Door Panel	Panel to back of door	Insulating Board	Amosite	Unsealed Asbestos Debris	Low	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	Medium Risk	7	12/03/2023	Identified	Medium Risk	86058	BA9067	9303.22	02/09/2022	WHS		
#REF!	SBD	Newtownhamilton Health Centre	01	Door Panel	Panel to back of door	Insulatino Board	Amosite	Unsealed Asbestos Debris	Low	Label & Manage	Re-inspection	HSG227	Unchecked	Medium Risk	7	12/03/2023	Identified	Medium Risk	86059	BA9067	9303.22	02/09/2022	WHS		
#REF!	SBD	Newtownhamilton Health Centre	01	NO ASBESTOS	Sink pad to sluice room	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86060	BA9067		21/08/2018			
#REF!	SBD	Newtownhamilton Health Centre	01	Residue to Walls	Sno to wall at flue oise	Thermal Insulation	Amosite	unsealed	Low	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	Hoh Risk	11	12/12/2022	Identified	Hoh Risk	86061	BA9067	9303.22	02/09/2022	WHS		
#REF!	SBD	Newtownhamilton Health Centre	01	NO ASBESTOS	Sarking felt to roof	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86062	BA9067		21/08/2018			
#REF!	SBD	Newtownhamilton Health Centre	01	Residue to Walls	Snot to wall at flue oise	Thermal Insulation	Amosite	unsealed	Low	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	Hoh Risk	11	12/12/2022	Identified	Hoh Risk	86063	BA9067	9303.22	02/09/2022	WHS		
#REF!	SBD	Newtownhamilton Health Centre	01	Flue Pipe	Flue pipe to corner behind boiler	Cement Products	Chrysotile	unsealed	Low	Label & Manage	Re-inspection	HSG227	Unchecked	Low Risk	6	12/09/2023	Identified	Low Risk	86064	BA9067	9303.22	02/09/2022	WHS		
#REF!	SBD	Newtownhamilton Health Centre	01	Pipe Residue	Residue to obework behind boiler	Thermal Insulation	Amosite	unsealed	Low	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	Hoh Risk	11	12/12/2022	Identified	Hoh Risk	86065	BA9067	9303.22	02/09/2022	WHS		
#REF!	SBD	Newtownhamilton Health Centre	01	Pipe Residue	Residue to obework behind boiler	Thermal Insulation	Amosite	Unsealed	Low	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	Hoh Risk	11	12/12/2022	Identified	Hoh Risk	86066	BA9067	9303.22	02/09/2022	WHS		
#REF!	SBD	Newtownhamilton Health Centre	01	Residue to Walls	Snot to wall behind boiler	Thermal Insulation	Amosite	unsealed	Low	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	High Risk	11	12/12/2022	Identified	High Risk	86067	BA9067	9303.22	02/09/2022	WHS		
#REF!	SBD	Newtownhamilton Health Centre	01	NO ASBESTOS	Residue to flange	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86068	BA9067		21/08/2018			
#REF!	SBD	Newtownhamilton Health Centre	01	Residue to Walls	Snot to wall behind calorifier	Thermal Insulation	Amosite	unsealed	Low	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	High Risk	11	12/12/2022	Identified	High Risk	86069	BA9067	9303.22	02/09/2022	WHS		
#REF!	SBD	Newtownhamilton Health Centre	01	Debris	Debris to floor behind boiler	Thermal Insulation	Amosite	Loose Asbestos Debris	Low	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	Hoh Risk	11	12/12/2022	Identified	Hoh Risk	86070	BA9067	9303.22	02/09/2022	WHS		
#REF!	SBD	Newtownhamilton Health Centre	01	Debris	Debris to floor at calorifier	Thermal Insulation	Amosite	Loose Asbestos Debris	Low	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	Hoh Risk	11	12/12/2022	Identified	Hoh Risk	86071	BA9067	9303.22	02/09/2022	WHS		
#REF!	SBD	Newtownhamilton Health Centre	01	Gaskets	Gasket to flange to front of boiler	Composite Material	Chrysotile	Composite Material	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Very Low Risk	3	12/09/2023	Identified	Very Low Risk	86072	BA9067	9303.22	02/09/2022	WHS		
#REF!	SBD	Newtownhamilton Health Centre	01	Gaskets	Loose gasket on floor LHS of door	Composite Material	Chrysotile	Composite Material	Medium	Remove	Re-inspection	HSG227	Unchecked	Very Low Risk	4	12/09/2023	Identified	Very Low Risk	86073	BA9067	9303.22	02/09/2022	WHS		
#REF!	SBD	Newtownhamilton Health Centre	01	Undercloak	Verge undercloak	Insulating Board	Amosite	Unsealed	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Medium Risk	8	12/03/2023	Identified	Medium Risk	86074	BA9067	9303.22	02/09/2022	WHS		
#REF!	SBD	Newtownhamilton Health Centre	01	Fuse Flash Guards	Electrical equipment	Textiles & Paper	Presumed Asbestos	unsealed	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Medium Risk	9	12/03/2023	Strongly Presumed	Medium Risk	86075		9303.22	02/09/2022	WHS		
#REF!	SBD	Newtownhamilton Health Centre	01	Board	Safe	Insulatino Board	Presumed Asbestos	Unsealed	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Medium Risk	9	12/03/2023	Stronnly Presumed	Medium Risk	86076	BA9067	9303.22	02/09/2022	WHS		
#REF!	SJD	Rathfriland Road Site	04	Soffit Boarding	Soffit to front	Cement Products	Crocidolite	Cement Sheets	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Low Risk	6	13/09/2023	Identified	Low Risk	86077	BA8817	9303.22	31/08/2022	WHS		
#REF!	SJD	Rathfriland Road Site	04	Verge Cloak	Verge Board	Cement Products	Chrysotile	Cement Sheets	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Very Low Risk	4	13/09/2023	Identified	Very Low Risk	86078	BA8817	-	31/08/2022	WHS		
#REF!	SJD	Rathfriland Road Site	04	NO ASBESTOS	Roof tiles	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86079	BA8817		03/05/2018			
#REF!	SJD	Rathfriland Road Site	04	NO ASBESTOS	Sarking felt to roof void	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86080	BA8817		03/05/2018			
#REF!	SJD	Rathfriland Road Site	04	NO ASBESTOS	Felt beneath CWST	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86081	BA8817		03/05/2018			
#REF!	SJD	Rathfriland Road Site	04	Soffit Boardino	Soffit to rear	Cement Products	Chrysotile	Cement Sheets	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Very Low Risk	4	13/09/2023	Identified	Very Low Risk	86082	BA8817	9303.22	31/08/2022	WHS		
#REF!	SJD	Rathfriland Road Site	04	Fuse Flash Guards	Switch gear	Textiles & Paper	Presumed Asbestos	Unsealed	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Medium Risk	9	13/03/2023	Stronnly Presumed	Medium Risk	86083	BA8817	9303.22	31/08/2022	WHS		
#REF!	SJD	Rathfriland Road Site	03	Board	Board Linino to walls	Insulatino Board	Amosite	Unsealed Asbestos Debris	Low	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	Medium Risk	7	13/08/2023	Identified	Medium Risk	86084	BA8816	-	31/08/2022	WHS		
#REF!	SJD	Rathfriland Road Site	03	NO ASBESTOS	Board to courtyard ceiling	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86085	BA8816		03/05/2018			
#REF!	SJD	Rathfriland Road Site	03	Gaskets	Gasket to boiler	Composite Material	Presumed Asbestos	Composite Material	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Low Risk	5	13/09/2023	Stronnly Presumed	Low Risk	86086	BA8816	9303.22	31/08/2022	WHS		
#REF!	SJD	Rathfriland Road Site	03	Gaskets	Flue gasket to boiler	Composite Material	Presumed Asbestos	Composite Material	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Low Risk	5	13/09/2023	Identified	Low Risk	86087	BA8816	-	31/08/2022	WHS		
#REF!	SJD	Rathfriland Road Site	05	NO ASBESTOS	Floor tile beneath carpet	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86088	BA9068		21/08/2018			
#REF!	SJD	Rathfriland Road Site	05	NO ASBESTOS	Ceiling tile	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86089	BA9068		21/08/2018			
#REF!	SJD	Rathfriland Road Site	05	NO ASBESTOS	Floor tile beneath carpet	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86090	BA9068		21/08/2018			
#REF!	SJD	Rathfriland Road Site	05	NO ASBESTOS	Floor tile beneath carpet	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86091	BA9068		21/08/2018			
#REF!	SJD	Rathfriland Road Site	05	NO ASBESTOS	Sink pad	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86092	BA9068		21/08/2018			

#REF!	SJD	Rathfriland Road Site	05	NO ASBESTOS	Loose insulation above ceiling within roof space a - 016	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86093	BA9068		21/08/2018		
#REF!	SJD	Rathfriland Road Site	05	NO ASBESTOS	Strip along rather to ceiling board above corridor	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86094	BA9068		21/08/2018		
#REF!	SJD	Rathfriland Road Site	05	NO ASBESTOS	Ceiling board	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86095	BA9068		21/08/2018		
#REF!	SJD	Rathfriland Road Site	05	NO ASBESTOS	Strip along rather to ceiling board above corridor	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86096	BA9068		21/08/2018		
#REF!	SJD	Rathfriland Road Site	05	NO ASBESTOS	Ceiling board	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86097	BA9068		21/08/2018		
#REF!	SJD	Rathfriland Road Site	05	NO ASBESTOS	Cap to calorifier to boiler room	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86098	BA9068		21/08/2018		
#REF!	SJD	Rathfriland Road Site	05	NO ASBESTOS	Ceiling to boiler room	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86099	BA9068		21/08/2018		
#REF!	SJD	Rathfriland Road Site	05	Roof Tiles	Roof tile to main roof	Cement Products	Chrysotile	Unsealed	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Low Risk	6	13/09/2023	Identified	Low Risk	86100	BA9068	9300/2	31/08/2022	WHS		
#REF!	SJD	Rathfriland Road Site	05	NO ASBESTOS	Verge undercloak to main roof	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86101	BA9068		21/08/2018		
#REF!	SBB	Crossmaglen Health Centre	01	Floor Tile and Bitumen Adhesive	Floor tile to cupboard beneath stairs RHS of lobby	Composite Material	Chrysotile	Composite Material	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Very Low Risk	3	21/09/2023	Identified	Very Low Risk	86102	BA9069	9300/2	12/09/2022	WHS		
#REF!	SBB	Crossmaglen Health Centre	01	Floor Tile and Bitumen Adhesive	Floor tile to pharmacy store	Composite Material	Chrysotile	Composite Material	Minor damage of	Manage and monitor	Re-inspection	HSG227	Unchecked	Very Low Risk	3	21/09/2023	Identified	Very Low Risk	86103	BA9069	9300/2	01/06/2022	WHS		
#REF!	SBB	Crossmaglen Health Centre	01	NO ASBESTOS	Strawboard ceiling to waiting area	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86104	BA9069		21/08/2018		
#REF!	SBB	Crossmaglen Health Centre	01	Sink Pad	Sink pad to kitchen	Composite Material	Chrysotile	Composite Material	Minor damage of	Manage and monitor	Re-inspection	HSG227	Unchecked	Very Low Risk	3	21/09/2023	Identified	Very Low Risk	86105	BA9069	9300/2	12/09/2022	WHS		
#REF!	SBB	Crossmaglen Health Centre	01	NO ASBESTOS	Panel to door to corridor between 002 and 018	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86106	BA9069		21/08/2018		
#REF!	SBB	Crossmaglen Health Centre	01	Floor Tile and Bitumen Adhesive	Floor tile	Composite Material	Chrysotile	Composite Material	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Very Low Risk	3	21/09/2023	Identified	Very Low Risk	86107	BA9069	9300/2	01/06/2022	WHS		
#REF!	SBB	Crossmaglen Health Centre	01	NO ASBESTOS	Panel to doors to corridor between 001 and 002	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86108	BA9069		21/08/2018		
#REF!	SBB	Crossmaglen Health Centre	01	Floor Tile and Bitumen Adhesive	Floor tile	Composite Material	Chrysotile	Composite Material	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Very Low Risk	3	21/09/2023	Identified	Very Low Risk	86109	BA9069	9300/2	01/06/2022	WHS		
#REF!	SBB	Crossmaglen Health Centre	01	Sink Pad	Sink oad	Composite Material	Chrysotile	Composite Material	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Very Low Risk	3	21/09/2023	Identified	Very Low Risk	86110	BA9069	9300/2	01/06/2022	WHS		
#REF!	SBB	Crossmaglen Health Centre	01	Floor Tiles	Floor tile	Composite Material	Chrysotile	Composite Material	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Very Low Risk	3	21/09/2023	Identified	Very Low Risk	86111	BA9069	9300/2	01/06/2022	WHS		
#REF!	SBB	Crossmaglen Health Centre	01	NO ASBESTOS	Snot to wall at calorifier	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86112	BA9069		21/08/2018		
#REF!	SBB	Crossmaglen Health Centre	01	NO ASBESTOS	Snot to wall RHS of boiler	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86113	BA9069		21/08/2018		
#REF!	SBB	Crossmaglen Health Centre	01	NO ASBESTOS	Debris to floor at calorifier	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86114	BA9069		21/08/2018		
#REF!	SBB	Crossmaglen Health Centre	01	NO ASBESTOS	Debris to floor at boiler	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86115	BA9069		21/08/2018		
#REF!	SBB	Crossmaglen Health Centre	01	Exterior Cladding	Outer cladding	Cement Products	Presumed Asbestos	Cement Sheets	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Low Risk	6	21/09/2023	Presumed	Low Risk	86116		9300/2	01/06/2022	WHS		
#REF!	SBB	Crossmaglen Health Centre	01	Panel	Wooden Panelling	Cement Products	Presumed Asbestos	Cement Sheets	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Low Risk	6	21/09/2023	Presumed	Low Risk	86117		9300/2	01/06/2022	WHS		
#REF!	OLA	Burnside Family Centre	01	Board	Board beneath CWST	Insulating Board	Amosite	Unsealed Asbestos Insulation	Medium	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	Medium Risk	8	15/04/2023	Identified	Medium Risk	86118	BA9087	9299/2	29/09/2022	WHS		
#REF!	QLA	Burnside Family Centre	01	Sink Pad	Sink pad	Composite Material	Chrysotile	Composite Material	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Very Low Risk	3	14/10/2023	Identified	Very Low Risk	86119	BA9087	9299/2	29/09/2022	WHS		
#REF!	QLA	Burnside Family Centre	01	NO ASBESTOS	Debris to store	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86120	BA9087		27/08/2018		
#REF!	QLA	Burnside Family Centre	01	NO ASBESTOS	Stair nosing	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86121	BA9087		27/08/2018		
#REF!	OLA	Burnside Family Centre	01	Board	Board beneath CWST	Insulating Board	Amosite	Unsealed Asbestos Insulation	Low	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	Medium Risk	7	15/04/2023	Identified	Medium Risk	86122	BA9087	9299/2	29/09/2022	WHS		
#REF!	QLA	Burnside Family Centre	01	NO ASBESTOS	Stair nosing	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86123	BA9087		27/08/2018		
#REF!	QLA	Burnside Family Centre	01	Board	Board beneath CWST	Insulating Board	Amosite	Unsealed Asbestos Insulation	Medium	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	Medium Risk	8	15/04/2023	Identified	Medium Risk	86124	BA9087	9299/2	29/09/2022	WHS		
#REF!	QLA	Burnside Family Centre	01	NO ASBESTOS	Bitumen flashing to vertical block walls	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86125	BA9087		27/08/2018		
#REF!	QLA	Burnside Family Centre	01	NO ASBESTOS	Bitumen felt to floor of roof void	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86126	BA9087		27/08/2018		
#REF!	OLA	Burnside Family Centre	01	Cement Flue	Redundant cement cowl	Cement Products	Chrysotile	Unsealed Cement	Low	Remove	Re-inspection	HSG227	Unchecked	Very Low Risk	4	14/10/2023	Identified	Very Low Risk	86127	BA9087	9299/2	29/09/2022	WHS		
#REF!	QLA	Burnside Family Centre	01	NO ASBESTOS	Sarking felt	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86128	BA9087		27/08/2018		
#REF!	QLA	Burnside Family Centre	01	Bitumen Adhesive	Bitumen underneath modern floor covering	Composite Material	Chrysotile	Composite Material	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Very Low Risk	3	13/10/2023	Identified	Very Low Risk	86129	BA9087	9299/2	29/09/2022	WHS		
#REF!	QLA	Burnside Family Centre	01	NO ASBESTOS	Sink pad to double sink	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86130	BA9087		27/08/2018		
#REF!	QLA	Burnside Family Centre	01	Floor Tiles	Vinyl floor tile beneath modern floor covering	Composite Material	Chrysotile	Composite Material	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Very Low Risk	3	13/10/2023	Identified	Very Low Risk	86131	BA9087	9299/2	29/09/2022	WHS		
#REF!	OLA	Burnside Family Centre	01	Bitumen Adhesive	Bitumen beneath vinyl floor tile	Composite Material	Chrysotile	Composite Material	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Very Low Risk	3	13/10/2023	Identified	Very Low Risk	86132	BA9087	9299/2	29/09/2022	WHS		
#REF!	QLA	Burnside Family Centre	01	Sink Pad	Sink pad	Composite Material	Chrysotile	Composite Material	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Very Low Risk	3	13/10/2023	Identified	Very Low Risk	86133	BA9087	9299/2	29/09/2022	WHS		
#REF!	QLA	Burnside Family Centre	01	NO ASBESTOS	Textured coating to ceiling	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86134	BA9087		27/08/2018		
#REF!	QLA	Burnside Family Centre	01	Floor Tile and Bitumen Adhesive	Vinyl floor tile coupled with bitumen beneath modern floor covering	Composite Material	Chrysotile	Composite Material	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Very Low Risk	3	14/10/2023	Identified	Very Low Risk	86135	BA9087	9299/2	29/09/2022	WHS		
#REF!	OLA	Burnside Family Centre	01	Debris Floor Tile	Bitumen and vinyl floor tile debris	Loose Asbestos	Chrysotile	Composite Material	Loose asbestos	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	Medium Risk	7	15/04/2023	Identified	Medium Risk	86136	BA9087	9299/2	29/09/2022	WHS		
#REF!	QLA	Burnside Family Centre	01	Floor Tile and Bitumen Adhesive	Vinyl floor tile with bitumen under modern vinyl floor covering	Composite Material	Chrysotile	Composite Material	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Very Low Risk	3	14/10/2023	Identified	Very Low Risk	86137	BA9087	9299/2	29/09/2022	WHS		
#REF!	QLA	Burnside Family Centre	01	NO ASBESTOS	Sink pad	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86138	BA9087		27/08/2018		
#REF!	QLA	Burnside Family Centre	01	NO ASBESTOS	Soffit to front of property	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86139	BA9087		27/08/2018		
#REF!	QLA	Burnside Family Centre	01	NO ASBESTOS	Canopy 3 - Verge under cloak to front canopy	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86140	BA9087		27/08/2018		
#REF!	QLA	Burnside Family Centre	01	NO ASBESTOS	Canopy 2 - Verge undercloak to front canopy	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86141	BA9087		27/08/2018		
#REF!	QLA	Burnside Family Centre	01	NO ASBESTOS	Canopy 2 - Bitumen felt beneath tiles	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86142	BA9087		27/08/2018		
#REF!	QLA	Burnside Family Centre	01	NO ASBESTOS	Boiler House - verge undercloak to external boiler house	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86143	BA9087		27/08/2018		
#REF!	QLA	Burnside Family Centre	01	NO ASBESTOS	Canopy 1 - Verge under cloak	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86144	BA9087		27/08/2018		
#REF!	QLA	Burnside Family Centre	01	NO ASBESTOS	Canopy 1 - Bitumen under tiles	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86145	BA9087		27/08/2018		
#REF!	QLA	Burnside Family Centre	01	NO ASBESTOS	Canopy 3 - Bitumen under tiles	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86146	BA9087		27/08/2018		
#REF!	OLA	Burnside Family Centre	01	Soffit Boardino	Soffit to rear of building	Cement Products	Presumed Asbestos	Unsealed Cement	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Low Risk	6	14/10/2023	Presumed	Low Risk	86147		9299/2	29/09/2022	WHS		
#REF!	QLA	Burnside Family Centre	01	Verge Cloak	Verge cloak to roof of building	Cement Products	Presumed Asbestos	Unsealed Cement	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Low Risk	6	14/10/2023	Presumed	Low Risk	86148		9299/2	29/09/2022	WHS		
#REF!	RAC	Tower Hill Site	07	NO ASBESTOS	Sarking felt to roof	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86157	BA9099		31/08/2018		
#REF!	RBB	Ballygawley Health Centre	01	Ceiling Board	Board to ceiling of store	Insulating Board	Amosite/Chrysotile	Asbestos Insulation	Low	Label & Manage	Documents Added	HSG227	Unchecked	Low Risk	6	10/03/2024	Identified	Medium Risk	86158	BA9100	9811/1	10/03/2023	WHS		
#REF!	RBB	Ballygawley Health Centre	01	Boardino	Board to ceiling above suspended	Cement Products	Chrysotile	Cement Sheets	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Very Low Risk	4	03/04/2021	Identified	Very Low Risk	86159	BA9100	9811/1	18/11/2019	WHS		
#REF!	RBB	Ballygawley Health Centre	01	Boarding	Ceiling board in alcove above electrical box	Cement Products	Chrysotile	Cement Sheets	Medium	remove	Re-inspection	HSG227	Unchecked	Low Risk	5	03/04/2021	Identified	Low Risk	86160	BA9100	9811/1	18/11/2019	WHS		
#REF!	RBB	Ballygawley Health Centre	01	NO ASBESTOS	Roof felt	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86161	BA9100		31/08/2018		
#REF!	RBB	Ballygawley Health Centre	01	NO ASBESTOS	Vinyl under modern carpet	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86162	BA9100		31/08/2018		
#REF!	RBB	Ballygawley Health Centre	01	NO ASBESTOS	Sink pad	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86163	BA9100		31/08/2018		
#REF!	RBB	Ballygawley Health Centre	01	NO ASBESTOS	Black vinyl skirting	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86164	BA9100		31/08/2018		
#REF!	RBB	Ballygawley Health Centre	01	NO ASBESTOS	Sink pad	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86165	BA9100		31/08/2018		
#REF!	RBB	Ballygawley Health Centre	01	Verge Cloak	Verge undercloak to rear	Cement Products	Chrysotile	Cement Sheets	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Very Low Risk	4	03/04/2021	Identified	Very Low Risk	86166	BA9100	9811/1	18/11/2019	WHS		
#REF!	RBB	Ballygawley Health Centre	01	NO ASBESTOS	Roof felt to edge	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86167	BA9100		31/08/2018		
#REF!	RBB	Ballygawley Health Centre	01	Verge Cloak	Verge undercloak to front	Cement Products	Chrysotile	Cement Sheets	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Very Low Risk	4	03/04/2021	Identified	Very Low Risk	86168	BA9100	9811/1	18/11/2019	WHS		
#REF!	QAA	Craigavon Hospital	01								Error Entry	HSG227	Unchecked	Error Entry	0		Identified	Very Low Risk	86169						
#REF!	RJA	Willowbank Resource Centre	01	NO ASBESTOS	Blue vinyl beneath modern vinyl	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86170	BA9101		31/08/2018		
#REF!	RJA	Willowbank Resource Centre	01	NO ASBESTOS	Sink pad	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86171	BA9101		31/08/2018		
#REF!	RJA	Willowbank Resource Centre	01	NO ASBESTOS	Sink pad to RHS	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86172	BA9101		31/08/2018		
#REF!	RJA	Willowbank Resource Centre	01	NO ASBESTOS	Sink pad to LHS	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86173	BA9101		31/08/2018		
#REF!	RJA	Willowbank Resource Centre	01	NO ASBESTOS	pale green vinyl beneath modern vinyl	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86174	BA9101		31/08/2018		
#REF!	RJA	Willowbank Resource Centre	01	NO ASBESTOS	Sink pad	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86175	BA9101		31/08/2018		
#REF!	RJA	Willowbank Resource Centre	01	NO ASBESTOS	Sink pad	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86176	BA9101		31/08/2018		
#REF!	RJA	Willowbank Resource Centre	01	NO ASBESTOS	Textured coating to building	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86177	BA9101		31/08/2018		
#REF!	RJA	Willowbank Resource Centre	01	Floor Tile and Bitumen Adhesive	Blue VFT & bitumen	Composite Material	Chrysotile	Composite Material	Medium	Manage and monitor	Re-inspection	HSG227	Unchecked	Very Low Risk	4	27/03/2021	Identified	Very Low Risk	86178	BA9101	9811/1	20/01/2020	WHS		
#REF!	RJA	Willowbank Resource Centre	01	NO ASBESTOS	Durasteel panel to floor	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86179	BA9101		31/08/2018		
#REF!	RJA	Willowbank Resource Centre	01	Panel	Panel to sides of boiler house	Cement Products	Chrysotile	Cement Sheets	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Very Low Risk	4	27/03/2021	Identified	Very Low Risk	86180	BA9101	9811/1	20/01/2020	WHS		
#REF!	RJA	Willowbank Resource Centre	01	Panel	Panel to rear of boiler room	Cement Products	Chrysotile	Cement Sheets	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Very Low Risk	4	27/03/2021	Identified	Very Low Risk	86181	BA9101	9811/1	20/01/2020	WHS		
#REF!	RJA	Willowbank Resource Centre	01	NO ASBESTOS	Durasteel debris to floor	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86182	BA9101		31/08/2018		
#REF!	RJA	Willowbank Resource Centre	01	NO ASBESTOS	Rope seal to boiler burner	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86183	BA9101		31/08/2018		
#REF!	RJA	Willowbank Resource Centre	01	NO ASBESTOS	Red felt to roof	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86184	BA9101		31/08/2018		
#REF!	RJA	Willowbank Resource Centre	01	NO ASBESTOS	Dark felt to roof	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86185	BA9101		31/08/2018		
#REF!	RJA	Willowbank Resource Centre	01	NO ASBESTOS	Cloth wrap to exhaust cowl on boiler	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86186	BA9101		31/08/2018		

#REF!	QAA	Craigavon Hospital	16	Bitumen Adhesive	Bitumen beneath carpet	Composite Material	Chrysotile	Composite Material	Low	Manage and monitor	Review – No Change	HSG227	Unchecked	Very Low Risk	3	24/06/2023	Identified	Very Low Risk	86187	BA9094	[illegible]	24/06/2022	WHS
#REF!	QAA	Craigavon Hospital	16	Bitumen Adhesive	Floor tile	Composite Material	Chrysotile	Composite Material	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Very Low Risk	3	24/06/2023	Identified	Very Low Risk	86188	BA9094	[illegible]	24/06/2022	WHS
#REF!	QAA	Craigavon Hospital	16		Grey floor tile	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86189	BA9094		04/09/2018	
#REF!	RAC	Tower Hill Site	14	NO ASBESTOS	Stair nosing	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86190	BA9102		31/08/2018	
#REF!	RAC	Tower Hill Site	14	NO ASBESTOS	Sarking felt	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86191	BA9102		31/08/2018	
#REF!	RAC	Tower Hill Site	14	NO ASBESTOS	Kitchen sink pad	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86192	BA9102		31/08/2018	
#REF!	QAA	Craigavon Hospital	16		White floor tile	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86193	BA9094		07/09/2018	
#REF!	QAA	Craigavon Hospital	16		Debris to floor of electric cupboard	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86194	BA9094		04/09/2018	
#REF!	QAA	Craigavon Hospital	16		Adhesive beneath carpet to stairwell	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86195	BA9094		04/09/2018	
#REF!	RAC	Tower Hill Site	04	Lino Flooring	Vinyl beneath carpet	Composite Material	Chrysotile	Composite Material	High	Manage and monitor	Re-inspection	HSG227	Unchecked	Low Risk	5	27/03/2021	Identified	Low Risk	86196	BA9105	[illegible]	28/11/2019	WHS
#REF!	RAC	Tower Hill Site	04	NO ASBESTOS	Vinyl beneath carpet	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86197	BA9105		03/09/2018	
#REF!	QAA	Craigavon Hospital	16		Adhesive beneath carpet to corridor	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86198	BA9094		04/09/2018	
#REF!	RAC	Tower Hill Site	04	NO ASBESTOS	Sink pad	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86199	BA9105		03/09/2018	
#REF!	QAA	Craigavon Hospital	16		Grey floor tile	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86200	BA9094		04/09/2018	
#REF!	RAC	Tower Hill Site	04	NO ASBESTOS	Vinyl beneath carpet	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86201	BA9105		03/09/2018	
#REF!	QAA	Craigavon Hospital	16		White floor tile	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86202	BA9094		04/09/2018	
#REF!	RAC	Tower Hill Site	04	NO ASBESTOS	Sink pad	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86203	BA9105		03/09/2018	
#REF!	RAC	Tower Hill Site	04	NO ASBESTOS	Black vinyl skirting	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86204	BA9105		03/09/2018	
#REF!	RAC	Tower Hill Site	04	NO ASBESTOS	Sink pad	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86205	BA9105		03/09/2018	
#REF!	RAC	Tower Hill Site	04	NO ASBESTOS	External brick wall outside room A-028 Damo oroof course	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86206	BA9105		03/09/2018	
#REF!	RAC	Tower Hill Site	04	Damp Proof Course	External brick wall outside room A-046 -Damo oroof course	Composite Material	Chrysotile	Composite Material	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Very Low Risk	3	27/03/2021	Identified	Very Low Risk	86207	BA9105	9811/19	28/11/2019	WHS
#REF!	RAC	Tower Hill Site	04	Damp Proof Course	External brick wall outside rooms A-042 & A-041 -Damo oroof course	Composite Material	Chrysotile	Composite Material	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Very Low Risk	3	27/03/2021	Identified	Very Low Risk	86208	BA9105	9811/19	28/11/2019	WHS
#REF!	QAA	Craigavon Hospital	16		Adhesive beneath carpet	NO ASBESTOS	NO ASBESTOS				New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86209	BA9094		04/09/2018	
#REF!	QAA	Craigavon Hospital	16		Adhesive beneath carpet	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86210	BA9094		07/09/2018	
#REF!	QAA	Craigavon Hospital	16		Adhesive beneath carpet	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86211	BA9094		04/09/2018	
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Grey Vinyl floor tile	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86212	BA9072		22/08/2018	
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Cream VFT	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86213	BA9072		22/08/2018	
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Grey VFT	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86214	BA9072		22/08/2018	
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Cream VFT	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86215	BA9072		22/08/2018	
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Grey VFT	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86216	BA9072		22/08/2018	
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Blue VFT	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86217	BA9072		22/08/2018	
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	White/Blue VFT	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86218	BA9072		22/08/2018	
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Brown VFT	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86219	BA9072		22/08/2018	
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	White/Blue VFT	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86220	BA9072		22/08/2018	
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Brown VFT	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86221	BA9072		22/08/2018	
#REF!	QAA	Craigavon Hospital	01	Bitumen Adhesive	White/Blue VFT	Composite Material	Chrysotile	Composite Material	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Very Low Risk	3	15/09/2023	Identified	Very Low Risk	86222	BA9072	[illegible]	15/09/2022	WHS
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Green VFT	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86223	BA9072		22/08/2018	
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	BA9072	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86224	BA9072		22/08/2018	
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	White/Blue VFT	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86225	BA9072		22/08/2018	
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Grey/Green VFT	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86226	BA9072		11/09/2018	
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Beige VFT	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86227	BA9072		22/08/2018	
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Beige VFT	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86228	BA9072		22/08/2018	
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Vinyl skirting	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86229	BA9072		22/08/2018	
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Dark Blue VFT	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86230	BA9072		22/08/2018	
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	White/Blue VFT	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86231	BA9072		22/08/2018	
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Brown VFT	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86232	BA9072		22/08/2018	
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Light Blue VFT	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86233	BA9072		22/08/2018	
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	White/Blue VFT	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86234	BA9072		22/08/2018	
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Beige VFT	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86235	BA9072		22/08/2018	
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Grey VFT	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86236	BA9072		22/08/2018	
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Green/Blue VFT	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86237	BA9072		22/08/2018	
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Green VFT	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86238	BA9072		22/08/2018	
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Cream VFT	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86239	BA9072		22/08/2018	
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Beige VFT	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86240	BA9072		22/08/2018	
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Vinyl skirting	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86241	BA9072		22/08/2018	
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Cream VFT	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86242	BA9072		22/08/2018	
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Beige VFT	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86243	BA9072		22/08/2018	
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Vinyl skirting	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86244	BA9072		22/08/2018	
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Cream VFT	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86245	BA9072		22/08/2018	
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Green/Grey VFT	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86246	BA9072		22/08/2018	
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Grey/Blue VFT	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86247	BA9072		22/08/2018	
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Beige VFT	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86248	BA9072		22/08/2018	
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Green VFT	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86249	BA9072		22/08/2018	
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Grey/Green VFT	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86250	BA9072		22/08/2018	
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	White/Blue VFT	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86251	BA9072		22/08/2018	
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Brown VFT	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86252	BA9072		22/08/2018	
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Beige VFT	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86253	BA9072		22/08/2018	
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Vinyl skirting	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86254	BA9072		22/08/2018	
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Blue/White speckled	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86255	BA9072		22/08/2018	
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Brown VFT	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86256	BA9072		22/08/2018	
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Cream/Blue VFT	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86257	BA9072		22/08/2018	
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Beige VFT	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86258	BA9072		22/08/2018	
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Vinyl Skirting	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86259	BA9072		22/08/2018	
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Pale blue VFT	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86260	BA9072		22/08/2018	
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Cream/Blue VFT	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86261	BA9072		22/08/2018	

#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Beige VFT	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86262	BA9072		22/08/2018		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Pale blue VFT	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86263	BA9072		22/08/2018		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Beige VFT	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86264	BA9072		22/08/2018		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Beige VFT	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86265	BA9072		22/08/2018		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Beige VFT	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86266	BA9072		22/08/2018		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Grey mottled VFT	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86267	BA9072		22/08/2018		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Yellow mottled VFT	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86268	BA9072		22/08/2018		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Brown mottled VFT	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86269	BA9072		22/08/2018		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Cream VFT	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86270	BA9072		22/08/2018		
#REF!	QAA	Craigavon Hospital	01	Bitumen Adhesive	Light brown VFT	Composite Material	Chrysotile	Composite Material	Low	Manage and monitor		New Incident	HSG227	Unchecked	Very Low Risk	3		Identified	Very Low Risk	86271	BA9072		22/08/2018		
#REF!	QAA	Craigavon Hospital	01	Bitumen Adhesive	Light brown VFT	Composite Material	Chrysotile	Composite Material	Low	Manage and monitor		New Incident	HSG227	Unchecked	Very Low Risk	3	11/09/2019	Identified	Very Low Risk	86272	BA9072		22/08/2018		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Brown VFT	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86273	BA9072		22/08/2018		
#REF!	QAA	Craigavon Hospital	16	Bitumen Adhesive	Floor tile beneath carpet to office	Composite Material	Chrysotile	Composite Material	Very Low	Manage and monitor		Re-inspection	HSG227	Unchecked	Very Low Risk	2	24/06/2023	Identified	Very Low Risk	86274	BA9094	9302.2	24/06/2022	WHS	
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Cream VFT	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86275	BA9072		22/08/2018		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Vinyl skirting	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86276	BA9072		22/08/2018		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Cream VFT	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Correcting Previous Data	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86277	BA9072		22/08/2018		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Beige VFT	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86278	BA9072		22/08/2018		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	White/Blue VFT	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86279	BA9072		22/08/2018		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Grey/Green VFT	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86280	BA9072		22/08/2018		
#REF!	QAA	Craigavon Hospital	16	Bitumen Adhesive	Floor tile beneath carpe to office	Composite Material	Chrysotile	Composite Material	Very Low	Manage and monitor		Re-inspection	HSG227	Unchecked	Very Low Risk	2	24/06/2023	Identified	Very Low Risk	86281	BA9094	9302.2	24/06/2022	WHS	
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Cream VFT	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86282	BA9072		22/08/2018		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Light grey VFT	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86283	BA9072		22/08/2018		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Dark grey VFT	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86284	BA9072		22/08/2018		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Aqua VFT	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86285	BA9072		22/08/2018		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Light blue VFT	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86286	BA9072		22/08/2018		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Dark blue VFT	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86287	BA9072		22/08/2018		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Brown VFT	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86288	BA9072		22/08/2018		
#REF!	QAA	Craigavon Hospital	16	Bitumen Adhesive	Adhesive beneath carpet	Composite Material	Chrysotile	Composite Material	Very Low	Manage and monitor		Re-inspection	HSG227	Unchecked	Very Low Risk	2	24/06/2023	Identified	Very Low Risk	86289	BA9094	9302.2	24/06/2022	WHS	
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Mid blue VFT	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86290	BA9072		22/08/2018		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Cream VFT	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86291	BA9072		22/08/2018		
#REF!	QAA	Craigavon Hospital	16	Bitumen Adhesive	Floor tile to cuctboard	Composite Material	Chrysotile	Composite Material	Very Low	Manage and monitor		Re-inspection	HSG227	Unchecked	Very Low Risk	2	24/06/2023	Identified	Very Low Risk	86292	BA9094	9302.2	24/06/2022	WHS	
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Dark Brown VFT	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86293	BA9072		22/08/2018		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Pale brown VFT	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86294	BA9072		22/08/2018		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Light brown VFT	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86295	BA9072		22/08/2018		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Dark brown VFT	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86296	BA9072		22/08/2018		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Light brown VFT	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86297	BA9072		22/08/2018		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	White/Blue VFT	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86298	BA9072		22/08/2018		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Olive Green VFT	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86299	BA9072		22/08/2018		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Aqua VFT	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86300	BA9072		22/08/2018		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Dark Blue VFT	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86301	BA9072		22/08/2018		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Light Blue VFT	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86302	BA9072		22/08/2018		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Beige VFT	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86303	BA9072		22/08/2018		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Brown VFT	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86304	BA9072		22/08/2018		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	White/Blue VFT	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86305	BA9072		22/08/2018		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Cream VFT	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86306	BA9072		22/08/2018		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Dark brown VFT	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86307	BA9072		22/08/2018		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Light Brown VFT	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86308	BA9072		22/08/2018		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Beige VFT	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86309	BA9072		22/08/2018		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Light Grey VFT	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86310	BA9072		22/08/2018		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Vinyl skirting - grey	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86311	BA9072		22/08/2018		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Vinyl skirting - White	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86312	BA9072		22/08/2018		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Dark Brown VFT	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86313	BA9072		22/08/2018		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	White/Blue VFT	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86314	BA9072		22/08/2018		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Cream VFT	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86315	BA9072		22/08/2018		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Light Brown VFT	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86316	BA9072		22/08/2018		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Beige VFT	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86317	BA9072		22/08/2018		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	White/Blue VFT	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86318	BA9072		22/08/2018		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Dark Brown VFT	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86319	BA9072		22/08/2018		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Light Brown VFT	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86320	BA9072		22/08/2018		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Cream VFT	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86321	BA9072		22/08/2018		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Beige VFT	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86322	BA9072		22/08/2018		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Grey/White speckled VFT	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86323	BA9072		22/08/2018		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	White/Blue VFT	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86324	BA9072		22/08/2018		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Dark Brown VFT	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86325	BA9072		22/08/2018		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Light Brown VFT	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86326	BA9072		22/08/2018		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Beige VFT	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86327	BA9072		22/08/2018		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	White/Blue VFT	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86328	BA9072		22/08/2018		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Dark Brown VFT	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86329	BA9072		22/08/2018		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Cream VFT	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86330	BA9072		22/08/2018		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Light Brown VFT	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86331	BA9072		22/08/2018		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Beige VFT	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86332	BA9072		22/08/2018		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	White/Blue VFT	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86333	BA9072		22/08/2018		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Dark Brown VFT	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86334	BA9072		22/08/2018		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Cream VFT	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86335	BA9072		22/08/2018		
#REF!	RAC	Tower Hill Site	06	NO ASBESTOS	Dpc Horizontal	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86336	BA9097		31/08/2018		
#REF!	RAC	Tower Hill Site	06	NO ASBESTOS	Sarking felt to roof	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86337	BA9097		31/08/2018		

#REF!	RAC	Tower Hill Site	06	NO ASBESTOS	DPC Vertical	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86338	BA9097		31/08/2018			
#REF!	SAA	Daisy Hill Hospital Estate	09	NO ASBESTOS	Snot to wall at light switch wall 1 LHS of door	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86339	BA9113		03/09/2018			
#REF!	SAA	Daisy Hill Hospital Estate	09	NO ASBESTOS	Debris to light switch LHS wall 1	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86340	BA9113		03/09/2018			
#REF!	SAA	Daisy Hill Hospital Estate	09	NO ASBESTOS	Snot to wall 1m from light switch	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86341	BA9113		03/09/2018			
#REF!	SAA	Daisy Hill Hospital Estate	09	NO ASBESTOS	Snot to wall 1 at alarm	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86342	BA9113		03/09/2018			
#REF!	SAA	Daisy Hill Hospital Estate	09	NO ASBESTOS	Snot to wall 1 at far corner	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86343	BA9113		03/09/2018			
#REF!	SAA	Daisy Hill Hospital Estate	09	NO ASBESTOS	Snot to wall 2 at LHS corner	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86344	BA9113		03/09/2018			
#REF!	SAA	Daisy Hill Hospital Estate	09	NO ASBESTOS	Snot to wall 2 above electrical eanels	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86345	BA9113		03/09/2018			
#REF!	SAA	Daisy Hill Hospital Estate	09	NO ASBESTOS	Snot to wall 3 at rear corner	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86346	BA9113		03/09/2018			
#REF!	SAA	Daisy Hill Hospital Estate	09	NO ASBESTOS	Snot to wall 3 at RHS corner	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86347	BA9113		03/09/2018			
#REF!	SAA	Daisy Hill Hospital Estate	09	NO ASBESTOS	Snot to wall 4 RHS corner	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86348	BA9113		03/09/2018			
#REF!	SAA	Daisy Hill Hospital Estate	09	NO ASBESTOS	Snot to wall at door	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86349	BA9113		03/09/2018			
#REF!	SAA	Daisy Hill Hospital Estate	09	NO ASBESTOS	Snot to wall at door	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86350	BA9113		03/09/2018			
#REF!	SAA	Daisy Hill Hospital Estate	09	NO ASBESTOS	Sprayed insulation to ceiling	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86351	BA9113		03/09/2018			
#REF!	SAA	Daisy Hill Hospital Estate	09	NO ASBESTOS	Sprayed insulation to ceiling	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86352	BA9113		03/09/2018			
#REF!	SAA	Daisy Hill Hospital Estate	09	NO ASBESTOS	Pipework insulation	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86353	BA9113		03/09/2018			
#REF!	SAA	Daisy Hill Hospital Estate	09	NO ASBESTOS	Pipework insulation	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86354	BA9113		03/09/2018			
#REF!	RAC	Tower Hill Site	09	Bitumen Adhesive	Bitumen beneath vinyl & carpet to lobby and toilet	Composite Material	Chrysotile	Composite Material	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Very Low Risk	3	27/03/2021	Identified	Very Low Risk	86409	BA9098	9811/19	28/11/2019	WHS			
#REF!	RAC	Tower Hill Site	09	Infill Panel	Infill panel to window	Insulating Board	Amosite/Chrysotile	Unsealed Asbestos Insulation	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Medium Risk	7	27/03/2021	Identified	Medium Risk	86410	BA9098	9811/19	28/11/2019	WHS			
#REF!	RAC	Tower Hill Site	09	NO ASBESTOS	roof slate to front porch	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)		New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86411	BA9098		31/08/2018			
#REF!	RAC	Tower Hill Site	09	Roof Slate	Roof slate to main roof	Cement Products	Chrysotile	Unsealed Cement	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Very Low Risk	4	27/03/2021	Identified	Very Low Risk	86412	BA9098	9811/19	28/11/2019	WHS			
#REF!	RAC	Tower Hill Site	09	Board	Rope seal and board to safe	Insulating Board	Presumed Asbestos	Unsealed Board	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Medium Risk	8	27/03/2021	Presumed	Medium Risk	86413		9811/19	20/11/2019	WHS			
#REF!	RAC	Tower Hill Site	09	Bitumen Adhesive	Bitumen beneath vinvl and carpet	Composite Material	Presumed Asbestos	Composite Material	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Low Risk	5	27/03/2021	Stronolv Presumed	Low Risk	86414		9811/19	28/11/2019	WHS			
#REF!	RAC	Tower Hill Site	13	NO ASBESTOS	VFT beneath modern vinyl	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)		New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86415	BA9096		31/08/2018			
#REF!	RAC	Tower Hill Site	13	NO ASBESTOS	Sink pad	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)		New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86416	BA9096		31/08/2018			
#REF!	RAC	Tower Hill Site	13	NO ASBESTOS	Sarking felt	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)		New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86417	BA9096		31/08/2018			
#REF!	RHA	Roxborough Site	01	NO ASBESTOS	Insulation to cold water supply pipe	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)		New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86426	BA9149		13/09/2018			
#REF!	RHA	Roxborough Site	01	NO ASBESTOS	Insulation to hot water supply	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)		New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86427	BA9149		13/09/2018			
#REF!	RHA	Roxborough Site	01	NO ASBESTOS	Debris to pipe joint on horizontal run	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)		New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86428	BA9149		13/09/2018			
#REF!	RHA	Roxborough Site	01	NO ASBESTOS	Debris to pipe bracket on horizontal run	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)		New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86429	BA9149		13/09/2018			
#REF!	RHA	Roxborough Site	01	NO ASBESTOS	Debris to pipe bracket on vertical run	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)		New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86430	BA9149		13/09/2018			
#REF!	RHA	Roxborough Site	01	NO ASBESTOS	Debris to wall to rear of vertical and horizontal runs	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)		New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86431	BA9149		13/09/2018			
#REF!	RAC	Tower Hill Site	04	NO ASBESTOS	Debris round entrance hatch to tank room	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)		New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86433	BA0138		10/09/2018			
#REF!	RAC	Tower Hill Site	04	NO ASBESTOS	Debris beneath right hand tank	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)		New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86434	BA0138		10/09/2018			
#REF!	RAC	Tower Hill Site	04	Residue to Walls	Snot to wall at right hand side of door behind oipes	Thermal Insulation	NO ASBESTOS	Unsealed	Loose asbestos debris or residue	No further action required (Asbestos removed)		Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	10/05/2022	Identified	Asbestos Removed	86435	BA0138	9009/21	28/11/2019	WHS		
#REF!	RAC	Tower Hill Site	04	NO ASBESTOS	Debris to floor behind calorifier	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)		New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86436	BA0138		10/09/2018			
#REF!	RAC	Tower Hill Site	04	NO ASBESTOS	Snot to wall midway along wall 2 behind conduit	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)		New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86437	BA0138		10/09/2018			
#REF!	RAC	Tower Hill Site	04	NO ASBESTOS	Debris to top of control panel	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)		New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86438	BA0138		10/09/2018			
#REF!	RAC	Tower Hill Site	04	NO ASBESTOS	Ceiling strawboard	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)		New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86439	BA0138		10/09/2018			
#REF!	RAC	Tower Hill Site	04	Residue to Walls	Snot to wall RHS of ladder to water tank room - hish level	Thermal Insulation	NO ASBESTOS	unsealed	Loose asbestos debris or residue	No further action required (Asbestos removed)		Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	10/05/2022	Identified	Asbestos Removed	86440	BA0138	9009/21	28/11/2019	WHS		
#REF!	RAC	Tower Hill Site	04	Residue to Walls	Snot to wall RHS of ladder to water tank room - low level	Thermal Insulation	NO ASBESTOS	unsealed	Loose asbestos debris or residue	No further action required (Asbestos removed)		Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	10/05/2022	Identified	Asbestos Removed	86441	BA0138	9009/21	28/11/2019	WHS		
#REF!	RAC	Tower Hill Site	04	NO ASBESTOS	Debris to floor behind expansion tank	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)		New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86442	BA0138		10/09/2018			
#REF!	RAC	Tower Hill Site	04	NO ASBESTOS	Debris to brackets mid way along wall 3	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)		New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86443	BA0138		10/09/2018			
#REF!	RAC	Tower Hill Site	04	Residue to Walls	Snot to wall behind flue pipe RHS	Thermal Insulation	NO ASBESTOS	unsealed	Loose asbestos debris or residue	No further action required (Asbestos removed)		Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	10/05/2022	Identified	Asbestos Removed	86444	BA0138	9009/21	28/11/2019	WHS		
#REF!	RAC	Tower Hill Site	04	Residue to Walls	Snot to wall 3, top RHS	Thermal Insulation	NO ASBESTOS	unsealed	Loose asbestos debris or residue	No further action required (Asbestos removed)		Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	10/05/2022	Identified	Asbestos Removed	86445	BA0138	9009/21	28/11/2019	WHS		
#REF!	RAC	Tower Hill Site	04	Residue to Walls	Snot to high level on wall 4 midway along	Thermal Insulation	NO ASBESTOS	unsealed	Loose asbestos debris or residue	No further action required (Asbestos removed)		Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	10/05/2022	Identified	Asbestos Removed	86446	BA0138	9009/21	28/11/2019	WHS		
#REF!	RAC	Tower Hill Site	04	Residue to Walls	Snot to wall LHS of gas boiler 2	Thermal Insulation	NO ASBESTOS	unsealed	Loose asbestos debris or residue	No further action required (Asbestos removed)		Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	10/05/2022	Identified	Asbestos Removed	86447	BA0138	9009/21	28/11/2019	WHS		
#REF!	RAC	Tower Hill Site	04	NO ASBESTOS	Debris to floor beneath boiler 1	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)		New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86448	BA0138		10/09/2018			
#REF!	RAC	Tower Hill Site	04	NO ASBESTOS	Debris to pipe bracket on wall 1 to RHS	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)		New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86449	BA0138		10/09/2018			
#REF!	RAC	Tower Hill Site	04	NO ASBESTOS	Debris to wall 1 to RHS of door	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)		New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86450	BA0138		10/09/2018			
#REF!	RAC	Tower Hill Site	04	NO ASBESTOS	Bitumen lining to floor duct	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)		New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86451	BA0138		10/09/2018			
#REF!	RAC	Tower Hill Site	04	NO ASBESTOS	Debris to floor duct	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)		New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86452	BA0138		10/09/2018			
#REF!	RAC	Tower Hill Site	04	NO ASBESTOS	Debris to floor duct	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)		New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86453	BA0138		10/09/2018			
#REF!	QAA	Craigavon Hospital	01	Floor Tile and Bitumen Adhesive	Orange thermoplastic tile to floor	Composite Material	Chrysotile	Composite Material	Low	Manage and monitor		New Incident	HSG227	Unchecked	Very Low Risk	3	10/10/2019	Identified	Very Low Risk	86454	BA9191		03/09/2018			
#REF!	QAA	Craigavon Hospital	01	Floor Tile and Bitumen Adhesive	Blue thermoplastic tile to floor	Composite Material	Chrysotile	Composite Material	Low	Manage and monitor		New Incident	HSG227	Unchecked	Very Low Risk	3	10/10/2019	Identified	Very Low Risk	86455	BA9191		03/09/2018			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Loose ceiling tiles	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)		New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86456	BA9191		03/09/2018			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Board lining to notice board to wall	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)		New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86457	BA9191		03/09/2018			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Sink pad below sink	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)		New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86458	BA9191		03/09/2018			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Debris and bitumen to front of riser	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)		New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86459	BA9191		03/09/2018			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Light blue thermoplastic floor tile	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)		New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86460	BA9191		03/09/2018			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Non slip floor covering to floor	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)		New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86461	BA9191		03/09/2018			
#REF!	QAA	Craigavon Hospital	01	Fire Break Panel	Firebreak above door to E-023	Insulating Board	Amosite/Chrysotile	Unsealed Asbestos Insulation	Low	Manage and monitor		New Incident	HSG227	Unchecked	Low Risk	6	10/10/2019	Identified	Low Risk	86462	BA9191		03/09/2018			
#REF!	QAA	Craigavon Hospital	01	Fire Break Panel	firebreak above door to E-018	Insulating Board	Amosite/Chrysotile	Unsealed Asbestos Insulation	Low	Manage and monitor		New Incident	HSG227	Unchecked	Low Risk	6	10/10/2019	Identified	Low Risk	86463	BA9191		03/09/2018			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Firebreak above door to E-002	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)		New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86464	BA9191		03/09/2018			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Firebreak above door to E-011	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)		New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86465	BA9191		03/09/2018			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	White floor tile to floor of riser	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)		New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86466	BA9191		03/09/2018			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Light grey floor tiles to riser floor	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)		New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86467	BA9191		03/09/2018			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Debris to floor of riser	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)		New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86468	BA9191		03/09/2018			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Concealed floor tile below vinyl sheet	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)		New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86469	BA9191		03/09/2018			
#REF!	QAA	Craigavon Hospital	01	Lino Flooring	Vinvl floor sheet	Composite Material	Presumed Asbestos	Composite Material	Low	Manage and monitor		New Incident	HSG227	Unchecked	Low Risk	5	10/10/2019	Presumed	Low Risk	86470			03/09/2018			
#REF!	SJD	Rathfriland Road Site	03	NO ASBESTOS	Office red vinyl beneath carpet	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)		New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86503	BA9246		23/10/2018			
#REF!	SJD	Rathfriland Road Site	03	NO ASBESTOS	Office red vinyl beneath carpet	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)		New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86504	BA9246		23/10/2018			
#REF!	SJD	Rathfriland Road Site	03	NO ASBESTOS	Corridor red vinyl beneath carpet	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)		New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86505	BA9246		23/10/2018			
#REF!	SJD	Rathfriland Road Site	03	NO ASBESTOS	Staircase and landing and adjoining corridor red vinyl beneath carpet	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)		New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86506	BA9246		23/10/2018			
#REF!	SJD	Rathfriland Road Site	03	NO ASBESTOS	Staircase and landing and adjoining corridor red vinyl beneath carpet	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)		New Incident	HSG227	Unchecked	NO ASBESTOS	0		Previously Identified	No Asbestos Detected	86507			23/10/2018			
#REF!	SJD	Rathfriland Road Site	03	NO ASBESTOS	Staircase and landing step nosing	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)		New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86508	BA9246		23/10/2018			
#REF!	SJD	Rathfriland Road Site	03	NO ASBESTOS	Office grey vinyl beneath carpet	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)		New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86509	BA9246		23/10/2018			

#REF!	SJD	Rathfriland Road Site	03	NO ASBESTOS	Office grey vinyl beneath carpet	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Previously Identified	No Asbestos Detected	86510			23/10/2018		
#REF!	SJD	Rathfriland Road Site	03	NO ASBESTOS	3 Adjoining corridors red vinyl beneath carpet	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86511	BA0246		23/10/2018		
#REF!	SJD	Rathfriland Road Site	03	NO ASBESTOS	3 Adjoining corridors red vinyl beneath carpet	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Previously Identified	No Asbestos Detected	86512			23/10/2018		
#REF!	SJD	Rathfriland Road Site	03	NO ASBESTOS	3 Adjoining corridors red vinyl beneath carpet	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Previously Identified	No Asbestos Detected	86513			23/10/2018		
#REF!	SJD	Rathfriland Road Site	03	NO ASBESTOS	Office cream vinyl beneath carpet	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86514	BA0246		23/10/2018		
#REF!	SJD	Rathfriland Road Site	03	Wall Panels	Hot press wall panels	Insulating Board	Amosite	[redacted]	Medium	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	Medium Risk	8	13/03/2023	Identified	Medium Risk	86515	BA0246	[redacted]	31/08/2022	WHS		
#REF!	SJD	Rathfriland Road Site	03	NO ASBESTOS	Attic modern pipe insulation	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86516	BA0246		23/10/2018		
#REF!	SJD	Rathfriland Road Site	03	NO ASBESTOS	Kitchen sink pad	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86517	BA0246		23/10/2018		
#REF!	SJD	Rathfriland Road Site	03	NO ASBESTOS	Office blue vinyl beneath carpet tiles	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86518	BA0246		23/10/2018		
#REF!	SJD	Rathfriland Road Site	03	NO ASBESTOS	Office red vinyl beneath carpet tiles	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86519	BA0246		23/10/2018		
#REF!	SJD	Rathfriland Road Site	03	NO ASBESTOS	Office grey vinyl beneath carpet tiles	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86520	BA0246		23/10/2018		
#REF!	SJD	Rathfriland Road Site	03	NO ASBESTOS	Office grey vinyl beneath carpet tiles	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Previously Identified	No Asbestos Detected	86521			23/10/2018		
#REF!	SJD	Rathfriland Road Site	03	NO ASBESTOS	Court yard ceiling panels	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86522	BA0246		23/10/2018		
#REF!	SJD	Rathfriland Road Site	03	Fuse Flash Guards	MEM switch and fuse equipment	Textiles & Paper	Presumed Asbestos	Enclosed Fuse Flash Guards	Low	Conduct further investigation prior to relevant ma	Re-inspection	HSG227	Unchecked	Medium Risk	7	13/03/2023	Presumed	Medium Risk	86523	BA0246	930/22	31/08/2022	WHS		
#REF!	NAB	St.Lukes	17	NO ASBESTOS	Electrical cupboard base	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	84563	BA0267		02/11/2018		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Firebreak above double doors adjacent to cashier office	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86564	BA0225		16/10/2018		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Firebreak to corridor adjacent to courtvard	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86565	BA0225		16/10/2018		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Firebreak over door to 080	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86566	BA0225		16/10/2018		
#REF!	QAA	Craigavon Hospital	01	Fire Break Panel	Firebreak over foor to 1073	Insulating Board	Amosite	[redacted]	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Low Risk	6	16/09/2023	Identified	Low Risk	86567	BA0225	[redacted]	16/09/2022	WHS		
#REF!	QAA	Craigavon Hospital	01	Fire Break Panel	Firebreak over door to 802	Insulating Board	Amosite	[redacted]	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Low Risk	6	16/09/2023	Identified	Low Risk	86568	BA0225	[redacted]	16/09/2022	WHS		
#REF!	QAA	Craigavon Hospital	01	Fire Break Panel	Firebreak over door to 920	Insulating Board	Amosite	[redacted]	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Low Risk	6	16/09/2023	Identified	Low Risk	86569	BA0225	[redacted]	16/09/2022	WHS		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Firebreak over door to 921	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86570	BA0225		16/10/2018		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Firebreak over door to 1034	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86571	BA0225		16/10/2018		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Firebreak over door to 925	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86572	BA0225		16/10/2018		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Firebreak over door to 1025	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86573	BA0225		16/10/2018		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Firebreak over door to 1025	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86574	BA0225		16/10/2018		
#REF!	QAA	Craigavon Hospital	01	Fire Break Panel	Firebreak over foor to 931	Insulating Board	Amosite	[redacted]	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Low Risk	6	15/09/2023	Identified	Low Risk	86575	BA0225	[redacted]	15/09/2022	WHS		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Firebreak over door to 1016	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86576	BA0225		16/10/2018		
#REF!	QAA	Craigavon Hospital	01	Fire Break Panel	Firebreak over door to 931	Insulating Board	Amosite	[redacted]	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Low Risk	6	29/09/2023	Identified	Low Risk	86577	BA0225	[redacted]	29/09/2022	WHS		
#REF!	QAA	Craigavon Hospital	01	Fire Break Panel	Firebreak over door to 933	Insulating Board	Amosite	[redacted]	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Low Risk	6	29/09/2023	Identified	Low Risk	86578	BA0225	[redacted]	29/09/2022	WHS		
#REF!	QAA	Craigavon Hospital	01	Fire Break Panel	Firebreak over door to 969	Insulating Board	Amosite	[redacted]	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Low Risk	6	15/09/2023	Identified	Low Risk	86579	BA0225	[redacted]	15/09/2022	WHS		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Firebreak over door to 978	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86580	BA0225		16/10/2018		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Firebreak over door to 980	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86581	BA0225		16/10/2018		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Firebreak over door to corridor	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86582	BA0225		16/10/2018		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Firebreak over roller shutter	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86583	BA0225		16/10/2018		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Firebreak over door to 826	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86584	BA0225		16/10/2018		
#REF!	QAA	Craigavon Hospital	01	Fire Break Panel	Firebreak over door to 802	Insulating Board	Amosite	[redacted]	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Low Risk	6	16/09/2023	Identified	Low Risk	86585	BA0225	[redacted]	16/09/2022	WHS		
#REF!	QAA	Craigavon Hospital	01	Fire Break Panel	Firebreak over door to 728	Insulating Board	Amosite	[redacted]	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Low Risk	6	16/09/2023	Identified	Low Risk	86586	BA0225	[redacted]	16/09/2022	WHS		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Firebreak over door to 851	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86587	BA0225		16/10/2018		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Firebreak over door to 848	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86588	BA0225		16/10/2018		
#REF!	QAA	Craigavon Hospital	01	Fire Break Panel	Firebreak over door to 880	Insulating Board	Amosite	[redacted]	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Low Risk	6	16/09/2023	Identified	Low Risk	86589	BA0225	[redacted]	16/09/2022	WHS		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Firebreak over door to 894	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86590	BA0225		16/10/2018		
#REF!	QAA	Craigavon Hospital	01	Fire Break Panel	Firebreakover door adjacent to 856	Insulating Board	Amosite	[redacted]	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Low Risk	6	21/09/2023	Identified	Low Risk	86591	BA0225	[redacted]	21/09/2022	WHS		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Firebreak over double doors	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86592	BA0225		16/10/2018		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Firebreak over RHS door to 104	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86593	BA0225		16/10/2018		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Firebreak over LHS door to 104	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86594	BA0225		16/10/2018		
#REF!	QAA	Craigavon Hospital	01	Fire Break Panel	Firebreak over door to 704	Insulating Board	Amosite	[redacted]	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Low Risk	6	16/09/2023	Identified	Low Risk	86595	BA0225	[redacted]	16/09/2022	WHS		
#REF!	QAA	Craigavon Hospital	01	Fire Break Panel	Firebreak over door to 650	Insulating Board	Amosite	[redacted]	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Low Risk	6	11/10/2023	Identified	Low Risk	86596	BA0225	[redacted]	11/10/2022	WHS		
#REF!	QAA	Craigavon Hospital	01	Fire Break Panel	Firebreak over door to 703	Insulating Board	Amosite	[redacted]	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Low Risk	6	21/09/2023	Identified	Low Risk	86597	BA0225	[redacted]	21/09/2022	WHS		
#REF!	QAA	Craigavon Hospital	01	Fire Break Panel	Firebreak over door to 704	Insulating Board	Amosite	[redacted]	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Low Risk	6	21/09/2023	Identified	Low Risk	86598	BA0225	[redacted]	21/09/2022	WHS		
#REF!	QAA	Craigavon Hospital	01	Fire Break Panel	Firebreak over door to 117	Insulating Board	Amosite	[redacted]	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Low Risk	6	11/10/2023	Identified	Low Risk	86599	BA0225	[redacted]	11/10/2022	WHS		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Firebreak over door to 080	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86600	BA0225		16/10/2018		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Firebreak over door to 193	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86601	BA0225		16/10/2018		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Firebreak over door to 197	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86602	BA0225		16/10/2018		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Firebreak over door to 259	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86603	BA0225		16/10/2018		
#REF!	QAA	Craigavon Hospital	01	Fire Break Panel	Firebreak over door to 309	Insulating Board	Amosite	[redacted]	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Low Risk	6	21/09/2023	Identified	Low Risk	86604	BA0225	[redacted]	21/09/2022	WHS		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Firebreak over door to 309	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86605	BA0225		16/10/2018		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Firebreak over door to 309	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86606	BA0225		16/10/2018		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Firebreak over door to 325	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86607	BA0225		16/10/2018		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Firebreak over door to 317	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86608	BA0225		16/10/2018		
#REF!	QAA	Craigavon Hospital	01	Fire Break Panel	Firebreak over door to 207	Insulating Board	Amosite	[redacted]	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Low Risk	6	11/10/2023	Identified	Low Risk	86609	BA0225	[redacted]	11/10/2022	WHS		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Firebreak over door to 215	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86610	BA0225		16/10/2018		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Firebreak over door to 182	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86611	BA0225		16/10/2018		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Firebreak over RHS door to 380	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86612	BA0225		16/10/2018		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Firebreak over LHS door to 380	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86613	BA0225		16/10/2018		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Firebreak over door to 374	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86614	BA0225		16/10/2018		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Firebreak over door to 383	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86615	BA0225		16/10/2018		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Firebreak over door to 383	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86616	BA0225		16/10/2018		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Firebreak over RHS door to 380	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86617	BA0225		16/10/2018		
#REF!	QAA	Craigavon Hospital	01	Fire Break Panel	Firebreak over LHS door to 380	Insulating Board	Amosite	[redacted]	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Low Risk	6	21/09/2023	Identified	Low Risk	86618	BA0225	[redacted]	21/09/2022	WHS		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Firebreak over door to 391	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86619	BA0225		16/10/2018		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Firebreak over door to 391	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86620	BA0225		16/10/2018		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Firebreak over door to 415	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86621	BA0225		16/10/2018		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Firebreak over door to 418	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86622	BA0225		16/10/2018		
#REF!	QAA	Craigavon Hospital	01	Fire Break Panel	Firebreak over door to 446	Insulating Board	Amosite	[redacted]	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Low Risk	6	21/09/2023	Identified	Low Risk	86623	BA0225	[redacted]	21/09/2022	WHS		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Firebreak over door to 515	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86624	BA0225		16/10/2018		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Firebreak over door to 481	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86625	BA0225		16/10/2018		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Firebreak over door to 473	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86626	BA0225		16/10/2018		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Firebreak over door to 482	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86627	BA0225		16/10/2018		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Firebreak over door to 493	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86628	BA0225		16/10/2018		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Firebreak over door to 174	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86629	BA0225		16/10/2018		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Firebreak over door to 494	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86630	BA0225		16/10/2018		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Firebreak over door to 375	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86631	BA0225		16/10/2018		

#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Firebreak over door to 004	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86632	BA9271		05/11/2018	
#REF!	QAA	Craigavon Hospital	01	Fire Break Panel	Firebreak over door to 003	Insulating Board	Amosite	[redacted]	Low	Manage and monitor	New Incident	HSG227	Unchecked	Low Risk	6	15/11/2019	Identified	Low Risk	86633	BA9271		05/11/2018	
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Firebreak over door to 012	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86634	BA9271		05/11/2018	
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Firebreak over doors 015, 016	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86635	BA9271		05/11/2018	
#REF!	QAA	Craigavon Hospital	01	Fire Break Panel	Firebreak over doors to 097	Insulating Board	Amosite	[redacted]	Low	Manage and monitor	New Incident	HSG227	Unchecked	Low Risk	6	15/11/2019	Identified	Low Risk	86636	BA9271		05/11/2018	
#REF!	QAA	Craigavon Hospital	01	Fire Break Panel	Firebreak over door to 133	Insulating Board	Amosite	[redacted]	Low	Manage and monitor	New Incident	HSG227	Unchecked	Low Risk	6	15/11/2019	Identified	Low Risk	86637	BA9271		05/11/2018	
#REF!	QAA	Craigavon Hospital	01	Fire Break Panel	Firebreak over door to 140	Insulating Board	Amosite	[redacted]	Low	Manage and monitor	New Incident	HSG227	Unchecked	Low Risk	6		Identified	Low Risk	86638	BA9271		05/11/2018	
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Firebreak over door to 223	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86639	BA9271		05/11/2018	
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Firebreak over door to 285	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86640	BA9271		05/11/2018	
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Firebreak over door to 265	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86641	BA9271		05/11/2018	
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Firebreak over door to 271	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86642	BA9271		05/11/2018	
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Firebreak over door to 034	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86643	BA9271		05/11/2018	
#REF!	QAA	Craigavon Hospital	01	Fire Break Panel	Firebreak over door to 026	Insulating Board	Amosite	[redacted]	Low	Manage and monitor	New Incident	HSG227	Unchecked	Low Risk	6	15/11/2019	Identified	Low Risk	86644	BA9271		05/11/2018	
#REF!	QAA	Craigavon Hospital	01	Fire Break Panel	Firebreak over door to 021	Insulating Board	Amosite	[redacted]	Low	Manage and monitor	New Incident	HSG227	Unchecked	Low Risk	6	15/11/2019	Identified	Low Risk	86645	BA9271		05/11/2018	
#REF!	QAA	Craigavon Hospital	01	Fire Break Panel	Firebreak over door to 002	Insulating Board	Amosite	Sealed Sorav or Lacoino	Low	Manage and monitor	New Incident	HSG227	Unchecked	Low Risk	6	15/11/2019	Identified	Low Risk	86646	BA9271		05/11/2018	
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Firebreak over door to 002	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86647	BA9271		05/11/2018	
#REF!	QAA	Craigavon Hospital	01	Fire Break Panel	Firebreak over door to 018	Insulating Board	Amosite	[redacted]	Low	Manage and monitor	New Incident	HSG227	Unchecked	Low Risk	6	15/11/2019	Identified	Low Risk	86648	BA9271		05/11/2018	
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Firebreak over door to 002	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86649	BA9271		05/11/2018	
#REF!	QAA	Craigavon Hospital	01	Fire Break Panel	Firebreak over door to 002	Insulating Board	Amosite	[redacted]	Low	Manage and monitor	New Incident	HSG227	Unchecked	Low Risk	6	15/11/2019	Identified	Low Risk	86650	BA9271		05/11/2018	
#REF!	QAA	Craigavon Hospital	01	Fire Break Panel	Firebreak over door to 021	Insulating Board	Amosite	[redacted]	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Low Risk	6	20/01/2024	Identified	Low Risk	86651	BA9271	9302/2	20/01/2023	WHS
#REF!	QAA	Craigavon Hospital	01	Fire Break Panel	Firebreak over door to 002	Insulating Board	Amosite	[redacted]	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Low Risk	6	05/07/2023	Identified	Low Risk	86652	BA9271	9302/2	05/07/2022	WHS
#REF!	QAA	Craigavon Hospital	01	Fire Break Panel	Firebreak over door to 076	Insulating Board	Amosite	[redacted]	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Low Risk	6	05/07/2023	Identified	Low Risk	86653	BA9271	9302/2	05/07/2022	WHS
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Firebreak over door to 080	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Error Entry	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86654	BA9271		05/11/2018	
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Firebreak over door	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86655	BA9271		05/11/2018	
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Firebreak over door to 073	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86656	BA9271		05/11/2018	
#REF!	QAA	Craigavon Hospital	01	Panel	Firebreak over door to 024	Cement Products	Chrysotile	Sealed Cement	Low	Manage and monitor	New Incident	HSG227	Unchecked	Very Low Risk	3	15/11/2019	Identified	Very Low Risk	86657	BA9271		05/11/2018	
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Firebreak over door to 335	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86658	BA9271		05/11/2018	
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Firebreak over door to 336	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86659	BA9271		05/11/2018	
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Firebreak over door to 330	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86660	BA9271		05/11/2018	
#REF!	QAC	Lurgan Hospital	01	NO ASBESTOS	Window reveal to RHS window LHS panel	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86661	BA9280	9506/18	11/08/2018	WHS
#REF!	QAC	Lurgan Hospital	01	NO ASBESTOS	Window reveal to RHS window top panel	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86662	BA9280	9506/18	11/08/2018	WHS
#REF!	QAC	Lurgan Hospital	01	NO ASBESTOS	Window reveal to RHS window RHS panel	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86663	BA9280	9506/18	11/08/2018	WHS
#REF!	QAC	Lurgan Hospital	01	Fire Break Panel	Firebreak panel above door	Insulating Board	Amosite	[redacted]	Medium	Conduct annual routine inspections	Correcting previous data entry error	HSG227	Unchecked	Medium Risk	7	29/07/2021	Identified	Medium Risk	86664	BA9284	9302/2	22/07/2020	WHS
#REF!	QAC	Lurgan Hospital	01	Fire Break Panel	Vertical firebreak panel at side of	Insulating Board	Amosite	[redacted]	Medium	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Medium Risk	7	29/07/2021	Identified	Medium Risk	86665	BA9284	9302/2	22/07/2020	WHS
#REF!	QAC	Lurgan Hospital	01	NO ASBESTOS	Sink pad	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86666	BA9284		13/11/2018	
#REF!	QAC	Lurgan Hospital	01	Heat Proof Mats	Ironing board pad	Cement Products	Chrysotile	Unsealed Board	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Low Risk	5	29/07/2021	Identified	Low Risk	86667	BA9284	9302/2	22/07/2020	WHS
#REF!	QAC	Lurgan Hospital	01	NO ASBESTOS	Cream vinyl floor tile & bitumen	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86668	BA9284		13/11/2018	
#REF!	QAC	Lurgan Hospital	01	NO ASBESTOS	Green vinyl floor tile and bitumen	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86669	BA9284		13/11/2018	
#REF!	QAC	Lurgan Hospital	01	NO ASBESTOS	Ceiling panel	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86670	BA9284		13/11/2018	
#REF!	RAB	Longstone/Mullinure	38	NO ASBESTOS	Brake shoe	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86671	BA9285		13/11/2018	
#REF!	RAB	Lonnstone/Mullinure	38	Fuse Flash Guards	Exterrical switchoear	Textiles & Paper	Presumed Asbestos	Enclosed Fuse Flash Guards	Low	Label & Manage	Re-inspection	HSG227	Unchecked	Medium Risk	7	25/03/2021	Presumed	Medium Risk	86672		9302/2	23/11/2019	WHS
#REF!	QAC	Lurgan Hospital	06	Cement Pipe	Pipe protruding through wall	Cement Products	Chrysotile	Unsealed Cement	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Very Low Risk	4	20/06/2023	Identified	Very Low Risk	86673	BA9289	9302/2	12/06/2022	WH Stephens
#REF!	RAB	Lonnstone/Mullinure	02	Residue to Walls	Snot to wall	Thermal Insulation	Amosite	Unsealed	Loose asbestos	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	Hioh Risk	11	27/03/2021	Identified	Hioh Risk	86674	BA9286	9501/1	20/01/2020	WHS
#REF!	RAB	Lonnstone/Mullinure	02	Residue to Walls	Snot to wall	Thermal Insulation	Amosite	unsealed	Loose asbestos	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	Hioh Risk	11	27/03/2021	Identified	Hioh Risk	86675	BA9286	9501/1	20/01/2020	WHS
#REF!	RAB	Lonnstone/Mullinure	02	Residue to Walls	Snot to wall	Thermal Insulation	Amosite	Medium	Loose asbestos	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	High Risk	10	27/03/2021	Identified	High Risk	86676	BA9286	9501/1	20/01/2020	WHS
#REF!	RAB	Lonnstone/Mullinure	02	Residue to Walls	Snot to wall	Thermal Insulation	Amosite	unsealed	Loose asbestos	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	Hioh Risk	11	27/03/2021	Identified	Hioh Risk	86677	BA9286	9501/1	20/01/2020	WHS
#REF!	RAB	Lonnstone/Mullinure	02	Debris Insulation	Debris to stee bracket	Loose Asbestos	Amosite	Loose Asbestos Debris	Loose asbestos	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	Hioh Risk	11	27/03/2021	Identified	Hioh Risk	86678	BA9286	9501/1	20/01/2020	WHS
#REF!	RAB	Lonnstone/Mullinure	01	Residue to Walls	Snot to wall	Thermal Insulation	Amosite	unsealed	Loose asbestos	Remove (Controlled Conditions)	New Incident	HSG227	Unchecked	High Risk	11	21/02/2019	Identified	High Risk	86679	BA9287		13/11/2018	
#REF!	RAB	Lonnstone/Mullinure	01	Residue to Walls	Snot to wall	Thermal Insulation	Amosite	unsealed	Loose asbestos	Remove (Controlled Conditions)	New Incident	HSG227	Unchecked	High Risk	11	21/02/2019	Identified	High Risk	86680	BA9287		13/11/2018	
#REF!	RAB	Lonnstone/Mullinure	01	Residue to Walls	Snot to wall	Thermal Insulation	Amosite	unsealed	Loose asbestos	Remove (Controlled Conditions)	New Incident	HSG227	Unchecked	High Risk	11	21/02/2019	Identified	High Risk	86681	BA9287		13/11/2018	
#REF!	RAB	Longstone/Mullinure	01	Residue to Walls	Snot to wall	Thermal Insulation	Amosite	unsealed	Loose asbestos	Remove (Controlled Conditions)	New Incident	HSG227	Unchecked	High Risk	11	21/02/2019	Identified	High Risk	86682	BA9287		13/11/2018	
#REF!	RAA	South Tyrone Hospital	02	NO ASBESTOS	Green replacement vinyl floor tile	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86702	BA9308		20/11/2018	
#REF!	RAA	South Tyrone Hospital	12	Residue to Walls	Snot to wall	Thermal Insulation	Amosite	[redacted]	Loose asbestos	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	High Risk	11	15/12/2023	Identified	High Risk	86703	BA9307	9302/2	15/12/2022	WHS
#REF!	RAA	South Tyrone Hospital	12	Residue to Walls	Snot to wall	Thermal Insulation	Amosite	[redacted]	Loose asbestos	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	High Risk	11	15/12/2023	Identified	High Risk	86704	BA9307	9302/2	15/12/2022	WHS
#REF!	RAA	South Tyrone Hospital	12	floor tile	Vinyl floor tile	Composite Material		Composite Material	Low	No further action required (Asbestos removed)	Re-inspection	HSG227	Unchecked	NO ASBESTOS	0	15/12/2023	Identified	Asbestos Removed	86705	BA9307	9302/2	15/12/2022	WHS
#REF!	QAC	Lurgan Hospital	02	NO ASBESTOS	Brake shoe to lift motor	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86706	BA9288		13/11/2018	
#REF!	QAC	Lurgan Hospital	02	Wall Panels	Panels to wall at door	Insulating Board		Sealed Asbestos Insulation Board	Low	No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0		Identified	Asbestos Removed	86707	BA9288	9299/2	15/09/2022	WHS
#REF!	QAC	Lurgan Hospital	02	Ceiling Panel	Ceiling panel	Insulating Board		[redacted]	Low	Manage and monitor	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	26/09/2023	Identified	Asbestos Removed	86708	BA9288	9299/2	15/09/2022	WHS
#REF!	QAC	Lurgan Hospital	02	Panel	Strip below door header	Insulating Board	Amosite/Chrysotile	[redacted]	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Low Risk	6	20/09/2023	Identified	Low Risk	86709	BA9288	[redacted]	12/09/2022	WHS
#REF!	QAC	Lurgan Hospital	02	NO ASBESTOS	Ceiling panel	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86710	BA9288		13/11/2018	
#REF!	QAC	Lurgan Hospital	02	Fuse Flash Guards	Fuse box	Textiles & Paper	Presumed Asbestos	Unsealed	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Medium Risk	9	20/03/2023	Presumed	Medium Risk	86711		9302/2	12/09/2022	WHS
#REF!	RSA	Dungannon Clinic	01	Residue to Walls	Snot to wall	Thermal Insulation	NO ASBESTOS	unsealed	Loose asbestos debris or residue	No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	13/04/2022	Identified	Asbestos Removed	86712	BA9277	9000/21	19/11/2019	WHS
#REF!	RSA	Dungannon Clinic	01	Residue to Walls	Snot to wall	Thermal Insulation	NO ASBESTOS	unsealed	Loose asbestos debris or residue	No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	13/04/2022	Identified	Asbestos Removed	86713	BA9277	9000/21	19/11/2019	WHS
#REF!	RSA	Dungannon Clinic	01	Residue to Walls	Snot to wall	Thermal Insulation	NO ASBESTOS	unsealed	Loose asbestos debris or residue	No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	13/04/2022	Identified	Asbestos Removed	86714	BA9277	9000/21	19/11/2019	WHS
#REF!	RSA	Dungannon Clinic	01	Residue to Walls	Snot to wall	Thermal Insulation	NO ASBESTOS	unsealed	Loose asbestos debris or residue	No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	13/04/2022	Identified	Asbestos Removed	86715	BA9277	9000/21	19/11/2019	WHS
#REF!	RSA	Dungannon Clinic	01	Residue to Walls	Snot to wall	Thermal Insulation	NO ASBESTOS	unsealed	Loose asbestos debris or residue	No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	13/04/2022	Identified	Asbestos Removed	86716	BA9277	9000/21	19/11/2019	WHS
#REF!	RSA	Dungannon Clinic	01	Residue to Walls	Snot to wall	Thermal Insulation	NO ASBESTOS	unsealed	Loose asbestos debris or residue	No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	13/04/2022	Identified	Asbestos Removed	86717	BA9277	9000/21	19/11/2019	WHS
#REF!	RSA	Dungannon Clinic	01	Residue to Walls	Snot to wall	Thermal Insulation	NO ASBESTOS	unsealed	Loose asbestos debris or residue	No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	13/04/2022	Identified	Asbestos Removed	86718	BA9277	9000/21	19/11/2019	WHS
#REF!	RSA	Dungannon Clinic	01	Residue to Walls	Snot to wall	Thermal Insulation	NO ASBESTOS	unsealed	Loose asbestos debris or residue	No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	13/04/2022	Identified	Asbestos Removed	86719	BA9277	9000/21	19/11/2019	WHS
#REF!	RSA	Dungannon Clinic	01	Stair Nosing	Step nosing	Composite Material	Chrysotile	Composite Material	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Very Low Risk	3	03/04/2021	Identified	Very Low Risk	86720	BA9277	[redacted]	19/11/2019	WHS
#REF!	RSA	Dungannon Clinic	01	NO ASBESTOS	Cement tiles to front	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86721	BA9277		05/11/2018	
#REF!	RSA	Dungannon Clinic	01	NO ASBESTOS	Visible DPC	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86722	BA9277		05/11/2018	
#REF!	RSA	Dungannon Clinic	01	NO ASBESTOS	Soffit	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86723	BA9277		05/11/2018	
#REF!	SAA	Daisy Hill Hospital Estate	11	floor tile	Floor tiles	Composite Material	Presumed Asbestos	Composite Material	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Low Risk	5	15/09/2023	Strongly Presumed	Low Risk	86724		9302/2	22/04/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	11	floor tile	Floor tiles	Composite Material	Presumed Asbestos	Composite Material	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Low Risk	5	15/09/2023	Strongly Presumed	Low Risk	86725		9302/2	22/04/2022	WHS
#REF!	RAA	South Tyrone Hospital	19	Soffit Boards	Soffit	Cement Products	Chrysotile	Unsealed Cement	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Very Low Risk	4	15/12/2023	Identified	Very Low Risk	86726	BA9323	[redacted]	15/12/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Bitumen to underside of flat timber roof	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86727	BA9321	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Firebreak material in ceiling void above double doors on C/S7	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86728	BA9321	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	Gaskets	Gasket to redundant vertical pipe at wall adjacent to service road	Composite Material	Chrysotile	Composite Material	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Very Low Risk	3	13/12/2023	Identified	Very Low Risk	86729	BA9321	9300/22	26/10/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Residue to external wall adjacent to service road	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86730	BA9321	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Residue to external wall adjacent to service road	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86731	BA9321	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Residue to external wall adjacent to service road	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86732	BA9321	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Residue to external wall adjacent to service road	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86733	BA9321	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Residue to external wall adjacent to service road	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86734	BA9321	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Residue to external wall adjacent to service road	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86735	BA9321	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Redundant pipe insulation on floor of plant room beside external wall adjacent to service road	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86736	BA9321	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Debris to ceiling void	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86747	BA9348	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Mastic to firebreak	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86748	BA9348	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Debris to ceiling void	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86749	BA9348	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Insulation to pipework in ceiling void	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86750	BA9348	9506/18	20/03/2019	WHS

#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Debris to ceiling void	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86751	BA9348	950616	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Debris to ceiling void	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86752	BA9348	950616	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Loose insulation to ceiling void	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86753	BA9348	950616	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Debris to ceiling void	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86754	BA9348	950616	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Debris to ceiling void	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86755	BA9348	950616	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Debris to ceiling void	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86756	BA9348	950616	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Debris to ceiling void	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86757	BA9348	950616	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Firebreak to ceiling void	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86758	BA9348	950616	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Insulation around plastic RWG behind E-009	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86759	BA9348	950616	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Insulation to horizontal pipe behind E-013	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86760	BA9348	950616	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Debris outside E-008	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86761	BA9348	950616	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Debris to floor behind E-010	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86762	BA9348	950616	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Firebreak LHS main entrance lobby	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86763	BA9348	950616	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Debris to ceiling void outside recestion	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86764	BA9348	950616	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	Gaskets	Gasket to flange at coffee area	Textiles & Paper	Chrysotile	unsealed	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Medium Risk	7	14/06/2023	Identified	Medium Risk	86765	BA9348	950616	26/10/2022	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Firebreak to ceiling void at double doors near x-ray	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86766	BA9348	950616	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Bitumen on concrete	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86767	BA9348	950616	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Firebreak above double doors leadins to cardiac	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86768	BA9348	950616	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Firebreak above double doors leadins to C-326	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86769	BA9348	950616	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Firebreak above double doors leadins to C-203	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86770	BA9348	950616	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Firebreak above double doors leadins to C-350	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86771	BA9348	950616	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Firebreak above double doors leadins to C-203	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86772	BA9348	950616	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Firebreak above double doors leadins to C-188	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86773	BA9348	950616	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Loose board to ceiling void	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86774	BA9348	950616	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Firebreak above double doors leadins to C-586	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86775	BA9348	950616	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Firebreak above double doors leadins to recestion	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86776	BA9348	950616	20/03/2019	WHS
#REF!	RAA	South Tyrone Hospital	09	Ceiling boards	Ceiling panels	Cement Products	Chrysotile	Cement Sheets	Low	Manage & Affix ID Labels	Re-inspection	HSG227	Unchecked	Very Low Risk	4	15/12/2023	Identified	Low Risk	86777	BA9344	930222	15/12/2022	WHS
#REF!	RAA	South Tyrone Hospital	09	Brake Pads	Lft motor brake shoes	Textiles & Paper	Presumed Asbestos	Unsealed	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Medium Risk	9	15/12/2023	Presumed	Medium Risk	86778		930222	15/12/2022	WHS
#REF!	RAA	South Tyrone Hospital	17	floor tile	Vinyl floor tiles under carpet	Composite Material	Chrysotile	Composite Material	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Very Low Risk	3	13/12/2023	Identified	Very Low Risk	86779	BA9345	930222	13/12/2022	WHS
#REF!	RAA	South Tyrone Hospital	17	Brake Pads	Lft 1	Textiles & Paper	Presumed Asbestos	unsealed	Low	Apply caution when maintaining and affix ID labels	Re-inspection	HSG227	Unchecked	Medium Risk	9	14/12/2023	Strongly Presumed	Medium Risk	86780		930222	14/12/2022	WHS
#REF!	RAA	South Tyrone Hospital	17	Brake Pads	Lft 2	Textiles & Paper	Presumed Asbestos	unsealed	Low	Apply caution when maintaining and affix ID labels	Re-inspection	HSG227	Unchecked	Medium Risk	9	14/12/2023	Strongly Presumed	Medium Risk	86781		930222	14/12/2022	WHS
#REF!	RAC	Tower Hill Site	01	NO ASBESTOS	Grey vinyl skirting	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86782	BA9359		17/12/2018	
#REF!	RAC	Tower Hill Site	01	NO ASBESTOS	Board to boxing in ceiling void	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86783	BA9359		17/12/2018	
#REF!	RAC	Tower Hill Site	01	Rope Seal	Door seal to stratford safe	Textiles & Paper	Chrysotile	unsealed	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Medium Risk	7	27/03/2021	Identified	Medium Risk	86784	BA9359	981191	28/11/2019	WHS
#REF!	RAC	Tower Hill Site	01	Rope Seal	Seal to inside of stratford safe	Textiles & Paper	Chrysotile	unsealed	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Medium Risk	7	27/03/2021	Identified	Medium Risk	86785	BA9359	981191	28/11/2019	WHS
#REF!	RAC	Tower Hill Site	01	NO ASBESTOS	Nosing to stairs	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86786	BA9359		17/12/2018	
#REF!	RAC	Tower Hill Site	01	NO ASBESTOS	Fire stop in service duct	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86787	BA9359		17/12/2018	
#REF!	RAC	Tower Hill Site	01	NO ASBESTOS	4 drawer Chubb fireproof cabinet	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86788	BA9359		17/12/2018	
#REF!	RAC	Tower Hill Site	01	NO ASBESTOS	Discarded roof tile	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86789	BA9359		17/12/2018	
#REF!	RAC	Tower Hill Site	01	NO ASBESTOS	Sarking felt	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86790	BA9359		17/12/2018	
#REF!	RAC	Tower Hill Site	01	NO ASBESTOS	Debris to floor at front door	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86791	BA9359		17/12/2018	
#REF!	RAC	Tower Hill Site	01	NO ASBESTOS	Dust to air conditioning equipment at rear	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86792	BA9359		17/12/2018	
#REF!	RAC	Tower Hill Site	01	NO ASBESTOS	Insulation to ceiling	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86793	BA9359		17/12/2018	
#REF!	RAC	Tower Hill Site	01	Rope Seal	Door seal and internal seal to stratford safe to stone	Textiles & Paper	Presumed Asbestos	unsealed	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Medium Risk	9	27/03/2021	Strongly Presumed	Medium Risk	86794		981191	28/11/2019	WHS
#REF!	RAC	Tower Hill Site	03	NO ASBESTOS	Sink pad	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86795	BA9361		17/12/2018	
#REF!	RAC	Tower Hill Site	03	NO ASBESTOS	Bitumen adhering tiles to timber plinth above suspended ceiling	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86796	BA9361		17/12/2018	
#REF!	RAC	Tower Hill Site	03	NO ASBESTOS	Vinyl skirting	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86797	BA9361		17/12/2018	
#REF!	RAC	Tower Hill Site	03	NO ASBESTOS	Vinyl skirting	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86798	BA9361		17/12/2018	
#REF!	RAC	Tower Hill Site	03	NO ASBESTOS	Vinyl floor tile	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86799	BA9361		17/12/2018	
#REF!	RAC	Tower Hill Site	03	NO ASBESTOS	Board above door	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86800	BA9361		17/12/2018	
#REF!	RAC	Tower Hill Site	03	floor tile	Vinyl floor tile	Composite Material	Chrysotile	Composite Material	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Very Low Risk	3	27/03/2021	Identified	Very Low Risk	86801	BA9361	981191	28/11/2019	WHS
#REF!	RAC	Tower Hill Site	03	NO ASBESTOS	Pad to drainer	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86802	BA9361		17/12/2018	
#REF!	RAC	Tower Hill Site	03	NO ASBESTOS	Sink pad and pad to drainer	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86803	BA9361		17/12/2018	
#REF!	RAC	Tower Hill Site	03	NO ASBESTOS	Vinyl floor tile	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86804	BA9361		17/12/2018	
#REF!	RAC	Tower Hill Site	03	NO ASBESTOS	Sink pad and pad to drainer	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86805	BA9361		17/12/2018	
#REF!	RAC	Tower Hill Site	03	NO ASBESTOS	Sink pad and pad to drainer	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86806	BA9361		17/12/2018	
#REF!	RAC	Tower Hill Site	03	NO ASBESTOS	Sink pad and pad to drainer	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86807	BA9361		17/12/2018	
#REF!	RAC	Tower Hill Site	03	NO ASBESTOS	Vinyl floor tile	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86808	BA9361		17/12/2018	
#REF!	RAC	Tower Hill Site	03	floor tile	Vinyl floor tile	Composite Material	Chrysotile	Composite Material	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Very Low Risk	3	27/03/2021	Identified	Very Low Risk	86809	BA9361	981191	28/11/2019	WHS
#REF!	RAC	Tower Hill Site	03	NO ASBESTOS	Sink pad	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86810	BA9361		17/12/2018	
#REF!	RAC	Tower Hill Site	03	floor tile	Vinyl floor tile	Composite Material	Chrysotile	Composite Material	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Very Low Risk	3	27/03/2021	Identified	Very Low Risk	86811	BA9361	981191	28/11/2019	WHS
#REF!	RAC	Tower Hill Site	03	NO ASBESTOS	Sink pad and pad to drainer	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86812	BA9361		17/12/2018	
#REF!	RAC	Tower Hill Site	03	Residue to Walls	Strip to left wall, 1m from rear	Thermal Insulation	Amosite	Unsealed	Low	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	High Risk	11	27/03/2021	Identified	High Risk	86813	BA9361	981191	28/11/2019	WHS
#REF!	RAC	Tower Hill Site	03	Residue to Walls	Strip to left wall, 0.5m from rear corner (LHS of electrical box)	Thermal Insulation	Amosite	unsealed	Low	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	High Risk	11	27/03/2021	Identified	High Risk	86814	BA9361	981191	28/11/2019	WHS
#REF!	RAC	Tower Hill Site	03	Residue to Walls	Strip to rear wall, 0.5m from left	Thermal Insulation	Amosite	unsealed	Low	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	High Risk	11	27/03/2021	Identified	High Risk	86815	BA9361	981191	28/11/2019	WHS
#REF!	RAC	Tower Hill Site	03	Damp Proof Course	DPC to ledge of rear wall	Composite Material	Chrysotile	Composite Material	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Very Low Risk	3	27/03/2021	Identified	Very Low Risk	86816	BA9361	981191	28/11/2019	WHS
#REF!	RAC	Tower Hill Site	03	Loose Fill Insulation	Loose to rear wall, under	Thermal Insulation	Amosite	Loose Asbestos Debris	Low	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	High Risk	11	27/03/2021	Identified	High Risk	86817	BA9361	981191	28/11/2019	WHS
#REF!	RAC	Tower Hill Site	03	floor tile	Vinyl floor tile	Composite Material	Presumed Asbestos	Composite Material	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Low Risk	5	27/03/2021	Stronnly Presumed	Low Risk	86818		981191	28/11/2019	WHS
#REF!	RAC	Tower Hill Site	02	NO ASBESTOS	Plaster to ceiling	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86819	BA9360		17/12/2018	
#REF!	RAC	Tower Hill Site	02	NO ASBESTOS	Sarking felt	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86820	BA9360		17/12/2018	
#REF!	RAC	Tower Hill Site	02	NO ASBESTOS	Sink pad	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86821	BA9360		17/12/2018	
#REF!	RAC	Tower Hill Site	02	NO ASBESTOS	Paper to wall	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86822	BA9360		17/12/2018	
#REF!	RAC	Tower Hill Site	02	NO ASBESTOS	Sarking felt	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86823	BA9360		17/12/2018	
#REF!	RAC	Tower Hill Site	02	NO ASBESTOS	Sash window cord	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86824	BA9360		17/12/2018	
#REF!	RAC	Tower Hill Site	02	NO ASBESTOS	Sash window cord	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86825	BA9360		17/12/2018	
#REF!	RAC	Tower Hill Site	02	NO ASBESTOS	Dust/Debris at 4 pipes on ground	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86826	BA9360		17/12/2018	
#REF!	RAC	Tower Hill Site	02	Roof Tiles	Roof tile	Cement Products	Chrysotile	Cement Sheets	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Very Low Risk	4	27/03/2021	Identified	Very Low Risk	86827	BA9360	981191	20/11/2019	WHS
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Vinyl beneath carpet tiles	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86828	BA9365		03/01/2019	
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Vinyl floor tiles beneath carpet tiles	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86829	BA9365		03/01/2019	
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Vinyl floor tiles beneath carpet tiles	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86830	BA9365		03/01/2019	

#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Pipe insulation above suspended ceilino	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86831	BA9365		03/01/2019		
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Ceiling tile	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86832	BA9365		03/01/2019		
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Insulation above ceiling tile	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86833	BA9365		03/01/2019		
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Floor covering beneath vinyl	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86834	BA9365		03/01/2019		
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Panel to wall	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86835	BA9365		03/01/2019		
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Vinyl beneath carpet	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86836	BA9609		03/01/2019		
#REF!	RAA	South Tyrone Hospital	17	Bitumen Adhesive	Bitumen beneath vinyl	Composite Material	Chrysotile	Composite Material	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Very Low Risk	3	13/12/2023	Identified	Very Low Risk	86837	BA9365	9302/2	13/12/2022	WHS		
#REF!	RAA	South Tyrone Hospital	15	NO ASBESTOS	Paper to ceiling	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86838	BA9365		03/01/2019		
#REF!	RAA	South Tyrone Hospital	15	NO ASBESTOS	Layer between carpet and plywood	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86839	BA9365		03/01/2019		
#REF!	RAA	South Tyrone Hospital	15	NO ASBESTOS	Layer beneath plywood under carset	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86840	BA9365		03/01/2019		
#REF!	RAA	South Tyrone Hospital	15	NO ASBESTOS	Paper to ceiling	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86841	BA9365		03/01/2019		
#REF!	RAA	South Tyrone Hospital	15	NO ASBESTOS	Covering to plywood under carpet	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86842	BA9365		03/01/2019		
#REF!	QAA	Craigavon Hospital	15	NO ASBESTOS	Infill panel to fire door	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86844	BA9238		18/10/2018		
#REF!	QAA	Craigavon Hospital	15	Floor Tile and Bitumen Adhesive	Brown speckled VFT & bitumen	Composite Material	Chrysotile	Composite Material	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Very Low Risk	3	13/12/2023	Identified	Very Low Risk	86845	BA9006	9302/2	05/09/2022	WH Stephens		
#REF!	QAA	Craigavon Hospital	15	Floor Tile and Bitumen Adhesive	Dark brown VFT & bitumen	Composite Material	Chrysotile	Composite Material	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Very Low Risk	3	13/12/2023	Identified	Very Low Risk	86846	BA9006	9302/2	05/09/2022	WH Stephens		
#REF!	QAA	Craigavon Hospital	15	Floor Tile and Bitumen Adhesive	Light brown VFT & bitumen	Composite Material	Chrysotile	Composite Material	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Very Low Risk	3	13/12/2023	Identified	Very Low Risk	86847	BA9006	9302/2	05/09/2022	WH Stephens		
#REF!	SHA	Drumalane Estate	09	Door Panel	Panel to rear of door	Insulating Board	Amosite	Unsealed Asbestos Insulation	Low	Remove if likely to be disturbed	Re-inspection	HSG227	Unchecked	Medium Risk	7	14/03/2023	Identified	Medium Risk	86848	BA9245	9302/2	06/04/2022	WHS		
#REF!	SHA	Drumalane Estate	09	Door Panel	Panel to rear of door	Insulating Board	Amosite	Unsealed Asbestos Insulation	Low	Remove if likely to be disturbed	Re-inspection	HSG227	Unchecked	Medium Risk	7	14/03/2023	Identified	Medium Risk	86849	BA9245	9302/2	06/04/2022	WHS		
#REF!	SHA	Drumalane Estate	09	Ceiling Panel	Panel to ceiling	Insulating Board	Amosite	Unsealed Asbestos Insulation	low	Remove if likely to be disturbed	Re-inspection	HSG227	Unchecked	Medium Risk	7	14/03/2023	Identified	Medium Risk	86850	BA9245	9302/2	06/04/2022	WHS		
#REF!	SHA	Drumalane Estate	09	NO ASBESTOS	Vinyl floor tile	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86851	BA9245		23/10/2018		
#REF!	SHA	Drumalane Estate	09	NO ASBESTOS	Vinyl floor tile	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86852	BA9245		23/10/2018		
#REF!	SHA	Drumalane Estate	09	NO ASBESTOS	Vinyl floor tile	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86853	BA9245		23/10/2018		
#REF!	SHA	Drumalane Estate	09	Stair Nosino	Step nosino	Composite Material	Chrysotile	Composite Material	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Very Low Risk	3	14/09/2023	Identified	Very Low Risk	86854	BA9245	9302/2	06/04/2022	WHS		
#REF!	SHA	Drumalane Estate	09	Stair Nosino	Step nosino	Composite Material	Chrysotile	Composite Material	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Very Low Risk	3	14/09/2023	Identified	Very Low Risk	86855	BA9245	9302/2	06/04/2022	WHS		
#REF!	SHA	Drumalane Estate	09	Wall Panels	Panel in fireplace	Cement Products	Amosite	Unsealed Cement	Low	Remove if likely to be disturbed	Re-inspection	HSG227	Unchecked	Low Risk	5	14/09/2023	Identified	Low Risk	86856	BA9245	9302/2	06/04/2022	WHS		
#REF!	SHA	Drumalane Estate	09	Door Panel	Panel to door	Insulating Board	Amosite	Unsealed Asbestos Insulation	Low	Remove if likely to be disturbed	Re-inspection	HSG227	Unchecked	Medium Risk	7	14/03/2023	Identified	Medium Risk	86857	BA9245	9302/2	06/04/2022	WHS		
#REF!	SHA	Drumalane Estate	09	Floor Tiles	Vinyl floor tiles	Composite Material	Chrysotile	Composite Material	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Very Low Risk	3	14/09/2023	Identified	Very Low Risk	86858	BA9245	9302/2	06/04/2022	WHS		
#REF!	SHA	Drumalane Estate	09	Door Panel	Panel to door	Insulating Board	Amosite	Unsealed Asbestos Insulation Board	Low	Label and Remove if likely to be disturbed	Re-inspection	HSG227	Unchecked	Medium Risk	7	14/03/2023	Identified	Medium Risk	86859	BA9245	9309/2 2	06/04/2022	WHS		
#REF!	SHA	Drumalane Estate	09	NO ASBESTOS	Ceiling in-fill panels	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86860	BA9245		23/10/2018		
#REF!	SHA	Drumalane Estate	09	NO ASBESTOS	Textured coating to walls	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86861	BA9245		23/10/2018		
#REF!	SHA	Drumalane Estate	09	NO ASBESTOS	Textured coating to walls	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86862	BA9245		23/10/2018		
#REF!	SHA	Drumalane Estate	09	NO ASBESTOS	Plastic shires cistern	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86863	BA9245		23/10/2018		
#REF!	SHA	Drumalane Estate	09	NO ASBESTOS	Plastic shires cistern	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86864	BA9245		23/10/2018		
#REF!	SHA	Drumalane Estate	09	Door Panel	Panel to door	Insulating Board	Amosite	Unsealed Asbestos Insulation	Low	Remove if likely to be disturbed	Re-inspection	HSG227	Unchecked	Medium Risk	7	14/03/2023	Identified	Medium Risk	86865	BA9245	9302/2	06/04/2022	WHS		
#REF!	SHA	Drumalane Estate	09	Door Panel	Panel to door	Insulating Board	Amosite	Unsealed Asbestos Insulation	Low	Remove if likely to be disturbed	Re-inspection	HSG227	Unchecked	Medium Risk	7	14/09/2023	Identified	Medium Risk	86866	BA9245	9302/2	06/04/2022	WHS		
#REF!	SHA	Drumalane Estate	09	NO ASBESTOS	Step nosing	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86867	BA9245		23/10/2018		
#REF!	SHA	Drumalane Estate	09	Door Panel	Panel to door	Insulating Board	Amosite	Unsealed Asbestos Insulation	Low	Remove if likely to be disturbed	Re-inspection	HSG227	Unchecked	Medium Risk	7	14/03/2023	Identified	Medium Risk	86868	BA9245	9302/2	06/04/2022	WHS		
#REF!	SHA	Drumalane Estate	09	Door Panel	Panel to door	Insulating Board	Amosite	Unsealed Asbestos Insulation	Low	Remove if likely to be disturbed	Re-inspection	HSG227	Unchecked	Medium Risk	7	14/03/2023	Identified	Medium Risk	86869	BA9245	9302/2	06/04/2022	WHS		
#REF!	SHA	Drumalane Estate	09	Door Panel	Panel to door	Cement Products	Chrysotile	Cement Sheets	Low	Remove if likely to be disturbed	Re-inspection	HSG227	Unchecked	Very Low Risk	4	14/09/2023	Identified	Very Low Risk	86870	BA9245	9302/2	06/04/2022	WHS		
#REF!	SHA	Drumalane Estate	09	Door Panel	Fire door	Insulating Board	Presumed Asbestos	Unsealed Asbestos Insulation	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Medium Risk	7	14/03/2023	Presumed	Medium Risk	86871		9302/2	06/04/2022	WHS		
#REF!	SHA	Drumalane Estate	09	Fuse Flash Guards	MEM switch - flash supressor	Textiles & Paper	Presumed Asbestos	Unsealed	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Medium Risk	9	14/03/2023	Presumed	Medium Risk	86872		9302/2	06/04/2022	WHS		
#REF!	SHA	Drumalane Estate	09	Fuse Flash Guards	Wylex fuse boxes - flash guards	Textiles & Paper	Presumed Asbestos	unsealed	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Medium Risk	9	14/09/2023	Presumed	Medium Risk	86873		9302/2	06/04/2022	WHS		
#REF!	QAA	Craigavon Hospital	16	NO ASBESTOS	Floor covering	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86877	BA9113		03/09/2018		
#REF!	QAA	Craigavon Hospital	16	NO ASBESTOS	Floor covering	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86878	BA9113		03/09/2018		
#REF!	QAA	Craigavon Hospital	16	NO ASBESTOS	Grey floor tile	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86879	BA9113		03/09/2018		
#REF!	QAA	Craigavon Hospital	16	NO ASBESTOS	White floor tile	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86880	BA9113		03/09/2018		
#REF!	QAA	Craigavon Hospital	16	NO ASBESTOS	White floor tile	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86881	BA9113		03/09/2018		
#REF!	QAA	Craigavon Hospital	16	NO ASBESTOS	Grey floor tile	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86882	BA9113		03/09/2018		
#REF!	QAA	Craigavon Hospital	16	NO ASBESTOS	Grey floor tile	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86883	BA9113		03/09/2018		
#REF!	QAA	Craigavon Hospital	16	NO ASBESTOS	White floor tile	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86884	BA9113		03/09/2018		
#REF!	QAA	Craigavon Hospital	16	NO ASBESTOS	Concealed floor tile	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86885	BA9113		03/09/2018		
#REF!	SHA	Drumalane Estate	06	NO ASBESTOS	Sink Pad	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86886	BA9244		23/10/2018		
#REF!	SHA	Drumalane Estate	06	NO ASBESTOS	Board to wall	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86887	BA9244		23/10/2018		
#REF!	SHA	Drumalane Estate	06	NO ASBESTOS	Board to ceiling	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86888	BA9244		23/10/2018		
#REF!	SHA	Drumalane Estate	06	NO ASBESTOS	Board to ceiling	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86889	BA9244		23/10/2018		
#REF!	SHA	Drumalane Estate	06	Ceilino Panel	Ceilino panel	Insulating Board	Amosite/Chrysotile	unsealed	Areas of damage or	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	Medium Risk	9	14/03/2023	Identified	Medium Risk	86890	BA9244	9302/2	30/08/2022	WHS		
#REF!	SHA	Drumalane Estate	06	NO ASBESTOS	Sealing strips to ceiling panel	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86891	BA9244		23/10/2018		
#REF!	SHA	Drumalane Estate	06	Ceilino Panel	Ceilino panel	Insulating Board	Amosite	Unsealed Asbestos Insulation	Low	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	Medium Risk	7	14/03/2023	Identified	Medium Risk	86892	BA9244	9302/2	30/08/2022	WHS		
#REF!	SHA	Drumalane Estate	06	NO ASBESTOS	Ceiling infill/repair panel	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86893	BA9244		23/10/2018		
#REF!	SHA	Drumalane Estate	06	Fuse Flash Guards	Simplex electrical switch gear	Textiles & Paper	Presumed Asbestos	unsealed	Low	Label & Manage	Re-inspection	HSG227	Unchecked	Medium Risk	9	14/03/2023	Presumed	Medium Risk	86894		9302/2	30/08/2022	WHS		
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Firebreak to lobby of delivery suite	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86895	BA9386	9506/18	20/03/2019	WHS	
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Firebreak to delivery suite	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86896	BA9386	9506/18	20/03/2019	WHS	
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Firebreak over double doors	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86897	BA9386	9506/1A	20/03/2019	WHS	
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Firebreak over double doors adjacent to nurses station	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86898	BA9386	9506/18	20/03/2019	WHS	
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Firebreak over double doors adjacent to Willow suite	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86899	BA9386	9506/18	20/03/2019	WHS	
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Firebreak over double doors	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86900	BA9386	9506/18	20/03/2019	WHS	
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Firebreak over double doors into ovnae 170	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86901	BA9386	9506/18	20/03/2019	WHS	
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Fire curtain over double doors into ovnae receotion (170 into 198)	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86902	BA9386	9506/18	20/03/2019	WHS	
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Firebreak over double doors into 198	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86903	BA9386	9506/1A	20/03/2019	WHS	
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Firebreak over double doors into 170	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86904	BA9386	9506/18	20/03/2019	WHS	
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Firebreak over double doors into 210	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86905	BA9386	9506/18	20/03/2019	WHS	
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Firebreak over double doors into 216	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86906	BA9386	9506/1A	20/03/2019	WHS	
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Firebreak over double doors into 236	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86907	BA9386	9506/18	20/03/2019	WHS	
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Firebreak over double doors into 216	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86908	BA9386	9506/18	20/03/2019	WHS	
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Firebreak above double doors into 223	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86909	BA9386	9506/1A	20/03/2019	WHS	
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Firebreak above double doors into 037	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86910	BA9386	9506/18	20/03/2019	WHS	
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Firebreak above double doors into 047	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86911	BA9386	9506/18	20/03/2019	WHS	
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Firebreak above double doors into 058	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86912	BA9386	9506/1A	20/03/2019	WHS	
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Firebreak above double doors into 070	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86913	BA9386	9506/18	20/03/2019	WHS	
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Firebreak above double doors into 076	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86914	BA9386	9506/18	20/03/2019	WHS	
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Firebreak above double doors into 033	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86915	BA9386	9506/18	20/03/2019	WHS	
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Firebreak above double doors into room 067	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86916	BA9386	9506/18	20/03/2019	WHS	
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Firebreak above double doors into room 077	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86917	BA9386	9506/18	20/03/2019	WHS	
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Firebreak above double doors into room 088	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86918	BA9386	9506/18	20/03/2019	WHS	

#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Firebreak over double doors into room 110	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86919	BA9386	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Firebreak above double doors into room 047	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86920	BA9386	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Firebreak above double doors into room 036	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		identified	No Asbestos Detected	86921	BA9386	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Firebreak above double doors into room 015	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86922	BA9386	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Firebreak above double doors into room 002	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86923	BA9386	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Firebreak above double doors into corridor 009	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86924	BA9386	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Firebreak above double doors into corridor 078	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86925	BA9386	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Firebreak above double doors into corridor 090	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86926	BA9386	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Firebreak above double doors into corridor 049	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86927	BA9386	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Firebreak above double doors into corridor 038	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86928	BA9386	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Firebreak above double doors into corridor 018	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86929	BA9386	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Firebreak above double doors into corridor 014	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86930	BA9386	9506/18	20/03/2019	WHS
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Firebreak above double doors into corridor 002	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86931	BA9386	9506/18	20/03/2019	WHS
#REF!	QCC	Dromore Health Clinic	01	NO ASBESTOS	Board to underside of water tank	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86933	BA8739		16/04/2018	
#REF!	QCC	Dromore Health Clinic	01	NO ASBESTOS	Board above door	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86934	BA8739		16/04/2018	
#REF!	SHC	Slieve Roe	01	Undercloak	Verge undercloak	Insulating Board	Amosite/Chrysotile	Unsealed asbestos insulation	Low		Manage and monitor	Re-inspection	HSG227	Unchecked	Medium Risk	7	12/03/2023	Identified	Medium Risk	86935	BA8406	9302/2	30/08/2022	WHS
#REF!	SHC	Slieve Roe	01	NO ASBESTOS	Textured ceiling coating	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86936	BA8406		23/01/2019	
#REF!	SHC	Slieve Roe	01	NO ASBESTOS	Sarking felt	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		identified	No Asbestos Detected	86937	BA8406		23/01/2019	
#REF!	SHC	Slieve Roe	01	NO ASBESTOS	Panel to rear of roof void access hatch	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86938	BA8406		23/01/2019	
#REF!	SHC	Slieve Roe	01	NO ASBESTOS	Grey vinyl skirting	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86939	BA8406		23/01/2019	
#REF!	SHC	Slieve Roe	01	NO ASBESTOS	Textured ceiling coating	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86940	BA8406		23/01/2019	
#REF!	SHC	Slieve Roe	01	NO ASBESTOS	Vinyl beneath carpet tiles	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86941	BA8406		23/01/2019	
#REF!	SHC	Slieve Roe	01	NO ASBESTOS	Board to inside cupboard above doors	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86942	BA8406		23/01/2019	
#REF!	SHC	Slieve Roe	01	NO ASBESTOS	Board above cupboard doors	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86943	BA8406		23/01/2019	
#REF!	SHC	Slieve Roe	01	NO ASBESTOS	Sink pad	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86944	BA8406		23/01/2019	
#REF!	SHC	Slieve Roe	01	NO ASBESTOS	Textured coating to ceiling	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86945	BA8406		23/01/2019	
#REF!	SHC	Slieve Roe	01	NO ASBESTOS	Board to bottom of door	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86946	BA8406		23/01/2019	
#REF!	SHC	Slieve Roe	01	NO ASBESTOS	Board to bottom of door	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86947	BA8406		23/01/2019	
#REF!	SHC	Slieve Roe	01	NO ASBESTOS	Board to bottom of door	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86948	BA8406		23/01/2019	
#REF!	SHC	Slieve Roe	01	Fuse Flash Guards	Flashguard residue	Textiles & Paper	Chrysotile	Unsealed	Low		Remove if likely to be disturbed	Re-inspection	HSG227	Unchecked	Medium Risk	9	12/03/2023	Identified	Medium Risk	86949	BA8406	9302/2	30/08/2022	WHS
#REF!	SHC	Slieve Roe	01	NO ASBESTOS	Board to side and above door (inside cupboard)	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86950	BA8406		23/01/2019	
#REF!	SHC	Slieve Roe	01	NO ASBESTOS	Bitumen on top of concrete beneath vinyl	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86951	BA8406		23/01/2019	
#REF!	SHC	Slieve Roe	01	NO ASBESTOS	Panel above cupboard	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86952	BA8406		23/01/2019	
#REF!	SHC	Slieve Roe	01	NO ASBESTOS	Panel to base of electric cupboard	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86953	BA8406		23/01/2019	
#REF!	SHC	Slieve Roe	01	NO ASBESTOS	Sink pad	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86954	BA8406		23/01/2019	
#REF!	SHC	Slieve Roe	01	NO ASBESTOS	Sink pad	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		identified	No Asbestos Detected	86955	BA8406		23/01/2019	
#REF!	SHC	Slieve Roe	01	NO ASBESTOS	Bitumen to floor of cupboard	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86956	BA8406		23/01/2019	
#REF!	SHC	Slieve Roe	01	NO ASBESTOS	Panel above cupboard doors	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86957	BA8406		23/01/2019	
#REF!	SHC	Slieve Roe	01	NO ASBESTOS	Textured ceiling coating	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86958	BA8406		23/01/2019	
#REF!	SHC	Slieve Roe	01	NO ASBESTOS	Board above door	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86959	BA8406		23/01/2019	
#REF!	SHC	Slieve Roe	01	NO ASBESTOS	Board above door	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86960	BA8406		23/01/2019	
#REF!	SHC	Slieve Roe	01	NO ASBESTOS	Sarking felt	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86961	BA8406		23/01/2019	
#REF!	SHC	Slieve Roe	01	NO ASBESTOS	Boards to rear of cooker hood	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86962	BA8406		23/01/2019	
#REF!	SHC	Slieve Roe	01	NO ASBESTOS	Board to upper side of roof void access hatch	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86963	BA8406		23/01/2019	
#REF!	SHC	Slieve Roe	01	NO ASBESTOS	Board above door (inside room)	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86964	BA8406		23/01/2019	
#REF!	SHC	Slieve Roe	01	NO ASBESTOS	Vinyl floor covering	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86965	BA8406		23/01/2019	
#REF!	SHC	Slieve Roe	01	NO ASBESTOS	Sink pad	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86966	BA8406		23/01/2019	
#REF!	SHC	Slieve Roe	01	NO ASBESTOS	Sarking felt to roof void	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86967	BA8406		23/01/2019	
#REF!	SHC	Slieve Roe	01	NO ASBESTOS	Cloth wrapped MMMF insulation to pipe	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86968	BA8406		23/01/2019	
#REF!	SHC	Slieve Roe	01	NO ASBESTOS	Board to upper side of roof hatch	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86969	BA8406		23/01/2019	
#REF!	SHC	Slieve Roe	01	NO ASBESTOS	Vinyl floor covering	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86970	BA8406		23/01/2019	
#REF!	SHC	Slieve Roe	01	NO ASBESTOS	Residue to wall in corner of plant room beneath door to tank	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86971	BA8406		23/01/2019	
#REF!	SHC	Slieve Roe	01	NO ASBESTOS	Residue to wall 3, 1m from previous corner	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86972	BA8406		23/01/2019	
#REF!	SHC	Slieve Roe	01	NO ASBESTOS	Residue to wall between calorifiers	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86973	BA8406		23/01/2019	
#REF!	SHC	Slieve Roe	01	NO ASBESTOS	Residue to wall behind right hand calorifiers	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86974	BA8406		23/01/2019	
#REF!	SHC	Slieve Roe	01	NO ASBESTOS	Residue to wall to right hand side of right calorifiers	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86975	BA8406		23/01/2019	
#REF!	SHC	Slieve Roe	01	NO ASBESTOS	Residue to wall 1, 1m from corner	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86976	BA8406		23/01/2019	
#REF!	SHC	Slieve Roe	01	NO ASBESTOS	Residue to wall 3, 2m from left hand corner	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86977	BA8406		23/01/2019	
#REF!	SHC	Slieve Roe	01	NO ASBESTOS	Air intake baffle	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86978	BA8406		23/01/2019	
#REF!	SHC	Slieve Roe	01	Fuse Flash Guards	Residue to flashbacks	Textiles & Paper	Presumed Asbestos	unsealed	Unsealed asbestos		Remove if likely to be disturbed	Re-inspection	HSG227	Unchecked	High Risk	11	12/12/2022	Strongly Presumed	High Risk	86979	BA8406	9302/2	30/08/2022	WHS
#REF!	SHC	Slieve Roe	01	Lino Flooring	Grey vinyl skirting	Composite Material	Presumed Asbestos	Composite Material	Low		Manage and monitor	Re-inspection	HSG227	Unchecked	Low Risk	5	12/09/2023	Identified	Low Risk	86980	BA8406	9302/2	30/08/2022	WHS
#REF!	SHC	Slieve Roe	01	Lino Flooring	Grey vinyl skirting	Composite Material	Presumed Asbestos	Composite Material	Low		Manage and monitor	Re-inspection	HSG227	Unchecked	Low Risk	5	12/09/2023	Identified	Low Risk	86981	BA8406	9302/2	30/08/2022	WHS
#REF!	SHC	Slieve Roe	01	Fuse Flash Guards	Flashguard residue	Textiles & Paper	Presumed Asbestos	unsealed	Unsealed asbestos		Remove if likely to be disturbed	Re-inspection	HSG227	Unchecked	High Risk	11	12/12/2022	Identified	High Risk	86982	BA8406	9302/2	30/08/2022	WHS
#REF!	SHC	Slieve Roe	01	Fuse Flash Guards	Residue to flashbacks	Textiles & Paper	Presumed Asbestos	unsealed	Unsealed asbestos		Remove if likely to be disturbed	Re-inspection	HSG227	Unchecked	High Risk	11	12/12/2022	Identified	High Risk	86983	BA8406	9302/2	30/08/2022	WHS
#REF!	SHC	Slieve Roe	01	Lino Flooring	Vinyl floor covering	Composite Material	Presumed Asbestos	Composite Material	Low		Manage and monitor	Re-inspection	HSG227	Unchecked	Low Risk	5	12/09/2023	Identified	Low Risk	86984	BA8406	9302/2	22/01/2020	WHS
#REF!	SHC	Slieve Roe	01	Fuse Flash Guards	flashboard residue	Textiles & Paper	Presumed Asbestos	unsealed	Unsealed asbestos		Remove if likely to be disturbed	Re-inspection	HSG227	Unchecked	High Risk	11	12/12/2022	Identified	High Risk	86985	BA8406	9302/2	30/08/2022	WHS
#REF!	SHC	Slieve Roe	01	Loose Fill Insulation	Exhaust silencer	Thermal Insulation	Presumed Asbestos	Unsealed	Unsealed asbestos		Manage and monitor	Re-inspection	HSG227	Unchecked	High Risk	12	12/12/2022	Identified	High Risk	86986	BA8406	9302/2	30/08/2022	WHS
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Board above roller shutter fire door beside room B-798	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	86995	BA8405		23/01/2019	
#REF!	RAB	Longstone/Mullinure	02	Residue to Walls	Residue to wall 1	Thermal Insulation	Amosite	Unsealed	Unsealed asbestos		Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	High Risk	11	27/03/2021	Identified	High Risk	86996	BA8420	9501/1	20/01/2020	WHS
#REF!	RAB	Longstone/Mullinure	02	Residue to Walls	Residue to wall 1	Thermal Insulation	Amosite	unsealed	Unsealed asbestos		Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	High Risk	11	27/03/2021	Identified	High Risk	86997	BA8420	9501/1	20/01/2020	WHS
#REF!	RAB	Longstone/Mullinure	02	Residue to Walls	Residue to wall 2	Thermal Insulation	Amosite	unsealed	Unsealed asbestos		Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	High Risk	11	27/03/2021	Identified	High Risk	86998	BA8420	9501/1	20/01/2020	WHS
#REF!	RAB	Longstone/Mullinure	02	Residue to Walls	Residue to wall 2	Thermal Insulation	Amosite	unsealed	Unsealed asbestos		Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	High Risk	11	27/03/2021	Identified	High Risk	86999	BA8420	9501/1	20/01/2020	WHS
#REF!	RAB	Longstone/Mullinure	02	Residue to Walls	Residue to wall 3	Thermal Insulation	Amosite	unsealed	Unsealed asbestos		Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	High Risk	11	27/03/2021	Identified	High Risk	87000	BA8420	9501/1	20/01/2020	WHS
#REF!	RAB	Longstone/Mullinure	02	Residue to Walls	Residue to wall 3	Thermal Insulation	Amosite	unsealed	Unsealed asbestos		Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	High Risk	11	27/03/2021	Identified	High Risk	87001	BA8420	9501/1	20/01/2020	WHS
#REF!	RAB	Longstone/Mullinure	02	Residue to Walls	Residue to wall 4	Thermal Insulation	Amosite	unsealed	Unsealed asbestos		Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	High Risk	11	27/03/2021	Identified	High Risk	87002	BA8420	9501/1	20/01/2020	WHS
#REF!	RAB	Longstone/Mullinure	02	Residue to Walls	Residue to wall 4	Thermal Insulation	Amosite	unsealed	Unsealed asbestos		Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	High Risk	11	27/03/2021	Identified	High Risk	87003	BA8420	9501/1	20/01/2020	WHS
#REF!	RAB	Longstone/Mullinure	02	Pipe Residue	Residue to pipe bracket	Thermal Insulation	Amosite	unsealed	Unsealed asbestos		Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	High Risk	11	27/03/2021	Identified	High Risk	87004	BA8420	9501/1	20/01/2020	WHS
#REF!	RAB	Longstone/Mullinure	02	Pipe Residue	Residue to pipework	Thermal Insulation	Amosite	unsealed	Unsealed asbestos		Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	High Risk	11	27/03/2021	Identified	High Risk	87005	BA8420	9501/1	20/01/2020	WHS
#REF!	RAB	Longstone/Mullinure	02	Debris	Debris to floor	Thermal Insulation	Amosite	unsealed	Unsealed asbestos		Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	High Risk	11	27/03/2021	Identified	High Risk	87006	BA8420	9501/1	20/01/2020	WHS
#REF!	RAB	Longstone/Mullinure	02	Debris	Debris to floor	Thermal Insulation	Amosite	unsealed	Unsealed asbestos		Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	High Risk	11	27/03/2021	Identified	High Risk	87007	BA8420	9501/1	20/01/2020	WHS
#REF!	RAB	Longstone/Mullinure	02	Debris	Debris to duct RHS of door	Thermal Insulation	Amosite	unsealed	Unsealed asbestos		Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	High Risk	11	27/03/2021	Identified	High Risk	87008	BA8420	9501/1	20/01/2020	WHS
#REF!	SBA	John Mitchel Place	01	NO ASBESTOS	Beige floor covering	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87051	BA8499		07/03/2019	
#REF!	SBA	John Mitchel Place	01	NO ASBESTOS	Grey floor covering	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87052	BA8499		07/03/2019	
#REF!	SBA	John Mitchel Place	01	NO ASBESTOS	Sink pad	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87053	BA8499		07/03/2019	

#REF!	SBA	John Mitchel Place	01	NO ASBESTOS	Firebreak above door from A-130	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87054	BA9499		07/03/2019		
#REF!	SBA	John Mitchel Place	01	NO ASBESTOS	Floor covering to lobby	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87055	BA9499		07/03/2019		
#REF!	SBA	John Mitchel Place	01	NO ASBESTOS	Floor covering	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87056	BA9499		07/03/2019		
#REF!	SBA	John Mitchel Place	01	NO ASBESTOS	Floor covering	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87057	BA9499		07/03/2019		
#REF!	SBA	John Mitchel Place	01	NO ASBESTOS	Floor covering	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87058	BA9499		07/03/2019		
#REF!	SBA	John Mitchel Place	01	NO ASBESTOS	Floor covering to cupboard store	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87059	BA9449		07/03/2019		
#REF!	SBA	John Mitchel Place	01	NO ASBESTOS	Floor covering to kitchen	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87060	BA9499		07/03/2019		
#REF!	QJA	Bamvale	05	NO ASBESTOS	Debris to floor wall 1 LHSof door	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87061	BA9455		18/02/2019		
#REF!	QJA	Bamvale	05	NO ASBESTOS	Ceiling board above electric panel to wall 1	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87062	BA9455		18/02/2019		
#REF!	QJA	Bamvale	05	NO ASBESTOS	Residue to wall 2 behind boiler 3	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87063	BA9455		18/02/2019		
#REF!	QJA	Bamvale	05	NO ASBESTOS	Debris to floor corner of wall 2 & 3	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87064	BA9455		18/02/2019		
#REF!	QJA	Bamvale	05	NO ASBESTOS	Rope seal to flue access hatch corner of wall 2 & 3	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87065	BA9455		18/02/2019		
#REF!	QJA	Bamvale	05	Loose Asbestos	Debris to floor of plinth pump area	Loose Asbestos	Chrysotile	Loose Asbestos Debris	Loose asbestos debris or residue	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	High Risk	10	09/12/2022	Identified	High Risk	87066	BA9455	24/08/2 -	06/04/2022	WHS	
#REF!	QJA	Bamvale	05	NO ASBESTOS	Debris to floor of plinth RHS	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87067	BA9455		18/02/2019		
#REF!	QJA	Bamvale	05	NO ASBESTOS	Panelling to mezzanine edge top of ladder	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87068	BA9455		18/02/2019		
#REF!	QJA	Bamvale	05	NO ASBESTOS	Panelling to beam at mezzanine level	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87069	BA9455		18/02/2019		
#REF!	QJA	Bamvale	05	NO ASBESTOS	Gasket to pump	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87070	BA9455		18/02/2019		
#REF!	QJA	Bamvale	05	NO ASBESTOS	Gasket to pump	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87071	BA9455		18/02/2019		
#REF!	QJA	Bamvale	05	NO ASBESTOS	Debris to flue at pump	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87072	BA9455		18/02/2019		
#REF!	QJA	Bamvale	05	NO ASBESTOS	Debris to flue pipe	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87073	BA9455		18/02/2019		
#REF!	QJA	Bamvale	05	NO ASBESTOS	Residue to flue back of boiler 2	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87074	BA9455		18/02/2019		
#REF!	QJA	Bamvale	05	NO ASBESTOS	Residue to flue back of boiler 4	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87075	BA9455		18/02/2019		
#REF!	QJA	Bamvale	05	NO ASBESTOS	Residue to pipe penetration at high level wall 4	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87076	BA9455		18/02/2019		
#REF!	QJA	Bamvale	05	NO ASBESTOS	Soffit above single door to boiler house	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87077	BA9455		18/02/2019		
#REF!	QJA	Bamvale	05		Gasket to oumos throughout	Textiles & Paper	Presumed Asbestos	Composite Material	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Low Risk	6	09/03/2023	Presumed	Medium Risk	87078		24/08/2 -	06/04/2022	WHS	
#REF!	QHB	Crozier House	01	NO ASBESTOS	Packer to door frame	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87079	BA9454		18/02/2019		
#REF!	QHB	Crozier House	01	General Debris	Residue to wall 1 RHS of door	General Debris	NO ASBESTOS	Residue Asbestos Pipe Insulation	Loose asbestos debris or residue	No further action required (Asbestos removed)	ACM Removed	HSG227	Unchecked	NO ASBESTOS	0	21/06/2019	Identified	No Asbestos Detected	87080	BA9454		18/02/2019		
#REF!	QHB	Crozier House	01	General Debris	Residue to wall 1 LHS of door	General Debris	NO ASBESTOS	Residue Asbestos Pipe Insulation	Loose asbestos debris or residue	No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	21/06/2019	Identified	Asbestos Removed	87081	BA9454		18/02/2019		
#REF!	QHB	Crozier House	01	General Debris	Debris to blue metal frame mid way wall 1	General Debris	NO ASBESTOS	Loose Asbestos Debris	Loose asbestos debris or residue	Remove (Controlled Conditions)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	21/06/2019	Identified	Asbestos Removed	87082	BA9454		18/02/2019		
#REF!	QHB	Crozier House	01	General Debris	Debris to redundant cable tray behind blue control panel wall 1	General Debris	NO ASBESTOS	Loose Asbestos Debris	Loose asbestos debris or residue	No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	21/06/2019	Identified	Asbestos Removed	87083	BA9454		18/02/2019		
#REF!	QHB	Crozier House	01	General Debris	Residue to wall 1 above wooden panelling	General Debris	NO ASBESTOS	Residue Asbestos Pipe Insulation	Loose asbestos debris or residue	No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	21/06/2019	Identified	Asbestos Removed	87084	BA9454		18/02/2019		
#REF!	QHB	Crozier House	01	General Debris	Residue to wall corner of wall 1 & 2	General Debris	NO ASBESTOS	Residue Asbestos Pipe Insulation	Loose asbestos debris or residue	No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	21/06/2019	Identified	Asbestos Removed	87085	BA9454		18/02/2019		
#REF!	QHB	Crozier House	01	General Debris	Residue to wall 2 behind boilers	General Debris	NO ASBESTOS	Residue Asbestos Pipe Insulation	Loose asbestos debris or residue	No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	21/06/2019	Identified	Asbestos Removed	87086	BA9454		18/02/2019		
#REF!	QHB	Crozier House	01	General Debris	Residue to wall 3 RHS of door to generator room	General Debris	NO ASBESTOS	Residue Asbestos Pipe Insulation	Loose asbestos debris or residue	No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	21/06/2019	Identified	Asbestos Removed	87087	BA9454		18/02/2019		
#REF!	QHB	Crozier House	01	General Debris	Residue to wall 3 at high level corner behind calorifier	General Debris	NO ASBESTOS	Residue Asbestos Pipe Insulation	Loose asbestos debris or residue	No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	21/06/2019	Identified	Asbestos Removed	87088	BA9454		18/02/2019		
#REF!	QHB	Crozier House	01	General Debris	Residue to wall 4 beneath beam mid room	General Debris	NO ASBESTOS	Residue Asbestos Pipe Insulation	Loose asbestos debris or residue	No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	21/06/2019	Identified	Asbestos Removed	87089	BA9454		18/02/2019		
#REF!	QHB	Crozier House	01	General Debris	Residue to wall 4 behind pumps	General Debris	NO ASBESTOS	Residue Asbestos Pipe Insulation	Loose asbestos debris or residue	No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	21/06/2019	Identified	Asbestos Removed	87090	BA9454		18/02/2019		
#REF!	QHB	Crozier House	01	General Debris	Residue to beam at high level above control panel	General Debris	NO ASBESTOS	Residue Asbestos Pipe Insulation	Loose asbestos debris or residue	No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	21/06/2019	Identified	Asbestos Removed	87091	BA9454		18/02/2019		
#REF!	QHB	Crozier House	01	General Debris	Residue to beam at high level adjacent cellar mid room	General Debris	NO ASBESTOS	Residue Asbestos Pipe Insulation	Loose asbestos debris or residue	No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	21/06/2019	Identified	Asbestos Removed	87092	BA9454		18/02/2019		
#REF!	QHB	Crozier House	01	General Debris	Residue to beam at high level above calorifiers	General Debris	NO ASBESTOS	Residue Asbestos Pipe Insulation	Loose asbestos debris or residue	No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	21/06/2019	Identified	Asbestos Removed	87093	BA9454		18/02/2019		
#REF!	QHB	Crozier House	01	General Debris	Residue to beam at high level above boiler	General Debris	NO ASBESTOS	Residue Asbestos Pipe Insulation	Loose asbestos debris or residue	No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	21/06/2019	Identified	Asbestos Removed	87094	BA9454		18/02/2019		
#REF!	OHB	Crozier House	01	Gaskets	Gasket to flanoe above boiler	Composite Material	Chrysotile	Composite Material	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Very Low Risk	3	06/10/2021	Identified	Very Low Risk	87095	BA9454	16/12/2 -	17/12/2019	WH Steehens	
#REF!	QHB	Crozier House	01	NO ASBESTOS	Panel to access hatch to roof space	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87096	BA9454		18/02/2019		
#REF!	QHB	Crozier House	01	NO ASBESTOS	Bitumen felt to flat roof within roof space	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87097	BA9454		18/02/2019		
#REF!	OHB	Crozier House	01	Fuse Flash Guards	Electrical equioment to oumos	Textiles & Paper	Presumed Asbestos	Unsealed	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Medium Risk	9	06/10/2021	Stronolv Presumed	Medium Risk	87098		16/12/2 -	17/12/2019	WH Steehens	
#REF!	QGD	Cherrygrove	01	NO ASBESTOS	Residue to wall 1 LHS of door	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87099	BA9465		19/02/2019		
#REF!	QGD	Cherrygrove	01	NO ASBESTOS	Residue to wall 2	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87100	BA9465		19/02/2019		
#REF!	QGD	Cherrygrove	01	NO ASBESTOS	Packer to flue pipe bracket to back of boiler	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87101	BA9465		19/02/2019		
#REF!	QGD	Cherrygrove	01	NO ASBESTOS	Residue to wall at flue extract	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87102	BA9465		19/02/2019		
#REF!	QGD	Cherrygrove	01	NO ASBESTOS	Residue to rear wall 3	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87103	BA9465		19/02/2019		
#REF!	QGD	Cherrygrove	01	NO ASBESTOS	Residue to wall 4	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87104	BA9465		19/02/2019		
#REF!	QGD	Cherrygrove	01	NO ASBESTOS	Residue to wall RHS of door	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87105	BA9465		19/02/2019		
#REF!	QGD	Cherrygrove	01	NO ASBESTOS	Debris to pumps wall 2	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87106	BA9465		19/02/2019		
#REF!	QGD	Cherrygrove	01	NO ASBESTOS	Debris to flue pipe rear of boiler	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87107	BA9465		19/02/2019		
#REF!	RAB	Longstone/Mullinure	02	NO ASBESTOS	Vinyl covering to floor	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87156	J008513		15/02/2019		
#REF!	RAB	Longstone/Mullinure	02	NO ASBESTOS	Felt packers to ceiling grid suspontine battens	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87157	J008513		15/02/2019		
#REF!	RAB	Longstone/Mullinure	02	NO ASBESTOS	Fire stop material above suspended ceiling	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87158	J008513		15/02/2019		
#REF!	RAB	Longstone/Mullinure	02	NO ASBESTOS	Ceiling tile	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87159	J008513		15/02/2019		
#REF!	RAB	Longstone/Mullinure	02	NO ASBESTOS	Bitumen to wall	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87160	J008513		15/02/2019		
#REF!	RAB	Longstone/Mullinure	02	NO ASBESTOS	Felt packers to wall	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87161	J008513		15/02/2019		
#REF!	RAB	Longstone/Mullinure	02	NO ASBESTOS	Vinyl covering to floor	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87162	J008513		15/02/2019		
#REF!	RAB	Longstone/Mullinure	02	NO ASBESTOS	Felt beneath window	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87163	J008513		15/02/2019		
#REF!	RAB	Longstone/Mullinure	02	NO ASBESTOS	Dust and debris around metal air ductino	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87164	J008513		15/02/2019		
#REF!	RAB	Lonostone/Mullinure	02	Window Puttv	Puttv at base of window	Composite Material	Chrysotile	Composite Material	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Very Low Risk	3	27/03/2021	Identified	Very Low Risk	87165	J008513	16/12/2 -	20/01/2020	WHS	
#REF!	RAB	Longstone/Mullinure	02	NO ASBESTOS	Bitumen to wall	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87166	J008513		15/02/2019		
#REF!	RAB	Lonostone/Mullinure	02	Window Puttv	Puttv at base of window	Composite Material	Chrysotile	Composite Material	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Very Low Risk	3	27/03/2021	Identified	Very Low Risk	87167	J008513	16/12/2 -	20/01/2020	WHS	
#REF!	RAB	Longstone/Mullinure	02	NO ASBESTOS	Vinyl covering to floor	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87168	J008513		15/02/2019		
#REF!	RAB	Longstone/Mullinure	02	NO ASBESTOS	Felt packers to wall	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87169	J008513		15/02/2019		
#REF!	RAB	Longstone/Mullinure	02	NO ASBESTOS	Felt beneath window	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87170	J008513		15/02/2019		
#REF!	RAB	Longstone/Mullinure	02	NO ASBESTOS	Fire stop material	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87171	J008513		15/02/2019		
#REF!	RAB	Longstone/Mullinure	02	NO ASBESTOS	Ceiling tile	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87172	J008513		15/02/2019		
#REF!	RAB	Longstone/Mullinure	02	NO ASBESTOS	Old black covering to original surface	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87173	J008513		15/02/2019		
#REF!	RAB	Longstone/Mullinure	02	NO ASBESTOS	Ceiling tile	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87174	J008513		15/02/2019		
#REF!	RAB	Longstone/Mullinure	02	NO ASBESTOS	Old black covering to original surface	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87175	J008513		15/02/2019		
#REF!	RAB	Longstone/Mullinure	02	NO ASBESTOS	Dust and debris inside metal air ductino	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87176	J008513		15/02/2019		
#REF!	RAB	Longstone/Mullinure	02	NO ASBESTOS	Dust and debris innside metal air ductino	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87177	J008513		15/02/2019		

#REF!	QAA	Craigavon Hospital	23	NO ASBESTOS	Vinyl floor tile beneath carpet	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87178	J008668		25/02/2019			
#REF!	QAA	Craigavon Hospital	23	NO ASBESTOS	Vinyl skirting	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87179	J008668		25/02/2019			
#REF!	QAA	Craigavon Hospital	23	NO ASBESTOS	Vinyl floor tile beneath carpet	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87180	J008668		25/02/2019			
#REF!	QAA	Craigavon Hospital	23	NO ASBESTOS	Vinyl skirting	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87181	J008668		25/02/2019			
#REF!	QAA	Craigavon Hospital	23	NO ASBESTOS	Vinyl floor covering	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87182	J008668		25/02/2019			
#REF!	QAA	Craigavon Hospital	23	NO ASBESTOS	Stairs down towards fire exit	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87183	J008668		25/02/2019			
#REF!	QAA	Craigavon Hospital	23	NO ASBESTOS	Dust/debris above suspended	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87184	J008329		31/01/2019			
#REF!	QAA	Craigavon Hospital	23	NO ASBESTOS	Tile debris above suspended ceiling	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87185	J008329		31/01/2019			
#REF!	QAA	Craigavon Hospital	23	NO ASBESTOS	Dust/debris above suspended ceiling	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87186	J008329		31/01/2019			
#REF!	SHA	Drumalane Estate	09	NO ASBESTOS	Side panel board	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87187	J008505		11/02/2019			
#REF!	SHA	Drumalane Estate	09	NO ASBESTOS	Front panel board	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87188	J008505		11/02/2019			
#REF!	SHA	Drumalane Estate	09	NO ASBESTOS	Ceiling to corridor	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87189	J008505		11/02/2019			
#REF!	SHA	Drumalane Estate	09	NO ASBESTOS	Board to door	NO ASBESTOS	NO ASBESTOS				Remove (Controlled Conditions)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87190	J008505		11/02/2019			
#REF!	SHA	Drumalane Estate	09	NO ASBESTOS	Ceiling to room	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87191	J008505		11/02/2019			
#REF!	SHA	Drumalane Estate	09	NO ASBESTOS	Ceiling to room	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87192	J008505		11/02/2019			
#REF!	SHA	Drumalane Estate	09	Lino Flooring	Vinyl beneath carpet	Composite Material	Chrysotile	Composite Material	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Very Low Risk	3	14/09/2023	Identified	Very Low Risk	87193	J008505	9300.2	06/04/2022	WHS			
#REF!	SHA	Drumalane Estate	09	Lino Flooring	Vinyl beneath carpet	Composite Material	Chrysotile	Composite Material	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Very Low Risk	3	14/09/2023	Identified	Very Low Risk	87194	J008505	9300.2	06/04/2022	WHS			
#REF!	SHA	Drumalane Estate	09	Door Panel	Board to rear of door	Insulatino Board	Amosite	Unsealed Board	Low	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	Medium Risk	7	14/03/2023	Identified	Medium Risk	87195	J008505	9300.2	06/04/2022	WHS			
#REF!	SHA	Drumalane Estate	09	Lino Flooring	Vinyl beneath carpet	Composite Material	Chrysotile	Composite Material	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Very Low Risk	3	14/09/2023	Identified	Very Low Risk	87196	J008505	9300.2	06/04/2022	WHS			
#REF!	SHA	Drumalane Estate	09	NO ASBESTOS	Board to stud partition	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87197	J008505		11/02/2019			
#REF!	SHA	Drumalane Estate	09	NO ASBESTOS	Board to stud partition	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87198	J008505		11/02/2019			
#REF!	SHA	Drumalane Estate	09	NO ASBESTOS	Board to door	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87199	J008505		11/02/2019			
#REF!	SHA	Drumalane Estate	09	NO ASBESTOS	Coating to solid wall	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87200	J008505		11/02/2019			
#REF!	SHA	Drumalane Estate	09	NO ASBESTOS	Coating to solid wall	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87201	J008505		11/02/2019			
#REF!	SHA	Drumalane Estate	09	NO ASBESTOS	Ceiling board	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87202	J008505		11/02/2019			
#REF!	SHA	Drumalane Estate	09	NO ASBESTOS	Ceiling board	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87203	J008505		11/02/2019			
#REF!	SHA	Drumalane Estate	09	NO ASBESTOS	Board beneath carpet	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87204	J008505		11/02/2019			
#REF!	SHA	Drumalane Estate	09	NO ASBESTOS	Board to wall	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87205	J008505		11/02/2019			
#REF!	SHA	Drumalane Estate	09	NO ASBESTOS	Board to wall	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87206	J008505		11/02/2019			
#REF!	SHA	Drumalane Estate	09	NO ASBESTOS	Board beneath carpet	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87208	J008505		11/02/2019			
#REF!	SHA	Drumalane Estate	09	NO ASBESTOS	Debris beneath floor	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87209	J008505		11/02/2019			
#REF!	SHA	Drumalane Estate	09	NO ASBESTOS	Debris to floor	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87210	J008505		11/02/2019			
#REF!	SHA	Drumalane Estate	09	NO ASBESTOS	Debris beneath floor	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87211	J008505		11/02/2019			
#REF!	SHA	Drumalane Estate	09	NO ASBESTOS	Debris to floor	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87212	J008505		11/02/2019			
#REF!	SHA	Drumalane Estate	09	Door Panel	Board to door (Re-sample)	Insulating Board	Amosite/Chrysotile	Unsealed Board	Low	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	Medium Risk	7	14/03/2023	Identified	Medium Risk	87213	J008505	9300.2	06/04/2022	WHS			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Dust and debris to floor	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87214	J008636		14/02/2019			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Sink pad	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87215	J008636		14/02/2019			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Dust and debris above ceiling	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87216	J008636		14/02/2019			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Vinyl floor tile	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87217	J008636		14/02/2019			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Dust and debris above ceiling	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87218	J008636		14/02/2019			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Cream vinyl floor tile	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87219	J008636		14/02/2019			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Grey vinyl floor tile	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87220	J008636		14/02/2019			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Cream vinyl floor tile	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87221	J008636		14/02/2019			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Dust and debris above ceiling	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87222	J008636		14/02/2019			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Vinyl skirting	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87223	J008636		14/02/2019			
#REF!	SHA	Drumalane Estate	09	NO ASBESTOS	Snot to wall	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Photographs Added	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87224	BA9472		21/02/2019			
#REF!	SHA	Drumalane Estate	09	NO ASBESTOS	Snot to wall RHS bay window	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Photographs Added	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87225	BA9472		21/02/2019			
#REF!	SHA	Drumalane Estate	09	Stair Nosing	Stair nosins to stairs to basement	Composite Material	Chrysotile	Composite Material	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Very Low Risk	3	14/09/2023	Identified	Very Low Risk	87226	BA9472	9300.2	06/04/2022	WHS			
#REF!	SHA	Drumalane Estate	09	NO ASBESTOS	Residue to pipework HL	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Photographs Added	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87227	BA9472		21/02/2019			
#REF!	SHA	Drumalane Estate	09	NO ASBESTOS	Residue to pipework LL	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Photographs Added	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87228	BA9472		21/02/2019			
#REF!	SHA	Drumalane Estate	09	NO ASBESTOS	Residue to pipework LL	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Photographs Added	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87229	BA9472		21/02/2019			
#REF!	SHA	Drumalane Estate	09	NO ASBESTOS	Insert to wall at corner	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Photographs Added	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87230	BA9472		21/02/2019			
#REF!	SHA	Drumalane Estate	09	NO ASBESTOS	Residue to pipework LL	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Photographs Added	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87231	BA9472		21/02/2019			
#REF!	SHA	Drumalane Estate	09	NO ASBESTOS	Floor tile to corridor to filing room	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Photographs Added	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87233	BA9472		21/02/2019			
#REF!	SHA	Drumalane Estate	09	NO ASBESTOS	Floor tile to toilet cubical	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Photographs Added	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87234	BA9472		21/02/2019			
#REF!	SHA	Drumalane Estate	09	NO ASBESTOS	Lagging to P/W HL corridor	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Photographs Added	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87235	BA9472		21/02/2019			
#REF!	SHA	Drumalane Estate	09	NO ASBESTOS	Lagging to P/W to corridor HL	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Photographs Added	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87236	BA9472		21/02/2019			
#REF!	SHA	Drumalane Estate	09	NO ASBESTOS	Lino to stairs to basement	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Photographs Added	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87237	BA9472		21/02/2019			
#REF!	SHA	Drumalane Estate	09	NO ASBESTOS	Textured coating to wall of stairs to basement	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Photographs Added	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87238	BA9472		21/02/2019			
#REF!	SHA	Drumalane Estate	09	Stair Nosing	Stair nosing to steps from main	Composite Material	Chrysotile	Composite Material	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Very Low Risk	3	14/09/2023	Identified	Very Low Risk	87239	BA9472	9300.2	06/04/2022	WHS			
#REF!	SHA	Drumalane Estate	09	NO ASBESTOS	Lino to steps from main corridor	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Photographs Added	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87240	BA9472		21/02/2019			
#REF!	SHA	Drumalane Estate	09	NO ASBESTOS	Floor covering to 1st floor bathroom	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Photographs Added	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87241	BA9472		21/02/2019			
#REF!	RJA	Willowbank Resource Centre	01	NO ASBESTOS	Electrical cupboard - Board to shelf	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87242	BA9597		25/04/2019			
#REF!	RJA	Willowbank Resource Centre	01	NO ASBESTOS	Electrical cupboard - Debris to shelf	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87243	BA9597		25/04/2019			
#REF!	SAA	Daisy Hill Hospital Estate	09	Residue to Walls	Snot to wall 3m in duct leading from A-002	Thermal Insulation	Amosite	unsealed	Loose asbestos debris or residue	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	High Risk	11	26/12/2022	Identified	High Risk	87244	BA9501	9300.2	20/04/2022	WHS			
#REF!	SAA	Daisy Hill Hospital Estate	09	Residue to Walls	Snot to wall 2m in duct leading from A-002	Thermal Insulation	Amosite	unsealed	Loose asbestos debris or residue	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	High Risk	11	26/12/2022	Identified	High Risk	87245	BA9501	9300.2	20/04/2022	WHS			
#REF!	SAA	Daisy Hill Hospital Estate	09	Residue to Walls	Snot to wall 1m in duct leading from A-002	Thermal Insulation	Amosite	unsealed	Loose asbestos debris or residue	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	High Risk	11	26/12/2022	Identified	High Risk	87246	BA9501	9300.2	20/04/2022	WHS			
#REF!	SAA	Daisy Hill Hospital Estate	09	General Debris	Debris to floor 4m in duct leading from A-002	General Debris	Amosite	Loose Asbestos Debris	Loose asbestos debris or residue	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	High Risk	11	26/09/2023	Identified	High Risk	87247	BA9501	9300.2	20/04/2022	WHS			
#REF!	SAA	Daisy Hill Hospital Estate	09	General Debris	Debris to floor 3m in duct leading from A-002	General Debris	Amosite	Loose Asbestos Debris	Loose asbestos debris or residue	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	High Risk	11	26/12/2022	Identified	High Risk	87248	BA9501	9300.2	20/04/2022	WHS			
#REF!	SAA	Daisy Hill Hospital Estate	09	General Debris	Debris to floor 2m in duct leading from A-002	General Debris	Amosite	Loose Asbestos Debris	Loose asbestos debris or residue	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	High Risk	11	26/12/2022	Identified	High Risk	87249	BA9501	9300.2	20/04/2022	WHS			
#REF!	SAA	Daisy Hill Hospital Estate	09	General Debris	Debris to floor 1m in duct leading from A-002	General Debris	Amosite	Loose Asbestos Debris	Loose asbestos debris or residue	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	High Risk	11	26/12/2022	Identified	High Risk	87250	BA9501	9300.2	20/04/2022	WHS			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Vinyl floor tiles	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87251	J008323		08/02/2019			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Vinyl skirting	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87252	J008323		08/02/2019			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Suspended ceiling tile	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87253	J008323		08/02/2019			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Fire stop above ceiling	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87254	J008323		08/02/2019			
#REF!	QAA	Craigavon Hospital	01	Pipe Insulation	Fabric around pipe bracket supporting bare copper pipe	Textiles & Paper	Chrysotile	Unsealed	Low	Remove (Controlled Conditions)	New Incident	HSG227	Unchecked	Medium Risk	7	29/10/2019	Identified	Medium Risk	87255	J008323		08/02/2019				
#REF!	QAA	Craigavon Hospital	01	Pipe Brackets	Fabric around pipe bracket supporting insulated pipe	Textiles & Paper	Chrysotile	unsealed	Low	Remove (Controlled Conditions)	New Incident	HSG227	Unchecked	Medium Risk	7	29/10/2019	Identified	Medium Risk	87256	J008323		08/02/2019				

#REF!	QAA	Craigavon Hospital	01	Bitumen Felt	Felt packer to metal grid support	Composite Material	Chrysotile	Composite Material	Low	Remove if likely to be disturbed	New Incident	HSG227	Unchecked	Very Low Risk	3	29/04/2020	Identified	Very Low Risk	87257	J008323		08/02/2019			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Black vinyl skirting	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87258	J008323		08/02/2019			
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Bitumen to roof above suspended ceilino	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87259	BA9489	9506/18	20/03/2019	WHS		
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Felt packer to roof above sussended ceilino	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87260	BA9489	9506/18	20/03/2019	WHS		
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Dust/debris to top of ceiling tile	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87261	BA9489	9506/18	20/03/2019	WHS		
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Dust/debris to top of ceiling tile	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87262	BA9489	9506/18	20/03/2019	WHS		
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Bitumen to roof above suspended ceilino	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87263	BA9489	9506/18	20/03/2019	WHS		
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Electrical cupboard - Dust/debris to top cupboard	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87264	BA9489	9506/18	20/03/2019	WHS		
#REF!	QAA	Craigavon Hospital	11	NO ASBESTOS	Vinyl beneath carpet	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87265	J008634		27/02/2019			
#REF!	QAA	Craigavon Hospital	11	NO ASBESTOS	Black vinyl skirting	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87266	J008634		27/02/2019			
#REF!	QAA	Craigavon Hospital	11	NO ASBESTOS	Vinyl floor covering	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87267	J008634		27/02/2019			
#REF!	QAA	Craigavon Hospital	11	NO ASBESTOS	Black vinyl skirting	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87268	J008634		27/02/2019			
#REF!	QAA	Craigavon Hospital	11	NO ASBESTOS	Void above suspended ceiling - Dust and Debris	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87269	J008634		27/02/2019			
#REF!	QAA	Craigavon Hospital	11	NO ASBESTOS	Void above suspended ceiling - Dust and debris	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87270	J008634		27/02/2019			
#REF!	QAA	Craigavon Hospital	11	NO ASBESTOS	Vinyl skirting	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87271	J008634		27/02/2019			
#REF!	QAA	Craigavon Hospital	11	NO ASBESTOS	Vinyl floor tiles to base	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87272	J008634		27/02/2019			
#REF!	QAA	Craigavon Hospital	11	NO ASBESTOS	Vinyl floor covering	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87273	J008918		05/03/2019			
#REF!	QAA	Craigavon Hospital	11	NO ASBESTOS	Black vinyl skirting	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87274	J008918		05/03/2019			
#REF!	QAA	Craigavon Hospital	11	NO ASBESTOS	Dust and debris to area above ceilino tile	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87275	J0.08919		05/03/2019			
#REF!	QAA	Craigavon Hospital	11	NO ASBESTOS	Vinyl beneath carpet	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87276	J008919		05/03/2019			
#REF!	QAA	Craigavon Hospital	11	NO ASBESTOS	Black vinyl skirting	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87277	J008919		05/03/2019			
#REF!	QAA	Craigavon Hospital	11	NO ASBESTOS	Vinyl skirting	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87278	J008919		14/02/2019			
#REF!	QAA	Craigavon Hospital	11	NO ASBESTOS	Vinyl floor tile	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87279	J008919		05/03/2019			
#REF!	QJE	Little Forest & Killycomaine	01	NO ASBESTOS	Sarking felt	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87281	J008327		01/02/2019			
#REF!	QJE	Little Forest & Killycomaine	01	NO ASBESTOS	Loose board	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87282	J008327		08/02/2019			
#REF!	QJE	Little Forest & Killycomaine	01	NO ASBESTOS	Board to upper side of access hatch panel	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87283	J008327		08/02/2019			
#REF!	QJE	Little Forest & Killycomaine	01	NO ASBESTOS	Loose insulation	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87284	J008327		08/02/2019			
#REF!	QJE	Little Forest & Killycomaine	01	NO ASBESTOS	Board to inner side of door	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87285	J008327		08/02/2019			
#REF!	QJE	Little Forest & Killycomaine	01	NO ASBESTOS	Felt packer	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87286	J008327		08/02/2019			
#REF!	QJE	Little Forest & Killycomaine	01	NO ASBESTOS	Board to inner side of door	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87287	J008327		08/02/2019			
#REF!	QJE	Little Forest & Killycomaine	01	NO ASBESTOS	Vinyl to floor	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87288	J008327		08/02/2019			
#REF!	QJE	Little Forest & Killycomaine	01	NO ASBESTOS	Vinyl skirting	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87289	J008327		08/02/2019			
#REF!	QJE	Little Forest & Killycomaine	01	NO ASBESTOS	Board to upper side access hatch panel	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87290	J008327		08/02/2019			
#REF!	QJE	Little Forest & Killycomaine	01	NO ASBESTOS	Sealant at flue	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87291	J008327		08/02/2019			
#REF!	QJE	Little Forest & Killycomaine	01	NO ASBESTOS	Dust to floor	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87292	J008327		08/02/2019			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Area above suspended ceiling - dust and debris to top of ceilino tiles	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87293	J008637		27/02/2019			
#REF!	QAA	Craigavon Hospital	01	Pipe Brackets	Area above suspended ceiling - Fabric strip on metal pipe support	Textiles & Paper	Chrysotile	Unsealed	Low	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	Medium Risk	7	29/09/2023	Identified	Medium Risk	87294	J008637	9302.22	29/09/2022	WHS		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Area above suspended ceiling - Dust and debris to top of ceilino tiles	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87295	J008637		27/02/2019			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Fire hose cupboard	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87296	J008637		27/02/2019			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Fire hose cupboard	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87297	J008637		27/02/2019			
#REF!	QAA	Craigavon Hospital	01	Board	Fire alarm cupboard - Board to base of cupboard	Insulating Board	Amosite/Chrysotile	Unsealed Asbestos Insulation Board	Low	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	Medium Risk	7	29/09/2023	Identified	Medium Risk	87298	J008637	9302.22	29/09/2022	WHS		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Fire alarm cupboard - dust and debris to base	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87299	J008637		27/02/2019			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Area above suspended ceiling - Pipe insulation	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87300	J008635		14/02/2019			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Area above suspended ceiling - dust and debris to top of tiles	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87301	J008635		14/02/2019			
#REF!	QAA	Craigavon Hospital	01	Pipe Brackets	Area above suspended ceiling - Fabric to plow hanger on bare	Textiles & Paper	Chrysotile	Unsealed	Low	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	Medium Risk	7	29/09/2023	Identified	Medium Risk	87302	J008635	9302.22	29/09/2022	WHS		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Area above suspended ceiling - Dust and debris to top of tiles	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87303	J009635		14/02/2019			
#REF!	RHA	Roxborough Site	01	NO ASBESTOS	Panel to access hatch to ceiling void	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87321	BA9636		09/05/2019			
#REF!	RHA	Roxborough Site	01	NO ASBESTOS	Debris to ledge to access hatch to ceiling void	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87322	BA9636		09/05/2019			
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Ceiling	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87323	BA9635		09/05/2019			
#REF!	QAA	Craigavon Hospital	08	Ceilino Board	Ceilino to floor duct to laundry	Insulating Board	Amosite/Chrysotile	Unsealed Asbestos Insulation Board	High	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	Medium Risk	9	08/03/2023	Identified	Medium Risk	87324	BA9419	9302.2	18/10/2022	WHS		
#REF!	RAA	South Tyrone Hospital	15	NO ASBESTOS	Pipe insulation	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87325	J008433		15/02/2019			
#REF!	RAA	South Tyrone Hospital	15	NO ASBESTOS	Pipe insulation	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87326	J008433		15/02/2019			
#REF!	RAA	South Tyrone Hospital	17	Floor Tile and Bitumen Adhesive	Vinyl floor tiles	Composite Material	Chrysotile	Composite Material	Medium	Manage and monitor	Re-inspection	HSG227	Unchecked	Very Low Risk	4	14/12/2023	Identified	Very Low Risk	87327	J008434	9302.2	14/12/2022	WHS		
#REF!	SHB	Cloughreagh House	01	NO ASBESTOS	Gasket to redundant blue pump	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87328	BA9322		28/11/2018			
#REF!	SHB	Cloughreagh House	01	NO ASBESTOS	Redundant gasket to floor	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87329	BA9322		28/11/2018			
#REF!	SHB	Cloughreagh House	01	NO ASBESTOS	Gasket to redundant red pump	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87330	BA9322		28/11/2018			
#REF!	SHB	Cloughreagh House	01	General Debris	Redundant gasket debris to flange extension	General Debris	Chrysotile	Loose Asbestos Debris	Loose asbestos debris or residue	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	High Risk	10	12/12/2022	Identified	High Risk	87331	BA9322	9300/22	31/08/2022	WHS		
#REF!	SHB	Cloughreagh House	01	NO ASBESTOS	Redundant gasket debris to floor	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87332	BA9322		28/11/2018			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	White floor tile	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Photographs Added	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87333	BA9470		21/02/2019			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Beige floor tile	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Photographs Added	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87334	BA9470		21/02/2019			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Grey floor tile	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Photographs Added	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87335	BA9470		21/02/2019			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Beige floor tile	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Photographs Added	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87336	BA9470		21/02/2019			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Grey floor tile	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Photographs Added	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87337	BA9470		21/02/2019			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Grey floor tile	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Photographs Added	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87338	BA9470		21/02/2019			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Blue floor tile	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Photographs Added	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87339	BA9470		21/02/2019			
#REF!	RAA	South Tyrone Hospital	01	Floor Tiles	Floor tile	Composite Material	Chrysotile	Composite Material	Medium	Manage and monitor	Re-inspection	HSG227	Unchecked	Very Low Risk	4	15/12/2023	Identified	Very Low Risk	87340	BA9615	9302.2	15/12/2022	WHS		
#REF!	RAA	South Tyrone Hospital	01	NO ASBESTOS	Sink pad	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87341	BA9615		29/04/2019			
#REF!	RAA	South Tyrone Hospital	01	Floor Tiles	Floor tile	Composite Material	Chrysotile	Composite Material	Medium	Manage and monitor	Re-inspection	HSG227	Unchecked	Very Low Risk	4	15/12/2023	Identified	Very Low Risk	87342	BA9615	9302.2	15/12/2022	WHS		
#REF!	RAA	South Tyrone Hospital	01	NO ASBESTOS	Bitumen adhesive	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87343	BA9615		29/04/2019			
#REF!	RAA	South Tyrone Hospital	01	Floor Tiles	Floor tile	Composite Material	Chrysotile	Composite Material	Medium	Manage and monitor	Re-inspection	HSG227	Unchecked	Very Low Risk	4	15/12/2023	Identified	Very Low Risk	87344	BA9615	9302.2	15/12/2022	WHS		
#REF!	RAA	South Tyrone Hospital	01	NO ASBESTOS	Cloth wrap and insulation to pipework	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87345	BA9615		29/04/2019			
#REF!	RAA	South Tyrone Hospital	01	Floor Tiles	Floor tile	Composite Material	Chrysotile	Composite Material	Medium	Manage and monitor	Re-inspection	HSG227	Unchecked	Very Low Risk	4	15/12/2023	Identified	Very Low Risk	87346	BA9615	9302.2	15/12/2022	WHS		
#REF!	RAA	South Tyrone Hospital	01	NO ASBESTOS	Sink pad	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87347	BA9615		29/04/2019			
#REF!	RAA	South Tyrone Hospital	01	Floor Tiles	Floor tile	Composite Material	Chrysotile	Composite Material	Medium	Manage and monitor	Re-inspection	HSG227	Unchecked	Very Low Risk	4	15/12/2023	Identified	Very Low Risk	87348	BA9615	9302.2	15/12/2022	WHS		
#REF!	RAA	South Tyrone Hospital	01	Floor Tiles	Floor tile	Composite Material	Chrysotile	Composite Material	Medium	Manage and monitor	Re-inspection	HSG227	Unchecked	Very Low Risk	4	15/12/2023	Identified	Very Low Risk	87349	BA9615	9302.2	15/12/2022	WHS		
#REF!	RAA	South Tyrone Hospital	01	NO ASBESTOS	Bitumen residue to underside of roof slab	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87350	BA9615		29/04/2019			
#REF!	RAA	South Tyrone Hospital	01	NO ASBESTOS	Debris to worktop	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87351	BA9615		29/04/2019			

#REF!	RAA	South Tyrone Hospital	01	NO ASBESTOS	Lagging to pipework in riser	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87352	BA9615		29/04/2019	
#REF!	RAA	South Tyrone Hospital	01	Bitumen Adhesive	Bitumen to external wall of plant	Composite Material	Chrysotile	Composite Material	Medium	Manage and monitor	Re-inspection	HSG227	Unchecked	Very Low Risk	4	15/12/2023	Identified	Very Low Risk	87353	BA9615	9302/2	15/12/2022	WHS	
#REF!	RAA	South Tyrone Hospital	01	NO ASBESTOS	Bitumen residue to timber joist	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87354	BA9615	-	29/04/2019	
#REF!	RAA	South Tyrone Hospital	01	NO ASBESTOS	Debris to floor of riser	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87355	BA9615	-	29/04/2019	
#REF!	RAA	South Tyrone Hospital	01	Floor Tiles	Vinyl floor tile	Composite Material	Chrysotile	Composite Material	Medium	Manage and monitor	Re-inspection	HSG227	Unchecked	Very Low Risk	4	15/12/2023	Identified	Very Low Risk	87356	BA9615	9302/2	15/12/2022	WHS	
#REF!	RAA	South Tyrone Hospital	01	Floor Tiles	Vinyl floor tile	Composite Material	Chrysotile	Composite Material	Medium	Manage and monitor	Re-inspection	HSG227	Unchecked	Very Low Risk	4	15/12/2023	Identified	Very Low Risk	87357	BA9615	9302/2	15/12/2022	WHS	
#REF!	RAA	South Tyrone Hospital	01	Floor Tiles	Vinyl floor tile	Composite Material	Chrysotile	Composite Material	Medium	Manage and monitor	Re-inspection	HSG227	Unchecked	Very Low Risk	4	15/12/2023	Identified	Very Low Risk	87358	BA9615	9302/2	15/12/2022	WHS	
#REF!	RAA	South Tyrone Hospital	01	NO ASBESTOS	Sink pad	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87359	BA9615	-	29/04/2019	
#REF!	RAA	South Tyrone Hospital	01	Stair Nosing	Stair nosing	Composite Material	Chrysotile	Composite Material	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Very Low Risk	3	15/12/2023	Identified	Very Low Risk	87360	BA9615	9302/2	15/12/2022	WHS	
#REF!	RAA	South Tyrone Hospital	12	NO ASBESTOS	Debris to duct	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87365	BA9617	-	29/04/2019	
#REF!	RAA	South Tyrone Hospital	12	NO ASBESTOS	Lagging to pipework	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87366	BA9617	-	29/04/2019	
#REF!	RAA	South Tyrone Hospital	12	Insulation	Laggino to oipe in boiler house	Thermal Insulation	Amosite	Unsealed Sorav or Laggino	High	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	Hioh Risk	11	15/12/2023	Identified	Hioh Risk	87367	BA9617	9302/2	15/12/2022	WHS	
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Board around soil pipe penetration	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87368	BA9616	-	29/04/2019	
#REF!	RHA	Roxborough Site	01	Floor Tile and Bitumen Adhesive	Vinvl floor tile and bitumen to stairs	Composite Material	Chrysotile	Composite Material	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Very Low Risk	3	08/04/2021	Identified	Very Low Risk	87369	BA9512	9501/1	14/11/2019	WHS	
#REF!	RHA	Roxborough Site	01	Fuse Flash Guards	Fuse flash guard	Textiles & Paper	Chrysotile	unsealed	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Medium Risk	7	08/04/2021	Identified	Medium Risk	87370	J008322	9501/1	14/11/2019	WHS	
#REF!	RHA	Roxborough Site	01	Fuse Flash Guards	Fuse flash guard	Textiles & Paper	Chrysotile	unsealed	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Medium Risk	7	08/04/2021	Identified	Medium Risk	87371	J008322	9501/1	14/11/2019	WHS	
#REF!	RHA	Roxborough Site	01	Floor Tile and Bitumen Adhesive	Black vinvl floor tiles and bitumen	Composite Material	Chrysotile	Composite Material	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Very Low Risk	3	08/04/2021	Identified	Very Low Risk	87372	J008322	9501/1	14/11/2019	WHS	
#REF!	RSA	Dungannon Clinic	01	Residue to Walls	Residue to wall 1 LHS of door	Thermal Insulation	NO ASBESTOS	unsealed	Loose asbestos debris or residue	No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	13/04/2022	Identified	Asbestos Removed	87374	BA9415	9000/2 1	19/11/2019	WHS	
#REF!	RSA	Dungannon Clinic	01	NO ASBESTOS	Panel to flue exhaust LHS	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87375	BA9415	-	25/01/2019	
#REF!	RSA	Dungannon Clinic	01	NO ASBESTOS	Panel to flue exhaust RHS	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87376	BA9415	-	25/01/2019	
#REF!	RSA	Dungannon Clinic	01	Residue to Walls	Residue to wall 1 beneath flue pipes	Thermal Insulation	NO ASBESTOS	unsealed	Loose asbestos debris or residue	No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	13/04/2022	Identified	Asbestos Removed	87377	BA9415	9000/2 1	19/11/2019	WHS	
#REF!	RSA	Dungannon Clinic	01	Residue to Walls	Residue to wall 2 at corner with wall 1	Thermal Insulation	NO ASBESTOS	unsealed	Loose asbestos debris or residue	No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	13/04/2022	Identified	Asbestos Removed	87378	BA9415	9000/2 1	19/11/2019	WHS	
#REF!	RSA	Dungannon Clinic	01	Residue to Walls	Residue to wall 2 at high level mid wall	Thermal Insulation	NO ASBESTOS	unsealed	Loose asbestos debris or residue	No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	13/04/2022	Identified	Asbestos Removed	87379	BA9415	9000/2 1	19/11/2019	WHS	
#REF!	RSA	Dungannon Clinic	01	Residue to Walls	Residue to wall 3 mid wall	Thermal Insulation	NO ASBESTOS	unsealed	Loose asbestos debris or residue	No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	13/04/2022	Identified	Asbestos Removed	87380	BA9415	9000/2 1	19/11/2019	WHS	
#REF!	RSA	Dungannon Clinic	01	Residue to Walls	Residue to wall 3 beneath electrical panels	Thermal Insulation	NO ASBESTOS	unsealed	Loose asbestos debris or residue	No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	13/04/2022	Identified	Asbestos Removed	87381	BA9415	9000/2 1	19/11/2019	WHS	
#REF!	RSA	Dungannon Clinic	01	Residue to Walls	Residue to wall 4	Thermal Insulation	NO ASBESTOS	unsealed	Loose asbestos debris or residue	No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	13/04/2022	Identified	Asbestos Removed	87382	BA9415	9000/2 1	19/11/2019	WHS	
#REF!	RSA	Dungannon Clinic	01	Residue to Walls	Residue to wall 4	Thermal Insulation	NO ASBESTOS	unsealed	Loose asbestos debris or residue	No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	13/04/2022	Identified	Asbestos Removed	87383	BA9415	9000/2 1	19/11/2019	WHS	
#REF!	RSA	Dungannon Clinic	01	Residue to Walls	Residue to pipework	Thermal Insulation	NO ASBESTOS	unsealed	Loose asbestos debris or residue	No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	13/04/2022	Identified	Asbestos Removed	87384	BA9415	9000/2 1	19/11/2019	WHS	
#REF!	RSA	Dungannon Clinic	01	Pipe Residue	Residue to pipework	Thermal Insulation	NO ASBESTOS	unsealed	Loose asbestos debris or residue	No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	13/04/2022	Identified	Asbestos Removed	87385	BA9415	9000/2 1	19/11/2019	WHS	
#REF!	RSA	Dungannon Clinic	01	Pipe Residue	Residue to flue to older boiler	Thermal Insulation	NO ASBESTOS	unsealed	Loose asbestos debris or residue	No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	13/04/2022	Identified	Asbestos Removed	87386	BA9415	9000/2 1	19/11/2019	WHS	
#REF!	RSA	Dungannon Clinic	01	NO ASBESTOS	Sleeve to flange	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87387	BA9415	-	25/01/2019	
#REF!	RSA	Dungannon Clinic	01	Debris	Debris to duct RHS of door	Thermal Insulation	NO ASBESTOS	unsealed	Loose asbestos debris or residue	No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	13/04/2022	Identified	Asbestos Removed	87388	BA9415	9000/2 1	19/11/2019	WHS	
#REF!	RSA	Dungannon Clinic	01	Debris	Derbis to floor	Thermal Insulation	NO ASBESTOS	Loose Asbestos Debris	Loose asbestos debris or residue	No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	13/04/2022	Identified	Asbestos Removed	87389	BA9415	9000/2 1	19/11/2019	WHS	
#REF!	RSA	Dungannon Clinic	01	Pipe Residue	Residue to redundant pipe at rear wall	Thermal Insulation	NO ASBESTOS	unsealed	Loose asbestos debris or residue	No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	13/04/2022	Identified	Asbestos Removed	87390	BA9415	9000/2 1	19/11/2019	WHS	
#REF!	RSA	Dungannon Clinic	01	NO ASBESTOS	Redundant boiler gasket wall 4	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87391	BA9415	-	25/01/2019	
#REF!	RSA	Dungannon Clinic	01	NO ASBESTOS	Gasket to burner of newer boiler	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87392	BA9415	-	25/01/2019	
#REF!	QAB	Banbridge Polyclinic	14	NO ASBESTOS	Insulation between joists	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87393	BA9387	-	10/01/2019	
#REF!	QAB	Banbridge Polyclinic	14	NO ASBESTOS	Pipe insulation	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87394	BA9387	-	10/01/2019	
#REF!	QAB	Banbridge Polyclinic	14	NO ASBESTOS	Sarking felt	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87395	BA9387	-	10/01/2019	
#REF!	QAB	Banbridge Polyclinic	14	Bitumen Skirting Boards	Black vinyl skirting with pipe boxing	Composite Material	Chrysotile	Composite Material	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Very Low Risk	3	09/09/2023	Identified	Very Low Risk	87396	BA9387	9302/2	11/04/2022	WHS	
#REF!	QAB	Banbridge Polyclinic	14	Bitumen Adhesive	Bitumen behind black vinyl skirting within oipe boxino	Composite Material	Chrysotile	Composite Material	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Very Low Risk	3	09/09/2023	Identified	Very Low Risk	87397	BA9387	9299/2 2	11/04/2022	WHS	
#REF!	QAB	Banbridge Polyclinic	14	NO ASBESTOS	Sink pad	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87398	BA9387	-	10/01/2019	
#REF!	QAB	Banbridge Polyclinic	14	NO ASBESTOS	Damp proof course	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87399	BA9387	-	10/01/2019	
#REF!	QAB	Banbridge Polyclinic	14	Soffit Boarding	Soffit at front corner of roof LHS	Cement Products	Chrysotile	Cement Sheets	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Very Low Risk	4	09/09/2023	Identified	Very Low Risk	87400	BA9387	9302/2	11/04/2022	WHS	
#REF!	QAB	Banbridge Polyclinic	14	Soffit Boarding	Soffit at front corner of roof RHS	Cement Products	Chrysotile	Cement Sheets	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Very Low Risk	4	09/09/2023	Identified	Very Low Risk	87401	BA9387	9302/2	11/04/2022	WHS	
#REF!	QAB	Banbridge Polyclinic	14	Soffit Boarding	Soffit at rear corner of roof RHS	Cement Products	Chrysotile	Cement Sheets	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Very Low Risk	4	09/09/2023	Identified	Very Low Risk	87402	BA9387	9302/2	11/04/2022	WHS	
#REF!	RAB	Longstone/Mullinure	01	Residue to Walls	Residue to wall 1	Thermal Insulation	Amosite	unsealed	Loose asbestos debris or residue	Remove (Controlled Conditions)	New Incident	HSG227	Unchecked	High Risk	11	21/08/2019	Identified	High Risk	87403	BA9421	-	30/01/2019		
#REF!	RAB	Longstone/Mullinure	01	Residue to Walls	Residue to wall 1	Thermal Insulation	Amosite	unsealed	Loose asbestos debris or residue	Remove (Controlled Conditions)	New Incident	HSG227	Unchecked	High Risk	11	21/08/2019	Identified	High Risk	87404	BA9421	-	30/01/2019		
#REF!	RAB	Longstone/Mullinure	01	Residue to Walls	Residue to wall 2	Thermal Insulation	Amosite	unsealed	Loose asbestos debris or residue	Remove (Controlled Conditions)	New Incident	HSG227	Unchecked	High Risk	11	21/08/2019	Identified	High Risk	87405	BA9421	-	30/01/2019		
#REF!	RAB	Longstone/Mullinure	01	Residue to Walls	Residue to wall 2	Thermal Insulation	Amosite	unsealed	Loose asbestos debris or residue	Remove (Controlled Conditions)	New Incident	HSG227	Unchecked	High Risk	11	21/08/2019	Identified	High Risk	87406	BA9421	-	30/01/2019		
#REF!	RAB	Longstone/Mullinure	01	Residue to Walls	Residue to wall 3	Thermal Insulation	Amosite	unsealed	Loose asbestos debris or residue	Remove (Controlled Conditions)	New Incident	HSG227	Unchecked	High Risk	11	21/08/2019	Identified	High Risk	87407	BA9421	-	30/01/2019		
#REF!	RAB	Longstone/Mullinure	01	Residue to Walls	Residue to wall 3	Thermal Insulation	Amosite	unsealed	Loose asbestos debris or residue	Remove (Controlled Conditions)	New Incident	HSG227	Unchecked	High Risk	11	21/08/2019	Identified	High Risk	87408	BA9421	-	30/01/2019		
#REF!	RAB	Longstone/Mullinure	01	Residue to Walls	Residue to wall 4	Thermal Insulation	Amosite	unsealed	Loose asbestos debris or residue	Remove (Controlled Conditions)	New Incident	HSG227	Unchecked	High Risk	11	21/08/2019	Identified	High Risk	87409	BA9421	-	30/01/2019		
#REF!	RAB	Longstone/Mullinure	01	Residue to Walls	Residue to wall 4	Thermal Insulation	Amosite	unsealed	Loose asbestos debris or residue	Remove (Controlled Conditions)	New Incident	HSG227	Unchecked	High Risk	11	21/08/2019	Identified	High Risk	87410	BA9421	-	30/01/2019		
#REF!	RAB	Longstone/Mullinure	01	Pipe Residue	Residue to pipework	Thermal Insulation	Amosite	unsealed	Loose asbestos debris or residue	Remove (Controlled Conditions)	New Incident	HSG227	Unchecked	High Risk	11	21/08/2019	Identified	High Risk	87411	BA9421	-	30/01/2019		
#REF!	RAB	Longstone/Mullinure	01	Pipe Residue	Residue to oipe bracket	Thermal Insulation	Amosite	unsealed	Loose asbestos debris or residue	Remove (Controlled Conditions)	New Incident	HSG227	Unchecked	High Risk	11	21/08/2019	Identified	High Risk	87412	BA9421	-	30/01/2019		
#REF!	RAB	Longstone/Mullinure	01	Debris	Debris to duct RHS of door	Thermal Insulation	Amosite	Loose Asbestos Debris	Loose asbestos debris or residue	Remove (Controlled Conditions)	New Incident	HSG227	Unchecked	High Risk	11	21/08/2019	Identified	High Risk	87413	BA9421	-	30/01/2019		
#REF!	RAB	Longstone/Mullinure	01	Debris	Debris to floor	Thermal Insulation	Amosite	unsealed	Loose asbestos debris or residue	Remove (Controlled Conditions)	New Incident	HSG227	Unchecked	High Risk	11	21/08/2019	Identified	High Risk	87414	BA9421	-	30/01/2019		
#REF!	RAB	Longstone/Mullinure	01	Debris	Debris to floor	Thermal Insulation	Amosite	unsealed	Loose asbestos debris or residue	Remove (Controlled Conditions)	New Incident	HSG227	Unchecked	High Risk	11	21/08/2019	Identified	High Risk	87415	BA9421	-	30/01/2019		
#REF!	QJA	Bannvale	05	NO ASBESTOS	Insulation to calorifier	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87416	J008408	-	15/02/2019	
#REF!	QJA	Bannvale	05	NO ASBESTOS	Insulation to calorifier	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87417	J008408	-	15/02/2019	
#REF!	QJA	Bannvale	05	NO ASBESTOS	Dust/debris around base of calorifier	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87418	J008408	-	15/02/2019	
#REF!	QJA	Bannvale	05	NO ASBESTOS	Debris to wall to LHS of calorifier	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87419	J008408	-	15/02/2019	
#REF!	QJA	Bannvale	05	NO ASBESTOS	Insulation residue to pipe work at base of calorifier	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87420	J008408	-	15/02/2019	
#REF!	QJA	Bannvale	05	NO ASBESTOS	Insulation residue to large diameter oipe work to rear of calorifier	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87421	J008408	-	15/02/2019	
#REF!	QJA	Bannvale	05	Gaskets	Gasket to pipe flange to vertical oipes between calorifier and first	Textiles & Paper	Chrysotile	unsealed	Low	Manage & Affix ID Labels	Re-inspection	HSG227	Unchecked	Medium Risk	7	09/03/2023	Identified	Medium Risk	87422	J008408	9299/2 2	06/04/2022	WHS	
#REF!	QJA	Bannvale	05	NO ASBESTOS	Board to sloping ceiling over calorifier	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87423	J008408	-	15/02/2019	
#REF!	QJA	Bannvale	05	NO ASBESTOS	Rope gasket to flue access panel	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87424	J008408	-	15/02/2019	
#REF!	QJA	Bannvale	05	NO ASBESTOS	Gasket to pipe flanges to pipe work and oumps	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87425	J008408	-	15/02/2019	
#REF!	QJA	Bannvale	05	NO ASBESTOS	Bboard to front edge of mezzanine floor	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87426	J008408	-	15/02/2019	
#REF!	QJA	Bannvale	05	NO ASBESTOS	Board covering structural roof beam	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87427	J008408	-	15/02/2019	
#REF!	QJA	Bannvale	05	NO ASBESTOS	Dust/debris to floor of mezzanine	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87428	J008408	-	15/02/2019	
#REF!	QJA	Bannvale	05	NO ASBESTOS	Dust/debris to rear of boilers	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87429	J008408	-	15/02/2019	
#REF!	QJA	Bannvale	05	NO ASBESTOS	Dust/debris to raised plinth supportino oumos	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87430	J008408	-	15/02/2019	
#REF!	QJA	Bannvale	05	NO ASBESTOS	Debris to knq wall at RHS of pump plinth	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87431	J008408	-	15/02/2019	
#REF!	QJA	Bannvale	05	Gaskets	Gaskts to oumos throughout	Textiles & Paper	Presumed Asbestos	unsealed	Low	Manage & Affix ID Labels	Re-inspection	HSG227	Unchecked	Medium Risk	9	09/03/2023	Presumed	Medium Risk	87432	-	9299/2 -	06/04/2022	WHS	
#REF!	QHB	Crozier House	01	NO ASBESTOS	Panel to access hatch to roof space	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87433	BA9536	-	29/03/2019	
#REF!	QHB	Crozier House	01	NO ASBESTOS	Panel to side of access hatch to roof soace	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87434	BA9536	-	29/03/2019	
#REF!	QHB	Crozier House	01	NO ASBESTOS	Felt to original flat roof throughout	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87435	BA9536	-	29/03/2019	
#REF!	QHB	Crozier House	01	NO ASBESTOS	Loose board to roof space	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87436	BA9536	-	29/03/2019	
#REF!	QHB	Crozier House	01	NO ASBESTOS	Loose board to roof space	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87437	BA9536	-	29/03/2019	
#REF!	QHB	Crozier House	01	NO ASBESTOS	Board to access hatch adjacent to bedroom 10	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87438	BA9536	-	29/03/2019	
#REF!	QHB	Crozier House	01	NO ASBESTOS	DPC above emergency door adjacent to bedroom 10	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87439	BA9536	-	29/03/2019	
#REF!	QHB	Crozier House	01	NO ASBESTOS	Board to access hatch adjacent to bedroom 1	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87440	BA9536	-	29/03/2019	
#REF!	QHB	Crozier House	01	NO ASBESTOS	Loose board to roof space above corridor adiacent bedroom 1	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87441	BA9536	-	29/03/2019	
#REF!	QHB	Crozier House	01	NO ASBESTOS	Board to access hatch at emergency door adiacent bedroom	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87442	BA9536	-	29/03/2019	

#REF!	QHB	Crozier House	01	NO ASBESTOS	Sarking felt to penetration above emergency door adjacent to	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87443	BA9536		29/03/2019		
#REF!	QHB	Crozier House	01	NO ASBESTOS	Panel to access hatch outside sewing room	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87444	BA9536		29/03/2019		
#REF!	QHB	Crozier House	01	NO ASBESTOS	Panel to access hatch adjacent to dining room	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87445	BA9536		29/03/2019		
#REF!	QHB	Crozier House	01	NO ASBESTOS	Panel to access hatch adjacent to sun room	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87446	BA9536		29/03/2019		
#REF!	QHB	Crozier House	01	NO ASBESTOS	Panel to access hatch adjacent to kitchen	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87447	BA9536		29/03/2019		
#REF!	QHB	Crozier House	01	NO ASBESTOS	Panel to access hatch at emergency door adjacent to staff toilet	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87448	BA9536		29/03/2019		
#REF!	QHB	Crozier House	01	NO ASBESTOS	Panel to access hatch to corridor to bedroom 22	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87449	BA9536		29/03/2019		
#REF!	QHB	Crozier House	01	NO ASBESTOS	Loose board to roof space adjacent to bedroom 22	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87450	BA9536		29/03/2019		
#REF!	QHB	Crozier House	01	NO ASBESTOS	Panel to access hatch adjacent to bedroom 23	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87451	BA9536		29/03/2019		
#REF!	QHB	Crozier House	01	NO ASBESTOS	Panel to access hatch outside kitchen A-062	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87452	BA9536		29/03/2019		
#REF!	QHB	Crozier House	01	NO ASBESTOS	Floor covering throughout	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87453	BA9536		29/03/2019		
#REF!	QHB	Crozier House	01	NO ASBESTOS	Panelling at high level to bulk head	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87454	BA9536		29/03/2019		
#REF!	QHB	Crozier House	01	NO ASBESTOS	Ceiling to drying room	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87455	BA9536		29/03/2019		
#REF!	QHB	Crozier House	01	Floor Tiles	Floor tile to store room	Composite Material	Chrysotile	Composite Material	Low	Manage and monitor	Review – No Change	HSG227	Unchecked	Very Low Risk	3	06/10/2021	Identified	Very Low Risk	87456	BA9536	9811/19	17/12/2019	WH Stephens		
#REF!	QHB	Crozier House	01	Floor Tiles	Floor tile to store	Composite Material	Chrysotile	Composite Material	Low	Manage and monitor	Review – No Change	HSG227	Unchecked	Very Low Risk	3	06/10/2021	Identified	Very Low Risk	87457	BA9536	9811/19	17/12/2019	WH Stephens		
#REF!	QHB	Crozier House	01	Floor Tiles	Floor tile to electrical switch room	Composite Material	Chrysotile	Composite Material	Low	Manage and monitor	Review – No Change	HSG227	Unchecked	Very Low Risk	3	06/10/2021	Identified	Very Low Risk	87458	BA9536	9811/19	17/12/2019	WH Stephens		
#REF!	QHB	Crozier House	01	NO ASBESTOS	Panel to access hatch	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87459	BA9536		29/03/2019		
#REF!	QHB	Crozier House	01	NO ASBESTOS	Panel to access hatch	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87460	BA9536		29/03/2019		
#REF!	QHB	Crozier House	01	Door Panel	Panels to door leading to A-073	Insulating Board	Amosite	[illegible]	Low	Remove if likely to be disturbed	Review – No Change	HSG227	Unchecked	Low Risk	6	06/10/2021	Identified	Low Risk	87461	BA9536	9811/19	17/12/2019	WH Stephens		
#REF!	QHB	Crozier House	01	Door Panel	Panel to door to dinnig room A-084	Insulating Board	Amosite	Several Asbestos Insulation	Low	Remove if likely to be disturbed	Review – No Change	HSG227	Unchecked	Low Risk	6	06/10/2021	Identified	Low Risk	87462	BA9536	9811/19	17/12/2019	WH Stephens		
#REF!	QHB	Crozier House	01	NO ASBESTOS	Panel to access hatch to dining room	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87463	BA9536		29/03/2019		
#REF!	QHB	Crozier House	01	Floor Tiles	Floor tile to store room on dining	Composite Material	Chrysotile	Composite Material	Low	Manage and monitor	Review – No Change	HSG227	Unchecked	Very Low Risk	3	06/10/2021	Identified	Very Low Risk	87464	BA9536	9811/19	17/12/2019	WH Stephens		
#REF!	QHB	Crozier House	01	Sink Pad	Bitumen panel to stainless steel servicing trolley	Composite Material	Chrysotile	Composite Material	Low	Manage and monitor	Review – No Change	HSG227	Unchecked	Very Low Risk	3	06/10/2021	Identified	Very Low Risk	87465	BA9536	9811/19	17/12/2019	WH Stephens		
#REF!	QHB	Crozier House	01	NO ASBESTOS	Panel to access hatch within kitchen	NO ASBESTOS	NO ASBESTOS				No further action required (Asbestos removed)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87466	BA9536		29/03/2019		
#REF!	QHB	Crozier House	01	NO ASBESTOS	Seal to oven door	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87467	BA9536		29/03/2019		
#REF!	QHB	Crozier House	01	Toilet Cistern	Toilet cistern	Composite Material	Amosite	Composite Material	Low	Manage and monitor	Review – No Change	HSG227	Unchecked	Very Low Risk	4	06/10/2021	Identified	Very Low Risk	87468	BA9536	9811/19	17/12/2019	WH Stephens		
#REF!	QHB	Crozier House	01	NO ASBESTOS	Sink pad to sluice room	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87469	BA9536		29/03/2019		
#REF!	QHB	Crozier House	01	Toilet Cistern	Toilet cistern to maintenance store	Composite Material	Amosite	Composite Material	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Very Low Risk	4	06/10/2021	Identified	Very Low Risk	87470	BA9536	9811/19	17/12/2019	WH Stephens		
#REF!	RAE	Drumglass Site	02	NO ASBESTOS	Sarking felt	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87472	J009005		08/03/2019		
#REF!	RAE	Drumglass Site	02	NO ASBESTOS	Loft insulation	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87473	J009005		08/03/2019		
#REF!	RAE	Drumglass Site	02	NO ASBESTOS	Cavity insulation	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87474	J009005		08/03/2019		
#REF!	RAE	Drumglass Site	02	NO ASBESTOS	Visible DPC	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87475	J009005		08/03/2019		
#REF!	RAE	Drumglass Site	02	NO ASBESTOS	Dust and debris to upper side of ceiling below	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87476	J009005		08/03/2019		
#REF!	RAE	Drumglass Site	02	NO ASBESTOS	Pipe insulation	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87477	J009005		08/03/2019		
#REF!	RAE	Drumglass Site	02	NO ASBESTOS	Ceiling material	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87478	J009005		08/03/2019		
#REF!	RAE	Drumglass Site	02	NO ASBESTOS	Verge cloak	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87479	J009005		08/03/2019		
#REF!	QPA	Eden SEC	02	Debris	Debris to top of electrical equipment within	Insulating Board	Amosite	Unsealed Asbestos Insulation Board	Loose asbestos debris or residue	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	Medium Risk	9	13/03/2023	Identified	Medium Risk	87480	BA9533	9299/22	11/04/2022	WHS		
#REF!	QPA	Eden SEC	02	Packing Material	Packer to ceiling grid frame within electrical cupboard	Insulating Board	Amosite	Unsealed Asbestos Insulation Board	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Medium Risk	7	13/03/2023	Identified	Medium Risk	87481	BA9533	9299/22	11/04/2022	WHS		
#REF!	QPA	Eden SEC	02	NO ASBESTOS	Debris to floor of electrical cupboard	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87482	BA9533		27/03/2019		
#REF!	QPA	Eden SEC	02	NO ASBESTOS	Debris to ceiling tile to lobby area	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87483	BA9533		27/03/2019		
#REF!	QPA	Eden SEC	02	NO ASBESTOS	Strawboard to upper ceiling along corridor	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87484	BA9533		27/03/2019		
#REF!	QPA	Eden SEC	02	NO ASBESTOS	Debris to ceiling tile to arts store room	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87485	BA9533		27/03/2019		
#REF!	SHC	Slieve Roe	01	NO ASBESTOS	Debris inside switchgear	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87486	BA9565		17/04/2019		
#REF!	SHC	Slieve Roe	01	NO ASBESTOS	Debris inside switchgear	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87487	BA9565		17/04/2019		
#REF!	SHC	Slieve Roe	01	NO ASBESTOS	Debris to top of switchgear	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87488	BA9565		17/04/2019		
#REF!	SHC	Slieve Roe	01	NO ASBESTOS	Debris to top of switchgear	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87489	BA9565		17/04/2019		
#REF!	SHC	Slieve Roe	01	NO ASBESTOS	Debris to top of switchgear	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87490	BA9565		17/04/2019		
#REF!	SHC	Slieve Roe	01	NO ASBESTOS	Debris to top of switchgear	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87491	BA9565		17/04/2019		
#REF!	SHC	Slieve Roe	01	NO ASBESTOS	Debris to floor	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87492	BA9565		17/04/2019		
#REF!	SHC	Slieve Roe	01	NO ASBESTOS	Debris to floor	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87493	BA9565		17/04/2019		
#REF!	SHC	Slieve Roe	01	NO ASBESTOS	Debris to frame of generator	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87494	BA9565		17/04/2019		
#REF!	SHC	Slieve Roe	01	NO ASBESTOS	Debris to frame of generator	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87495	BA9565		17/04/2019		
#REF!	SHC	Slieve Roe	01	NO ASBESTOS	Debris to top of generator	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87496	BA9565		17/04/2019		
#REF!	SHC	Slieve Roe	01	NO ASBESTOS	Debris to top of generator	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87497	BA9565		17/04/2019		
#REF!	SHC	Slieve Roe	01	NO ASBESTOS	Residue to pipework	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87498	BA9565		17/04/2019		
#REF!	SHC	Slieve Roe	01	NO ASBESTOS	Residue to wall	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87499	BA9565		17/04/2019		
#REF!	SHC	Slieve Roe	01	NO ASBESTOS	Debris to floor	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87500	BA9565		17/04/2019		
#REF!	SHC	Slieve Roe	01	Flash Guard	Flashboard to switchbox	Textiles & Paper	Chrysotile	unsealed	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Medium Risk	7	12/03/2023	Identified	Medium Risk	87501	BA9565	9300/22	30/08/2022	WHS		
#REF!	SHC	Slieve Roe	01	NO ASBESTOS	debris to floor	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87502	BA9565		17/04/2019		
#REF!	SAA	Daisy Hill Hospital Estate	04	Paper	Paper to fuse carrier	Textiles & Paper	Chrysotile	Enclosed Paper Backing	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Low Risk	5	14/09/2023	Identified	Low Risk	87503	BA9551	9300/22	22/04/2022	WHS		
#REF!	SAA	Daisy Hill Hospital Estate	04	NO ASBESTOS	Blanking plate to fuse carrier	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87504	BA9551		09/04/2019		
#REF!	SAA	Daisy Hill Hospital Estate	04	Paper	Paper to fuse carrier	Textiles & Paper	Chrysotile	Enclosed Paper Backing	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Low Risk	5	14/09/2023	Identified	Low Risk	87505	BA9551	9300/22	22/04/2022	WHS		
#REF!	SAA	Daisy Hill Hospital Estate	04	NO ASBESTOS	Debris inside switchgear	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87506	BA9551		09/04/2019		
#REF!	SAA	Daisy Hill Hospital Estate	04	NO ASBESTOS	Debris to top of switchgear	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87507	BA9551		09/04/2019		
#REF!	SAA	Daisy Hill Hospital Estate	04	NO ASBESTOS	Debris to top of switchgear	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87508	BA9551		09/04/2019		
#REF!	SAA	Daisy Hill Hospital Estate	04	Loose Asbestos	Debris below switchgear	Loose Asbestos	Chrysotile	Loose Asbestos Debris	Loose asbestos debris or residue	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	High Risk	10	14/12/2022	Identified	High Risk	87509	BA9551	9300/22	22/04/2022	WHS		
#REF!	SAA	Daisy Hill Hospital Estate	04	NO ASBESTOS	Debris below switchgear	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87510	BA9551		09/04/2019		
#REF!	SAA	Daisy Hill Hospital Estate	04	NO ASBESTOS	Debris below switchgear	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87511	BA9551		09/04/2019		
#REF!	SAA	Daisy Hill Hospital Estate	04	Paper	Paper to fuse carrier	Textiles & Paper	Chrysotile	Enclosed Paper Backing	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Low Risk	5	14/09/2023	Identified	Low Risk	87512	BA9552	9300/22	22/04/2022	WHS		
#REF!	SAA	Daisy Hill Hospital Estate	04	Paper	Paper to fuse carrier	Textiles & Paper	Chrysotile	Enclosed Paper Backing	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Low Risk	5	14/09/2023	Identified	Low Risk	87513	BA9552	9300/22	22/04/2022	WHS		
#REF!	SAA	Daisy Hill Hospital Estate	04	NO ASBESTOS	Blanking plate to fuse carrier	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87514	BA9552		09/04/2019		
#REF!	SAA	Daisy Hill Hospital Estate	04	Loose Asbestos	Debris inside switchgear	Loose Asbestos	Chrysotile	Loose Asbestos Debris	Loose asbestos debris or residue	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	High Risk	10	14/12/2022	Identified	High Risk	87515	BA9552	9300/22	22/04/2022	WHS		
#REF!	SAA	Daisy Hill Hospital Estate	04	NO ASBESTOS	Debris inside switchgear	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87516	BA9552		09/04/2019		
#REF!	SAA	Daisy Hill Hospital Estate	04	NO ASBESTOS	Fuse carrier	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87517	BA9552		09/04/2019		
#REF!	SAA	Daisy Hill Hospital Estate	04	NO ASBESTOS	Backing plate	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87518	BA9552		09/04/2019		
#REF!	QHA	Moylinn House	01	NO ASBESTOS	Residue to wall 1	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87519	BA9596		25/04/2019		
#REF!	QHA	Moylinn House	01	NO ASBESTOS	Residue to wall 1	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87520	BA9596		25/04/2019		
#REF!	QHA	Moylinn House	01	NO ASBESTOS	Residue to corner to wall 1 + 2	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87521	BA9596		25/04/2019		
#REF!	QHA	Moylinn House	01	NO ASBESTOS	Residue to wall 2	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87522	BA9596		25/04/2019		
#REF!	QHA	Moylinn House	01	NO ASBESTOS	Residue to corner of walls 2 + 3	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87523	BA9596		25/04/2019		

#REF!	QHA	Moylinn House	01	NO ASBESTOS	Residue to wall 3	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87524	BA9596		25/04/2019	
#REF!	QHA	Moylinn House	01	NO ASBESTOS	Residue to wall 4	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87525	BA9596		25/04/2019	
#REF!	QHA	Moylinn House	01	NO ASBESTOS	Lagging to calorifier Nr 1	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87526	BA9596		24/04/2019	
#REF!	QHA	Moylinn House	01	NO ASBESTOS	Lagging to calorifier Nr 2	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87527	BA9596		24/04/2019	
#REF!	QHA	Moylinn House	01	NO ASBESTOS	Residue to ceiling	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87528	BA9596		25/04/2019	
#REF!	QHA	Moylinn House	01	NO ASBESTOS	Debris to floor	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87529	BA9596		25/04/2019	
#REF!	QHA	Moylinn House	01	Rope Seal	Rope to generator exhaust	Textiles & Paper	Chrysotile	Unsealed Rope	Medium	Manage and monitor		Re-inspection	HSG227	Unchecked	Medium Risk	7	14/04/2023	Identified	Medium Risk	87530	BA9596	9/29/22	29/09/2022	WHS
#REF!	QHA	Moylinn House	01	NO ASBESTOS	Floor covering	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87531	BA9596		25/04/2019	
#REF!	QHA	Moylinn House	01	NO ASBESTOS	Staircase floor covering	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87532	BA9596		25/04/2019	
#REF!	OHA	Moylinn House	01	Stair Nosino	Stair nosino	Composite Material	Chrysotile	Composite Material	Low	Manage and monitor		Re-inspection	HSG227	Unchecked	Very Low Risk	3	13/10/2023	Identified	Very Low Risk	87533	BA9596	9/29/22	29/09/2022	WHS
#REF!	QHA	Moylinn House	01	Sink Pad	Sink pad	Composite Material	Chrysotile	Composite Material	Low	Manage and monitor		Re-inspection	HSG227	Unchecked	Very Low Risk	3	13/10/2023	Identified		87534	BA9596	9/29/22	29/09/2022	WHS
#REF!	QHA	Moylinn House	01	NO ASBESTOS	Floor covering to cupboard	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87535	BA9596		25/04/2019	
#REF!	QHA	Moylinn House	01	NO ASBESTOS	Blue floor covering	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87536	BA9596		25/04/2019	
#REF!	OHA	Moylinn House	01	NO ASBESTOS	Floor coverino to Utility room	NO ASBESTOS	NO ASBESTOS				No action required	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87537	BA9596		25/04/2019	
#REF!	QHA	Moylinn House	01	NO ASBESTOS	Floor covering to Store room	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87538	BA9596		25/04/2019	
#REF!	QHA	Moylinn House	01	NO ASBESTOS	Floor covering to Store	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87539	BA9596		25/04/2019	
#REF!	QHA	Moylinn House	01	NO ASBESTOS	Panels to electrical cupboard	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87540	BA9596		25/04/2019	
#REF!	QHA	Moylinn House	01	NO ASBESTOS	Panel to access hatch	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87541	BA9596		25/04/2019	
#REF!	QHA	Moylinn House	01	NO ASBESTOS	Panel to access hatch to roof space	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87542	BA9596		25/04/2019	
#REF!	QHA	Moylinn House	01	NO ASBESTOS	Sink pad	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87543	BA9596		25/04/2019	
#REF!	QHA	Moylinn House	01	NO ASBESTOS	Sink pad to Kitchen	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87544	BA9596		25/04/2019	
#REF!	QHA	Moylinn House	01	NO ASBESTOS	Floor covering to toilet	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87545	BA9596		25/04/2019	
#REF!	QHA	Moylinn House	01	NO ASBESTOS	Floor covering	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87546	BA9596		25/04/2019	
#REF!	QHA	Moylinn House	01	NO ASBESTOS	Floor covering	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87547	BA9596		25/04/2019	
#REF!	QHA	Moylinn House	01	NO ASBESTOS	Sink pad	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87548	BA9596		25/04/2019	
#REF!	QHA	Moylinn House	01	NO ASBESTOS	Floor covering	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87549	BA9596		25/04/2019	
#REF!	QHA	Moylinn House	01	NO ASBESTOS	Bitumen adhesive	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87550	BA9596		25/04/2019	
#REF!	QHA	Moylinn House	01	NO ASBESTOS	Floor covering	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87551	BA9596		25/04/2019	
#REF!	QHA	Moylinn House	01	NO ASBESTOS	Stair nosing	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87552	BA9596		25/04/2019	
#REF!	QHA	Moylinn House	01	NO ASBESTOS	Concealed floor covering	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87553	BA9596		25/04/2019	
#REF!	QHA	Moylinn House	01	NO ASBESTOS	Floor covering	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87554	BA9596		25/04/2019	
#REF!	QHA	Moylinn House	01	NO ASBESTOS	Floor covering	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87555	BA9596		25/04/2019	
#REF!	QHA	Moylinn House	01	NO ASBESTOS	Toilet cistern	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87556	BA9596		25/04/2019	
#REF!	QHA	Moylinn House	01	NO ASBESTOS	Floor covering	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87557	BA9596		25/04/2019	
#REF!	QHA	Moylinn House	01	NO ASBESTOS	Bitumen adhesive	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87558	BA9596		25/04/2019	
#REF!	QHA	Moylinn House	01	NO ASBESTOS	Concealed bitumen adhesive	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87559	BA9596		25/04/2019	
#REF!	QHA	Moylinn House	01	NO ASBESTOS	Floor covering	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87560	BA9596		25/04/2019	
#REF!	QHA	Moylinn House	01	NO ASBESTOS	Floor covering	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87561	BA9596		25/04/2019	
#REF!	QHA	Moylinn House	01	NO ASBESTOS	Sink pad	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87562	BA9596		25/04/2019	
#REF!	OHA	Moylinn House	01	Verose Cloak	Verose undercloak	Cement Products	Chrysotile	Cement Sheets	Low	Manage and monitor		Re-inspection	HSG227	Unchecked	Very Low Risk	4	13/10/2023	Identified	Very Low Risk	87563	BA9596	9/29/22	29/09/2022	WHS
#REF!	QHA	Moylinn House	01	NO ASBESTOS	Felt roof covering	NO ASBESTOS	NO ASBESTOS			No action required		New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87564	BA9596		25/04/2019	
#REF!	QHA	Moylinn House	03	NO ASBESTOS	Lino beneath carpet	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87565	BA9596		21/01/2020	WH Stephens
#REF!	QHA	Moylinn House	03	NO ASBESTOS	Bitumen beneath carpet	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87566	BA9596		21/01/2020	WH Stephens
#REF!	QHA	Moylinn House	03	NO ASBESTOS	Roof felt to void above QHA-03-A-007	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87567	BA9596		21/01/2020	WH Stephens
#REF!	QHA	Moylinn House	01	NO ASBESTOS	Vinyl sheet - Upper layer	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87568	BA9596		25/04/2019	
#REF!	QHA	Moylinn House	01	NO ASBESTOS	Vinyl sheet - Lower layer	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87569	BA9596		25/04/2019	
#REF!	QHA	Moylinn House	01	NO ASBESTOS	Vinyl sheet - Upper layer	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87570	BA9596		25/04/2019	
#REF!	QHA	Moylinn House	01	NO ASBESTOS	Vinyl sheet - Lower layer	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87571	BA9596		25/04/2019	
#REF!	QHA	Moylinn House	01									New Incident	HSG227	Checked	High Risk	0			High Risk	87572				
#REF!	OHA	Moylinn House	01									New Incident	HSG227	Checked	Hioh Risk	0			Hioh Risk	87573			25/04/2019	
#REF!	OHA	Moylinn House	01									New Incident	HSG227	Checked	Hioh Risk	0			Hioh Risk	87574			25/04/2019	
#REF!	QHA	Moylinn House	01									New Incident	HSG227	Checked	High Risk	0			High Risk	87575			25/04/2019	
#REF!	OHA	Moylinn House	01									New Incident	HSG227	Checked	Hioh Risk	0			Hioh Risk	87576			25/04/2019	
#REF!	QHA	Moylinn House	01									New Incident	HSG227	Checked	High Risk	0			High Risk	87577			25/04/2019	
#REF!	QHA	Moylinn House	03									Review – No Change	HSG227	Checked	High Risk	0			High Risk	87578			21/01/2020	WH Stephens
#REF!	OHA	Moylinn House	03									Review – No Change	HSG227	Checked	Hioh Risk	0			Hioh Risk	87579			21/01/2020	WH Stephens
#REF!	QHA	Moylinn House	03									Review – No Change	HSG227	Checked	High Risk	0			High Risk	87580			21/01/2020	WH Stephens
#REF!	QHA	Moylinn House	03									Review – No Change	HSG227	Checked	High Risk	0			High Risk	87581			21/01/2020	WH Stephens
#REF!	OHA	Moylinn House	03									Review – No Change	HSG227	Checked	Hioh Risk	0			Hioh Risk	87582			21/01/2020	WH Stephens
#REF!	QHA	Moylinn House	03									Review – No Change	HSG227	Checked	High Risk	0			High Risk	87583			21/01/2020	WH Stephens
#REF!	OHA	Moylinn House	03									Review – No Change	HSG227	Checked	Hioh Risk	0			Hioh Risk	87584			21/01/2020	WH Stephens
#REF!	OHA	Moylinn House	03									Review – No Change	HSG227	Checked	Hioh Risk	0			Hioh Risk	87585			21/01/2020	WH Stephens
#REF!	OHA	Moylinn House	03									Review – No Change	HSG227	Checked	Hioh Risk	0			Hioh Risk	87586			21/01/2020	WH Stephens
#REF!	QAC	Lurgan Hospital	02	NO ASBESTOS	Debris to floor	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87587	BA9541		03/04/2019	
#REF!	QAC	Lurgan Hospital	02	NO ASBESTOS	Debris to floor	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87588	BA9541		03/04/2019	
#REF!	QAC	Lurgan Hospital	02	NO ASBESTOS	Debris to floor	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87589	BA9541		03/04/2019	
#REF!	QAC	Lurgan Hospital	02	NO ASBESTOS	Debris to floor	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87590	BA9541		03/04/2019	
#REF!	QAC	Lurgan Hospital	02	NO ASBESTOS	Debris to floor	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87591	BA9541		03/04/2019	
#REF!	QAC	Lurgan Hospital	02	NO ASBESTOS	Debris to floor	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87592	BA9541		03/04/2019	
#REF!	QAC	Lurgan Hospital	02	NO ASBESTOS	Debris to floor	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87593	BA9541		03/04/2019	
#REF!	QAC	Lurgan Hospital	02	NO ASBESTOS	Debris to floor	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87594	BA9541		03/04/2019	
#REF!	QAC	Lurgan Hospital	02	NO ASBESTOS	Debris to floor	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87595	BA9541		03/04/2019	
#REF!	QAC	Lurgan Hospital	02	NO ASBESTOS	Debris to floor	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87596	BA9541		03/04/2019	
#REF!	QAC	Lurgan Hospital	02	NO ASBESTOS	Debris to floor	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87597	BA9541		03/04/2019	
#REF!	QAC	Lurgan Hospital	02	NO ASBESTOS	Debris to floor	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87598	BA9541		03/04/2019	
#REF!	QAC	Lurgan Hospital	02	NO ASBESTOS	Debris to floor	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87599	BA9541		03/04/2019	
#REF!	QAC	Lurgan Hospital	02	NO ASBESTOS	Debris to floor	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87600	BA9541		03/04/2019	
#REF!	QAC	Lurgan Hospital	02	NO ASBESTOS	Debris to floor	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87601	BA9541		03/04/2019	
#REF!	QAC	Lurgan Hospital	02	Loose Asbestos	Debris to floor	Loose Asbestos		Loose Asbestos Debris	Loose asbestos debris or residue	No further action required (Asbestos removed)		Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	26/12/2022	Identified	Asbestos Removed	87602	BA9541	9/29/22	12/09/2022	WHS
#REF!	QAC	Lurgan Hospital	02	Loose Asbestos	Debris to floor	Loose Asbestos		Loose Asbestos Debris	Loose asbestos	Remove (Controlled Conditions)		Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	26/12/2022	Identified	Asbestos Removed	87603	BA9541	9/29/22	12/09/2022	WHS
#REF!	QAC	Lurgan Hospital	02	Loose Asbestos	Debris to floor	Loose Asbestos		Loose Asbestos Debris	Loose asbestos	Remove (Controlled Conditions)		Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	26/12/2022	Identified	Asbestos Removed	87604	BA9541	9/29/22	12/09/2022	WHS
#REF!	QAC	Lurgan Hospital	02	Loose Asbestos	Debris to floor	Loose Asbestos		Loose Asbestos Debris	Loose asbestos debris or residue	No further action required (Asbestos removed)		Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	26/12/2022	Identified	Asbestos Removed	87605	BA9541	9/29/22	12/09/2022	WHS
#REF!	QAC	Lurgan Hospital	02	Loose Asbestos	Debris to floor	Loose Asbestos		Loose Asbestos Debris	Loose asbestos debris or residue	No further action required (Asbestos removed)		Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	26/12/2022	Identified	Asbestos Removed	87606	BA9541	9/29/22	12/09/2022	WHS
#REF!	QAC	Lurgan Hospital	02	Loose Asbestos	Debris to floor	Loose Asbestos		Loose Asbestos Debris	Loose asbestos debris or residue	No further action required (Asbestos removed)		Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	20/12/2022	Identified	Asbestos Removed	87607	BA541	9/29/22	12/09/2022	WHS

#REF!	QAC	Lurgan Hospital	02	Loose Asbestos	Debris to floor	Loose Asbestos		Loose Asbestos Debris	Loose asbestos debris or residue	No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	26/12/2022	Identified	Asbestos Removed	87608	BA9541	9299/22	12/09/2022	WHS
#REF!	QAC	Lurgan Hospital	02	NO ASBESTOS	Debris to floor	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87609	BA9541		03/04/2019	
#REF!	QAC	Lurgan Hospital	02	Loose Asbestos	Debris to floor	Loose Asbestos		Loose Asbestos Debris	Loose asbestos debris or residue	No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	26/12/2022	Identified	Asbestos Removed	87610	BA9541	9299/22	12/09/2022	WHS
#REF!	QAC	Lurgan Hospital	02	NO ASBESTOS	Debris to floor	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87611	BA9541		03/04/2019	
#REF!	QAC	Lurgan Hospital	02	NO ASBESTOS	Debris to floor adjacent to lift plant room	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87612	BA9541		03/04/2019	
#REF!	QAC	Lurgan Hospital	02	Loose Asbestos	Debris to floor adjacent to lift plant room	Loose Asbestos		Loose Asbestos Debris	Loose asbestos debris or residue	No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	26/12/2022	Identified	Asbestos Removed	87613	BA9541	9299/22	12/09/2022	WHS
#REF!	QAC	Lurgan Hospital	02	Loose Asbestos	Debris to floor	Loose Asbestos		Loose Asbestos Debris	Loose asbestos debris or residue	No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	26/12/2022	Identified	Asbestos Removed	87614	BA9541	9299/22	12/09/2022	WHS
#REF!	QAC	Lurgan Hospital	02	Loose Asbestos	Debris to floor	Loose Asbestos		Loose Asbestos Debris	Loose asbestos debris or residue	No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	26/12/2022	Identified	Asbestos Removed	87615	BA9541	9299/22	12/09/2022	WHS
#REF!	QAC	Lurgan Hospital	02	Loose Asbestos	Debris to floor adjacent to water tank	Loose Asbestos		Loose Asbestos Debris	Loose asbestos debris or residue	No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	26/12/2022	Identified	Asbestos Removed	87616	BA9541	9299/22	12/09/2022	WHS
#REF!	QAC	Lurgan Hospital	02	Loose Asbestos	Debris to floor	Loose Asbestos		Loose Asbestos Debris	Loose asbestos debris or residue	No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	26/12/2022	Identified	Asbestos Removed	87617	BA9541	9299/22	12/09/2022	WHS
#REF!	QAC	Lurgan Hospital	02	Loose Asbestos	Debris to floor opposite water tank	Loose Asbestos		Loose Asbestos Debris	Loose asbestos debris or residue	No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	26/12/2022	Identified	Asbestos Removed	87618	BA9541	9299/22	12/09/2022	WHS
#REF!	QAC	Lurgan Hospital	02	NO ASBESTOS	Lift brake pads	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87619	BA9541		03/04/2019	
#REF!	QAC	Lurgan Hospital	02	Ceiling Board	Ceiling to lift plant room	Insulating Board		Unsealed Asbestos Insulation Board	Low	No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	28/03/2023	Identified	Asbestos Removed	87620	BA9541	9299/22	12/09/2022	WHS
#REF!	QAC	Lurgan Hospital	02	Wall Panels	Wall panel to lift plant room	Insulating Board		unsealed	Low	No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	28/03/2023	Identified	Asbestos Removed	87621	BA9541	9299/22	12/09/2022	WHS
#REF!	QAC	Lurgan Hospital	02	Loose Asbestos	Debris to floor adjacent to lift plant room	Loose Asbestos		Loose Asbestos Debris	Loose asbestos debris or residue	No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	26/12/2022	Identified	Asbestos Removed	87622	BA9541	9299/22	12/09/2022	WHS
#REF!	QAC	Lurgan Hospital	02	Loose Asbestos	Residue to vertical wooden beam	Loose Asbestos		Loose Asbestos Debris	Loose asbestos debris or residue	No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	26/12/2022	Identified	Asbestos Removed	87623	BA9541	9299/22	12/09/2022	WHS
#REF!	QAC	Lurgan Hospital	02	Loose Asbestos	Residue to vertical wooden beam	Loose Asbestos		Loose Asbestos Debris	Loose asbestos debris or residue	No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	26/12/2022	Identified	Asbestos Removed	87624	BA9541	9299/22	12/09/2022	WHS
#REF!	QAC	Lurgan Hospital	02	Loose Asbestos	Residue to vertical wooden beam	Loose Asbestos		Loose Asbestos Debris	Loose asbestos debris or residue	No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	26/12/2022	Identified	Asbestos Removed	87625	BA9541	9299/22	12/09/2022	WHS
#REF!	QAC	Lurgan Hospital	02	Loose Asbestos	Residue to vertical wooden beam	Loose Asbestos		Loose Asbestos Debris	Loose asbestos debris or residue	No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	26/12/2022	Identified	Asbestos Removed	87626	BA9541	9299/22	12/09/2022	WHS
#REF!	QAC	Lurgan Hospital	02	Loose Asbestos	Residue to vertical wooden beam	Loose Asbestos		Loose Asbestos Debris	Loose asbestos debris or residue	No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	26/09/2023	Identified	Asbestos Removed	87627	BA9541	9299/22	12/09/2022	WHS
#REF!	QAC	Lurgan Hospital	02	Loose Asbestos	Residue to vertical wooden beam	Loose Asbestos		Loose Asbestos Debris	Loose asbestos debris or residue	No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	26/12/2022	Identified	Asbestos Removed	87628	BA9541	9299/22	12/09/2022	WHS
#REF!	QAC	Lurgan Hospital	02	Loose Asbestos	Residue to vertical wooden beam	Loose Asbestos		Loose Asbestos Debris	Loose asbestos debris or residue	No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	26/12/2022	Identified	Asbestos Removed	87629	BA9541	9299/22	12/09/2022	WHS
#REF!	QAC	Lurgan Hospital	02	Loose Asbestos	Debris to floor	Loose Asbestos		Loose Asbestos Debris	Loose asbestos debris or residue	No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	26/12/2022	Identified	Asbestos Removed	87630	BA9541	9299/22	12/09/2022	WHS
#REF!	QAC	Lurgan Hospital	02	Loose Asbestos	Residue to vertical wooden beam	Loose Asbestos		Loose Asbestos Debris	Loose asbestos debris or residue	No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	26/12/2022	Identified	Asbestos Removed	87631	BA9541	9299/22	12/09/2022	WHS
#REF!	QAC	Lurgan Hospital	02	NO ASBESTOS	Residue to redundant pipe work	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87632	BA9541		03/04/2019	
#REF!	QAC	Lurgan Hospital	02	Loose Asbestos	Residue to vertical wooden beam	Loose Asbestos		Loose Asbestos Debris	Loose asbestos debris or residue	No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	26/12/2022	Identified	Asbestos Removed	87633	BA9541	9299/22	15/09/2022	WHS
#REF!	QAC	Lurgan Hospital	02	Loose Asbestos	Debris to floor	Loose Asbestos		Loose Asbestos Debris	Loose asbestos debris or residue	No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	26/12/2022	Identified	Asbestos Removed	87634	BA9541	9299/22	12/09/2022	WHS
#REF!	QAC	Lurgan Hospital	02	Loose Asbestos	Debris to floor	Loose Asbestos		Loose Asbestos Debris	Loose asbestos debris or residue	No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	26/12/2022	Identified	Asbestos Removed	87635	BA9541	9299/22	12/09/2022	WHS
#REF!	QAC	Lurgan Hospital	02	Loose Asbestos	Residue to vertical wooden beam	Loose Asbestos		Loose Asbestos Debris	Loose asbestos debris or residue	No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	26/12/2022	Identified	Asbestos Removed	87636	BA9541	9299/22	12/09/2022	WHS
#REF!	QAC	Lurgan Hospital	02	Loose Asbestos	Debris to floor	Loose Asbestos		Loose Asbestos Debris	Loose asbestos debris or residue	No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	26/12/2022	Identified	Asbestos Removed	87637	BA9541	9299/22	12/09/2022	WHS
#REF!	QAC	Lurgan Hospital	02	Loose Asbestos	Debris to floor	Loose Asbestos		Loose Asbestos Debris	Loose asbestos debris or residue	No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	26/12/2022	Identified	Asbestos Removed	87638	BA9541	9299/22	12/09/2022	WHS
#REF!	QAC	Lurgan Hospital	02	Loose Asbestos	Residue to vertical wooden beam	Loose Asbestos		Loose Asbestos Debris	Loose asbestos debris or residue	No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	26/12/2022	Identified	Asbestos Removed	87639	BA9541	9299/22	12/09/2022	WHS
#REF!	QAC	Lurgan Hospital	02	Loose Asbestos	Debris to floor	Loose Asbestos		Loose Asbestos Debris	Loose asbestos debris or residue	No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	26/12/2022	Identified	Asbestos Removed	87640	BA9541	9299/22	12/09/2022	WHS
#REF!	QAC	Lurgan Hospital	02	Loose Asbestos	Debris to floor	Loose Asbestos		Loose Asbestos Debris	Loose asbestos debris or residue	Remove (Controlled Conditions)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	26/12/2022	Identified	Asbestos Removed	87641	BA9541	9541/1	12/09/2022	WHS
#REF!	QAC	Lurgan Hospital	02	Loose Asbestos	Residue to vertical wooden beam	Loose Asbestos		Loose Asbestos Debris	Loose asbestos debris or residue	No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	26/12/2022	Identified	Asbestos Removed	87642	BA9541	9299/22	12/09/2022	WHS
#REF!	QAC	Lurgan Hospital	02	Loose Asbestos	Residue to vertical wooden beam	Loose Asbestos		Loose Asbestos Debris	Loose asbestos debris or residue	No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	26/12/2022	Identified	Asbestos Removed	87643	BA9541	9299/22	15/09/2022	WHS
#REF!	QAC	Lurgan Hospital	02	Loose Asbestos	Residue to vertical wooden beam	Loose Asbestos		Loose Asbestos Debris	Loose asbestos debris or residue	No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	26/12/2022	Identified	Asbestos Removed	87644	BA9541	9299/22	15/09/2022	WHS
#REF!	QAC	Lurgan Hospital	02	Loose Asbestos	Residue to vertical wooden beam	Loose Asbestos		Loose Asbestos Debris	Loose asbestos debris or residue	No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	26/12/2022	Identified	Asbestos Removed	87645	BA9541	9299/22	12/09/2022	WHS
#REF!	QAC	Lurgan Hospital	02	Loose Asbestos	Residue to vertical wooden beam	Loose Asbestos		Loose Asbestos Debris	Loose asbestos debris or residue	No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	26/12/2022	Identified	Asbestos Removed	87646	BA9541	9299/22	15/09/2022	WHS
#REF!	QAC	Lurgan Hospital	02	Loose Asbestos	Residue to vertical wooden beam	Loose Asbestos		Loose Asbestos Debris	Loose asbestos debris or residue	No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	26/12/2022	Identified	Asbestos Removed	87647	BA9541	9299/22	12/09/2022	WHS
#REF!	QAC	Lurgan Hospital	02	Loose Asbestos	Residue to vertical wooden beam	Loose Asbestos		Loose Asbestos Debris	Loose asbestos debris or residue	No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	26/12/2022	Identified	Asbestos Removed	87648	BA9541	9299/22	12/09/2022	WHS
#REF!	QAC	Lurgan Hospital	02	Loose Asbestos	Residue to vertical wooden beam	Loose Asbestos		Loose Asbestos Debris	Loose asbestos debris or residue	No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	26/12/2022	Identified	Asbestos Removed	87649	BA9541	9299/22	12/09/2022	WHS
#REF!	QAA	Craigavon Hospital	01	Bitumen Adhesive	Bitumen behind polystyrene to wall 1 at top of ladder	Composite Material	Chrysotile	Composite Material	Low	Manage and monitor	New Incident	HSG227	Unchecked	Very Low Risk	3	14/06/2020	Identified	Very Low Risk	87738	BA6698		12/06/2019	
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Bitumen to timber to wall 1 at top of ladder	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87739	BA6698		12/06/2019	
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Seal to small redundant water tank - over ladder	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87740	BA6698		12/06/2019	
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Gasket to flange in front of water tank 1 (LHS)	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87741	BA6698		12/06/2019	
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Rope to top of pipework in front of water tank 1 (LHS)	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87742	BA6698		12/06/2019	
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Gasket to flange in front of water tank 1 (RHS)	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87743	BA6698		12/06/2019	
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Bitumen wall covering to top of ladder	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87744	BA6698		12/06/2019	
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Debris to pit behind ladder	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87745	BA6698		12/06/2019	
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Hairfelt below floor covering to pit behind ladder	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87746	BA6698		12/06/2019	
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Debris to ledge beside ladder	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87747	BA6698		12/06/2019	
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Insulation to high level air vent trunking	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87748	BA6698		14/06/2019	
#REF!	QAA	Craigavon Hospital	01	Seal	Sealant to water tank 1	Composite Material	Chrysotile	Composite Material	Low	Remove	New Incident	HSG227	Unchecked	Very Low Risk	3	14/06/2020	Identified	Very Low Risk	87749	BA6698		12/06/2019	
#REF!	QAA	Craigavon Hospital	01	Seal	Sealant to water tank 1	Composite Material	Chrysotile	Composite Material	Low	Remove	New Incident	HSG227	Unchecked	Very Low Risk	3	14/06/2020	Identified	Very Low Risk	87750	BA6698		12/06/2019	
#REF!	QAA	Craigavon Hospital	01	Bitumen Adhesive	Bitumen behind steel beam to wall 2	Composite Material	Chrysotile	Composite Material	Low	Remove	New Incident	HSG227	Unchecked	Very Low Risk	3	14/06/2020	Identified	Very Low Risk	87751	BA6698		12/06/2019	
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Splashed bitumen to timber to wall 2	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87752	BA6698		12/06/2019	
#REF!	QAA	Craigavon Hospital	01	Seal	Sealant to water tank 1	Composite Material	Chrysotile	Composite Material	Low	Remove	New Incident	HSG227	Unchecked	Very Low Risk	3	14/06/2020	Identified	Very Low Risk	87753	BA6698		12/06/2019	
#REF!	QAA	Craigavon Hospital	01	Seal	Sealant to water tank 1	Composite Material	Chrysotile	Composite Material	Low	Remove	New Incident	HSG227	Unchecked	Very Low Risk	3	14/06/2020	Identified	Very Low Risk	87754	BA6698		12/06/2019	
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Bitumen to plinth below water tank 1	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87755	BA6698		12/06/2019	
#REF!	QAA	Craigavon Hospital	01	Seal	Sealant around bolt to water tank 1	Composite Material	Chrysotile	Composite Material	Low	Remove	New Incident	HSG227	Unchecked	Very Low Risk	3	14/06/2020	Identified	Very Low Risk	87756	BA6698		12/06/2019	
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Redundant gasket to top of water tank 1	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87757	BA6698		12/06/2019	
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Bitumen wall and floor covering throughout	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87758	BA6698		12/06/2019	
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Snot to wall at eye-level to wall 3 - bottom of steps	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87759	BA6698		12/06/2019	
#REF!	QAA	Craigavon Hospital	01	Seal	Sealant to water tank 1	Composite Material	Chrysotile	Composite Material	Low	Remove	New Incident	HSG227	Unchecked	Very Low Risk	3	14/06/2020	Identified	Very Low Risk	87760	BA6698		12/06/2019	
#REF!	QAA	Craigavon Hospital	01	Seal	Sealant to water tank 1	Composite Material	Chrysotile	Composite Material	Low	Remove	New Incident	HSG227	Unchecked	Very Low Risk	3	14/06/2020	Identified	Very Low Risk	87761	BA6698		12/06/2019	
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Gasket to rear of water tank 1	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87762	BA6698		12/06/2019	
#REF!	QAA	Craigavon Hospital	01	Seal	Sealant to water tank 1	Composite Material	Chrysotile	Composite Material	Low	Remove	New Incident	HSG227	Unchecked	Very Low Risk	3	14/06/2020	Identified	Very Low Risk	87763	BA6698		12/06/2019	
#REF!	QAA	Craigavon Hospital	01	Seal	Sealant to water tank 1	Composite Material	Chrysotile	Composite Material	Low	Remove	New Incident	HSG227	Unchecked	Very Low Risk	3	14/06/2020	Identified	Very Low Risk	87764	BA6698		12/06/2019	
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Gasket to flange to water tank 1	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87765	BA6698		12/06/2019	
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Bitumen to plinths below water tank 2	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87766	BA6698		12/06/2019	
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Gasket to flange to water tank 2	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87767	BA6698		12/06/2019	
#REF!	QAA	Craigavon Hospital	01	Seal	Sealant to water tank 2	Composite Material	Chrysotile	Composite Material	Low	Remove	New Incident	HSG227	Unchecked	Very Low Risk	3	14/06/2020	Identified	Very Low Risk	87768	BA6698		12/06/2019	
#REF!	QAA	Craigavon Hospital	01	Seal	Sealant to water tank 2	Composite Material	Chrysotile	Composite Material	Low	Remove	New Incident	HSG227	Unchecked	Very Low Risk	3	14/06/2020	Identified	Very Low Risk	87769	BA6698		12/06/2019	
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Mastic to end of second plinth at water tank 2	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87770	BA6698		12/06/2019	
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Gasket to flange to top of water tank 2	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87771	BA6698		12/06/2019	
#REF!	QAA	Craigavon Hospital	01	Seal	Sealant to water tank 2	Composite Material	Chrysotile	Composite Material	Low	Remove	New Incident	HSG227	Unchecked	Very Low Risk	3	14/06/2020	Identified	Very Low Risk	87772	BA6698		12/06/2019	
#REF!	QAA	Craigavon Hospital	01	Seal	Sealant to bolt to water tank 2	Composite Material	Chrysotile	Composite Material	Low	Remove	New Incident	HSG227	Unchecked	Very Low Risk	3	14/06/2020	Identified	Very Low Risk	87773	BA6698		12/06/2019	
#REF!	QAA	Craigavon Hospital	01	Seal	Sealant to water tank 2	Composite Material	Chrysotile	Composite Material	Low	Remove	New Incident	HSG227	Unchecked	Very Low Risk	3	14/06/2020	Identified	Very Low Risk	87774	BA6698		12/06/2019	
#REF!	QAA	Craigavon Hospital	01	Seal	Sealant to tank 2	Composite Material	Chrysotile	Composite Material	Low	Remove	New Incident	HSG227	Unchecked	Very Low Risk	3	17/06/2020	Identified	Very Low Risk	87775	BA6698		12/06/2019	
#REF!	QAA	Craigavon Hospital	01	Seal	Sealant to tank 2	Composite Material	Chrysotile	Composite Material	Low	Remove	New Incident	HSG227	Unchecked	Very Low Risk	3	17/06/2020	Identified	Very Low Risk	87776	BA6698		12/06/2019	
#REF!	QAA	Craigavon Hospital	01	Seal	Sealant to water tank 2	Composite Material	Chrysotile	Composite Material	Low	Remove	New Incident	HSG227	Unchecked	Very Low Risk	3	17/06/2020	Identified	Very Low Risk	87777	BA6698		12/06/2019	

#REF!	QAA	Craigavon Hospital	01	Seal	Sealant to water tank 2	Composite Material	Chrysotile	Composite Material	Low	Remove	New Incident	HSG227	Unchecked	Very Low Risk	3	17/06/2020	Identified	Very Low Risk	87778	BA0698		12/06/2019		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Mastic seal to small patch repair to top of water tank 2	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87779	BA0698		12/06/2019		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Snot to wall 5 at mid- level	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87780	BA0698		12/06/2019		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Bitumen to trunking above electrical switch near to wall 5	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87781	BA0698		12/06/2019		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Rope seal to end of vent trunking	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87782	BA0698		12/06/2019		
#REF!	QAA	Craigavon Hospital	01	Damp Proof Course	DPC at high level around skylight [illegible]	Composite Material	Chrysotile	Composite Material	Low	Manage and monitor	New Incident	HSG227	Unchecked	Very Low Risk	3	17/06/2020	Identified	Very Low Risk	87783	BA0698		12/06/2019		
#REF!	QAA	Craigavon Hospital	01	Bitumen Felt	[illegible]	Composite Material	Chrysotile	Composite Material	Low	Manage and monitor	New Incident	HSG227	Unchecked	Very Low Risk	3	17/06/2020	Identified	Very Low Risk	87784	BA0698		12/06/2019		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Sealant around skylight	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87785	BA0698		12/06/2019		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Bitumen seal to vent trunking to wall 3	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87786	BA0698		12/06/2019		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Bitumen packer to door frame	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87787	BA0698		12/06/2019		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Debris to floor	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87788	BA0698		12/06/2019		
#REF!	OAA	Craigavon Hospital	01	Loose Asbestos	Debris to floor	Loose Asbestos	Chrysotile	Loose Asbestos Debris	[illegible]	Remove (Controlled Conditions)	New Incident	HSG227	Unchecked	High Risk	10	16/09/2019	Identified	High Risk	87789	BA0698		12/06/2019		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Debris to floor	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87790	BA0698		12/06/2019		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Debris to floor	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87791	BA0698		12/06/2019		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Debris to floor	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87792	BA0698		12/06/2019		
#REF!	RAA	South Tyrone Hospital	01	NO ASBESTOS	Floor screed beneath carpet	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87793	BA0682		05/06/2019		
#REF!	RAA	South Tyrone Hospital	01	NO ASBESTOS	Floor screed beneath carpet	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87794	BA0682		05/06/2019		
#REF!	RAA	South Tyrone Hospital	01	NO ASBESTOS	Floor screed	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87795	BA0682		05/06/2019		
#REF!	RAA	South Tyrone Hospital	01	NO ASBESTOS	Pipe penetration at low level	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87796	BA0682		05/06/2019		
#REF!	RAA	South Tyrone Hospital	01	NO ASBESTOS	Floor covering to toilet	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87797	BA0682		05/06/2019		
#REF!	RAA	South Tyrone Hospital	01	NO ASBESTOS	Floor covering	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87798	BA0682		05/06/2019		
#REF!	RAA	South Tyrone Hospital	01	NO ASBESTOS	Sink pad to kitchen	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87799	BA0682		05/06/2019		
#REF!	RAA	South Tyrone Hospital	01	Stair Nosing	Stair nosing	Composite Material	Chrysotile	Composite Material	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Very Low Risk	3	15/12/2023	Identified	Very Low Risk	87800	BA0682	[illegible]	15/12/2022	WHS	
#REF!	RAA	South Tyrone Hospital	01	Floor Tiles	Floor tile to kitchen	Composite Material	Chrysotile	Composite Material	Medium	Manage and monitor	New Incident	HSG227	Unchecked	Very Low Risk	4	17/06/2020	Identified	Very Low Risk	87801	BA0682		05/06/2019		
#REF!	RAA	South Tyrone Hospital	01	NO ASBESTOS	Sink pad to kitchen	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87802	BA0682		05/06/2019		
#REF!	RAA	South Tyrone Hospital	01	Floor Tiles	Floor tile to bathroom	Composite Material	Chrysotile	Composite Material	Medium	Manage and monitor	Re-inspection	HSG227	Unchecked	Very Low Risk	4	15/12/2023	Identified	Very Low Risk	87803	BA0682	[illegible]	15/12/2022	WHS	
#REF!	RAA	South Tyrone Hospital	01	Floor Tiles	Floor tile to bathroom	Composite Material	Chrysotile	Composite Material	Medium	Manage and monitor	Re-inspection	HSG227	Unchecked	Very Low Risk	4	15/12/2023	Identified	Very Low Risk	87804	BA0682	[illegible]	15/12/2022	WHS	
#REF!	RAA	South Tyrone Hospital	01	Floor Tiles	Floor tile to toilet	Composite Material	Chrysotile	Composite Material	Medium	Manage and monitor	Re-inspection	HSG227	Unchecked	Very Low Risk	4	15/12/2023	Identified	Very Low Risk	87805	BA0682	[illegible]	15/12/2022	WHS	
#REF!	RAA	South Tyrone Hospital	01	NO ASBESTOS	Floor screed beneath carpet	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87806	BA0682		05/06/2019		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Board to top of riser	NO ASBESTOS	NO ASBESTOS			No further action required (Asbestos removed)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87851	BA0699		12/06/2019		
#REF!	QAA	Craigavon Hospital	01		N/A						Error Entry	HSG227	Unchecked		0				87852					
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Bitumen wall and floor covering throughout	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87853	BA0699		12/06/2019		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Redundant grinder disk	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87854	BA0699		12/06/2019		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Debris to floor at wall 1	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87855	BA0699		12/06/2019		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Seal to pipe junction at high level	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87856	BA0699		12/06/2019		
#REF!	QAA	Craigavon Hospital	01	Gaskets	[illegible]	Composite Material	Chrysotile	Composite Material	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Very Low Risk	3	29/09/2023	Identified	Very Low Risk	87857	BA0699	[illegible]	29/09/2022	WHS	
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Lining around pipe penetration at high level	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87858	BA0699		12/06/2019		
#REF!	QAA	Craigavon Hospital	01	seal	Seal to tank 1	Composite Material	Chrysotile	Composite Material	Medium	Remove	Re-inspection	HSG227	Unchecked	Very Low Risk	4	29/09/2023	Identified	Very Low Risk	87859	BA0699	[illegible]	29/09/2022	WHS	
#REF!	QAA	Craigavon Hospital	01	Seal	Seal to tank 1	Composite Material	Chrysotile	Composite Material	Medium	Remove	Re-inspection	HSG227	Unchecked	Very Low Risk	4	29/09/2023	Identified	Very Low Risk	87860	BA0699	[illegible]	29/09/2022	WHS	
#REF!	QAA	Craigavon Hospital	01	Seal	Seal to tank 1	Composite Material	Chrysotile	Composite Material	Medium	Remove	Re-inspection	HSG227	Unchecked	Very Low Risk	4	29/09/2023	Identified	Very Low Risk	87861	BA0699	[illegible]	29/09/2022	WHS	
#REF!	QAA	Craigavon Hospital	01	Seal	Seal to tank 1	Composite Material	Chrysotile	Composite Material	Medium	Remove	Re-inspection	HSG227	Unchecked	Very Low Risk	4	10/07/2020	Identified	Very Low Risk	87862	BA0699	[illegible]	12/06/2019	WHS	
#REF!	QAA	Craigavon Hospital	01	Seal	Seal to tank 1	Composite Material	Chrysotile	Composite Material	Medium	Remove	Re-inspection	HSG227	Unchecked	Very Low Risk	4	29/09/2023	Identified	Very Low Risk	87863	BA0699	[illegible]	29/09/2022	WHS	
#REF!	QAA	Craigavon Hospital	01	Seal	Seal to tank 1	Composite Material	Chrysotile	Composite Material	Medium	remove	Re-inspection	HSG227	Unchecked	Very Low Risk	4	29/09/2023	Identified	Very Low Risk	87864	BA0699	[illegible]	29/09/2022	WHS	
#REF!	QAA	Craigavon Hospital	01	Seal	Seal to tank 1	Composite Material	Chrysotile	Composite Material	Medium	Remove	Re-inspection	HSG227	Unchecked	Very Low Risk	4	29/09/2023	Identified	Very Low Risk	87865	BA0699	[illegible]	29/09/2022	WHS	
#REF!	OAA	Craigavon Hospital	01	Seal	Seal to tank 1	Composite Material	Chrysotile	Composite Material	Medium	Remove	Re-inspection	HSG227	Unchecked	Very Low Risk	4	29/09/2023	Identified	Very Low Risk	87866	BA0699	[illegible]	29/09/2022	WHS	
#REF!	QAA	Craigavon Hospital	01	Seal	Seal to tank 2	Composite Material	Chrysotile	Composite Material	Medium	Remove	Re-inspection	HSG227	Unchecked	Very Low Risk	4	29/09/2023	Identified	Very Low Risk	87867	BA0699	[illegible]	29/09/2022	WHS	
#REF!	QAA	Craigavon Hospital	01	Seal	Seal to tank 2	Composite Material	Chrysotile	Composite Material	Medium	Remove	Re-inspection	HSG227	Unchecked	Very Low Risk	4	29/09/2023	Identified	Very Low Risk	87868	BA0699	[illegible]	29/09/2022	WHS	
#REF!	OAA	Craigavon Hospital	01	Seal	Seal to tank 2	Composite Material	Chrysotile	Composite Material	Medium	Remove	Re-inspection	HSG227	Unchecked	Very Low Risk	4	29/09/2023	Identified	Very Low Risk	87869	BA0699	[illegible]	29/09/2022	WHS	
#REF!	QAA	Craigavon Hospital	01	Seal	Seal to tank 2	Composite Material	Chrysotile	Composite Material	Medium	Remove	Re-inspection	HSG227	Unchecked	Very Low Risk	4	29/09/2024	Identified	Very Low Risk	87870	BA0699	[illegible]	29/09/2022	WHS	
#REF!	QAA	Craigavon Hospital	01	Seal	Seal to tank 2	Composite Material	Chrysotile	Composite Material	Medium	Remove	Re-inspection	HSG227	Unchecked	Very Low Risk	4	29/09/2023	Identified	Very Low Risk	87871	BA0699	[illegible]	29/09/2022	WHS	
#REF!	QAA	Craigavon Hospital	01	Seal	Seal to tank 2	Composite Material	Chrysotile	Composite Material	Medium	Remove	Re-inspection	HSG227	Unchecked	Very Low Risk	4	29/09/2023	Identified	Very Low Risk	87872	BA0699	[illegible]	29/09/2022	WHS	
#REF!	QAA	Craigavon Hospital	01	Seal	Seal to tank 2	Composite Material	Chrysotile	Composite Material	Medium	Remove	Re-inspection	HSG227	Unchecked	Very Low Risk	4	29/09/2023	Identified	Very Low Risk	87873	BA0699	[illegible]	29/09/2022	WHS	
#REF!	QAA	Craigavon Hospital	01	Seal	Seal to tank 2	Composite Material	Chrysotile	Composite Material	Medium	Remove	Re-inspection	HSG227	Unchecked	Very Low Risk	4	29/09/2023	Identified	Very Low Risk	87874	BA0699	[illegible]	29/09/2022	WHS	
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Gasket to flange at rear of tank 1 - low level	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87875	BA0699		12/06/2019		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Gasket to flange at front of tank 1 - low level	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87876	BA0699		12/06/2019		
#REF!	QAA	Craigavon Hospital	01	cloth	Cloth lining to pipe bracket in front of tank 2	Textiles & Paper	Chrysotile	unsealed	Medium	remove	Re-inspection	HSG227	Unchecked	Medium Risk	8	09/01/2020	Identified	Medium Risk	87877	BA0699	9302.22	12/06/2019	WHS	
#REF!	QAA	Craigavon Hospital	01	cloth	Cloth to redundant bracket in front of tank 2	Textiles & Paper	Chrysotile	unsealed	Medium	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	Medium Risk	8	29/09/2023	Identified	Medium Risk	87878	BA0699	9302.22	29/09/2022	WHS	
#REF!	QAA	Craigavon Hospital	01	cloth	Cloth to bracket above walkway in front of tank 2	Textiles & Paper	Chrysotile	unsealed	Medium	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	Medium Risk	8	29/09/2023	Identified	Medium Risk	87879	BA0699	9302.22	29/09/2022	WHS	
#REF!	QAA	Craigavon Hospital	01	Gaskets	[illegible]	Composite Material	Chrysotile	Composite Material	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Very Low Risk	3	29/09/2023	Identified	Very Low Risk	87880	BA0699	[illegible]	29/09/2022	WHS	
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Debris to floor	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87881	BA0699		12/06/2019		
#REF!	NAB	St.Lukes	32	NO ASBESTOS	Gasket to front of boiler	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87882	BA0641		14/05/2019		
#REF!	NAB	St.Lukes	32	NO ASBESTOS	Residue to wall 1 RHS of door	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87883	BA0641		14/05/2019		
#REF!	NAB	St.Lukes	32	NO ASBESTOS	Residue to wall 2 to rear of boiler	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87884	BA0641		14/05/2019		
#REF!	NAB	St.Lukes	32	NO ASBESTOS	Residue to wall 3	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87885	BA0641		14/05/2019		
#REF!	NAB	St.Lukes	32	NO ASBESTOS	Residue to wall 4	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87886	BA0641		14/05/2019		
#REF!	NAB	St.Lukes	32	NO ASBESTOS	Debris to floor	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87887	BA0641		14/05/2019		
#REF!	NAB	St.Lukes	32	NO ASBESTOS	Felt to roof	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87888	BA0641		14/05/2019		
#REF!	RJK	Oaklands-Victoria Grove	01	NO ASBESTOS	Board beneath CWST tank to roof soace	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87889	BA0549		09/04/2019		
#REF!	RJK	Oaklands-Victoria Grove	01	NO ASBESTOS	Board beneath CWST tank to roof soace	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87890	BA0549		09/04/2019		
#REF!	RJK	Oaklands-Victoria Grove	01	NO ASBESTOS	Gasket to burner to boiler at side of house	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87891	BA0549		09/04/2019		
#REF!	RAB	Longstone/Mullinure	39	NO ASBESTOS	Gasket to burner front of boiler	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87892	BA0640		14/05/2019		
#REF!	RAB	Longstone/Mullinure	39	NO ASBESTOS	Debris to front of boiler	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87893	BA0640		14/05/2019		
#REF!	RAB	Longstone/Mullinure	39	NO ASBESTOS	Sealant to flue pipe to rear of boiler	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87894	BA0640		14/05/2019		
#REF!	RAB	Longstone/Mullinure	39	NO ASBESTOS	Rope seal to access hatch to flue pipe to rear of boiler	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87895	BA0640		14/05/2019		
#REF!	RAB	Longstone/Mullinure	39	Rope Seal	Rope seal to flue penetration through wall at high level	Textiles & Paper	Chrysotile	Unsealed Rope	Medium	Manage and monitor	Re-inspection	HSG227	Unchecked	Medium Risk	7	25/03/2021	Identified	Medium Risk	87896	BA0640	9811/19	27/11/2019	WHS	
#REF!	RAB	Longstone/Mullinure	39	NO ASBESTOS	Debris to floor	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87897	BA0640		14/05/2019		
#REF!	SBA	John Mitchel Place	01	NO ASBESTOS	Lagging to upper of two pipes at high level	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87898	BA0664		29/05/2019		
#REF!	SBA	John Mitchel Place	01	NO ASBESTOS	Lagging to lower of two pipes at high level	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87899	BA0664		29/05/2019		
#REF!	SBA	John Mitchel Place	01	NO ASBESTOS	Lagging to pipework at low level	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87900	BA0664		29/05/2019		
#REF!	RHA	Roxborough Site	01	NO ASBESTOS	Soffit outside A-038	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87901	BA0663		29/05/2019		
#REF!	RHA	Roxborough Site	01	NO ASBESTOS	Soffit outside A-038	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87902	BA0663		29/05/2019		
#REF!	RHA	Roxborough Site	01	NO ASBESTOS	Soffit debris outside A-038	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87903	BA0663		29/05/2019		
#REF!	RHA	Roxborough Site	01	NO ASBESTOS	Soffit outside A-072	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87904	BA0663		29/05/2019		
#REF!	NAB	St.Lukes	16	NO ASBESTOS	Debris to cable tray at compartment wall in roofsoace	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87905	BA0823		03/09/2019		
#REF!	NAB	St.Lukes	16	NO ASBESTOS	Inner lining - RHS heating pipe	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87906	BA0692		10/06/2019		
#REF!	NAB	St.Lukes	16	NO ASBESTOS	Outer lining to heating pipe	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87907	BA0692		10/06/2019		

#REF!	NAB	St.Lukes	16	NO ASBESTOS	Debris lagging to floor	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87908	BA9692		10/06/2019	
#REF!	NAB	St.Lukes	16	NO ASBESTOS	Inner LHS heating	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87909	BA9692		10/06/2019	
#REF!	NAB	St.Lukes	13	NO ASBESTOS	Debris to cill	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87910	BA9694		10/06/2019	
#REF!	NAB	St.Lukes	13	NO ASBESTOS	Debris to top of lower sash	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87911	BA9694		10/06/2019	
#REF!	NAB	St.Lukes	13	NO ASBESTOS	Debris to top of lower sash	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87912	BA9694		10/06/2019	
#REF!	NAB	St.Lukes	13	NO ASBESTOS	Debris to top of fridge	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87913	BA9694		10/06/2019	
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Textured coating at HL between CT room and control room	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87914	BA9748		16/07/2019	
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Textured coating at HL between CT room and chanaina room 2	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87915	BA9748		16/07/2019	
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Vinyl floor covering to CT scanner room	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87916	BA9748		16/07/2019	
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Vinyl floor covering to changing room 2	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87917	BA9748		16/07/2019	
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Wall panels at high level between chanaina rooms 1 & 2	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87918	BA9748		16/07/2019	
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Debris to ceiling tiles in changing room 1	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87919	BA9748		16/07/2019	
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Skirting trim to changing room 1	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87920	BA9748		16/07/2019	
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Debris to ceiling tile to control room	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87921	BA9748		16/07/2019	
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Vinyl floor covering	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to 4	No Asbestos Detected	87922	BA9748		16/07/2019	
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Vinyl floor covering	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Strongly Presumed Similar to 3	No Asbestos Detected	87923	BA9748		16/07/2019	
#REF!	SAA	Daisy Hill Hospital Estate	09	NO ASBESTOS	Brake pad to lift machinery	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87933	BA9763		25/07/2019	
#REF!	SAA	Daisy Hill Hospital Estate	09	NO ASBESTOS	Debris to cable tray adjacent to lift plant room	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87934	BA9763		25/07/2019	
#REF!	SAA	Daisy Hill Hospital Estate	09	Fuse Flash Guards	Electrical Equipment	Textiles & Paper	Presumed Asbestos	Unsealed	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Medium Risk	9	12/04/2023	Presumed	Medium Risk	87935	[illegible]		20/04/2022	WHS	
#REF!	SAA	Daisy Hill Hospital Estate	09	NO ASBESTOS	Debris to floor of lift plant room	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87936	BA9763		25/07/2019		
#REF!	SAA	Daisy Hill Hospital Estate	09	Panel	Panel to access hatch to lift plant room	Cement Products	Chrysotile	Unsealed Cement	Significant areas of damage or	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	Low Risk	6	12/10/2023	Identified	Medium Risk	87937	BA9763	9309/22	20/04/2022	WHS	
#REF!	SAA	Daisy Hill Hospital Estate	09	NO ASBESTOS	Debris to door sill	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87938	BA9763		25/07/2019		
#REF!	SAA	Daisy Hill Hospital Estate	09	NO ASBESTOS	Debris to door frame between level 2 & 3	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87939	BA9763		25/07/2019		
#REF!	SAA	Daisy Hill Hospital Estate	09	NO ASBESTOS	Debris to counterweight	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87940	BA9763		25/07/2019		
#REF!	SAA	Daisy Hill Hospital Estate	09	NO ASBESTOS	Debris to ledge	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87941	BA9763		25/07/2019		
#REF!	SAA	Daisy Hill Hospital Estate	09	Panel	Panel to access hatch outside lift	Insulating Board	Amosite/Chrysotile	[illegible]	Low	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	Medium Risk	7	12/10/2023	Identified	Medium Risk	87942	BA9763	[illegible]	20/04/2022	WHS	
#REF!	SAA	Daisy Hill Hospital Estate	09	NO ASBESTOS	Floor covering to lift car	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87943	BA9763		25/07/2019		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Floor covering to lift car	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87944	BA9766		25/06/2019		
#REF!	QAA	Craigavon Hospital	01	Fuse Flash Guards	Electrical equipment	Textiles & Paper	Presumed Asbestos	unsealed	Low	Manage and monitor	New Incident	HSG227	Unchecked	Medium Risk	9	29/01/2020	Presumed	Medium Risk	87945			25/06/2019		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Debris to floor of lift plant room	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87946	BA9766		25/06/2019		
#REF!	QAA	Craigavon Hospital	01	Gaskets	[illegible] gasket to water tank	Composite Material	Chrysotile	Composite Material	Medium	remove	Re-inspection	HSG227	Unchecked	Very Low Risk	4	30/06/2023	Identified	Very Low Risk	87947	BA9766	[illegible]	30/06/2022	WHS	
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Debris to door sill level 4	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87948	BA9766		25/06/2019		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Debris to guide bracket	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87949	BA9766		28/07/2019		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Debris to door sill level 3	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87950	BA9766		25/06/2019		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Debris to guide bracket level 3	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87951	BA9766		25/06/2019		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Debris to counterweight	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87952	BA9766		25/06/2019		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Debris to guide bracket level 2	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87953	BA9766		25/06/2019		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Debris to door sill level 1	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87954	BA9766		25/06/2019		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Debris to door frame between levels 1 and ground	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87955	BA9766		25/06/2019		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Debris to ledge level 1	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87956	BA9766		25/06/2019		
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Panel to redundant lift selector	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87957	BA9764		25/07/2019		
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Debris to lift machinery frame	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87958	BA9764		25/07/2019		
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Debris to lift plant frame	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87959	BA9764		25/07/2019		
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Debris to bracket	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87960	BA9764		25/07/2019		
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Debris to door frame	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87961	BA9764		25/07/2019		
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Debris to sill	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87962	BA9764		25/07/2019		
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Debris to sill	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87963	BA9764		25/07/2019		
#REF!	SAA	Daisy Hill Hospital Estate	01	Fuse Flash Guards	Electrical equipment	Textiles & Paper	Presumed Asbestos	unsealed	Low	Conduct annual routine inspections	Re-inspection	HSG227	Unchecked	Medium Risk	9	13/12/2023	Presumed	Medium Risk	87964	[illegible]		26/10/2022	WHS	
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Debris to ground floor door header	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87965	BA9764		25/07/2019		
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Debris to lift car frame	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87966	BA9764		25/07/2019		
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Floor covering to lift car	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87967	BA9764		25/07/2019		
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Wall panel to lift car	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87968	BA9764		25/07/2019		
#REF!	SAA	Daisy Hill Hospital Estate	07	Cement Flat Sheet	Cement sheet to top of brick wall to roof space	Cement Products	Chrysotile	Cement Sheets	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Very Low Risk	4	14/09/2023	Identified	Very Low Risk	87981	BA9792	9309/29	07/09/2022	WHS	
#REF!	SAA	Daisy Hill Hospital Estate	07	NO ASBESTOS	Partition wall between B-004 and B-005	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87982	BA9792		12/08/2019		
#REF!	SAA	Daisy Hill Hospital Estate	07	NO ASBESTOS	Ceiling above suspended ceiling B003/004/005	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87983	BA9792		12/08/2019		
#REF!	SAA	Daisy Hill Hospital Estate	07	NO ASBESTOS	Floor covering to male toilets	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87984	BA9792		12/08/2019		
#REF!	SAA	Daisy Hill Hospital Estate	07	NO ASBESTOS	Floor covering to female toilets	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87985	BA9792		12/08/2019		
#REF!	SAA	Daisy Hill Hospital Estate	07	NO ASBESTOS	Pipe lagging to ceiling void	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87986	BA9792		12/08/2019		
#REF!	SAA	Daisy Hill Hospital Estate	07	Door Panel	Panel to back door to store room under stairs	Insulating Board	Amosite	Unsealed Asbestos Insulation Board	Low	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	Medium Risk	7	14/03/2023	Identified	Medium Risk	87987	BA9792	9309/29	07/09/2022	WHS	
#REF!	SAA	Daisy Hill Hospital Estate	07	NO ASBESTOS	Stair nosings	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87988	BA9792		12/08/2019		
#REF!	SAA	Daisy Hill Hospital Estate	07	NO ASBESTOS	Damaged board to ceiling void	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87989	BA9792		12/08/2019		
#REF!	SAA	Daisy Hill Hospital Estate	07	Panel	Panel to access hatch to roof space	Insulating Board	Amosite	[illegible]	Low	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	Low Risk	6	14/09/2023	Identified	Low Risk	87990	BA9792	[illegible]	07/09/2022	WHS	
#REF!	SAA	Daisy Hill Hospital Estate	07	NO ASBESTOS	Floor covering to kitchen	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87991	BA9792		12/08/2019		
#REF!	SAA	Daisy Hill Hospital Estate	07	NO ASBESTOS	Sink pad to kitchen	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87992	BA9792		12/08/2019		
#REF!	SAA	Daisy Hill Hospital Estate	07	NO ASBESTOS	Ceiling panel to photocopy room	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87993	BA9792		12/08/2019		
#REF!	SAA	Daisy Hill Hospital Estate	07	NO ASBESTOS	Light brown floor covering	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87994	BA9792		12/08/2019		
#REF!	SAA	Daisy Hill Hospital Estate	07	NO ASBESTOS	Dark brown floor covering	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87995	BA9792		12/08/2019		
#REF!	SAA	Daisy Hill Hospital Estate	07	NO ASBESTOS	Debris to floor of boiler house	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	87996	BA9792		12/08/2019		
#REF!	OHB	Crozier House	01	Gaskets	Gasket to pipework valve (Large [illegible]	Composite Material	Chrysotile	Composite Material	Low	Remove	Re-inspection	HSG227	Unchecked	Very Low Risk	3	06/10/2021	Identified	Very Low Risk	87997	BA9805	[illegible]	17/12/2019	WH Stephens	
#REF!	OHB	Crozier House	01	Gaskets	Gasket to pipework valve (Large [illegible]	Composite Material	Chrysotile	Composite Material	Low	Remove	Re-inspection	HSG227	Unchecked	Very Low Risk	3	06/10/2021	Identified	Very Low Risk	87998	BA9805	[illegible]	17/12/2019	WH Stephens	
#REF!	OHB	Crozier House	01	Gaskets	Gasket to pipework valve (Large [illegible]	Composite Material	Chrysotile	Composite Material	Low	Remove	Re-inspection	HSG227	Unchecked	Very Low Risk	3	06/10/2021	Identified	Very Low Risk	87999	BA9805	[illegible]	17/12/2019	WH Stephens	
#REF!	OHB	Crozier House	01	Gaskets	Gasket to pipework valve (Large [illegible]	Composite Material	Chrysotile	Composite Material	Low	Remove	Re-inspection	HSG227	Unchecked	Very Low Risk	3	06/10/2021	Identified	Very Low Risk	88000	BA9805	[illegible]	17/12/2019	WH Stephens	
#REF!	QHB	Crozier House	01	NO ASBESTOS	Gasket to pipework valve (Large section)	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88001	BA9805		28/08/2019		
#REF!	QHB	Crozier House	01	NO ASBESTOS	Gasket to pipework valve (Large section)	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88002	BA9805		28/08/2019		
#REF!	QHB	Crozier House	01	Gaskets	Gasket to pipework valve (Large [illegible]	Composite Material	Chrysotile	Composite Material	Low	Remove	Review – No Change	HSG227	Unchecked	Very Low Risk	3	06/10/2021	Identified	Very Low Risk	88003	BA9805	[illegible]	17/12/2019	WH Stephens	
#REF!	QHB	Crozier House	01	Debris	Debris found at gasket location to pipework valve (Small section)	Thermal Insulation	Amosite	Unsealed	Loose asbestos debris or residue	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	High Risk	11	06/10/2021	Identified	High Risk	88004	BA9805	9811/19	17/12/2019	WH Stephens	
#REF!	QHB	Crozier House	01	NO ASBESTOS	Gasket to pipework valve (Large section)	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88005	BA9805		28/08/2019		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Vinyl sheet to corridor	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88006	BA9801		22/08/2019		

#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Grey vinyl sheet to corridor	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88007	BA6801		22/08/2019			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Wall lining to external cladding	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88008	BA6801		22/08/2019			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Wall lining to external cladding	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88009	BA6801		22/08/2019			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Green vinyl sheet to corridor	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88010	BA6801		22/08/2019			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Vinyl sheet to male toilet	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88011	BA6801		22/08/2019			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Vinyl sheet to female toilets	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88012	BA6801		22/08/2019			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Light grey vinyl sheet to dining room	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88013	BA6801		22/08/2019			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Dark grey vinyl floor sheet to centre of dining room	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88014	BA6801		22/08/2019			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Green vinyl to trolley park	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88015	BA6801		22/08/2019			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Pink vinyl to trolley park	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88016	BA6801		22/08/2019			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Vinyl sheet to floor	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88017	BA6801		22/08/2019			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Blue vinyl floor covering	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88018	BA6801		22/08/2019			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Grey vinyl floor covering	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88019	BA6801		22/08/2019			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Vinyl sheet to B411 & 408	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88020	BA6801		22/08/2019			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Vinyl sheet	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88021	BA6801		22/08/2019			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Vinyl tile (yellow)	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88022	BA6801		22/08/2019			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Vinyl tile (cream 1)	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88023	BA6801		22/08/2019			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Vinyl tile (cream)	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88024	BA6801		22/08/2019			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Vinyl tile (grey)	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88025	BA6801		22/08/2019			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Vinyl tile (cream 2)	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88026	BA6801		22/08/2019			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Vinyl tile (green)	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88027	BA6801		22/08/2019			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Vinyl tile (grey)	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88028	BA6801		22/08/2019			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Lining to pipe duct	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88029	BA6801		22/08/2019			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Wall lining to external cladding	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88030	BA6801		22/08/2019			
#REF!	QAA	Craigavon Hospital	01	Loose Asbestos	Safe	Loose Asbestos	Presumed Asbestos	Loose Asbestos Debris	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	High Risk	10	21/09/2023	Presumed	High Risk	88031		9302/2	21/09/2022	WHS			
#REF!	SHB	Cloughreagh House	01	NO ASBESTOS	Residue to wall 1, 1m from door	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88032	BA6830		05/09/2019			
#REF!	SHB	Cloughreagh House	01	NO ASBESTOS	Residue to wall 1, 2m from door	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88033	BA6830		05/09/2019			
#REF!	SHB	Cloughreagh House	01	NO ASBESTOS	Residue to wall 1, 3m from door	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88034	BA6830		05/09/2019			
#REF!	SHB	Cloughreagh House	01	NO ASBESTOS	Residue to wall 1 at corner of wall 2	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88035	BA6830		05/09/2019			
#REF!	SHB	Cloughreagh House	01	NO ASBESTOS	Residue to wall 2 at corner to wall 1	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88036	BA6830		05/09/2019			
#REF!	SHB	Cloughreagh House	01	NO ASBESTOS	Residue to wall 2 mid wall	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88037	BA6830		05/09/2019			
#REF!	SHB	Cloughreagh House	01	NO ASBESTOS	Residue to wall 2 mid wall	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88038	BA6830		05/09/2019			
#REF!	SHB	Cloughreagh House	01	NO ASBESTOS	Residue to wall 3 left hand side of door	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88039	BA6830		05/09/2019			
#REF!	SHB	Cloughreagh House	01	NO ASBESTOS	Residue to wall 3 above door	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88040	BA6830		05/09/2019			
#REF!	SHB	Cloughreagh House	01	NO ASBESTOS	Residue to wall 3 at electrical panel	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88041	BA6830		05/09/2019			
#REF!	SHB	Cloughreagh House	01	NO ASBESTOS	Residue to wall 3 at corner to wall 4	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88042	BA6830		05/09/2019			
#REF!	SHB	Cloughreagh House	01	NO ASBESTOS	Residue to wall 4 at corner to wall 3	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88043	BA6830		05/09/2019			
#REF!	SHB	Cloughreagh House	01	NO ASBESTOS	Residue to wall 4 above window	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88044	BA6830		05/09/2019			
#REF!	SHB	Cloughreagh House	01	NO ASBESTOS	Residue to wall 4 at corner to wall 1	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88045	BA6830		05/09/2019			
#REF!	SHB	Cloughreagh House	01	Gaskets	1 of 4 gaskets at low levelto rear of 2nr chaiwie boilers	Composite Material	Chrysotile	Composite Material	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Very Low Risk	3	12/09/2023	Identified	Very Low Risk	88046	BA6830	9300/2 2	31/08/2022	WHS		
#REF!	SHB	Cloughreagh House	01	NO ASBESTOS	Gasket to burner to boiler no. 1	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88047	BA6830		05/09/2019			
#REF!	SHB	Cloughreagh House	01	NO ASBESTOS	Gasket to plate to front of boiler no. 1	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88048	BA6830		05/09/2019			
#REF!	SHB	Cloughreagh House	01	NO ASBESTOS	Gasket to burner of boiler no.2	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88049	BA6830		05/09/2019			
#REF!	SHB	Cloughreagh House	01	NO ASBESTOS	Gasket to plate to front of boiler no. 2	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88050	BA6830		05/09/2019			
#REF!	SHB	Cloughreagh House	01	NO ASBESTOS	Gasket to front of ideal boiler	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88051	BA6830		05/09/2019			
#REF!	SHB	Cloughreagh House	01	NO ASBESTOS	Debris to floor of boiler room	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88052	BA6830		05/09/2019			
#REF!	SHB	Cloughreagh House	01	NO ASBESTOS	Debris to floor of boiler room	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88053	BA6830		05/09/2019			
#REF!	SHB	Cloughreagh House	01	Gaskets	Gasket to flange at pumps	Composite Material	Chrysotile	Composite Material	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Very Low Risk	3	12/09/2023	Identified	Very Low Risk	88054	BA6830	9302/2	31/08/2022	WHS		
#REF!	SHB	Cloughreagh House	01		Gasket to flange at pumps	Textiles & Paper	Chrysotile	Composite Material	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Very Low Risk	4	12/09/2023	Identified	Very Low Risk	88055	BA6830	9302/2	31/08/2022	WHS		
#REF!	SHB	Cloughreagh House	01	NO ASBESTOS	Debris to pipe penetration to floor wall 4	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88056	BA6830		05/09/2019			
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Vinyl sheet	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88057	BA6834		09/09/2019			
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Vinyl sheet	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88058	BA6834		09/09/2019			
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Courtyard entrance door, door threshold linino	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88059	BA6834		09/09/2019			
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Courtyard, DPC to courtyard	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88060	BA6834		09/09/2019			
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Courtyard side, DPC to typical window	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88061	BA6834		09/09/2019			
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Courtyard Area, lining behind metal casins to fascia	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88062	BA6834		09/09/2019			
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Courtyard, DPC to cill	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88063	BA6834		09/09/2019			
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Courtyard window, window cavity lining	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88064	BA6834		09/09/2019			
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Bitumen to wooden beam	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88065	BA6834		09/09/2019			
#REF!	RJK	Oaklands-Victoria Grove	01	NO ASBESTOS	Vinyl floor tile from kitchen	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88066	BA6862		13/09/2019			
#REF!	RAA	South Tyrone Hospital	01	NO ASBESTOS	Vinyl sheet	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88067	BA6853		11/09/2019			
#REF!	RAA	South Tyrone Hospital	01	NO ASBESTOS	Sink pad	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88068	BA6853		11/09/2019			
#REF!	RAA	South Tyrone Hospital	01	NO ASBESTOS	Vinyl sheet	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88069	BA6853		11/09/2019			
#REF!	RAA	South Tyrone Hospital	01	NO ASBESTOS	Ceiling tile	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88070	BA6853		11/09/2019			
#REF!	RAA	South Tyrone Hospital	01	NO ASBESTOS	Riser off room B-024 - Debris to floor of riser	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88071	BA6853		11/09/2019			
#REF!	RAA	South Tyrone Hospital	01	Floor Tiles	Vinyl tile	Composite Material	Chrysotile	Composite Material	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Very Low Risk	3	15/12/2023	Identified	Very Low Risk	88072	BA6853	9302/2	15/12/2022	WHS		
#REF!	RAA	South Tyrone Hospital	01	Floor Tiles	Stair nosino	Composite Material	Chrysotile	Composite Material	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Very Low Risk	3	15/12/2023	Identified	Very Low Risk	88073	BA6853	9302/2	15/12/2022	WHS		
#REF!	RAA	South Tyrone Hospital	01	NO ASBESTOS	Vinyl sheet	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88074	BA6853		11/09/2019			
#REF!	RAA	South Tyrone Hospital	01	NO ASBESTOS	Snot to wall beneath light switch	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88075	BA6853		11/09/2019			
#REF!	RAA	South Tyrone Hospital	01	Floor Tiles	Vinvl tile	Composite Material	Chrysotile	Composite Material	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Very Low Risk	3	15/12/2023	Identified	Very Low Risk	88076	BA6853	9302/2	15/12/2022	WHS		
#REF!	RAA	South Tyrone Hospital	01	NO ASBESTOS	Pipe to ceiling	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88077	BA6853		11/09/2019			
#REF!	RAA	South Tyrone Hospital	01	Stair Nosino	Stair nosino	Composite Material	Chrysotile	Composite Material	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Very Low Risk	3	15/12/2023	Identified	Very Low Risk	88078	BA6853	9302/2	15/12/2022	WHS		
#REF!	RAA	South Tyrone Hospital	01	NO ASBESTOS	Vinyl sheet	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88079	BA6853		11/09/2019			
#REF!	RAA	South Tyrone Hospital	01	NO ASBESTOS	Vinyl sheet	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88080	BA6853		11/09/2019			
#REF!	RAA	South Tyrone Hospital	01	NO ASBESTOS	Sink pad	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88081	BA6853		11/09/2019			
#REF!	RAA	South Tyrone Hospital	01	NO ASBESTOS	Sink pad	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88082	BA6853		11/09/2019			

#REFI	RAA	South Tyrone Hospital	01	NO ASBESTOS	Debris to electrical switchgear boxes	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88083	BA9853		11/09/2019		
#REFI	RAA	South Tyrone Hospital	01	NO ASBESTOS	Riser off room B-007 Debris to riser	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88084	BA9853		11/09/2019		
#REFI	RAA	South Tyrone Hospital	01	NO ASBESTOS	Riser off room B-007 - Debris to riser	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88085	BA9853		11/09/2019		
#REFI	RAA	South Tyrone Hospital	01	NO ASBESTOS	Debris to floor	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88086	BA9853		11/09/2019		
#REFI	RAA	South Tyrone Hospital	01	NO ASBESTOS	Lining to ceiling	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88087	BA9853		11/09/2019		
#REFI	RAA	South Tyrone Hospital	01	NO ASBESTOS	Snot to wall 4	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Review of Data	HSG227	Unchecked	NO ASBESTOS	0	15/12/2023	Identified	No Asbestos Detected	88088	BA9853		15/12/2022		
#REFI	RAA	South Tyrone Hospital	01	NO ASBESTOS	Snot to wall 4	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88089	BA9853		11/09/2019		
#REFI	RAA	South Tyrone Hospital	01	Lining Panels	Lining to recestion desk	Insulating Board	Amosite	Unsealed Asbestos Insulation Board	Low	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	Medium Risk	7	15/12/2023	Identified	Medium Risk	88090	BA9853	[illegible]	15/12/2022	WHS		
#REFI	RAA	South Tyrone Hospital	17	Floor Tiles	Floor tile	Composite Material	Chrysotile	Composite Material	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Very Low Risk	3	14/12/2023	Identified	Very Low Risk	88091	BA9854	[illegible]	14/12/2022	WHS		
#REFI	RAA	South Tyrone Hospital	17	NO ASBESTOS	Sink pad	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88092	BA9854		11/09/2019		
#REFI	RAA	South Tyrone Hospital	17	NO ASBESTOS	Vinyl sheet	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88093	BA9854		11/09/2019		
#REFI	RAA	South Tyrone Hospital	17	NO ASBESTOS	Vinyl sheet	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88094	BA9854		11/09/2019		
#REFI	RAA	South Tyrone Hospital	17	NO ASBESTOS	Debris to riser in ladies toilets	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88095	BA9854		11/09/2019		
#REFI	RAA	South Tyrone Hospital	17	NO ASBESTOS	Lining to pipework at ceiling of ladies toilet riser	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88096	BA9854		11/09/2019		
#REFI	RAA	South Tyrone Hospital	17	NO ASBESTOS	Vinyl sheet (ladies toilet)	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88097	BA9854		11/09/2019		
#REFI	RAA	South Tyrone Hospital	17	NO ASBESTOS	Debris to visitor toilet riser duct	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88098	BA9854		11/09/2019		
#REFI	RAA	South Tyrone Hospital	17	NO ASBESTOS	Loose board in visitor toilet riser	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88099	BA9854		11/09/2019		
#REFI	RAA	South Tyrone Hospital	17	NO ASBESTOS	Loose board in visitor toilet riser	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88100	BA9854		11/09/2019		
#REFI	RAA	South Tyrone Hospital	17	Floor Tiles	Vinyl floor tile	Composite Material	Chrysotile	Composite Material	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Very Low Risk	3	14/12/2023	Identified	Very Low Risk	88101	BA9854	[illegible]	14/12/2022	WHS		
#REFI	RAA	South Tyrone Hospital	17	NO ASBESTOS	Vinyl floor tile	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88102	BA9854		11/09/2019		
#REFI	RAA	South Tyrone Hospital	17	NO ASBESTOS	Ceilings throughout - suspended ceiling throughout	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88103	BA9854		11/09/2019		
#REFI	SJC	Millview Resource Centre	01	NO ASBESTOS	Debris to cable tray above electrical panel	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88104	BA9851		11/09/2019		
#REFI	SJC	Millview Resource Centre	01	NO ASBESTOS	Residue to wall 1	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88105	BA9851		11/09/2019		
#REFI	SJC	Millview Resource Centre	01	NO ASBESTOS	Residue to wall 1	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88106	BA9851		11/09/2019		
#REFI	SJC	Millview Resource Centre	01	NO ASBESTOS	Debris to cable tray wall 2	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88107	BA9851		11/09/2019		
#REFI	SJC	Millview Resource Centre	01	NO ASBESTOS	Debris to cable tray wall 3	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88108	BA9851		11/09/2019		
#REFI	SJC	Millview Resource Centre	01	NO ASBESTOS	Panel to access hatch to roof space	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88109	BA9851		11/09/2019		
#REFI	SJC	Millview Resource Centre	01	NO ASBESTOS	Panel around flue pipe within roof space	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88110	BA9851		11/09/2019		
#REFI	SJC	Millview Resource Centre	01	NO ASBESTOS	Debris to roof space	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88111	BA9851		11/09/2019		
#REFI	SJC	Millview Resource Centre	01	NO ASBESTOS	Sarking felt to roof above boiler house	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88112	BA9851		11/09/2019		
#REFI	SJC	Millview Resource Centre	01	NO ASBESTOS	Debris to floor	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88113	BA9851		11/09/2019		
#REFI	SAA	Daisy Hill Hospital Estate	18	NO ASBESTOS	Soffit board to eaves	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88114	BA9811		02/09/2019		
#REFI	SAA	Daisy Hill Hospital Estate	18	NO ASBESTOS	Soffit board to eaves	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88115	BA9811		02/09/2019		
#REFI	SAA	Daisy Hill Hospital Estate	18		Soffit board to eaves						No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked		0				88116					
#REFI	SAA	Daisy Hill Hospital Estate	18	NO ASBESTOS	Ceiling tile to ceiling	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88117	BA9811		02/09/2019		
#REFI	SAA	Daisy Hill Hospital Estate	18	NO ASBESTOS	Ceiling lining to ceiling	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88118	BA9811		02/09/2019		
#REFI	SAA	Daisy Hill Hospital Estate	18	NO ASBESTOS	Acoustic wall lining	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88119	BA9811		02/09/2019		
#REFI	SAA	Daisy Hill Hospital Estate	18	NO ASBESTOS	Floor covering over chipboard	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88120	BA9811		02/09/2019		
#REFI	SAA	Daisy Hill Hospital Estate	18	NO ASBESTOS	Wall linings	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88121	BA9811		02/09/2019		
#REFI	QAA	Craigavon Hospital	08									Error Entry	HSG227	Unchecked		0				88122					
#REFI	QAA	Craigavon Hospital	08	NO ASBESTOS	Lining to back of corridor ceiling	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88123	BA9804		28/09/2019		
#REFI	QAA	Craigavon Hospital	08	NO ASBESTOS	Lining to compartment wall each side of corridor	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88124	BA9804		28/09/2019		
#REFI	SAA	Daisy Hill Hospital Estate	19	NO ASBESTOS	Vinyl sheet	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88125	BA9836		09/09/2019		
#REFI	SAA	Daisy Hill Hospital Estate	19	NO ASBESTOS	Vinyl sheet	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88126	BA9836		09/09/2019		
#REFI	SAA	Daisy Hill Hospital Estate	19	NO ASBESTOS	Vinyl sheet	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88127	BA9836		09/09/2019		
#REFI	SAA	Daisy Hill Hospital Estate	19	NO ASBESTOS	Vinyl sheet	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88128	BA9836		09/09/2019		
#REFI	SAA	Daisy Hill Hospital Estate	19	NO ASBESTOS	Vinyl sheet	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88129	BA9836		09/09/2019		
#REFI	SAA	Daisy Hill Hospital Estate	19	NO ASBESTOS	Vinyl sheet	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88130	BA9836		09/09/2019		
#REFI	SAA	Daisy Hill Hospital Estate	19	Sink Pad	Sink pad	Composite Material	Chrysotile	Composite Material	Low	Re-insect within 12 months	Re-inspection	HSG227	Unchecked	Very Low Risk	3	07/11/2023	Identified	Very Low Risk	88131	BA9836	[illegible]	01/06/2022	WHS		
#REFI	SAA	Daisy Hill Hospital Estate	19	NO ASBESTOS	Lining to external ramp	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88132	BA9836		09/09/2019		
#REFI	SAA	Daisy Hill Hospital Estate	19	NO ASBESTOS	DPC to ramp	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88133	BA9836		09/09/2019		
#REFI	SAA	Daisy Hill Hospital Estate	19	NO ASBESTOS	Ceiling void between A-001 and A-002. firebreak to ceilino void	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88134	BA9836		09/09/2019		
#REFI	SAA	Daisy Hill Hospital Estate	03	NO ASBESTOS	Vinyl sheet	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88135	BA9850		11/09/2019		
#REFI	SAA	Daisy Hill Hospital Estate	03	NO ASBESTOS	Vinyl sheet	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88136	BA9850		11/09/2019		
#REFI	SAA	Daisy Hill Hospital Estate	03	NO ASBESTOS	External front porch soffit to front entrance	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88137	BA9850		11/09/2019		
#REFI	SAA	Daisy Hill Hospital Estate	03	NO ASBESTOS	External side (LHS) door, soffit to side entrance	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88138	BA9850		11/09/2019		
#REFI	SAA	Daisy Hill Hospital Estate	03	NO ASBESTOS	Vinyl sheet	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88139	BA9850		11/09/2019		
#REFI	SAA	Daisy Hill Hospital Estate	03	NO ASBESTOS	External RHS gable verge underlook	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88140	BA9850		11/09/2019		
#REFI	SAA	Daisy Hill Hospital Estate	03	NO ASBESTOS	External lean to roof RHS verge underlook	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88141	BA9850		11/09/2019		
#REFI	SAA	Daisy Hill Hospital Estate	03	NO ASBESTOS	Gable RHS of lean to roof verge underlook	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88142	BA9850		11/09/2019		
#REFI	SAA	Daisy Hill Hospital Estate	03	Soffit	RHS door to switch gear room, door soffit to switchgear	Insulating Board	NO ASBESTOS	Unsealed Asbestos Insulation Board	Medium	No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	26/03/2020	Identified	Asbestos Removed	88143	BA9850		11/09/2019		
#REFI	SAA	Daisy Hill Hospital Estate	03	NO ASBESTOS	A-018 to A-022 Vinyl sheet	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88144	BA9850		11/09/2019		
#REFI	SAA	Daisy Hill Hospital Estate	03	NO ASBESTOS	Sink pad	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88145	BA9850		11/09/2019		
#REFI	SAA	Daisy Hill Hospital Estate	03	NO ASBESTOS	Vinyl sheet	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88146	BA9850		11/09/2019		
#REFI	SAA	Daisy Hill Hospital Estate	03	NO ASBESTOS	B-005 - B-006 Vinyl tile	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88147	BA9850		11/09/2019		
#REFI	SAA	Daisy Hill Hospital Estate	03	NO ASBESTOS	B-005 - B-006 stair nosing	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88148	BA9850		11/09/2019		
#REFI	SAA	Daisy Hill Hospital Estate	03	NO ASBESTOS	Vinyl sheet	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88149	BA9850		11/09/2019		
#REFI	SAA	Daisy Hill Hospital Estate	03	Residue to Walls	Snot to wall 2	Thermal Insulation	NO ASBESTOS	Unsealed	Loose asbestos debris or residue	No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	25/12/2019	Identified	Asbestos Removed	88150	BA9850		11/09/2019			
#REFI	SAA	Daisy Hill Hospital Estate	03	Residue to Walls	High level snot to wall 2	Thermal Insulation	NO ASBESTOS	unsealed	Loose asbestos debris or residue	No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	25/12/2019	Identified	Asbestos Removed	88151	BA9850		11/09/2019			
#REFI	SAA	Daisy Hill Hospital Estate	03	Residue to Walls	high level snot to wall 3	Thermal Insulation	NO ASBESTOS	unsealed	Loose asbestos debris or residue	No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	25/12/2019	Identified	Asbestos Removed	88152	BA9850		11/09/2019			
#REFI	SAA	Daisy Hill Hospital Estate	03	Residue to Walls	High level snot to wall 3	Thermal Insulation	NO ASBESTOS	unsealed	Loose asbestos debris or residue	No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	25/12/2019	Identified	Asbestos Removed	88153	BA9850		11/09/2019			
#REFI	SAA	Daisy Hill Hospital Estate	03	Residue to Walls	High level snot to wall 3	Thermal Insulation	NO ASBESTOS	unsealed	Loose asbestos debris or residue	No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	25/12/2019	Identified	Asbestos Removed	88154	BA9850		11/09/2019			
#REFI	SAA	Daisy Hill Hospital Estate	03	Residue to Walls	High level snot to wall 1	Thermal Insulation	NO ASBESTOS	unsealed	Loose asbestos debris or residue	No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	25/12/2019	Identified	Asbestos Removed	88155	BA9850		11/09/2019			
#REFI	SAA	Daisy Hill Hospital Estate	03	Residue to Walls	High level snot to wall 1	Thermal Insulation	NO ASBESTOS	unsealed	Loose asbestos debris or residue	No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0		Identified	Asbestos Removed	88156	BA9850		11/09/2019			
#REFI	SAA	Daisy Hill Hospital Estate	03	Residue to Walls	High level wall 2 snot to wall	Thermal Insulation	NO ASBESTOS	unsealed	Loose asbestos debris or residue	No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	25/12/2019	Identified	Asbestos Removed	88157	BA9850		11/09/2019			

#REF!	SAA	Daisy Hill Hospital Estate	03	Residue to Walls	High level snot to wall 2	Thermal Insulation	NO ASBESTOS	unsealed	Loose asbestos debris or residue	No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	25/12/2019	Identified	Asbestos Removed	88158	BA9850		11/09/2019	
#REF!	SAA	Daisy Hill Hospital Estate	03	Residue to Walls	High level snot to wall 2	Thermal Insulation	NO ASBESTOS	unsealed	Loose asbestos debris or residue	No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	25/12/2019	Identified	Asbestos Removed	88159	BA9850		11/09/2019	
#REF!	SAA	Daisy Hill Hospital Estate	03	NO ASBESTOS	High level gasket to pump on wall 4	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88160	BA9850		11/09/2019	
#REF!	SAA	Daisy Hill Hospital Estate	03	Residue to Walls	High level snot to wall 4	Thermal Insulation	NO ASBESTOS	unsealed	Loose asbestos debris or residue	No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	25/12/2019	Identified	Asbestos Removed	88161	BA9850		11/09/2019	
#REF!	SAA	Daisy Hill Hospital Estate	03	Thermal Insulation	Ceilino linino	Thermal Insulation	Chrvsotile	Unsealed Board	Low	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	Medium Risk	7	14/03/2023	Identified	Medium Risk	88162	BA9850	9302.2	22/04/2022	WHS
#REF!	NAB	St.Lukes	25	Ceiling Board	Ceiling board	Insulating Board	Amosite	Unsealed Asbestos Insulation	Low	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	Medium Risk	7	02/03/2021	Identified	Medium Risk	88163	BA9555	9501.1	03/01/2020	WHS
#REF!	QHD	Transna House	01	NO ASBESTOS	Boiler room residue to wall 1 at door to generator room	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88164	BA9848		11/09/2019	
#REF!	QHD	Transna House	01	NO ASBESTOS	Boiler room residue to wall 1 at electrical panel	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88165	BA9848		11/09/2019	
#REF!	QHD	Transna House	01	NO ASBESTOS	Boiler room residue to wall 2 at corner of wall 3	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88167	BA9848		11/09/2019	
#REF!	QHD	Transna House	01	NO ASBESTOS	Boiler room residue to wall 3 at gauge	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88168	BA9848		11/09/2019	
#REF!	QHD	Transna House	01	NO ASBESTOS	Boiler room residue to wall 3 right hand side of boiler	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88169	BA9848		11/09/2019	
#REF!	QHD	Transna House	01	NO ASBESTOS	Boiler room residue to wall 4 behind boilers	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88170	BA9848		11/09/2019	
#REF!	QHD	Transna House	01	Packing Strips	Switch room cavity closers x3 to ventilation opening	Cement Products	Chrysotile	Cement Sheets	Areas of damage or deterioration	Manage and monitor	Re-inspection	HSG227	Unchecked	Low Risk	5	14/10/2023	Identified	Very Low Risk	88171	BA9848	9299/22	29/09/2022	WHS
#REF!	QHD	Transna House	01	Cloth firebreak	Generator room cloth wrap to generator exhaust	Textiles & Paper	Chrysotile	Unsealed Rope	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Low Risk	6	14/10/2023	Identified	Low Risk	88172	BA9848	9299/22	29/09/2022	WHS
#REF!	QHD	Transna House	01	NO ASBESTOS	Boiler room debris to floor of boiler room	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88173	BA9848		11/09/2019	
#REF!	OHD	Transna House	01	Packing Strips	Cavity closers to ventilation opening	Cement Products	Chrysotile	Unsealed Cement	Minor damage or	Encapsulate, label and manage	Re-inspection	HSG227	Unchecked	Very Low Risk	4	14/10/2023	Identified	Very Low Risk	88174	BA9848	9299/2	29/09/2022	WHS
#REF!	RAB	Lonsstone/Mullinure	02	Rope Seal	Rope seal to vent trunkino	Textiles & Paper	Chrysotile	Unsealed Rope	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Low Risk	6	27/03/2021	Identified	Low Risk	88175	BA9540	9501.1	20/01/2020	WHS
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Ceiling Panel	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88176	BA9774		31/07/2019	
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Floor covering	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88177	BA9774		31/07/2019	
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Ceiling panel	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88178	BA9774		31/07/2019	
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Debris to vent trunking to adjoining riser	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88179	BA9774		31/07/2019	
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Debris to vent trunking to adjoining riser	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88180	BA9774		31/07/2019	
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Older pipe lagging to adjoining riser	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88181	BA9774		31/07/2019	
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Debris to cast iron pipe to adjoining riser	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88182	BA9774		31/07/2019	
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Panelling behind shelving	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88183	BA9774		31/07/2019	
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Skirting Trim	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88184	BA9774		31/07/2019	
#REF!	RAA	South Tyrone Hospital	10	Residue to Walls	Residue to wall 2	Thermal Insulation	Amosite	Unsealed	Loose asbestos	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	High Risk	11	15/12/2023	Identified	High Risk	88186	BA9778	9302.2	15/12/2022	WHS
#REF!	RAA	South Tyrone Hospital	10	Residue to Walls	Residue to wall 2 behind metal	Thermal Insulation	Amosite	unsealed	Loose asbestos	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	High Risk	11	15/12/2023	Identified	High Risk	88187	BA9778	9302.2	15/12/2022	WHS
#REF!	RAA	South Tyrone Hospital	10	Loose Asbestos	Residue to pipe bracket beneath metal platform	Thermal Insulation	Amosite	unsealed	Loose asbestos debris or residue	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	High Risk	11	15/12/2023	Identified	High Risk	88188	BA9778	9302.2	15/12/2022	WHS
#REF!	RAA	South Tyrone Hospital	10	Debris	Debris to metal platform	Thermal Insulation	Amosite	unsealed	Loose asbestos	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	High Risk	11	15/12/2023	Identified	High Risk	88189	BA9778	9302.2	15/12/2022	WHS
#REF!	RAA	South Tyrone Hospital	10	Residue to Walls	Residue to wall 2 above metal	Thermal Insulation	Amosite	unsealed	Loose asbestos	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	High Risk	11	15/12/2023	Identified	High Risk	88190	BA9778	9302.2	15/12/2022	WHS
#REF!	RAA	South Tyrone Hospital	10	Residue to Walls	Residue to wall 2 above metal	Thermal Insulation	Amosite	unsealed	High	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	High Risk	11	15/12/2023	Identified	High Risk	88191	BA9778	9302.2	15/12/2022	WHS
#REF!	RAA	South Tyrone Hospital	10	Residue to Walls	Residue to wall 2	Thermal Insulation	Amosite	unsealed	Loose asbestos	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	High Risk	11	15/12/2023	Identified	High Risk	88192	BA9778	9302.2	15/12/2022	WHS
#REF!	RAA	South Tyrone Hospital	10	NO ASBESTOS	Residue to wall 2	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88193	BA9778		31/07/2019	
#REF!	RAA	South Tyrone Hospital	10	Residue to Walls	Residue to wall 2	Thermal Insulation	Amosite	unsealed	Loose asbestos	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	High Risk	11	15/12/2023	Identified	High Risk	88194	BA9778	9302.2	15/12/2022	WHS
#REF!	RAA	South Tyrone Hospital	10	Loose Asbestos	Residue to wall 3	Loose Asbestos	Amosite	unsealed	Loose asbestos	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	High Risk	11	15/12/2023	Identified	High Risk	88195	BA9778	9302.2	15/12/2022	WHS
#REF!	RAA	South Tyrone Hospital	10	Residue to Walls	Residue to wall 3	Thermal Insulation	Amosite	unsealed	Loose asbestos	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	High Risk	11	15/12/2023	Identified	High Risk	88196	BA9778	9302.2	15/12/2022	WHS
#REF!	RAA	South Tyrone Hospital	10	Loose Asbestos	Residue to wall 3	Loose Asbestos	Amosite	unsealed	Loose asbestos	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	High Risk	11	15/12/2023	Identified	High Risk	88197	BA9778	9302.2	15/12/2022	WHS
#REF!	RAA	South Tyrone Hospital	10	NO ASBESTOS	Residue to wall 4	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88198	BA9778		31/07/2019	
#REF!	RAA	South Tyrone Hospital	10	NO ASBESTOS	Residue to wall 4	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88199	BA9778		31/07/2019	
#REF!	RAA	South Tyrone Hospital	10	NO ASBESTOS	Residue to wall 4	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88200	BA9778		31/07/2019	
#REF!	RAA	South Tyrone Hospital	10	Residue to Walls	Residue to wall 4	Thermal Insulation	Amosite	unsealed	Loose asbestos	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	High Risk	11	15/12/2023	Identified	High Risk	88201	BA9778	9302.2	15/12/2022	WHS
#REF!	RAA	South Tyrone Hospital	10	Residue to Walls	Residue to wall 5	Thermal Insulation	Amosite	unsealed	Loose asbestos	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	High Risk	11	15/12/2023	Identified	High Risk	88202	BA9778	9302.2	15/12/2022	WHS
#REF!	RAA	South Tyrone Hospital	10	Residue to Walls	Residue to wall 5	Thermal Insulation	Amosite	unsealed	Loose asbestos	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	High Risk	11	15/12/2023	Identified	High Risk	88203	BA9778	9302.2	15/12/2022	WHS
#REF!	RAA	South Tyrone Hospital	10	Residue to Walls	Residue to wall 5	Thermal Insulation	Amosite	unsealed	Loose asbestos	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	High Risk	11	15/12/2023	Identified	High Risk	88204	BA9778	9302.2	15/12/2022	WHS
#REF!	RAA	South Tyrone Hospital	10	Residue to Walls	Residue to wall 5	Thermal Insulation	Amosite	unsealed	Loose asbestos	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	High Risk	11	15/12/2023	Identified	High Risk	88205	BA9778	9302.2	15/12/2022	WHS
#REF!	RAA	South Tyrone Hospital	10	NO ASBESTOS	Roof tile to canopy over side door	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88206	BA9778		31/07/2019	
#REF!	RAA	South Tyrone Hospital	10	NO ASBESTOS	Pipe work lagging at 22 outside oil tank room	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88207	BA9778		31/07/2019	
#REF!	RAA	South Tyrone Hospital	10	NO ASBESTOS	Pipe work lagging at 22 outside oil tank room	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88284	BA9778		31/07/2019	
#REF!	RAA	South Tyrone Hospital	10	NO ASBESTOS	Pipe lagging to oil tank	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88285	BA9778		31/07/2019	
#REF!	RAA	South Tyrone Hospital	10	NO ASBESTOS	Jackets to flanges to oil tank	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88286	BA9778		31/07/2019	
#REF!	RAA	South Tyrone Hospital	10	Seal	Sealant between oil tank sections	Composite Material	Chrysotile	Composite Material	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Very Low Risk	3	15/12/2023	Identified	Very Low Risk	88287	BA9778	9302.2	15/12/2022	WHS
#REF!	RAA	South Tyrone Hospital	10	NO ASBESTOS	Debris to floor of oil tank room	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88288	BA9778		31/07/2019	
#REF!	RAA	South Tyrone Hospital	10	NO ASBESTOS	Debris to floor of oil tank room	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88289	BA9778		31/07/2019	
#REF!	QAA	Craigavon Hospital	16	Putty	Putty within fuse housing to distribution board	Composite Material	Chrysotile	Composite Material	Low	Label & Manage	Re-inspection	HSG227	Unchecked	Very Low Risk	3	24/06/2023	Identified	Very Low Risk	88324	BA9787	9302.2	24/06/2022	WHS
#REF!	QAA	Craigavon Hospital	16	NO ASBESTOS	Debris within electrical distribution board (1st floor)	NO ASBESTOS	NO ASBESTOS	Unsealed Spray / Lagging / Dust Debris	Medium	No further action required (No Asbestos Detected)	Review of Data	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88325	BA9787		06/08/2019	
#REF!	QAA	Craigavon Hospital	16	NO ASBESTOS	Floor tile beneath carpet to Flat B (1st floor)	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88326	BA9787		06/08/2019	
#REF!	QAA	Craigavon Hospital	16	NO ASBESTOS	White floor tile to laundry store Flat B (1st Floor)	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88327	BA9787		06/08/2019	
#REF!	QAA	Craigavon Hospital	16	NO ASBESTOS	Grey floor tile at door saddle to laundry store (1st floor)	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88328	BA9787		06/08/2019	
#REF!	QAA	Craigavon Hospital	16	NO ASBESTOS	White floor tile to cupboard to Flat B (1st floor)	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88329	BA9787		06/08/2019	
#REF!	QAA	Craigavon Hospital	16	NO ASBESTOS	Grey floor tile to cupboard to Flat B (1st floor)	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88330	BA9787		06/08/2019	
#REF!	QAA	Craigavon Hospital	16	NO ASBESTOS	Floor tile beneath carpet to Flat C (1st Floor)	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88331	BA9798		06/08/2019	
#REF!	QAA	Craigavon Hospital	16	NO ASBESTOS	White floor tile to cupboard to Flat C	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88332	BA9787		06/08/2019	
#REF!	QAA	Craigavon Hospital	16	NO ASBESTOS	White floor tile to cupboard to Flat C (1st Floor)	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88333	BA9798		06/08/2019	
#REF!	QAA	Craigavon Hospital	16	NO ASBESTOS	Grey floor tile to cupboard to Flat C (1st floor)	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88334	BA9787		06/08/2019	
#REF!	QAA	Craigavon Hospital	16	NO ASBESTOS	Floor tile beneath carpet to Flat H (1st floor)	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88335	BA9787		06/08/2019	
#REF!	QAA	Craigavon Hospital	16	NO ASBESTOS	White floor tile to cupboard to Flat H (1st floor)	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88336	BA9787		06/08/2019	
#REF!	QAA	Craigavon Hospital	16	NO ASBESTOS	Grey floor tile to cupboard to Flat H (1st floor)	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88337	BA9787		06/08/2019	
#REF!	QAA	Craigavon Hospital	16	NO ASBESTOS	Floor tile to laundry store Flat H (1st floor)	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88338	BA9787		06/08/2019	
#REF!	QAA	Craigavon Hospital	16	NO ASBESTOS	White floor tile beneath carpet to Flat G (1st floor)	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88339	BA9787		06/08/2019	
#REF!	QAA	Craigavon Hospital	16	NO ASBESTOS	Grey floor tile beneath carpet to Flat G (1st floor)	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88340	BA9787		06/08/2019	
#REF!	QAA	Craigavon Hospital	16	NO ASBESTOS	White floor tile to cupboard to Flat G (1st floor)	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88341	BA9787		06/08/2019	
#REF!	QAA	Craigavon Hospital	16	NO ASBESTOS	Grey floor tile to cupboard to Flat G (1st floor)	NO ASBESTOS	NO ASBESTOS				New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88342	BA9787		06/08/2019	
#REF!	QAA	Craigavon Hospital	16	NO ASBESTOS	Stair nosing	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88343	BA9787		06/08/2019	
#REF!	QAA	Craigavon Hospital	16	NO ASBESTOS	White floor tile to Flat I (2nd floor)	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88344	BA9787		06/08/2019	
#REF!	QAA	Craigavon Hospital	16	NO ASBESTOS	Grey floor tile to Flat I (2nd floor)	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88345	BA9787		06/08/2019	
#REF!	QAA	Craigavon Hospital	16	NO ASBESTOS	White floor tile to cupboard to Flat I (2nd floor)	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88346	BA9787		06/08/2019	
#REF!	QAA	Craigavon Hospital	16	NO ASBESTOS	Grey floor tile to cupboard to Flat I (2nd floor)	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88347	BA9787		06/08/2019	
#REF!	QAA	Craigavon Hospital	16	NO ASBESTOS	White floor tile to wardrobe to Flat I (2nd floor)	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88348	BA9787		06/08/2019	
#REF!	QAA	Craigavon Hospital	01	Pipe Brackets	Cloth between bracket and pipework	Textiles & Paper	Chrysotile	Unsealed Friable Pipework Insulation	Medium	Label and Remove if likely to be disturbed	Re-inspection	HSG227	Unchecked	Medium Risk	8	11/10/2023	Identified	Medium Risk	88349	BA9957	9302.2	11/10/2022	WHS
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Debris to enclosed cable tray	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88350	BA9957		24/10/2019	
#REF!	QAA	Craigavon Hospital	01	Pipe Brackets	Cloth between bracket and pipework	Textiles & Paper	Chrysotile	Unsealed Friable Pipework Insulation	Medium	Label and Remove if likely to be disturbed	Re-inspection	HSG227	Unchecked	Medium Risk	8	11/10/2023	Identified	Medium Risk	88351	BA9957	9302.2	11/10/2022	WHS

#REF!	QAA	Craigavon Hospital	01	Pipe Brackets	Cloth between pipework and bracket	Textiles & Paper	Chrysotile	Unsealed Friable Pipework Insulation	Medium	Label and Remove if likely to be disturbed	Re-inspection	HSG227	Unchecked	Medium Risk	8	11/10/2023	Identified	Medium Risk	88352	BA9957	9302.22	11/10/2022	WHS		
#REF!	QAA	Craigavon Hospital	01	Pipe Brackets	Cloth between bracket and pipework	Textiles & Paper	Chrysotile	Unsealed Friable Pipework Insulation	Medium	Label and Remove if likely to be disturbed	Re-inspection	HSG227	Unchecked	Medium Risk	8	11/10/2023	Identified	Medium Risk	88353	BA9957	9302.22	11/10/2022	WHS		
#REF!	QAA	Craigavon Hospital	01	Pipe Brackets	Cloth between bracket and pipework (above door to B-129)	Textiles & Paper	Chrysotile	Unsealed Friable Pipework Insulation	Medium	Label and Remove if likely to be disturbed	Re-inspection	HSG227	Unchecked	Medium Risk	8	11/10/2023	Identified	Medium Risk	88354	BA9957	9302.22	11/10/2022	WHS		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Debris to enclosed cable tray	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88355	BA9957		24/10/2019			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Debris to suspended ceiling tile	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88356	BA9957		24/10/2019			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Debris to suspended ceiling tile	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88357	BA9957		24/10/2019			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Debris to suspended ceiling tile	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88358	BA9957		24/10/2019			
#REF!	QAA	Craigavon Hospital	01	Gaskets	Gasket (1 of 2) to flange above suscended ceilino	Composite Material	Chrysotile	Composite Material	Low	Manage and monitor	Re-inspection	HSG227	Unchecked	Very Low Risk	3	09/09/2023	Identified	Very Low Risk	88359	BA9957	9302.22	09/09/2022	WHS		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Debris to suspended ceiling tile	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88360	BA9957		24/10/2019			
#REF!	QAA	Craigavon Hospital	01	General Debris	Debris to suspended ceiling tile	General Debris	Chrysotile	unsealed	Loose asbestos	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	High Risk	10	09/09/2023	Identified	High Risk	88361	BA9957	9302.22	09/09/2022	WHS		
#REF!	QAA	Craigavon Hospital	01	Pipe Brackets	Cloth between pipework and bracket	Textiles & Paper	Chrysotile	Unsealed Friable Pipework Insulation	Medium	Label and Remove if likely to be disturbed	Re-inspection	HSG227	Unchecked	Medium Risk	8	09/09/2023	Identified	Medium Risk	88362	BA9957	9302.22	09/09/2022	WHS		
#REF!	QAA	Craigavon Hospital	01	Pipe Brackets	Cloth between bracket and pipework	Textiles & Paper	Chrysotile	Unsealed Friable Pipework Insulation	Medium	Label and Remove if likely to be disturbed	Re-inspection	HSG227	Unchecked	Medium Risk	8	29/09/2023	Identified	Medium Risk	88363	BA9957	9302.22	29/09/2022	WHS		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Lining to roof void hatch	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88364	BA9957		24/10/2019			
#REF!	QAA	Craigavon Hospital	01	Pipe Brackets	Cloth between pipework and bracket	Textiles & Paper	Chrysotile	Unsealed Friable Pipework Insulation	Medium	Label and Remove if likely to be disturbed	Re-inspection	HSG227	Unchecked	Medium Risk	8	29/09/2023	Identified	Medium Risk	88365	BA9957	9302.22	29/09/2022	WHS		
#REF!	QAA	Craigavon Hospital	01	Pipe Brackets	Cloth between bracket and pipework	Textiles & Paper	Chrysotile	Unsealed Friable Pipework Insulation	Medium	Label and Remove if likely to be disturbed	Re-inspection	HSG227	Unchecked	Medium Risk	8	29/09/2023	Identified	Medium Risk	88366	BA9957	9302.22	29/09/2022	WHS		
#REF!	QAA	Craigavon Hospital	01	Pipe Brackets	Cloth between bracket and pipework	Textiles & Paper	Chrysotile	Unsealed Friable Pipework Insulation	Medium	Label and Remove if likely to be disturbed	Re-inspection	HSG227	Unchecked	Medium Risk	8	29/09/2023	Identified	Medium Risk	88367	BA9957	9302.22	29/09/2022	WHS		
#REF!	QAA	Craigavon Hospital	01	Pipe Brackets	Cloth between bracket and pipework	Textiles & Paper	Chrysotile	Unsealed Friable Pipework Insulation	Medium	Label and Remove if likely to be disturbed	Re-inspection	HSG227	Unchecked	Medium Risk	8	29/09/2023	Identified	Medium Risk	88368	BA9957	9302.22	29/09/2022	WHS		
#REF!	QAA	Craigavon Hospital	01	Pipe Brackets	Cloth between bracket and pipework	Textiles & Paper	Chrysotile	Unsealed Friable Pipework Insulation	Medium	Label and Remove if likely to be disturbed	Re-inspection	HSG227	Unchecked	Medium Risk	8	29/09/2023	Identified	Medium Risk	88369	BA9957	9302.22	29/09/2022	WHS		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Cloth between bracket and ducting	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88370	BA9957		24/10/2019			
#REF!	QAA	Craigavon Hospital	01	Pipe Brackets	Cloth between bracket and pipework	Textiles & Paper	Chrysotile	Unsealed Friable Pipework Insulation	Medium	Label and Remove if likely to be disturbed	Re-inspection	HSG227	Unchecked	Medium Risk	8	29/09/2023	Identified	Medium Risk	88371	BA9957	9302.22	29/09/2022	WHS		
#REF!	QAA	Craigavon Hospital	01	Pipe Brackets	Cloth between bracket and pipework	Textiles & Paper	Chrysotile	Unsealed Friable Pipework Insulation	Medium	Label and Remove if likely to be disturbed	Re-inspection	HSG227	Unchecked	Medium Risk	8	29/09/2023	Identified	Medium Risk	88372	BA9957	9302.22	29/09/2022	WHS		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Cloth between bracket and ducting	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88373	BA9957		24/10/2019			
#REF!	QAA	Craigavon Hospital	01	Pipe Brackets	Cloth between bracket and pipework	Textiles & Paper	Chrysotile	Unsealed Friable Pipework Insulation	Medium	Label and Remove if likely to be disturbed	Re-inspection	HSG227	Unchecked	Medium Risk	8	29/09/2023	Identified	Medium Risk	88374	BA9957	9302.22	29/09/2022	WHS		
#REF!	QAA	Craigavon Hospital	01	Pipe Brackets	Cloth between bracket and pipework	Textiles & Paper	Chrysotile	Unsealed Friable Pipework Insulation	Medium	Label and Remove if likely to be disturbed	Re-inspection	HSG227	Unchecked	Medium Risk	8	29/09/2023	Identified	Medium Risk	88375	BA9957	9302.22	29/09/2022	WHS		
#REF!	QAA	Craigavon Hospital	01	Pipe Brackets	Cloth between bracket and pipework	Textiles & Paper	Chrysotile	Unsealed Friable Pipework Insulation	Medium	Label and Remove if likely to be disturbed	Re-inspection	HSG227	Unchecked	Medium Risk	8	29/09/2023	Identified	Medium Risk	88376	BA9957	9302.22	29/09/2022	WHS		
#REF!	QAA	Craigavon Hospital	01	Pipe Brackets	Cloth between bracket and pipework	Textiles & Paper	Chrysotile	Unsealed Friable Pipework Insulation	Medium	Label and Remove if likely to be disturbed	Re-inspection	HSG227	Unchecked	Medium Risk	8	29/09/2023	Identified	Medium Risk	88377	BA9957	9302.22	29/09/2022	WHS		
#REF!	QAA	Craigavon Hospital	01	Pipe Brackets	Cloth between bracket and pipework	Textiles & Paper	Chrysotile	Unsealed Friable Pipework Insulation	Medium	Label and Remove if likely to be disturbed	Re-inspection	HSG227	Unchecked	Medium Risk	8	29/09/2023	Identified	Medium Risk	88378	BA9957	9302.22	29/09/2022	WHS		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Ceiling board to flat roof section	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88379	BA9957		24/10/2019			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Fire break to roof void	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88380	BA9957		24/10/2019			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Firebreak above double doors to RV	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88381	BA9957		24/10/2019			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Board to roof void	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88382	BA9957		24/10/2019			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Debris to roof void	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88383	BA9957		24/10/2019			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Firebreak above wall	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88384	BA9957		24/10/2019			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Board below roof covering	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88385	BA9957		24/10/2019			
#REF!	QAA	Craigavon Hospital	01	Pipe Brackets	Cloth between bracket and pipework	Textiles & Paper	Chrysotile	Unsealed Friable Pipework Insulation	Medium	Label and Remove if likely to be disturbed	Re-inspection	HSG227	Unchecked	Medium Risk	8	29/09/2023	Identified	Medium Risk	88386	BA9957	9302.22	29/09/2022	WHS		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Debris to roof void	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88387	BA9957		24/10/2019			
#REF!	QAA	Craigavon Hospital	01	Pipe Brackets	Cloth between bracket and pipework	Textiles & Paper	Chrysotile	Unsealed Friable Pipework Insulation	Medium	Label and Remove if likely to be disturbed	Re-inspection	HSG227	Unchecked	Medium Risk	8	29/09/2023	Identified	Medium Risk	88388	BA9957	9302.22	29/09/2022	WHS		
#REF!	QAA	Craigavon Hospital	01	Pipe Brackets	Cloth between bracket and pipework	Textiles & Paper	Chrysotile	Unsealed Friable Pipework Insulation	Medium	Label and Remove if likely to be disturbed	Re-inspection	HSG227	Unchecked	Medium Risk	8	29/09/2023	Identified	Medium Risk	88389	BA9957	9302.22	29/09/2022	WHS		
#REF!	QAA	Craigavon Hospital	16	NO ASBESTOS	Grey floor tile to wardrobe to Flat I (2nd floor)	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88390	BA9787		06/08/2019			
#REF!	QAA	Craigavon Hospital	01	Pipe Brackets	Cloth between bracket and pipework	Textiles & Paper	Chrysotile	Unsealed Friable Pipework Insulation	Medium	Label and Remove if likely to be disturbed	Re-inspection	HSG227	Unchecked	Medium Risk	8	29/09/2023	Identified	Medium Risk	88391	BA9957	9302.22	29/09/2022	WHS		
#REF!	QAA	Craigavon Hospital	16	NO ASBESTOS	White floor tile to Flat J (2nd floor)	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88392	BA9787		06/08/2019			
#REF!	QAA	Craigavon Hospital	01	Pipe Brackets	Cloth between bracket and pipework	Textiles & Paper	Chrysotile	Unsealed Friable Pipework Insulation	Medium	Label and Remove if likely to be disturbed	Re-inspection	HSG227	Unchecked	Medium Risk	8	29/09/2023	Identified	Medium Risk	88393	BA9957	9302.22	29/09/2022	WHS		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Debris to roof void	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88394	BA9957		24/10/2019			
#REF!	QAA	Craigavon Hospital	16	NO ASBESTOS	Grey floor tile to Flat J (2nd floor)	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88395	BA9787		06/08/2019			
#REF!	QAA	Craigavon Hospital	16	NO ASBESTOS	White floor tile to cupboard to Flat J (2nd floor)	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88396	BA9787		06/08/2019			
#REF!	QAA	Craigavon Hospital	01	Pipe Brackets	Cloth between bracket and pipework	Textiles & Paper	Chrysotile	Unsealed Friable Pipework Insulation	Medium	Label and Remove if likely to be disturbed	Re-inspection	HSG227	Unchecked	Medium Risk	8	29/09/2023	Identified	Medium Risk	88397	BA9957	9302.22	29/09/2022	WHS		
#REF!	QAA	Craigavon Hospital	16	NO ASBESTOS	White floor tile to cupboard to Flat J (2nd floor)	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88398	BA9787		06/08/2019			
#REF!	QAA	Craigavon Hospital	16	NO ASBESTOS	White floor tile to Flat E (2nd floor)	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88399	BA9787		06/08/2019			
#REF!	QAA	Craigavon Hospital	16	NO ASBESTOS	Grey floor tile to Flat E (2nd floor)	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88400	BA9787		06/08/2019			
#REF!	QAA	Craigavon Hospital	16	NO ASBESTOS	White floor tile to cupboard to Flat E (2nd floor)	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88401	BA9787		06/08/2019			
#REF!	QAA	Craigavon Hospital	16	NO ASBESTOS	Grey floor tile to cupboard to Flat E (2nd floor)	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88402	BA9787		06/08/2019			
#REF!	QAA	Craigavon Hospital	16	NO ASBESTOS	Redundant white floor tile to laundry store (2nd floor)	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88403	BA9787		06/08/2019			
#REF!	QAA	Craigavon Hospital	16	NO ASBESTOS	Redundant brown floor tile to laundry store (2nd floor)	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88404	BA9787		06/08/2019			
#REF!	QAA	Craigavon Hospital	16	NO ASBESTOS	White floor tile to Flat D (2nd floor)	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88405	BA9787		06/08/2019			
#REF!	QAA	Craigavon Hospital	16	NO ASBESTOS	Grey floor tile to Flat D (2nd floor)	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88406	BA9787		06/08/2019			
#REF!	QAA	Craigavon Hospital	16	NO ASBESTOS	White floor tile to cupboard to Flat D (2nd floor)	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88407	BA9787		06/08/2019			
#REF!	QAA	Craigavon Hospital	16	NO ASBESTOS	Grey floor tile to cupboard to Flat D (2nd floor)	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88408	BA9787		06/08/2019			
#REF!	QAA	Craigavon Hospital	16	NO ASBESTOS	White floor tile to wardrobe to Flat D (2nd floor)	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88409	BA9787		06/08/2019			
#REF!	QAA	Craigavon Hospital	16	NO ASBESTOS	Grey floor tile to wardrobe to Flat D (2nd floor)	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88410	BA9787		06/08/2019			
#REF!	QAA	Craigavon Hospital	16	NO ASBESTOS	Stair nosing	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88411	BA9787		06/08/2019			
#REF!	OAB	Banbridge Polvclinic	15	Residue to Walls	Residue to wall 1	Thermal Insulation	Amosite/Chrvsotile	Unsealed Sorav or Laqqino	High	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	High Risk	11	09/12/2022	Identified	High Risk	88412	BA9846	9302.2	06/04/2022	WHS		
#REF!	OAB	Banbridge Polvclinic	15	Residue to Walls	Residue to wall 2	Thermal Insulation	Amosite/Chrvsotile	Unsealed Spray or Lagging	High	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	High Risk	11	09/12/2022	Identified	High Risk	88413	BA9846	9302.2	06/04/2022	WHS		
#REF!	OAB	Banbridge Polvclinic	15	General Debris	Debris to plinth of calorifier	General Debris	Amosite	Loose Asbestos Debris	High	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	High Risk	11	09/12/2022	Identified	High Risk	88414	BA9846	9302.2	06/04/2022	WHS		
#REF!	OAB	Banbridge Polvclinic	15	NO ASBESTOS	Residue to wall 3 between windows	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88415	BA9846		10/09/2019			
#REF!	OAB	Banbridge Polvclinic	15	Residue to Walls	Residue to wall 4	Thermal Insulation	Amosite/Chrvsotile	Unsealed Sorav or Laqqino	High	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	High Risk	11	09/12/2022	Identified	High Risk	88416	BA9846	9302.2	06/04/2022	WHS		
#REF!	OAB	Banbridge Polvclinic	15	Residue to Walls	Residue to wall 4	Thermal Insulation	Amosite/Chrvsotile	Unsealed Sorav or Laqqino	High	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	High Risk	11	09/12/2022	Identified	High Risk	88417	BA9846	9302.2	06/04/2022	WHS		
#REF!	OAB	Banbridge Polvclinic	15	Door Panel	Door to oil tank room	Cement Products	Chrysotile	Cement Sheets	Low	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	Very Low Risk	4	09/12/2022	Identified	Very Low Risk	88418	BA9846	9302.2	06/04/2022	WHS		
#REF!	OAB	Banbridge Polvclinic	15	NO ASBESTOS	Gasket to burner to boiler	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88419	BA9846		10/09/2019			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Putty to ducting	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88420	BA9957		24/10/2019			
#REF!	QAA	Craigavon Hospital	01	Pipe Brackets	Cloth between bracket and pipework	Textiles & Paper	Chrysotile	Unsealed Friable Pipework Insulation	Medium	Label and Remove if likely to be disturbed	Re-inspection	HSG227	Unchecked	Medium Risk	8	13/05/2020	Identified	Medium Risk	88421	BA9957	9302.22	24/10/2019	WHS		
#REF!	QAA	Craigavon Hospital	01	Pipe Brackets	Cloth between bracket and pipework	Textiles & Paper	Chrysotile	Unsealed Friable Pipework Insulation	Medium	Label and Remove if likely to be disturbed	Re-inspection	HSG227	Unchecked	Medium Risk	8	29/09/2023	Identified	Medium Risk	88422	BA9957	9302.22	29/09/2022	WHS		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Putty to ducting	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88423	BA9957		24/10/2019			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Putty to ducting	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88424	BA9957		24/10/2019			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Cloth between bracket and ducting	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88425	BA9957		24/10/2019			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Bitumen to redundant roof sheet	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88426	BA9957		24/10/2019			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Bitumen above metal cladding to ceilino	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88427	BA9957		24/10/2019			

#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Debris to walkway to roof void	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88428	BA9957		24/10/2019			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Debris to beam to roof void	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88429	BA9957		24/10/2019			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Cloth to redundant bracket	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88430	BA9957		24/10/2019			
#REF!	QAA	Craigavon Hospital	01	Pipe Brackets	Cloth between bracket and pipework	Textiles & Paper	Chrysotile	Unsealed Friable Pipework Insulation	Medium	Label and Remove if likely to be disturbed	Re-inspection	HSG227	Unchecked	Medium Risk	8	29/09/2023	Identified	Medium Risk	88431	BA9957	9302.22	29/09/2022	WHS			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Bitumen splash to joists	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88432	BA9957		24/10/2019			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Debris to walkway	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88433	BA9957		24/10/2019			
#REF!	QAA	Craigavon Hospital	01	Pipe Brackets	Cloth between bracket and pipework	Textiles & Paper	Chrysotile	Unsealed Friable Pipework Insulation	Medium	Label and Remove if likely to be disturbed	Re-inspection	HSG227	Unchecked	Medium Risk	8	29/09/2023	Identified	Medium Risk	88434	BA9957	9302.22	29/09/2022	WHS			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Debris to roof void	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88435	BA9957		24/10/2019			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Putty to ducting	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88436	BA9957		24/10/2019			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Putty to ducting	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88437	BA9957		24/10/2019			
#REF!	QPB	Manor Centre and Stores	01	NO ASBESTOS	Residue to wall 1	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88438	BA9874		17/09/2019			
#REF!	QPB	Manor Centre and Stores	01	NO ASBESTOS	Residue to wall 1	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88439	BA9874		17/09/2019			
#REF!	QPB	Manor Centre and Stores	01	NO ASBESTOS	Residue to wall 2	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88440	BA9874		17/09/2019			
#REF!	QAA	Craigavon Hospital	01	Pipe Brackets	Cloth between brackets and pipework	Textiles & Paper	Chrysotile	Unsealed Friable Pipework Insulation	Medium	Label and Remove if likely to be disturbed	Re-inspection	HSG227	Unchecked	Medium Risk	8	29/09/2023	Identified	Medium Risk	88441	BA9957	9302.22	29/09/2022	WHS			
#REF!	QPB	Manor Centre and Stores	01	NO ASBESTOS	Residue to wall 2	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88442	BA9874		17/09/2019			
#REF!	QAA	Craigavon Hospital	01	Pipe Brackets	Cloth between bracket and pipework	Textiles & Paper	Chrysotile	Unsealed Friable Pipework Insulation	Medium	Label and Remove if likely to be disturbed	Re-inspection	HSG227	Unchecked	Medium Risk	8	29/09/2023	Identified	Medium Risk	88443	BA9957	9302.22	29/09/2022	WHS			
#REF!	QAA	Craigavon Hospital	01	Pipe Brackets	Cloth between bracket and pipework	Textiles & Paper	Chrysotile	Unsealed Friable Pipework Insulation	Medium	Label and Remove if likely to be disturbed	Re-inspection	HSG227	Unchecked	Medium Risk	8	29/09/2023	Identified	Medium Risk	88444	BA9957	9302.22	29/09/2022	WHS			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Debris to roof void	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88445	BA9957		24/10/2019			
#REF!	QPB	Manor Centre and Stores	01	NO ASBESTOS	Residue to wall 2	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88446	BA9874		17/09/2019			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Bitumen sealant near roof hatch	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88447	BA9957		24/10/2019			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Cloth between bracket and ducting	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88448	BA9957		24/10/2019			
#REF!	QAA	Craigavon Hospital	01	Pipe Brackets	Cloth between bracket and pipework	Textiles & Paper	Chrysotile	Unsealed Friable Pipework Insulation	Medium	Label and Remove if likely to be disturbed	Re-inspection	HSG227	Unchecked	Medium Risk	8	29/09/2023	Identified	Medium Risk	88449	BA9957	9302.22	29/09/2022	WHS			
#REF!	QPB	Manor Centre and Stores	01	NO ASBESTOS	Residue to wall 3	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88450	BA9874		17/09/2019			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Redundant board next to roof hatch	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88451	BA9957		24/10/2019			
#REF!	QPB	Manor Centre and Stores	01	NO ASBESTOS	Residue to wall 4	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88452	BA9874		17/09/2019			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Ceiling above suspended ceiling	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88453	BA9967		30/10/2019			
#REF!	QPB	Manor Centre and Stores	01	NO ASBESTOS	Residue to wall 4	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88454	BA9874		17/09/2019			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Floor covering	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88455	BA9967		30/10/2019			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Skirting trim	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88456	BA9967		30/10/2019			
#REF!	QPB	Manor Centre and Stores	01	Wall Panels	Vertical boxing to wall 1	Insulating Board	Amosite	Unsealed Asbestos Insulation Board	Low	Remove (Controlled Conditions)	Review – No Change	HSG227	Unchecked	Medium Risk	7	13/05/2020	Identified	Medium Risk	88457	BA9874	9812.21	21/01/2020	WH Stephens			
#REF!	QAA	Craigavon Hospital	01	Wall Panels	Panelling to electrical switch room	Insulating Board	Presumed Asbestos	Unsealed Asbestos Insulation Board	Low	Label and Remove if likely to be disturbed	Re-inspection	HSG227	Unchecked	Medium Risk	8	11/10/2023	Previously Identified	Medium Risk	88458		9302.22	11/10/2022	WHS			
#REF!	QAA	Craigavon Hospital	01	Fire Break Panel	Firebreak over door to B-174	Insulating Board	Presumed Asbestos	Unsealed Asbestos Insulation Board	Low	Label and Remove if likely to be disturbed	Re-inspection	HSG227	Unchecked	Medium Risk	8	11/10/2023	Previously Identified	Medium Risk	88459		9302.22	11/10/2022	WHS			
#REF!	QPB	Manor Centre and Stores	01	Wall Panels	Vertical boxing to wall 3	Insulating Board	Amosite	Unsealed Asbestos Insulation Board	Low	Remove (Controlled Conditions)	Review – No Change	HSG227	Unchecked	Medium Risk	7	13/05/2020	Identified	Medium Risk	88460	BA9874	9812.21	21/01/2020	WH Stephens			
#REF!	QPB	Manor Centre and Stores	01	Ceilino Board	Ceilino to main boiler room	Insulatino Board	Amosite	Unsealed Asbestos Insulation Board	Low	Remove (Controlled Conditions)	Review – No Change	HSG227	Unchecked	Low Risk	6	12/11/2020	Identified	Low Risk	88461	BA9874	9812.21	21/01/2020	WH Stephens			
#REF!	QPB	Manor Centre and Stores	01	Ceilino Panel	Ceilino to electrical switch room	Insulatino Board	Amosite	Unsealed Asbestos Insulation Board	Low	Remove (Controlled Conditions)	Review – No Change	HSG227	Unchecked	Medium Risk	7	13/05/2020	Identified	Medium Risk	88462	BA9874	9812.21	21/01/2020	WH Stephens			
#REF!	QPB	Manor Centre and Stores	01	Ceiling Panelling	Ceiling to oil tank room	Insulating Board	Amosite	Unsealed Asbestos Insulation Board	Low	No further action required (No Asbestos Detected)	Review – No Change	HSG227	Unchecked	Medium Risk	7	13/05/2020	Identified	Medium Risk	88463	BA9874	9812.21	21/01/2020	WH Stephens			
#REF!	QPB	Manor Centre and Stores	01	NO ASBESTOS	Rope seal to front of boiler	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88464	BA9874		17/09/2019			
#REF!	QPB	Manor Centre and Stores	01	NO ASBESTOS	Gasket to burner	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88465	BA9874		17/09/2019			
#REF!	QPB	Manor Centre and Stores	01	NO ASBESTOS	Rope seal to flue pipe of boiler adjacent to door	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88466	BA9874		17/09/2019			
#REF!	QHA	Moylinn House	01	NO ASBESTOS	Residue to wall 1	NO ASBESTOS	NO ASBESTOS				No further action required (Asbestos removed)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88467	BA9847		06/06/2019			
#REF!	QHA	Moylinn House	01	NO ASBESTOS	Residue to wall of door leading to stairwell	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88468	BA9847		06/06/2019			
#REF!	QHA	Moylinn House	01	NO ASBESTOS	Residue to wall at electrical panel	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88469	BA9847		06/06/2019			
#REF!	QHA	Moylinn House	01	NO ASBESTOS	Residue to wall 2 behind calorifier 1	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88470	BA9847		06/06/2019			
#REF!	QHA	Moylinn House	01	NO ASBESTOS	Residue to wall 2 mid wall	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88471	BA9847		06/06/2019			
#REF!	QHA	Moylinn House	01	NO ASBESTOS	Residue to wall 3 at corner to wall 3	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88472	BA9847		06/06/2019			
#REF!	QHA	Moylinn House	01	NO ASBESTOS	Residue to wall 3 at corner to wall 4	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88473	BA9847		06/06/2019			
#REF!	QHA	Moylinn House	01	NO ASBESTOS	Debris to switch box behind calorifier 1	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88474	BA9847		06/06/2019			
#REF!	QHA	Moylinn House	01	NO ASBESTOS	Lagging to calorifier Nr1	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88475	BA9847		06/06/2019			
#REF!	QHA	Moylinn House	01	NO ASBESTOS	Lagging to calorifier Nr 2	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88476	BA9847		06/06/2019			
#REF!	QHA	Moylinn House	01	NO ASBESTOS	Debris to plinth beneath pumps	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88477	BA9847		06/06/2019			
#REF!	QHA	Moylinn House	01	NO ASBESTOS	Debris to floor behind pump plinth	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88478	BA9847		06/06/2019			
#REF!	QHA	Moylinn House	01	NO ASBESTOS	Debris to floor behind boilers	NO ASBESTOS	NO ASBESTOS				No further action required (Asbestos removed)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88479	BA9847		06/06/2019			
#REF!	QHA	Moylinn House	01	NO ASBESTOS	Debris to floor right hand side of door	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88480	BA9847		06/06/2019			
#REF!	QHA	Moylinn House	01	Cloth wrap	Cloth wrap to exhaust pipe from generator	Textiles & Paper	Chrysotile	Unsealed Friable Pipework Insulation	Medium	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	Medium Risk	8	14/04/2023	Identified	Medium Risk	88481	BA9847	9299/2	29/09/2022	WHS			
#REF!	QHA	Moylinn House	01	NO ASBESTOS	Residue to wall 3 generator room	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88482	BA9847		06/06/2019			
#REF!	QHA	Moylinn House	01	NO ASBESTOS	Residue to wall 4	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88483	BA9847		06/06/2019			
#REF!	QHA	Moylinn House	01	NO ASBESTOS	Residue to wall 2 electrical switch room	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88484	BA9847		06/06/2019			
#REF!	QHA	Moylinn House	01	Panel	Panel to cable tray penetration at high level to right hand side of door	Insulating Board	Amosite	Unsealed Asbestos Insulation Board	High	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	Medium Risk	9	14/04/2023	Identified	Medium Risk	88485	BA9847	9299/2	29/09/2022	WHS			
#REF!	QHA	Moylinn House	01	NO ASBESTOS	Debris to floor beneath electrical panels	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88486	BA9847		06/06/2019			
#REF!	NAB	St.Lukes	16	NO ASBESTOS	Paper lining to fire lining	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88487	BA0823		03/09/2019			
#REF!	NAB	St.Lukes	16	NO ASBESTOS	Fire curtain at compartment wall to roofspace	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88488	BA0823		03/09/2019			
#REF!	NAB	St.Lukes	16	Gaskets	Gasket to oize valve in roofsoace	Textiles & Paper	Chrvsotile	Unsealed Rope	Low	Remove	Re-inspection	HSG227	Unchecked	Low Risk	6	24/02/2021	Identified	Low Risk	88489	BA0823	9812.21	03/01/2020	WHS			
#REF!	NAB	St.Lukes	16	NO ASBESTOS	Inner lining pipe insulation to roofsoace	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88490	BA0823		03/09/2019			
#REF!	NAB	St.Lukes	16	NO ASBESTOS	Debris on roof insulation	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88491	BA0823		03/09/2019			
#REF!	NAB	St.Lukes	16	NO ASBESTOS	Fire barrier to ceiling	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88492	BA0823		03/09/2019			
#REF!	NAB	St.Lukes	16	NO ASBESTOS	Fire blanket across ceiling	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88493	BA0823		03/09/2019			
#REF!	NAB	St.Lukes	16	NO ASBESTOS	Fire curtain at compartment wall	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88494	BA0823		03/09/2019			
#REF!	NAB	St.Lukes	16	NO ASBESTOS	Fire curtain at compartment wall	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88495	BA0823		03/09/2019			
#REF!	NAB	St.Lukes	16	NO ASBESTOS	Fire blanket to ceiling	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88496	BA0823		03/09/2019			
#REF!	NAB	St.Lukes	16	NO ASBESTOS	Fire blanket to ceiling	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88497	BA0823		03/09/2019			
#REF!	NAB	St.Lukes	16	NO ASBESTOS	Ceiling lining to porch	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88498	BA0823		03/09/2019			
#REF!	NAB	St.Lukes	16	Soffit Boards	External soffit to eaves	Cement Products	Chrvsotile	Sealed Cement	Low	Remove	Re-inspection	HSG227	Unchecked	Very Low Risk	3	24/02/2021	Identified	Very Low Risk	88499	BA0823	9812.21	03/01/2020	WHS			
#REF!	NAB	St.Lukes	16	NO ASBESTOS	External soffit to eaves	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88500	BA0823		03/09/2019			
#REF!	NAB	St.Lukes	16	NO ASBESTOS	Vinyl sheet & bitumen	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88501	BA0823		03/09/2019			
#REF!	NAB	St.Lukes	16	NO ASBESTOS	Vinyl sheet	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88502	BA0823		03/09/2019			
#REF!	NAB	St.Lukes	16	NO ASBESTOS	Vinyl sheet	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88503	BA0823		03/09/2019			

#REF!	NAB	St.Lukes	16	NO ASBESTOS	Vinyl sheet	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88504	BA9823		03/09/2019				
#REF!	NAB	St.Lukes	16	NO ASBESTOS	Vinyl sheet	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88505	BA9823		03/09/2019				
#REF!	NAB	St.Lukes	16	NO ASBESTOS	Vinyl sheet	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88506	BA9823		03/09/2019				
#REF!	NAB	St.Lukes	16	NO ASBESTOS	Sink pad	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88507	BA9823		03/09/2019				
#REF!	NAB	St.Lukes	16	NO ASBESTOS	Vinyl sheet	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88508	BA9823		03/09/2019				
#REF!	NAB	St.Lukes	16	NO ASBESTOS	Vinyl sheet	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88509	BA9823		03/09/2019				
#REF!	NAB	St.Lukes	16	NO ASBESTOS	Vinyl sheet	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88510	BA9823		03/09/2019				
#REF!	NAB	St.Lukes	16	NO ASBESTOS	Ceiling tile	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88511	BA9823		03/09/2019				
#REF!	NAB	St.Lukes	16	NO ASBESTOS	Vinyl sheet	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88512	BA9823		03/09/2019				
#REF!	NAB	St.Lukes	16	NO ASBESTOS	Vinyl sheet	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88513	BA9823		03/09/2019				
#REF!	NAB	St.Lukes	16	NO ASBESTOS	Vinyl sheet	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88514	BA9823		03/09/2019				
#REF!	NAB	St.Lukes	16	NO ASBESTOS	Vinyl sheet	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88515	BA9823		03/09/2019				
#REF!	NAB	St.Lukes	16	NO ASBESTOS	Vinyl sheet	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88516	BA9823		03/09/2019				
#REF!	NAB	St.Lukes	16	NO ASBESTOS	Vinyl sheet	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88517	BA9823		03/09/2019				
#REF!	NAB	St.Lukes	16	NO ASBESTOS	Vinyl sheet	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88518	BA9823		03/09/2019				
#REF!	NAB	St.Lukes	16	NO ASBESTOS	Vinyl sheet	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88519	BA9823		03/09/2019				
#REF!	SJB	Needham House	01	NO ASBESTOS	Residue to wall 1	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88520	BA9849		06/09/2019				
#REF!	SJB	Needham House	01	NO ASBESTOS	Residue to wall 1	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88521	BA9849		06/09/2019				
#REF!	SJB	Needham House	01	NO ASBESTOS	Residue to wall 3	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88522	BA9849		06/09/2019				
#REF!	SJB	Needham House	01	NO ASBESTOS	Debris to cable tray at high level	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88523	BA9849		06/09/2019				
#REF!	SJB	Needham House	01	NO ASBESTOS	Ceiling panels to boiler house	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88524	BA9849		06/09/2019				
#REF!	SJB	Needham House	01	NO ASBESTOS	Gasket to burner front of boiler	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88525	BA9849		06/09/2019				
#REF!	SJB	Needham House	01	NO ASBESTOS	Debris to floor of boiler room	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88526	BA9849		06/09/2019				
#REF!	SJB	Needham House	01	NO ASBESTOS	Debris to floor of boiler room	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88527	BA9849		06/09/2019				
#REF!	SJB	Needham House	01	NO ASBESTOS	Verge undercloak to roof above boiler room	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88528	BA9849		06/09/2019				
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Loose sectional lagging to top of air handling unit. near roller door	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88529	BA9903		01/10/2019				
#REF!	SAA	Daisy Hill Hospital Estate	01	Gaskets	Gasket to flange to wall. LHS of roller door	Textiles & Paper	Chrysotile	Unsealed Rope	Low	Remove		Re-inspection	HSG227	Unchecked	Low Risk	6	13/12/2023	Identified	Low Risk	88530	BA9903	9309/22	26/10/2022	WHS				
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	DPC to wall, LHS of roller door	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88531	BA9903		01/10/2019				
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Debris to cable tray	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88532	BA9903		01/10/2019				
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Debris to air handling unit	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88533	BA9903		01/10/2019				
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Sectional lagging to floor	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88534	BA9903		01/10/2019				
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Sectional lagging debris to top of vent trunking	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88535	BA9903		01/10/2019				
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Debris to electrical switch gear	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88536	BA9903		01/10/2019				
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Sealant to vent trunking	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88537	BA9903		01/10/2019				
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Residue to wall	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88538	BA9903		01/10/2019				
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Lagging coating to large vent trunking	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88539	BA9903		01/10/2019				
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Straw board to ceiling of plant room	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88540	BA9903		01/10/2019				
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Debris to floor	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88541	BA9903		01/10/2019				
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Residue to switch room	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88542	BA9903		01/10/2019				
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Ceiling to canopy at goods intake	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88543	BA9903		01/10/2019				
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Ceiling to tin store	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88544	BA9903		01/10/2019				
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Ceiling to corridor outside fridges	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88545	BA9903		01/10/2019				
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Debrsi to ceiling void to corridor	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88546	BA9903		01/10/2019				
#REF!	SAA	Daisy Hill Hospital Estate	01	Gaskets	Gasket (1 of 4) to pipework flanges, outside pharmacy intake	Textiles & Paper	Chrysotile	Sealed Rope	Low	Remove		Re-inspection	HSG227	Unchecked	Low Risk	5	13/12/2023	Identified	Low Risk	88547	BA9903	9309/22	26/10/2022	WHS				
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Fire break above doors to lift lobby	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88548	BA9903		01/10/2019				
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Floor tiles to IT room	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88549	BA9903		01/10/2019				
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Debris to ceiling tile Xray room 5	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88550	BA9906		03/10/2019				
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Debris to metal beam Xray room 5	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88551	BA9906		03/10/2019				
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Debris to ceiling tile to corridor	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88552	BA9906		03/10/2019				
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Debris to ceiling tile to room 16 imaging	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88553	BA9906		03/10/2019				
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Debris to ceiling tile to corridor	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88554	BA9906		03/10/2019				
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Packer between vent trunking and frame to corridor	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88555	BA9906		03/10/2019				
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Debris to ceiling tile to corridor	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88556	BA9906		03/10/2019				
#REF!	QAA	Craigavon Hospital	01	Cloth	Cloth between pipework and bracket to corridor	Textiles & Paper	Chrysotile	Unsealed Rope	Medium	Remove (Controlled Conditions)		Re-inspection	HSG227	Unchecked	Medium Risk	7	21/09/2023	Identified	Medium Risk	88557	BA9906	9302.22	21/09/2022	WHS				
#REF!	QAA	Craigavon Hospital	01	Cloth	Cloth between pipework and bracket to corridor	Textiles & Paper	Chrysotile	Unsealed Rope	Medium	Remove (Controlled Conditions)		Re-inspection	HSG227	Unchecked	Medium Risk	7	21/09/2023	Identified	Medium Risk	88558	BA9906	9302.22	21/09/2022	WHS				
#REF!	QAA	Craigavon Hospital	01	Cloth	Cloth between pipework and bracket to corridor	Textiles & Paper	Chrysotile	Unsealed Rope	Medium	Remove (Controlled Conditions)		Re-inspection	HSG227	Unchecked	Medium Risk	7	11/10/2023	Identified	Medium Risk	88559	BA9906	9302.22	11/10/2022	WHS				
#REF!	QAA	Craigavon Hospital	01	Cloth	Cloth between pipework and bracket to corridor	Textiles & Paper	Chrysotile	Unsealed Rope	Medium	Remove (Controlled Conditions)		Re-inspection	HSG227	Unchecked	Medium Risk	7	11/10/2023	Identified	Medium Risk	88560	BA9906	9302.22	11/10/2022	WHS				
#REF!	QAA	Craigavon Hospital	01	Cloth	Cloth between pipework and bracket to corridor	Textiles & Paper	Chrysotile	Unsealed Rope	Medium	Remove (Controlled Conditions)		Re-inspection	HSG227	Unchecked	Medium Risk	7	11/10/2023	Identified	Medium Risk	88561	BA9906	9302.22	11/10/2022	WHS				
#REF!	QAA	Craigavon Hospital	01	Cloth	Cloth between pipework and bracket to corridor	Textiles & Paper	Chrysotile	Unsealed Rope	Medium	Remove (Controlled Conditions)		Re-inspection	HSG227	Unchecked	Medium Risk	7	11/10/2023	Identified	Medium Risk	88562	BA9906	9302.22	11/10/2022	WHS				
#REF!	QAA	Craigavon Hospital	01	Cloth	Cloth between pipework and bracket to corridor	Textiles & Paper	Chrysotile	Unsealed Rope	Medium	Remove (Controlled Conditions)		Re-inspection	HSG227	Unchecked	Medium Risk	7	11/10/2023	Identified	Medium Risk	88563	BA9906	9302.22	11/10/2022	WHS				
#REF!	QAA	Craigavon Hospital	01	Cloth	Cloth between pipework and bracket to corridor	Textiles & Paper	Chrysotile	Unsealed Rope	Medium	No further action required (No Asbestos Detected)		Re-inspection	HSG227	Unchecked	Medium Risk	7	11/10/2023	Identified	Medium Risk	88564	BA9906	9302.22	11/10/2022	WHS				
#REF!	QAA	Craigavon Hospital	01	Cloth	Cloth between pipework and bracket to corridor	Textiles & Paper	Chrysotile	Unsealed Rope	High	Remove (Controlled Conditions)		Re-inspection	HSG227	Unchecked	Medium Risk	8	11/10/2023	Identified	Medium Risk	88565	BA9906	9302.22	11/10/2022	WHS				
#REF!	QAA	Craigavon Hospital	01	Wall Panels	Panels to electrical switch room	Cement Products	Chrysotile	Cement Sheets	Low	Remove (Controlled Conditions)		Re-inspection	HSG227	Unchecked	Very Low Risk	4	11/10/2023	Identified	Very Low Risk	88566	BA9906	9302.22	11/10/2022	WHS				
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Upper ceiling to Xray room 2	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88567	BA9906		03/10/2019				
#REF!	QAA	Craigavon Hospital	01	Fire Break Panel	Firebreaks above doors to Xray department from lift lobby	Insulating Board	Amosite	Partially Sealed Asbestos Insulation Board	Low	Remove if likely to be disturbed		Re-inspection	HSG227	Unchecked	Medium Risk	7	11/10/2023	Previously Identified	Medium Risk	88568	N/A	9302.22	11/10/2022	WHS				
#REF!	QAA	Craigavon Hospital	19	NO ASBESTOS	Ceiling board to plant room	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88569	BA9968		29/10/2019				
#REF!	QAA	Craigavon Hospital	19	NO ASBESTOS	Bulkhead over door to inner room	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88570	BA9968		29/10/2019				
#REF!	QAA	Craigavon Hospital	19	NO ASBESTOS	Panel at toilet extract fan	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88571	BA9968		29/10/2019				
#REF!	QAA	Craigavon Hospital	19	NO ASBESTOS	Gasket to flange	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88572	BA9968		29/10/2019				
#REF!	QAA	Craigavon Hospital	19	Gaskets	Loose gasket to top of pipework	Textiles & Paper	Chrysotile	Encapsulated Rope	Low	Remove		Re-inspection	HSG227	Unchecked	Low Risk	5	24/12/2022	Identified	Low Risk	88573	BA9968	9302.22	24/06/2022	WHS				
#REF!	QAA	Craigavon Hospital	19	NO ASBESTOS	Panel above door to main building	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88574	BA9968		29/10/2019				
#REF!	QAA	Craigavon Hospital	19	NO ASBESTOS	White floor tile	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88575	BA9968		29/10/2019				
#REF!	QAA	Craigavon Hospital	19	NO ASBESTOS	Grey floor tile	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88576	BA9968		29/10/2019				
#REF!	QAA	Craigavon Hospital	19	Floor Tiles	Orange floor tile	Composite Material	Chrysotile	Composite Material	Low	Remove		Re-inspection	HSG227	Unchecked	Very Low Risk	3	26/11/2020	Identified	Very Low Risk	88577	BA9968	9302.22	15/01/2020	WH Stephens				

#REF!	QAA	Craigavon Hospital	20	NO ASBESTOS	Debris to electrical cupboard off corridor	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88578	BA9968		29/10/2019	
#REF!	QBC	Gilford Health Centre	01	Soffit Boards	Soffit board	Insulating Board	Amosite/Chrysotile	Partially Sealed Asbestos Insulation Board	Low	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	Medium Risk	7	09/03/2023	Identified	Medium Risk	88587	BA9978	9299/2 2	11/04/2022	WHS
#REF!	QBC	Gilford Health Centre	01	Roof Tiles	Roof tile	Cement Products	Chrysotile	Partially Sealed Cement	[illegible]	Remove	Re-inspection	HSG227	Unchecked	Very Low Risk	4	09/03/2023	Identified	Medium Risk	88588	BA9978	[illegible]	11/04/2022	WHS
#REF!	QBC	Gilford Health Centre	01	NO ASBESTOS	Snot to wall 2 mid level	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88589	BA9978		31/10/2019	
#REF!	QBC	Gilford Health Centre	01	NO ASBESTOS	Gasket 1 & 3 to burner 1	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88590	BA9978		31/10/2019	
#REF!	QBC	Gilford Health Centre	01	Rope Seal	Rope seal to burner 1	Textiles & Paper	Chrysotile	Encapsulated Rope	Low	Remove	Re-inspection	HSG227	Unchecked	Low Risk	5	09/09/2023	Identified	Low Risk	88591	BA9978	9288/2 -	11/04/2022	WHS
#REF!	QBC	Gilford Health Centre	01	NO ASBESTOS	Gasket 1 & 3 to burner 2	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88592	BA9978		31/10/2019	
#REF!	QBC	Gilford Health Centre	01	Rope Seal	Rope seal to burner 2	Textiles & Paper	Chrysotile	Sealed Rope	Low	Encapsulate, Manage & Affix ID Labels	Re-inspection	HSG227	Unchecked	Low Risk	5	09/09/2023	Identified	Low Risk	88593	BA9978	9288/2 -	11/04/2022	WHS
#REF!	QBC	Gilford Health Centre	01	Rope Seal	Rope seal to burner 2	Textiles & Paper	Chrysotile	Sealed Rope	Low	Remove	Re-inspection	HSG227	Unchecked	Low Risk	5	09/09/2023	Identified	Low Risk	88594	BA9978	9288/2 -	11/04/2022	WHS
#REF!	QBC	Gilford Health Centre	01	NO ASBESTOS	Gasket 1 of 3 to flanges to pipework	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88595	BA9978		31/10/2019	
#REF!	QBC	Gilford Health Centre	01	NO ASBESTOS	Debris to floor to rear of burners	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88596	BA9978		31/10/2019	
#REF!	QBC	Gilford Health Centre	01	NO ASBESTOS	Snot to wall 3 low level	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88597	BA9978		31/10/2019	
#REF!	QBC	Gilford Health Centre	01	NO ASBESTOS	Skirting trim	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88598	BA9978		31/10/2019	
#REF!	QBC	Gilford Health Centre	01	NO ASBESTOS	Floor covering	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88599	BA9978		31/10/2019	
#REF!	QBC	Gilford Health Centre	01	NO ASBESTOS	Debris to top of electrical equipment	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88600	BA9978		31/10/2019	
#REF!	QBC	Gilford Health Centre	01	NO ASBESTOS	Floor covering to corridors	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88601	BA9978		31/10/2019	
#REF!	QBC	Gilford Health Centre	01	NO ASBESTOS	Floor covering to male toilets	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88602	BA9978		31/10/2019	
#REF!	QBC	Gilford Health Centre	01	NO ASBESTOS	Floor covering to store	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88603	BA9978		31/10/2019	
#REF!	QBC	Gilford Health Centre	01	NO ASBESTOS	Roof void - Roof felt	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88604	BA9978		31/10/2019	
#REF!	QBC	Gilford Health Centre	01	Roof Slate debris	Roof Void - Rood slate debris	Cement Products	Chrysotile	Residue Cement	High	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	Medium Risk	8	09/12/2022	Identified	High Risk	88605	BA9978	9288/2 -	11/04/2022	WHS
#REF!	QBC	Gilford Health Centre	01	NO ASBESTOS	Sink pad to kitchen	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88606	BA9978		31/10/2019	
#REF!	QBC	Gilford Health Centre	01	NO ASBESTOS	Floor covering to public toilet	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88607	BA9978		31/10/2019	
#REF!	QBC	Gilford Health Centre	01	NO ASBESTOS	Floor covering to treatment room	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88608	BA9978		31/10/2019	
#REF!	QBC	Gilford Health Centre	01	NO ASBESTOS	Floor tile beneath floor covering	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88609	BA9978		31/10/2019	
#REF!	QBC	Gilford Health Centre	01	NO ASBESTOS	Floor covering	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88610	BA9978		31/10/2019	
#REF!	QBC	Gilford Health Centre	01	Soffit	Soffit to canopy	Insulating Board	Amosite/Chrysotile	[illegible]	Medium	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	Medium Risk	7	11/03/2023	Identified	Medium Risk	88611	BA9978	[illegible]	11/04/2022	WHS
#REF!	QBC	Gilford Health Centre	01	NO ASBESTOS	Sink pd to physio	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88612	BA9978		31/10/2019	
#REF!	QBC	Gilford Health Centre	01	NO ASBESTOS	Floor tile to store	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88613	BA9978		31/10/2019	
#REF!	QBC	Gilford Health Centre	01	NO ASBESTOS	Floor tile to domestic store	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88614	BA9978		31/10/2019	
#REF!	QAA	Craigavon Hospital	11	NO ASBESTOS	Debris to ceiling tile	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88615	BA10002		11/11/2019	
#REF!	QAA	Craigavon Hospital	11	NO ASBESTOS	Outer panels to ceiling void above doors to labs	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88616	BA10002		11/11/2019	
#REF!	QAA	Craigavon Hospital	11	Thermoplastic & bitumen adhesive	Floor tile to reception area just inside doors to labs	Composite Material	Chrysotile	Concealed	Medium	Remove	Re-inspection	HSG227	Unchecked	Low Risk	5	06/09/2023	Identified	Low Risk	88617	BA10002	9302/2 2	18/10/2022	WHS
#REF!	QAA	Craigavon Hospital	11	NO ASBESTOS	Grey floor tile to main corridor	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88618	BA10002		11/11/2019	
#REF!	QAA	Craigavon Hospital	11	NO ASBESTOS	Blue floor tile to main corridor	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88619	BA10002		11/11/2019	
#REF!	QAA	Craigavon Hospital	11	NO ASBESTOS	Red floor tile to main corridor	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88620	BA10002		11/11/2019	
#REF!	QAA	Craigavon Hospital	11	NO ASBESTOS	Green floor tile to main corridor	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88621	BA10002		11/11/2019	
#REF!	QAA	Craigavon Hospital	11	NO ASBESTOS	Fire break above doors to main corridor	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88622	BA10002		11/11/2019	
#REF!	QAA	Craigavon Hospital	11	NO ASBESTOS	Debris to ceiling void	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88623	BA10002		11/11/2019	
#REF!	QAA	Craigavon Hospital	11	NO ASBESTOS	Debris to ceiling void	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88624	BA10002		11/11/2019	
#REF!	QAA	Craigavon Hospital	11	NO ASBESTOS	Debris to ceiling void above double doors at duplex	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88625	BA10002		11/11/2019	
#REF!	QAA	Craigavon Hospital	11	NO ASBESTOS	Debris to ceiling void	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88626	BA10002		11/11/2019	
#REF!	QAA	Craigavon Hospital	11	NO ASBESTOS	Panels around door to corridor outside room OAA-11-A-036	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88627	BA10002		11/11/2019	
#REF!	QAA	Craigavon Hospital	11	NO ASBESTOS	Panels around double doors to lab OAA-11-A-045	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88628	BA10002		11/11/2019	
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Floor covering to main corridor	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88629	BA100024		19/11/2019	
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Floor covering to post room	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88630	BA100024		19/11/2019	
#REF!	RAA	South Tyrone Hospital	17	Thermoplastic	Floor covering beneath carpet to [illegible]	Composite Material	Chrysotile	Composite Material	Low	Remove	Re-inspection	HSG227	Unchecked	Very Low Risk	3	13/12/2023	Identified	Very Low Risk	88631	BA100024	[illegible]	13/12/2022	WHS
#REF!	RAA	South Tyrone Hospital	17	Rope Seal	Rope seal to pump equipment under counter	Textiles & Paper	Chrysotile	Sealed Rope	Low	Remove	Re-inspection	HSG227	Unchecked	Low Risk	5	13/12/2023	Identified	Low Risk	88632	BA100024	9302/2 2	13/12/2022	WHS
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Rope seal to isolater box beneath counter	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88633	BA100024		19/11/2019	
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Paper to isolater box beneath counter	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88634	BA100024		19/11/2019	
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Floor covering	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88635	BA100024		19/11/2019	
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Debris to riser behind toilets	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88636	BA100024		19/11/2019	
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Floor covering to toilets	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88637	BA100024		19/11/2019	
#REF!	RAA	South Tyrone Hospital	17	Floor Covering	Floor coverino	Composite Material	Chrysotile	Composite Material	None	Remove	Re-inspection	HSG227	Unchecked	Very Low Risk	2	13/12/2023	Identified	Very Low Risk	88638	BA100024	9302/2 -	13/12/2022	WHS
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Debris to riser adjacent to store	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88639	BA100024		19/11/2019	
#REF!	RAA	South Tyrone Hospital	17	Floor coverino	Floor coverino to store	Composite Material	Chrysotile	Composite Material	None	Remove	Re-inspection	HSG227	Unchecked	Very Low Risk	2	13/12/2023	Identified	Very Low Risk	88642	BA100024	9302/2 -	13/12/2022	WHS
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Floor covering	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88644	BA100024		19/11/2019	
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Sealant to vent trunking beneath counter	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88646	BA100024		19/11/2019	
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Fire breal panels above doors to store area	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88648	BA100024		19/11/2019	
#REF!	NAB	St.Lukes	12	NO ASBESTOS	Fire break above door at bottom of stairs	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88654	BA10028		21/11/2019	
#REF!	NAB	St.Lukes	12	NO ASBESTOS	Floor covering to corridor	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Correcting previous data entry error	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88655	BA10028		21/11/2019	
#REF!	NAB	St.Lukes	12	NO ASBESTOS	Skirting trim to corridor	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88656	BA10028		21/11/2019	
#REF!	NAB	St.Lukes	12	NO ASBESTOS	Cloth sleeve (x4) to flanges at door to corridor	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88657	BA10028		21/11/2019	
#REF!	NAB	St.Lukes	12	NO ASBESTOS	Floor screed beneath carpet	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88658	BA10028		21/11/2019	
#REF!	NAB	St.Lukes	12	NO ASBESTOS	Floor covering to shower/toilets	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Correcting previous data entry error	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88659	BA10028		21/11/2019	
#REF!	NAB	St.Lukes	12	NO ASBESTOS	Lining to showers	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88660	BA10028		21/11/2019	
#REF!	NAB	St.Lukes	12	NO ASBESTOS	Lining to shower to bathroom	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88661	BA10028		21/11/2019	
#REF!	NAB	St.Lukes	12	NO ASBESTOS	Debris to floor of duct	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88662	BA10028		21/11/2019	
#REF!	NAB	St.Lukes	12	NO ASBESTOS	Debris to floor of duct	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88663	BA10028		21/11/2019	
#REF!	NAB	St.Lukes	12	NO ASBESTOS	Debris to floor of duct	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88664	BA10028		21/11/2019	
#REF!	NAB	St.Lukes	12	NO ASBESTOS	Debris to floor of duct	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88665	BA10028		21/11/2019	
#REF!	NAB	St.Lukes	12	NO ASBESTOS	Floor covering to store	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88666	BA10028		21/11/2019	
#REF!	NAB	St.Lukes	12	NO ASBESTOS	Sink pad to kitchen	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88667	BA10028		21/11/2019	
#REF!	NAB	St.Lukes	12	NO ASBESTOS	Floor covering to toilets and kitchen A-084, A-084, A-086	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88668	BA10028		21/11/2019	
#REF!	NAB	St.Lukes	12	NO ASBESTOS	Bitumen to parquet flooring beneath caroet	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88669	BA10028		21/11/2019	
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Debris to riser	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88670	BA10021		18/11/2019	
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Cloth wrap within pipework to riser	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88671	BA10021		18/11/2019	
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Seal to pipework joint wihtin riser	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88672	BA10021		18/11/2019	

#REF!	RAA	South Tyrone Hospital	06	NO ASBESTOS	Soffit to front	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88673	BA10022		19/11/2019			
#REF!	RAA	South Tyrone Hospital	06	NO ASBESTOS	Putty to window	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88674	BA10022		19/11/2019			
#REF!	RAA	South Tyrone Hospital	06	NO ASBESTOS	Felt to flat roof	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88675	BA10022		19/11/2019			
#REF!	RAA	South Tyrone Hospital	06	Fuse Pad	Fuse pad to redundant fuses beneath shelving	Textiles & Paper	Chrysotile	Composite Material	Low	Remove	New Incident	HSG227	Unchecked	Very Low Risk	4		Identified	Very Low Risk	88676	BA10022		19/11/2019			
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Ceiling panels	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88677	BA10051		04/12/2019			
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Debris to riser	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88678	BA10051		04/12/2019			
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Sink pad	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88679	BA10051		04/12/2019			
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Ceiling panel	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88680	BA10051		04/12/2019			
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Debris to riser	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88681	BA10051		04/12/2019			
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Sink pad	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88682	BA10051		04/12/2019			
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Debris to riser	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88683	BA10051		04/12/2019			
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Floor covering	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88684	BA10051		04/12/2019			
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Ceiling panel	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88685	BA10051		04/12/2019			
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Lining to shelving unit	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88686	BA10051					
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Ceiling panel	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88687	BA10051		04/12/2019			
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Debris to cable tray at high level	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88688	BA10051		04/12/2019			
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Floor covering	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88689	BA10051		04/12/2019			
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Floor covering	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88690	BA10051		04/12/2019			
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Debris to floor	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88691	BA10051		04/12/2019			
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Debris to floor	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88692	BA10051		04/12/2019			
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Floor covering	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88693	BA10051		04/12/2019			
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Ceiling panel	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88694	BA10051		04/12/2019			
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Debris to ledge	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88695	BA10051		04/12/2019			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Brake pad to lift machinery	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88696	BA0765		24/07/2019			
#REF!	QAA	Craigavon Hospital	01	Cement pad	Pad within selector panel	Cement Products	Chrysotile	Partially Sealed Cement	Low	Remove	New Incident	HSG227	Unchecked	Very Low Risk	4	12/12/2020	Identified	Very Low Risk	88697	BA0765		24/07/2019			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Debris to floor	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88698	BA0765		24/07/2019				
#REF!	QAA	Craigavon Hospital	01	Rope Seal	Rope to electrical cable tray within lift shaft	Textiles & Paper	Chrysotile	Encapsulated Rope	Low	Remove	Re-inspection	HSG227	Unchecked	Low Risk	5	05/07/2023	Identified	Low Risk	88699	BA0765	9302.22	05/07/2022	WHS		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Debris to sill level 4	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88700	BA0765		24/07/2019			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Debris to guide bracket between levels 2 & 3	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88701	BA0765		24/07/2019			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Debris to door frame level 2	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88702	BA0765		24/07/2019			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Debris to counterweight	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88703	BA0765		24/07/2019			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Debris to door sill	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88704	BA0765		24/07/2019			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Packer to top of lift car	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88705	BA0765		24/07/2019			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Debris to guide frame	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88706	BA0765		24/07/2019			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Debris to ground floor cill	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88707	BA0765		24/07/2019			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Floor coving to lift car	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88708	BA0765		24/07/2019			
#REF!	QAA	Craigavon Hospital	01	Cloth	Cloth between pipe work and bracket outside 051	Textiles & Paper	Chrysotile	Unsealed Rope	Medium	Remove (Controlled Conditions)	New Incident	HSG227	Unchecked	Medium Risk	7	16/07/2020	Identified	Medium Risk	88718	BA1071		18/12/2019			
#REF!	QAA	Craigavon Hospital	01	Cloth	Cloth between pipe work and bracket outside room 054	Textiles & Paper	Chrysotile	Unsealed Rope	Low	Remove (Controlled Conditions)	New Incident	HSG227	Unchecked	Low Risk	6	15/01/2021	Identified	Low Risk	88719	BA1071		18/12/2019			
#REF!	QAA	Craigavon Hospital	01	Cloth	Cloth between pipe work and hansino bracket to ceilino void	Textiles & Paper	Chrysotile	Unsealed Rope	Medium	Remove (Controlled Conditions)	New Incident	HSG227	Unchecked	Medium Risk	7	16/07/2020	Identified	Medium Risk	88720	BA1071		18/12/2019			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Floor tile beneath lino floor covering	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88721	BA1071		18/12/2019			
#REF!	QAA	Craigavon Hospital	01	Cloth	Cloth between pipe work and hansino bracket to ceilino void	Textiles & Paper	Chrysotile	Unsealed Rope	Medium	Remove (Controlled Conditions)	New Incident	HSG227	Unchecked	Medium Risk	7	16/07/2020	Identified	Medium Risk	88722	BA1071		18/12/2019			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Floor covering to toilet and lobby	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88724	BA1071		18/12/2019			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Floor covering to main corridor	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88725	BA1071		18/12/2019			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Debris to ceiling void of utility room	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88728	BA1071		18/12/2019			
#REF!	QAA	Craigavon Hospital	01	Cloth	Cloth between pipe work and bracket outside room 056	Textiles & Paper	Chrysotile	Unsealed Rope	Medium	Remove (Controlled Conditions)	New Incident	HSG227	Unchecked	Medium Risk	7	16/07/2020	Identified	Medium Risk	88731	BA1071		18/12/2019			
#REF!	QAA	Craigavon Hospital	01	Cloth	Cloth between pipe work and bracket outside 057	Textiles & Paper	Chrysotile	Unsealed Rope	Medium	Remove (Controlled Conditions)	New Incident	HSG227	Unchecked	Medium Risk	7	16/07/2020	Identified	Medium Risk	88733	BA1071		18/12/2019			
#REF!	QAA	Craigavon Hospital	01	Cloth	Cloth between pipe work and hansino bracket to ceilino void /1 of	Textiles & Paper	Chrysotile	Unsealed Rope	Medium	Remove (Controlled Conditions)	New Incident	HSG227	Unchecked	Medium Risk	7	16/07/2020	Identified	Medium Risk	88734	BA1071		18/12/2019			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Floor covering to 4 bed ward	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88735	BA1071		18/12/2019			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Floor tile to electrical cupboard	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88736	BA1071		18/12/2019			
#REF!	QAA	Craigavon Hospital	01	Cloth	Cloth between pipe work and hansino bracket to ceilino void /1 of	Textiles & Paper	Chrysotile	Unsealed Rope	Medium	Remove (Controlled Conditions)	New Incident	HSG227	Unchecked	Medium Risk	7	16/07/2020	Identified	Medium Risk	88737	BA1071		18/12/2019			
#REF!	QAA	Craigavon Hospital	01	Cloth	Cloth between pipe work and bracket outside 058	Textiles & Paper	Chrysotile	Unsealed Rope	Medium	Remove (Controlled Conditions)	New Incident	HSG227	Unchecked	Medium Risk	7	16/07/2020	Identified	Medium Risk	88738	BA1071		18/12/2019			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Debris to ceiling void	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88769	BA1071		18/12/2019			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Floor covering to office	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88770	BA1071		18/12/2019			
#REF!	QAA	Craigavon Hospital	01	Cloth	Cloth between pipe work and hansino bracket to ceilino void	Textiles & Paper	Chrysotile	Unsealed Rope	Medium	Remove (Controlled Conditions)	New Incident	HSG227	Unchecked	Medium Risk	7	22/07/2020	Identified	Medium Risk	88771	BA1071		18/12/2019			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Panel to wall of 4 bed ward	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88772	BA1071		19/12/2019			
#REF!	QAA	Craigavon Hospital	01	Cloth	Cloth between pipe work and hansino bracket to ceilino void	Textiles & Paper	Chrysotile	Unsealed Rope	Medium	Remove (Controlled Conditions)	New Incident	HSG227	Unchecked	Medium Risk	7	22/07/2020	Identified	Medium Risk	88773	BA1071		18/12/2019			
#REF!	QAA	Craigavon Hospital	01	Cloth	Cloth between pipe work and bracket outside room 059	Textiles & Paper	Chrysotile	Unsealed Rope	Medium	Remove (Controlled Conditions)	New Incident	HSG227	Unchecked	Medium Risk	7	22/07/2020	Identified	Medium Risk	88774	BA1071		18/12/2019			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Debris to riser	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88775	BA1071		18/12/2019			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Debris to riser	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88776	BA1071		18/12/2019			
#REF!	QAA	Craigavon Hospital	01	Cloth	Cloth between pipework and bracket outside 017 /1 of 2\	Textiles & Paper	Chrysotile	Unsealed Rope	Medium	Remove (Controlled Conditions)	New Incident	HSG227	Unchecked	Medium Risk	7	22/07/2020	Identified	Medium Risk	88777	BA1071		18/12/2019			
#REF!	QAA	Craigavon Hospital	01	Cloth	Cloth between pipe work and bracket outside room 014 /1 of 2\	Textiles & Paper	Chrysotile	Unsealed Rope	Medium	Remove (Controlled Conditions)	New Incident	HSG227	Unchecked	Medium Risk	7	22/07/2020	Identified	Medium Risk	88778	BA1071		18/12/2019			
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Floor tile beneath carpet	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88779	BA1071		18/12/2019			
#REF!	SBE	Rathfriland Health Centre & Library	01	Debris	Debris to main switchboard	Insulating Board	Amosite	Loose Asbestos Debris	[illegible]	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	High Risk	10	12/12/2022	Identified	High Risk	88780	BA0916	[illegible]	02/09/2022	WHS		
#REF!	SBE	Rathfriland Health Centre & Library	01	NO ASBESTOS	Debris to distribution box	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88781	BA0916		08/10/2019			
#REF!	RSA	Dungannon Clinic	01	NO ASBESTOS	Sink pad	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88907	BA10072		23/12/2019			
#REF!	RSA	Dungannon Clinic	01	NO ASBESTOS	Vinyl floor sheeting	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88908	BA10072		23/12/2019			
#REF!	RSA	Dungannon Clinic	01	NO ASBESTOS	Vinyl skirting to wall	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88909	BA10072		23/12/2019			
#REF!	RSA	Dungannon Clinic	01	NO ASBESTOS	Suspended ceiling tile	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88910	BA10072		23/12/2019			
#REF!	RSA	Dungannon Clinic	01	NO ASBESTOS	Above ceiling - Paper lining between timbe and metal roof	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88911	BA10072		23/12/2019			
#REF!	RSA	Dungannon Clinic	01	NO ASBESTOS	High level void - Panel to high level void	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88912	BA10072		23/12/2019			
#REF!	RSA	Dungannon Clinic	01	NO ASBESTOS	High level void - Debris to floor of high level void	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88913	BA10072		23/12/2019			
#REF!	RSA	Dungannon Clinic	01	Ceiling Panels	High level void - Pnale to roof of high level void	Cement Products	Chrysotile	Unsealed Board	Medium	Remove	New Incident	HSG227	Unchecked	Low Risk	6	26/02/2021	Identified	Low Risk	88914	BA10072		23/12/2019			
#REF!	RSA	Dungannon Clinic	01	NO ASBESTOS	Panel to rear of wall heater	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88915	BA10072		23/12/2019			
#REF!	RSA	Dungannon Clinic	01	NO ASBESTOS	Bitumen felt behind skirting	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88916	BA10072		23/12/2019			

#REF!	RSA	Dungannon Clinic	01	NO ASBESTOS	Notice board panel	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88917	BA10072		23/12/2019		
#REF!	RSA	Dungannon Clinic	01	NO ASBESTOS	Ceiling panels	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88918	BA10072		23/12/2019		
#REF!	RSA	Dungannon Clinic	01	NO ASBESTOS	Screed below carpet	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88919	BA10072		23/12/2019		
#REF!	RSA	Dungannon Clinic	01	NO ASBESTOS	At folding partition - Vinyl floor tiles below carpet	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88920	BA10072		23/12/2019		
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Residue to RH pipe work on N&M-C-003 Chiller	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Error Entry	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88921	BA10107		23/01/2020		
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Residue to RH pipe work on N&M-C-003 Chiller	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88922	BA10107		23/01/2020		
#REF!	SAA	Daisy Hill Hospital Estate	01	Gaskets	Gasket to RH pipe work on N&M-C-003 Chiller	Textiles & Paper	Chrysotile	Encapsulated Rope	Medium	Remove	Re-inspection	HSG227	Unchecked	Low Risk	6	13/12/2023	Identified	Low Risk	88923	BA10107	9300.22	26/10/2022	WHS	
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Residue to LH pipe work on N&M-C-003 Chiller	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Error Entry	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88924	BA10107		23/01/2020		
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Residue to LH pipe work on N&M-C-003 Chiller	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88925	BA10107		23/01/2020		
#REF!	SAA	Daisy Hill Hospital Estate	01	Gaskets	Residue to LH pipe work on N&M-C-003 Chiller	Textiles & Paper	Chrysotile	Encapsulated Rope	Medium	Remove	Re-inspection	HSG227	Unchecked	Low Risk	6	13/12/2023	Identified	Low Risk	88926	BA10107	9300.22	26/10/2022	WHS	
#REF!	SAA	Daisy Hill Hospital Estate	01	General Debris	Debris to floor below pipes on N&M-C-003 Chiller	General Debris	Chrysotile	Loose Asbestos Debris	Loose asbestos debris or residue	Remove	Re-inspection	HSG227	Unchecked	High Risk	10	13/12/2023	Identified	High Risk	88927	BA10107	9300/22	26/10/2022	WHS	
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Residue to RH pipe work top of N&M-C-003 Chiller	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88928	BA10107		23/01/2020		
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Residue to LH pipe work top of N&M-C-003 Chiller	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88929	BA10107		23/01/2020		
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Residue to LH pipe work on N&M-C-001 Chiller	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88930	BA10107		23/01/2020		
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Residue to LH pipe work on N&M-C-001 Chiller	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88931	BA10107		23/01/2020		
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Gasket to LH pip on N&M-C-001 Chiller	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88932	BA10107		23/01/2020		
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Residue to RH pipe work on N&M-C-001 Chiller	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88933	BA10107		23/01/2020		
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Gasket X4 to pipes on N&M-C-001 Chiller	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88934	BA10107		23/01/2020		
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Residue to LH pipe work on N&M-C-002 Chiller	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Error Entry	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88935	BA10107		23/01/2020		
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Residue to LH pipe work on N&M-C-002 Chiller	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88936	BA10107		23/01/2020		
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Residue to RH pipe work on N&M-C-002 Chiller	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88937	BA10107		23/01/2020		
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Residue to RH pipe work on N&M-C-002 Chiller	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88938	BA10107		23/01/2020		
#REF!	SAA	Daisy Hill Hospital Estate	01	Gaskets	Gaskets to pipes on N&M-C-002	Textiles & Paper	Chrysotile	Encapsulated Rope	Medium	Remove	Re-inspection	HSG227	Unchecked	Low Risk	6	13/12/2023	Identified	Low Risk	88939	BA10107	9300.2	26/10/2022	WHS	
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Gaskets X2 on valves on N&M-C-002 Chiller	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88940	BA10107		23/01/2020		
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Gaskets X6 to Valves on N&M-C-003 Chiller	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	88941	BA10107		23/01/2020		
#REF!	QAA	Craigavon Hospital	23	Soffit Boarding	Soffit board to roof eaves at gables	Cement Products	Chrysotile	Cement Sheets	Low	Label & Manage	Re-inspection	HSG227	Unchecked	Very Low Risk	4	17/01/2024	Identified	Very Low Risk	89019	BA10217	9302.2	05/09/2022	WHS	
#REF!	OAA	Craigavon Hospital	23	Soffit Boarding	Soffit board at mid eaves level	Cement Products	Chrysotile	Cement Sheets	Low	Label & Manage	Re-inspection	HSG227	Unchecked	Very Low Risk	4	17/01/2024	Identified	Very Low Risk	89020	BA10217	9302.2	05/09/2022	WHS	
#REF!	SBA	John Mitchel Place	01	NO ASBESTOS	Gasket to pump 2	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	89446	BA10108		23/01/2020		
#REF!	SBA	John Mitchel Place	01	NO ASBESTOS	Gasket to pump 3	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	89447	BA10108		23/01/2020		
#REF!	SBA	John Mitchel Place	01	NO ASBESTOS	Gasket to pump 4	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	89448	BA10108		23/01/2020		
#REF!	SBA	John Mitchel Place	01	Gaskets	Gasket to rear pipework - Pump 1	Textiles & Paper	Chrysotile	Enclosed	Low	Remove	Re-inspection	HSG227	Unchecked	Low Risk	5	15/09/2023	Identified	Very Low Risk	89449	BA10108	9302.2	06/04/2022	WHS	
#REF!	SBA	John Mitchel Place	01	Gaskets	Gasket to rear pipework - Pump 2	Textiles & Paper	Chrysotile	Enclosed	Low	Remove	Re-inspection	HSG227	Unchecked	Low Risk	5	15/09/2023	Identified	Very Low Risk	89450	BA10108	9302.2	06/04/2022	WHS	
#REF!	SBA	John Mitchel Place	01	Gaskets	Gasket to rear pumpwork - Pump 3	Textiles & Paper	Chrysotile	Enclosed	Low	Remove	Re-inspection	HSG227	Unchecked	Low Risk	5	15/09/2023	Identified	Very Low Risk	89451	BA10108	9302.2	06/04/2022	WHS	
#REF!	SBA	John Mitchel Place	01	Gaskets	Gasket to rear pumpwork - Pump 4	Textiles & Paper	Chrysotile	Enclosed	Low	Remove	Re-inspection	HSG227	Unchecked	Low Risk	5	15/09/2023	Identified	Very Low Risk	89452	BA10108	9302.2	06/04/2022	WHS	
#REF!	SBA	John Mitchel Place	01	Gaskets	Gasket to fornt pipework - Pump 1	Textiles & Paper	Chrysotile	Enclosed	Low	Remove	Re-inspection	HSG227	Unchecked	Low Risk	5	15/09/2023	Identified	Very Low Risk	89453	BA10108	9302.2	06/04/2022	WHS	
#REF!	SBA	John Mitchel Place	01	Gaskets	Gasket to front pipework - Pump 3	Textiles & Paper	Chrysotile	Enclosed	Low	Remove	Re-inspection	HSG227	Unchecked	Low Risk	5	15/09/2023	Identified	Very Low Risk	89454	BA10108	9302.2	06/04/2022	WHS	
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Paper to insulation above heating panel to corridor	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	89455	BA10140		01/02/2020		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Debris to ceiling void	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	89456	BA10150		09/02/2020		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Floor tile to dry riser	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	89457	BA10150		09/02/2020		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Floor covering to landing	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	89458	BA10150		09/02/2020		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Skirting trim to landing	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	89459	BA10150		09/02/2020		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Firebreak above door to landing	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	89460	BA10150		09/02/2020		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Stair nosings to all levels	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	89461	BA10150		09/02/2020		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Firebreak over door to landing	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	89462	BA10150		10/02/2020		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Firebreak above door to landing	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	89463	BA10150		09/02/2020		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Firebreak above door to landing	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	89464	BA10150		09/02/2020		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Floor covering to landing basement	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	89465	BA10150		09/02/2020		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Skirting trim to landing basement	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	89466	BA10150		09/02/2020		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Mesh and plaster to ceiling void to landing basement level	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	89467	BA10150		09/02/2020		
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Wall panel to Haematology Laboratory RHS	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90708	BA10151		07/02/2020		
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Skirting trim to Haematology Laboratory RHS	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90709	BA10151		07/02/2020		
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Speckled floor covering to Haematology Laboratory	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90710	BA10151		07/02/2020		
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Light green floor covering to Haematology Laboratory	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90711	BA10151		07/02/2020		
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Wall panel to Haematology Laboratory LHS	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90712	BA10151		07/02/2020		
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Lagging to pipework within ceiling void to Haematolotv Laboratorv	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90713	BA10151		07/02/2020		
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Insulation to top of heating panel to Haematolotv Laboratorv	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90714	007		07/02/2020		
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Wall panel to rear wall Clinical Chemistrv Laboratorv	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90715	BA10151		07/02/2020		
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Wall panel to wash up room	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90716	BA10151		07/02/2020		
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Brown floor covering to wash up room	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90717	BA10151		07/02/2020		
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Blue floor covering to wash up room	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90718	BA10151		07/02/2020		
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Grey skirting trim to wash up room	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90719	BA10151		07/02/2020		
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Boxing at high level to wash room	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90720	BA10151		07/02/2020		
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Wall panel to Autoclave room	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90721	BA10151		07/02/2020		
#REF!	SAA	Daisy Hill Hospital Estate	01	NO ASBESTOS	Floor covering to Autoclave room	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90722	BA10151		07/02/2020		
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Panel at high level to basement plant room	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90723	BA10143		06/02/2020		
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Floor covering to electrical riser at rear of theatres	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90724	BA10143		06/02/2020		
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Infill to electrical riser	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90725	BA10143		06/02/2020		
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Panel at high level to plant room	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90726	BA10143		06/02/2020		
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Coating to cladding at vent trunking roof level	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90727	BA10143		06/02/2020		
#REF!	RAA	South Tyrone Hospital	17								Error Entry	HSG227	Unchecked		0				90728					
#REF!	RSA	Dungannon Clinic	01	NO ASBESTOS	Lagging to pipe penetration to heating unit 1	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90729	BA10152		09/02/2020		
#REF!	RSA	Dungannon Clinic	01	NO ASBESTOS	Backing panel to heating unit 1 waiting area	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90730	BA10152		09/02/2020		
#REF!	RSA	Dungannon Clinic	01	NO ASBESTOS	Lagging to pipe penetration to heating unit 2	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90731	BA10152		09/02/2020		
#REF!	RSA	Dungannon Clinic	01	NO ASBESTOS	Backing panel to heating unit 2	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90732	BA10152		09/02/2020		
#REF!	RAE	Drumglass Site	01	NO ASBESTOS	Sink pad	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90733	BA10160		14/02/2020		
#REF!	RAE	Drumglass Site	01	NO ASBESTOS	Wall panel to wall to 031	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90734	BA10160		14/02/2020		
#REF!	RAE	Drumglass Site	01	NO ASBESTOS	Lagging to pipe work	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90735	BA10160		14/02/2020		
#REF!	RAE	Drumglass Site	01	NO ASBESTOS	Ceiling panel	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90736	BA10160		14/02/2020		

#REF!	RAE	Drumglass Site	01	NO ASBESTOS	Floor covering	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90737	BA10160	14/02/2020
#REF!	RAE	Drumglass Site	01	NO ASBESTOS	Ceiling panel	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90738	BA10160	14/02/2020
#REF!	RAE	Drumglass Site	01	NO ASBESTOS	Wall panel to wall to 032	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90739	BA10160	14/02/2020
#REF!	RAE	Drumglass Site	01	NO ASBESTOS	Floor covering	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90740	BA10160	14/02/2020
#REF!	RAE	Drumglass Site	01	NO ASBESTOS	Ceiling panel	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90741	BA10160	14/02/2020
#REF!	RAE	Drumglass Site	01	NO ASBESTOS	Lagging to pipework	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90742	BA10160	14/02/2020
#REF!	RAE	Drumglass Site	01	NO ASBESTOS	Textured coating to outer wall panel	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90743	BA10160	14/02/2020
#REF!	RAE	Drumglass Site	01	NO ASBESTOS	Textured coating to outer wall panel	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90744	BA10160	14/02/2020
#REF!	RHA	Roxborough Site	01	NO ASBESTOS	Residue to wall 1	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90787	BA10161	14/02/2020
#REF!	RHA	Roxborough Site	01	NO ASBESTOS	Residue to wall 1	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90788	BA10161	14/02/2020
#REF!	RHA	Roxborough Site	01	NO ASBESTOS	Residue to wall 1	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90789	BA10161	14/02/2020
#REF!	RHA	Roxborough Site	01	NO ASBESTOS	Residue to wall 2	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90790	BA10161	14/02/2020
#REF!	RHA	Roxborough Site	01	NO ASBESTOS	Residue to wall 2	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90791	BA10161	14/02/2020
#REF!	RHA	Roxborough Site	01	NO ASBESTOS	Residue to wall 3	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90792	BA10161	14/02/2020
#REF!	RHA	Roxborough Site	01	NO ASBESTOS	Residue to wall 3	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90793	BA10161	14/02/2020
#REF!	RHA	Roxborough Site	01	NO ASBESTOS	Residue to wall 4	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90794	BA10161	14/02/2020
#REF!	RHA	Roxborough Site	01	NO ASBESTOS	Residue to wall 4	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90795	BA10161	14/02/2020
#REF!	RHA	Roxborough Site	01	NO ASBESTOS	Residue to wall 4	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90796	BA10161	14/02/2020
#REF!	RHA	Roxborough Site	01	NO ASBESTOS	Residue to floor	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90797	BA10161	14/02/2020
#REF!	RHA	Roxborough Site	01	Debris Material	Debris to floor	Loose Asbestos	Amosite	Asbestos Containinre Dust	Medium	Remove (Controlled Conditions)	New Incident	HSG227	Unchecked	Hioh Risk	10	29/09/2020	Identified	Hioh Risk	90798	BA10161	14/02/2020
#REF!	RHA	Roxborough Site	01	NO ASBESTOS	Debris to floor	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90799	BA10161	14/02/2020
#REF!	RHA	Roxborough Site	01	NO ASBESTOS	Debris to floor	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90800	BA10161	14/02/2020
#REF!	RHA	Roxborough Site	01	NO ASBESTOS	Debris to floor	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90801	BA10161	14/02/2020
#REF!	RHA	Roxborough Site	01	NO ASBESTOS	Debris to floor	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90802	BA10161	14/02/2020
#REF!	RHA	Roxborough Site	01	NO ASBESTOS	Gasket to burner 2	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90803	BA10161	14/02/2020
#REF!	RHA	Roxborough Site	01	NO ASBESTOS	Gasket of burner 1	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90804	BA10161	14/02/2020
#REF!	RHA	Roxborough Site	01	NO ASBESTOS	Packer material	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90805	BA10161	14/02/2020
#REF!	RHA	Roxborough Site	01	NO ASBESTOS	Debris to worktop	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90806	BA10161	14/02/2020
#REF!	RHA	Roxborough Site	01	NO ASBESTOS	Soffit to storerooms	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90807	BA10161	14/02/2020
#REF!	RHA	Roxborough Site	01	NO ASBESTOS	Soffit to storerooms at doors to stores	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90808	BA10161	14/02/2020
#REF!	RHA	Roxborough Site	01	NO ASBESTOS	Ceiling to storerooms	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90809	BA10161	14/02/2020
#REF!	RHA	Roxborough Site	01	Undercloak to Roof Verge	Verge undercloak to gable end above storeroom	Cement Products	Chrysotile	Cement Sheets	None	Remove	New Incident	HSG227	Unchecked	Very Low Risk	3	30/06/2021	Identified	Very Low Risk	90810	BA10161	14/02/2020
#REF!	QAC	Lurgan Hospital	01	NO ASBESTOS	Gasket to flange at wall penetration to roof ssace	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90813	BA100297	24/06/2020
#REF!	QAC	Lurgan Hospital	01	NO ASBESTOS	Gasket to flange at wall penetration to roof ssace	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90814	BA100297	24/06/2020
#REF!	QAC	Lurgan Hospital	01	NO ASBESTOS	Sarking felt to roof	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90815	BA100297	24/06/2020
#REF!	QAC	Lurgan Hospital	01	NO ASBESTOS	Pipework insulation to roofspace	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90816	BA100297	24/06/2020
#REF!	QAC	Lurgan Hospital	01	NO ASBESTOS	Debris to roof space	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90817	BA100297	24/06/2020
#REF!	QAC	Lurgan Hospital	01	NO ASBESTOS	Debris to roof space	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90818	BA100297	24/06/2020
#REF!	QAC	Lurgan Hospital	01	NO ASBESTOS	Debris to roof space	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90819	BA100297	24/06/2020
#REF!	QAC	Lurgan Hospital	01	NO ASBESTOS	Debris to roof space	NO ASBESTOS	NO ASBESTOS			No further action required (Asbestos removed)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90820	BA100297	24/06/2020
#REF!	QAC	Lurgan Hospital	01	NO ASBESTOS	Lath and plaster to roof space	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90821	BA100297	24/06/2020
#REF!	QAC	Lurgan Hospital	01	NO ASBESTOS	Floor covering	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90822	BA100297	24/06/2020
#REF!	QAC	Lurgan Hospital	01	NO ASBESTOS	Door saddle strip (representative)	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90823	BA100297	24/06/2020
#REF!	QAC	Lurgan Hospital	01	NO ASBESTOS	Floor covering to corridor	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90824	BA100297	24/06/2020
#REF!	QAC	Lurgan Hospital	01	NO ASBESTOS	Floor covering	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90825	BA100297	24/06/2020
#REF!	QAC	Lurgan Hospital	01	NO ASBESTOS	Floor covering	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90826	BA100297	24/06/2020
#REF!	QAC	Lurgan Hospital	01	NO ASBESTOS	Floor covering	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90827	BA100297	24/06/2020
#REF!	QAC	Lurgan Hospital	01	Door Panel	Panelling around door to 076	Insulating Board	NO ASBESTOS	Consealed Asbestos Insulation Board	Low	No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0		Identified	Asbestos Removed	90828	BA100297	24/06/2020
#REF!	QAC	Lurgan Hospital	01	NO ASBESTOS	Floor covering to bathroom and toilet	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90829	BA100297	24/06/2020
#REF!	QAC	Lurgan Hospital	01	NO ASBESTOS	Bath panel	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90830	BA100297	24/06/2020
#REF!	QAC	Lurgan Hospital	01	NO ASBESTOS	Floor covering	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90831	BA100297	24/06/2020
#REF!	QAC	Lurgan Hospital	01	NO ASBESTOS	Door saddle strip (representative)	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90832	BA100297	24/06/2020
#REF!	QAC	Lurgan Hospital	01	NO ASBESTOS	Floor covering to corridor	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90833	BA100297	24/06/2020
#REF!	QAC	Lurgan Hospital	01	NO ASBESTOS	Floor covering	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90834	BA100297	24/06/2020
#REF!	QAC	Lurgan Hospital	01	NO ASBESTOS	Floor covering	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90835	BA100297	24/06/2020
#REF!	QAC	Lurgan Hospital	01	NO ASBESTOS	Floor covering	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90836	BA100297	24/06/2020
#REF!	QAC	Lurgan Hospital	01	NO ASBESTOS	Floor covering	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90837	BA100297	24/06/2020
#REF!	QAC	Lurgan Hospital	01	NO ASBESTOS	Floor covering	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90838	BA100297	24/06/2020
#REF!	QAC	Lurgan Hospital	01	NO ASBESTOS	Floor covering	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90839	BA100297	24/06/2020
#REF!	QAC	Lurgan Hospital	01	NO ASBESTOS	Floor covering	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90840	BA100297	24/06/2020
#REF!	QAC	Lurgan Hospital	01	Door Panel	Panelling around door to 077	Insulating Board	NO ASBESTOS	Enclosed Asbestos Insulation Board	Low	No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	06/07/2021	Identified	Asbestos Removed	90841	BA100297	24/06/2020
#REF!	QAC	Lurgan Hospital	01	NO ASBESTOS	Floor covering to bathroom and toilet	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90842	BA100297	24/06/2020
#REF!	QAC	Lurgan Hospital	01	NO ASBESTOS	Floor covering to stairwell	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90843	BA100297	24/06/2020
#REF!	QAC	Lurgan Hospital	01	NO ASBESTOS	Stair nosings	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90844	BA100297	24/06/2020
#REF!	QAC	Lurgan Hospital	01	NO ASBESTOS	Loose board at bottom of stairs	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90845	BA100297	24/06/2020
#REF!	QAC	Lurgan Hospital	01	NO ASBESTOS	Floor covering to cupboard	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90846	BA100297	24/06/2020
#REF!	QAC	Lurgan Hospital	01	NO ASBESTOS	Floor covering to bathroom	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90847	BA100297	24/06/2020
#REF!	QAC	Lurgan Hospital	01	Door Panel	Panelling around door to 102	Insulating Board	NO ASBESTOS	Consealed Asbestos Insulation Board	Low	No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	06/07/2021	Identified	Asbestos Removed	90848	BA100297	24/06/2020
#REF!	QAC	Lurgan Hospital	01	NO ASBESTOS	Lagging to lower vertical pipe at hoth level	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90849	BA100297	24/06/2020
#REF!	QAC	Lurgan Hospital	01	NO ASBESTOS	Lagging to middle vertical pipe at hoth level	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90850	BA100297	24/06/2020
#REF!	QAC	Lurgan Hospital	01	NO ASBESTOS	Lagging to upper vertical pipe at hoth level	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90851	BA100297	24/06/2020
#REF!	QAC	Lurgan Hospital	01	Panel	Panelling to bench	Cement Products	NO ASBESTOS	Partially Sealed Cement	Low	No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	06/07/2021	Identified	Asbestos Removed	90852	BA100297	24/06/2020
#REF!	QAC	Lurgan Hospital	01	NO ASBESTOS	Bitumen screed at door saddle	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90853	BA100297	24/06/2020

#REF!	QAC	Lurgan Hospital	01	NO ASBESTOS	Floor covering to corridor	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90854	BA100297		24/06/2020		
#REF!	QAC	Lurgan Hospital	01	Ironino Board Hot Plate	Ironino board oad to kitchen	Cement Products	Chrysotile	Cement Sheets	Low	Conduct annual routine insoections	Re-inspection	HSG227	Unchecked	Very Low Risk	4	29/07/2021	Identified	Very Low Risk	90855	BA100297	[illegible]	22/07/2020	WHS	
#REF!	QAC	Lurgan Hospital	01	NO ASBESTOS	Sink pad to kitchen	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90856	BA100297		24/06/2020		
#REF!	QAC	Lurgan Hospital	01	NO ASBESTOS	Floor covering to kitchen	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90857	BA100297		24/06/2020		
#REF!	QAC	Lurgan Hospital	01	NO ASBESTOS	Lagging to lower pipe at high level	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90858	BA100297		24/06/2020		
#REF!	QAC	Lurgan Hospital	01	NO ASBESTOS	Lagging to upper pipe at high level	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90859	BA100297		24/06/2020		
#REF!	QAC	Lurgan Hospital	01	NO ASBESTOS	Floor covering	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90860	BA100297		24/06/2020		
#REF!	QAC	Lurgan Hospital	01	NO ASBESTOS	Floor covering	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90861	BA100297		24/06/2020		
#REF!	QAC	Lurgan Hospital	01	NO ASBESTOS	Lagging to pipework at high level to corridor	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90862	BA100297		24/06/2020		
#REF!	NAB	St.Lukes	12	NO ASBESTOS	Gasket to horizontal flange rear of oumo Nr 1 nearest door	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90866	BA10162		14/02/2020		
#REF!	NAB	St.Lukes	12	NO ASBESTOS	Gasket to vertical flange rear of oumo Nr 1 nearest door	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90867	BA10162		14/02/2020		
#REF!	NAB	St.Lukes	12	NO ASBESTOS	Gasket to vertical flange rear of oumo Nr 2	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90868	BA10162		14/02/2020		
#REF!	NAB	St.Lukes	12	NO ASBESTOS	Gasket to horizontal flange rear of oumo Nr 2	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90869	BA10162		14/02/2020		
#REF!	NAB	St.Lukes	12	Gaskets	Gasket to horizontal flange rear of oumo Nr 3	Textiles & Paper	Chrysotile	Enclosed Spray or Laoaino/Sealed ACM	Low	Remove	Error Entry	HSG227	Unchecked	Low Risk	5	20/07/2021	Identified	Low Risk	90870	BA10162		14/02/2020		
#REF!	NAB	St.Lukes	12	NO ASBESTOS	Mastic pump Nr 3	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90871	BA10162		14/02/2020		
#REF!	NAB	St.Lukes	12	Gaskets	Gasket to horizontal flange rear of oumo Nr 4	Textiles & Paper	Chrysotile	Enclosed Spray or Laoaino/Sealed ACM	Low	Remove	New Incident	HSG227	Unchecked	Low Risk	5	20/07/2021	Identified	Low Risk	90872	BA10162		14/02/2020		
#REF!	NAB	St.Lukes	12	NO ASBESTOS	Gasket to stop can of pump Nr 4	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90873	BA10162		14/02/2020		
#REF!	NAB	St.Lukes	12	Gaskets	Gasket to horizontal flange rear of oumo Nr 5	Textiles & Paper	Chrysotile	Enclosed Spray or Laoaino/Sealed ACM	Low	Remove	New Incident	HSG227	Unchecked	Low Risk	5	20/07/2021	Identified	Low Risk	90874	BA10162		14/02/2020		
#REF!	NAB	St.Lukes	12	Gaskets	Gasket to horizontal flange rear of oumo Nr 6	Textiles & Paper	Chrysotile	Enclosed Spray or Laoaino/Sealed ACM	Low	Remove	New Incident	HSG227	Unchecked	Low Risk	5	20/07/2021	Identified	Low Risk	90875	BA10162		14/02/2020		
#REF!	NAB	St.Lukes	12	NO ASBESTOS	Debris to cable tray to front of plinth	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Original Survey	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90876	BA10162		14/02/2020		
#REF!	NAB	St.Lukes	12	General Debris	Debris to cable tray to front of plinth	General Debris	NO ASBESTOS	Loose Asbestos Debris	Loose asbestos debris or residue	No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	19/10/2020	Identified	Asbestos Removed	90877	BA10162		14/02/2020		
#REF!	NAB	St.Lukes	12	NO ASBESTOS	Redundant gasket between pumps 8 & 9	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90878	BA10162		14/02/2020		
#REF!	RAB	Longstone/Mullinure	38	NO ASBESTOS	Debris to riser mid room	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90879	BA10169		20/02/2020		
#REF!	RAB	Longstone/Mullinure	38	NO ASBESTOS	Debris to riser corner of room	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90880	BA10169		20/02/2020		
#REF!	RAB	Longstone/Mullinure	38	NO ASBESTOS	Insulation and paper to corridor ceilino void	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90881	BA10169		20/02/2020		
#REF!	RAB	Longstone/Mullinure	38	NO ASBESTOS	Floor covering to corridor	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90882	BA10169		20/02/2020		
#REF!	RAB	Longstone/Mullinure	38	NO ASBESTOS	Green floor covering	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90883	BA10169		20/02/2020		
#REF!	RAB	Longstone/Mullinure	38	NO ASBESTOS	Blue floor covering	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90884	BA10169		20/02/2020		
#REF!	RAB	Longstone/Mullinure	38	NO ASBESTOS	Skirting trim	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90885	BA10169		20/02/2020		
#REF!	RAB	Longstone/Mullinure	38	NO ASBESTOS	Sealant to vent trunking	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90886	BA10169		20/02/2020		
#REF!	RAB	Longstone/Mullinure	38	NO ASBESTOS	Ceiling tile to main corridor	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90887	BA10169		20/02/2020		
#REF!	RAB	Longstone/Mullinure	38	NO ASBESTOS	Debris to ceiling void at front door	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90888	BA10169		20/02/2020		
#REF!	RAB	Longstone/Mullinure	38	NO ASBESTOS	Rope seal to cooker in kitchen	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90889	BA10169		20/02/2020		
#REF!	RAB	Longstone/Mullinure	38	NO ASBESTOS	Floor covering to kitchen	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90890	BA10169		20/02/2020		
#REF!	RAB	Longstone/Mullinure	38	NO ASBESTOS	Skirting trim to kitchen	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90891	BA10169		20/02/2020		
#REF!	RAB	Longstone/Mullinure	38	NO ASBESTOS	Debris to riser	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90892	BA10169		20/02/2020		
#REF!	OAC	Lurgan Hospital	01	Door Panel	Panel to access door warm roll	Insulatino Board	Presumed Asbestos	Unsealed Board	Low	Conduct annual routine insoections	New Incident	HSG227	Unchecked	Medium Risk	8	29/07/2021	Stronolv Presumed	Medium Risk	90893			22/07/2020		
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Firebreak above door to waiting room	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90900	BA10227		13/03/2020		
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Firebreak above double doors to corridor	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90901	BA10227		13/03/2020		
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Panel above window to link corridor	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90902	BA10227		13/03/2020		
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Debris to enclosed cable tray to link corridor	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90903	BA10227		13/03/2020		
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Debris to ceiling void lift lobby	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90904	BA10227		13/03/2020		
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Debris to ceiling void top of light housina	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90905	BA10227		13/03/2020		
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Debris to ceiling void to corridor	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90906	BA10227		13/03/2020		
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Debris to ceiling void beside electrical switchroom	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90907	BA10227		13/03/2020		
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Debris to ceiling void adjacent to admissions office	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90908	BA10227		13/03/2020		
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Debris to ceiling void to corridor beside gent's toilet	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90909	BA10227		13/03/2020		
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Debris to trunking	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90910	BA10227		13/03/2020		
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Wrap to pipe insulation	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90911	BA10227		13/03/2020		
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Mastic to trunking to roof void	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90912	BA10227		13/03/2020		
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Firebreak above door leading to A-002	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90913	BA10227		13/03/2020		
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Board to wall within roof void	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90914	BA10227		13/03/2020		
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Debris to ceiling tile	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90915	BA10227		13/03/2020		
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Debris to ceiling tile	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90916	BA10227		13/03/2020		
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Debris to ceiling tile	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90917	BA10227		13/03/2020		
#REF!	RAA	South Tyrone Hospital	17	Textiles & Paper	Cloth wrap to pipe end	Textiles & Paper	Chrysotile	Enclosed Woven Textile	Medium	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	Low Risk	6	13/12/2023	Identified	Low Risk	90918	BA10227	[illegible]	13/12/2022	WHS	
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Mastic to vent trunking to roof void	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90919	BA10227		13/03/2020		
#REF!	RAA	South Tyrone Hospital	17	Ropes	Rope to pipe bracket to roof void	Textiles & Paper	Chrysotile	Encapsulated Rope	Low	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	Low Risk	5	13/12/2023	Identified	Low Risk	90920	BA10227	[illegible]	13/12/2022	WHS	
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Debris to ceiling tile	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90921	BA10227		13/03/2020		
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Debris to ceiling tile	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90922	BA10227		13/03/2020		
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Firebreak above door leading to D-009	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90923	BA10227		13/03/2020		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Outer wall panels to ceiling void	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90924	BA10221		13/03/2020		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Wall panels to ceiling void	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90925	BA10221		13/03/2020		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Panel to access hatch to roof space	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90926	BA10221		13/03/2020		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Debris to ceiling void	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90927	BA10221		13/03/2020		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Debris to ceiling void to link corridor	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90928	BA10221		13/03/2020		
#REF!	QAA	Craigavon Hospital	01	NO ASBESTOS	Ceiling tile to link corridor	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90929	BA10221		13/03/2020		
#REF!	QAA	Craigavon Hospital	01	Cloth	Cloth between pipework and bracket to ceilino void	Textiles & Paper	Chrysotile	Unsealed Rope	Low	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	Low Risk	6	16/09/2023	Identified	Low Risk	90930	BA10221	9302.22	16/09/2022	WHS	
#REF!	QAA	Craigavon Hospital	01	Cloth	Cloth between pipework and bracket to ceilino void	Textiles & Paper	Chrysotile	Unsealed Rope	Low	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	Low Risk	6	16/09/2023	Identified	Low Risk	90931	BA10221	9302.22	16/09/2022	WHS	
#REF!	QAA	Craigavon Hospital	01	Cloth	Cloth between pipework and bracket to ceilino void	Textiles & Paper	Chrysotile	Unsealed Rope	Low	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	Low Risk	6	16/09/2023	Identified	Low Risk	90932	BA10221	9302.22	16/09/2022	WHS	
#REF!	QAA	Craigavon Hospital	01	Cloth	Cloth between pipework and bracket to ceilino void	Textiles & Paper	Chrysotile	Unsealed Rope	Low	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	Low Risk	6	16/09/2023	Identified	Low Risk	90933	BA10221	9302.22	16/09/2022	WHS	
#REF!	QAA	Craigavon Hospital	01	Cloth	Cloth debris to ceilino void	Textiles & Paper	Chrysotile	Unsealed Rope	Low	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	Low Risk	6	16/09/2023	Identified	Low Risk	90934	BA10221	[illegible]	16/09/2022	WHS	
#REF!	QAA	Craigavon Hospital	01	Cloth	Cloth between pipework and bracket to ceilino void	Textiles & Paper	Chrysotile	Unsealed Rope	Low	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	Low Risk	6	16/09/2023	Identified	Low Risk	90935	BA10221	9302.22	16/09/2022	WHS	
#REF!	QAA	Craigavon Hospital	01	Cloth	cloth between pipework and bracket to ceilino void	Textiles & Paper	Chrysotile	Unsealed Rope	Low	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	Low Risk	6	16/09/2023	Identified	Low Risk	90936	BA10221	9302.22	16/09/2022	WHS	
#REF!	QAA	Craigavon Hospital	01	Cloth	Cloth between pipework and bracket to ceilino void	Textiles & Paper	Chrysotile	Unsealed Rope	Low	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	Low Risk	6	16/09/2023	Identified	Low Risk	90937	BA10221	9302.22	16/09/2022	WHS	

#REF!	QAA	Craigavon Hospital	01	Cloth	Cloth between pipework and bracket to ceilino void	Textiles & Paper	Chrysotile	Unsealed Rope	Low	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	Low Risk	6	16/09/2023	Identified	Low Risk	90938	BA10221	9302.22	16/09/2022	WHS
#REF!	SJB	Needham House	01	NO ASBESTOS	Debris to electrical panel	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90939	BA10209		11/03/2020	
#REF!	SJC	Millview Resource Centre	01	NO ASBESTOS	Debris to electrical panel	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90940	BA10210		11/03/2020	
#REF!	SHB	Cloughreagh House	01	NO ASBESTOS	Debris to electrical panel	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	90941	BA10211		11/03/2020	
#REF!	RAA	South Tyrone Hospital	15	NO ASBESTOS	Vinyl floor covering	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	91900	BA10226		19/03/2020	
#REF!	RAA	South Tyrone Hospital	15	NO ASBESTOS	Adhesive beneath floor covering	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	91901	BA10226		19/03/2020	
#REF!	RAA	South Tyrone Hospital	15	NO ASBESTOS	Debris to window cill	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	91902	BA10226		19/03/2020	
#REF!	RAA	South Tyrone Hospital	15	NO ASBESTOS	Debris to window cill	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	91903	BA10226		19/03/2020	
#REF!	RAA	South Tyrone Hospital	15	NO ASBESTOS	Filler at window cill	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	91904	BA10226		19/03/2020	
#REF!	RAA	South Tyrone Hospital	15	NO ASBESTOS	Floor covering	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	91905	BA10226		19/03/2020	
#REF!	RAA	South Tyrone Hospital	15	NO ASBESTOS	Adhesive beneath floor covering	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	91906	BA10226		19/03/2020	
#REF!	RAA	South Tyrone Hospital	15	NO ASBESTOS	Debris to floor covering	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	91907	BA10226		19/03/2020	
#REF!	RAA	South Tyrone Hospital	15	NO ASBESTOS	Debris to floor	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	91908	BA10226		19/03/2020	
#REF!	RAA	South Tyrone Hospital	15	NO ASBESTOS	Debris to floor	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	91909	BA10226		19/03/2020	
#REF!	RAA	South Tyrone Hospital	15	NO ASBESTOS	Floor covering	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	91910	BA10226		19/03/2020	
#REF!	RAA	South Tyrone Hospital	15	NO ASBESTOS	Floor covering	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	91911	BA10226		19/03/2020	
#REF!	RAA	South Tyrone Hospital	15	NO ASBESTOS	Ceiling tile	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	91912	BA10226		19/03/2020	
#REF!	RAA	South Tyrone Hospital	15	NO ASBESTOS	Debris to ceiling	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	91913	BA10226		19/03/2020	
#REF!	QAA	Craigavon Hospital	12	NO ASBESTOS	Debris to ceiling void above toilet to male chanaina room behind	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	91914	BAC100230		09/04/2020	
#REF!	QAA	Craigavon Hospital	12	NO ASBESTOS	Toilet cistern ceiling void above toilet to male chanaina room behind	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	91915	BAC100230		09/04/2020	
#REF!	QAA	Craigavon Hospital	12	NO ASBESTOS	Redundant toilet cistern to ceiling void above female chanaina room	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	91916	BAC100230		09/04/2020	
#REF!	QAA	Craigavon Hospital	12	NO ASBESTOS	Redundant toilet cistern to ceiling void above female chanaina room	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	91917	BAC100230		09/04/2020	
#REF!	QAA	Craigavon Hospital	12	NO ASBESTOS	Hair felt lagging to ceiling void above female chanaina room	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	91918	BAC100230		09/04/2020	
#REF!	QAA	Craigavon Hospital	12	NO ASBESTOS	Lining to wall panels throughout ceilino void	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	91919	BAC100230		09/04/2020	
#REF!	QAA	Craigavon Hospital	12	NO ASBESTOS	Floor covering to main corridor	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	91920	BAC100230		09/04/2020	
#REF!	QAA	Craigavon Hospital	12	NO ASBESTOS	Skirting trim to main corridor	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	91921	BAC100230		09/04/2020	
#REF!	QAA	Craigavon Hospital	12	NO ASBESTOS	Floor covering to staff kitchen	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	91922	BAC100230		09/04/2020	
#REF!	QAA	Craigavon Hospital	12	NO ASBESTOS	Sink pad to staff kitchen	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	91923	BAC100230		09/04/2020	
#REF!	QAA	Craigavon Hospital	12	NO ASBESTOS	Floor covering to female changing room	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	91924	BAC100230		09/04/2020	
#REF!	QAA	Craigavon Hospital	12	NO ASBESTOS	Skirting trim to female changing room toilet	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	91925	BAC100230		09/04/2020	
#REF!	QAA	Craigavon Hospital	12	NO ASBESTOS	Panel to back of toilet to female chanaina room toilet	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	91926	BAC100230		09/04/2020	
#REF!	QAA	Craigavon Hospital	12	NO ASBESTOS	Floor covering to male changing room toilet behind receotion	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	91927	BAC100230		09/04/2020	
#REF!	QAA	Craigavon Hospital	12	NO ASBESTOS	Wall tile to male changing room toilet behind receotion	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	91928	BAC100230		09/04/2020	
#REF!	QAA	Craigavon Hospital	12	NO ASBESTOS	Blue floor covering to recovery area	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	91929	BAC100230		09/04/2020	
#REF!	QAA	Craigavon Hospital	12	NO ASBESTOS	Grey floor covering to recovery area	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	91930	BAC100230		09/04/2020	
#REF!	QAA	Craigavon Hospital	12	NO ASBESTOS	Sink pad to theatres sluice room	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	91931	BAC100230		09/04/2020	
#REF!	QAA	Craigavon Hospital	12	NO ASBESTOS	Floor covering to endoscopy room	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	91932	BAC100230		09/04/2020	
#REF!	NAB	St.Lukes	12	Rope Seal	Rope gasket between outer and	Textiles & Paper	Chrysotile	Encapsulated Rope	Low	Remove	Correctino previous data entry error	HSG227	Unchecked	Low Risk	5	11/08/2021	Identified	Low Risk	91933	BAC100235		23/04/2020	
#REF!	NAB	St.Lukes	12	NO ASBESTOS	Rope seal to rear of boiler	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	91934	BAC100235		23/04/2020	
#REF!	NAB	St.Lukes	12	Gaskets	Horizontal gasket to stop cap left hand side of boiler at chest heiaht	Textiles & Paper	Chrysotile	Sealed Rope	Low	Remove	New Incident	HSG227	Unchecked	Low Risk	5	11/08/2021	Identified	Low Risk	91935	BAC100235		23/04/2020	
#REF!	NAB	St.Lukes	12	Gaskets	Vertical gasket to stop cap left hand side of boiler at hath level	Textiles & Paper	Chrysotile	Sealed Rope	Low	Remove	New Incident	HSG227	Unchecked	Low Risk	5	11/08/2021	Identified	Low Risk	91936	BAC100235		23/04/2020	
#REF!	NAB	St.Lukes	12	NO ASBESTOS	Gasket left hand side 1 of 3 above boiler	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	91937	BAC100235		23/04/2020	
#REF!	NAB	St.Lukes	12	NO ASBESTOS	Residue to flange above boiler	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	91938	BAC100235		23/04/2020	
#REF!	NAB	St.Lukes	12	Gaskets	Gasket middle 1 of 3 above boiler	Textiles & Paper	Chrysotile	Sealed Rope	Low	Remove	New Incident	HSG227	Unchecked	Low Risk	5	11/08/2021	Identified	Low Risk	91939	BAC100235		23/04/2020	
#REF!	NAB	St.Lukes	12	Gaskets	Gasket right hand side 1 of 3 above boiler	Textiles & Paper	Chrysotile	Sealed Rope	Low	Remove	New Incident	HSG227	Unchecked	Low Risk	5	11/08/2021	Identified	Low Risk	91940	BAC100235		23/04/2020	
#REF!	NAB	St.Lukes	12	NO ASBESTOS	Horizontal gasket to right hand side above boiler	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	91941	BAC100235		23/04/2020	
#REF!	NAB	St.Lukes	12	Gaskets	Single vertical gasket above boiler towards front	Textiles & Paper	Chrysotile	Sealed Rope	Low	Remove	New Incident	HSG227	Unchecked	Low Risk	5	11/08/2021	Identified	Low Risk	91942	BAC100235		23/04/2020	
#REF!	NAB	St.Lukes	12	NO ASBESTOS	Gasket debris to top of boiler	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	91943	BAC100235		23/04/2020	
#REF!	NAB	St.Lukes	12	NO ASBESTOS	Rope seal to front of boiler	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	91944	BAC100235		23/04/2020	
#REF!	NAB	St.Lukes	12	NO ASBESTOS	Gasket to pump at low level right hand side of boiler	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	91945	BAC100235		23/04/2020	
#REF!	NAB	St.Lukes	12	NO ASBESTOS	Gasket to pump at low level right hand side of boiler	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	91946	BAC100235		23/04/2020	
#REF!	NAB	St.Lukes	12	NO ASBESTOS	Gasket debris to floor to rear of boiler	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	91947	BAC100235		23/04/2020	
#REF!	NAB	St.Lukes	12	NO ASBESTOS	Residue to boiler barrel	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	91948	BAC100235		23/04/2020	
#REF!	NAB	St.Lukes	12	NO ASBESTOS	Residue to boiler barrel	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	91949	BAC100235		23/04/2020	
#REF!	NAB	St.Lukes	12	NO ASBESTOS	Residue to boiler barrel	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	91950	BAC100235		23/04/2020	
#REF!	NAB	St.Lukes	12	NO ASBESTOS	Residue to boiler barrel	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	91951	BAC100235		23/04/2020	
#REF!	NAB	St.Lukes	12	NO ASBESTOS	Debris to electrical control panel right hand side of boiler	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	91952	BAC100235		23/04/2020	
#REF!	NAB	St.Lukes	12	NO ASBESTOS	Debris to plinth beneath boiler	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	91953	BAC100235		23/04/2020	
#REF!	NAB	St.Lukes	12	NO ASBESTOS	Debris to plinth beneath boiler	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	91954	BAC100235		23/04/2020	
#REF!	NAB	St.Lukes	12	NO ASBESTOS	Residue to door to front of boiler	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	91955	BAC100235		23/04/2020	
#REF!	NAB	St.Lukes	12	NO ASBESTOS	Residue to pipework above boiler	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	91956	BAC100235		23/04/2020	
#REF!	NAB	St.Lukes	12	NO ASBESTOS	Residue to flue pipe at rear of boiler	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	91957	BAC100235		23/04/2020	
#REF!	NAB	St.Lukes	12	NO ASBESTOS	Residue to flue pipe at rear of boiler	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	91958	BAC100235		23/04/2020	
#REF!	NAB	St.Lukes	12	Gaskets	Rope seal a flue penetration through	Textiles & Paper	Chrysotile	Sealed Rope	Low	Remove	Correctino previous data entry error	HSG227	Unchecked	Low Risk	5	11/08/2021	Identified	Low Risk	91959	BAC100235		23/04/2020	
#REF!	NAB	St.Lukes	12	NO ASBESTOS	Debris to floor duct left hand side of boiler	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	91960	BAC100235		23/04/2020	
#REF!	NAB	St.Lukes	12	NO ASBESTOS	Debris to floor duct to front of boiler	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	91961	BAC100235		23/04/2020	
#REF!	NAB	St.Lukes	12	NO ASBESTOS	Debris to floor duct to front of boiler	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	91962	BAC100235		23/04/2020	
#REF!	NAB	St.Lukes	12	NO ASBESTOS	Debris to floor duct right hand side of boiler	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	91963	BAC100235		23/04/2020	
#REF!	NAB	St.Lukes	12	NO ASBESTOS	Residue to wall left hand side door 1	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	91964	BAC100235		23/04/2020	
#REF!	NAB	St.Lukes	12	NO ASBESTOS	Residue to wall 2	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	91965	BAC100235		23/04/2020	
#REF!	NAB	St.Lukes	12	NO ASBESTOS	Residue to wall 2	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	91966	BAC100235		23/04/2020	
#REF!	NAB	St.Lukes	12	NO ASBESTOS	Residue to wall 3	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	91967	BAC100235		23/04/2020	
#REF!	NAB	St.Lukes	12	NO ASBESTOS	Sarking felt to roof	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	91968	BAC100235		23/04/2020	
#REF!	NAB	St.Lukes	12	Gaskets	Rope seal at flue penetration through exterior wall	Textiles & Paper	Chrysotile	Sealed Rope	Low	Remove	New Incident	HSG227	Unchecked	Low Risk	5	11/08/2021	Identified	Low Risk	91969	BAC100235		23/04/2020	

#REF!	QBA	Brownlow Health Centre	01	NO ASBESTOS	Firebreak between A-077 and A-082	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	91970	BAC100261		15/05/2020			
#REF!	QBA	Brownlow Health Centre	01	NO ASBESTOS	Debris to ceiling void at door to pharmacy shop	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	91971	BAC100261		15/05/2020			
#REF!	QBA	Brownlow Health Centre	01	NO ASBESTOS	Debris to ceiling void	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	91972	BAC100261		15/05/2020			
#REF!	QBA	Brownlow Health Centre	01	NO ASBESTOS	Firebreak above door to pharmacy	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	91973	BAC100261		15/05/2020			
#REF!	QBA	Brownlow Health Centre	01	NO ASBESTOS	Firebreak above door to store	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	91974	BAC100261		15/05/2020			
#REF!	QBA	Brownlow Health Centre	01	NO ASBESTOS	Firebreak above door	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	91975	BAC100261		15/05/2020			
#REF!	QBA	Brownlow Health Centre	01	NO ASBESTOS	Debris to ceiling void	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	91976	BAC100261		15/05/2020			
#REF!	QBA	Brownlow Health Centre	01	NO ASBESTOS	Firebreak between A-077 and A-092	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	91977	BAC100261		15/05/2020			
#REF!	QBA	Brownlow Health Centre	01	NO ASBESTOS	Firebreak above door	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	91978	BAC100261		15/05/2020			
#REF!	QBA	Brownlow Health Centre	01	NO ASBESTOS	Debris to ceiling void	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	91979	BAC100261		15/05/2020			
#REF!	QBA	Brownlow Health Centre	01	NO ASBESTOS	Debris to ceiling void	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	91980	BAC100261		15/05/2020			
#REF!	QBA	Brownlow Health Centre	01	NO ASBESTOS	Bulkhead panelling to external trolley store	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	91981	BAC100261		15/05/2020			
#REF!	QBA	Brownlow Health Centre	01	NO ASBESTOS	Firebreak between A-002 and A-077	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	91982	BAC100261		15/05/2020			
#REF!	QBA	Brownlow Health Centre	01	NO ASBESTOS	Skylight over main entrance	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	91983	BAC100261		15/05/2020			
#REF!	QBA	Brownlow Health Centre	01	NO ASBESTOS	Debris to ceiling void	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	91984	BAC100261		15/05/2020			
#REF!	QBA	Brownlow Health Centre	01	NO ASBESTOS	Purple wall panelling to corridor	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	91985	BAC100261		15/05/2020			
#REF!	QBA	Brownlow Health Centre	01	NO ASBESTOS	Panelling to skylight	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	91986	BAC100261		15/05/2020			
#REF!	QBA	Brownlow Health Centre	01	NO ASBESTOS	Panelling to beam	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	91987	BAC100261		15/05/2020			
#REF!	QBA	Brownlow Health Centre	01	NO ASBESTOS	Firebreak between A-025 and A-023	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	91988	BAC100261		15/05/2020			
#REF!	QBA	Brownlow Health Centre	01	NO ASBESTOS	Older type ceiling tile throughout	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	91989	BAC100261		15/05/2020			
#REF!	QBA	Brownlow Health Centre	01	NO ASBESTOS	Debris to ceiling void	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	91990	BAC100261		15/05/2020			
#REF!	QBA	Brownlow Health Centre	01	NO ASBESTOS	Packer to beam	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	91991	BAC100261		15/05/2020			
#REF!	QBA	Brownlow Health Centre	01	NO ASBESTOS	Debris to ceiling tile	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	91992	BAC100261		15/05/2020			
#REF!	QBA	Brownlow Health Centre	01	NO ASBESTOS	Bulkhead panelling to large skylight	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	91993	BAC100261		15/05/2020			
#REF!	QBA	Brownlow Health Centre	01	NO ASBESTOS	Firebreak between A-039 and A-041	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	91994	BAC100261		15/05/2020			
#REF!	QBA	Brownlow Health Centre	01	NO ASBESTOS	Firebreak between A-039 and A-033	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	91995	BAC100261		15/05/2020			
#REF!	QBA	Brownlow Health Centre	01	NO ASBESTOS	Debris to cable housing to riser	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	91996	BAC100261		15/05/2020			
#REF!	QBA	Brownlow Health Centre	01	NO ASBESTOS	Debris to floor of riser	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	91997	BAC100261		15/05/2020			
#REF!	QBA	Brownlow Health Centre	01	NO ASBESTOS	Debris to ceiling void	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	91998	BAC100261		15/05/2020			
#REF!	QBA	Brownlow Health Centre	01	NO ASBESTOS	Pipework lagging to ceiling void	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	91999	BAC100261		15/05/2020			
#REF!	QBA	Brownlow Health Centre	01	NO ASBESTOS	Debris to ceiling void	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92000	BAC100261		15/05/2020			
#REF!	QBA	Brownlow Health Centre	01	NO ASBESTOS	Firebreak between A-055 and A-059	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92001	BAC100261		15/05/2020			
#REF!	QBA	Brownlow Health Centre	01	NO ASBESTOS	QBA-01-C-002 - DPC between top of wall and concrete slab to water tank room	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Photographs Added	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92002	BAC100261		15/05/2020			
#REF!	QBA	Brownlow Health Centre	01	NO ASBESTOS	QBA-01-C-002 - Debris to floor of water tank room	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92003	BAC100261		15/05/2020			
#REF!	QBA	Brownlow Health Centre	01	NO ASBESTOS	QBA-01-C-002 - Pipework insulation in water tank room	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92004	BAC100261		15/05/2020			
#REF!	QBA	Brownlow Health Centre	01	NO ASBESTOS	Firebreak between B-003 and B-002	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92006	BAC100261		15/05/2020			
#REF!	QBA	Brownlow Health Centre	01	NO ASBESTOS	Firebreak between B-003 and B-004	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92008	BAC100261		15/05/2020			
#REF!	QBA	Brownlow Health Centre	01	NO ASBESTOS	Firebreak above door to electrical switch room	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92009	BAC100261		15/05/2020			
#REF!	QBA	Brownlow Health Centre	01	NO ASBESTOS	QBA-01-A-001 - Debris to floor	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92010	BAC100261		15/05/2020			
#REF!	QBA	Brownlow Health Centre	01	Rope Seal	Rope seal to flue pipe penetration throuah wall of boiler house	Textiles & Paper	Chrysotile	Sealed Rope	Minor damage or deterioration	Remove (Controlled Conditions)	Re-inspection	HSG227	Unchecked	Low Risk	5	13/10/2023	Identified	Low Risk	92011	BAC100261	9299/2 2	29/09/2022	WHS		
#REF!	QBA	Brownlow Health Centre	01	Flue Pipe	Flue cioe to boiler house	Cement Products	Chrysotile	Cement Asbestos	Low	Remove	Re-inspection	HSG227	Unchecked	Verv Low Risk	4	13/10/2023	Identified	Very Low Risk	92012	BAC100261	9299/2 2	29/09/2022	WHS		
#REF!	QBA	Brownlow Health Centre	01	Rope Seal	Rope seal to flue pipe penetration throuah ceilina of boiler house	Textiles & Paper	Chrysotile	Encapsulated Rope	Low	Remove	Re-inspection	HSG227	Unchecked	Low Risk	5	13/10/2023	Identified	Low Risk	92013	BAC100261	9299/2 2	29/09/2022	WHS		
#REF!	QBA	Brownlow Health Centre	01	NO ASBESTOS	Snot to wall behind gas boilers within boiler house	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92014	BAC100261		15/05/2020			
#REF!	QBA	Brownlow Health Centre	01	NO ASBESTOS	Snot to wall 3 at high level within boiler house	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92015	BAC100261		15/05/2020			
#REF!	QBA	Brownlow Health Centre	01	NO ASBESTOS	Snot to wall 4 at mid level within boiler house	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92016	BAC100261		15/05/2020			
#REF!	QBA	Brownlow Health Centre	01	NO ASBESTOS	Snot to wall 1 at mid level within boiler house	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92017	BAC100261		15/05/2020			
#REF!	RAC	Tower Hill Site	02	NO ASBESTOS	Gasket to heat pump at window	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92018	BAC100281		15/06/2020			
#REF!	RAC	Tower Hill Site	02	NO ASBESTOS	Gasket to heat pump at window RHS	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92019	BAC100281		15/06/2020			
#REF!	RAC	Tower Hill Site	02	NO ASBESTOS	Debris to floor	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92020	BAC100281		15/06/2020			
#REF!	RAC	Tower Hill Site	02	NO ASBESTOS	Debris to floor	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92021	BAC100281		15/06/2020			
#REF!	RAC	Tower Hill Site	02	NO ASBESTOS	Sarking felt to roof	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92022	BAC100281		15/06/2020			
#REF!	RAC	Tower Hill Site	02	NO ASBESTOS	Residue to wall 2	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92023	BAC100281		15/06/2020			
#REF!	RAC	Tower Hill Site	02	NO ASBESTOS	Residue to wall 4	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92024	BAC100281		15/06/2020			
#REF!	RAC	Tower Hill Site	02	NO ASBESTOS	Residue to wall 1	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92025	BAC100281		15/06/2020			
#REF!	RAC	Tower Hill Site	02	Roof Tiles	Roof tile to plantroom	Cement Products	Chrysotile	Cement Sheets	Low	Remove	New Incident	HSG227	Unchecked	Verv Low Risk	4	12/08/2021	Identified	Verv Low Risk	92026	BAC100281		15/06/2020			
#REF!	RAC	Tower Hill Site	02	NO ASBESTOS	Residue to pipe penetration to vertical duct to rear of plantroom	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92027	BAC100281		15/06/2020			
#REF!	RAC	Tower Hill Site	01	Gaskets	Gasket to pump (representative)	Textiles & Paper	Chrysotile	Sealed Rope	Low	Remove	New Incident	HSG227	Unchecked	Low Risk	5	12/08/2021	Identified	Low Risk	92028	BAC100281		15/06/2020			
#REF!	RAC	Tower Hill Site	01	Gaskets	Gasket to pump (representative)	Textiles & Paper	Chrysotile	Sealed Rope	Low	Remove	New Incident	HSG227	Unchecked	Low Risk	5	12/08/2021	Identified	Low Risk	92029	BAC100281		15/06/2020			
#REF!	RAC	Tower Hill Site	01	Gaskets	Gasket to pump (representative)	Textiles & Paper	Chrysotile	Sealed Rope	Low	Remove	New Incident	HSG227	Unchecked	Low Risk	5	12/08/2021	Identified	Low Risk	92030	BAC100281		15/06/2020			
#REF!	RAC	Tower Hill Site	01	Gaskets	Gasket to pump (representative)	Textiles & Paper	Chrysotile	Sealed Rope	Low	Remove	New Incident	HSG227	Unchecked	Low Risk	5	12/08/2021	Identified	Low Risk	92031	BAC100281		15/06/2020			
#REF!	RAC	Tower Hill Site	01	NO ASBESTOS	Panel to beam to ceiling front	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92032	BAC100281		15/06/2020			
#REF!	RAC	Tower Hill Site	01	NO ASBESTOS	Panel to beam to ceiling mid room	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92033	BAC100281		15/06/2020			
#REF!	RAC	Tower Hill Site	01	NO ASBESTOS	Panel to beam to ceiling rear	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92034	BAC100281		15/06/2020			
#REF!	RAC	Tower Hill Site	01	Gaskets	Gasket to stop cap wall 4 adjacent to control panel	Textiles & Paper	Chrysotile	Sealed Rope	Low	Remove	New Incident	HSG227	Unchecked	Low Risk	5	12/08/2021	Identified	Low Risk	92035	BAC100281		15/06/2020			
#REF!	RAC	Tower Hill Site	01	Gaskets	Gasket to stop cap wall 4 adjacent to control panel	Textiles & Paper	Chrysotile	Sealed Rope	Low	Remove	New Incident	HSG227	Unchecked	Low Risk	5	12/08/2021	Identified	Low Risk	92036	BAC100281		15/06/2020			
#REF!	RAC	Tower Hill Site	01	NO ASBESTOS	Debris to floor	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92037	BAC100281		15/06/2020			
#REF!	RAC	Tower Hill Site	14	NO ASBESTOS	Residue to wall 2	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92038	BAC100281		15/06/2020			
#REF!	RAC	Tower Hill Site	14	NO ASBESTOS	Residue to wall 3	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92039	BAC100281		15/06/2020			
#REF!	RAC	Tower Hill Site	14	NO ASBESTOS	Debris to floor	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92040	BAC100281		15/06/2020			
#REF!	RAC	Tower Hill Site	14	NO ASBESTOS	Debris to floor	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92041	BAC100281		15/06/2020			
#REF!	RAC	Tower Hill Site	14	NO ASBESTOS	Gasket to pump flange	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92042	BAC100281		15/06/2020			
#REF!	RAC	Tower Hill Site	04	General Debris	Residue to wall 1	General Debris	NO ASBESTOS	Unsealed	High	No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	12/11/2020	Identified	Asbestos Removed	92043	BAC100281	9009/2 1	15/06/2020			
#REF!	RAC	Tower Hill Site	04	General Debris	Residue to wall 2	General Debris	NO ASBESTOS	Unsealed	High	No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	12/11/2020	Identified	Asbestos Removed	92044	BAC100281	9009/2 1	15/06/2020			
#REF!	RAC	Tower Hill Site	04	General Debris	Residue to wall 3	General Debris	NO ASBESTOS	Unsealed	High	No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	12/11/2020	Identified	Asbestos Removed	92045	BAC100281	9009/2 1	15/06/2020			
#REF!	RAC	Tower Hill Site	04	General Debris	Residue to wall 4	General Debris	NO ASBESTOS	Unsealed	High	No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	12/11/2020	Identified	Asbestos Removed	92046	BAC100281	9009/2 1	15/06/2020			

#REF!	RAC	Tower Hill Site	04	NO ASBESTOS	Residue to pipe penetration wall 3	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92047	BAC100281		15/06/2020			
#REF!	RAC	Tower Hill Site	04	NO ASBESTOS	Residue to older pipework wall 3	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92048	BAC100281		15/06/2020			
#REF!	RAC	Tower Hill Site	04	NO ASBESTOS	Strawboard to ceiling	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92049	BAC100281		15/06/2020			
#REF!	RAC	Tower Hill Site	04	General Debris	Debris to floor of duct at RHS of door	General Debris	NO ASBESTOS	Loose Asbestos Debris	Loose asbestos debris or residue		No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	12/11/2020	Identified	Asbestos Removed	92050	BAC100281	9009/21	15/06/2020			
#REF!	RAC	Tower Hill Site	04	NO ASBESTOS	Debris to floor	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92051	BAC100281		15/06/2020			
#REF!	RAC	Tower Hill Site	04	General Debris	Debris to floor	General Debris	NO ASBESTOS	Loose Asbestos Debris	Loose asbestos debris or residue		No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	12/11/2020	Identified	Asbestos Removed	92053	BAC100281	9009/21	15/06/2020			
#REF!	RAC	Tower Hill Site	03	General Debris	Residue to wall 1	General Debris	Amosite/Chrysotile	Loose Asbestos Debris	High		Remove (Controlled Conditions)	New Incident	HSG227	Unchecked	High Risk	11	12/11/2020	Identified	High Risk	92056	BAC100281		15/06/2020			
#REF!	RAC	Tower Hill Site	03	General Debris	Residue to wall 2	General Debris	Amosite/Chrysotile	Loose Asbestos Debris	Loose asbestos		Remove (Controlled Conditions)	New Incident	HSG227	Unchecked	High Risk	11	12/11/2020	Identified	High Risk	92059	BAC100281		15/06/2020			
#REF!	RAC	Tower Hill Site	03	General Debris	Residue to wall 2	General Debris	Amosite/Chrysotile	Loose Asbestos Debris	Loose asbestos		Remove (Controlled Conditions)	New Incident	HSG227	Unchecked	High Risk	11	12/11/2020	Identified	High Risk	92061	BAC100281		15/06/2020			
#REF!	RAC	Tower Hill Site	03	NO ASBESTOS	Residue to wall 3	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92063	BAC100281		15/06/2020			
#REF!	RAC	Tower Hill Site	03	NO ASBESTOS	Residue to entrance to duct to rear	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92065	BAC100281		15/06/2020			
#REF!	RAC	Tower Hill Site	03	NO ASBESTOS	Residue to wall 4	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92066	BAC100281		15/06/2020			
#REF!	RAC	Tower Hill Site	03	General Debris	Residue to beam to ceiling	General Debris	Amosite/Chrysotile	Loose Asbestos Debris	Loose asbestos		Remove (Controlled Conditions)	New Incident	HSG227	Unchecked	High Risk	11	12/11/2020	Identified	High Risk	92067	BAC100281		15/06/2020			
#REF!	RAC	Tower Hill Site	03	NO ASBESTOS	Debris to floor	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92068	BAC100281		15/06/2020			
#REF!	RAA	South Tyrone Hospital	17	Brake pad	Brake pad to lift machinery	Composite Material	Chrysotile	Enclosed	Low		Remove	Re-inspection	HSG227	Unchecked	Very Low Risk	4	14/12/2023	Identified	Very Low Risk	92078	BAC100282	[illegible]	14/12/2022		WHS	
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Panel within control panel	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92087	BAC100282		15/06/2020			
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Coil housing within control panel	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92088	BAC100282		15/06/2020			
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Panel to back of door to lift plantroom	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92089	BAC100282		15/06/2020			
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Red strip floor covering to stairs	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92090	BAC100282		15/06/2020			
#REF!	RAA	South Tyrone Hospital	17	Floor Tiles	[illegible] floor tile to stairs and lift plant	Composite Material	Chrysotile	Composite Material	Low		Remove	Re-inspection	HSG227	Unchecked	Very Low Risk	3	14/12/2023	Identified	Very Low Risk	92091	BAC100282	[illegible]	14/12/2022		WHS	
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	DPC to vent opening within lift shaft	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92092	BAC100282		15/06/2020			
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Debris to door housing within lift shaft	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92095	BAC100282		15/06/2020			
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Debris to door ledge within lift shaft	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92096	BAC100282		15/06/2020			
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Debris to door ledge within lift shaft	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92097	BAC100282		15/06/2020			
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Debris to counter weight within lift shaft	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92098	BAC100282		15/06/2020			
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Debris to door ledge within lift shaft	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92099	BAC100282		15/06/2020			
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Debris to door ledge within lift shaft	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92100	BAC100282		15/06/2020			
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Debris to door ledge within lift shaft	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92101	BAC100282		15/06/2020			
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Debris to floor pit within lift shaft	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92102	BAC100282		15/06/2020			
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Debris to floor pit within lift shaft	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92103	BAC100282		15/06/2020			
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Floor covering to lift car	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92104	BAC100282		15/06/2020			
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Debris to ceiling void lift lobby	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92105	BAC100282		15/06/2020			
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Debris to ceiling void lift lobby	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92106	BAC100282		15/06/2020			
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Debris to ceiling void lift lobby	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92107	BAC100282		15/06/2020			
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Debris to ceiling void lift lobby	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92108	BAC100282		15/06/2020			
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Debris to ceiling void lift lobby	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92109	BAC100282		15/06/2020			
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Debris to ceiling void lift lobby	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92110	BAC100282		15/06/2020			
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Debris to floor	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92111	BAC100282		15/06/2020			
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Bitumen to floor penetration	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92112	BAC100282		15/06/2020			
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Debris at floor to floor penetration	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92113	BAC100282		15/06/2020			
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Ceiling to switch room	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92114	BAC100282		15/06/2020			
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	debris to floor	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92115	BAC100282		15/06/2020			
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Debris to floor	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92116	BAC100282		15/06/2020			
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Panelling to boxing	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92117	BAC100282		15/06/2020			
#REF!	NAB	St.Lukes	14	NO ASBESTOS	Soffit to electrical switch room	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92118	BAC100324		17/07/2020			
#REF!	NAB	St.Lukes	14	NO ASBESTOS	Roof tile to electrical switch room	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92119	BAC100324		17/07/2020			
#REF!	NAB	St.Lukes	14	NO ASBESTOS	Debris to floor of electrical switchroom	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92120	BAC100324		17/07/2020			
#REF!	NAB	St.Lukes	16	Soffit Boardino	Soffit	Cement Products	Chrysotile	Cement Sheets	Low		Remove (Controlled Conditions)	New Incident	HSG227	Unchecked	Very Low Risk	4	14/08/2021	Identified	Very Low Risk	92121	BAC100324		17/07/2020			
#REF!	NAB	St.Lukes	16	NO ASBESTOS	Floor covering to electrical switch room	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92122	BAC100324		17/07/2020			
#REF!	NAB	St.Lukes	16	NO ASBESTOS	Lagging to pipe work to roof space	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92123	BAC100324		17/07/2020			
#REF!	NAB	St.Lukes	16	NO ASBESTOS	Lagging to pipework to roof space	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92124	BAC100324		17/07/2020			
#REF!	NAB	St.Lukes	16	NO ASBESTOS	Lagging to pipework to roofspace	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified		92125	BAC100324		17/07/2020			
#REF!	NAB	St.Lukes	16	NO ASBESTOS	Debris to roofspace	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92126	BAC100324		17/07/2020			
#REF!	NAB	St.Lukes	16	NO ASBESTOS	Debris to roof space	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92127	BAC100324		17/07/2020			
#REF!	NAB	St.Lukes	16	NO ASBESTOS	Debris to roof space	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92128	BAC100324		17/07/2020			
#REF!	NAB	St.Lukes	16	NO ASBESTOS	Debris to roofspace	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92129	BAC100324		17/07/2020			
#REF!	NAB	St.Lukes	16	NO ASBESTOS	Debris to cable tray roofspace	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92130	BAC100324		17/07/2020			
#REF!	NAB	St.Lukes	16	NO ASBESTOS	Ceiling to store to rear of Haven Close	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92131	BAC100324		17/07/2020			
#REF!	NAB	St.Lukes	16	NO ASBESTOS	Soffit to store to rear of Haven Close	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92132	BAC100324		17/07/2020			
#REF!	NAB	St.Lukes	16	NO ASBESTOS	Soffit to riser housing on roof to rear of Haven Close	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92133	BAC100324		17/07/2020			
#REF!	NAB	St.Lukes	16	Soffit Boards	Soffit to gable end to rear of Haven Close	Cement Products	Chrysotile	Cement Sheets	Low		Remove (Controlled Conditions)	New Incident	HSG227	Unchecked	Very Low Risk	4	14/08/2021	Identified	Very Low Risk	92134	BAC100324		17/07/2020			
#REF!	NAB	St.Lukes	16	NO ASBESTOS	Felt to flat roof to rear of Haven Close	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92135	BAC100324		17/07/2020			
#REF!	NAB	St.Lukes	16									Error Entry	HSG227	Unchecked		0				92136						
#REF!	NAB	St.Lukes	17	NO ASBESTOS	Lino to electrical switchroom	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92137	BAC100324		17/07/2020			
#REF!	NAB	St.Lukes	17	Soffit Boards	Soffit	Cement Products	Chrysotile	Cement Sheets	Low		Remove (Controlled Conditions)	New Incident	HSG227	Unchecked	Very Low Risk	4	14/08/2021	Identified	Very Low Risk	92138	BAC100324		17/07/2020			
#REF!	NAB	St.Lukes	17	NO ASBESTOS	Debris to switchgear in electrical switch room	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92139	BAC100324		17/07/2020			
#REF!	NAB	St.Lukes	17	NO ASBESTOS	Pipework insulation to roofspace	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92140	BAC100324		17/07/2020			
#REF!	NAB	St.Lukes	17	NO ASBESTOS	Debris to roofspace	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92141	BAC100324		17/07/2020			
#REF!	NAB	St.Lukes	17	NO ASBESTOS	Debris to roofspace	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92142	BAC100324		17/07/2020			
#REF!	NAB	St.Lukes	17	NO ASBESTOS	Debris to roof space	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92143	BAC100324		17/07/2020			
#REF!	NAB	St.Lukes	17	NO ASBESTOS	Debris to roofspace	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92144	BAC100324		17/07/2020			
#REF!	NAB	St.Lukes	17	NO ASBESTOS	Debris to roofspace	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92145	BAC100324		17/07/2020			
#REF!	NAB	St.Lukes	17	Gaskets	Gasket to flange	Textiles & Paper	Chrysotile	Sealed	Low		Remove (Controlled Conditions)	New Incident	HSG227	Unchecked	Very Low Risk	4	14/08/2021	Identified	Very Low Risk	92146	BAC100324		17/07/2020			
#REF!	NAB	St.Lukes	17	Gaskets	Gasket to flange to roofspace	Textiles & Paper	Chrysotile	Sealed	Low		Remove (Controlled Conditions)	New Incident	HSG227	Unchecked	Very Low Risk	4	14/08/2021	Identified	Very Low Risk	92147	BAC100324		17/07/2020			
#REF!	NAB	St.Lukes	17	NO ASBESTOS	Ceiling to store to rear of Villa 2	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92148	BAC100324		17/07/2020			
#REF!	NAB	St.Lukes	17	NO ASBESTOS	Soffit to store to rear of Villa 2	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92149	BAC100324		17/07/2020			
#REF!	NAB	St.Lukes	17	NO ASBESTOS	Soffit to riser housing on roof to rear of Villa 2	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92150	BAC100324		17/07/2020			
#REF!	NAB	St.Lukes	17	Soffit Boarding	Soffit to gable to rear of Villa 2	Cement Products	Chrysotile	Cement Sheets	Low		Remove (Controlled Conditions)	New Incident	HSG227	Unchecked	Very Low Risk	4	14/08/2021	Identified	Very Low Risk	92151	BAC100324		17/07/2020			
#REF!	NAB	St.Lukes	17	NO ASBESTOS	Felt to flat roof to rear of Villa 2	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92152	BAC100324		17/07/2020			

#REF!	NAB	St.Lukes	18	Soffit Boards	Soffit outside electrical switchroom Villa 3	Cement Products	Chrysotile	Cement Sheets	Low	Remove (Controlled Conditions)	New Incident	HSG227	Unchecked	Very Low Risk	4	14/08/2021	Identified	Very Low Risk	92153	BAC100324		17/07/2020			
#REF!	NAB	St.Lukes	18	NO ASBESTOS	Lino to electrical switch room Villa 3	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92154	BAC100324		17/07/2020			
#REF!	NAB	St.Lukes	18	NO ASBESTOS	Debris to electrical switchgear room Villa 3	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92155	BAC100324		17/07/2020			
#REF!	NAB	St.Lukes	18	NO ASBESTOS	Debris to roof space	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92156	BAC100324		17/07/2020			
#REF!	NAB	St.Lukes	18	NO ASBESTOS	Debris to roof space	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92157	BAC100324		17/07/2020			
#REF!	NAB	St.Lukes	18	NO ASBESTOS	Debris to roof space	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92158	BAC100324		17/07/2020			
#REF!	NAB	St.Lukes	18	NO ASBESTOS	Ceiling to store to rear of Villa 3	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92159	BAC100324		17/07/2020			
#REF!	NAB	St.Lukes	18	Gaskets	Gasket to pipework within riser to rear of Villa 3	Textiles & Paper	Chrysotile	Sealed	Low	Remove (Controlled Conditions)	New Incident	HSG227	Unchecked	Very Low Risk	4	14/08/2021	Identified	Very Low Risk	92160	BAC100324		17/07/2020			
#REF!	NAB	St.Lukes	18	NO ASBESTOS	Soffit to store to rear of Villa 3	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92161	BAC100324		17/07/2020			
#REF!	NAB	St.Lukes	18	NO ASBESTOS	Soffit to riser housing on roof to rear of Villa 3	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92162	BAC100324		17/07/2020			
#REF!	NAB	St.Lukes	18	Soffit Boards	Soffit to sable rear of Villa 3	Cement Products	Chrysotile	Cement Sheets	Low	Remove (Controlled Conditions)	New Incident	HSG227	Unchecked	Very Low Risk	4	14/08/2021	Identified	Very Low Risk	92163	BAC100324		17/07/2020			
#REF!	NAB	St.Lukes	18	NO ASBESTOS	Felt to flat roof over flat roof to rear of Villa 3	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92164	BAC100324		17/07/2020			
#REF!	NAB	St.Lukes	19	NO ASBESTOS	Ceiling to switchroom Nurses Accommodation	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92165	BAC100324		17/07/2020			
#REF!	NAB	St.Lukes	19	NO ASBESTOS	Lino to switch room Nurses Accommodation	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92166	BAC100324		17/07/2020			
#REF!	NAB	St.Lukes	19	NO ASBESTOS	Soffit above door to lobby Nurses Accommodation	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92167	BAC100324		17/07/2020			
#REF!	NAB	St.Lukes	19	NO ASBESTOS	Verge undercloak to gable above Nurses Accommodation	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92168	BAC100324		17/07/2020			
#REF!	NAB	St.Lukes	20	Insulation residue	Residue to wall behind pipe RHS of storeroom Generator room	Thermal Insulation	Crocidolite/Chrysotile	Insulation	High	Remove (Controlled Conditions)	New Incident	HSG227	Unchecked	High Risk	12	17/11/2020	Identified	High Risk	92184	BAC100324		17/07/2020			
#REF!	NAB	St.Lukes	20	NO ASBESTOS	Panelling to storeroom Generator room	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92185	BAC100324		17/07/2020			
#REF!	NAB	St.Lukes	20	Bitumen Felt	UPL to wall opening Generator	Composite Material	Chrysotile	Sealed	Low	Remove (Controlled Conditions)	New Incident	HSG227	Unchecked	Very Low Risk	3	18/08/2021	Identified	Very Low Risk	92186	BAC100324		17/07/2020			
#REF!	NAB	St.Lukes	13	Insulation residue	Residue to wall basement	Thermal Insulation		Insulation	High	Remove (Controlled Conditions)	ACM Removed	HSG227	Unchecked	NO ASBESTOS	0	17/11/2020	Identified	Asbestos Removed	92187	BAC100324		17/07/2020			
#REF!	NAB	St.Lukes	13	Insulation residue	Residue to wall basement	Thermal Insulation		Insulation	Loose asbestos debris or residue	No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	17/11/2020	Identified	Asbestos Removed	92188	BAC100324		17/07/2020			
#REF!	NAB	St.Lukes	13	Insulation residue	Residue to wall basement	Thermal Insulation		Insulation	Loose asbestos debris or residue	No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	17/11/2020	Identified	Asbestos Removed	92189	BAC100324		17/07/2020			
#REF!	NAB	St.Lukes	13	Insulation residue	Residue to wall basement	Thermal Insulation		Insulation	Loose asbestos debris or residue	Remove (Controlled Conditions)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	17/11/2020	Identified	Asbestos Removed	92190	BAC100324		17/07/2020			
#REF!	NAB	St.Lukes	13	Insulation residue	Residue to wall basement	Thermal Insulation		Insulation	Loose asbestos debris or residue	Remove (Controlled Conditions)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	17/11/2020	Identified	Asbestos Removed	92191	BAC100324		17/07/2020	WHS		
#REF!	NAB	St.Lukes	13	Gaskets	Gasket (1 of 2) to basement	Textiles & Paper		Sealed	Low	Minor encapsulation and label as asbestos	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	18/08/2021	Identified	Asbestos Removed	92192	BAC100324		17/07/2020			
#REF!	NAB	St.Lukes	13	Insulation residue	Residue to wall basement	Thermal Insulation		Insulation	High	Remove (Controlled Conditions)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	18/08/2021	Identified	Asbestos Removed	92193	BAC100324		17/07/2020			
#REF!	NAB	St.Lukes	13	NO ASBESTOS	Residue to wall at light switch basement	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92194	BAC100324		17/07/2020			
#REF!	NAB	St.Lukes	13	NO ASBESTOS	Residue to wall basement	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92195	BAC100324		17/07/2020			
#REF!	NAB	St.Lukes	13	NO ASBESTOS	Residue to wall basement	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92196	BAC100324		17/07/2020			
#REF!	NAB	St.Lukes	13	NO ASBESTOS	Residue to wall basement	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92197	BAC100324		17/07/2020			
#REF!	NAB	St.Lukes	13	NO ASBESTOS	Residue to wall basement	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92198	BAC100324		17/07/2020			
#REF!	NAB	St.Lukes	13	NO ASBESTOS	Residue to wall basement	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92199	BAC100324		17/07/2020			
#REF!	NAB	St.Lukes	13	NO ASBESTOS	Debris to floor basement	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92200	BAC100324		17/07/2020			
#REF!	NAB	St.Lukes	13	NO ASBESTOS	Debris to floor basement	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92201	BAC100324		17/07/2020			
#REF!	NAB	St.Lukes	13	NO ASBESTOS	Debris to floor basement	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92202	BAC100324		17/07/2020			
#REF!	NAB	St.Lukes	13	NO ASBESTOS	Debris to cable tray basement	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92203	BAC100324		17/07/2020			
#REF!	NAB	St.Lukes	13	NO ASBESTOS	Debris to cable tray basement	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92204	BAC100324		17/07/2020			
#REF!	NAB	St.Lukes	13	NO ASBESTOS	Debris to floor basement	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92205	BAC100324		17/07/2020			
#REF!	NAB	St.Lukes	13	NO ASBESTOS	Debris to floor basement	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92206	BAC100324		17/07/2020			
#REF!	NAB	St.Lukes	13	Ridge Tiles	Stack of ridge tiles basement	Cement Products		Partially Sealed Cement	Low	No further action required (Asbestos removed)	Asbestos Removed	HSG227	Unchecked	NO ASBESTOS	0	18/08/2021	Identified	Asbestos Removed	92207	BAC100324		17/07/2020			
#REF!	NAB	St.Lukes	29	Gaskets	Gasket to flange to generator room	Textiles & Paper	Chrysotile	Sealed	Low	Remove (Controlled Conditions)	New Incident	HSG227	Unchecked	Very Low Risk	4	18/08/2021	Identified	Very Low Risk	92208	BAC100324		17/07/2020			
#REF!	QAA	Craigavon Hospital	08	NO ASBESTOS	Debris to ledge first floor	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92209	BAC100335		27/07/2020			
#REF!	QAA	Craigavon Hospital	08	NO ASBESTOS	Debris to ledge first floor	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92210	BAC100335		27/07/2020			
#REF!	QAA	Craigavon Hospital	08	NO ASBESTOS	Debris to top lift car	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92211	BAC100335		27/07/2020			
#REF!	QAA	Craigavon Hospital	08	NO ASBESTOS	Debris to frame within lift shaft	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92212	BAC100335		27/07/2020			
#REF!	QAA	Craigavon Hospital	08	NO ASBESTOS	Debris to lift plant room	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92213	BAC100335		27/07/2020			
#REF!	QAA	Craigavon Hospital	08	NO ASBESTOS	Debris to lift plant room	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92214	BAC100335		27/07/2020			
#REF!	QAA	Craigavon Hospital	08	NO ASBESTOS	Debris to shaft pit	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92215	BAC100335		27/07/2020			
#REF!	QAA	Craigavon Hospital	08	NO ASBESTOS	Debris to shaft pit	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92216	BAC100335		27/07/2020			
#REF!	QAA	Craigavon Hospital	08	NO ASBESTOS	Debris to counter weight	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92217	BAC100335		27/07/2020			
#REF!	QAA	Craigavon Hospital	08	NO ASBESTOS	DPC to lift doors	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92218	BAC100335		27/07/2020			
#REF!	QAA	Craigavon Hospital	08	NO ASBESTOS	Gasket to stop cap, at door to chanaino room	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92219	BAC100335		27/07/2020			
#REF!	QAA	Craigavon Hospital	08	Gaskets	Gasket to flange at door to chanaino room	Textiles & Paper	Chrysotile	Encapsulated Rope	Low	Remove	Re-inspection	HSG227	Unchecked	Low Risk	5	06/09/2023	Identified	Low Risk	92220	BAC100335	930202	18/10/2022	WHS		
#REF!	QAA	Craigavon Hospital	08	Gaskets	Gasket to flange at door to chanaino room	Textiles & Paper	Chrysotile	Encapsulated Rope	Low	Remove	Re-inspection	HSG227	Unchecked	Low Risk	5	06/09/2023	Identified	Low Risk	92221	BAC100335	930202	18/10/2022	WHS		
#REF!	QAA	Craigavon Hospital	08	NO ASBESTOS	Debris to cable tray penetration at doors to chanaino room	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92222	BAC100335		27/07/2020			
#REF!	QAA	Craigavon Hospital	08	NO ASBESTOS	Blanket to flange adjacent to goods lift	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92223	BAC100335		27/07/2020			
#REF!	QAA	Craigavon Hospital	08	NO ASBESTOS	Debris to ceiling tile above toilet	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92224	BAC100335		27/07/2020			
#REF!	QAA	Craigavon Hospital	08	NO ASBESTOS	Debris to ceiling void	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92225	BAC100335		27/07/2020			
#REF!	QAA	Craigavon Hospital	08	Gaskets	Gasket to flange to ceiling void	Textiles & Paper	Chrysotile	Encapsulated Rope	Low	Remove	Re-inspection	HSG227	Unchecked	Low Risk	5	06/09/2023	Identified	Low Risk	92226	BAC100335	930202	18/10/2022	WHS		
#REF!	QAA	Craigavon Hospital	08	Cloth	Gasket between pipework and	Textiles & Paper	Chrysotile	Enclosed Woven Textile	Low	Remove	Re-inspection	HSG227	Unchecked	Low Risk	5	06/09/2023	Identified	Low Risk	92227	BAC100335	930202	18/10/2022	WHS		
#REF!	QAA	Craigavon Hospital	08	Debris	Debris to ceiling void at door to	Insulating Board	Amosite/Chrysotile	Loose Asbestos Debris		Remove	Re-inspection	HSG227	Unchecked	High Risk	10	06/09/2023	Identified	High Risk	92228	BAC100335	[illegible]	18/10/2022	WHS		
#REF!	QAA	Craigavon Hospital	08	NO ASBESTOS	Panelling to skylight	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92229	BAC100335		27/07/2020			
#REF!	QAA	Craigavon Hospital	08	NO ASBESTOS	Dark grey floor tile to corridor	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92230	BAC100335		27/07/2020			
#REF!	QAA	Craigavon Hospital	08	NO ASBESTOS	Light grey floor tile to corridor	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92231	BAC100335		27/07/2020			
#REF!	QAA	Craigavon Hospital	08	NO ASBESTOS	White floor tile to corridor	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92232	BAC100335		27/07/2020			
#REF!	QAA	Craigavon Hospital	08	NO ASBESTOS	Debris to floor of switch room	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92233	BAC100335		27/07/2020			
#REF!	QAA	Craigavon Hospital	08	NO ASBESTOS	Debris to cable penetration at high level into switch room	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92234	BAC100335		27/07/2020			
#REF!	QAA	Craigavon Hospital	08	NO ASBESTOS	Debris to control panel	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92235	BAC100335		27/07/2020			
#REF!	QAA	Craigavon Hospital	08	Back Board	Backing panel to electrics	Insulating Board	Presumed Asbestos	Encapsulated Asbestos	Low	Further Investion Required	Re-inspection	HSG227	Unchecked	Medium Risk	7	08/03/2023	Strongly Presumed	Medium Risk	92236	N/A	[illegible]	18/10/2022	WHS		
#REF!	QAA	Craigavon Hospital	08	Gaskets	Gasket to flange to ceiling void	Textiles & Paper		Encapsulated Rope	Low	Further investigation Required	Re-inspection	HSG227	Unchecked	Very Low Risk	4	06/09/2023	Strongly Presumed	Very Low Risk	92254	N/A	[illegible]	18/10/2022	WHS		
#REF!	RAA	South Tyrone Hospital	17	Cloth wrap	Cloth wrap to pipework to ceiling	Textiles & Paper	Chrysotile	Encapsulated Rope	Low	Remove	Re-inspection	HSG227	Unchecked	Low Risk	5	13/12/2023	Identified	Low Risk	92262	BAC100359	[illegible]	13/12/2022	WHS		
#REF!	RAA	South Tyrone Hospital	17	Cloth wrap	Cloth wrap to pipework to ceiling	Textiles & Paper	Chrysotile	Encapsulated Rope	Low	Remove	Re-inspection	HSG227	Unchecked	Low Risk	5	13/12/2023	Identified	Low Risk	92263	BAC100359	[illegible]	13/12/2022	WHS		
#REF!	RAA	South Tyrone Hospital	17	Cloth wrap	Cloth wrap to pipework to ceiling	Textiles & Paper	Chrysotile	Encapsulated Rope	Low	Remove	Re-inspection	HSG227	Unchecked	Low Risk	5	13/12/2023	Identified	Low Risk	92264	BAC100359	[illegible]	13/12/2022	WHS		
#REF!	RAA	South Tyrone Hospital	17	Cloth wrap	Cloth wrap to pipework to ceiling	Textiles & Paper	Chrysotile	Encapsulated Rope	Low	Remove	Re-inspection	HSG227	Unchecked	Low Risk	5	13/12/2023	Identified	Low Risk	92266	BAC100359	[illegible]	13/12/2022	WHS		
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Lagging to pipework to ceiling void	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92269	BAC100359		03/08/2020			
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Insulation to top side of heating panel to ceilino void	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92280	BAC100359		03/08/2020			
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Ceiling tile	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92281	BAC100359		03/08/2020			
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Debris to ceiling void	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92282	BAC100359		03/08/2020			
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Debris to ceiling void	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92283	BAC100359		03/08/2020			
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Debris to floor	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92284	BAC100370		17/08/2020			
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Debris to floor	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92285	BAC100370		17/08/2020			

#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Debris to floor	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92286	BAC100370			17/08/2020		
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	White board to pipe penetration at ceilino to riser adiacent to 005	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92287	BAC100370			17/08/2020		
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Grey board to pipe penetration at ceilino to riser adiacent to 005	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92288	BAC100370			17/08/2020		
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Paper to joint in ceiling within riser adiacent to 005	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	Error Entry	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92289	BAC100370			17/08/2020		
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Bitumen splash above door to riser adiacent to 005	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92290	BAC100370			17/08/2020		
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Bitumen splash to LHS wall at eye-level to riser adiacent to 005	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92291	BAC100370			17/08/2020		
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Debris to pipework at mid-level to RHS wall to riser adiacent to 005	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92292	BAC100370			17/08/2020		
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Debris to metal ledge LHS to riser adiacent to 005	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92293	BAC100370			17/08/2020		
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Debris to metal ledge RHS to riser adiacent to 005	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92294	BAC100370			17/08/2020		
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Debris to LHS of grating to riser adiacent to 005	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92295	BAC100370			17/08/2020		
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Debris to RHS of grating to riser adiacent to 005	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92296	BAC100370			17/08/2020		
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Debris to rear ledge to riser adiacent to 005	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92297	BAC100370			17/08/2020		
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Debris to low level ledge to LHS wall	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92298	BAC100370			17/08/2020		
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Debris to mid-level ledge to RHS wall	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92299	BAC100370			17/08/2020		
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Debris to LHS grating at floor level	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92300	BAC100370			17/08/2020		
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Debris to RHS grating at floor level	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92301	BAC100370			17/08/2020		
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Debris to top of electrical box "F" to LHS	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92302	BAC100370			17/08/2020		
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Residue at eye-level to bracket to first pipe on RHS wall	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92303	BAC100370			17/08/2020		
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Residue below bracket to pipe to rear wall at head-height	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92304	BAC100370			17/08/2020		
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Insulation to edge of door frame at hiah level	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92305	BAC100370			17/08/2020		
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Fire stopping to pipe penetration above door	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92306	BAC100370			17/08/2020		
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Debris to top of light at high level	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92307	BAC100370			17/08/2020		
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Debris to bracket to black pipe in rear riaht corner at mid-level	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92308	BAC100370			17/08/2020		
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Residue to concrete ledge at doorway	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92309	BAC100370			17/08/2020		
#REF!	RAA	South Tyrone Hospital	17	Floor Tiles	VFT at door saddle	Composite Material	Chrysotile	Composite Material	Low	Label and Remove if likely to be disturbed	Re-inspection	HSG227	Unchecked	Very Low Risk	3	14/12/2023	Identified	Very Low Risk	92310	BAC100370	9302.22	14/12/2022	WHS		
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Debris to low level ledge to LHS wall	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92311	BAC100370			17/08/2020		
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Debris to high level ledge to RHS wall	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92312	BAC100370			17/08/2020		
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Debris to top of electrical box "E" to LHS	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92313	BAC100370			17/08/2020		
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Debris to LHS of grating at floor level	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92314	BAC100370			17/08/2020		
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Debris to RHS of grating at floor level	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92315	BAC100370			17/08/2020		
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Debris to bracket to pipes RHS at hiah level	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92316	BAC100370			17/08/2020		
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Bitumen to bracket to pipe at high level	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92317	BAC100370			17/08/2020		
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Debris to concrete ledge at door at low level	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92318	BAC100370			17/08/2020		
#REF!	RAA	South Tyrone Hospital	17	Floor Tiles	VFT at door saddle	Composite Material	Chrysotile	Composite Material	Low	Label and Remove if likely to be disturbed	Re-inspection	HSG227	Unchecked	Very Low Risk	3	14/12/2023	Identified	Very Low Risk	92319	BAC100370	9302.22	14/12/2022	WHS		
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Debris to low level ledge to LHS wall	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92320	BAC100370			17/08/2020		
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Debris to high level ledge to RHS wall	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92321	BAC100370			17/08/2020		
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Debris to LHS of grating at floor level	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92322	BAC100370			17/08/2020		
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Debris to RHS of grating at floor level	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92323	BAC100370			17/08/2020		
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Debris to top of electrical box "D" to LHS	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92324	BAC100370			17/08/2020		
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Debris to concrete ledge at door at low level	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92325	BAC100370			17/08/2020		
#REF!	RAA	South Tyrone Hospital	17	Floor Tiles	VFT at door saddle	Composite Material	Chrysotile	Composite Material	Low	Label and Remove if likely to be disturbed	Re-inspection	HSG227	Unchecked	Very Low Risk	3	13/12/2023	Identified	Very Low Risk	92326	BAC100370	9302.22	13/12/2022	WHS		
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Residue to first pipe on RHS at mid-level	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92327	BAC100370			17/08/2020		
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Redundant cloth at high level to rear left corner	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92328	BAC100370			17/08/2020		
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Loose paper at high level to rear left corner	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92329	BAC100370			17/08/2020		
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Debris to low level ledge to LHS wall	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92330	BAC100370			17/08/2020		
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Debris to high level ledge to RHS wall	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92331	BAC100370			17/08/2020		
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Debris to LHS of grating at floor level	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92332	BAC100370			17/08/2020		
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Debris to RHS of grating at floor level	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92333	BAC100370			17/08/2020		
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Debris to top of electrical panel "C" to LHS	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92334	BAC100370			17/08/2020		
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Debris to concrete ledge at door at low level	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92335	BAC100370			17/08/2020		
#REF!	RAA	South Tyrone Hospital	17	Floor Tiles	VFT at door saddle	Composite Material	Chrysotile	Composite Material	Low	Label and Remove if likely to be disturbed	Re-inspection	HSG227	Unchecked	Very Low Risk	3	13/12/2023	Identified	Very Low Risk	92336	BAC100370	9302.22	13/12/2022	WHS		
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Bitumen to bracket at eye level to RHS wall	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92337	BAC100370			17/08/2020		
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Debris to low level ledge to LHS wall	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92338	BAC100370			17/08/2020		
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Debris to high level ledge to RHS wall	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92339	BAC100370			17/08/2020		
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Debris to LHS of grating at floor level	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92340	BAC100370			17/08/2020		
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Debris to RHS of grating at floor level	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92341	BAC100370			17/08/2020		
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Debris to top of electrical box "B" to LHS	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92342	BAC100370			17/08/2020		
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	VTF to door saddle	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92343	BAC100370			17/08/2020		
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Debris to top of electrical box to LHS	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92344	BAC100370			17/08/2020		
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Debris to flange to black pipe in riaht rear corner	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92345	BAC100370			17/08/2020		
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Residue to pipework bend at high level to rear wall	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92346	BAC100370			17/08/2020		
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Debris to concrete plinth at low level to right rear corner	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92347	BAC100370			17/08/2020		
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Residue under bracket adjacent to pipe bend at door	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92348	BAC100370			17/08/2020		
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Bitumen seal to ventilation ducting flange above ceilino tiles	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92349	BAC100370			17/08/2020		
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Debris to top of ceiling tile	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92350	BAC100370			17/08/2020		
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Debris to floor	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92351	BAC100370			17/08/2020		
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Debris to metal grating	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92352	BAC100372			21/08/2020		
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Debris to high level ledge to RHS wall	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92353	BAC100372			21/08/2020		
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Debris to low level ledge at rear wall	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92354	BAC100372			21/08/2020		
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Debris to riser	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92355	BAC100372			21/08/2020		
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Debris to high level ledge to RHS wall	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92356	BAC100372			21/08/2020		
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Debris to redundant electrical box to LHS	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92357	BAC100372			21/08/2020		
#REF!	RAA	South Tyrone Hospital	17	NO ASBESTOS	Debris to riser	NO ASBESTOS	NO ASBESTOS				No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92358	BAC100372			21/08/2020		

#REFI	RAA	South Tyrone Hospital	17	Cloth	Cloth between bracket and vent trunkino above suspended ceilino	Textiles & Paper	Chrysotile	Unsealed Rope	Low	Label and Remove if likely to be disturbed	Re-inspection	HSG227	Unchecked	Low Risk	6	13/12/2023	Identified	Low Risk	92359	BAC100372	9302.22	13/12/2022	WHS
#REFI	RAA	South Tyrone Hospital	17	Cloth	Cloth between bracket and vent trunkino above suspended ceilino	Textiles & Paper	Chrysotile	Unsealed Rope	Low	Label and Remove if likely to be disturbed	Re-inspection	HSG227	Unchecked	Low Risk	6	13/12/2023	Identified	Low Risk	92360	BAC100372	9302.22	13/12/2022	WHS
#REFI	RAA	South Tyrone Hospital	17	NO ASBESTOS	Debris to riser adjacent vent 005	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92361	BAC100372		21/08/2020	
#REFI	RAA	South Tyrone Hospital	17	Cloth	Cloth between bracket and vent trunkino above suspended ceilino	Textiles & Paper	Presumed Asbestos	Unsealed Rope	Low	Label and Remove if likely to be disturbed	Re-inspection	HSG227	Unchecked	Medium Risk	8	13/12/2023	Strongly Presumed	Medium Risk	92362	N/A	9302.22	13/12/2022	WHS
#REFI	NAB	St.Lukes	12	NO ASBESTOS	Fascia board to walk-way canopy	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92419	BAC100234		23/04/2020	
#REFI	NAB	St.Lukes	12	NO ASBESTOS	Lath and plaster soffit to walk-way canopy	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	Adding Documentation	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92420	BA100234		23/04/2020	
#REFI	NAB	St.Lukes	12	NO ASBESTOS	Lath and plaster soffit to walk-way canopy	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92421	BA100234		23/04/2020	
#REFI	NAB	St.Lukes	12	NO ASBESTOS	Replacement board to walk-way canopy	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92422	BAC100234		23/04/2020	
#REFI	NAB	St.Lukes	12	NO ASBESTOS	Lath and plaster soffit to walk-way canopy	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92423	BAC100234		23/04/2020	
#REFI	NAB	St.Lukes	12	Gaskets	Horizontal gasket to flange above Male Wino Front Pumps Nr 1 & 2	Textiles & Paper	Chrysotile	Encapsulated Rope	Low	Remove	New Incident	HSG227	Unchecked	Low Risk	5	03/09/2021	Identified	Low Risk	92424	BAC100229		09/03/2020	
#REFI	NAB	St.Lukes	12	NO ASBESTOS	Horizontal gasket to flange above Male Wino Soine Section Pumps	NO ASBESTOS	NO ASBESTOS			No further action required (No Asbestos Detected)	New Incident	HSG227	Unchecked	NO ASBESTOS	0		Identified	No Asbestos Detected	92425	BAC100229		03/09/2020	